



Maeda - CRGL - SELI Joint Venture

Contract No. DC/2007/12 - Design and  
Construction of Tsuen Wan Drainage Tunnel

Monthly EM&A Report (May 2013)

---

**Hyder Consulting Limited**

Company Number 126012

47th Floor, Hopewell Centre  
183 Queen's Road East  
Wanchai  
Hong Kong

Tel: +852 2911 2233

Fax: +852 2805 5028

hyder.hk@hyderconsulting.com  
www.hyderconsulting.com



**MAEDA** 中国中铁



## Maeda - CRGL - SELI Joint Venture

# Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel

## Monthly EM&A Report (May 2013)

---

**Report No** EB000364R0961

**F.C. Tsang**

**Certified By** ET Leader

**David Yeung**

**Verified By** Independent Environmental Checker

  
\_\_\_\_\_  
  
\_\_\_\_\_

Hyder Consulting Limited

Company Number 126012

47th Floor, Hopewell Centre  
183 Queen's Road East  
Wanchai  
Hong Kong

Tel: +852 2911 2233

Fax: +852 2805 5028

hyder.hk@hyderconsulting.com  
www.hyderconsulting.com



MAEDA 中国中铁

## Maeda - CRGL - SELI Joint Venture

# Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel

## Monthly EM&A Report (May 2013)

---

**Author** Ray Tam

**Checker** F.C. Tsang

**Approver** John Berry

**Report No** EB000364R0961

**Date** 17 June 2013

Three horizontal lines representing signature lines. The first line has a signature of Ray Tam. The second line has a signature of F.C. Tsang. The third line has a signature of John Berry.

This Monthly EM&A Report (May 2013) is prepared for Maeda - CRGL - SELI Joint Venture in accordance with the terms and conditions of appointment dated 18 December 2007. Hyder Consulting Limited (Company Number 126012) cannot accept any responsibility for any use of or reliance on the contents of this report by any third party.

# CONTENTS

---

|   |    |
|---|----|
| EXECUTIVE SUMMARY .....   | 1  |
| 1 INTRODUCTION .....  | 3  |
| 2 PROJECT INFORMATION.....  | 4  |
| 2.1 Project Organization and Management Structure.....  | 4  |
| 2.2 Construction Progress .....   | 4  |
| 2.3 Mitigation Measures .....   | 5  |
| 2.4 Statuses of Licences and Permits .....  | 5  |
| 3 SUMMARY OF EM&A REQUIREMENT .....   | 6  |
| 3.1 Air Quality .....   | 6  |
| 3.2 Noise .....   | 10 |
| 3.3 Water Quality .....   | 13 |
| 4 MONITORING RESULT .....   | 19 |
| 4.1 Air Quality .....   | 19 |
| 4.2 Noise .....   | 21 |
| 4.3 Water Quality Monitoring .....  | 22 |
| 4.4 Summary of Project-Related Exceedances .....  | 32 |
| 5 WASTE MANAGEMENT .....  | 33 |
| 6 NON-COMPLIANCE AND DEFICIENCY .....   | 34 |
| 6.1 Site Audit by ET.....   | 34 |
| 7 COMPLAINT.....  | 35 |
| 8 SUMMARY OF NOTIFICATION OF SUMMONS, SUCCESSFUL<br>PROSECUTIONS AND CORRECTIVE ACTIONS ..... | 36 |
| 9 FUTURE KEY ISSUE .....  | 37 |

## TABLES

---

|            |  |
|------------|--|
| Table 3-1  | Air Quality Monitoring Equipment   |
| Table 3-2  | Air Quality Monitoring Locations   |
| Table 3-3  | Action & Limit Levels for Air Quality  |
| Table 3-4  | Event/Action Plan for Air Quality  |
| Table 3-5  | Noise Monitoring Equipment   |
| Table 3-6  | Noise Monitoring Locations   |
| Table 3-7  | Action & Limit Levels for Air Borne Noise  |
| Table 3-8  | Event/Action Plan for Airborne Noise   |
| Table 3-9  | Water Quality Monitoring Equipment   |
| Table 3-10 | Water Quality Monitoring Locations   |
| Table 3-11 | Action/Limit Levels for Water Quality  |
| Table 3-12 | Event/Action Plan for Water Quality  |
| Table 4-1  | Air Quality Monitoring Results   |
| Table 4-2  | Air Borne Noise Monitoring Results   |
| Table 4-3  | Summary of Exceedances for I-1   |
| Table 4-4  | Summary of Exceedances for I-2   |
| Table 4-5  | Summary of Exceedances for I-3   |
| Table 4-6  | Water Quality Monitoring Results   |
| Table 4-7  | Summary of Project-Related Exceedances   |
| Table 5-1  | Waste Generated in May 2013  |
| Table 6-1  | Site Inspections by ET   |
| Table 7-1  | Cumulative Statistics of Environmental Complaints  |
| Table 8-1  | Cumulative Statistics of Notification of Summons and Successful Prosecutions and Convictions |

## APPENDICES

---

|            |   |
|------------|---|
| Appendix A | Site Map and Works Area   |
| Appendix B | Organization Chart  |
| Appendix C | Construction Programme  |
| Appendix D | Implementation Status of Environmental Mitigation Measures        |
| Appendix E | Status of License and Permit                                      |
| Appendix F | Calibration Certificates  |
| Appendix G | Monitoring Locations  |
| Appendix H | EM&A Schedule   |
| Appendix I | Monitoring Results  |
| Appendix J | Interim Notifications of Environmental Quality Limits Exceedances |
| Appendix K | Complaint Log   |

## EXECUTIVE SUMMARY

- Drainage Services Department (DSD) has awarded the contract for the Design and Construction of Tsuen Wan Drainage Tunnel (hereafter referred to as the “Project”) to Maeda-CRGL-SELI Joint Venture (MCSJV). MCSJV has appointed Hyder Consulting Limited (HCL) as the Environmental Team (ET) to undertake the Environmental Monitoring and Audit (EM&A) works in accordance with the EM&A Manual and Environmental Permit (EP). Commencement of the construction work had been notified to the Environmental Protection Department (EPD) in January 2008. This Monthly EM&A Report summarises the EM&A works undertaken in May 2013.
- According to the EM&A Manual, there are four designated air quality monitoring locations, five designated noise monitoring locations and five water quality monitoring locations during the construction phase: (i) Sik Sik Yuen Ho Fung College (ASR 1, NSR 1 and Intake I-1); (ii) Hong Hoi Chee Hong Temple (ASR 3, NSR 3 and Intake I-2); (iii) Squatters (NSR 6 and Intake I-3); (iv) Beach Tower (Long Beach Gardens) (ASR 8, NSR 8 and Outfall O-1); and (v) Greenview Terrace (Block 1) (ASR 9, NSR 9 and Outfall O-1).
- During the non-restricted hours, major construction activities undertaken by the Contractor at Tsuen Wan Drainage Tunnel included site cleaning and tidying at Outfall, I-1, I-2 and I-3; construction of reinforced concrete (RC) structure of trellis beams and Outfall “W” at Outfall; construction of surface drainage at Outfall; backfilling on top of box culvert at Outfall; slope reinstatement works at Outfall; landscape works at Outfall; installation of miscellaneous steel works at trellis beam and tapered channel at Outfall; construction of RC structure of buttress wall at I-3; excavation and construction of permanent access road and surface drainage at I-3; construction of maintenance staircase below PA wall at I-3; water proofing for approach channel and vortex shaft at I-3; mucking out for +76mPD platform at I-3; construction of RC structure of man access shaft at I-2; excavation and construction of associated drainage of access platform next to man access shaft at I-2; water proofing works at roof of equipment room at I-2; installation of miscellaneous steel works for vortex shaft, approach channel and air vent shaft at I-2; finishing works for spiral ramp at I-1; installation of security fencing at I-1; landscape works at I-1; and reinstatement of site entrance at I-1.
- No exceedance was recorded for air quality monitoring during the reporting month.
- No exceedance was recorded for noise monitoring during the reporting month.
- Exceedances for river water quality monitoring are summarised in the following table:

| Parameter | Action Level Exceedance          | Limit Level Exceedance  |
|-----------|----------------------------------|---|
| DO        | Nil                              | Nil   |
| Turbidity | One record at I-1 on 22 May 2013 | One record at I-2 on 22 May 2013<br>Two records at I-3 on 22 May 2013 and 29 May 2013 |
| SS        | One record at I-1 on 18 May 2013 | One record at I-1 on 22 May 2013<br>One record at I-2 on 22 May 2013                  |

- Marine water quality monitoring for dredging and marine works has been terminated since 1 May 2012. As such, there was no marine water quality monitoring in this reporting month.
- The status of waste generation in the reporting month is:

- A total of 1789.8 m<sup>3</sup> C&D material was disposed to public fill at Tuen Mun. No inert C&D material was reused in this Contract and no inert C&D material was reused in other Contracts. Detail information could be referred to Section 5.1.1 of this report;
  - About 25.7 m<sup>3</sup> general waste was disposed of to NENT Landfill;
  - 400 kg paper/cardboard was recycled in the reporting month;
  - 23 kg metal was generated in the reporting month;
  - 20 kg plastic waste was disposed of in the reporting month; and
  - No chemical waste was disposed of in the reporting month.
- In this reporting month, two site inspections and one monthly site audit were carried out by the ET and Independent Environmental Checker (IEC) respectively, to ensure proper implementation of environmental mitigation measures specified in the EM&A Manual and compliance with environmental legislation. All observations, which were recorded on the site inspection checklists, were passed to the Contractor together with the ET's recommendations.
  - As advised by the Contractor and verified by ET:
    - No non-compliance regarding the site inspection was received in the reporting month;
    - No environmental complaint was received in the reporting month; and
    - No summons and prosecution was received in the reporting month.
  - The major construction works for the upcoming three months will be:
    - Site cleaning and tidying at Outfall, I-1, I-2 and I-3;
    - Construction of RC structures of Outfall "W" at Outfall;
    - Slope reinstatement Works at Outfall;
    - Backfilling on top of box culvert at Outfall;
    - Finishing works for spiral ramp at Outfall;
    - Construction of surface drainage at Outfall;
    - Installation of GRP panels of spiral ramp and miscellaneous steel works at Outfall;
    - Landscape works at Outfall;
    - Installation of additional irrigation system at Outfall and I-1;
    - Excavation and construction of permanent access road and associated drainage at I-3;
    - Installation of stone facing for vortex shaft at I-3;
    - Construction of access platform and associated drainage next to man access shaft at I-2;
    - Tiling works for man access shaft at I-2; and
    - Reinstatement of site entrance and installation of fencing and railing at I-1.

# 1 INTRODUCTION

- 1.1.1 The Drainage Services Department (DSD) proposed to construct a tunnel with an internal diameter of 6.5 m and a length of 5.13 km, with the purpose to alleviate the flooding risk in Tsuen Wan and Kwai Chung.
- 1.1.2 This project is a Designated Project under Schedule 2 Part I Category Q, of the Environmental Impact Assessment Ordinance (EIAO) as part of the proposed Tsuen Wan Drainage Tunnel (TWDT) passes underneath the existing Tai Mo Shan Country Park. An Environmental Impact Assessment (EIA) Study has therefore been undertaken to provide information on the nature and extent of environmental impacts arising from the construction and operation of the proposed designated project and related activities taking place concurrently. From the EIA, the recommendations for monitoring contained herein are made.
- 1.1.3 The Maeda-CRGL-SELI Joint Venture (MCSJV) was awarded by DSD with the Contract – Design and Construction of Tsuen Wan Drainage Tunnel.
- 1.1.4 Hyder was commissioned by the MCSJV as the Environmental Team (ET) to implement an EM&A programme in accordance with the EM&A Manual. The proposed tunnel section flows from the junction of Shing Mun Road and Wo Yi Hop Road and discharges to south of Yau Kom Tau underneath Castle Peak Road as shown in Appendix A.
- 1.1.5 The construction works of the Project was commenced in January 2008. This is the sixty-second monthly EM&A report summarising the impact monitoring results and audit findings of the EM&A programme in May 2013.



## 2 PROJECT INFORMATION

### 2.1 Project Organization and Management Structure

2.1.1 The organization chart and lines of communication with respect to the on-site environmental management are shown in Appendix B.

### 2.2 Construction Progress

2.2.1 The overall project programme from the detail design to completion of all civil works shall take approximately 70 months. The construction programme is presented in Appendix C.

2.2.2 The major construction activities undertaken in the reporting month were:

- Site cleaning and tidying at Outfall, I-1, I-2 and I-3;
- Construction of reinforced concrete (RC) structure of trellis beams and Outfall “W” at Outfall;
- Construction of surface drainage at Outfall;
- Backfilling on top of box culvert at Outfall;
- Slope reinstatement works at Outfall;
- Landscape works at Outfall;
- Installation of miscellaneous steel works at trellis beam and tapered channel at Outfall;
- Construction of RC structure of buttress wall at I-3;
- Excavation and construction of permanent access road and surface drainage at I-3;
- Construction of maintenance staircase below PA wall at I-3;
- Water proofing for approach channel and vortex shaft at I-3;
- Mucking out for +76mPD platform at I-3;
- Construction of RC structure of man access shaft at I-2;
- Excavation and construction of associated drainage of access platform next to man access shaft at I-2;
- Water proofing works at roof of equipment room at I-2;
- Installation of miscellaneous steel works for vortex shaft, approach channel and air vent shaft at I-2;
- Finishing works for spiral ramp at I-1;
- Installation of security fencing at I-1;
- Landscape works at I-1; and
- Reinstatement of site entrance at I-1.

2.2.3 No marine mud dredging works for basin scheme at portion E was conducted in the reporting month, as all marine works were completed on 30 March 2012.

2.2.4 No work was undertaken during the restricted hours in the reporting period.

## 2.3 Mitigation Measures

2.3.1 The implemented environmental mitigation measures and their statuses are given in Appendix D.

## 2.4 Statuses of Licences and Permits

2.4.1 A summary of relevant permits and licences for the Project is given in Appendix E.

## 3 SUMMARY OF EM&A REQUIREMENT

### 3.1 Air Quality

#### Air Quality Parameters

- 3.1.1 One-hour total suspended particulates (TSP) levels were measured at the designated air quality monitoring locations in accordance with the EM&A Manual. Information such as date of monitoring, duration, weather condition, equipment used and monitoring results were recorded on the field data sheet developed for the Project. The monitoring results are presented in Section 4.

#### Monitoring Methodology

- 3.1.2 One-hour TSP monitoring was carried out under typical weather conditions (with no adverse weather such as typhoon signal or rain storm warning) three times every six days using High Volume Air Samplers (HVASs). Monitoring was conducted in accordance with the standard sampling method as set out in High Volume Method for Total Suspended Particulates, Part 50 Chapter 1 Appendix B, Title 40 of the Code of Federal Regulations of the USEPA.
- 3.1.3 After each sampling, the filter paper loaded with dust was kept in a clean and tightly sealed plastic bag. The filter paper was then re-conditioned in desiccators for 24 hours before obtaining the weight under laboratory conditions.
- 3.1.4 The average concentrations of the TSP were calculated based on the following information obtained from monitoring:
- Flow rate;
  - Weight of the filter paper before and after sampling; and
  - Sampling period indicated by the elapsed-time meter.
- 3.1.5 All samples were kept in good condition (i.e. stored in sealed plastic bags, with brief description of the monitoring dates and locations) for a period of 6 months before disposal. Sample analysis was carried out by ALS Technichem (HK) Pty Limited (HOKLAS Registration Number 066).

#### Monitoring Equipment and Calibration

- 3.1.6 High Volume Air Samplers (HVASs) were used for 1-hour TSP monitoring to comply with the USEPA specifications in Appendix B Part 5 - Reference Method for the Determination of Suspended Particulate Matter in the Atmosphere (High-Volume Method) of the Code of Federal Regulation dated June 1, 1991.
- 3.1.7 All HVASs were calibrated before commencement of monitoring using standard orifice 5-points calibration method with orifice calibrator to determine the actual flow rate of each HVAS. This was used for the calculation of the TSP level. Calibration Kit Model - TE5025A was used for calibration of the HVAS. Recalibration of the HVAS was carried out after motor maintenance, at least once every six months, which was about the expected life of carbon brush. The air quality monitoring equipment used during the

reporting month is shown in Table 3-1 below. The calibration certificates are included in Appendix F.

| Equipment Type | Model    | Serial Number | Calibration Orifice Number | Location |
|----------------|----------|---------------|----------------------------|----------|
| HVAS           | BM2000HX | 4994          | 1785                       | ASR 1    |
| HVAS           | BM2000HX | 5875          | 1785                       | ASR 3    |
| HVAS           | TE5005X  | 1059          | 1785                       | ASR 8    |
| HVAS           | TE5005X  | 1713          | 1785                       | ASR 9    |

**Table 3-1 Air Quality Monitoring Equipment**

## Monitoring Location

3.1.8 Four designated air quality monitoring locations were identified in the contract specific EM&A Manual. They are listed in Table 3-2 below and shown in Appendix G.

| Monitoring Station ID | Name of Premises                | Floor Level |
|-----------------------|---------------------------------|-------------|
| ASR1                  | Sik Sik Yuen Ho Fung College    | G/F         |
| ASR3                  | Hong Hoi Chee Hong Temple       | Podium      |
| ASR8                  | Beach Tower (Long Beach Garden) | G/F         |
| ASR9                  | Greenview Terrace (Block 1)     | G/F         |

**Table 3-2 Air Quality Monitoring Locations**

## Action and Limit Levels

3.1.9 The Action and Limit Levels for the 1-hour TSP monitoring are shown in Table 3-3. In case exceedances of Action and/or Limit levels for air quality occur, Event Contingency Plans (ECPs) would be implemented. The ECPs for Action and Limit levels exceedances are shown in Table 3-4.

| Station | 1-hour TSP Level in $\mu\text{g}/\text{m}^3$ |             |
|---------|--|-------------|
|         | Action Level                                 | Limit Level |
| ASR 1   | 307  | 500         |
| ASR 3   | 327  | 500         |
| ASR 8   | 337  | 500         |
| ASR 9   | 329  | 500         |

**Table 3-3 Action & Limit Levels for Air Quality**

| EVENT  | ACTION   |  |   |  |
|--|--|--|---|--|
|  | ET   | IEC  | SOR   | CONTRACTOR   |
| <b>ACTION LEVEL</b>                            |  |  |   |  |
| Exceedance for one sample                      | <ul style="list-style-type: none"> <li>Identify source, investigate the causes of exceedance and propose remedial measures;</li> <li>Inform IEC and SOR;</li> <li>Repeat measurement to confirm finding;</li> <li>Increase monitoring frequency to daily.</li> </ul>   | <ul style="list-style-type: none"> <li>Check monitoring data submitted by ET;</li> <li>Check Contractor's working method.</li> </ul>   | <ul style="list-style-type: none"> <li>Notify Contractor.</li> </ul>  | <ul style="list-style-type: none"> <li>Rectify any unacceptable practice;</li> <li>Amend working methods if appropriate.</li> </ul>  |
| Exceedance for two or more consecutive samples | <ul style="list-style-type: none"> <li>Identify source;</li> <li>Inform IEC and SOR;</li> <li>Advise SOR on the effectiveness of the proposed remedial measures;</li> <li>Repeat measurements to confirm findings;</li> <li>Increase monitoring frequency to daily;</li> <li>Discuss with IEC and Contractor on remedial actions required;</li> <li>If exceedance continues, arrange meeting with IEC and SOR;</li> <li>If exceedance stops, cease additional monitoring.</li> </ul> | <ul style="list-style-type: none"> <li>Check monitoring data submitted by ET;</li> <li>Check Contractor's working method;</li> <li>Discuss with ET and Contractor on possible remedial measures;</li> <li>Advise the ET on the effectiveness of the proposed remedial measures;</li> <li>Supervise Implementation of remedial measures.</li> </ul> | <ul style="list-style-type: none"> <li>Confirm receipt of notification of exceedance in writing;</li> <li>Notify Contractor;</li> <li>Ensure remedial measures properly implemented.</li> </ul> | <ul style="list-style-type: none"> <li>Submit proposals for remedial actions to SOR within 3 working days of notification;</li> <li>Implement the agreed proposals;</li> <li>Amend proposal if appropriate.</li> </ul> |
| <b>LIMIT LEVEL</b>                             |  |  |   |  |
| Exceedance for one sample                      | <ul style="list-style-type: none"> <li>Identify source, investigate the causes of exceedance and propose remedial measures;</li> </ul>   | <ul style="list-style-type: none"> <li>Check monitoring data submitted by ET;</li> <li>Check Contractor's working method;</li> <li>Discuss with ET and</li> </ul>  | <ul style="list-style-type: none"> <li>Confirm receipt of notification of exceedance in writing;</li> <li>Notify Contractor;</li> <li>Ensure remedial</li> </ul>                                | <ul style="list-style-type: none"> <li>Take immediate action to avoid further exceedance;</li> <li>Submit proposals for remedial actions to IEC within 3 working</li> </ul>  |

| EVENT  | ACTION  |   |  |   |
|--|---|---|--|---|
|  | ET  | IEC   | SOR  | CONTRACTOR  |
|  | <ul style="list-style-type: none"> <li>• Inform IEC, SOR, Contractor and EPD;</li> <li>• Repeat measurement to confirm finding;</li> <li>• Increase monitoring frequency to daily;</li> <li>• Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and SOR informed of the results.</li> </ul>   | <ul style="list-style-type: none"> <li>• Contractor on possible remedial measures;</li> <li>• Advise SOR on the effectiveness of the proposed remedial measures;</li> <li>• Supervise implementation of remedial measures.</li> </ul>   | <ul style="list-style-type: none"> <li>• measures properly implemented.</li> </ul>   | <ul style="list-style-type: none"> <li>• days of notification;</li> <li>• Implement the agreed proposals;</li> <li>• Amend proposal if appropriate.</li> </ul>  |
| Exceedance for two or more consecutive samples | <ul style="list-style-type: none"> <li>• Notify IEC, SOR, Contractor and EPD;</li> <li>• Identify source;</li> <li>• Repeat measurement to confirm findings;</li> <li>• Increase monitoring frequency to daily;</li> <li>• Carry out analysis of Contractor's working procedures to determine possible mitigation to be implemented;</li> <li>• Arrange meeting with IEC and SOR to discuss the remedial actions to be taken;</li> <li>• Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and SOR informed of the results;</li> <li>• If exceedance stops, cease additional monitoring.</li> </ul> | <ul style="list-style-type: none"> <li>• Discuss amongst SOR, ET, and Contractor on the potential remedial actions;</li> <li>• Review Contractor's remedial actions whenever necessary to assure their effectiveness and advise SOR accordingly;</li> <li>• Supervise the implementation of remedial measures.</li> </ul> | <ul style="list-style-type: none"> <li>• Confirm receipt of notification of exceedance in writing;</li> <li>• Notify Contractor;</li> <li>• In consultation with the IEC, agree with the Contractor on the remedial measures to be implemented;</li> <li>• Ensure remedial measures properly implemented;</li> <li>• If exceedance continues, consider what portion of the work is responsible and instruct the Contractor to stop that portion of work until the exceedance is abated.</li> </ul> | <ul style="list-style-type: none"> <li>• Take immediate action to avoid further exceedance;</li> <li>• Submit proposals for remedial actions to IEC within 3 working days of notification;</li> <li>• Implement the agreed proposals;</li> <li>• Resubmit proposals if problem still not under control;</li> <li>• Stop the relevant portion of works as determined by SOR until the exceedance is abated.</li> </ul> |

**Table 3-4 Event/Action Plan for Air Quality**

## 3.2 Noise

### Noise Parameters

- 3.2.1 The construction noise level was measured in terms of equivalent A-weighted sound pressure level ( $L_{eq}$ ) measured in decibels (dB(A)). Monitoring of  $L_{eq(30 \text{ min})}$  was carried out at the noise monitoring locations on a weekly basis during normal construction working hours (0700-1900 hours from Monday to Saturday except public holidays). For all other time periods (i.e. restricted hours),  $L_{eq(5 \text{ min})}$  would be employed for comparison with the Noise Control Ordinance (NCO) criteria if necessary.
- 3.2.2 The two statistical sound levels  $L_{10}$  and  $L_{90}$ , the level exceeded for 10 and 90 percent of the time respectively, were also recorded during monitoring. Major noise sources observed, both on-site and off-site, were recorded on the field data sheet. All measurements were recorded and presented to the nearest 0.1 dB(A) in this report. Results are presented in Section 4.

### Monitoring Methodology

- 3.2.3 Sound level meters, which comply with the International Electrotechnical Commission Publication 651:1979 (Type 1) and 804:1985 (Type 1) specifications as referred to the Technical Memorandum (TM) issued under the Noise Control Ordinance, were used. Noise levels for the A-weighted levels  $L_{eq(30 \text{ min})}$ ,  $L_{10}$  and  $L_{90}$  were measured throughout the impact monitoring. An average, by sound power, of six consecutive 5-minute readings was used to provide  $L_{eq(30 \text{ min})}$  for non-restricted hours (0700-1900 hours from Monday to Saturday except public holidays). A facade correction of 3 dB(A) was applied to the measurements that were carried out under free field conditions.
- 3.2.4 During the impact monitoring, parameters such as dates, weather condition, equipment used, measurement results and major noise sources were recorded on the field data record sheet. Monitoring would not be carried out in the presence of fog, rain or strong wind with a steady speed exceeding 5 m/s. In relation to the monitored noise levels, other noise sources such as road traffic might make a significant contribution to the overall noise environment. Therefore, noise monitoring activities would take into account such influencing factors, which were not present during the baseline monitoring period.

### Monitoring Equipment and Calibration

- 3.2.5 Rion Precision Sound Level Meters of Type NL-31 and B&K Integrating Sound Level Meter of Type 2238 in compliance with the International Electrotechnical Commission Publication specifications (Paragraph 3.2.3) were used for noise monitoring in this reporting month.
- 3.2.6 Prior to and following each noise measurement, the accuracy of the sound level meters was checked using an acoustic calibrator generating a known sound pressure level at a known frequency. Measurements were considered as valid only if the calibration levels from before and after the noise measurement agreed to within 1.0 dB(A). Sound level meters and calibrators were calibrated annually to ensure they performed to the same level of accuracy as stated in the manufacturer's specifications. The noise monitoring

equipment used during the reporting month are shown in Table 3-5 below. The calibration certificates are included in Appendix F.

| Equipment Type         | Manufacturer | Type Number | Serial Number | Location               |
|------------------------|--------------|-------------|---------------|------------------------|
| Sound Level Meter      | Rion         | NL-31       | 00410224      | NSR1, NSR3,            |
| Sound Level Meter      | B&K          | 2238        | 2448529       | NSR6, NSR8 and<br>NSR9 |
| Sound Level Calibrator | Rion         | NC-73       | 10486660      |                        |
| Sound Level Calibrator | B&K          | 4231        | 2699361       |                        |

**Table 3-5 Noise Monitoring Equipment**

## Monitoring Location

3.2.7 Five designated noise monitoring locations were identified in the contract specific EM&A Manual. They are listed in Table 3-6 below and shown in Appendix G. All the locations below are in facade measurement.

| Monitoring Station ID | Name of Premises                | Floor Level  |
|-----------------------|---------------------------------|--|
| NSR1                  | Sik Sik Yuen Ho Fung College    | G/F  |
| NSR3                  | Hong Hoi Chee Hong Temple       | Podium   |
| NSR6                  | Squatters                       | G/F  |
| NSR8                  | Beach Tower (Long Beach Garden) | G/F  |
| NSR9                  | Greenview Terrace (Block 1)     | Podium (up to 6 July 2009)<br>Roof* (since 16 July 2009) |

\* The noise monitoring location of NSR9 had been adjusted to rooftop since 16 July 2009.

**Table 3-6 Noise Monitoring Locations**

## Action and Limit Levels

3.2.8 The Action and Limit levels for construction noise are defined in Table 3-7. If non-compliance of the criteria occurs, actions in accordance with the Action Plan in Table 3-8 would be carried out.

| Time Period                          | Action                                    | Limit     |
|--------------------------------------|---|-----------|
| 0700 – 1900 hours on normal weekdays | When one documented complaint is received | 75 dB(A)* |

\* For educational establishments the limit level shall be 70 dB(A) and reduced to 65 dB(A) during examination periods between 0700 and 1900 hours on normal weekdays.

**Table 3-7 Action & Limit Levels for Air Borne Noise**



| Event        | Action  |   |  |  |
|--------------|---|---|--|--|
|              | ET Leader   | IEC   | SOR  | Contractor   |
| Action Level | <ul style="list-style-type: none"> <li>• Notify IEC and the Contractor.</li> <li>• Carry out investigation.</li> <li>• Report the results of investigation to IEC and the Contractor.</li> <li>• Discuss with the Contractor and formulate remedial measures.</li> <li>• Increase monitoring frequency to check mitigation measures.</li> </ul>   | <ul style="list-style-type: none"> <li>• Review with analysed results submitted by ET.</li> <li>• Review the proposed remedial measures by the Contractor and advise SOR accordingly.</li> <li>• Supervise the implementation of remedial measures.</li> </ul>  | <ul style="list-style-type: none"> <li>• Confirm receipt of notification of exceedance in writing.</li> <li>• Notify the Contractor.</li> <li>• Require the Contractor to propose remedial measures for the analysed noise problem.</li> <li>• Ensure remedial measures are properly implemented.</li> </ul>   | <ul style="list-style-type: none"> <li>• Submit noise mitigation proposals to IEC.</li> <li>• Implement noise mitigation proposals.</li> </ul>   |
| Limit Level  | <ul style="list-style-type: none"> <li>• Identify the source.</li> <li>• Notify IEC, SOR, EPD and the Contractor.</li> <li>• Repeat measurement to confirm findings.</li> <li>• Increase monitoring frequency.</li> <li>• Carry out analysis of Contractor's working procedures to determine possible mitigation to be implemented.</li> <li>• Inform IEC, SOR, and EPD the causes and actions taken for the exceedances.</li> <li>• Assess effectiveness of the Contractor's remedial actions and keep IEC, EPD and SOR informed of the results.</li> <li>• If exceedance stops, cease additional monitoring.</li> </ul> | <ul style="list-style-type: none"> <li>• Discuss amongst SOR, ET Leader and the Contractor on the potential remedial actions.</li> <li>• Review the Contractor's remedial actions whenever necessary to assure their effectiveness and advise SOR accordingly.</li> <li>• Supervise the implementation of remedial measures.</li> </ul> | <ul style="list-style-type: none"> <li>• Confirm receipt of notification of exceedance in writing.</li> <li>• Notify the Contractor.</li> <li>• Require the Contractor to propose remedial measures for the analysed noise problem.</li> <li>• Ensure remedial measures are properly implemented.</li> <li>• If exceedance continues, consider what activity of the work is responsible and instruct the Contractor to stop that activity of work until the exceedance is abated.</li> </ul> | <ul style="list-style-type: none"> <li>• Take immediate action to avoid further exceedance.</li> <li>• Submit proposals for remedial actions to IEC within 3 working days of notification.</li> <li>• Implement the agreed proposals.</li> <li>• Resubmit proposals if problem still not under control.</li> <li>• Stop the relevant activity of works as determined by the SOR until the exceedance is abated.</li> </ul> |

**Table 3-8 Event/Action Plan for Airborne Noise**

## 3.3 Water Quality

- 3.3.1 The water quality impact would be insignificant with the protection measures recommended in Section 5.6 of the EIA report. However, in view of the sensitive nature of the rivers/streams and bathing beaches near the Project site, it is suggested that a programme of monitoring should be established to confirm the effectiveness of these mitigation measures in protecting these water bodies.

### Water Quality Parameters

- 3.3.2 Monitoring for dissolved oxygen (DO), temperature, turbidity, pH and suspended solids (SS) should be undertaken at designated monitoring locations. It should be noted that DO, temperature, turbidity and pH should be measured in-situ whereas SS is assayed in a laboratory.
- 3.3.3 In association with the water quality parameters, other relevant data should also be measured, such as monitoring location/position, time, weather conditions, and any special phenomena and description of work underway at the construction site etc.

### Monitoring Methodology

- 3.3.4 In accordance with the EM&A Manual, the water quality monitoring for all specified parameters were measured at all designated monitoring locations including control points at an interval of 3 days per week. DO, temperature, turbidity, pH and SS measurements were undertaken at designated monitoring locations.
- 3.3.5 It should be noted that water samples for all monitoring parameters were collected, stored, preserved and analysed according to Standard Methods, APHA 17 ed. and/or methods agreed by the Director of Environmental Protection.
- 3.3.6 Each sample was analysed in accordance with the APHA Standard Methods for the Examination of Water and Wastewater, 18<sup>th</sup> edition, or an equivalent method approved by the EPD. In any circumstance, the sample testing should comply with a comprehensive quality assurance and quality control programme. The laboratory should be prepared to demonstrate the quality programmes to the EPD when requested.

### Monitoring Equipment and Calibration

- 3.3.7 All the water samples collected were transferred to clearly labelled and pre-cleaned sample containers with necessary preservatives immediately after collection. The sample containers were provided by a HOKLAS accredited laboratory. About 1 L of samples was collected for all laboratory analysis. Following sampling, samples should be stored in a cool box at temperature between 0 and 4 °C, and transported to the laboratory within the sample retention time as advised by the laboratory under proper chain-of-custody system. The water quality monitoring equipment used during the reporting month is shown in Table 3-9 below.

| Equipment Type              | Manufacturer | Model             | Quantity |
|-----------------------------|--------------|-------------------|----------|
| DO / Temperature Meter      | YSI          | 55/12             | 1        |
| DO / Temperature Meter / pH | YSI          | Professional Plus | 1        |
| pH Meter                    | Hanna        | HI-8014           | 1        |
| Turbidimeter                | Hanna        | HI 98703-02       | 1        |

**Table 3-9 Water Quality Monitoring Equipment**

- 3.3.8 All in-situ monitoring equipment were checked and calibrated prior to use. They were calibrated by a laboratory accredited under HOKLAS or any other international accreditation scheme, and subsequently re-calibrated at 3 monthly intervals throughout all stages of the water quality monitoring. Responses of sensors and electrodes were checked with certified standard solutions before each use. Wet bulb calibrations for all DO meters were carried out before measurement at each monitoring location. For the on-site calibration of field equipment, BS 127:1993, "Guide to field and on-site test methods for the analysis of waters" was observed. The calibration certificates are included in Appendix F.

## Monitoring Location

- 3.3.9 Five designated impact monitoring locations (three river stations and two marine stations) and five control locations (three river control stations and two marine control stations) were identified in the contract specific EM&A Manual for river and marine water quality monitoring. These monitoring stations are listed in Table 3-10 below and shown in Appendix G.

| Monitoring Station ID | Name of Premises                           |
|-----------------------|--|
| <i>River</i>          |  |
| I-1                   | Intake I-1                                 |
| I-1-C                 | Control of Intake I-1                      |
| I-2                   | Intake I-2                                 |
| I-2-C                 | Control of Intake I-2                      |
| I-3                   | Intake I-3                                 |
| I-3-C*                | Control of Intake I-3                      |
| <i>Marine</i>         |  |
| O-1 (FT) and (ET)     | Outfall O-1 during Flood Tide and Ebb Tide |
| O-1-C (FT)            | Control of Outfall O-1 during Flood Tide   |
| O-1-C (ET)            | Control of Outfall O-1 during Ebb Tide     |

\*The upper stream location (I-3-C\*) had been relocated from end of February 2009 due to coarse stone blockage.

**Table 3-10 Water Quality Monitoring Locations**

- 3.3.10 Note that there were two control stations for Outfall O-1, one for sampling during flood tide and one for sampling during ebb tide. Only one of these control stations for Outfall O-1 was sampled during each sampling. Control station to be sampled was determined based on the tidal information provided by the Hong Kong Observatory.
- 3.3.11 Referring to Section 4.4 of the approved Contract Specific EM&A Manual (Report No. EB000364R0273, dated 6 January 2010), while the construction of the Outfall requires minor dredging, water quality monitoring at the Outfall shall be undertaken during the period of the dredging works. As advised by the Contractor, all relevant marine works at Portion E of the site were completed in April 2012. As such, the ET submitted a proposal to EPD on 30 April 2012 to terminate the marine water quality monitoring effective from 1 May 2012. EPD had no objection to the proposal in their reply on 7 May 2012.

## Action and Limit Levels

- 3.3.12 The Action and Limit levels for water quality monitoring parameters are defined in Table 3-11. In case of any exceedance, appropriate actions would be undertaken in accordance with the Event and Action Plan as described in Table 3-12.

| Parameters                                 | Action  | Limit  |
|--|---|--|
| DO in mg/L<br>(Surface, Middle and Bottom) | <p><u>Surface and Middle</u><br/>5%-ile of baseline data for surface and middle layer.</p> <p><u>Bottom</u><br/>5%-ile of baseline data for bottom layer.</p> | <p><u>Surface and Middle</u><br/>4 mg/L except 5 mg/L for Fish Culture Zone or<br/>1%-ile of baseline data for surface and middle layer</p> <p><u>Bottom</u><br/>2 mg/L or 1%-ile of baseline data for bottom layer</p>          |
| SS in mg/L<br>(depth-averaged)             | 95%-ile of baseline data or 120% of upstream control station's SS at the same tide of the same day  | 99%-ile of baseline or 130% of upstream control station's SS at the same tide of the same day and specific sensitive receiver water quality requirements (e.g. required suspended solids levels for concerned sea water intakes) |
| Turbidity (Tby) in NTU<br>(depth-averaged) | 95%-ile of baseline data or 120% of upstream control station's Tby at the same tide of the same day   | 99%-ile of baseline or 130% of upstream control station's Tby at the same tide of the same day   |

Notes:

- For DO, non-compliance of the water quality limits occurs when monitoring result is lower than the limit.
- For SS and Tby, non-compliance of the water quality limits occurs when monitoring result is higher than the limits.
- All the figures given in the table are used for reference only and the EPD may amend the figures whenever it is considered necessary.

**Table 3-11 Action/Limit Levels for Water Quality**

| Event   | ET Leader  | IEC   | SOR   | Contractor   |
|---|--|---|---|--|
| Action Level being exceeded by one sampling day                       | <ul style="list-style-type: none"> <li>Repeat in-situ measurement to confirm findings;</li> <li>Identify source(s) of impact;</li> <li>Inform IEC and Contractor;</li> <li>Check monitoring data, all plant, equipment and Contractor's working methods;</li> <li>Discuss mitigation measures with IEC and Contractor; and</li> <li>Repeat measurement on next day of exceedance.</li> </ul>   | <ul style="list-style-type: none"> <li>Discuss with ET and Contractor on the mitigation measures;</li> <li>Review proposals on mitigation measures submitted by Contractor and advise the SOR accordingly; and</li> <li>Assess the effectiveness of the implemented mitigation measures.</li> </ul> | <ul style="list-style-type: none"> <li>Discuss with IEC on the proposed mitigation measures; and</li> <li>Make agreement on the mitigation measures to be implemented.</li> </ul>   | <ul style="list-style-type: none"> <li>Inform the SOR and confirm notification of the non-compliance in writing;</li> <li>Rectify unacceptable practice;</li> <li>Check all plant and equipment;</li> <li>Consider changes of working methods;</li> <li>Discuss with ET and IEC and propose mitigation measures to IEC and SOR; and</li> <li>Implement the agreed mitigation measures.</li> </ul>                            |
| Action Level being exceeded by more than one consecutive sampling day | <ul style="list-style-type: none"> <li>Repeat in-situ measurement to confirm findings;</li> <li>Identify source(s) of impact;</li> <li>Inform IEC and Contractor;</li> <li>Check monitoring data, all plant, equipment and Contractor's working methods;</li> <li>Discuss mitigation measures with IEC and Contractor;</li> <li>Ensure mitigation measures are implemented;</li> <li>Prepare to increase the monitoring frequency to daily; and</li> <li>Repeat</li> </ul> | <ul style="list-style-type: none"> <li>Discuss with ET and Contractor on the mitigation measures;</li> <li>Review proposals on mitigation measures submitted by Contractor and advise the SOR accordingly; and</li> <li>Assess the effectiveness of the implemented mitigation measures.</li> </ul> | <ul style="list-style-type: none"> <li>Discuss with IEC on the proposed mitigation measures;</li> <li>Make agreement on the mitigation measures to be implemented; and</li> <li>Assess the effectiveness of the implemented mitigation measures.</li> </ul> | <ul style="list-style-type: none"> <li>Inform the Engineer and confirm notification of the non-compliance in writing;</li> <li>Rectify unacceptable practice;</li> <li>Check all plant and equipment;</li> <li>Consider changes of working methods;</li> <li>Discuss with ET and IEC and propose mitigation measures to IEC and SOR within 3 working days; and</li> <li>Implement the agreed mitigation measures.</li> </ul> |

| Event  | ET Leader  | IEC   | SOR  | Contractor   |
|--|--|---|--|--|
|  | measurement on next day of exceedance.   |   |  |  |
| Limit Level being exceeded by one sampling day                       | <ul style="list-style-type: none"> <li>Repeat in-situ measurement to confirm findings;</li> <li>Identify source(s) of impact;</li> <li>Inform IEC, Contractor and EPD;</li> <li>Check monitoring data, all plant, equipment and Contractor's working methods;</li> <li>Discuss mitigation measures with IEC, SOR and Contractor;</li> <li>Ensure mitigation measures are implemented; and</li> <li>Increase the monitoring frequency to daily until no exceedance of Limit level.</li> </ul> | <ul style="list-style-type: none"> <li>Discuss with ET and Contractor on the mitigation measures;</li> <li>Review proposals on mitigation measures submitted by Contractor and advise the SOR accordingly; and</li> <li>Assess the effectiveness of the implemented mitigation measures.</li> </ul> | <ul style="list-style-type: none"> <li>Discuss with IEC, ET and Contractor on the proposed mitigation measures;</li> <li>Request Contractor to critically review the working methods;</li> <li>Make agreement on the mitigation measures to be implemented; and</li> <li>Assess the effectiveness of the implemented mitigation measures.</li> </ul> | <ul style="list-style-type: none"> <li>Inform the SOR and confirm notification of the non-compliance in writing;</li> <li>Rectify unacceptable practice;</li> <li>Check all plant and equipment;</li> <li>Consider changes of working methods;</li> <li>Discuss with ET, IEC and SOR and propose mitigation measures to IEC and SOR within 3 working days; and</li> <li>Implement the agreed mitigation measures.</li> </ul> |
| Limit Level being exceeded by more than one consecutive sampling day | <ul style="list-style-type: none"> <li>Repeat in-situ measurement to confirm findings;</li> <li>Identify source(s) of impact;</li> <li>Inform IEC, Contractor and EPD;</li> <li>Check monitoring data, all plant, equipment and Contractor's working methods;</li> <li>Discuss mitigation measures with</li> </ul>   | <ul style="list-style-type: none"> <li>Discuss with ET and Contractor on the mitigation measures;</li> <li>Review proposals on mitigation measures submitted by Contractor and advise the SOR accordingly; and</li> <li>Assess the effectiveness of the implemented mitigation</li> </ul>           | <ul style="list-style-type: none"> <li>Discuss with IEC, ET and Contractor on the proposed mitigation measures;</li> <li>Request Contractor to critically review the working methods;</li> <li>Make agreement on the mitigation measures to be implemented;</li> <li>Assess the effectiveness of</li> </ul>  | <ul style="list-style-type: none"> <li>Inform the SOR and confirm notification of the non-compliance in writing;</li> <li>Rectify unacceptable practice;</li> <li>Check all plant and equipment;</li> <li>Consider changes of working methods;</li> <li>Discuss with ET, IEC and SOR and</li> </ul>  |

| Event | ET Leader  | IEC       | SOR  | Contractor   |
|-------|--|-----------|--|--|
|       | IEC, SOR and Contractor;<br><ul style="list-style-type: none"> <li>• Ensure mitigation measures are implemented; and</li> <li>• Increase the monitoring frequency to daily until no exceedance of Limit level for two consecutive days.</li> </ul> | measures. | the implemented mitigation measures; and<br><ul style="list-style-type: none"> <li>• Consider and instruct, if necessary, the Contractor to slow down or to stop all or part of the marine work until no exceedance of Limit Level.</li> </ul> | propose mitigation measures to IEC and SOR within 3 working days;<br><ul style="list-style-type: none"> <li>• Implement the agreed mitigation measures; and</li> <li>• As directed by the SOR, to slow down or to stop all or part of the marine work or construction activities.</li> </ul> |

**Table 3-12 Event/Action Plan for Water Quality**

## 4 MONITORING RESULT

### 4.1 Air Quality

4.1.1 The air quality monitoring schedule of the reporting period is given in Appendix H.

#### 1-hour TSP Monitoring

4.1.2 Results of 1-hour TSP level are shown in Table 4-1. All measurements were recorded and presented to the nearest  $0.1 \mu\text{g}/\text{m}^3$  in this report. Detailed results including weather conditions and graphical presentations are presented in Appendix I.

| Station   | Monitoring Date | Monitoring Result ( $\mu\text{g}/\text{m}^3$ ) | Action/Limit Levels ( $\mu\text{g}/\text{m}^3$ ) |
|-----------|-----------------|--|--|
| ASR 1     | 3-May-13        | 64.0   | 307/500  |
|           |                 | 72.7   |  |
|           |                 | 75.1   |  |
|           | 8-May-13        | 92.4   |  |
|           |                 | 83.7   |  |
|           |                 | 87.4   |  |
|           | 14-May-13       | 85.0   |  |
|           |                 | 76.3   |  |
|           |                 | 98.5   |  |
|           | 20-May-13       | 98.5   |  |
|           |                 | 87.4   |  |
|           |                 | 80.0   |  |
|           | 24-May-13       | 76.3   |  |
|           |                 | 61.6   |  |
|           |                 | 44.3   |  |
| 30-May-13 | 69.7            |  |  |
|           | 72.3            |  |  |
|           | 50.0            |  |  |
| ASR 3     | 3-May-13        | 121.4  | 327/500  |
|           |                 | 110.4  |  |
|           |                 | 78.5   |  |
|           | 8-May-13        | 66.2   |  |
|           |                 | 76.0   |  |
|           |                 | 155.8  |  |



| Station | Monitoring Date | Monitoring Result<br>( $\mu\text{g}/\text{m}^3$ ) | Action/Limit Levels<br>( $\mu\text{g}/\text{m}^3$ ) |
|---------|-----------------|---|---|
|         |                 | 100.6   |   |
|         | 14-May-13       | 72.4  |   |
|         |                 | 63.8  |   |
|         | 20-May-13       | 105.5   |   |
|         |                 | 127.6   |   |
|         |                 | 83.4  |   |
|         | 24-May-13       | 93.2  |   |
|         |                 | 99.4  |   |
|         |                 | 45.4  |   |
|         | 30-May-13       | 71.2  |   |
|         |                 | 72.6  |   |
|         |                 | 67.0  |   |
|         |                 | 41.1  |   |
|         | 3-May-13        | 66.8  |   |
|         |                 | 33.4  |   |
|         | 8-May-13        | 98.9  |   |
|         |                 | 96.3  |   |
|         |                 | 82.2  |   |
|         | 14-May-13       | 79.6  |   |
|         |                 | 65.5  |   |
|         |                 | 60.4  |   |
| ASR 8   | 20-May-13       | 73.2  | 337/500   |
|         |                 | 92.5  |   |
|         |                 | 83.5  |   |
|         | 24-May-13       | 75.8  |   |
|         |                 | 70.6  |   |
|         |                 | 98.9  |   |
|         | 30-May-13       | 71.7  |   |
|         |                 | 64.8  |   |
|         |                 | 56.5  |   |
|         |                 | 63.3  |   |
| ASR 9   | 3-May-13        | 98.4  | 329/500   |
|         |                 | 80.9  |   |

| Station | Monitoring Date | Monitoring Result ( $\mu\text{g}/\text{m}^3$ ) | Action/Limit Levels ( $\mu\text{g}/\text{m}^3$ ) |
|---------|-----------------|--|--|
|         |                 | 144.2  |  |
|         | 8-May-13        | 94.3   |  |
|         |                 | 87.6   |  |
|         | 14-May-13       | 60.7   |  |
|         |                 | 83.6   |  |
|         |                 | 55.3   |  |
|         | 20-May-13       | 82.2   |  |
|         |                 | 94.3   |  |
|         |                 | 118.6  |  |
|         | 24-May-13       | 55.3   |  |
|         |                 | 109.2  |  |
|         |                 | 75.5   |  |
|         | 30-May-13       | 77.4   |  |
|         |                 | 65.0   |  |
|         |                 | 76.1   |  |

Note: *Italic* indicates the occurrence of exceedance of *Action level*

**Bold** indicates the occurrence of exceedance of **Limit Level**

**Table 4-1 Air Quality Monitoring Results**

4.1.3 No project related air quality exceedance was recorded in the reporting month.

## 4.2 Noise

### Air Borne Noise Monitoring

4.2.2 The air borne noise monitoring schedule of the reporting period is given in Appendix H. Results of measured noise level, in terms of  $L_{eq(30min)}$ , during the construction are shown in Table 4-2. All measurements including  $L_{10}$  and  $L_{90}$  are recorded and presented to the nearest 0.1 dB(A) in this report. Detailed results including weather conditions and graphical presentation are presented in Appendix I.

| Station | Monitoring Date | $L_{eq(30min)}$ dB(A) | Limit Levels dB(A) |
|---------|-----------------|-----------------------|--------------------|
| NSR 1   | 8-May-13        | 63.6                  | 70                 |
|         | 14-May-13       | 63.7                  |                    |
|         | 20-May-13       | 64.7                  |                    |
|         | 30-May-13       | 64.0                  |                    |
| NSR 3   | 8-May-13        | 60.5                  | 75                 |
|         | 14-May-13       | 61.6                  |                    |
|         | 20-May-13       | 61.2                  |                    |

| Station | Monitoring Date | $L_{eq}$ (30 min) dB(A) | Limit Levels dB(A) |
|---------|-----------------|-------------------------|--------------------|
| NSR 6   | 30-May-13       | 61.7                    |                    |
|         | 8-May-13        | 63.8                    |                    |
|         | 14-May-13       | 59.4                    |                    |
|         | 20-May-13       | 57.4                    |                    |
|         | 30-May-13       | 62.0                    |                    |
| NSR 8   | 8-May-13        | 64.5                    |                    |
|         | 14-May-13       | 63.9                    |                    |
|         | 20-May-13       | 62.6                    |                    |
|         | 30-May-13       | 64.3                    |                    |
| NSR 9   | 8-May-13        | 72.9                    |                    |
|         | 14-May-13       | 65.7                    |                    |
|         | 20-May-13       | 65.0                    |                    |
|         | 30-May-13       | 66.5                    |                    |

**Table 4-2 Air Borne Noise Monitoring Results**

4.2.3 No project related noise exceedance was recorded in the reporting month.

## 4.3 Water Quality Monitoring

4.3.1 The water quality monitoring schedule of the reporting period is given in Appendix H. Summaries of exceedances for water quality monitoring are provided in Table 4-3 to Table 4-5.

| Parameter | Action Level Exceedance          | Limit Level Exceedance           |
|-----------|----------------------------------|----------------------------------|
| DO        | Nil                              | Nil                              |
| Turbidity | One record at I-1 on 22 May 2013 | Nil                              |
| SS        | One record at I-1 on 18 May 2013 | One record at I-1 on 22 May 2013 |
| Total     | 2                                | 1                                |

**Table 4-3 Summary of Exceedances for I-1**

| Parameter | Action Level Exceedance | Limit Level Exceedance           |
|-----------|-------------------------|----------------------------------|
| DO        | Nil                     | Nil                              |
| Turbidity | Nil                     | One record at I-2 on 22 May 2013 |
| SS        | Nil                     | One record at I-2 on 22 May 2013 |
| Total     | 0                       | 2                                |

**Table 4-4 Summary of Exceedances for I-2**

| Parameter | Action Level Exceedance | Limit Level Exceedance                            |
|-----------|-------------------------|---|
| DO        | Nil                     | Nil   |
| Turbidity | Nil                     | Two records at I-3 on 22 May 2013 and 29 May 2013 |
| SS        | Nil                     | Nil   |
| Total     | 0                       | 2   |

**Table 4-5 Summary of Exceedances for I-3**

4.3.2 Results of measured water quality parameters during the reporting month are shown in Table 4-6. Detailed results including weather conditions and graphical presentations are enclosed in Appendix I.

## River Water Quality Monitoring

- 4.3.3 Seven exceedances were recorded for the river water quality monitoring within the reporting month.

### Exceedances of Turbidity Level

#### Action Level at I-1 on 22 May 2013

- 4.3.4 One exceedance of turbidity action level was recorded at I-1 on 22 May 2013. The measured turbidity level (11.25 NTU) was higher than the baseline action level, but lower than the turbidity level (11.45 NTU) of the upstream control station (I-1-C). Details of the construction activities conducted on the monitoring day are given in Appendix J. No direct disturbance was observed from the site. Heavy Rain was observed and about 205 mm rainfall was recorded at Tsuen Wan by the Hong Kong Observatory between 0:45 to 16:45 on the monitoring day. Therefore, the exceedance was considered to be contributed by heavy rainfall and high turbidity level at upstream location. Since the exceedance was non-project related, no further action was required.

#### Limit Level at I-2 on 22 May 2013

- 4.3.5 One exceedance of turbidity limit level was recorded at I-2 on 22 May 2013. The measured turbidity level (32.05 NTU) was higher than the baseline limit level, but lower than the turbidity level (32.25 NTU) of the upstream control station (I-2-C). Details of the construction activities conducted on the monitoring day are given in Appendix J. No direct disturbance was observed from the site. Heavy Rain was observed and about 205 mm rainfall was recorded at Tsuen Wan by the Hong Kong Observatory between 0:45 to 16:45 on the monitoring day. Therefore, the exceedance was considered to be contributed by heavy rainfall and high turbidity level at upstream location. Since the exceedance was non-project related, no further action was required.

#### Limit Level at I-3 on 22 May 2013

- 4.3.6 One exceedance of turbidity limit level was recorded at I-3 on 22 May 2013. The measured turbidity level (6.76 NTU) was higher than the baseline limit level, but lower than the turbidity level (6.91 NTU) of the upstream control station (I-3-C). Details of the construction activities conducted on the monitoring day are given in Appendix J. No direct disturbance was observed from the site. Heavy Rain was observed and about 205 mm rainfall was recorded at Tsuen Wan by the Hong Kong Observatory between 0:45 to 16:45 on the monitoring day. Therefore, the exceedance was considered to be contributed by heavy rainfall and high turbidity level at upstream location. Since the exceedance was non-project related, no further action was required.

#### Limit Level at I-3 on 29 May 2013

- 4.3.7 One exceedance of turbidity limit level was recorded at I-3 on 29 May 2013. The measured turbidity level (4.73 NTU) was higher than the baseline limit level, but lower than 120% of the turbidity level (4.62 NTU) of the upstream control station (I-3-C).

Details of the construction activities conducted on the monitoring day are given in Appendix J. No direct disturbance was observed from the site. Therefore, the exceedance was considered to be contributed by natural variation. Since the exceedance was non-project related, no further action was required.

## Exceedances of Suspended Solids Level

### Action Level at I-1 on 18 May 2013

- 4.3.8 One exceedance of SS action level was recorded at I-1 on 18 May 2013. The measured SS level (5.35 mg/L) was lower than the baseline action level, but higher than 120% of the SS level (4.45 mg/L) of the upstream control station (I-1-C). Details of the construction activities conducted on the monitoring day are given in Appendix J. No direct disturbance was observed from the site. Therefore, the exceedance was considered to be contributed by natural variation. Since the exceedance was non-project related, no further action was required.

### Limit Level at I-1 on 22 May 2013

- 4.3.9 One exceedance of SS limit level was recorded at I-1 on 22 May 2013. The measured SS level (16.65 mg/L) was higher than the baseline limit level, and higher than 130% of the SS level (10.35 mg/L) of the upstream control station (I-1-C). Details of the construction activities conducted on the monitoring day are given in Appendix J. No direct disturbance was observed from the site. Heavy Rain was observed and about 205 mm rainfall was recorded at Tsuen Wan by the Hong Kong Observatory between 0:45 to 16:45 on the monitoring day. Therefore, the exceedance was considered to be contributed by heavy rainfall and high turbidity level at upstream location. Since the exceedance was non-project related, no further action was required.

### Limit Level at I-2 on 22 May 2013

- 4.3.10 One exceedance of SS limit level was recorded at I-2 on 22 May 2013. The measured SS level (19.40 mg/L) was higher than the baseline limit level, but lower than the SS level (22.70 mg/L) of the upstream control station (I-2-C). Details of the construction activities conducted on the monitoring day are given in Appendix J. No direct disturbance was observed from the site. Heavy Rain was observed and about 205 mm rainfall was recorded at Tsuen Wan by the Hong Kong Observatory between 0:45 to 16:45 on the monitoring day. Therefore, the exceedance was considered to be contributed by heavy rainfall and high turbidity level at upstream location. Since the exceedance was non-project related, no further action was required.

| Station | Date      | Temperature (°C) | DO (mg/L) | Action/Limit Level for DO (mg/L) | pH   | Turbidity (NTU) | Action/Limit Level for Turbidity (NTU) | SS (mg/L)    | Action/Limit Level for SS (mg/L) |
|---------|-----------|------------------|-----------|----------------------------------|------|-----------------|--|--------------|----------------------------------|
| I-1     | 2-May-13  | 25.80            | 7.69      | 3.42 / 3.34                      | 7.85 | 7.45            | 9.75 / 12.47                           | 4.55         | 8.85 / 10.17                     |
|         | 4-May-13  | 24.90            | 8.20      |                                  | 7.96 | 4.31            |  | 3.00         |                                  |
|         | 6-May-13  | 24.80            | 9.19      |                                  | 7.86 | 3.09            |  | <2.00        |                                  |
|         | 8-May-13  | 24.60            | 8.07      |                                  | 7.70 | 2.68            |  | <2.00        |                                  |
|         | 10-May-13 | 25.20            | 7.93      |                                  | 7.74 | 3.45            |  | <2.00        |                                  |
|         | 13-May-13 | 26.20            | 7.86      |                                  | 7.70 | 2.72            |  | 2.95         |                                  |
|         | 15-May-13 | 26.00            | 8.02      |                                  | 7.80 | 4.76            |  | <2.00        |                                  |
|         | 18-May-13 | 26.10            | 7.88      |                                  | 7.75 | 3.88            |  | 5.35         |                                  |
|         | 20-May-13 | 25.60            | 8.05      |                                  | 7.80 | 3.58            |  | 2.20         |                                  |
|         | 22-May-13 | 23.60            | 7.85      |                                  | 7.90 | <b>11.25</b>    |  | <b>16.65</b> |                                  |
|         | 24-May-13 | 26.50            | 8.68      |                                  | 7.95 | 5.44            |  | 2.30         |                                  |
|         | 27-May-13 | 25.50            | 8.28      |                                  | 7.76 | 4.21            |  | 2.75         |                                  |
|         | 29-May-13 | 26.60            | 8.20      |                                  | 7.98 | 3.61            |  | <2.00        |                                  |
|         | 31-May-13 | 27.70            | 8.22      |                                  | 7.80 | 3.46            |  | <2.00        |                                  |

Note: *Italic* indicates the occurrence of exceedance of *Action level*. **Bold** indicates the occurrence of exceedance of **Limit level**

| Station | Date      | Temperature (°C) | DO (mg/L) | Action/Limit Level for DO (mg/L) | pH   | Turbidity (NTU) | Action/Limit Level for Turbidity (NTU) | SS (mg/L) | Action/Limit Level for SS (mg/L) |
|---------|-----------|------------------|-----------|----------------------------------|------|-----------------|--|-----------|----------------------------------|
| I-1-C   | 2-May-13  | 25.90            | 7.71      | - / -                            | 7.85 | 7.65            | - / -                                  | 4.20      | - / -                            |
|         | 4-May-13  | 25.00            | 8.12      |                                  | 7.96 | 4.53            |  | 2.75      |                                  |
|         | 6-May-13  | 24.80            | 9.11      |                                  | 7.86 | 3.24            |  | <2.00     |                                  |
|         | 8-May-13  | 24.60            | 7.99      |                                  | 7.70 | 2.59            |  | <2.00     |                                  |
|         | 10-May-13 | 25.20            | 7.99      |                                  | 7.74 | 3.58            |  | <2.00     |                                  |
|         | 13-May-13 | 26.20            | 7.97      |                                  | 7.70 | 2.79            |  | 2.70      |                                  |
|         | 15-May-13 | 26.00            | 8.11      |                                  | 7.80 | 4.85            |  | <2.00     |                                  |
|         | 18-May-13 | 26.10            | 7.82      |                                  | 7.75 | 3.84            |  | 4.45      |                                  |
|         | 20-May-13 | 25.60            | 8.13      |                                  | 7.80 | 3.48            |  | 2.30      |                                  |
|         | 22-May-13 | 23.60            | 7.77      |                                  | 7.90 | 11.45           |  | 10.35     |                                  |
|         | 24-May-13 | 26.50            | 8.62      |                                  | 7.95 | 5.60            |  | 2.40      |                                  |
|         | 27-May-13 | 25.50            | 8.20      |                                  | 7.76 | 4.05            |  | 2.45      |                                  |
|         | 29-May-13 | 26.60            | 8.12      |                                  | 7.98 | 3.50            |  | <2.00     |                                  |
|         | 31-May-13 | 27.70            | 8.17      |                                  | 7.80 | 3.37            |  | <2.00     |                                  |

Note: *Italic* indicates the occurrence of exceedance of *Action level*. **Bold** indicates the occurrence of exceedance of **Limit level**



| Station | Date      | Temperature (°C) | DO (mg/L) | Action/Limit Level for DO (mg/L) | pH   | Turbidity (NTU) | Action/Limit Level for Turbidity (NTU) | SS (mg/L)    | Action/Limit Level for SS (mg/L) |
|---------|-----------|------------------|-----------|----------------------------------|------|-----------------|--|--------------|----------------------------------|
| I-2     | 2-May-13  | 26.00            | 7.76      | 3.66 / 3.63                      | 7.86 | 1.36            | 6.63 / 6.99                            | <2.00        | 7.68 / 8.34                      |
|         | 4-May-13  | 24.90            | 8.06      |                                  | 7.95 | 4.14            |  | 2.75         |                                  |
|         | 6-May-13  | 24.90            | 8.95      |                                  | 7.81 | 1.46            |  | <2.00        |                                  |
|         | 8-May-13  | 24.60            | 8.11      |                                  | 7.78 | 1.16            |  | <2.00        |                                  |
|         | 10-May-13 | 25.10            | 7.80      |                                  | 7.76 | 4.66            |  | 2.50         |                                  |
|         | 13-May-13 | 26.30            | 7.77      |                                  | 7.72 | 1.33            |  | <2.00        |                                  |
|         | 15-May-13 | 26.10            | 7.89      |                                  | 7.80 | 1.32            |  | <2.00        |                                  |
|         | 18-May-13 | 26.00            | 7.95      |                                  | 7.77 | 1.22            |  | 2.85         |                                  |
|         | 20-May-13 | 25.70            | 8.28      |                                  | 7.76 | 1.23            |  | <2.00        |                                  |
|         | 22-May-13 | 23.70            | 7.92      |                                  | 7.86 | <b>32.05</b>    |  | <b>19.40</b> |                                  |
|         | 24-May-13 | 26.30            | 8.45      |                                  | 7.90 | 2.01            |  | <2.00        |                                  |
|         | 27-May-13 | 25.60            | 8.06      |                                  | 7.80 | 2.78            |  | 2.25         |                                  |
|         | 29-May-13 | 26.80            | 8.30      |                                  | 7.95 | 6.38            |  | 2.35         |                                  |
|         | 31-May-13 | 27.80            | 8.02      |                                  | 7.85 | 1.38            |  | <2.00        |                                  |

Note: *Italic* indicates the occurrence of exceedance of *Action level*. **Bold** indicates the occurrence of exceedance of **Limit level**

| Station   | Date      | Temperature (°C) | DO (mg/L)   | Action/Limit Level for DO (mg/L) | pH          | Turbidity (NTU) | Action/Limit Level for Turbidity (NTU) | SS (mg/L) | Action/Limit Level for SS (mg/L) |
|-----------|-----------|------------------|-------------|----------------------------------|-------------|-----------------|--|-----------|----------------------------------|
| I-2-C     | 2-May-13  | 26.00            | 7.83        | - / -                            | 7.86        | 1.42            | - / -                                  | <2.00     | - / -                            |
|           | 4-May-13  | 24.90            | 8.18        |                                  | 7.95        | 4.23            |  | 3.45      |                                  |
|           | 6-May-13  | 24.90            | 8.99        |                                  | 7.81        | 1.50            |  | <2.00     |                                  |
|           | 8-May-13  | 24.60            | 8.07        |                                  | 7.78        | 1.19            |  | <2.00     |                                  |
|           | 10-May-13 | 25.10            | 7.85        |                                  | 7.76        | 4.99            |  | 2.70      |                                  |
|           | 13-May-13 | 26.30            | 7.91        |                                  | 7.72        | 1.35            |  | <2.00     |                                  |
|           | 15-May-13 | 26.10            | 7.95        |                                  | 7.80        | 1.25            |  | <2.00     |                                  |
|           | 18-May-13 | 26.00            | <i>7.77</i> |                                  | <i>7.77</i> | 1.24            |  | 3.15      |                                  |
|           | 20-May-13 | 25.70            | 8.22        |                                  | 7.76        | 1.29            |  | <2.00     |                                  |
|           | 22-May-13 | 23.70            | 7.94        |                                  | 7.86        | 32.25           |  | 22.70     |                                  |
|           | 24-May-13 | 26.30            | 8.53        |                                  | 7.91        | 1.97            |  | <2.00     |                                  |
|           | 27-May-13 | 25.60            | 8.13        |                                  | 7.79        | 2.88            |  | <2.00     |                                  |
|           | 29-May-13 | 26.80            | 8.22        |                                  | 7.95        | 6.57            |  | 2.25      |                                  |
| 31-May-13 | 27.80     | 8.10             |             | 7.85                             | 1.43        |                 | 2.00                                   |           |                                  |

Note: *Italic* indicates the occurrence of exceedance of *Action level*. **Bold** indicates the occurrence of exceedance of **Limit level**

| Station | Date      | Temperature (°C) | DO (mg/L) | Action/Limit Level for DO (mg/L) | pH   | Turbidity (NTU) | Action/Limit Level for Turbidity (NTU) | SS (mg/L) | Action/Limit Level for SS (mg/L) |
|---------|-----------|------------------|-----------|----------------------------------|------|-----------------|--|-----------|----------------------------------|
| I-3     | 2-May-13  | 25.90            | 8.01      | 3.65 / 3.51                      | 7.85 | 1.30            | 3.99 / 4.18                            | <2.00     | 6.13 / 7.23                      |
|         | 4-May-13  | 24.90            | 8.12      |                                  | 7.95 | 3.62            |  | 2.95      |                                  |
|         | 6-May-13  | 24.80            | 8.96      |                                  | 7.85 | 1.75            |  | <2.00     |                                  |
|         | 8-May-13  | 24.50            | 7.87      |                                  | 7.77 | 1.76            |  | <2.00     |                                  |
|         | 10-May-13 | 25.10            | 8.02      |                                  | 7.78 | 1.88            |  | <2.00     |                                  |
|         | 13-May-13 | 26.30            | 8.08      |                                  | 7.77 | 1.91            |  | <2.00     |                                  |
|         | 15-May-13 | 26.10            | 7.97      |                                  | 7.86 | 2.06            |  | <2.00     |                                  |
|         | 18-May-13 | 26.00            | 7.93      |                                  | 7.76 | 2.02            |  | 3.15      |                                  |
|         | 20-May-13 | 25.80            | 8.12      |                                  | 7.75 | 1.71            |  | <2.00     |                                  |
|         | 22-May-13 | 23.70            | 7.85      |                                  | 7.07 | <b>6.76</b>     |  | 3.65      |                                  |
|         | 24-May-13 | 26.30            | 8.42      |                                  | 7.90 | 3.22            |  | <2.00     |                                  |
|         | 27-May-13 | 25.60            | 8.09      |                                  | 7.80 | 3.70            |  | <2.00     |                                  |
|         | 29-May-13 | 26.80            | 8.16      |                                  | 7.96 | <b>4.73</b>     |  | <2.00     |                                  |
|         | 31-May-13 | 27.70            | 8.25      |                                  | 7.84 | 2.28            |  | 2.30      |                                  |

Note: *Italic* indicates the occurrence of exceedance of *Action level*. **Bold** indicates the occurrence of exceedance of **Limit level**

| Station | Date      | Temperature (°C) | DO (mg/L) | Action/Limit Level for DO (mg/L) | pH   | Turbidity (NTU) | Action/Limit Level for Turbidity (NTU) | SS (mg/L) | Action/Limit Level for SS (mg/L) |
|---------|-----------|------------------|-----------|----------------------------------|------|-----------------|--|-----------|----------------------------------|
| I-3-C   | 2-May-13  | 25.90            | 7.95      | - / -                            | 7.85 | 1.24            | - / -                                  | <2.00     | - / -                            |
|         | 4-May-13  | 24.90            | 8.00      |                                  | 7.95 | 3.75            |  | 3.05      |                                  |
|         | 6-May-13  | 24.80            | 8.88      |                                  | 7.85 | 1.71            |  | <2.00     |                                  |
|         | 8-May-13  | 24.50            | 7.91      |                                  | 7.77 | 1.71            |  | 2.25      |                                  |
|         | 10-May-13 | 25.10            | 7.94      |                                  | 7.78 | 1.82            |  | <2.00     |                                  |
|         | 13-May-13 | 26.30            | 8.03      |                                  | 7.77 | 1.95            |  | <2.00     |                                  |
|         | 15-May-13 | 26.00            | 7.86      |                                  | 7.86 | 2.12            |  | <2.00     |                                  |
|         | 18-May-13 | 26.00            | 7.89      |                                  | 7.76 | 2.06            |  | 4.35      |                                  |
|         | 20-May-13 | 25.80            | 8.19      |                                  | 7.75 | 1.82            |  | <2.00     |                                  |
|         | 22-May-13 | 23.70            | 7.74      |                                  | 7.85 | 6.91            |  | 3.20      |                                  |
|         | 24-May-13 | 26.30            | 8.53      |                                  | 7.90 | 3.43            |  | <2.00     |                                  |
|         | 27-May-13 | 25.60            | 8.17      |                                  | 7.80 | 3.95            |  | <2.00     |                                  |
|         | 29-May-13 | 26.80            | 8.08      |                                  | 7.96 | 4.62            |  | <2.00     |                                  |
|         | 31-May-13 | 27.70            | 8.20      |                                  | 7.84 | 2.28            |  | 2.20      |                                  |

Note: *Italic* indicates the occurrence of exceedance of *Action level*. **Bold** indicates the occurrence of exceedance of **Limit level**

**Table 4-6 Water Quality Monitoring Results**

## 4.4 Summary of Project-Related Exceedances

4.4.1 Table 4-7 summarises the project-related exceedance results recorded in May 2013. Note that exceedances that are considered not related to the construction activities are not included in this table.

| Environmental Monitoring | Total No. of Measurement | Action Level Exceedance | % of Action Level Exceedance | Limit Level Exceedance | % of Limit Level Exceedance |
|--------------------------|--------------------------|-------------------------|------------------------------|------------------------|-----------------------------|
| Air Quality              | 72                       | 0                       | 0                            | 0                      | 0                           |
| Air Borne Noise          | 20                       | 0                       | 0                            | 0                      | 0                           |
| Water                    | 84                       | 0                       | 0                            | 0                      | 0                           |

Note: Exceedances that are considered not related to the construction activities are not included in this table.

**Table 4-7 Summary of Project-Related Exceedances**

## 5 WASTE MANAGEMENT

5.1.1 The status of waste management is summarised in Table 5-1.

| Status of waste management   | Quantity |
|--|----------|
| Inert C&D Material Disposed to Public Fill at Tuen Mun (m <sup>3</sup> ) | 1789.8   |
| Inert C&D Material Reused in this Contract (m <sup>3</sup> )             | 0        |
| Inert C&D Material Reused in other Contract(s) (m <sup>3</sup> )         | 0        |
| Metals Generated (kg)  | 23       |
| Paper / Cardboard Packaging (kg)   | 400      |
| Plastics (kg)  | 20       |
| Chemical Waste (kg)  | 0        |
| General Waste Disposed of to NENT Landfill (m <sup>3</sup> )             | 25.7     |

**Table 5-1 Waste Generated in May 2013**

## 6 NON-COMPLIANCE AND DEFICIENCY

### 6.1 Site Audit by ET

6.1.1 ET has carried out two site inspections in the reporting month. All observations together with the appropriate recommended mitigation measures where necessary were recorded in the audit checklists that were passed to the Contractor. Major environmental deficiencies observed during site inspections / audits and recommendation, which were made by the ET, are summarised in Table 6-1 below. No non-compliance was observed.

| Inspection Date | Observation | Recommendation | Status |
|-----------------|-------------|----------------|--------|
| 9 May<br>2013   | Nil         | Nil            | Nil    |
| 23 May<br>2013  | Nil         | Nil            | Nil    |

**Table 6-1 Site Inspections by ET**

## 7 COMPLAINT

- 7.1.1 A complaint hotline at **9850 3241** of the Contractor has been established for the Project.
- 7.1.2 No environmental complaint was received during the reporting month.
- 7.1.3 Details of the past complaint investigation and observations can also be referred to Appendix K.
- 7.1.4 Cumulative statistics of environmental complaints are shown in Table 7-1.

| Complaints Received in the Reporting Month | Cumulative Number of Complaints |
|--|---------------------------------|
| 0  | 27                              |

**Table 7-1 Cumulative Statistics of Environmental Complaints**



## 8 SUMMARY OF NOTIFICATION OF SUMMONS, SUCCESSFUL PROSECUTIONS AND CORRECTIVE ACTIONS

8.1.1 No summons and successful prosecution was received during the reporting month.

8.1.2 Cumulative statistics of notification of summons, successful prosecutions and convictions are shown in Table 8-1.

| Notification of Summons |            | Successful Prosecution and Conviction |            |
|-------------------------|------------|---------------------------------------|------------|
| May 2013                | Cumulative | May 2013                              | Cumulative |
| 0                       | 0          | 0                                     | 0          |

**Table 8-1 Cumulative Statistics of Notification of Summons and Successful Prosecutions and Convictions**

## 9 FUTURE KEY ISSUE


9.1.1 The forecast of construction works for the upcoming three months are:

- Site cleaning and tidying at Outfall, I-1, I-2 and I-3;
- Construction of RC structures of Outfall "W" at Outfall;
- Slope reinstatement Works at Outfall;
- Backfilling on top of box culvert at Outfall;
- Finishing works for spiral ramp at Outfall;
- Construction of surface drainage at Outfall;
- Installation of GRP panels of spiral ramp and miscellaneous steel works at Outfall;
- Landscape works at Outfall;
- Installation of additional irrigation system at Outfall and I-1;
- Excavation and construction of permanent access road and associated drainage at I-3;
- Installation of stone facing for vortex shaft at I-3;
- Construction of access platform and associated drainage next to man access shaft at I-2;
- Tiling works for man access shaft at I-2; and
- Reinstatement of site entrance and installation of fencing and railing at I-1.

## Appendix A

---

### Site Map and Works Area



**Key Plan:**

**Notes:**

1. CO-ORDINATES REFER TO HONG KONG METRIC GRID (1980).
2. ALL LEVELS ARE IN METRES ABOVE PRINCIPAL DATUM (P.D.).
3. ALL DIMENSIONS ARE IN MILLIMETRES UNLESS OTHERWISE STATED.

**Key to symbols**

**LEGENDS :**

- TUNNEL ALIGNMENT
- INTAKE/OUTFALL STRUCTURES

|     |        |       |                 |          |           |
|-----|--------|-------|-----------------|----------|-----------|
| B1  | MAR 05 | EL    | FOR EMAA MANUAL | <i>M</i> | <i>De</i> |
| Rev | Date   | Drawn | Description     | Ch'kd    | App'd     |

Client

The Government of the Hong Kong  
Special Administrative Region  
Drainage Services Department

Consulting Engineers  
**Mott Connell Ltd.**  
in Association with  
MVA Hong Kong Ltd EDAW Earth Asia Ltd Environmental Resources  
WL/Delft Hydraulics Ltd Chesterton Petty Ltd Management

Project  
**Drainage Improvement in  
Tsuen Wan and Kwai Chung -  
Tsuen Wan Drainage Tunnel -  
Investigation**

Title  
**TUNNEL ALIGNMENT  
AND SURROUNDING AREA**

|             |  |           |          |     |           |
|-------------|--|-----------|----------|-----|-----------|
| Designed    | CF   | <i>cf</i> | Eng.Chk. | MT  | <i>M</i>  |
| Drawn       | HL   | HL        | Approved | TMC | <i>De</i> |
| Dwg.Chk.    | KN   | <i>KN</i> | Scale    |     |           |
| Project     | 204417   |           |          |     | Status    |
| CAD file    | J:\204417\DRAWING\FIGURE EMAA MANUAL\FIGURE1.1.dgn |           |          |     |           |
| Drawing No. | FIGURE 1.1   |           |          |     | Rev 01    |


© COPYRIGHT RESERVED

This document should not be relied on or used in circumstances other than those for which it was originally prepared and for which Mott Connell Ltd was commissioned. Mott Connell Ltd accepts no responsibility for this document to any other party other than the person by whom it was commissioned.

## Appendix B

---

### Organization Chart



## Appendix C

---

# Construction Programme

| ID                        | Activity Description                   | WP10 Dur | WP09 Dur | WP10 Start | WP10 Finish | % Comp | WP09 Start | WP09 Finish | Total Float | 2012      |                                      |    |    |           |    |    |    |               |    |    |    | 2013      |    |    |    |               |    |    |    |         |    |    |    | 2014 |    |    |    |    |    |    |    |    |  |  |  | 2015 |  |  |  |  |  |  |  |  |  |  |  |  |
|---------------------------|--|----------|----------|------------|-------------|--------|------------|-------------|-------------|-----------|--------------------------------------|----|----|-----------|----|----|----|---------------|----|----|----|-----------|----|----|----|---------------|----|----|----|---------|----|----|----|------|----|----|----|----|----|----|----|----|--|--|--|------|--|--|--|--|--|--|--|--|--|--|--|--|
|                           |  |          |          |            |             |        |            |             |             | A S O N D |                                      |    |    | J F M A M |    |    |    | J J A S O N D |    |    |    | J F M A M |    |    |    | J J A S O N D |    |    |    | J F M A |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
|                           |  |          |          |            |             |        |            |             |             | 63        | 64                                   | 65 | 66 | 67        | 68 | 69 | 70 | 71            | 72 | 73 | 74 | 75        | 76 | 77 | 78 | 79            | 80 | 81 | 82 | 83      | 84 | 85 | 86 | 87   | 88 | 89 | 90 | 91 | 92 | 93 | 94 | 95 |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| <b>Preliminaries</b>      |  |          |          |            |             |        |            |             |             |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| <b>Project Dates</b>      |  |          |          |            |             |        |            |             |             |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R0000002                | Tender Issue Date                      | 0        | 0        | 26JUN07A   |             | 100    | 26JUN07A   |             |             |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R0000004                | Tender Closing Date                    | 0        | 0        | 05OCT07A   |             | 100    | 05OCT07A   |             |             |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R0000006                | Letter of Acceptance Issued Date       | 0        | 0        | 14DEC07A   |             | 100    | 14DEC07A   |             |             |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R0000008                | Contract Commencement Date             | 0        | 0        | 28DEC07A   |             | 100    | 28DEC07A   |             |             |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R0000010                | Completion of Section 1 of the Works   | 0        | 0        |            | 28MAR14     | 0      |            | 29APR13     | -836        |           | Contract completion date on 13/12/11 |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R0000012                | Completion of Section 2 of the Works   | 0        | 0        |            | 06SEP11A    | 100    |            | 06SEP11A    |             |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R0000014                | Completion of Section 3 of the Works   | 0        | 0        |            | 03AUG11A    | 100    |            | 03AUG11A    |             |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R0000016                | Completion of Section 4 of the Works   | 0        | 0        |            | 11AUG11A    | 100    |            | 11AUG11A    |             |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R0000018                | Completion of Section 5 of the Works   | 0        | 0        |            | 19SEP11A    | 100    |            | 19SEP11A    |             |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R0000020                | Completion of Section 6 of the Works   | 0        | 0        |            | 16AUG12A    | 100    |            | 14SEP12     |             |           | Contract completion date on 29/07/11 |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R0000022                | Completion of Section 7 of the Works   | 0        | 0        |            | 06NOV14     | 0      |            | 29APR14     | -713        |           | Contract completion date on 23/11/12 |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| <b>Possession of Area</b> |  |          |          |            |             |        |            |             |             |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R00A0102                | Possession Portion A - 90d of DOC      | 0        | 0        | 27FEB08A   |             | 100    | 27FEB08A   |             |             |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R00A0104                | Handover of Portion A                  | 0        | 0        |            | 07MAR14     | 0      |            | 12DEC12     | -815        |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R00B0102                | Possession of Portion B - 90d of DOC   | 0        | 0        | 07MAR08A   |             | 100    | 07MAR08A   |             |             |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R00B0104                | Handover of Portion B                  | 0        | 0        |            | 14MAR14     | 0      |            | 22MAR13     | -822        |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R00C0102                | Possession of Portion C - 90d of DOC   | 0        | 0        | 26MAR08A   |             | 100    | 26MAR08A   |             |             |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R00C0104                | Handover of Portion C                  | 0        | 0        |            | 14MAR14     | 0      |            | 16APR13     | -822        |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R00D0102                | Possession of Portion D on DOC         | 0        | 0        | 28DEC07A   |             | 100    | 28DEC07A   |             |             |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R00D0104                | Handover of Portion D                  | 0        | 0        |            | 06NOV13     | 0      |            | 29APR13     | -694        |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R00E0102                | Possession of Portion E - 650d of DOC  | 0        | 0        | 09JUL09A   |             | 100    | 09JUL09A   |             |             |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R00E0104                | Handover of Portion E                  | 0        | 0        |            | 06NOV13     | 0      |            | 29APR13     | -694        |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R00F0102                | Possession of Portion F on DOC         | 0        | 0        | 28DEC07A   |             | 100    | 28DEC07A   |             |             |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R00F0104                | Handover of Portion F                  | 0        | 0        |            | 28MAR14     | 0      |            | 09MAR13     | -836        |           | After Tunnel commission              |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R00G0102                | Possession of Portion G - 700d of DOC  | 0        | 0        | 26NOV09A   |             | 100    | 26NOV09A   |             |             |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R00G0104                | Handover of Portion G                  | 0        | 0        |            | 07NOV12     | 0      |            | 14SEP12     | 857         |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R00I0102                | Possession of Portion I on DOC         | 0        | 0        | 28DEC07A   |             | 100    | 28DEC07A   |             |             |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R00I0104                | Handover of Portion I                  | 0        | 0        |            | 06NOV14     | 0      |            | 29APR14     | 0           |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R00J0102                | Possession of Portion J                | 0        | 0        | 15MAR15    |             | 0      | 29JUN14    |             | 0           |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R00J0104                | Handover of Portion J                  | 0        | 0        |            | 23NOV11A    | 100    |            | 23NOV11A    |             |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R0H10102                | Possession of Portion H1 on DOC        | 0        | 0        | 28DEC07A   |             | 100    | 28DEC07A   |             |             |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R0H10104                | Handover of Portion H1                 | 0        | 0        |            | 05JAN15     | 0      |            | 28JUN14     | 0           |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |
| 01R0H20102                | Possession of Portion H2 - 300d of DOC | 0        | 0        | 04NOV08A   |             | 100    | 04NOV08A   |             |             |           |                                      |    |    |           |    |    |    |               |    |    |    |           |    |    |    |               |    |    |    |         |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |  |  |  |

Start Date 29JUN07  
 Finish Date 14MAR15  
 Data Date 28AUG12  
 Run Date 19SEP12 11:47

Early Bar  
 Target Bar  
 Progress Bar  
 Critical Activity

WP10 **Maeda-CREC-SELI JV**  
**CONTRACT NO. DC/2007/12**  
**Design and Construction of**  
**Tsuen Wan Drainage Tunnel**  
**Works Programme**

Sheet 1 of 66

| WP10    |          |         |          |
|---------|----------|---------|----------|
| Date    | Revision | Checked | Approved |
| 05SEP11 | WP8A     |         |          |
| 09MAR12 | WP09     |         |          |
| 13SEP12 | WP10     |         |          |
|         |          |         |          |







| ID   | Activity Description                             | WP10 Dur | WP09 Dur | WP10 Start | WP10 Finish | % Comp | WP09 Start | WP09 Finish | Total Float | 2012 |    |    |    | 2013 |    |    |    | 2014 |    |    |    | 2015 |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
|--|--|----------|----------|------------|-------------|--------|------------|-------------|-------------|------|----|----|----|------|----|----|----|------|----|----|----|------|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|
|  |  |          |          |            |             |        |            |             |             | A    | S  | O  | N  | D    | J  | F  | M  | A    | M  | J  | J  | A    | S  | O  | N  | D  | J  | F  | M  | A  | M  | J  | J  | A  | S  | O  | N  | D  | J  | F  | M  | A  |
|  |  |          |          |            |             |        |            |             |             | 63   | 64 | 65 | 66 | 67   | 68 | 69 | 70 | 71   | 72 | 73 | 74 | 75   | 76 | 77 | 78 | 79 | 80 | 81 | 82 | 83 | 84 | 85 | 86 | 87 | 88 | 89 | 90 | 91 | 92 | 93 | 94 | 95 |
| 17R0000902   | Fulfill all relevant environmental obligation    | 1,950    | 1,950    | 28DEC07A   | 14MAR14     | 84     | 28DEC07A   | 29APR13     | 0           |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| <b>Excavation Permit/Utilities per SCC 54 &amp; SCC 83</b> |  |          |          |            |             |        |            |             |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001002   | Nominate IIUMS co-ordinator                      | 7        | 7        | 14DEC07A   | 15JAN08A    | 100    | 14DEC07A   | 15JAN08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001004   | SO approve IIUMS co-ordinator                    | 14       | 14       | 16JAN08A   | 29FEB08A    | 100    | 16JAN08A   | 29FEB08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001006   | Submit brand name of UGS detection equipment     | 7        | 7        | 28DEC07A   | 18FEB08A    | 100    | 28DEC07A   | 18FEB08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001008   | Utilities detection & report to the SO           | 21       | 21       | 29FEB08A   | 05APR08A    | 100    | 29FEB08A   | 05APR08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001010   | Liaison with UUs                                 | 21       | 21       | 04JAN08A   | 29FEB08A    | 100    | 04JAN08A   | 29FEB08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001012   | Apply XP for site entrance construction          | 7        | 7        | 21JAN08A   | 08MAR08A    | 100    | 21JAN08A   | 08MAR08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001014   | HyD process XP for site entrance construction    | 20       | 20       | 10MAR08A   | 28MAY08A    | 100    | 10MAR08A   | 28MAY08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001016   | HyD issue XP for site entrance construction      | 0        | 0        |            | 28MAY08A    | 100    |            | 28MAY08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001018   | Apply XP for GI works at I-1 & I-2               | 1        | 1        | 22APR08A   | 20MAY08A    | 100    | 22APR08A   | 20MAY08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001020   | HyD process XP for GI works at I-1 & I-2         | 30       | 30       | 23APR08A   | 26SEP08A    | 100    | 23APR08A   | 26SEP08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001022   | HyD issue XP for GI works at I-1 & I-2           | 0        | 0        |            | 26SEP08A    | 100    |            | 26SEP08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001024   | Apply XP for trial grout at Fault F1             | 1        | 1        | 22APR08A   | 20MAY08A    | 100    | 22APR08A   | 20MAY08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001026   | HyD process XP for trial grout at Fault F1       | 30       | 30       | 23APR08A   | 22JUL08A    | 100    | 23APR08A   | 22JUL08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001028   | HyD issue XP for trial grout at Fault F1         | 0        | 0        |            | 22JUL08A    | 100    |            | 22JUL08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| <b>Pre-construction Condition Survey</b>                   |  |          |          |            |             |        |            |             |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| <b>Preliminaries</b>                                       |  |          |          |            |             |        |            |             |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001102   | Appoint a Qualified Structural Engineer          | 30       | 30       | 28DEC07A   | 19MAR08A    | 100    | 28DEC07A   | 19MAR08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001104   | Submit nos. & extent of the affected EBS         | 30       | 30       | 28DEC07A   | 19MAR08A    | 100    | 28DEC07A   | 19MAR08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| <b>PCS Stage 1 between I-1 &amp; I-2</b>                   |  |          |          |            |             |        |            |             |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001118   | Carry out stg 1 PCS between I-1 & I-2            | 6        | 6        | 22APR08A   | 23APR08A    | 100    | 22APR08A   | 23APR08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001120   | Prepare/submit reports for stg 1 PCS bet I-1&I-2 | 60       | 60       | 24APR08A   | 22SEP08A    | 100    | 24APR08A   | 22SEP08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001122   | Review/accept reports for stg 1 PCS bet I-1&I-2  | 60       | 60       | 31MAY08A   | 20JAN09A    | 100    | 31MAY08A   | 20JAN09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| <b>PCS Stage 1 between I-2 &amp; I-3</b>                   |  |          |          |            |             |        |            |             |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001130   | Carry out stg 1 PCS between I-2 & I-3            | 5        | 5        | 25MAR08A   | 30APR08A    | 100    | 25MAR08A   | 30APR08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001132   | Prepare/submit reports for stg 1 PCS bet I-2&I-3 | 60       | 60       | 24APR08A   | 22SEP08A    | 100    | 24APR08A   | 22SEP08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001134   | Review/accept reports for stg 1 PCS bet I-2&I-3  | 60       | 60       | 24MAY08A   | 04FEB09A    | 100    | 24MAY08A   | 04FEB09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| <b>PCS Stage 1 between I-3 &amp; O-1</b>                   |  |          |          |            |             |        |            |             |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001142   | Carry out stg 1 PCS between I-3 & O-1            | 5        | 5        | 25MAR08A   | 26MAR08A    | 100    | 25MAR08A   | 26MAR08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001144   | Prepare/submit reports for stg 1 PCS bet I-3&O-1 | 60       | 60       | 26MAR08A   | 11SEP08A    | 100    | 26MAR08A   | 11SEP08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001146   | Review/accept reports for stg 1 PCS bet I-3&O-1  | 60       | 60       | 31MAY08A   | 04FEB09A    | 100    | 31MAY08A   | 04FEB09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| <b>PCS Stage 1 at vicinity of O-1</b>                      |  |          |          |            |             |        |            |             |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001106   | Carry out stg 1 PCS at vicinity of O-1           | 5        | 5        | 25MAR08A   | 29MAR08A    | 100    | 25MAR08A   | 29MAR08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001108   | Prepare/submit reports for stg 1 PCS at O-1      | 60       | 60       | 31MAR08A   | 10SEP08A    | 100    | 31MAR08A   | 10SEP08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001110   | Review/accept reports for stg 1 PCS at O-1       | 60       | 60       | 27MAY08A   | 09FEB09A    | 100    | 27MAY08A   | 09FEB09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| <b>PCS Stage 2 between I-1 &amp; I-2</b>                   |  |          |          |            |             |        |            |             |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001124   | Carry out stg 2 PCS between I-1 & I-2            | 5        | 5        | 22APR08A   | 02JUN08A    | 100    | 22APR08A   | 02JUN08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001126   | Prepare/submit reports for stg 2 PCS bet I-1&I-2 | 60       | 60       | 24APR08A   | 10JUN08A    | 100    | 24APR08A   | 10JUN08A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 01R0001128   | Review/accept reports for stg 2 PCS bet I-1&I-2  | 60       | 60       | 11JUN08A   | 09FEB09A    | 100    | 11JUN08A   | 09FEB09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |























































































| ID  | Activity Description                              | WP10 Dur | WP09 Dur | WP10 Start | WP10 Finish | % Comp | WP09 Start | WP09 Finish | Total Float | 2012                                    |    |    |    |    |    |    |    |    |    |    |    | 2013 |    |    |    |    |    |    |    |    |    |    |    | 2014 |    |    |    |    |    |    |    |    |  |  |  | 2015 |  |  |  |  |  |  |  |  |  |
|---|---|----------|----------|------------|-------------|--------|------------|-------------|-------------|---|----|----|----|----|----|----|----|----|----|----|----|------|----|----|----|----|----|----|----|----|----|----|----|------|----|----|----|----|----|----|----|----|--|--|--|------|--|--|--|--|--|--|--|--|--|
|   |   |          |          |            |             |        |            |             |             | A                                       | S  | O  | N  | D  | J  | F  | M  | A  | M  | J  | J  | A    | S  | O  | N  | D  | J  | F  | M  | A  | M  | J  | J  | A    | S  | O  | N  | D  | J  | F  | M  | A  |  |  |  |      |  |  |  |  |  |  |  |  |  |
|   |   |          |          |            |             |        |            |             |             | 63                                      | 64 | 65 | 66 | 67 | 68 | 69 | 70 | 71 | 72 | 73 | 74 | 75   | 76 | 77 | 78 | 79 | 80 | 81 | 82 | 83 | 84 | 85 | 86 | 87   | 88 | 89 | 90 | 91 | 92 | 93 | 94 | 95 |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 05L1BI2818  | Construct wall & crown                            | 20       | 20       | 03OCT12    | 26OCT12     | 0      | 11AUG12    | 03SEP12     | -377        |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| <b>Junction Between Main Tunnel &amp; Adit Tunnel</b> |   |          |          |            |             |        |            |             |             |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 3BL1BI2100  | Remove TBM services/delivery of steel arches      | 0        | 0        |            | 24APR12A    | 100    |            | 03MAY12     |             |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 3BL1BI2106  | Install steel arches from main tunnel             | 19       | 24       | 25APR12A   | 18MAY12A    | 100    | 04MAY12    | 31MAY12     |             |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 3BL1BI2107  | Excavate (breathrough);2m                         | 69       | 32       | 09JUL12A   | 26SEP12     | 45     | 14JUL12    | 20AUG12     | -377        |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 3BL1BI2108  | Construct invert                                  | 8        | 8        | 05OCT12    | 13OCT12     | 0      | 21AUG12    | 29AUG12     | -363        |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 3BL1BI2118  | Construct wall & crown                            | 34       | 34       | 15OCT12    | 23NOV12     | 0      | 30AUG12    | 09OCT12     | -343        |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 3BL1BI2128  | Remove steel arches                               | 6        | 6        | 24NOV12    | 30NOV12     | 0      | 10OCT12    | 16OCT12     | -343        |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| <b>Remaining Works Prior to Handover</b>              |   |          |          |            |             |        |            |             |             |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| <b>Radio Communication System</b>                     |   |          |          |            |             |        |            |             |             |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| VO180I205   | Construct equipment room                          | 18       | 18       | 20NOV12    | 10DEC12     | 0      | 03DEC12    | 22DEC12     | -345        |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| VO180I210   | Lay tiles on equipment room                       | 12       | 12       | 11DEC12    | 24DEC12     | 0      | 24DEC12    | 09JAN13     | -345        |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| VO180I215   | Install radio communication system                | 18       | 18       | 27DEC12    | 17JAN13     | 0      | 10JAN13    | 30JAN13     | -345        |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 08R1BI2102  | Finishing & reinstatement works; Portion B        | 36       | 36       | 22JAN14    | 07MAR14     | 0      | 30JAN13    | 15MAR13     | -679        |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 08R1BI2103  | Pre-handover inspections and remedial works       | 30       | 30       | 08FEB14    | 14MAR14     | 0      | 16FEB13    | 22MAR13     | -679        |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 16R7BI2102  | Landscaping works at Portion B                    | 30       | 30       | 15APR13    | 21MAY13     | 0      | 16FEB13    | 22MAR13     | -466        |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 16R7BI2104  | Establishment Works at Portion B                  | 365      | 365      | 22MAY13    | 21MAY14     | 0      | 23MAR13    | 22MAR14     | -576        |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| <b>Schedule of Milestones for Cost Centre No. 3bL</b> |   |          |          |            |             |        |            |             |             |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 3BL1BI2A02  | 3bL 1; On establishing tunnelling equipments      | 0        | 0        |            | 20FEB12A    | 100    |            | 20FEB12A    |             |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 3BL1BI2A04  | 3bL 2; On completion of 12.5% perm. tunnel lining | 0        | 0        |            | 20OCT12     | 0      |            | 27JUL12     | 875         | ◆ for Adit Tunnel at Intake I-2         |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 3BL1BI2A06  | 3bL 3; On completion of 25% perm. tunnel lining   | 0        | 0        |            | 29OCT12     | 0      |            | 03AUG12     | 866         | ◆ for Adit Tunnel at Intake I-2         |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 3BL1BI2A08  | 3bL 4; On completion of 37.5% perm. tunnel lining | 0        | 0        |            | 05NOV12     | 0      |            | 10AUG12     | 859         | ◆ for Adit Tunnel at Intake I-2         |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 3BL1BI2A10  | 3bL 5; On completion of 50% perm. tunnel lining   | 0        | 0        |            | 12NOV12     | 0      |            | 17AUG12     | 852         | ◆ for Adit Tunnel at Intake I-2         |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 3BL1BI2A12  | 3bL 6; On completion of 62.5% perm. tunnel lining | 0        | 0        |            | 19NOV12     | 0      |            | 24AUG12     | 845         | ◆ for Adit Tunnel at Intake I-2         |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 3BL1BI2A14  | 3bL 7; On completion of 75% perm. tunnel lining   | 0        | 0        |            | 26NOV12     | 0      |            | 31AUG12     | 838         | ◆ for Adit Tunnel at Intake I-2         |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 3BL1BI2A16  | 3bL 8; On completion of 87.5% perm. tunnel lining | 0        | 0        |            | 03DEC12     | 0      |            | 07SEP12     | 831         | ◆ for Adit Tunnel at Intake I-2         |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 3BL1BI2A18  | 3bL 9; On completion of perm. tunnel lining       | 0        | 0        |            | 24DEC12     | 0      |            | 28SEP12     | 810         | ◆ for Adit Tunnel at Intake I-2         |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 3BL1BI2A20  | 3bL 10; On completion of all works under this CC  | 0        | 0        |            | 24DEC12     | 0      |            | 16OCT12     | 810         | ◆ under this Cost Centre                |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| <b>Schedule of Milestones for Cost Centre No. 5L</b>  |   |          |          |            |             |        |            |             |             |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 05L1BI2M02  | 5L 1; On completion of 25% of excavation          | 0        | 0        |            | 27MAY11A    | 100    |            | 27MAY11A    |             |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 05L1BI2M04  | 5L 2; On completion of 50% of excavation          | 0        | 0        |            | 27DEC11A    | 100    |            | 27DEC11A    |             |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 05L1BI2M06  | 5L 3; On completion of 75% of excavation          | 0        | 0        |            | 14MAR12A    | 100    |            | 14MAR12     |             |   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 05L1BI2M08  | 5L 4; On completion of all excavation             | 0        | 0        |            | 26SEP12     | 0      |            | 20AUG12     | 899         | ◆ below G.L. except for Adit Intake I-2 |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 05L1BI2M10  | 5L 5; On completion of drop shaft & vortex shaft  | 0        | 0        |            | 17NOV12     | 0      |            | 29NOV12     | 847         | ◆ vortex shaft at Intake I-2            |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 05L1BI2M12  | 5L 6; On completion of de-aeration chamber        | 0        | 0        |            | 05OCT12     | 0      |            | 27NOV12     | 890         | ◆ chamber at Intake I-2                 |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 05L1BI2M14  | 5L 7; On completion of air vent shaft             | 0        | 0        |            | 11JAN13     | 0      |            | 29JAN13     | 792         | ◆ shaft at Intake I-2                   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 05L1BI2M16  | 5L 8; On completion of man access shaft           | 0        | 0        |            | 10DEC12     | 0      |            | 09FEB13     | 824         | ◆ shaft at Intake I-2                   |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |
| 05L1BI2M18  | 5L 9; On completion of man access adit            | 0        | 0        |            | 09FEB13     | 0      |            | 21MAY12     | 763         | ◆ adit at Intake I-2                    |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |      |    |    |    |    |    |    |    |    |  |  |  |      |  |  |  |  |  |  |  |  |  |





| ID   | Activity Description                           | WP10 Dur | WP09 Dur | WP10 Start | WP10 Finish | % Comp | WP09 Start | WP09 Finish | Total Float | 2012 |    |    |    | 2013 |    |    |    | 2014 |    |    |    | 2015 |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
|--|--|----------|----------|------------|-------------|--------|------------|-------------|-------------|------|----|----|----|------|----|----|----|------|----|----|----|------|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|
|  |  |          |          |            |             |        |            |             |             | A    | S  | O  | N  | D    | J  | F  | M  | A    | M  | J  | J  | A    | S  | O  | N  | D  | J  | F  | M  | A  | M  | J  | J  | A  | S  | O  | N  | D  | J  | F  | M  |
|  |  |          |          |            |             |        |            |             |             | 63   | 64 | 65 | 66 | 67   | 68 | 69 | 70 | 71   | 72 | 73 | 74 | 75   | 76 | 77 | 78 | 79 | 80 | 81 | 82 | 83 | 84 | 85 | 86 | 87 | 88 | 89 | 90 | 91 | 92 | 93 | 94 |
| VO-095-02  | Green slope arrangement as per VO# 095         | 24       | 24       | 15MAY13    | 13JUN13     | 0      | 04DEC12    | 03JAN13     | -473        |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| <b>Preliminary Works for Works included VO#043</b>     |  |          |          |            |             |        |            |             |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO043-010  | Receive VO for revising design                 | 0        | 0        |            | 02FEB09A    | 100    |            | 02FEB09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO043-020  | Recieve amendment to VO#043                    | 0        | 0        |            | 05MAY09A    | 100    |            | 05MAY09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO043-030  | Procurement of lean mix concrete               | 12       | 12       | 06MAY09A   | 14MAY09A    | 100    | 06MAY09A   | 14MAY09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO043-040  | Testing & approval of lean mix concrete        | 18       | 18       | 15MAY09A   | 06JUN09A    | 100    | 15MAY09A   | 06JUN09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| <b>Mass Wall to Protect Retained Trees; VO #043</b>    |  |          |          |            |             |        |            |             |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO043-120  | Setting out at site                            | 69       | 69       | 03FEB09A   | 28APR09A    | 100    | 03FEB09A   | 28APR09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO043-130  | Excavate & muck out manually; 50m @ 4m/day     | 2        | 2        | 29APR09A   | 30APR09A    | 100    | 29APR09A   | 30APR09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO043-140  | Erect formwork; 70m2 @ 14m2/day                | 5        | 5        | 04MAY09A   | 08MAY09A    | 100    | 04MAY09A   | 08MAY09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO043-150  | Set up for concreting                          | 2        | 2        | 08MAY09A   | 09MAY09A    | 100    | 08MAY09A   | 09MAY09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO043-160  | Pour concrete & removal of formwork            | 2        | 2        | 09MAY09A   | 11MAY09A    | 100    | 09MAY09A   | 11MAY09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| <b>Ch.460 to 370; VO# 043</b>                          |  |          |          |            |             |        |            |             |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO043-060  | Bulk excavation for benching;1061 @ 45m3/day   | 12       | 12       | 29MAY09A   | 09JUL09A    | 100    | 29MAY09A   | 09JUL09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO043-070  | Fill & compaction; 39 layers @ 1 day/layer     | 39       | 39       | 08JUN09A   | 09JUL09A    | 100    | 08JUN09A   | 09JUL09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| <b>Ch. 370 to Ch. 270; VO #043</b>                     |  |          |          |            |             |        |            |             |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO043-090  | Excavation for access road Ch. 370 to 310      | 4        | 4        | 07AUG09A   | 15AUG09A    | 100    | 07AUG09A   | 15AUG09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO043-100  | Bulk excavation for benching; Ch. 310 to 270   | 7        | 7        | 28AUG09A   | 05SEP09A    | 100    | 28AUG09A   | 05SEP09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO043-110  | Fill & compaction lean mix concrete; 15 layers | 7        | 7        | 07SEP09A   | 09SEP09A    | 100    | 07SEP09A   | 09SEP09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| <b>Works On &amp; Above Access Road; Ch. 460-270</b>   |  |          |          |            |             |        |            |             |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 09R1CI3610   | Temporary concrete paving & curing             | 16       | 16       | 21AUG09A   | 11SEP09A    | 100    | 21AUG09A   | 11SEP09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 09R1CI3620   | Excavation of slope batter above access road   | 135      | 135      | 13JUL09A   | 19DEC09A    | 100    | 13JUL09A   | 19DEC09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| <b>Ch. 270 to Ch. 210</b>                              |  |          |          |            |             |        |            |             |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 09R1CI3624   | Excavation & soil nailing                      | 54       | 54       | 03AUG09A   | 17NOV09A    | 100    | 03AUG09A   | 17NOV09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 09R1CI3626   | Backfill (grade 200) & compaction              | 3        | 3        | 18NOV09A   | 20NOV09A    | 100    | 18NOV09A   | 20NOV09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| <b>Ch. 210 to Ch. 130</b>                              |  |          |          |            |             |        |            |             |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 09R1CI3630   | Excavation as per conforming design            | 48       | 48       | 12DEC08A   | 11MAY09A    | 100    | 12DEC08A   | 11MAY09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 09R1CI3632   | Temporary road paving from Ch. 270 to 100      | 7        | 7        | 11MAR10A   | 12MAR10A    | 100    | 11MAR10A   | 12MAR10A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO-084-02  | VO#084 revising the design received            | 0        | 0        | 12MAY09A   |             | 100    | 12MAY09A   |             |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO-084-12  | Works resumed as per VO #084                   | 0        | 0        | 16MAY09A   |             | 100    | 16MAY09A   |             |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO-084-22  | Excavate slope profile as per VO#084           | 34       | 34       | 16MAY09A   | 25JUN09A    | 100    | 16MAY09A   | 25JUN09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO-084-26  | Remove excavated material off site; 6000m3     | 18       | 18       | 07OCT09A   | 29OCT09A    | 100    | 07OCT09A   | 29OCT09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO-084-32  | Soil nailing at Ch. 198 to 210                 | 4        | 4        | 13NOV09A   | 17NOV09A    | 100    | 13NOV09A   | 17NOV09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO-084-42  | Excavate to access road formation              | 26       | 26       | 23NOV09A   | 10MAR10A    | 100    | 23NOV09A   | 10MAR10A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO-127-02  | VO#127 received                                | 0        | 0        |            | 26NOV09A    | 100    |            | 26NOV09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO-127-12  | Excavation & formation                         | 24       | 24       | 30NOV09A   | 29DEC09A    | 100    | 30NOV09A   | 29DEC09A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO-127-22  | Permanent soil nailing #24                     | 18       | 18       | 30DEC09A   | 22JAN10A    | 100    | 30DEC09A   | 22JAN10A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| VO-127-32  | Placing grade 200 rockfill                     | 6        | 6        | 23JAN10A   | 26JAN10A    | 100    | 23JAN10A   | 26JAN10A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| <b>Ch. 130 to Ch. 0; up to Temp. Access to Wall PB</b> |  |          |          |            |             |        |            |             |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 09R1CI3634   | 55 deg. cut slope & soil nailing               | 62       | 62       | 27OCT09A   | 27MAR10A    | 100    | 27OCT09A   | 27MAR10A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 09R1CI3636   | Temporary access to wall PB                    | 15       | 15       | 22JAN10A   | 27MAR10A    | 100    | 22JAN10A   | 27MAR10A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 09R1CI3646   | 10# additional soil nails instructed by SOR    | 0        | 0        |            | 25JAN10A    | 100    |            | 25JAN10A    |             |      |    |    |    |      |    |    |    |      |    |    |    |      |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |















































## Appendix D

---

# Implementation Status of Environmental Mitigation Measures

## IMPLEMENTATION SCHEDULE      May 2013

| EIA Ref.           | Recommended Mitigation Measures  | Who to implement the measure ? | Location of the measure | What requirements or standards for the measure to achieve ? | Status   |
|--------------------|--|--------------------------------|-------------------------|---|--|
| <b>Air Quality</b> |  |                                |                         |   |  |
| 3.6.1              | <p data-bbox="293 384 1218 523"><b>Specific</b><br/>As mentioned in Section 3.5, exceedances of 1-hour and 24-hour average TSP guideline levels have been predicted at most of the ASRs. Hence, mitigation measures are considered necessary in order to suppress the potential dust impact.</p> <p data-bbox="293 528 1218 667">The dust suppression measures set out in the <i>Air Pollution Control (Construction Dust) Regulation</i>, in fact, are more extensive. Therefore, it is expected that with watering the construction site every four times daily together with strict implementation of dust suppression measures as stipulated in the <i>Air Pollution Control (Construction Dust) Regulation</i>, the dust level is expected to be reduced by over 75%.</p> <p data-bbox="293 671 1218 890"><b>General</b><br/>To further ensure compliance with the guideline and AQO limit at the ASRs at all time, it is recommended to implement the <i>Air Pollution Control (Construction Dust) Regulation</i> and include good site practice in the contract clauses to minimize cumulative dust impact. In addition, a comprehensive dust monitoring and audit programme is recommended to ensure proper implementation of the identified mitigation measures. Details of the monitoring and audit requirements are provided in a separate EM&amp;A Manual.</p> <ul data-bbox="293 895 1218 1235" style="list-style-type: none"> <li>• effective dust screens, sheeting or netting should be provided to enclose the scaffolding from the ground floor level of the building or if a canopy is provided at the first floor level, from the first floor level, up to the highest level of the scaffolding where a scaffolding is erected around the perimeter of a building under construction;</li> <li>• dump truck for material transport should be totally enclosed by impervious sheeting;</li> <li>• any excavated dusty materials or stockpile of dusty materials should be covered entirely by impervious sheeting or sprayed with water so as to maintain the entire surface wet, and recovered or backfilled or reinstated within 24 hours of the excavation or unloading;</li> <li>• stockpile of dusty materials should not extend beyond the pedestrian barriers, fencing or traffic cones;</li> <li>• dusty materials remaining after a stockpile is removed should be wetted with water and cleared from the surface of roads;</li> </ul> | DSD's Contractor               | Construction Work Sites | Air Pollution Control (Construction Dust) Regulation        | <p data-bbox="1928 384 2096 523">✓</p> <p data-bbox="1928 528 2096 667">✓</p> <p data-bbox="1928 671 2096 890">N/A</p> <p data-bbox="1928 895 2096 1034">✓</p> <p data-bbox="1928 1038 2096 1177">✓</p> <p data-bbox="1928 1182 2096 1235">✓</p> |

## Appendix D

| EIA Ref.     | Recommended Mitigation Measures   | Who to implement the measure ? | Location of the measure | What requirements or standards for the measure to achieve ? | Status |
|--------------|---|--------------------------------|-------------------------|---|--------|
| 3.6.1        | <ul style="list-style-type: none"> <li>• the area where vehicle washing takes place and the section of the road between the washing facilities and the exit point should be paved with concrete, bituminous materials or hardcores;</li> </ul>                                | DSD's Contractor               | Construction Work Sites | Air Pollution Control (Construction Dust) Regulation        | ✓      |
|              | <ul style="list-style-type: none"> <li>• where a site boundary adjoins a road, street or other area accessible to the public, hoarding of not less than 2.4m high from ground level should be provided along the entire length except for a site entrance or exit;</li> </ul> |                                |                         |   | ✓      |
|              | <ul style="list-style-type: none"> <li>• every main haul road should be sealed with concrete and kept clear of dusty materials or sprayed with water so as to maintain the entire road surface wet;</li> </ul>  |                                |                         |   | ✓      |
|              | <ul style="list-style-type: none"> <li>• the portion of road leading only to a construction site that is within 30m of a designated vehicle entrance or exit should be kept clear of dusty materials;</li> </ul>  |                                |                         |   | ✓      |
|              | <ul style="list-style-type: none"> <li>• stockpile of dusty materials should be either covered entirely by impervious sheeting, placed in an area sheltered on the top and the 3 sides; or sprayed with water so as to maintain the entire surface wet;</li> </ul>            |                                |                         |   | ✓      |
|              | <ul style="list-style-type: none"> <li>• all dusty materials should be sprayed with water prior to any loading, unloading or transfer operation so as to maintain the dusty material wet;</li> </ul>  |                                |                         |   | ✓      |
|              | <ul style="list-style-type: none"> <li>• vehicle speed should be limited to 10 kph except on completed access roads;</li> </ul>   |                                |                         |   | ✓      |
|              | <ul style="list-style-type: none"> <li>• every vehicle should be washed to remove any dusty materials from its body and wheels before leaving the construction sites;</li> </ul>  |                                |                         |   | ✓      |
|              | <ul style="list-style-type: none"> <li>• the load of dusty materials carried by vehicle leaving a construction site should be covered entirely by clean impervious sheeting to ensure that the dusty materials do not leak from the vehicle; and</li> </ul>                   |                                |                         |   | ✓      |
|              | <ul style="list-style-type: none"> <li>• the working area of excavation should be sprayed with water immediately before, during and immediately after the operations so as to maintain the entire surface wet.</li> </ul>   |                                |                         |   | ✓      |
| <b>Noise</b> |   |                                |                         |   |        |
| 4.6.1        | <b>During Construction</b>  | DSD's Contractor               | Construction Work Sites | PN 2/93 Noise from Construction Activities & EIAO           |        |
|              | Appropriate mitigation measures such as the use of quiet equipment and movable barriers will be developed to ensure that noise can be reduced to acceptable levels without causing programme delays   |                                |                         |   | ✓      |
|              | <i>Good Site Practice</i><br>Good site practice and noise management can significantly reduce the impact of construction site activities on nearby NSRs. The following package of measures should be followed during construction:  |                                |                         |   |        |
|              | <ul style="list-style-type: none"> <li>• only well-maintained plant should be operated on-site and plant should be serviced regularly during the construction works;</li> </ul>   |                                |                         |   | ✓      |
|              | <ul style="list-style-type: none"> <li>• machines and plant that may be in intermittent use should be shut down between work periods or should be throttled down to a minimum;</li> </ul>   |                                |                         |   | ✓      |

## Appendix D

| EIA Ref.             | Recommended Mitigation Measures   | Who to implement the measure ? | Location of the measure | What requirements or standards for the measure to achieve ?                                   | Status                |
|----------------------|---|--------------------------------|-------------------------|---|-----------------------|
| 4.6.1                | <ul style="list-style-type: none"> <li>● plant known to emit noise strongly in one direction should, where possible, be orientated to direct noise away from the NSRs;</li> </ul>   | DSD's Contractor               | Construction Work Sites | PN 2/93 Noise from Construction Activities & EIAO   | ✓                     |
|                      | <ul style="list-style-type: none"> <li>● mobile plant should be sited as far away from NSRs as possible; and</li> </ul>   |                                |                         |   | ✓                     |
|                      | <ul style="list-style-type: none"> <li>● material stockpiles and other structures should be effectively utilised, where practicable, to screen noise from on-site construction activities.</li> </ul>   |                                |                         |   | ✓                     |
|                      | <i>For Drill and Blast Works</i> <ul style="list-style-type: none"> <li>● Charge mass per delay should be decreased by minimising the number of blastholes firing on each delay.</li> </ul>   |                                |                         |   | N/A                   |
|                      | <ul style="list-style-type: none"> <li>● Smaller blasthole patterns and longer delays should be used between dependent charges.</li> </ul>  |                                |                         |   | N/A                   |
|                      | <ul style="list-style-type: none"> <li>● Times of blasting should be established to suit the situation and firing blasts when neighbours are busy with their daily tasks (and at a regular time such as lunch time).</li> </ul>   |                                |                         |   | N/A                   |
|                      | <i>For TBM Tunnelling</i> <ul style="list-style-type: none"> <li>● For the tunnel excavation, it is anticipated that beyond the initial length (say within 30m), excavation will be carried out well within the tunnel and door should be provided to further minimize the noise nuisance to the nearby receivers.</li> </ul>   |                                |                         |   | N/A                   |
| 4.6.2                | <p><b>During Operation</b></p> <p>Good site practice and noise management can significantly reduce the impact of maintenance activities on nearby NSRs. The following package of measures should be followed during construction</p> <ul style="list-style-type: none"> <li>● only well-maintained plant should be operated on-site;</li> <li>● machines and plant that may be in intermittent use should be shut down between work periods or should be throttled down to a minimum; and</li> <li>● plant known to emit noise strongly in one direction should, where possible, be orientated to direct noise away from the NSRs.</li> </ul>   | DSD's Contractor               | Project Area            | NCO & EIAO  | N/A<br>N/A<br>N/A     |
| <b>Water Quality</b> |   |                                |                         |   |                       |
| 5.9.1                | <p><b>During Construction</b></p> <p>Mitigation measures and a spill control and response plan have been prepared for works at the intakes and work sites.</p> <p><i>Precautions to be taken at any time of year when rainstorms are likely:</i></p> <ul style="list-style-type: none"> <li>● Temporarily exposed surfaces should be covered e.g. by tarpaulin.</li> <li>● Temporary access roads should be protected by crushed stone or gravel.</li> <li>● Trenches should be dug and backfilled in short sections. Measures should be taken to minimize the ingress of rainwater into trenches.</li> </ul> <p><i>Actions to be taken when a rainstorm is imminent or forecast:</i></p> <ul style="list-style-type: none"> <li>● Silt removal facilities, should be checked to ensure that they can function properly.</li> </ul> | DSD's Contractor               | Construction Work Sites | Practice Note for Professional Persons with regard to site drainage (ProPECC PN 1/94) and WQO | ✓<br>✓<br>✓<br>✓<br>✓ |

## Appendix D

| EIA Ref.   | Recommended Mitigation Measures  | Who to implement the measure ? | Location of the measure | What requirements or standards for the measure to achieve ? | Status |
|--|--|--------------------------------|-------------------------|---|--------|
| 5.9.1  | <ul style="list-style-type: none"> <li>• Open stockpiles of construction materials on site should be covered with tarpaulin or similar fabric.</li> </ul>  | DSD's Contractor               | Construction Work Sites | WQO   | ✓      |
|  | <ul style="list-style-type: none"> <li>• All temporary covers to slopes and stockpiles should be secured.</li> </ul>   |                                |                         |   | ✓      |
|  | <p><i>Actions to be taken during or after rainstorms:</i></p> <ul style="list-style-type: none"> <li>• Silt removal facilities should be checked and maintained to ensure satisfactory working conditions.</li> </ul>                              |                                |                         |   | ✓      |
|  | <p><b><u>Spill Control and Response Plan</u></b></p>   |                                |                         |   |        |
|  | <p><b>1 Prevention and Precaution Measures</b></p>   |                                |                         |   |        |
|  | <p><b><i>General Precautions</i></b></p>   |                                |                         |   | ✓      |
|  | <ul style="list-style-type: none"> <li>• No discharge of silty water into watercourses.</li> </ul>   |                                |                         |   | ✓      |
|  | <ul style="list-style-type: none"> <li>• All materials to be used during construction and operation shall be identified and their hazard potential evaluated.</li> </ul>   |                                |                         |   | ✓      |
|  | <ul style="list-style-type: none"> <li>• Maintenance of vehicles and equipment involving activities with potential for leakage and spillage shall only be undertaken with the areas appropriately equipped to control these discharges.</li> </ul> |                                |                         |   | ✓      |
|  | <ul style="list-style-type: none"> <li>• Any soil contaminated with chemicals/oils shall be removed from site and the void created shall be filled with suitable materials.</li> </ul>   |                                |                         |   | ✓      |
|  | <ul style="list-style-type: none"> <li>• Any construction plant which causes pollution to catchwaters or water gathering ground due to leakage of oil or fuel shall be removed off-site immediately.</li> </ul>                                    |                                |                         |   | ✓      |
|  | <ul style="list-style-type: none"> <li>• Suitable containers shall be used to hold the chemical wastes to avoid leakage or spillage during storage, handling and transport</li> </ul>  |                                |                         |   | ✓      |
|  | <ul style="list-style-type: none"> <li>• Chemical waste containers shall be suitably labelled to notify and warn the personnel who are handling the wastes to avoid accidents.</li> </ul>  |                                |                         |   | ✓      |
|  | <ul style="list-style-type: none"> <li>• Storage areas shall be selected at safe locations on site and adequate space shall be allocated to the storage area.</li> </ul>   |                                |                         |   | ✓      |
|  | <ul style="list-style-type: none"> <li>• Prevent obstructions and tripping hazards.</li> </ul>   |                                |                         |   | ✓      |
|  | <p><b><i>Storage Precautions</i></b></p>   |                                |                         |   | ✓      |
|  | <ul style="list-style-type: none"> <li>• All chemical storage containers shall be correctly labelled.</li> </ul>   |                                |                         |   | ✓      |
| <ul style="list-style-type: none"> <li>• Solid and impermeable enclosure walls or storage shelves shall be used.</li> </ul>  | ✓  |                                |                         |   |        |
| <ul style="list-style-type: none"> <li>• Only compatible chemical wastes shall be stored in the same storage area.</li> </ul>  | ✓  |                                |                         |   |        |
| <ul style="list-style-type: none"> <li>• The storage areas shall be inspected to detect any leakages or defective containers on a regular basis.</li> </ul>  | ✓  |                                |                         |   |        |
| <ul style="list-style-type: none"> <li>• Suitable notices warning of hazards, emergency response plans, telephone numbers etc shall be posted around the site, including storage areas.</li> </ul> | ✓  |                                |                         |   |        |
| <ul style="list-style-type: none"> <li>• Large and heavy containers shall be stored at ground level.</li> </ul>  | ✓  |                                |                         |   |        |

## Appendix D

| EIA Ref.   | Recommended Mitigation Measures   | Who to implement the measure ? | Location of the measure | What requirements or standards for the measure to achieve ? | Status |
|--|---|--------------------------------|-------------------------|---|--------|
|  | <ul style="list-style-type: none"> <li>Chemical waste containers shall be stored below eye level.</li> </ul>  |                                |                         |   | ✓      |
| 5.9.1  | <ul style="list-style-type: none"> <li>Adequate space for handling of the containers shall be provided</li> </ul>   | DSD's Contractor               | Construction Work Sites | WQO   | ✓      |
|  | <ul style="list-style-type: none"> <li>Spill response kits shall be located adjacent/near to the storage areas.</li> </ul>  |                                |                         |   | ✓      |
|  | <ul style="list-style-type: none"> <li>A log of chemical wastes shall be maintained.</li> </ul>   |                                |                         |   | ✓      |
|  | <ul style="list-style-type: none"> <li>Incompatible chemicals shall be stored separately.</li> </ul>  |                                |                         |   | ✓      |
|  | <p><b>2 Responses/Action Plan</b></p>   |                                |                         |   |        |
|  | <p>All Workers shall be made aware of emergency telephone numbers and the location of all relevant pollution control equipment. Training be given in emergency response/action plans. The action include the following steps:</p> |                                |                         |   | ✓      |
|  | <ul style="list-style-type: none"> <li>Only trained personnel who are equipped with protective clothing and equipment shall be allowed to enter the spillage area for clean up.</li> </ul>  |                                |                         |   | ✓      |
|  | <ul style="list-style-type: none"> <li>Spills shall be transferred appropriate back into containers using suitable equipment.</li> </ul>  |                                |                         |   | ✓      |
|  | <ul style="list-style-type: none"> <li>Absorbent materials shall be used to clean up the spills and shall be disposed of as chemical wastes.</li> </ul>   |                                |                         |   | ✓      |
|  | <ul style="list-style-type: none"> <li>Where appropriate suitable solvents may be used to clean the contaminated area after removal of all contaminated materials.</li> </ul>   |                                |                         |   | ✓      |
|  | <ul style="list-style-type: none"> <li>All necessary protective devices, safety equipment, containers and clean up materials for emergency use shall be maintained to a high standard.</li> </ul>                                 |                                |                         |   | ✓      |
|  | <p><b>3 Spill Clean Up and Disposal</b></p>   |                                |                         |   |        |
|  | <p>Effect the response plan.</p>  |                                |                         |   | ✓      |
|  | <p>Control the leakage and absorb the spillage using suitably absorbent materials.</p>  |                                |                         |   | ✓      |
|  | <p>Provide safety equipment and personal protective equipment for handling of chemical wastes would be similar to that for handling of chemicals.</p>   |                                |                         |   | ✓      |
|  | <p><i>Safety equipment includes but is not limited to:</i></p> <ul style="list-style-type: none"> <li>Fire extinguishers.</li> </ul>  |                                |                         |   | ✓      |
|  | <ul style="list-style-type: none"> <li>Spades, brushes, dustpan, mop and bucket (or similar readily available on site).</li> </ul>  |                                |                         |   | ✓      |
|  | <ul style="list-style-type: none"> <li>Absorbent material such as dry sand, tissues and toweling (all materials readily available on-site).</li> </ul>  |                                |                         |   | ✓      |
|  | <ul style="list-style-type: none"> <li>Containers including plaster bags, drums, etc.</li> </ul>  |                                |                         |   | ✓      |
|  | <ul style="list-style-type: none"> <li>Absorbing materials.</li> </ul>  |                                |                         |   | ✓      |
| <ul style="list-style-type: none"> <li>Pumps.</li> </ul>   | ✓   |                                |                         |   |        |
| <p><i>Personal protective equipment includes as appropriate:</i></p> <ul style="list-style-type: none"> <li>First-aid kits.</li> </ul> | ✓   |                                |                         |   |        |
| <ul style="list-style-type: none"> <li>Safety helmet and goggles.</li> </ul>   | ✓   |                                |                         |   |        |
| <ul style="list-style-type: none"> <li>Gloves which can resist chemical reaction.</li> </ul>   | ✓   |                                |                         |   |        |

## Appendix D

| EIA Ref.                | Recommended Mitigation Measures  | Who to implement the measure ? | Location of the measure | What requirements or standards for the measure to achieve ?  | Status |
|-------------------------|--|--------------------------------|-------------------------|--|--------|
| 5.9.1                   | <ul style="list-style-type: none"> <li>• Protective boot and clothing.</li> </ul>  | DSD's Contractor               | Construction Work Sites | WQO  | ✓      |
|                         | <ul style="list-style-type: none"> <li>• Respirators and gas masks.</li> </ul>   |                                |                         |  | ✓      |
|                         | <ul style="list-style-type: none"> <li>• Face visor and masks.</li> </ul>  |                                |                         |  | ✓      |
| 5.9.2                   | <p><b>Emergency Responses to Spillages</b></p> <p>Emergency plans and clean up procedures will need to be provided by the Contractor recognising his specific working methods and construction programme, activities and sequences. Agreement must be sought prior to commencement of the construction work but the following principles should be considered.</p> <p><i>The emergency plans should include the procedures for:</i></p> <ul style="list-style-type: none"> <li>• spill prevention and precaution;</li> <li>• response actions; and</li> <li>• spill clean up and disposal.</li> </ul> <p><i>Spill prevention and precaution embraces good site practice and covers:</i></p> <ul style="list-style-type: none"> <li>• good housekeeping practices;</li> <li>• chemical storage requirements; and</li> <li>• chemical transfer and transport.</li> </ul> | DSD's Contractor               | Project Area            |  | ✓      |
| 5.9.3                   | <p><b>During Operation</b></p> <p>Regular inspection of the tunnels is essential to monitor the structural integrity and proper functioning of the drainage tunnel, which allows repairing of structural deterioration when it begins to develop. It is recommended that routine inspection shall be carried out at least two times per year for the drainage tunnel at the beginning and end of wet season from April to September.</p>   |                                |                         |  | N/A    |
| <b>Waste Management</b> |  |                                |                         |  |        |
| 6.5.1                   | <p><b>During Construction</b></p> <p><i>Vegetation Removed from Site Clearance</i><br/>Wastes generated from site clearance shall be sorted and excavated topsoil segregated from roots for re-use in landscaping works, thus eliminating the need for off-site disposal.</p> <p><i>Construction and Demolition Materials</i><br/>The Contractor should reuse any C&amp;D material on-site. C&amp;D waste should be segregated and stored in different containers to other wastes to encourage the re-use or recycling of materials and their proper disposal. The use of wooden hoardings shall not be allowed. An alternative material, which can be reused or recycled, for example, metal (aluminium, alloy, etc) shall be used.</p>   | DSD's Contractor               | Construction Work Sites | Waste Disposal Ordinance (Cap.354); Waste Disposal (Chemical Wastes) (General) Regulation (Cap 354) and ETWBTC No. 15/2003, Waste anagement on Construction Site | ✓      |
|                         |  |                                |                         |  | ✓      |



## Appendix D

| EIA Ref. | Recommended Mitigation Measures   | Who to implement the measure ? | Location of the measure | What requirements or standards for the measure to achieve ?                  | Status |
|----------|---|--------------------------------|-------------------------|--|--------|
| 6.5.1    | As referred to the section 6.4.1, the 317,936m <sup>3</sup> of inert surplus material generated by the project is suitable for public fill. The public fill reception facility at Tuen Mun Area 38 provides a suitable facility for the reuse of surplus inert C&D material generated from the project.   | DSD's Contractor               | Construction Work Sites | WDO (Cap.354), ETWBTC No. 15/2003, ETWBTC No. 12/2002 and ETWBTC No. 31/2004 |        |
|          | Under the contract, the contractor will be required to minimise the generation of C&D material and reuse it on site through the following:  |                                |                         |  |        |
|          | (a) to plan in the design and construction, methods to minimise the generation of C&D material;   |                                |                         |  | ✓      |
|          | (b) to submit a Waste Management Plan (WMP) in accordance with Environment Transport and Works Bureau Technical Circular (ETWBTC) No. 15/2003 or any superseding circular(s);   |                                |                         |  | ✓      |
|          | (c) to reuse recycled aggregates in accordance with ETWBTC No. 12/2002 or any superseding circular(s);  |                                |                         |  | ✓      |
|          | (d) to observe the requirements of the Trip-Ticket System, stipulated in ETWBTC No. 31/2004 or any superceding circular(s), for disposal of C&D material;   |                                |                         |  | ✓      |
|          | (e) to incorporate a Waste Management System into the WMP for effective management and control of C&D materials to avoid/reduce/minimise the generation of C&D material during construction.  |                                |                         |  | ✓      |
|          | The contractor will be required to properly sort into inert C&D materials, metals, timber and other non-inert C&D material in the workplace to prevent cross-contamination.   | ✓                              |                         |  |        |
|          | In addition, DSD will conduct site inspection to monitor the contractors' performance in the implementation of the WMP and other relevant specified requirements.   | DSD                            | Construction Work Sites | WDO (Cap.354) and ETWBTC No. 15/2003   | ✓      |
|          | <i>Excavated Materials</i><br>Excavated materials should be segregated from other wastes to avoid contamination thereby ensuring acceptability at public filling areas and avoiding the need for disposal at landfill.  | DSD's Contractor               | Construction Work Sites | WDO (Cap.354) and ETWBTC No. 15/2003   | ✓      |
|          | <i>Municipal Waste</i><br>Temporary refuse collection facilities should be set-up by the contractor and wastes should be stored in appropriate containers prior to collection and disposal.   |                                |                         |  | ✓      |
|          | Domestic effluent generated by the workforce will be directed to foul sewer or chemical toilets if public facilities are not available.   |                                |                         |  | ✓      |
| 6.5.1    | <i>Waste Management Plan</i><br>A Waste Management Plan (WMP) for the construction of the Project should be prepared as part of the contractors submission. It will provide recommendations for appropriate recycling or disposal route and should include method statement for stockpiling and transportation of the excavated material and other construction wastes should also be included in the WMP and approved before the commencement of construction. All mitigation measures arising from the approved WMP shall be fully implemented. | DSD's Contractor               | Construction Work Sites | WDO (Cap.354), ETWBTC No. 15/2003 and ETWBTC No. 33/2002                     | ✓      |

## Appendix D

| EIA Ref.       | Recommended Mitigation Measures  | Who to implement the measure ? | Location of the measure | What requirements or standards for the measure to achieve ? | Status |
|----------------|--|--------------------------------|-------------------------|---|--------|
|                | For the purpose of enhancing the management of C&D material including rock, and to minimize its generation at source, a C&D Material Management Plan (C&DMMP) has been prepared for this project and would be processed in accordance with the Environment, Transport and Works Bureau Technical Circular (Works) No. 33/2002 - Management of Construction and Demolition Material Including Rock.   |                                |                         |   | N/A    |
| <b>Ecology</b> |  |                                |                         |   |        |
| 7.7.1          | <p><b>Avoidance</b></p> <p>The surface structures are located mainly on existing disturbed areas (ie pollution and urbanisation) and have generally avoided the natural stream sections of higher species diversity and abundance of aquatic organisms.</p> <p>The major construction activities at streams are scheduled to avoid wet season of high water flow which may adversely affect the downstream natural habitats due to the construction runoff.</p>  | DSD's Contractor               | Construction Work Sites | EIAO  | ✓      |
| 7.7.2          | <p><b>Minimisation</b></p> <p>The previous discussion in Section 7.6.4 has indicated that the impacts on ecological resources due to the construction and operation of the proposed Project are generally expected to be low. The following mitigation measures to minimise impacts and disturbance to the surrounding habitats, are recommended.</p> <p><i>Measures for Construction Runoff</i><br/>Install sheet piles/cofferdam/weir along the boundary of the works area within the stream habitats in particular Sam Dip Tam Stream and Tso Kung Tam Stream before the commencement of works to prevent construction runoff during construction. Provision of adequate designed sand/ silt removal facilities such as sand traps, silt traps and sediment basin in the areas which could potentially be affected may be required.</p> <p><i>Good Construction Practice</i></p> <p>Erect fences along the boundary of the works area before the commencement of works to prevent tipping, vehicle movements, and encroachment of personnel onto adjacent areas, particularly the stream habitats.</p> <p>Avoid any damage and disturbance, particularly those caused by filling and illegal dumping, to the remaining and surrounding natural stream habitats.</p> <p>Regularly check the work site boundaries to ensure that they are not breached and that no damage occurs to surrounding areas.</p> <p>Prohibit and prevent open fires within the site boundary during construction and provide temporary fire fighting equipment in the work areas.</p> <p>Treat any damage that may have occurred to individual major trees in the adjacent area with surgery.</p> | DSD's Contractor               | Construction Work Sites | EIAO  | ✓      |
|                |  |                                |                         |   | ✓      |
|                |  |                                |                         |   | ✓      |
|                |  |                                |                         |   | ✓      |
|                |  |                                |                         |   | ✓      |

## Appendix D

| EIA Ref. | Recommended Mitigation Measures   | Who to implement the measure ? | Location of the measure | What requirements or standards for the measure to achieve ? | Status |
|----------|---|--------------------------------|-------------------------|---|--------|
|          | Reinstate temporary work sites/disturbed areas, particularly stream of natural bottom and bank, plantation, intertidal habitat, and the areas located within the proposed Ecological Park, immediately after completion of the construction works, ie through on-site tree/shrub planting and reprovision of natural or semi-natural bottom (also refer to Section 7.7.3), in order to facilitate the recolonisation of the wildlife recorded during the baseline surveys. Tree/shrub species used should make reference from those in the surrounding area   | DSD's Contractor               | Construction Work Sites | EIAO  | ✓      |
| 7.7.3    | <b>Compensation</b>   |                                |                         |   |        |
|          | Provide natural stream bed (approximately 0.03 ha) for the new Dry Weather Flow Channel (created from village-orchard) by laying natural stones at Intake I-2 (Figure 7.7). The reinstated stream bed shall mimic the existing natural conditions with certain portion of big boulders creating the lentic and lotic zones for the aquatic fauna, and while it will be developed during detailed design may draw on concepts shown in Figure 2.18.  |                                |                         |   | N/A    |
|          | Provide natural stream bed (approximately 0.5 ha,) for the Approach Channel and Dry Weather Flow Channel by laying natural stones at Intake I-3 (Figure 7.8). The reinstated stream bed shall mimic the existing natural conditions (rocky bottom with very limited aquatic plants) with certain portion of big boulders creating the lentic and lotic zones for the aquatic fauna, and while it will be developed during detailed design may draw on concepts shown in Figure 2.18.  |                                |                         |   | N/A    |
|          | Provide natural bottom (ie retain the existing stream bed or reinstate the stream bed by providing boulders/ rocks, riprap or gabion) for the affected stream sections (Figure 7.8) in order to allow natural colonisation of aquatic fauna.  |                                |                         |   | N/A    |
|          | Provide at least 2.2 ha of compensatory planting on the permanent and temporary affected plantation areas, particularly the slopes along access road and adjacent to Intake I-3 and cascade at Outfall O-1, after construction to stabilise the slope to present soil erosion and consequent stream sedimentation. Among the 2.2 ha compensatory planting, at least 0.5 ha of compensatory tree planting on the new formed slope along the access road of the Intake I-3 and 0.5 ha of compensatory tree planting over the cascade (by constructing intermediate platform) at Outfall O-1 will be provided (location refer to Figures 7.4 – 7.6). Species used for planting should take reference from the species identified in Appendix F and be native to Hong Kong or South China region. |                                |                         |   | N/A    |
|          | Provide armour rocks for the affected intertidal habitat in order to allow natural colonisation of intertidal organisms.  |                                |                         |   | N/A    |

## Appendix D

| EIA Ref.                 | Recommended Mitigation Measures  | Who to implement the measure ?                        | Location of the measure | What requirements or standards for the measure to achieve ? | Status |
|--------------------------|--|---|-------------------------|---|--------|
| <b>Cultural Heritage</b> |  |   |                         |   |        |
| 8.6                      | As no impacts on recorded archaeological sites or area with archaeological potential were identified within the Study Area, no mitigation measure for archaeological resources is considered necessary.  |   |                         |   | N/A    |
|                          | The construction methods to be employed should seek to avoid potential vibration impacts to Kuen Yuen Tung Monastery at Lo Wai, the Western Monastery, Yuen Yuen Home for the Aged, Hong Hoi Chee Hong Temple, Chiu Yum Tsing Yuen, Tse's Grave, Wan Lin Bridge and Sam Dip Tam Rock Carving in Sam Dip Tam and the Tin Hau Temple, Yam Kom Tau Village Rural Committee and the Yeung's Ancestral Hall in Yau Kom Tau as these sites fall within 50 m of the Preferred Option of the drainage tunnel alignment or associated Intakes/Outfall construction activities. Construction works that generates excessive vibration in close proximity to these sites should be restricted to protect the building from adverse vibration impacts and to ensure that the building structures will not be damaged as a result of these impacts. | DSD's Contractor                                      | Construction Work Sites | EIAO  | ✓      |
|                          | In order to ensure that no structural or superficial damage will be caused by the construction activities, a precautionary approach involving a pre-construction condition survey and establishment of appropriate vibration limits for the potentially impacted structures should be adopted. Protection measures for the potentially impacted structures, if considered necessary from the pre-construction condition survey, should be implemented prior to the commencement of construction works. Vibration monitoring during the construction phase should be undertaken as part of the EM&A programme.  | Qualified archaeologist/<br>built heritage specialist | Construction Work Sites | EIAO  | ✓      |
| <b>Fisheries</b>         |  |   |                         |   |        |
| 10.6                     | In accordance with the guidelines in the <i>EIAO-TM</i> on fisheries impact assessment the general policy for mitigating impacts to fisheries, in order of priority are avoidance, minimization and compensation.  | DSD's Contractor                                      | Construction Work Sites | EIAO  | N/A    |
|                          | Impacts to fisheries resources and fishing operations have largely been avoided during the construction and operation of the drainage tunnel through the avoidance of dredging, reclamation and filling activities. Good construction practice and associated measures were recommended in Water Quality Assessment in Section 5 to control water quality impacts to within acceptable levels and are also expected to control impacts to fisheries resources. Hence, no fisheries-species mitigation measures are required during construction and operation of the drainage tunnel.  |   |                         |   | N/A    |

Remarks:

- ✓ Compliance of mitigation measure
- × Non-compliance of mitigation measure
- N/A Not applicable

## Appendix E

---

### Status of License and Permit

**Updated Status of Environmental Permit & Licence**

| Application Date | Environmental Permit / Licence  | Issued Date | Ref No.                  | Account No. | Permit / Licence No. | Permit / Licence Validity Date | Remarks |
|------------------|---|-------------|--------------------------|-------------|----------------------|--------------------------------|---------|
| 2 Jan 2008       | Waste Disposal (Charges for Disposal of Construction Waste) Regulation - Billing Account          | 17 Jan 2008 | WFG06289                 | 7006574     | ----                 | ----                           | Valid   |
| 10 Jan 2008      | Notification Pursuant to Section 3(1) of the Air Pollution Control (Construction Dust) Regulation | 10 Jan 2008 | 001026901                | ----        | ----                 | ----                           | Valid   |
| 18 Apr 2008      | Water Discharge Licence – Intake I-1  | 19 Jun 2008 | 001029978                | ----        | EP760/327/013315I    | 19 Jun 2008 - 30 Jun 2013      | Valid   |
| 18 Apr 2008      | Water Discharge Licence – Intake I-2  | 2 Jul 2008  | 001029959                | ----        | EP760/321/013020I    | 02 Jul 2008 - 31 Jul 2013      | Valid   |
| 18 Apr 2008      | Water Discharge Licence – Intake I-3  | 5 Aug 2008  | 001029960                | ----        | EP760/323/013324I    | 05 Aug 2008 - 31 Aug 2013      | Valid   |
| 18 Apr 2008      | Water Discharge Licence – Portion I   | 26 Jun 2008 | 001029974                | ----        | EP760/350/013334I    | 26 Jun 2008 - 30 Jun 2013      | Valid   |
| 23 Jul 2008      | Water Discharge Licence – Intake I-1 (Intersection of Wo Yi Hop Lane and Ho Fung College)         | 27 Aug 2008 | 001031974                | ----        | EP760/325/013536I    | 27 Aug 2008 - 31 Aug 2013      | Valid   |
| 2 Sep 2008       | Variation of Environmental Permit   | 25 Sep 2008 | VEP-271/2008             | ----        | EP-275/2007/B        | ----                           | Valid   |
| 29 Apr 2009      | Water Discharge Licence – Intake I-3 (Additional Discharge Point)                                 | 25 Mar 2010 | 305058                   | ----        | WT00005917-2010      | 25 Mar 2010 - 31 Mar 2015      | Valid   |
| 4 Sep 2010       | Water Discharge Licence – Portion G   | 28 Oct 2010 | 321337                   | ----        | WT00007685-2010      | 28 Oct 2010 - 31 Oct 2015      | Valid   |
| 16 Nov 2010      | Water Discharge Licence - Outfall   | 17 Nov 2011 | (14) in EP/RW/0000080206 | ----        | WT-00008094-2010     | 17 Nov 2011 - 30 Nov 2016      | Valid   |
| 6 Aug 2012       | Further Environmental Permit  | 29 Aug 2012 | FEP-140/2012             | ----        | FEP-02/275/2007/B    | ----                           | Valid   |
| 26 Jul 2012      | Waste Disposal (Chemical Waste) (General) - Chemical Waste Producer                               | 9 Oct 2012  | (7) in EP/RW/0000062354  | ----        | 5111-324-M2703-01    | ----                           | Valid   |
| 23 Jan 2013      | Construction Noise Permit - Intake I-3  | 04 Feb 2013 | (5) in EP/RW/0000080194  | ----        | GW-RW0071-13         | 13 Feb 2013 - 12 Aug 2013      | Valid   |
| 23 Jan 2013      | Construction Noise Permit - Portion I   | 06 Feb 2013 | (4) in EP/RW/0000080230  | ----        | GW-RW0096-13         | 11 Feb 2013 - 10 Aug 2013      | Valid   |
| 6 Mar 2013       | Construction Noise Permit - Outfall   | 18 Mar 2013 | (4) in EP/RW/0000301563  | ----        | GW-RW0172-13         | 19 Mar 2013 - 17 Sept 2013     | Valid   |

## Appendix F

---

## Calibration Certificates

**High Volume Air Sampler Calibration Worksheet**

**Project Title:** Design and Construction of Tsuen Wan Drainage Tunnel  
**Monitoring Location:** Ho Fung College (ASR 1)  
**Calibration Date:** 28-Mar-13  
**Calibration Due Date:** 28-May-13  
**Time:** 8:15

|                         |          |
|-------------------------|----------|
| Sampler Model:          | BM2000HX |
| Serial No.:             | 4994     |
| Calibrator Orifice no.: | 1785     |
| Slope (m):              | 2.00815  |
| Intercept (b):          | -0.01705 |
| Correction coeff. (r)   | 0.99998  |


$$\text{Flow (corrected)} = \sqrt{H \times \frac{Pa}{Pstd} \times \frac{Tstd}{Ta}}$$

|                                 |       |
|---------------------------------|-------|
| Standard pressure (mmHg) Pstd:  | 763.9 |
| Standard temp. (K) Tstd:        | 290.8 |
| Calibration pressure (mmHg) Pa: | 759.4 |
| Calibration temp. (K) Ta:       | 291.0 |


$$Qstd = \frac{1}{m} \times \left( \sqrt{H \times \frac{Pa}{Pstd} \times \frac{Tstd}{Ta}} - b \right)$$

| Sample no. | Pressure Drop (H), inch | Flow (corrected), m <sup>3</sup> /min | Actual flow rate (Qstd), m <sup>3</sup> /min | Flow indication (I), arbitrary |
|------------|-------------------------|---------------------------------------|--|--------------------------------|
| 1          | 12.6                    | 3.581                                 | 1.792  | 55.0                           |
| 2          | 10.0                    | 3.191                                 | 1.597  | 48.0                           |
| 3          | 8.0                     | 2.854                                 | 1.430  | 42.0                           |
| 4          | 5.4                     | 2.345                                 | 1.176  | 33.0                           |
| 5          | 2.9                     | 1.718                                 | 0.864  | 25.0                           |


Correlation Coefficient : 0.9972



Remark  
 1HPa = 0.750062 mmHg

**Calibrated by:** Ray TAM  
 (  )

**Date:** 28 March 2013

**Checked by:** F.C. Tsang  
 (  )

**Date:** 28 March 2013



**High Volume Air Sampler Calibration Worksheet**

**Project Title:** Design and Construction of Tsuen Wan Drainage Tunnel  
**Monitoring Location:** Hong Hoi Chi Hong Ship Temple (ASR 3)  
**Calibration Date:** 28-Mar-13  
**Calibration Due Date:** 28-May-13  
**Time:** 9:00

|                         |          |
|-------------------------|----------|
| Sampler Model:          | BM2000HX |
| Serial No.:             | 5875     |
| Calibrator Orifice no.: | 1785     |
| Slope (m):              | 2.00815  |
| Intercept (b):          | -0.01705 |
| Correction coeff. (r)   | 0.99998  |


|                                 |       |
|---------------------------------|-------|
| Standard pressure (mmHg) Pstd:  | 763.9 |
| Standard temp. (K) Tstd:        | 290.8 |
| Calibration pressure (mmHg) Pa: | 760.4 |
| Calibration temp. (K) Ta:       | 291.0 |

$$\text{Flow (corrected)} = \sqrt{H \times \frac{Pa}{Pstd} \times \frac{Tstd}{Ta}}$$

$$Qstd = \frac{1}{m} \times (\sqrt{H \times \frac{Pa}{Pstd} \times \frac{Tstd}{Ta}} - b)$$

| Sample no. | Pressure Drop (H), inch | Flow (corrected), m <sup>3</sup> /min | Actual flow rate (Qstd), m <sup>3</sup> /min | Flow indication (I), arbitrary |
|------------|-------------------------|---------------------------------------|--|--------------------------------|
| 1          | 12.4                    | 3.555                                 | 1.779  | 54.0                           |
| 2          | 10.0                    | 3.193                                 | 1.598  | 48.0                           |
| 3          | 7.7                     | 2.802                                 | 1.404  | 41.0                           |
| 4          | 5.0                     | 2.258                                 | 1.133  | 32.0                           |
| 5          | 2.8                     | 1.689                                 | 0.850  | 24.0                           |

Correlation Coefficient : 0.9991



Remark  
 1HPa = 0.750062 mmHg

**Calibrated by:** Ray Tam ( *[Signature]* )

**Date:** 28 March 2013

**Checked by:** F.C. Tsang ( *[Signature]* )

**Date:** 28 March 2013

**High Volume Air Sampler Calibration Worksheet**

**Project Title:** Design and Construction of Tsuen Wan Drainage Tunnel  
**Monitoring Location:** Long Beach Garden (ASR 8)  
**Calibration Date:** 28-Mar-13  
**Calibration Due Date:** 28-May-13  
**Time:** 8:30

|                         |          |
|-------------------------|----------|
| Sampler Model:          | TE5005X  |
| Serial No.:             | 1059     |
| Calibrator Orifice no.: | 1785     |
| Slope (m):              | 2.00815  |
| Intercept (b):          | -0.01705 |
| Correction coeff. (r)   | 0.99998  |


|                                 |       |
|---------------------------------|-------|
| Standard pressure (mmHg) Pstd:  | 763.9 |
| Standard temp. (K) Tstd:        | 290.8 |
| Calibration pressure (mmHg) Pa: | 759.4 |
| Calibration temp. (K) Ta:       | 291.0 |

$$\text{Flow (corrected)} = \sqrt{H \times \frac{Pa}{Pstd} \times \frac{Tstd}{Ta}}$$


$$Q_{std} = \frac{1}{m} \times \left( \sqrt{H \times \frac{Pa}{Pstd} \times \frac{Tstd}{Ta}} - b \right)$$

| Sample no. | Pressure Drop (H), inch | Flow (corrected), m <sup>3</sup> /min | Actual flow rate (Qstd), m <sup>3</sup> /min | Flow indication (I), arbitrary |
|------------|-------------------------|---------------------------------------|--|--------------------------------|
| 1          | 12.5                    | 3.567                                 | 1.785  | 55.0                           |
| 2          | 9.8                     | 3.159                                 | 1.581  | 49.0                           |
| 3          | 8.0                     | 2.854                                 | 1.430  | 43.0                           |
| 4          | 5.4                     | 2.345                                 | 1.176  | 36.0                           |
| 5          | 2.8                     | 1.688                                 | 0.849  | 27.0                           |


Correlation Coefficient : 0.9983



Remark  
 1HPa = 0.750062 mmHg

**Calibrated by:** Ray Tam  
 (  )

**Date:** 28 March 2013

**Checked by:** F.C. Tsang  
 (  )

**Date:** 28 March 2013

**High Volume Air Sampler Calibration Worksheet**

**Project Title:** Design and Construction of Tsuen Wan Drainage Tunnel  
**Monitoring Location:** Greenview Terrace (ASR 9)  
**Calibration Date:** 28-Mar-13  
**Calibration Due Date:** 28-May-13  
**Time:** 8:00

|                         |          |
|-------------------------|----------|
| Sampler Model:          | TE5005X  |
| Serial No.:             | 1713     |
| Calibrator Orifice no.: | 1785     |
| Slope (m):              | 2.00815  |
| Intercept (b):          | -0.01705 |
| Correction coeff. (r)   | 0.99998  |


|                                 |       |
|---------------------------------|-------|
| Standard pressure (mmHg) Pstd:  | 763.9 |
| Standard temp. (K) Tstd:        | 290.8 |
| Calibration pressure (mmHg) Pa: | 759.4 |
| Calibration temp. (K) Ta:       | 291.0 |

$$\text{Flow (corrected)} = \sqrt{H \times \frac{Pa}{Pstd} \times \frac{Tstd}{Ta}}$$


$$Q_{std} = \frac{1}{m} \times (\sqrt{H \times \frac{Pa}{Pstd} \times \frac{Tstd}{Ta}} - b)$$

| Sample no. | Pressure Drop (H), inch | Flow (corrected), m <sup>3</sup> /min | Actual flow rate (Qstd), m <sup>3</sup> /min | Flow indication (I), arbitrary |
|------------|-------------------------|---------------------------------------|--|--------------------------------|
| 1          | 12.2                    | 3.524                                 | 1.763  | 54.0                           |
| 2          | 9.8                     | 3.159                                 | 1.581  | 50.0                           |
| 3          | 7.6                     | 2.782                                 | 1.394  | 45.0                           |
| 4          | 4.8                     | 2.211                                 | 1.109  | 37.0                           |
| 5          | 2.7                     | 1.658                                 | 0.834  | 28.0                           |


Correlation Coefficient : 0.9978



Remark  
 1HPa = 0.750062 mmHg

**Calibrated by:** Ray Tam (  )

**Date:** 28 March 2013

**Checked by:** F.C. Tsang (  )

**Date:** 28 March 2013



TISCH ENVIRONMENTAL, INC.  
 145 SOUTH MIAMI AVE.  
 VILLAGE OF CLEVELAND, OH 45002  
 513.467.9000  
 877.263.7610 TOLL FREE  
 513.467.9009 FAX  
 WWW.TISCH-ENV.COM

AIR POLLUTION MONITORING EQUIPMENT

ORIFICE TRANSFER STANDARD CERTIFICATION WORKSHEET TE-5025A

Date - May 04, 2012 Rootsmeter S/N 0438320 Ta (K) - 297  
 Operator Tisch Orifice I.D. - 1785 Pa (mm) - 751.84

| PLATE OR Run # | VOLUME START (m3) | VOLUME STOP (m3) | DIFF VOLUME (m3) | DIFF TIME (min) | METER DIFF Hg (mm) | ORFICE DIFF H2O (in.) |
|----------------|-------------------|------------------|------------------|-----------------|--------------------|-----------------------|
| 1              | NA                | NA               | 1.00             | 1.3940          | 3.2                | 2.00                  |
| 2              | NA                | NA               | 1.00             | 0.9830          | 6.4                | 4.00                  |
| 3              | NA                | NA               | 1.00             | 0.8780          | 7.9                | 5.00                  |
| 4              | NA                | NA               | 1.00             | 0.8360          | 8.8                | 5.50                  |
| 5              | NA                | NA               | 1.00             | 0.6920          | 12.7               | 8.00                  |

DATA TABULATION

| Vstd                               | (x axis) Qstd | (y axis) | Va                        | (x axis) Qa | (y axis) |
|------------------------------------|---------------|----------|---------------------------|-------------|----------|
| 0.9884                             | 0.7090        | 1.4090   | 0.9957                    | 0.7143      | 0.8889   |
| 0.9842                             | 1.0012        | 1.9926   | 0.9915                    | 1.0087      | 1.2570   |
| 0.9821                             | 1.1185        | 2.2278   | 0.9894                    | 1.1269      | 1.4054   |
| 0.9810                             | 1.1734        | 2.3365   | 0.9883                    | 1.1822      | 1.4740   |
| 0.9758                             | 1.4101        | 2.8179   | 0.9831                    | 1.4206      | 1.7777   |
| Qstd slope (m) = 2.00815           |               |          | Qa slope (m) = 1.25747    |             |          |
| intercept (b) = -0.01705           |               |          | intercept (b) = -0.01076  |             |          |
| coefficient (r) = 0.99998          |               |          | coefficient (r) = 0.99998 |             |          |
| y axis = SQRT[H2O(Pa/760)(298/Ta)] |               |          | y axis = SQRT[H2O(Ta/Pa)] |             |          |

CALCULATIONS

$$Vstd = \text{Diff. Vol} [(Pa - \text{Diff. Hg}) / 760] (298 / Ta)$$

$$Qstd = Vstd / \text{Time}$$

$$Va = \text{Diff Vol} [(Pa - \text{Diff Hg}) / Pa]$$

$$Qa = Va / \text{Time}$$

For subsequent flow rate calculations:

$$Qstd = 1/m \{ [\text{SQRT}(\text{H2O}(\text{Pa}/760)(298/\text{Ta}))] - b \}$$

$$Qa = 1/m \{ [\text{SQRT}(\text{H2O}(\text{Ta}/\text{Pa}))] - b \}$$

**High Volume Air Sampler Calibration Worksheet**

**Project Title:** Design and Construction of Tsuen Wan Drainage Tunnel  
**Monitoring Location:** Ho Fung College (ASR 1)  
**Calibration Date:** 29-May-13  
**Calibration Due Date:** 29-Jul-13  
**Time:** 8:15

|                         |          |
|-------------------------|----------|
| Sampler Model:          | BM2000HX |
| Serial No.:             | 4994     |
| Calibrator Orifice no.: | 1785     |
| Slope (m):              | 2.00979  |
| Intercept (b):          | -0.01403 |
| Correction coeff. (r)   | 0.99995  |


$$\text{Flow (corrected)} = \sqrt{H \times \frac{Pa}{Pstd} \times \frac{Tstd}{Ta}}$$

|                                 |       |
|---------------------------------|-------|
| Standard pressure (mmHg) Pstd:  | 763.9 |
| Standard temp. (K) Tstd:        | 290.8 |
| Calibration pressure (mmHg) Pa: | 758.2 |
| Calibration temp. (K) Ta:       | 301.9 |


$$Qstd = \frac{1}{m} \times \left( \sqrt{H \times \frac{Pa}{Pstd} \times \frac{Tstd}{Ta}} - b \right)$$

| Sample no. | Pressure Drop (H), inch | Flow (corrected), m <sup>3</sup> /min | Actual flow rate (Qstd), m <sup>3</sup> /min | Flow indication (I), arbitrary |
|------------|-------------------------|---------------------------------------|--|--------------------------------|
| 1          | 11.8                    | 3.400                                 | 1.699  | 55.0                           |
| 2          | 9.5                     | 3.051                                 | 1.525  | 48.0                           |
| 3          | 7.2                     | 2.656                                 | 1.328  | 42.0                           |
| 4          | 4.7                     | 2.146                                 | 1.075  | 33.0                           |
| 5          | 2.8                     | 1.656                                 | 0.831  | 26.0                           |


Correlation Coefficient : 0.9987



Remark  
 1HPa = 0.750062 mmHg

**Calibrated by:** Ray TAM  
 (  )

**Date:** 29 May 2013

**Checked by:** F.C. Tsang  
 (  )

**Date:** 29 May 2013

**High Volume Air Sampler Calibration Worksheet**

**Project Title:** Design and Construction of Tsuen Wan Drainage Tunnel  
**Monitoring Location:** Hong Hoi Chi Hong Ship Temple (ASR 3)  
**Calibration Date:** 29-May-13  
**Calibration Due Date:** 29-Jul-13  
**Time:** 9:00

|                         |          |
|-------------------------|----------|
| Sampler Model:          | BM2000HX |
| Serial No.:             | 5875     |
| Calibrator Orifice no.: | 1785     |
| Slope (m):              | 2.00979  |
| Intercept (b):          | -0.01403 |
| Correction coeff. (r)   | 0.99995  |


$$\text{Flow (corrected)} = \sqrt{H \times \frac{Pa}{Pstd} \times \frac{Tstd}{Ta}}$$

|                                 |       |
|---------------------------------|-------|
| Standard pressure (mmHg) Pstd:  | 763.9 |
| Standard temp. (K) Tstd:        | 290.8 |
| Calibration pressure (mmHg) Pa: | 758.2 |
| Calibration temp. (K) Ta:       | 301.9 |


$$Qstd = \frac{1}{m} \times \left( \sqrt{H \times \frac{Pa}{Pstd} \times \frac{Tstd}{Ta}} - b \right)$$

| Sample no. | Pressure Drop (H), inch | Flow (corrected), m <sup>3</sup> /min | Actual flow rate (Qstd), m <sup>3</sup> /min | Flow indication (I), arbitrary |
|------------|-------------------------|---------------------------------------|--|--------------------------------|
| 1          | 11.6                    | 3.371                                 | 1.684  | 58.0                           |
| 2          | 9.4                     | 3.035                                 | 1.517  | 52.0                           |
| 3          | 7.4                     | 2.693                                 | 1.347  | 45.0                           |
| 4          | 4.8                     | 2.169                                 | 1.086  | 36.0                           |
| 5          | 2.8                     | 1.656                                 | 0.831  | 27.0                           |


Correlation Coefficient : 0.9996



Remark  
 1HPa = 0.750062 mmHg

**Calibrated by:** Ray Tam (  )

**Date:** 29 May 2013

**Checked by:** F.C. Tsang (  )

**Date:** 29 May 2013

**High Volume Air Sampler Calibration Worksheet**

**Project Title:** Design and Construction of Tsuen Wan Drainage Tunnel  
**Monitoring Location:** Long Beach Garden (ASR 8)  
**Calibration Date:** 29-May-13  
**Calibration Due Date:** 29-Jul-13  
**Time:** 8:30

|                         |          |
|-------------------------|----------|
| Sampler Model:          | TE5005X  |
| Serial No.:             | 1059     |
| Calibrator Orifice no.: | 1785     |
| Slope (m):              | 2.00979  |
| Intercept (b):          | -0.01403 |
| Correction coeff. (r)   | 0.99995  |


$$\text{Flow (corrected)} = \sqrt{H \times \frac{Pa}{Pstd} \times \frac{Tstd}{Ta}}$$

|                                 |       |
|---------------------------------|-------|
| Standard pressure (mmHg) Pstd:  | 763.9 |
| Standard temp. (K) Tstd:        | 290.8 |
| Calibration pressure (mmHg) Pa: | 758.2 |
| Calibration temp. (K) Ta:       | 301.9 |


$$Q_{std} = \frac{1}{m} \times \left( \sqrt{H \times \frac{Pa}{Pstd} \times \frac{Tstd}{Ta}} - b \right)$$

| Sample no. | Pressure Drop (H), inch | Flow (corrected), m <sup>3</sup> /min | Actual flow rate (Qstd), m <sup>3</sup> /min | Flow indication (I), arbitrary |
|------------|-------------------------|---------------------------------------|--|--------------------------------|
| 1          | 11.2                    | 3.313                                 | 1.655  | 56.0                           |
| 2          | 9.2                     | 3.002                                 | 1.501  | 51.0                           |
| 3          | 7.0                     | 2.619                                 | 1.310  | 45.0                           |
| 4          | 4.8                     | 2.169                                 | 1.086  | 35.0                           |
| 5          | 2.7                     | 1.626                                 | 0.816  | 25.0                           |

Correlation Coefficient : 0.9982



Remark  
 1HPa = 0.750062 mmHg

**Calibrated by:** Ray Tam (  )

**Date:** 29 May 2013

**Checked by:** F.C. Tsang (  )

**Date:** 29 May 2013

**High Volume Air Sampler Calibration Worksheet**

**Project Title:** Design and Construction of Tsuen Wan Drainage Tunnel  
**Monitoring Location:** Greenview Terrace (ASR 9)  
**Calibration Date:** 29-May-13  
**Calibration Due Date:** 29-Jul-13  
**Time:** 8:00

|                         |          |
|-------------------------|----------|
| Sampler Model:          | TE5005X  |
| Serial No.:             | 1713     |
| Calibrator Orifice no.: | 1785     |
| Slope (m):              | 2.00979  |
| Intercept (b):          | -0.01403 |
| Correction coeff. (r)   | 0.99995  |


$$\text{Flow (corrected)} = \sqrt{H \times \frac{Pa}{Pstd} \times \frac{Tstd}{Ta}}$$

|                                 |       |
|---------------------------------|-------|
| Standard pressure (mmHg) Pstd:  | 763.9 |
| Standard temp. (K) Tstd:        | 290.8 |
| Calibration pressure (mmHg) Pa: | 758.2 |
| Calibration temp. (K) Ta:       | 301.9 |


$$Qstd = \frac{1}{m} \times \left( \sqrt{H \times \frac{Pa}{Pstd} \times \frac{Tstd}{Ta}} - b \right)$$

| Sample no. | Pressure Drop (H), inch | Flow (corrected), m <sup>3</sup> /min | Actual flow rate (Qstd), m <sup>3</sup> /min | Flow indication (I), arbitrary |
|------------|-------------------------|---------------------------------------|--|--------------------------------|
| 1          | 11.6                    | 3.371                                 | 1.684  | 55.0                           |
| 2          | 9.5                     | 3.051                                 | 1.525  | 50.0                           |
| 3          | 7.0                     | 2.619                                 | 1.310  | 45.0                           |
| 4          | 4.7                     | 2.146                                 | 1.075  | 36.0                           |
| 5          | 2.8                     | 1.656                                 | 0.831  | 27.0                           |


Correlation Coefficient : 0.9962



Remark  
 1HPa = 0.750062 mmHg

**Calibrated by:** Ray Tam (  )

**Date:** 29 May 2013

**Checked by:** F.C. Tsang (  )

**Date:** 29 May 2013





TISCH ENVIRONMENTAL, INC.  
 145 SOUTH MIAMI AVE.  
 VILLAGE OF CLEVELAND, OH 45002  
 513.467.9000  
 877.263.7610 TOLL FREE  
 513.467.9009 FAX  
 WWW.TISCH-ENV.COM

**AIR POLLUTION MONITORING EQUIPMENT**  
 ORIFICE TRANSFER STANDARD CERTIFICATION WORKSHEET TE-5025A

Date - Apr 15, 2013    Roots-meter S/N    0438320    Ta (K) -    294  
 Operator Tisch    Orifice I.D. -    1785    Pa (mm) -    750.57

| PLATE OR Run # | VOLUME START (m3) | VOLUME STOP (m3) | DIFF VOLUME (m3) | DIFF TIME (min) | METER DIFF Hg (mm) | ORFICE DIFF H2O (in.) |
|----------------|-------------------|------------------|------------------|-----------------|--------------------|-----------------------|
| 1              | NA                | NA               | 1.00             | 1.4050          | 3.2                | 2.00                  |
| 2              | NA                | NA               | 1.00             | 0.9870          | 6.4                | 4.00                  |
| 3              | NA                | NA               | 1.00             | 0.8850          | 7.9                | 5.00                  |
| 4              | NA                | NA               | 1.00             | 0.8420          | 8.7                | 5.50                  |
| 5              | NA                | NA               | 1.00             | 0.6960          | 12.7               | 8.00                  |

DATA TABULATION

| Vstd                                | (x axis) Qstd | (y axis) | Va                        | (x axis) Qa | (y axis) |
|-------------------------------------|---------------|----------|---------------------------|-------------|----------|
| 0.9967                              | 0.7094        | 1.4149   | 0.9957                    | 0.7087      | 0.8851   |
| 0.9925                              | 1.0056        | 2.0010   | 0.9915                    | 1.0045      | 1.2517   |
| 0.9904                              | 1.1191        | 2.2372   | 0.9894                    | 1.1179      | 1.3995   |
| 0.9894                              | 1.1751        | 2.3464   | 0.9884                    | 1.1739      | 1.4678   |
| 0.9840                              | 1.4139        | 2.8299   | 0.9830                    | 1.4124      | 1.7702   |
| Qstd slope (m) = 2.00979            |               |          | Qa slope (m) = 1.25849    |             |          |
| intercept (b) = -0.01403            |               |          | intercept (b) = -0.00878  |             |          |
| coefficient (r) = 0.99995           |               |          | coefficient (r) = 0.99995 |             |          |
| y axis = SQRT[H2O(Pa/760) (298/Ta)] |               |          | y axis = SQRT[H2O(Ta/Pa)] |             |          |

CALCULATIONS

Vstd = Diff. Vol [(Pa-Diff. Hg)/760] (298/Ta)  
 Qstd = Vstd/Time

Va = Diff Vol [(Pa-Diff Hg)/Pa]  
 Qa = Va/Time

For subsequent flow rate calculations:

Qstd = 1/m { [SQRT(H2O(Pa/760) (298/Ta))] - b }  
 Qa = 1/m { [SQRT H2O(Ta/Pa)] - b }

# Certificate of Calibration

## 校正證書

Certificate No. : C123580

證書編號

### ITEM TESTED / 送檢項目 ( Job No. / 序引編號 : IC12-1472 )

Description / 儀器名稱 : Sound Level Meter  
Manufacturer / 製造商 : Rion  
Model No. / 型號 : NL-31  
Serial No. / 編號 : 00410224  
Supplied By / 委託者 : Envirotech Services Co.  
Shop 6, G/F., Casio Mansion, 209 Shaukeiwan Road,  
Hong Kong

### TEST CONDITIONS / 測試條件

Temperature / 溫度 :  $(23 \pm 2)^{\circ}\text{C}$       Relative Humidity / 相對濕度 :  $(55 \pm 20)\%$   
Line Voltage / 電壓 : ---

### TEST SPECIFICATIONS / 測試規範

Calibration check

DATE OF TEST / 測試日期 : 15 June 2012

### TEST RESULTS / 測試結果

The results apply to the particular unit-under-test only.  
All results are within manufacturer's specification.  
The results are detailed in the subsequent page(s).

The test equipment used for calibration are traceable to National Standards via :

- The Government of The Hong Kong Special Administrative Region Standard & Calibration Laboratory
- Rohde & Schwarz Laboratory, Germany
- Fluke Precision Measurement Ltd., UK
- Fluke Everett Service Center, USA
- Agilent Technologies, USA

Tested By :   
測試 : L K Yeung

Certified By :   
核證 : K C Lee

Date of Issue : 15 June 2012  
簽發日期

The test equipment used for calibration are traceable to the Nation Standards as specified in this certificate. This certificate shall not be reproduced except in full, without the prior written approval of this laboratory.

本證書所載校正用之測試器材均可溯源至國際標準。局部複印本證書需先獲本實驗所書面批准。

# Certificate of Calibration

## 校正證書

Certificate No. : C123580  
證書編號

- The unit-under-test (UUT) was allowed to stabilize in the laboratory for over 12 hours, and switched on to warm up for over 10 minutes before the commencement of the test.
- Self-calibration was performed before the test.
- The results presented are the mean of 3 measurements at each calibration point.
- Test equipment :

| Equipment ID | Description                         | Certificate No. |
|--------------|-------------------------------------|-----------------|
| CL280        | 40 MHz Arbitrary Waveform Generator | C120016         |
| CL281        | Multifunction Acoustic Calibrator   | DC110233        |

- Test procedure : MA101N.

- Results :

- 6.1 Sound Pressure Level

- 6.1.1 Reference Sound Pressure Level

| UUT Setting |                |                     |                | Applied Value |             | UUT Reading (dB) | IEC 61672 Class 1 Spec. (dB) |
|-------------|----------------|---------------------|----------------|---------------|-------------|------------------|------------------------------|
| Range (dB)  | Mode           | Frequency Weighting | Time Weighting | Level (dB)    | Freq. (kHz) |                  |                              |
| 30 - 120    | L <sub>A</sub> | A                   | Fast           | 94.00         | 1           | 93.7             | ± 1.1                        |

- 6.1.2 Linearity

| UUT Setting |                |                     |                | Applied Value |             | UUT Reading (dB) |
|-------------|----------------|---------------------|----------------|---------------|-------------|------------------|
| Range (dB)  | Mode           | Frequency Weighting | Time Weighting | Level (dB)    | Freq. (kHz) |                  |
| 30 - 120    | L <sub>A</sub> | A                   | Fast           | 94.00         | 1           | 93.7 (Ref.)      |
|             |                |                     |                | 104.00        |             | 103.7            |
|             |                |                     |                | 114.00        |             | 113.7            |

IEC 61672 Class 1 Spec. : ± 0.6 dB per 10 dB step and ± 1.1 dB for overall different.

- 6.2 Time Weighting

| UUT Setting |                |                     |                | Applied Value |             | UUT Reading (dB) | IEC 61672 Class 1 Spec. (dB) |
|-------------|----------------|---------------------|----------------|---------------|-------------|------------------|------------------------------|
| Range (dB)  | Mode           | Frequency Weighting | Time Weighting | Level (dB)    | Freq. (kHz) |                  |                              |
| 30 - 120    | L <sub>A</sub> | A                   | Fast           | 94.00         | 1           | 93.7             | Ref.                         |
|             |                |                     | Slow           |               |             | 93.6             | ± 0.3                        |

The test equipment used for calibration are traceable to the Nation Standards as specified in this certificate. This certificate shall not be reproduced except in full, without the prior written approval of this laboratory.

本證書所載校正用之測試器材均可溯源至國際標準。局部複印本證書需先獲本實驗室所書面批准。

# Certificate of Calibration

## 校正證書

Certificate No. : C123580  
證書編號

### 6.3 Frequency Weighting

#### 6.3.1 A-Weighting

| UUT Setting |                |                     |                | Applied Value |          | UUT Reading (dB) | IEC 61672 Class 1 Spec. (dB) |
|-------------|----------------|---------------------|----------------|---------------|----------|------------------|------------------------------|
| Range (dB)  | Mode           | Frequency Weighting | Time Weighting | Level (dB)    | Freq.    |                  |                              |
| 30 - 120    | L <sub>A</sub> | A                   | Fast           | 94.00         | 63 Hz    | 67.3             | -26.2 ± 1.5                  |
|             |                |                     |                |               | 125 Hz   | 77.4             | -16.1 ± 1.5                  |
|             |                |                     |                |               | 250 Hz   | 85.0             | -8.6 ± 1.4                   |
|             |                |                     |                |               | 500 Hz   | 90.4             | -3.2 ± 1.4                   |
|             |                |                     |                |               | 1 kHz    | 93.7             | Ref.                         |
|             |                |                     |                |               | 2 kHz    | 95.0             | +1.2 ± 1.6                   |
|             |                |                     |                |               | 4 kHz    | 94.8             | +1.0 ± 1.6                   |
|             |                |                     |                |               | 8 kHz    | 92.7             | -1.1 (+2.1 ; -3.1)           |
|             |                |                     |                |               | 12.5 kHz | 89.8             | -4.3 (+3.0 ; -6.0)           |

#### 6.3.2 C-Weighting

| UUT Setting |                |                     |                | Applied Value |          | UUT Reading (dB) | IEC 61672 Class 1 Spec. (dB) |
|-------------|----------------|---------------------|----------------|---------------|----------|------------------|------------------------------|
| Range (dB)  | Mode           | Frequency Weighting | Time Weighting | Level (dB)    | Freq.    |                  |                              |
| 30 - 120    | L <sub>C</sub> | C                   | Fast           | 94.00         | 63 Hz    | 92.8             | -0.8 ± 1.5                   |
|             |                |                     |                |               | 125 Hz   | 93.5             | -0.2 ± 1.5                   |
|             |                |                     |                |               | 250 Hz   | 93.7             | 0.0 ± 1.4                    |
|             |                |                     |                |               | 500 Hz   | 93.8             | 0.0 ± 1.4                    |
|             |                |                     |                |               | 1 kHz    | 93.7             | Ref.                         |
|             |                |                     |                |               | 2 kHz    | 93.6             | -0.2 ± 1.6                   |
|             |                |                     |                |               | 4 kHz    | 93.1             | -0.8 ± 1.6                   |
|             |                |                     |                |               | 8 kHz    | 90.8             | -3.0 (+2.1 ; -3.1)           |
|             |                |                     |                |               | 12.5 kHz | 88.0             | -6.2 (+3.0 ; -6.0)           |

Remarks : - Mfr's Spec. : IEC 61672 Class 1

- Uncertainties of Applied Value : 94 dB : 63 Hz - 125 Hz : ± 0.35 dB  
 250 Hz - 500 Hz : ± 0.30 dB  
 1 kHz : ± 0.20 dB  
 2 kHz - 4 kHz : ± 0.35 dB  
 8 kHz : ± 0.45 dB  
 12.5 kHz : ± 0.70 dB  
 104 dB : 1 kHz : ± 0.10 dB (Ref. 94 dB)  
 114 dB : 1 kHz : ± 0.10 dB (Ref. 94 dB)

- The uncertainties are for a confidence probability of not less than 95 %.

#### Note :

The values given in this Certificate only relate to the values measured at the time of the test and any uncertainties quoted will not include allowance for the equipment long term drift, variations with environment changes, vibration and shock during transportation, overloading, mis-handling, or the capability of any other laboratory to repeat the measurement. Sun Creation Engineering Limited shall not be liable for any loss or damage resulting from the use of the equipment.

The test equipment used for calibration are traceable to the Nation Standards as specified in this certificate. This certificate shall not be reproduced except in full, without the prior written approval of this laboratory.

本證書所載校正用之測試器材均可溯源至國際標準。局部複印本證書需先獲本實驗室書面批准。

# Certificate of Calibration

## 校正證書

Certificate No. : C126333

證書編號

### ITEM TESTED / 送檢項目 (Job No. / 序引編號 : IC12-2717)

Description / 儀器名稱 : Integrating Sound Level Meter  
Manufacturer / 製造商 : Brüel & Kjær  
Model No. / 型號 : 2238  
Serial No. / 編號 : 2448529  
Supplied By / 委託者 : Hyder Consulting Limited  
47/F., Hopewell Centre, 183 Queen's Road East,  
Wanchai, Hong Kong

### TEST CONDITIONS / 測試條件

Temperature / 溫度 :  $(23 \pm 2)^{\circ}\text{C}$       Relative Humidity / 相對濕度 :  $(55 \pm 20)\%$   
Line Voltage / 電壓 : ---

### TEST SPECIFICATIONS / 測試規範

Calibration check

DATE OF TEST / 測試日期 : 3 November 2012

### TEST RESULTS / 測試結果

The results apply to the particular unit-under-test only.  
All results are within manufacturer's specification.  
The results are detailed in the subsequent page(s).

The test equipment used for calibration are traceable to National Standards via :

- The Government of The Hong Kong Special Administrative Region Standard & Calibration Laboratory
- Rohde & Schwarz Laboratory, Germany
- Fluke Precision Measurement Ltd., UK
- Fluke Everett Service Center, USA
- Agilent Technologies, USA

Tested By :   
測試 : K C Lee

Certified By :   
核證 : C C Cheung

Date of Issue : 5 November 2012  
簽發日期

The test equipment used for calibration are traceable to the Nation Standards as specified in this certificate. This certificate shall not be reproduced except in full, without the prior written approval of this laboratory.

本證書所載校正用之測試器材均可溯源至國際標準。局部複印本證書需先獲本實驗室書面批准。

# Certificate of Calibration

## 校正證書

Certificate No. : C126665

證書編號

ITEM TESTED / 送檢項目 ( Job No. / 序引編號 : IC12-2878 )

Description / 儀器名稱 : Sound Level Calibrator  
Manufacturer / 製造商 : Rion  
Model No. / 型號 : NC-73  
Serial No. / 編號 : 10486660  
Supplied By / 委託者 : Envirotech Services Co.  
Shop 6, G/F., Casio Mansion, 209 Shaukeiwan Road,  
Hong Kong

TEST CONDITIONS / 測試條件

Temperature / 溫度 :  $(23 \pm 2)^{\circ}\text{C}$

Relative Humidity / 相對濕度 :  $(55 \pm 20)\%$

Line Voltage / 電壓 : ---

TEST SPECIFICATIONS / 測試規範

Calibration check

DATE OF TEST / 測試日期 : 19 November 2012

TEST RESULTS / 測試結果

The results apply to the particular unit-under-test only.  
All results are within manufacturer's specification.  
The results are detailed in the subsequent page(s).

The test equipment used for calibration are traceable to National Standards via :

- The Government of The Hong Kong Special Administrative Region Standard & Calibration Laboratory
- Rohde & Schwarz Laboratory, Germany
- Fluke Everett Service Center, USA
- Agilent Technologies, USA

Tested By :   
測試 : K C Lee

Certified By :   
核證 : C C Cheung

Date of Issue : 21 November 2012  
簽發日期

The test equipment used for calibration are traceable to the Nation Standards as specified in this certificate. This certificate shall not be reproduced except in full, without the prior written approval of this laboratory.

本證書所載校正用之測試器材均可溯源至國際標準。局部複印本證書需先獲本實驗室書面批准。



# Calibration Certificate

Certificate No. **28658**

Page 1 of 2 Pages

**Customer :** Hyder Consulting Limited

**Address :** 47/F., Hopewell Centre, 183 Queens Road East, Wanchai, Hong Kong

**Order No. :** Q23280

**Date of receipt :** 17-Dec-12

## Item Tested

**Description :** Sound Level Calibrator

**Manufacturer :** B&K

**Model :** Type 4231

**Serial No. :** 2699361

## Test Conditions

**Date of Test :** 28-Dec-12

**Supply Voltage :** --

**Ambient Temperature :** (23 ± 3)°C

**Relative Humidity :** (50 ± 25) %

## Test Specifications

Calibration check.

Ref. Document/Procedure : F21, Z02.

## Test Results

All results were within the IEC 942 Class 1 specification.

The results are shown in the attached page(s).


Main Test equipment used:


| <u>Equipment No.</u> | <u>Description</u>     | <u>Cert. No.</u> | <u>Traceable to</u> |
|----------------------|------------------------|------------------|---------------------|
| S014                 | Spectrum Analyzer      | 13535            | NIM-PRC & SCL-HKSAR |
| S024                 | Sound Level Calibrator | 28588            | NIM-PRC & SCL-HKSAR |
| S041                 | Universal Counter      | 28347            | SCL-HKSAR           |
| S206                 | Sound Level Meter      | 16338            | SCL-HKSAR           |

The values given in this Calibration Certificate only relate to the values measured at the time of the test and any uncertainties quoted will not include allowance for the equipment long term drift, variations with environmental changes, vibration and shock during transportation, overloading, mis-handling, or the capability of any other laboratory to repeat the measurement. Hong Kong Calibration Ltd. shall not be liable for any loss or damage resulting from the use of the equipment.

The test equipment used for calibration are traceable to International System of Units (SI).

The test results apply to the above Unit-Under-Test only

**Calibrated by :**   
P. F. Wong

**Approved by :**   
Dorothy Cheuk

**Date:** 28-Dec-12

This Certificate is issued by:

Hong Kong Calibration Ltd.

Unit 8B, 24/F., Well Fung Industrial Centre, No. 58-76, Ta Chuen Ping Street, Kwai Chung, NT, Hong Kong.

Tel: 2425 8801 Fax: 2425 8646



# Calibration Certificate

Certificate No. 28658

Page 2 of 2 Pages

Results :

## 1. Level Accuracy

| UUT Nominal Value (dB) | Measured Value (dB) | IEC 942 Class 1 Spec. |
|------------------------|---------------------|-----------------------|
| 94                     | 94.10               | ± 0.3 dB              |
| 114                    | 114.14              |                       |

Uncertainty : ± 0.1 dB

## 2. Frequency

| UUT Nominal Value | Measured Value | IEC 942 Class 1 Spec. |
|-------------------|----------------|-----------------------|
| 1 kHz             | 1.000 kHz      | ± 2 %                 |

Uncertainty : ± 3.6 x 10<sup>-6</sup>

- 3. Level Stability : 0.0 dB**  
IEC 942 Class 1 Spec. : ± 0.1 dB  
Uncertainty : ± 0.01 dB

- 4. Total Harmonic Distortion : < 0.5 %**  
IEC 942 Class 1 Spec. : < 3 %  
Uncertainty : ± 2.3 % of reading

Remark : 1. UUT : Unit-Under-Test

2. The above measured values are the mean of 3 measurement.
3. The uncertainty claimed is for a confidence probability of not less than 95%.
4. Atmospheric Pressure : 1005 hPa.

----- END -----



# REPORT OF EQUIPMENT PERFORMANCE CHECK/CALIBRATION



**Work Order:** HK1306753  
**Date of Issue:** 15/03/2013  
**Client:** HYDER CONSULTING LIMITED

**Description:** Multimeter  
**Brand Name:** YSI  
**Model No.:** Professional Plus  
**Serial No.:** 11J100824  
**Equipment No.:** --  
**Date of Calibration:** 15 March, 2013      **Date of next Calibration:** 15 June, 2013

**Parameters:**

**Dissolved Oxygen**

**Method Ref: APHA (21st edition), 4500O: G**

| Expected Reading (mg/L)       | Displayed Reading (mg/L) | Tolerance (mg/L) |
|-------------------------------|--------------------------|------------------|
| 2.73                          | 2.82                     | 0.09             |
| 5.36                          | 5.51                     | 0.15             |
| 8.65                          | 8.74                     | 0.09             |
| Tolerance Limit ( $\pm$ mg/L) |                          | 0.20             |

**Temperature**

**Method Ref: Section 6 of International Accreditation New Zealand Technical Guide No. 3 Second edition March 2008: Working Thermometer Calibration Procedure.**

| Expected Reading ( $^{\circ}$ C)      | Displayed Reading ( $^{\circ}$ C) | Tolerance ( $^{\circ}$ C) |
|---------------------------------------|-----------------------------------|---------------------------|
| 9.0                                   | 9.1                               | 0.1                       |
| 23.0                                  | 22.5                              | -0.5                      |
| 45.0                                  | 46.3                              | 1.3                       |
| Tolerance Limit ( $\pm$ $^{\circ}$ C) |                                   | 2.0                       |

**pH Value**

**Method Ref: APHA 21st Ed. 4500H:B**

| Expected Reading (pH Unit)       | Displayed Reading (pH Unit) | Tolerance (pH unit) |
|----------------------------------|-----------------------------|---------------------|
| 4.0                              | 4.00                        | 0.00                |
| 7.0                              | 6.97                        | -0.03               |
| 10.0                             | 9.96                        | -0.04               |
| Tolerance Limit ( $\pm$ pH unit) |                             | 0.20                |

**Conductivity**

**Method Ref: APHA (21st edition), 2510B**

| Expected Reading (uS/cm)   | Displayed Reading (uS/cm) | Tolerance (%) |
|----------------------------|---------------------------|---------------|
| 146.9                      | 138.4                     | -5.8          |
| 6667                       | 6154                      | -7.7          |
| 12890                      | 11994                     | -7.0          |
| 58670                      | 55390                     | -5.6          |
| Tolerance Limit ( $\pm$ %) |                           | 10.0          |

Remark: "Displayed Reading" presents the figures shown on item under calibration / checking regardless of equipment precision or significant figures.

Mr. Fung Lim Chee, Richard  
 General Manager -  
 Greater China & Hong Kong

# REPORT OF EQUIPMENT PERFORMANCE CHECK/CALIBRATION

Work Order: HK1306041  
Date of Issue: 08/03/2013  
Client: HYDER CONSULTING LIMITED



Description: Turbidimeter  
Brand Name: HANNA  
Model No.: HI 98703-02  
Serial No.: 08498735  
Equipment No.: --  
Date of Calibration: 08 March, 2013

Date of next Calibration: 08 June, 2013

## Parameters:

### Turbidity

Method Ref: APHA 21st Ed. 2130B

| Expected Reading (NTU) | Displayed Reading (NTU)     | Tolerance (%) |
|------------------------|-----------------------------|---------------|
| 0                      | 0.05                        | --            |
| 4                      | 4.17                        | 4.3           |
| 40                     | 42.2                        | 5.5           |
| 80                     | 85.7                        | 7.1           |
| 400                    | 410                         | 2.5           |
| 800                    | 829                         | 3.6           |
|                        | Tolerance Limit ( $\pm\%$ ) | 10.0          |

Remark: "Displayed Reading" presents the figures shown on item under calibration / checking regardless of equipment precision or significant figures.

# REPORT OF EQUIPMENT PERFORMANCE CHECK/CALIBRATION



**Work Order:** HK1305864  
**Date of Issue:** 08/03/2013  
**Client:** HYDER CONSULTING LIMITED

**Description:** DO METER  
**Brand Name:** YSI  
**Model No.:** 55/12  
**Serial No.:** 95J38390  
**Equipment No.:** --

**Date of Calibration:** 08 March, 2013                      **Date of next Calibration:** 08 June, 2013

**Parameters:**

**Dissolved Oxygen**                      **Method Ref: APHA (21st edition), 4500O: G**

| Expected Reading (mg/L) | Displayed Reading (mg/L) | Tolerance (mg/L) |
|-------------------------|--------------------------|------------------|
| 5.45                    | 5.53                     | 0.08             |
| 6.62                    | 6.71                     | 0.09             |
| 8.77                    | 8.90                     | 0.13             |
|                         | Tolerance Limit (±mg/L)  | 0.20             |

**Temperature**

**Method Ref: Section 6 of International Accreditation New Zealand Technical Guide No. 3 Second edition March 2008: Working Thermometer Calibration Procedure.**

| Expected Reading (°C) | Displayed Reading (°C) | Tolerance (°C) |
|-----------------------|------------------------|----------------|
| 11.0                  | 11.2                   | 0.2            |
| 21.5                  | 21.0                   | -0.5           |
| 38.5                  | 38.7                   | 0.2            |
|                       | Tolerance Limit (±°C)  | 2.0            |

Remark: "Displayed Reading" presents the figures shown on item under calibration / checking regardless of equipment precision or significant figures.

  
 \_\_\_\_\_  
 Mr. Fung Lim Chee, Richard  
 General Manager -  
 Greater China & Hong Kong

# REPORT OF EQUIPMENT PERFORMANCE CHECK/CALIBRATION



**Work Order:** HK1307213  
**Date of Issue:** 20/03/2013  
**Client:** HYDER CONSULTING LIMITED

**Description:** pH meter  
**Brand Name:** Hanna  
**Model No.:** HI-8014  
**Serial No.:** SN 08345212  
**Equipment No.:** --  
**Date of Calibration:** 20 March, 2013

**Date of next Calibration:** 20 June, 2013

**Parameters:**

**pH Value**

**Method Ref: APHA 21st Ed. 4500H:B**

| Expected Reading (pH Unit) | Displayed Reading (pH Unit)      | Tolerance (pH unit) |
|----------------------------|----------------------------------|---------------------|
| 4.0                        | 4.06                             | 0.06                |
| 7.0                        | 7.09                             | 0.09                |
| 10.0                       | 10.02                            | 0.02                |
|                            | Tolerance Limit ( $\pm$ pH unit) | 0.20                |

Remark: "Displayed Reading" presents the figures shown on item under calibration / checking regardless of equipment precision or significant figures.

Mr. Fung Lim Chee, Richard  
 General Manager  
 Greater China & Hong Kong

## Appendix G

---

### Monitoring Locations




Figure 1 Air Quality Monitoring Stations




Figure 2 Noise Monitoring Stations




Figure 3 Water Quality Monitoring Stations: I-1 & I-1-C at Intake I-1







Figure 4 Water Quality Monitoring Stations: I-2 & I-2-C at Intake I-2



Figure 5 Water Quality Monitoring Stations: I-3 & I-3-C at Intake I-3



**Figure 6 Water Quality Monitoring Stations: O-1 (FT) & (ET), O-1-C(FT) & O-1-C(FT) at Outfall O-1**

## Appendix H

---

### EM&A Schedule

**Contract No. DC/2007/12 – Design and Construction of  
Tsuen Wan Drainage Tunnel  
Impact Monitoring Programme – May 13 (Tentative)**

| Date      |     | Air | Noise | Water |
|-----------|-----|-----|-------|-------|
| 1-May-13  | Wed |     |       |       |
| 2-May-13  | Thu |     |       | ✓     |
| 3-May-13  | Fri | ✓   |       |       |
| 4-May-13  | Sat |     |       | ✓     |
| 5-May-13  | Sun |     |       |       |
| 6-May-13  | Mon |     |       | ✓     |
| 7-May-13  | Tue |     |       |       |
| 8-May-13  | Wed | ✓   | ✓     | ✓     |
| 9-May-13  | Thu |     |       |       |
| 10-May-13 | Fri |     |       | ✓     |
| 11-May-13 | Sat |     |       |       |
| 12-May-13 | Sun |     |       |       |
| 13-May-13 | Mon |     |       | ✓     |
| 14-May-13 | Tue | ✓   | ✓     |       |
| 15-May-13 | Wed |     |       | ✓     |
| 16-May-13 | Thu |     |       |       |
| 17-May-13 | Fri |     |       |       |
| 18-May-13 | Sat |     |       | ✓     |
| 19-May-13 | Sun |     |       |       |
| 20-May-13 | Mon | ✓   | ✓     | ✓     |
| 21-May-13 | Tue |     |       |       |
| 22-May-13 | Wed |     |       | ✓     |
| 23-May-13 | Thu |     |       |       |
| 24-May-13 | Fri | ✓   |       | ✓     |
| 25-May-13 | Sat |     |       |       |
| 26-May-13 | Sun |     |       |       |
| 27-May-13 | Mon |     |       | ✓     |
| 28-May-13 | Tue |     |       |       |
| 29-May-13 | Wed |     |       | ✓     |
| 30-May-13 | Thu | ✓   | ✓     |       |
| 31-May-13 | Fri |     |       | ✓     |

**Note:**

Shaded area indicates public holiday.

Air – Monitoring 1-hour TSP is undertaken three times per every six days

Noise – Noise measurements is undertaken once every week at (0700-1900 Monday to Saturday)

Water –Water quality monitoring is undertaken three times per week

**Contract No. DC/2007/12 – Design and Construction of  
Tsuen Wan Drainage Tunnel  
Impact Monitoring Programme – June 13 (Tentative)**

| Date      |     | Air | Noise | Water |
|-----------|-----|-----|-------|-------|
| 1-Jun-13  | Sat |     |       |       |
| 2-Jun-13  | Sun |     |       |       |
| 3-Jun-13  | Mon |     |       | ✓     |
| 4-Jun-13  | Tue |     |       |       |
| 5-Jun-13  | Wed | ✓   | ✓     | ✓     |
| 6-Jun-13  | Thu |     |       |       |
| 7-Jun-13  | Fri |     |       | ✓     |
| 8-Jun-13  | Sat |     |       |       |
| 9-Jun-13  | Sun |     |       |       |
| 10-Jun-13 | Mon |     |       | ✓     |
| 11-Jun-13 | Tue | ✓   | ✓     |       |
| 12-Jun-13 | Wed |     |       |       |
| 13-Jun-13 | Thu |     |       | ✓     |
| 14-Jun-13 | Fri |     |       |       |
| 15-Jun-13 | Sat |     |       | ✓     |
| 16-Jun-13 | Sun |     |       |       |
| 17-Jun-13 | Mon | ✓   | ✓     | ✓     |
| 18-Jun-13 | Tue |     |       |       |
| 19-Jun-13 | Wed |     |       | ✓     |
| 20-Jun-13 | Thu |     |       |       |
| 21-Jun-13 | Fri | ✓   |       | ✓     |
| 22-Jun-13 | Sat |     |       |       |
| 23-Jun-13 | Sun |     |       |       |
| 24-Jun-13 | Mon |     |       | ✓     |
| 25-Jun-13 | Tue |     |       |       |
| 26-Jun-13 | Wed |     |       | ✓     |
| 27-Jun-13 | Thu | ✓   | ✓     |       |
| 28-Jun-13 | Fri |     |       | ✓     |
| 29-Jun-13 | Sat |     |       |       |
| 30-Jun-13 | Sun |     |       |       |

Note:

Shaded area indicates public holiday.

Air – Monitoring 1-hour TSP is undertaken three times per every six days

Noise – Noise measurements is undertaken once every week at (0700-1900 Monday to Saturday)

Water –Water quality monitoring is undertaken three times per week

**Contract No. DC/2007/12 – Design and Construction of  
Tsuen Wan Drainage Tunnel  
Impact Monitoring Programme – Jul 13 (Tentative)**

| Date      |     | Air | Noise | Water |
|-----------|-----|-----|-------|-------|
| 1-Jul-13  | Mon |     |       |       |
| 2-Jul-13  | Tue |     |       | ✓     |
| 3-Jul-13  | Wed | ✓   | ✓     |       |
| 4-Jul-13  | Thu |     |       | ✓     |
| 5-Jul-13  | Fri |     |       |       |
| 6-Jul-13  | Sat |     |       | ✓     |
| 7-Jul-13  | Sun |     |       |       |
| 8-Jul-13  | Mon |     |       | ✓     |
| 9-Jul-13  | Tue | ✓   | ✓     |       |
| 10-Jul-13 | Wed |     |       | ✓     |
| 11-Jul-13 | Thu |     |       |       |
| 12-Jul-13 | Fri |     |       | ✓     |
| 13-Jul-13 | Sat |     |       |       |
| 14-Jul-13 | Sun |     |       |       |
| 15-Jul-13 | Mon | ✓   | ✓     | ✓     |
| 16-Jul-13 | Tue |     |       |       |
| 17-Jul-13 | Wed |     |       | ✓     |
| 18-Jul-13 | Thu |     |       |       |
| 19-Jul-13 | Fri | ✓   |       | ✓     |
| 20-Jul-13 | Sat |     |       |       |
| 21-Jul-13 | Sun |     |       |       |
| 22-Jul-13 | Mon |     |       | ✓     |
| 23-Jul-13 | Tue |     |       |       |
| 24-Jul-13 | Wed |     |       | ✓     |
| 25-Jul-13 | Thu | ✓   | ✓     |       |
| 26-Jul-13 | Fri |     |       | ✓     |
| 27-Jul-13 | Sat |     |       |       |
| 28-Jul-13 | Sun |     |       |       |
| 29-Jul-13 | Mon |     |       | ✓     |
| 30-Jul-13 | Tue |     |       |       |
| 31-Jul-13 | Wed | ✓   | ✓     | ✓     |

**Note:**

Shaded area indicates public holiday.

Air – Monitoring 1-hour TSP is undertaken three times per every six days

Noise – Noise measurements is undertaken once every week at (0700-1900 Monday to Saturday)

Water –Water quality monitoring is undertaken three times per week

**Contract No. DC/2007/12 – Design and Construction of  
Tsuen Wan Drainage Tunnel  
Impact Monitoring Programme – August 13 (Tentative)**

| Date      |     | Air | Noise | Water |
|-----------|-----|-----|-------|-------|
| 1-Aug-13  | Thu |     |       |       |
| 2-Aug-13  | Fri |     |       | ✓     |
| 3-Aug-13  | Sat |     |       |       |
| 4-Aug-13  | Sun |     |       |       |
| 5-Aug-13  | Mon |     |       | ✓     |
| 6-Aug-13  | Tue | ✓   | ✓     |       |
| 7-Aug-13  | Wed |     |       | ✓     |
| 8-Aug-13  | Thu |     |       |       |
| 9-Aug-13  | Fri |     |       | ✓     |
| 10-Aug-13 | Sat |     |       |       |
| 11-Aug-13 | Sun |     |       |       |
| 12-Aug-13 | Mon | ✓   | ✓     | ✓     |
| 13-Aug-13 | Tue |     |       |       |
| 14-Aug-13 | Wed |     |       | ✓     |
| 15-Aug-13 | Thu |     |       |       |
| 16-Aug-13 | Fri | ✓   |       | ✓     |
| 17-Aug-13 | Sat |     |       |       |
| 18-Aug-13 | Sun |     |       |       |
| 19-Aug-13 | Mon |     |       | ✓     |
| 20-Aug-13 | Tue |     |       |       |
| 21-Aug-13 | Wed |     |       | ✓     |
| 22-Aug-13 | Thu | ✓   | ✓     |       |
| 23-Aug-13 | Fri |     |       | ✓     |
| 24-Aug-13 | Sat |     |       |       |
| 25-Aug-13 | Sun |     |       |       |
| 26-Aug-13 | Mon |     |       | ✓     |
| 27-Aug-13 | Tue |     |       |       |
| 28-Aug-13 | Wed | ✓   | ✓     | ✓     |
| 29-Aug-13 | Thu |     |       |       |
| 30-Aug-13 | Fri |     |       | ✓     |
| 31-Aug-13 | Sat |     |       |       |

**Note:**

Shaded area indicates public holiday.

Air – Monitoring 1-hour TSP is undertaken three times per every six days

Noise – Noise measurements is undertaken once every week at (0700-1900 Monday to Saturday)

Water –Water quality monitoring is undertaken three times per week



## Appendix I

---


### Monitoring Results

Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel


Air Quality Impact Monitoring Results (1-Hour TSP)

| Location                                     | Monitoring Date | Weather Conditions | Wind Speed with Direction (m/s) | Temp (°C) | Timer-I | Timer-F | Time (mins) | Flow-I (CFM) | Flow-F (CFM) | Flow-I (m³/min) | Flow-F (m³/min) | Flow-avg (m³/min) | Volume (m³) | Weight-H (g) | Weight-F (g) | Weight-diff. (g) | 1-hr TSP (µg/m³) | Average 1-Hr TSP (µg/m³) | Action/Limit Levels | Observation / Site Condition        | Other Possible Dust Sources |
|--|-----------------|--------------------|---------------------------------|-----------|---------|---------|-------------|--------------|--------------|-----------------|-----------------|-------------------|-------------|--------------|--------------|------------------|------------------|--------------------------|---------------------|-------------------------------------|-----------------------------|
| Sik Sik Yuen Ho Fung College - Intake (ASR1) | 3-May-13        | Cloudy             | 0.3E                            | 24        | 652642  | 652742  | 60.0        | 40           | 40           | 1.35            | 1.35            | 1.35              | 81.21       | 2.8530       | 2.8582       | 0.0052           | 64.0             | 70.6                     | 306.6/500           | Nil                                 | Vehicles                    |
|  |                 | Cloudy             | 0.3E                            | 24        | 652742  | 652842  | 60.0        | 40           | 40           | 1.35            | 1.35            | 1.35              | 81.21       | 2.8536       | 2.8695       | 0.0059           | 72.7             |                          |                     |                                     |                             |
|  | 8-May-13        | Cloudy             | 0.3E                            | 25        | 652942  | 653042  | 60.0        | 40           | 40           | 1.35            | 1.35            | 1.35              | 81.21       | 2.7584       | 2.7659       | 0.0075           | 92.4             | 87.8                     | 306.6/500           | Crane operation                     | Vehicles                    |
|  |                 | Cloudy             | 0.3E                            | 25        | 653042  | 653142  | 60.0        | 40           | 40           | 1.35            | 1.35            | 1.35              | 81.21       | 2.7647       | 2.7715       | 0.0068           | 83.7             |                          |                     |                                     |                             |
|  | 14-May-13       | Cloudy             | 0.3E                            | 25        | 653142  | 653242  | 60.0        | 40           | 40           | 1.35            | 1.35            | 1.35              | 81.21       | 2.7669       | 2.7740       | 0.0071           | 87.4             | 86.6                     | 306.6/500           | Nil                                 | Vehicles                    |
|  |                 | Sunny              | 0.5E                            | 27        | 653242  | 653342  | 60.0        | 40           | 40           | 1.35            | 1.35            | 1.35              | 81.21       | 2.8670       | 2.8739       | 0.0069           | 85.0             |                          |                     |                                     |                             |
|  | 20-May-13       | Sunny              | 0.5E                            | 27        | 653342  | 653442  | 60.0        | 40           | 40           | 1.35            | 1.35            | 1.35              | 81.21       | 2.8678       | 2.8640       | 0.0038           | 76.3             | 88.7                     | 306.6/500           | Rock breaking                       | Vehicles                    |
|  |                 | Sunny              | 0.5E                            | 27        | 653442  | 653542  | 60.0        | 40           | 40           | 1.35            | 1.35            | 1.35              | 81.21       | 2.8465       | 2.8548       | 0.0083           | 98.5             |                          |                     |                                     |                             |
|  | 24-May-13       | Sunny              | 0.3E                            | 31        | 653542  | 653642  | 60.0        | 40           | 40           | 1.35            | 1.35            | 1.35              | 81.21       | 2.8646       | 2.8726       | 0.0080           | 98.5             | 60.8                     | 306.6/500           | Nil                                 | Vehicles                    |
|  |                 | Sunny              | 0.3E                            | 31        | 653642  | 653742  | 60.0        | 40           | 40           | 1.35            | 1.35            | 1.35              | 81.21       | 2.8537       | 2.8608       | 0.0071           | 87.4             |                          |                     |                                     |                             |
|  | 30-May-13       | Sunny              | 0.3E                            | 31        | 653742  | 653842  | 60.0        | 40           | 40           | 1.35            | 1.35            | 1.35              | 81.21       | 2.8701       | 2.8766       | 0.0065           | 80.0             | 64.0                     | 306.6/500           | Nil                                 | Vehicles                    |
|  |                 | Sunny              | 0.3E                            | 28        | 653842  | 653942  | 60.0        | 40           | 40           | 1.35            | 1.35            | 1.35              | 81.21       | 2.8322       | 2.8384       | 0.0062           | 78.3             |                          |                     |                                     |                             |
| Hong Hoi Chee Hong Temple - Intake (ASR3)    | 3-May-13        | Sunny              | 0.3E                            | 28        | 654042  | 654142  | 60.0        | 40           | 40           | 1.35            | 1.35            | 1.35              | 81.21       | 2.8241       | 2.8277       | 0.0036           | 44.3             | 103.4                    | 306.6/500           | Crane operation and excavation work | Vehicles                    |
|  |                 | Sunny              | 0.3E                            | 28        | 654142  | 654242  | 60.0        | 40           | 40           | 1.27            | 1.27            | 1.27              | 76.05       | 2.8802       | 2.8855       | 0.0053           | 69.7             |                          |                     |                                     |                             |
|  | 8-May-13        | Sunny              | 0.3E                            | 30        | 654242  | 654342  | 60.0        | 40           | 40           | 1.27            | 1.27            | 1.27              | 76.05       | 2.8773       | 2.8826       | 0.0055           | 72.3             | 99.4                     | 327.4/500           | Crane operation and excavation work | Vehicles                    |
|  |                 | Sunny              | 0.3E                            | 24        | 621490  | 621590  | 60.0        | 40           | 40           | 1.36            | 1.36            | 1.36              | 81.53       | 2.8815       | 2.8914       | 0.0099           | 121.4            |                          |                     |                                     |                             |
|  | 14-May-13       | Cloudy             | 0.3E                            | 24        | 621590  | 621690  | 60.0        | 40           | 40           | 1.36            | 1.36            | 1.36              | 81.53       | 2.8827       | 2.8917       | 0.0090           | 110.4            | 78.9                     | 327.4/500           | Crane operation                     | Vehicles                    |
|  |                 | Cloudy             | 0.3E                            | 24        | 621690  | 621790  | 60.0        | 40           | 40           | 1.36            | 1.36            | 1.36              | 81.53       | 2.8827       | 2.8891       | 0.0064           | 78.5             |                          |                     |                                     |                             |
|  | 20-May-13       | Cloudy             | 0.4E                            | 25        | 621790  | 621890  | 60.0        | 40           | 40           | 1.36            | 1.36            | 1.36              | 81.53       | 2.8598       | 2.8652       | 0.0054           | 66.2             | 105.5                    | 327.4/500           | Crane operation                     | Vehicles                    |
|  |                 | Cloudy             | 0.4E                            | 25        | 621890  | 621990  | 60.0        | 40           | 40           | 1.36            | 1.36            | 1.36              | 81.53       | 2.8777       | 2.8839       | 0.0062           | 76.0             |                          |                     |                                     |                             |
|  | 24-May-13       | Cloudy             | 0.4E                            | 25        | 621990  | 622090  | 60.0        | 40           | 40           | 1.36            | 1.36            | 1.36              | 81.53       | 2.8423       | 2.8500       | 0.0077           | 158.8            | 79.3                     | 327.4/500           | Crane operation                     | Vehicles                    |
|  |                 | Sunny              | 0.3E                            | 27        | 622090  | 622190  | 60.0        | 40           | 40           | 1.36            | 1.36            | 1.36              | 81.53       | 2.8514       | 2.8598       | 0.0084           | 109.6            |                          |                     |                                     |                             |
|  | 30-May-13       | Sunny              | 0.3E                            | 27        | 622190  | 622290  | 60.0        | 40           | 40           | 1.36            | 1.36            | 1.36              | 81.53       | 2.8446       | 2.8505       | 0.0059           | 72.4             | 70.3                     | 327.4/500           | Crane operation                     | Vehicles                    |
|  |                 | Sunny              | 0.3E                            | 27        | 622290  | 622390  | 60.0        | 40           | 40           | 1.36            | 1.36            | 1.36              | 81.53       | 2.8394       | 2.8446       | 0.0052           | 63.8             |                          |                     |                                     |                             |
| Long Beach Gardens - Outfall (ASR8)          | 3-May-13        | Sunny              | 0.3E                            | 31        | 622390  | 622490  | 60.0        | 40           | 40           | 1.36            | 1.36            | 1.36              | 81.53       | 2.8325       | 2.8411       | 0.0086           | 105.5            | 47.1                     | 336.6/500           | Crane operation and concrete work   | Vehicles                    |
|  |                 | Sunny              | 0.3E                            | 31        | 622490  | 622590  | 60.0        | 40           | 40           | 1.36            | 1.36            | 1.36              | 81.53       | 2.8327       | 2.8431       | 0.0104           | 127.6            |                          |                     |                                     |                             |
|  | 8-May-13        | Sunny              | 0.3E                            | 31        | 622590  | 622690  | 60.0        | 40           | 40           | 1.36            | 1.36            | 1.36              | 81.53       | 2.8536       | 2.8603       | 0.0068           | 83.4             | 92.5                     | 336.6/500           | Crane operation and rock breaking   | Vehicles                    |
|  |                 | Sunny              | 0.3E                            | 28        | 622690  | 622790  | 60.0        | 40           | 40           | 1.36            | 1.36            | 1.36              | 81.53       | 2.8540       | 2.8616       | 0.0076           | 93.2             |                          |                     |                                     |                             |
|  | 14-May-13       | Sunny              | 0.3E                            | 28        | 622790  | 622890  | 60.0        | 40           | 40           | 1.36            | 1.36            | 1.36              | 81.53       | 2.8513       | 2.8594       | 0.0081           | 99.4             | 68.5                     | 336.6/500           | Crane operation and excavation work | Vehicles                    |
|  |                 | Sunny              | 0.3E                            | 28        | 622890  | 622990  | 60.0        | 40           | 40           | 1.36            | 1.36            | 1.36              | 81.53       | 2.8403       | 2.844        | 0.0037           | 45.4             |                          |                     |                                     |                             |
|  | 20-May-13       | Sunny              | 0.4E                            | 30        | 622990  | 623090  | 60.0        | 40           | 40           | 1.19            | 1.19            | 1.19              | 71.65       | 2.8640       | 2.8691       | 0.0051           | 71.2             | 83.1                     | 336.6/500           | Crane operation and excavation work | Vehicles                    |
|  |                 | Sunny              | 0.4E                            | 30        | 623090  | 623190  | 60.0        | 40           | 40           | 1.19            | 1.19            | 1.19              | 71.65       | 2.8655       | 2.8707       | 0.0052           | 72.6             |                          |                     |                                     |                             |
|  | 24-May-13       | Sunny              | 0.4E                            | 30        | 623190  | 623290  | 60.0        | 40           | 40           | 1.19            | 1.19            | 1.19              | 71.65       | 2.8659       | 2.8707       | 0.0048           | 67.0             | 81.8                     | 336.6/500           | Crane operation and excavation work | Vehicles                    |
|  |                 | Sunny              | 0.5E                            | 24        | 615634  | 615734  | 60.0        | 40           | 40           | 1.30            | 1.30            | 1.30              | 77.86       | 2.8565       | 2.8597       | 0.0032           | 41.1             |                          |                     |                                     |                             |
|  | 30-May-13       | Cloudy             | 0.5E                            | 24        | 615734  | 615834  | 60.0        | 40           | 40           | 1.30            | 1.30            | 1.30              | 77.86       | 2.7947       | 2.7999       | 0.0052           | 66.8             | 64.3                     | 336.6/500           | Crane operation and excavation work | Vehicles                    |
|  |                 | Cloudy             | 0.5E                            | 24        | 615834  | 615934  | 60.0        | 40           | 40           | 1.30            | 1.30            | 1.30              | 77.86       | 2.8565       | 2.8591       | 0.0026           | 33.4             |                          |                     |                                     |                             |
| Greenview Terrace - Outfall (ASR9)           | 3-May-13        | Cloudy             | 0.5E                            | 25        | 615934  | 616034  | 60.0        | 40           | 40           | 1.30            | 1.30            | 1.30              | 77.86       | 2.7666       | 2.7743       | 0.0077           | 98.9             | 108.7                    | 329.2/500           | Crane operation and rock breaking   | Vehicles                    |
|  |                 | Cloudy             | 0.5E                            | 25        | 616034  | 616134  | 60.0        | 40           | 40           | 1.30            | 1.30            | 1.30              | 77.86       | 2.7741       | 2.7816       | 0.0075           | 96.3             |                          |                     |                                     |                             |
|  | 8-May-13        | Cloudy             | 0.5E                            | 25        | 616134  | 616234  | 60.0        | 40           | 40           | 1.30            | 1.30            | 1.30              | 77.86       | 2.7782       | 2.7848       | 0.0066           | 82.2             | 66.5                     | 329.2/500           | Crane operation and excavation work | Vehicles                    |
|  |                 | Sunny              | 0.4E                            | 27        | 616234  | 616334  | 60.0        | 40           | 40           | 1.30            | 1.30            | 1.30              | 77.86       | 2.8518       | 2.8580       | 0.0062           | 79.6             |                          |                     |                                     |                             |
|  | 14-May-13       | Sunny              | 0.4E                            | 27        | 616334  | 616434  | 60.0        | 40           | 40           | 1.30            | 1.30            | 1.30              | 77.86       | 2.8555       | 2.8606       | 0.0051           | 65.5             | 81.8                     | 329.2/500           | Crane operation and excavation work | Vehicles                    |
|  |                 | Sunny              | 0.4E                            | 27        | 616434  | 616534  | 60.0        | 40           | 40           | 1.30            | 1.30            | 1.30              | 77.86       | 2.8530       | 2.8577       | 0.0047           | 60.4             |                          |                     |                                     |                             |
|  | 20-May-13       | Sunny              | 0.4E                            | 31        | 616534  | 616634  | 60.0        | 40           | 40           | 1.30            | 1.30            | 1.30              | 77.86       | 2.8323       | 2.8380       | 0.0057           | 73.2             | 80.0                     | 329.2/500           | Crane operation and excavation work | Vehicles                    |
|  |                 | Sunny              | 0.4E                            | 31        | 616634  | 616734  | 60.0        | 40           | 40           | 1.30            | 1.30            | 1.30              | 77.86       | 2.8307       | 2.8379       | 0.0072           | 92.5             |                          |                     |                                     |                             |
|  | 24-May-13       | Sunny              | 0.4E                            | 31        | 616734  | 616834  | 60.0        | 40           | 40           | 1.30            | 1.30            | 1.30              | 77.86       | 2.8204       | 2.8269       | 0.0065           | 83.5             | 64.3                     | 329.2/500           | Crane operation and excavation work | Vehicles                    |
|  |                 | Sunny              | 0.5E                            | 28        | 616842  | 616942  | 60.0        | 40           | 40           | 1.30            | 1.30            | 1.30              | 77.86       | 2.8644       | 2.8703       | 0.0059           | 75.8             |                          |                     |                                     |                             |
|  | 30-May-13       | Sunny              | 0.5E                            | 28        | 616942  | 617042  | 60.0        | 40           | 40           | 1.30            | 1.30            | 1.30              | 77.86       | 2.8447       | 2.8502       | 0.0055           | 70.6             | 80.9                     | 329.2/500           | Crane operation and excavation work | Vehicles                    |
|  |                 | Sunny              | 0.5E                            | 28        | 617042  | 617142  | 60.0        | 40           | 40           | 1.30            | 1.30            | 1.30              | 77.86       | 2.8848       | 2.8925       | 0.0077           | 98.9             |                          |                     |                                     |                             |
| Greenview Terrace - Outfall (ASR9)           | 3-May-13        | Sunny              | 0.5E                            | 30        | 617142  | 617242  | 60.0        | 40           | 40           | 1.21            | 1.21            | 1.21              | 72.57       | 2.8707       | 2.8759       | 0.0052           | 71.7             | 108.7                    | 329.2/500           | Crane operation and excavation work | Vehicles                    |
|  |                 | Sunny              | 0.5E                            | 30        | 617242  | 617342  | 60.0        | 40           | 40           | 1.21            | 1.21            | 1.21              | 72.57       | 2.8249       | 2.8296       | 0.0047           | 64.8             |                          |                     |                                     |                             |
|  | 8-May-13        | Sunny              | 0.5E                            | 30        | 617342  | 617442  | 60.0        | 40           | 40           | 1.21            | 1.21            | 1.21              | 72.57       | 2.8396       | 2.8437       | 0.0041           | 56.5             | 66.5                     | 329.2/500           | Crane operation and excavation work | Vehicles                    |
|  |                 | Cloudy             | 0.5E                            | 24        | 608180  | 608280  | 60.0        | 40           | 40           | 1.24            | 1.24            | 1.24              | 74.19       | 2.8814       | 2.8861       | 0.0047           | 63.3             |                          |                     |                                     |                             |
|  | 14-May-13       | Cloudy             | 0.5E                            | 24        | 608280  | 608380  | 60.0        | 40           | 40           | 1.24            | 1.24            | 1.24              | 74.19       | 2.8297       | 2.8370       | 0.0073           | 98.4             | 98.4                     | 329.2/500           | Crane operation and concrete work   | Vehicles                    |
|  |                 | Cloudy             | 0.5E                            | 24        | 608380  | 608480  | 60.0        | 40           | 40           | 1.24            | 1.24            | 1.24              | 74.19       | 2.8728       | 2.8788       | 0.0060           | 80.9             |                          |                     |                                     |                             |
|  | 20-May-13       | Cloudy             | 0.5E                            | 25        | 608480  | 608580  | 60.0        | 40           | 40           | 1.24            | 1.24            | 1.24              | 74.19       | 2.7713       | 2.7820       | 0.0107           | 144.2            | 108.7                    | 329.2/500           | Crane operation and rock breaking   | Vehicles                    |
|  |                 | Cloudy             | 0.5E                            | 25        | 608580  | 608680  | 60.0        | 40           | 40           | 1.24            | 1.24            | 1.24              | 74.19       | 2.8478       | 2.8548       | 0.0070           | 94.3             |                          |                     |                                     |                             |
|  | 24-May-13       | Cloudy             | 0.5E                            | 25        | 608680  | 608780  | 60.0        | 40           | 40           | 1.24            | 1.24            | 1.24              | 74.19       | 2.8555       | 2.8620       | 0.0065           | 87.6             | 98.4                     | 329.2/500           | Crane operation and excavation work | Vehicles                    |
|  |                 | Sunny              | 0.4E                            | 27        | 608780  | 608880  | 60.0        | 40           | 40           | 1.24            | 1.24            | 1.24              | 74.19       | 2.8930       | 2.8975       | 0.0045           | 60.7             |                          |                     |                                     |                             |
|  |                 |                    |                                 |           |         |         |             |              |              |                 |                 |                   |             |              |              |                  |                  |                          |                     |                                     |                             |


**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
 Air Quality Monitoring (1-hr TSP) Results at Sik Sik Yuen Ho Fung College - Intake (ASR1)  
 Feb-13 to May-13**




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
 Air Quality Monitoring (1-hr TSP) Results at Hong Hoi Chee Hong Temple - Intake (ASR3)  
 Feb-13 to May-13**



**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
 Air Quality Monitoring (1-hr TSP) Results at Long Beach Gardens - Outfall (ASR8)  
 Feb-13 to May-13**



**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
 Air Quality Monitoring (1-hr TSP) Results at Greenview Terrace - Outfall (ASR9)  
 Feb-13 to May-13**



Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel


Noise Impact Monitoring Results

| Monitoring Locations                  | Date      | Weather Conditions | Temperature (°C) | Wind Speed (m/s) | Wind Direction | Start Time | End Time | BL <sup>1</sup><br>dB(A) | LL <sup>2</sup> | L <sub>eq(30min)</sub> | L <sub>10(30min)</sub> | L <sub>90(30min)</sub> | CNL <sup>3</sup> | Observation / Site Condition        | Other Noise Sources              |
|---------------------------------------|-----------|--------------------|------------------|------------------|----------------|------------|----------|--------------------------|-----------------|------------------------|------------------------|------------------------|------------------|-------------------------------------|----------------------------------|
|                                       |           |                    |                  |                  |                |            |          |                          | dB(A)           | dB(A)                  | dB(A)                  | dB(A)                  | dB(A)            |                                     |                                  |
| Sik Sik Yuen Ho Fung College<br>NSR 1 | 8-May-13  | Cloudy             | 25               | 0.3              | E              | 15:16      | 15:46    | 66.1                     | 70              | 63.6                   | 66.1                   | 60.2                   | -                | Crane operation                     | Traffic noise                    |
|                                       | 14-May-13 | Sunny              | 27               | 0.5              | E              | 16:40      | 17:10    |                          | 70              | 63.7                   | 65.8                   | 60.3                   | -                | Nil                                 | Traffic noise                    |
|                                       | 20-May-13 | Sunny              | 31               | 0.3              | E              | 16:00      | 16:30    |                          | 70              | 64.7                   | 67.4                   | 61.1                   | -                | Rock breaking                       | Traffic noise                    |
|                                       | 30-May-13 | Sunny              | 30               | 0.3              | E              | 17:00      | 17:30    |                          | 70              | 64.0                   | 67.0                   | 58.6                   | -                | Nil                                 | Traffic noise and aircraft noise |
| Hong Hoi Chee Hong Temple<br>NSR 3    | 8-May-13  | Cloudy             | 25               | 0.4              | E              | 14:35      | 15:05    | 57.9                     | 75              | 60.5                   | 62.4                   | 57.7                   | -                | Crane operation and excavation work | Traffic noise                    |
|                                       | 14-May-13 | Sunny              | 27               | 0.3              | E              | 16:00      | 16:30    |                          | 75              | 61.6                   | 64.4                   | 57.2                   | -                | Crane operation                     | Traffic noise                    |
|                                       | 20-May-13 | Sunny              | 31               | 0.3              | E              | 16:40      | 17:30    |                          | 75              | 61.2                   | 63.0                   | 58.7                   | -                | Crane operation                     | Traffic noise                    |
|                                       | 30-May-13 | Sunny              | 30               | 0.4              | E              | 16:20      | 16:50    |                          | 75              | 61.7                   | 64.8                   | 57.8                   | -                | Crane operation                     | Traffic noise and aircraft noise |
| Squatters<br>NSR 6                    | 8-May-13  | Cloudy             | 25               | 0.4              | E              | 11:17      | 11:47    | 61.2                     | 75              | 63.8                   | 67.5                   | 55.4                   | -                | Rock breaking and excavation work   | Birds                            |
|                                       | 14-May-13 | Sunny              | 27               | 0.3              | E              | 11:17      | 11:47    |                          | 75              | 59.4                   | 62.1                   | 51.5                   | -                | Rock breaking and excavation work   | Birds                            |
|                                       | 20-May-13 | Sunny              | 31               | 0.3              | E              | 11:14      | 11:44    |                          | 75              | 57.4                   | 59.6                   | 53.8                   | -                | Excavation work                     | Birds                            |
|                                       | 30-May-13 | Sunny              | 30               | 0.3              | E              | 11:16      | 11:46    |                          | 75              | 62.0                   | 65.4                   | 53.7                   | -                | Rock breaking and excavation work   | Birds and aircraft noise         |
| Long Beach Gardens<br>NSR 8           | 8-May-13  | Cloudy             | 25               | 0.5              | E              | 10:35      | 11:05    | 60.9                     | 75              | 64.5                   | 67.0                   | 61.7                   | -                | Crane operation and rock breaking   | Traffic noise                    |
|                                       | 14-May-13 | Sunny              | 27               | 0.4              | E              | 10:35      | 11:05    |                          | 75              | 63.9                   | 65.2                   | 62.5                   | -                | Crane operation and excavation work | Traffic noise                    |
|                                       | 20-May-13 | Sunny              | 31               | 0.4              | E              | 10:33      | 11:03    |                          | 75              | 62.6                   | 64.4                   | 60.6                   | -                | Crane operation and excavation work | Traffic noise                    |
|                                       | 30-May-13 | Sunny              | 30               | 0.5              | E              | 10:35      | 11:05    |                          | 75              | 64.3                   | 66.1                   | 62.5                   | -                | Crane operation of excavation work  | Traffic noise and aircraft noise |
| Greenview Terrace<br>NSR 9            | 8-May-13  | Cloudy             | 25               | 0.5              | E              | 9:55       | 10:25    | 59.7                     | 75              | 72.9                   | 76.9                   | 63.8                   | -                | Crane operation and rock breaking   | Traffic noise                    |
|                                       | 14-May-13 | Sunny              | 27               | 0.4              | E              | 9:55       | 10:25    |                          | 75              | 65.7                   | 67.9                   | 63.2                   | -                | Crane operation and excavation work | Traffic noise                    |
|                                       | 20-May-13 | Sunny              | 31               | 0.5              | E              | 9:53       | 10:23    |                          | 75              | 65.0                   | 66.6                   | 62.6                   | -                | Crane operation and excavation work | Traffic noise                    |
|                                       | 30-May-13 | Sunny              | 30               | 0.5              | E              | 9:55       | 10:25    |                          | 75              | 66.5                   | 68.1                   | 64.6                   | -                | Crane operation and excavation work | Traffic noise and aircraft noise |


1: Baseline Noise Level  
2: Limit Level  
3: Corrected Noise Level

Note:  
The limit level of NSR1 is 65dB(A) during school examination period.  
**Red Bold indicates an exceedance of Limit Level**

**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
Noise Monitoring Results at Sik Sik Yuen Ho Fung College (NSR 1)  
Feb-13 to May-13**




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
Noise Monitoring Results at Hong Hoi Chee Hong Temple (NSR 3)  
Feb-13 to May-13**







**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
Noise Monitoring Results at Squatters (NSR 6)  
Feb-13 to May-13**



**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
Noise Monitoring Results at Long Beach Gardens (NSR 8)  
Feb-13 to May-13**



**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel**  
**Noise Monitoring Results at Greenview Terrace (NSR 9)**  
**Feb-13 to May-13**




Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel


Water Quality Impact Monitoring Results

| Monitoring Locations                | Date                                  | Start Time | Weather | Water Depth(m) | Temp  |       |       | DO (mg/L) |      |      | Action/Limit Level of DO(mg/L) | pH   |      |       | Turbidity (NTU) |       |       | Action/Limit Level of Tby | SS (mg/L) |       |                                     | Action/Limit Level of SS(mg/L)    | Remarks | Action to be taken |     |     |
|-------------------------------------|---------------------------------------|------------|---------|----------------|-------|-------|-------|-----------|------|------|--------------------------------|------|------|-------|-----------------|-------|-------|---------------------------|-----------|-------|-------------------------------------|-----------------------------------|---------|--------------------|-----|-----|
|                                     |                                       |            |         |                | 1     | 2     | Avg   | 1         | 2    | Avg  |                                | 1    | 2    | Avg   | 1               | 2     | Avg   |                           | 1         | 2     | Avg                                 |                                   |         |                    |     |     |
| Sik Sik Yuen Ho Fung College<br>I-1 | 2-May-13                              | 9:53       | Cloudy  | <1             | 25.80 | 25.80 | 25.80 | 7.71      | 7.67 | 7.69 | 3.42 / 3.34                    | 7.85 | 7.85 | 7.85  | 7.40            | 7.50  | 7.45  | 9.75 / 12.47              | 4.80      | 4.30  | 4.55                                | 8.85 / 10.17                      | Nil     | Nil                |     |     |
|                                     | 4-May-13                              | 11:15      | Cloudy  | <1             | 24.60 | 24.90 | 24.90 | 8.19      | 8.22 | 8.20 | 7.96                           | 7.96 | 7.96 | 4.37  | 4.25            | 4.31  | 3.10  | 2.90                      | 3.00      | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
|                                     | 6-May-13                              | 15:11      | Cloudy  | <1             | 24.80 | 24.80 | 24.80 | 9.16      | 9.21 | 9.19 | 7.86                           | 7.86 | 7.86 | 3.10  | 3.07            | 3.09  | <2.00 | <2.00                     | <2.00     | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
|                                     | 8-May-13                              | 15:33      | Cloudy  | <1             | 24.60 | 24.60 | 24.60 | 8.06      | 8.08 | 8.07 | 7.70                           | 7.70 | 7.70 | 2.70  | 2.66            | 2.68  | <2.00 | <2.00                     | <2.00     | Nil   | Crane operation                     | Nil                               | Nil     | Nil                | Nil |     |
|                                     | 10-May-13                             | 11:10      | Sunny   | <1             | 25.20 | 25.20 | 25.20 | 7.84      | 7.84 | 7.83 | 7.74                           | 7.74 | 7.74 | 3.46  | 3.41            | 3.45  | <2.00 | <2.00                     | <2.00     | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
|                                     | 13-May-13                             | 15:16      | Sunny   | <1             | 26.20 | 26.20 | 26.20 | 8.07      | 8.04 | 8.06 | 7.70                           | 7.70 | 7.70 | 2.70  | 2.74            | 2.72  | <2.00 | <2.00                     | <2.00     | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
|                                     | 15-May-13                             | 10:40      | Sunny   | <1             | 26.00 | 26.00 | 26.00 | 8.05      | 7.99 | 8.02 | 7.80                           | 7.80 | 7.80 | 4.74  | 4.77            | 4.76  | <2.00 | <2.00                     | <2.00     | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
|                                     | 18-May-13                             | 9:55       | Sunny   | <1             | 26.10 | 26.10 | 26.10 | 7.87      | 7.89 | 7.88 | 7.75                           | 7.75 | 7.75 | 3.90  | 3.85            | 3.88  | 5.40  | 5.30                      | 5.35      | Nil   | Rock breaking                       | Nil                               | Nil     | Nil                | Nil | Nil |
|                                     | 20-May-13                             | 15:23      | Sunny   | <1             | 25.60 | 25.60 | 25.60 | 8.07      | 8.02 | 8.05 | 7.76                           | 7.76 | 7.76 | 3.28  | 3.28            | 3.28  | <2.00 | <2.00                     | <2.00     | Nil   | Rock breaking                       | Nil                               | Nil     | Nil                | Nil | Nil |
|                                     | 22-May-13                             | 16:10      | Rainy   | <1             | 23.60 | 23.60 | 23.60 | 7.82      | 7.87 | 7.85 | 7.90                           | 7.90 | 7.90 | 11.20 | 11.30           | 11.25 | 16.60 | 16.70                     | 16.65     | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
|                                     | 24-May-13                             | 9:59       | Sunny   | <1             | 26.50 | 26.50 | 26.50 | 8.67      | 8.69 | 8.68 | 7.95                           | 7.95 | 7.95 | 5.40  | 5.47            | 5.44  | 2.40  | 2.20                      | 2.30      | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
|                                     | 27-May-13                             | 11:16      | Cloudy  | <1             | 25.50 | 25.50 | 25.50 | 8.26      | 8.29 | 8.28 | 7.76                           | 7.76 | 7.76 | 4.20  | 4.22            | 4.21  | 2.70  | 2.80                      | 2.75      | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
|                                     | 29-May-13                             | 13:33      | Sunny   | <1             | 26.60 | 26.60 | 26.60 | 8.19      | 8.21 | 8.20 | 7.98                           | 7.98 | 7.98 | 3.59  | 3.63            | 3.61  | <2.00 | <2.00                     | <2.00     | Nil   | Rock breaking                       | Nil                               | Nil     | Nil                | Nil | Nil |
|                                     | 31-May-13                             | 11:21      | Sunny   | <1             | 27.70 | 27.70 | 27.70 | 8.21      | 8.23 | 8.22 | 7.80                           | 7.80 | 7.80 | 3.44  | 3.47            | 3.46  | <2.00 | <2.00                     | <2.00     | Nil   | Rock breaking                       | Nil                               | Nil     | Nil                | Nil | Nil |
|                                     | Sik Sik Yuen Ho Fung College<br>I-1-C | 2-May-13   | 9:41    | Cloudy         | <1    | 25.90 | 25.90 | 25.90     | 7.73 | 7.69 | 7.71                           | 7.85 | 7.85 | 7.85  | 7.58            | 7.71  | 7.65  | 4.30                      | 4.10      | 4.20  | Nil                                 | Nil                               | Nil     | Nil                | Nil | Nil |
| 4-May-13                            |                                       | 11:05      | Cloudy  | <1             | 25.00 | 25.00 | 25.00 | 8.10      | 8.14 | 8.12 | 7.96                           | 7.96 | 7.96 | 4.46  | 4.59            | 4.53  | 2.90  | 2.60                      | 2.75      | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
| 6-May-13                            |                                       | 15:00      | Cloudy  | <1             | 24.90 | 24.90 | 24.90 | 9.10      | 9.12 | 9.11 | 7.86                           | 7.86 | 7.86 | 3.20  | 3.27            | 3.24  | <2.00 | <2.00                     | <2.00     | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
| 8-May-13                            |                                       | 15:22      | Cloudy  | <1             | 24.60 | 24.60 | 24.60 | 7.96      | 8.02 | 7.99 | 7.70                           | 7.70 | 7.70 | 2.55  | 2.62            | 2.59  | <2.00 | <2.00                     | <2.00     | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
| 10-May-13                           |                                       | 11:00      | Sunny   | <1             | 25.20 | 25.20 | 25.20 | 7.96      | 8.01 | 7.99 | 7.74                           | 7.74 | 7.74 | 3.60  | 3.55            | 3.58  | <2.00 | <2.00                     | <2.00     | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
| 13-May-13                           |                                       | 15:05      | Sunny   | <1             | 26.20 | 26.20 | 26.20 | 7.96      | 7.98 | 7.97 | 7.70                           | 7.70 | 7.70 | 2.80  | 2.77            | 2.79  | 2.80  | 2.60                      | 2.70      | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
| 15-May-13                           |                                       | 10:30      | Sunny   | <1             | 26.00 | 26.00 | 26.00 | 8.10      | 8.12 | 8.11 | 7.80                           | 7.80 | 7.80 | 4.83  | 4.86            | 4.85  | <2.00 | <2.00                     | <2.00     | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
| 18-May-13                           |                                       | 9:44       | Sunny   | <1             | 26.10 | 26.10 | 26.10 | 7.80      | 7.83 | 7.82 | 7.75                           | 7.75 | 7.75 | 3.86  | 3.81            | 3.84  | 5.30  | 3.60                      | 4.45      | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
| 20-May-13                           |                                       | 16:10      | Sunny   | <1             | 25.60 | 25.60 | 25.60 | 8.11      | 8.15 | 8.13 | 7.80                           | 7.80 | 7.80 | 3.44  | 3.51            | 3.48  | 2.50  | 2.10                      | 2.30      | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
| 22-May-13                           |                                       | 15:00      | Rainy   | <1             | 23.60 | 23.60 | 23.60 | 7.75      | 7.78 | 7.77 | 7.90                           | 7.90 | 7.90 | 11.60 | 11.50           | 11.45 | 9.80  | 10.80                     | 10.35     | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
| 24-May-13                           |                                       | 9:48       | Sunny   | <1             | 26.50 | 26.50 | 26.50 | 8.60      | 8.63 | 8.62 | 7.95                           | 7.95 | 7.95 | 5.53  | 5.66            | 5.60  | 2.20  | 2.60                      | 2.40      | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
| 27-May-13                           |                                       | 11:05      | Cloudy  | <1             | 25.50 | 25.50 | 25.50 | 8.18      | 8.21 | 8.20 | 7.76                           | 7.76 | 7.76 | 3.96  | 4.14            | 4.05  | 2.20  | 2.70                      | 2.45      | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
| 29-May-13                           |                                       | 13:22      | Sunny   | <1             | 26.60 | 26.60 | 26.60 | 8.15      | 8.15 | 8.15 | 7.98                           | 7.98 | 7.98 | 3.48  | 3.50            | 3.49  | <2.00 | <2.00                     | <2.00     | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
| 31-May-13                           |                                       | 11:10      | Sunny   | <1             | 27.70 | 27.70 | 27.70 | 8.15      | 8.18 | 8.17 | 7.80                           | 7.80 | 7.80 | 3.33  | 3.41            | 3.37  | <2.00 | <2.00                     | <2.00     | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
| Hong Hoi Chee Hong Temple<br>I-2    |                                       | 2-May-13   | 9:30    | Cloudy         | <1    | 26.00 | 26.00 | 26.00     | 7.75 | 7.77 | 7.76                           | 7.86 | 7.86 | 7.86  | 1.37            | 1.35  | 1.36  | <2.00                     | <2.00     | <2.00 | Nil                                 | Crane operation and rock breaking | Nil     | Nil                | Nil | Nil |
|                                     | 4-May-13                              | 10:50      | Cloudy  | <1             | 24.90 | 24.90 | 24.90 | 8.07      | 8.04 | 8.06 | 7.95                           | 7.95 | 7.95 | 4.10  | 4.17            | 4.14  | 2.50  | 3.00                      | 2.75      | Nil   | Crane operation and rock breaking   | Nil                               | Nil     | Nil                | Nil |     |
|                                     | 6-May-13                              | 15:45      | Cloudy  | <1             | 24.90 | 24.90 | 24.90 | 8.96      | 8.93 | 8.95 | 7.81                           | 7.81 | 7.81 | 1.47  | 1.44            | 1.46  | <2.00 | <2.00                     | <2.00     | Nil   | Crane operation and rock breaking   | Nil                               | Nil     | Nil                | Nil |     |
|                                     | 8-May-13                              | 14:56      | Cloudy  | <1             | 24.60 | 24.60 | 24.60 | 8.12      | 8.10 | 8.11 | 7.78                           | 7.78 | 7.78 | 1.17  | 1.14            | 1.16  | <2.00 | <2.00                     | <2.00     | Nil   | Crane operation and excavation work | Nil                               | Nil     | Nil                | Nil |     |
|                                     | 10-May-13                             | 10:55      | Sunny   | <1             | 25.10 | 25.10 | 25.10 | 7.81      | 7.79 | 7.80 | 7.76                           | 7.76 | 7.76 | 4.62  | 4.62            | 4.66  | 2.40  | 2.60                      | 2.50      | Nil   | Crane operation and excavation work | Nil                               | Nil     | Nil                | Nil |     |
|                                     | 13-May-13                             | 15:42      | Sunny   | <1             | 26.30 | 26.30 | 26.30 | 7.82      | 7.72 | 7.77 | 7.72                           | 7.72 | 7.72 | 1.30  | 1.35            | 1.33  | <2.00 | <2.00                     | <2.00     | Nil   | Crane operation                     | Nil                               | Nil     | Nil                | Nil |     |
|                                     | 15-May-13                             | 11:06      | Sunny   | <1             | 26.10 | 26.10 | 26.10 | 7.90      | 7.87 | 7.89 | 7.80                           | 7.80 | 7.80 | 3.30  | 3.33            | 3.32  | <2.00 | <2.00                     | <2.00     | Nil   | Crane operation                     | Nil                               | Nil     | Nil                | Nil |     |
|                                     | 18-May-13                             | 9:30       | Sunny   | <1             | 26.00 | 26.00 | 26.00 | 7.96      | 7.94 | 7.95 | 7.77                           | 7.77 | 7.77 | 1.20  | 1.23            | 1.22  | 2.40  | 3.30                      | 2.85      | Nil   | Crane operation                     | Nil                               | Nil     | Nil                | Nil |     |
|                                     | 20-May-13                             | 17:00      | Sunny   | <1             | 25.70 | 25.70 | 25.70 | 8.26      | 8.29 | 8.28 | 7.76                           | 7.76 | 7.76 | 1.21  | 1.25            | 1.23  | <2.00 | <2.00                     | <2.00     | Nil   | Crane operation                     | Nil                               | Nil     | Nil                | Nil |     |
|                                     | 23-May-13                             | 15:33      | Sunny   | <1             | 23.70 | 23.70 | 23.70 | 7.93      | 7.90 | 7.92 | 7.86                           | 7.86 | 7.86 | 3.20  | 3.23            | 3.22  | 2.80  | 19.00                     | 18.00     | Nil   | Crane operation                     | Nil                               | Nil     | Nil                | Nil |     |
|                                     | 24-May-13                             | 10:22      | Sunny   | <1             | 26.30 | 26.30 | 26.30 | 8.47      | 8.42 | 8.45 | 7.90                           | 7.90 | 7.90 | 1.97  | 2.04            | 2.01  | <2.00 | <2.00                     | <2.00     | Nil   | Crane operation                     | Nil                               | Nil     | Nil                | Nil |     |
|                                     | 27-May-13                             | 10:53      | Cloudy  | <1             | 25.60 | 25.60 | 25.60 | 8.07      | 8.04 | 8.06 | 7.80                           | 7.80 | 7.80 | 2.80  | 2.76            | 2.78  | 2.20  | 2.30                      | 2.25      | Nil   | Crane operation                     | Nil                               | Nil     | Nil                | Nil |     |
|                                     | 29-May-13                             | 13:10      | Sunny   | <1             | 26.80 | 26.80 | 26.80 | 8.29      | 8.31 | 8.30 | 7.95                           | 7.95 | 7.95 | 6.33  | 6.42            | 6.38  | 2.60  | 2.10                      | 2.25      | Nil   | Crane operation                     | Nil                               | Nil     | Nil                | Nil |     |
|                                     | 31-May-13                             | 10:57      | Sunny   | <1             | 27.60 | 27.60 | 27.60 | 8.04      | 8.00 | 8.02 | 7.85                           | 7.85 | 7.85 | 1.36  | 1.39            | 1.38  | <2.00 | <2.00                     | <2.00     | Nil   | Crane operation                     | Nil                               | Nil     | Nil                | Nil |     |
|                                     | Hong Hoi Chee Hong Temple<br>I-2-C    | 2-May-13   | 9:20    | Cloudy         | <1    | 26.00 | 26.00 | 26.00     | 7.80 | 7.86 | 7.83                           | 7.86 | 7.86 | 7.86  | 1.43            | 1.41  | 1.42  | <2.00                     | <2.00     | <2.00 | Nil                                 | Nil                               | Nil     | Nil                | Nil | Nil |
| 4-May-13                            |                                       | 10:40      | Cloudy  | <1             | 24.90 | 24.90 | 24.90 | 8.19      | 8.16 | 8.18 | 7.95                           | 7.95 | 7.95 | 4.20  | 4.26            | 4.23  | 2.90  | 4.00                      | 3.45      | Nil   | Nil                                 | Nil                               | Nil     | Nil                |     |     |
| 6-May-13                            |                                       | 15:33      | Cloudy  | <1             | 24.60 | 24.60 | 24.60 | 9.00      | 8.98 | 8.99 | 7.81                           | 7.81 | 7.81 | 1.52  | 1.49            | 1.50  | <2.00 | <2.00                     | <2.00     | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
| 8-May-13                            |                                       | 14:44      | Cloudy  | <1             | 24.60 | 24.60 | 24.60 | 8.06      | 8.08 | 8.07 | 7.78                           | 7.78 | 7.78 | 1.20  | 1.18            | 1.19  | <2.00 | <2.00                     | <2.00     | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
| 10-May-13                           |                                       | 10:44      | Sunny   | <1             | 25.10 | 25.10 | 25.10 | 7.87      | 7.83 | 7.85 | 7.76                           | 7.76 | 7.76 | 5.01  | 4.96            | 4.99  | 2.30  | 3.10                      | 2.70      | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
| 13-May-13                           |                                       | 15:30      | Sunny   | <1             | 26.30 | 26.30 | 26.30 | 7.92      | 7.89 | 7.91 | 7.72                           | 7.72 | 7.72 | 1.32  | 1.38            | 1.35  | <2.00 | <2.00                     | <2.00     | Nil   | Nil                                 | Nil                               | Nil     | Nil                | Nil |     |
| 15-May-1                            |                                       |            |         |                |       |       |       |           |      |      |                                |      |      |       |                 |       |       |                           |           |       |                                     |                                   |         |                    |     |     |


**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
 Water Quality Results at Sik Sik Yuen Ho Fung College (I-1)  
 Feb-13 to May-13**




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
 Water Quality Results at Sik Sik Yuen Ho Fung College (I-1-C)  
 Feb-13 to May-13**




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
 Water Quality Results at Hong Hoi Chee Hong Temple (I-2)  
 Feb-13 to May-13**




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
 Water Quality Results at Hong Hoi Chee Hong Temple (I-2-C)  
 Feb-13 to May-13**




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
 Water Quality Results at Squatters (I-3)  
 Feb-13 to May-13**




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
 Water Quality Results at Squatters (I-3-C)  
 Feb-13 to May-13**




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
 Water Quality Results at Sik Sik Yuen Ho Fung College (I-1)  
 Feb-13 to May-13**




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
 Water Quality Results at Sik Sik Yuen Ho Fung College (I-1-C)  
 Feb-13 to May-13**



**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
 Water Quality Results at Hong Hoi Chee Hong Temple (I-2)  
 Feb-13 to May-13**




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
 Water Quality Results at Hong Hoi Chee Hong Temple (I-2-C)  
 Feb-13 to May-13**






**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel**  
**Water Quality Results at Squatters (I-3)**  
**Feb-13 to May-13**




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel**  
**Water Quality Results at Squatters (I-3-C)**  
**Feb-13 to May-13**




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
 Water Quality Results at Sik Sik Yuen Ho Fung College (I-1)  
 Feb-13 to May-13**

Note: Exceedances of Action / Limit Levels occur when the levels of DO are below the respective limit levels.




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
 Water Quality Results at Sik Sik Yuen Ho Fung College (I-1-C)  
 Feb-13 to May-13**




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
Water Quality Results at Hong Hoi Chee Hong Temple (I-2)  
Feb-13 to May-13**

Note: Exceedances of Action / Limit Levels occur when the levels of DO are below the respective limit levels.




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
Water Quality Results at Hong Hoi Chee Hong Temple (I-2-C)  
Feb-13 to May-13**




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel**  
**Water Quality Results at Squatters (I-3)**  
**Feb-13 to May-13**


Note: Exceedances of Action / Limit Levels occur when the levels of DO are below the respective limit levels.




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel**  
**Water Quality Results at Squatters (I-3-C)**  
**Feb-13 to May-13**




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
 Water Quality Results at Sik Sik Yuen Ho Fung College (I-1)  
 Feb-13 to May-13**




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
 Water Quality Results at Sik Sik Yuen Ho Fung College (I-1-C)  
 Feb-13 to May-13**




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
 Water Quality Results at Hong Hoi Chee Hong Temple (I-2)  
 Feb-13 to May-13**




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
 Water Quality Results at Hong Hoi Chee Hong Temple (I-2-C)  
 Feb-13 to May-13**




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
 Water Quality Results at Squatters (I-3)  
 Feb-13 to May-13**




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
 Water Quality Results at Squatters (I-3-C)  
 Feb-13 to May-13**



**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
Water Quality Results at Sik Sik Yuen Ho Fung College (I-1)  
Feb-13 to May-13**




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
Water Quality Results at Sik Sik Yuen Ho Fung College (I-1-C)  
Feb-13 to May-13**




Note:# - For average SS level smaller than 2 mg/L, the level is plotted as 2 mg/L in the graph



**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
Water Quality Results at Hong Hoi Chee Hong Temple (I-2)  
Feb-13 to May-13**




**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
Water Quality Results at Hong Hoi Chee Hong Temple (I-2-C)  
Feb-13 to May-13**




Note:# - For average SS level smaller than 2 mg/L, the level is plotted as 2 mg/L in the graph

**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
Water Quality Results at Squatters (I-3)  
Feb-13 to May-13**



**Contract No. DC/2007/12 - Design and Construction of Tsuen Wan Drainage Tunnel  
Water Quality Results at Squatters (I-3-C)  
Feb-13 to May-13**



Note:# - For average SS level smaller than 2 mg/L, the level is plotted as 2 mg/L in the graph

## Appendix J


---

# Interim Notifications of Environmental Quality Limits Exceedances

**Interim Notification of Environmental Quality Limit Exceedance**

Incident Report on Action Level Non-compliance

|  |   |
|--|---|
| Project  | Tsuen Wan Drainage Tunnel   |
| Date   | 22-May-13   |
| Time   | 4:10 PM   |
| Monitoring Location                                      | Sik Sik Yuen Ho Fung College (I-1)  |
| Parameter  | Turbidity   |
| Action & Limit Levels (NTU)                              | 9.75 / 12.47  |
| Measured Level (NTU)                                     | 11.25   |
| Control Station  | I-1-C   |
| Measured Level at the Control Station (NTU)              | 11.45   |
| Possible reason for Action or Limit Level Non-compliance | The measured turbidity level was higher than the baseline action level, but lower than the turbidity level of the control station (I-1-C). General site cleaning and housekeeping, and mucking out at site entrance were undertaken during the monitoring day. No direct disturbance was observed from the site. Heavy rain was observed and about 205 mm rainfall was recorded at Tsuen Wan by the Hong Kong Observatory between 0:45 and 16:45 on the monitoring day. Therefore, the exceedance was considered to be contributed by heavy rainfall and high turbidity level at upstream location. Since the exceedance was non-project related, no further action was required. |
| Actions taken / to be taken                              | None  |
| Remarks  | No wastewater discharge for the above work activities.  |

Prepared by: Fan Cheong Tsang  
 Designation: Environmental Team Leader  
 Signature:   
 Date: 27-May-13

**Photographic record for exceedance of Turbidity recorded at Sik Sik Yuen Ho Fung College (I-1) on 22-May-13**



Photo taken at I-1




Photo of I-1-C

**Interim Notification of Environmental Quality Limit Exceedance**

Incident Report on Limit Level Non-compliance

|  |  |
|--|--|
| Project  | Tsuen Wan Drainage Tunnel  |
| Date   | 22-May-13  |
| Time   | 4:33 PM  |
| Monitoring Location                                      | Hong Hoi Chee Hong Temple (I-2)  |
| Parameter  | Turbidity  |
| Action & Limit Levels (NTU)                              | 6.63 / 6.99  |
| Measured Level (NTU)                                     | 32.05  |
| Control Station  | I-2-C  |
| Measured Level at the Control Station (NTU)              | 32.25  |
| Possible reason for Action or Limit Level Non-compliance | The measured turbidity level was higher than the baseline limit level, but lower than the turbidity level of the control station (I-2-C). General site cleaning and housekeeping, site clearance at access platform, and dismantling temporary scaffold platform for diversion of DN100 pipe were undertaken during the monitoring day. No direct disturbance was observed from the site. Heavy rain was observed and about 205 mm rainfall was recorded at Tsuen Wan by the Hong Kong Observatory between 0:45 and 16:45 on the monitoring day. Therefore, the exceedance was considered to be contributed by heavy rainfall and high turbidity level at upstream location. Since the exceedance was non-project related, no further action was required. |
| Actions taken / to be taken                              | None   |
| Remarks  | No wastewater discharge for the above work activities.   |

Prepared by: Fan Cheong Tsang  
 Designation: Environmental Team Leader  
 Signature:   
 Date: 27-May-13

**Photographic record for exceedance of Turbidity recorded at Hong Hoi Chee Hong Temple (I-2) on 22-May-13**



Photo taken at I-2




Photo of I-2-C

**Interim Notification of Environmental Quality Limit Exceedance**

Incident Report on Limit Level Non-compliance

|  |  |
|--|--|
| Project  | Tsuen Wan Drainage Tunnel  |
| Date   | 22-May-13  |
| Time   | 5:12 PM  |
| Monitoring Location                                      | Squatters (I-3)  |
| Parameter  | Turbidity  |
| Action & Limit Levels (NTU)                              | 3.99 / 4.18  |
| Measured Level (NTU)                                     | 6.76   |
| Control Station  | I-3-C  |
| Measured Level at the Control Station (NTU)              | 6.91   |
| Possible reason for Action or Limit Level Non-compliance | The measured turbidity level was higher than the baseline limit level, but lower than the turbidity level of the control station (I-3-C). General site cleaning and housekeeping were undertaken during the monitoring day. No direct disturbance was observed from the site. Heavy rain was observed and about 205 mm rainfall was recorded at Tsuen Wan by the Hong Kong Observatory between 0:45 and 16:45 on the monitoring day. Therefore, the exceedance was considered to be contributed by heavy rainfall and high turbidity level at upstream location. Since the exceedance was non-project related, no further action was required. |
| Actions taken / to be taken                              | None   |
| Remarks  | No wastewater discharge for the above work activities.   |

Prepared by: Fan Cheong Tsang  
 Designation: Environmental Team Leader  
 Signature:   
 Date: 27-May-13

**Photographic record for exceedance of Turbidity recorded at Squatters (I-3) on 22-May-13**



Photo taken at I-3




Photo of I-3-C

**Interim Notification of Environmental Quality Limit Exceedance**

Incident Report on Limit Level Non-compliance

|  |  |
|--|--|
| Project  | Tsuen Wan Drainage Tunnel  |
| Date   | 29-May-13  |
| Time   | 11:42 AM   |
| Monitoring Location                                      | Squatters (I-3)  |
| Parameter  | Turbidity  |
| Action & Limit Levels (NTU)                              | 3.99 / 4.18  |
| Measured Level (NTU)                                     | 4.73   |
| Control Station  | I-3-C  |
| Measured Level at the Control Station (NTU)              | 4.62   |
| Possible reason for Action or Limit Level Non-compliance | The measured turbidity level was higher than the baseline limit level, but lower than 120% of turbidity level of the control station (I-3-C). General site cleaning and housekeeping, installation of K1 kerb at Ch.200, formwork shuttering for additional power cable drawpit at Ch.160, mucking out at +76mPD platform, excavation for temporary access road, and excavation and formwork shuttering for extended 300mm U-channel near approach channel were undertaken during the monitoring day. No direct disturbance was observed from the site. Therefore, the exceedance was considered to be contributed by natural variation. Since the exceedance was non-project related, no further action was required. |
| Actions taken / to be taken                              | The following mitigation measure was provided on-site during monitoring: (1) wastewater was collected and diverted to wastewater treatment plant for treatment before discharge.   |
| Remarks  | None   |

Prepared by: Fan Cheong Tsang  
 Designation: Environmental Team Leader  
 Signature:   
 Date: 31-May-13

**Photographic record for exceedance of Turbidity recorded at Squatters (I-3) on 29-May-13**



Photo taken at I-3




Photo of I-3-C

**Interim Notification of Environmental Quality Limit Exceedance**

Incident Report on Limit Level Non-compliance

|  |   |
|--|---|
| Project  | Tsuen Wan Drainage Tunnel   |
| Date   | 22-May-13   |
| Time   | 4:10 PM   |
| Monitoring Location                                      | Sik Sik Yuen Ho Fung College (I-1)  |
| Parameter  | Suspended Solids (SS)   |
| Action & Limit Levels (mg/L)                             | 8.85 / 10.17  |
| Measured Level (mg/L)                                    | 16.65   |
| Control Station  | I-1-C   |
| Measured Level at the Control Station (mg/L)             | 10.35   |
| Possible reason for Action or Limit Level Non-compliance | The measured SS level was higher than the baseline limit level, and higher than 130% of the SS level of the control station (I-1-C). General site cleaning and housekeeping, and mucking out at site entrance were undertaken during the monitoring day. No wastewater directly discharged from the site. Heavy rain was observed and about 205 mm rainfall was recorded at Tsuen Wan by the Hong Kong Observatory between 0:45 and 16:45 on the monitoring day. Therefore, the exceedance was considered to be contributed by heavy rainfall and high SS level at upstream location. Since the exceedance was non-project related, no further action was required. |
| Actions taken / to be taken                              | None  |
| Remarks  | No wastewater discharge for the above work activities.  |

Prepared by: Fan Cheong Tsang  
 Designation: Environmental Team Leader  
 Signature:   
 Date: 31-May-13

**Photographic record for exceedance of Suspended Solids (SS) recorded at Sik Sik Yuen Ho Fung College (I-1) on 22-May-13**



Photo taken at I-1




Photo taken at I-1-C



**Interim Notification of Environmental Quality Limit Exceedance**

Incident Report on Limit Level Non-compliance

|  |   |
|--|---|
| Project  | Tsuen Wan Drainage Tunnel   |
| Date   | 22-May-13   |
| Time   | 4:33 PM   |
| Monitoring Location                                      | Hong Hoi Chee Hong Temple (I-2)   |
| Parameter  | Suspended Solids (SS)   |
| Action & Limit Levels (mg/L)                             | 7.68 / 8.34   |
| Measured Level (mg/L)                                    | 19.40   |
| Control Station  | I-2-C   |
| Measured Level at the Control Station (mg/L)             | 22.70   |
| Possible reason for Action or Limit Level Non-compliance | The measured SS level was higher than the baseline limit level, but lower than the SS level of the control station (I-2-C). General site cleaning and housekeeping, site clearance at access platform, and dismantling temporary scaffold platform for diversion of DN100 pipe were undertaken during the monitoring day. No direct disturbance was observed from the site. Heavy rain was observed and about 205 mm rainfall was recorded at Tsuen Wan by the Hong Kong Observatory between 0:45 and 16:45 on the monitoring day. Therefore, the exceedance was considered to be contributed by heavy rainfall and high SS level at upstream location. Since the exceedance was non-project related, no further action was required. |
| Actions taken / to be taken                              | None  |
| Remarks  | No wastewater discharge for the above work activities.  |

Prepared by: Fan Cheong Tsang  
 Designation: Environmental Team Leader  
 Signature:   
 Date: 31-May-13

**Photographic record for exceedance of Suspended Solids (SS) recorded at Hong Hoi Chee Hong Temple (I-2) on 22-May-13**



Photo taken at I-2




Photo of I-2-C

**Interim Notification of Environmental Quality Limit Exceedance**

Incident Report on Action Level Non-compliance

|  |   |
|--|---|
| Project  | Tsuen Wan Drainage Tunnel   |
| Date   | 18-May-13   |
| Time   | 9:55 AM   |
| Monitoring Location                                      | Sik Sik Yuen Ho Fung College (I-1)  |
| Parameter  | Suspended Solids (SS)   |
| Action & Limit Levels (mg/L)                             | 8.85 / 10.17  |
| Measured Level (mg/L)                                    | 5.35  |
| Control Station  | I-1-C   |
| Measured Level at the Control Station (mg/L)             | 4.45  |
| Possible reason for Action or Limit Level Non-compliance | The measured SS level was lower than the baseline action level, but higher than 120% of the SS level of the control station (I-1-C). General site cleaning and housekeeping, and reinstatement of site entrance were undertaken during the monitoring day. No direct disturbance was observed from the site. Therefore, the exceedance was considered to be contributed by natural variation. Since the exceedance was non-project related, no further action was required. |
| Actions taken / to be taken                              | None  |
| Remarks  | No wastewater discharge for the above work activities.  |

Prepared by: Fan Cheong Tsang  
 Designation: Environmental Team Leader  
 Signature:   
 Date: 31-May-13

**Photographic record for exceedance of Suspended Solids (SS) recorded at Sik Sik Yuen Ho Fung College (I-1) on 18-May-13**



Photo taken at I-1



Photo taken at I-1-C

## Appendix K

---

### Complaint Log

COMPLAINT LOG

| Complaint No. | Log Ref. | Date/Location              | Complainant        | Details of Complaint  | Investigation / Mitigation Action  | Status |
|---------------|----------|----------------------------|--------------------|---|--|--------|
| 1             | CIR-001  | 9 March 2009<br>at Outfall | Public through EPD | EPD has received a complaint (EPD ref: EP3/N22/RW/04846-09) regarding to muddy effluent discharged from the outfall of the construction site from a public on 9 March 2009. Site investigation was also carried out by EPD with the Contractor on the same day. | <p><u>Findings/ Observations</u><br/>                     In the afternoon on 9 March 2009, the Contractor was carrying out regular maintenance for removing silt accumulated in the wastewater treatment plant. During the maintenance works, some residual silt inside the plant was accidentally leaked out to the outfall discharge outlet. The reason was that a flexible pipe for disposing silt was found connecting to the concrete platform of the outfall discharge outlet.</p> <p><u>Conclusion/Remedial Action</u><br/>                     The complaint was valid and it was due to maintenance works at the wastewater treatment plant at the outfall area. The contractor had cleaned up the silt at discharge outlet and the channel at the outfall area on 12 March 2009 as shown in the attached photo. The ET will closely inspect the discharge outlet and the channel during the routine site inspections and provide advice to the Contractor. The Contractor was also advised to provide mitigation measures during any occasion of the maintenance work on the wastewater treatment plant.</p> <p>The discharge pipe of the treatment plant should be plugged and ensure not functioned when carrying out maintenance works on the wastewater treatment plant in order to prevent the discharge of silt or muddy water to the outlet.</p> <p>Flexible pipe for discharge of sludge should not be placed on the concrete platform under the outfall discharge outlet. For disposal of slit or sludge in the wastewater treatment plant, tanker should be used.</p> | Closed |
| 2             | CIR-002  | 8 May 2009<br>at Outfall   | Public through EPD | EPD has received a complaint (EPD ref: EP3/N22/RW/09755-09) regarding to construction dust from the outfall   | <p><u>Findings/ Observations</u><br/>                     Regular 1-hour TSP monitoring, in accordance with EM&amp;A Manual, is performed by Environmental Team. The monitoring station concerned is ASR9 (i.e. at the podium level of Greenview Terrace facing to the construction site).</p> <p>The closest date for the 1-hour TSP concentration monitoring was on 6</p>  | Closed |

| Complaint No. | Log Ref. | Date/Location          | Complainant        | Details of Complaint   | Investigation / Mitigation Action  | Status |
|---------------|----------|------------------------|--------------------|--|--|--------|
|               |          |                        |                    | <p>construction site on 8 May 2009. Site investigation was also carried out by EPD with the Contractor on 14 May 2009.</p> | <p>May 2009 and 12 May 2009 at Greenview Terrace, ASR9. Soil nailing works and loading &amp; unloading excavated materials were observed during monitoring. In accordance with the EM&amp;A Manual and the Baseline Monitoring Report, all 1-hour TSP concentrations at ASR9 were below the established Action and Limit Levels. No exceedance was recorded on 6 and 12 May 2009.</p> <p>The contractor and the environmental team were also undertaken site investigation on the subject area in response to the complaint. It was confirmed that the air quality mitigation measures as recommended in EIA have been provided by the Contractor. The mitigation measures are as follows:</p> <ul style="list-style-type: none"> <li>• Water spraying was provided to the exposed surface.</li> <li>• Several automatic sprinklers were provided at the outfall construction site for water spraying of the haul road.</li> <li>• Water spraying was provided during dust generating works (e.g. rock breaking and soil nailing works).</li> </ul> <p><u>Conclusion/Remedial Action</u></p> <p>Based on the site inspection and monitoring results, the complaint is considered not justifiable since no action &amp; limit level exceedance on construction dust are identified. Air quality mitigation measures as recommended in EIA have been implemented in order to control and minimise the air quality impact and nuisance arising from the construction activities. Nevertheless, in view of the recent dry and sunny weather, the haul road and the exposed area would be dry very quickly. The Contractor was recommended to provide more frequent water spraying especially in the dry and sunny weather.</p> |        |
| 3             | CIR-003  | 14 May 2009 at Outfall | Public through EPD | <p>EPD has received a complaint (EPD ref: EP/RW/080206) regarding to daytime construction rock breaking at 7:15 am</p>     | <p>The closest date to the complaint for the 1-hour TSP monitoring &amp; daytime construction noise monitoring was on 12, 18 and 27 May 2009 at Greenview Terrace, ASR9 and NSR9. Soil nailing, excavation, rock breaking, loading and unloading the materials were observed during monitoring period. The measured noise levels complied with the limit level in accordance with the EIAO-TM. All 1-hour TSP concentrations at ASR9 were below the established Action and Limit Levels. No 1-hour TSP</p>   | Closed |

| Complaint No. | Log Ref. | Date/Location | Complainant | Details of Complaint  | Investigation / Mitigation Action   | Status |
|---------------|----------|---------------|-------------|---|---|--------|
|               |          |               |             | <p>and dusty at the outfall construction site on 14 May 2009.</p> | <p>exceedance was recorded.<br/>                     The contractor and the environmental team were also undertaken site investigation on the subject area in response to the complaint. Air quality mitigation measures as recommended in EIA have been implemented by the Contractor. However, noise mitigation measures could be further improved.<br/>                     Based on our site inspection and monitoring results, the complaint for dust is considered not justifiable since no action &amp; limit level exceedance on construction dust is identified. Air quality mitigation measures as recommended in EIA have also been implemented in order to control and minimise the air quality impact arising from the construction activities. In view of the recent dry and sunny weather, the haul road and the exposed area would be dry very quickly. The Contractor was recommended to enhance water spraying especially in the dry and sunny weather.<br/>                     On the other hand, the complaint for noise is considered due to works and the Contractor was agreed to improve the on-site noise mitigation measures such as the following measures. ET's site inspection and the joint inspection with relevant parties was conducted on 29 May 2009 and 4 June 2009 respectively to confirm all the below measures have been implemented.</p> <ul style="list-style-type: none"> <li>• For the idling plant, it should be switched off to reduce noise level generated.</li> <li>• The sound insulation sheets and noise insulation materials should be placed to enclose the breaking tip tightly and also aside or surrounding the breaking activities as recommended in the following photos 1-3 in noise mitigation measures.</li> <li>• Noise monitoring frequency was increased in order to check the effectiveness of the mitigation measures. The additional measurement was taken on 27 May, 8 June, 10 June and 12 June 2009 after all the measures implemented. The noise levels (<math>L_{eq, 30 \text{ min}}</math>) were 70.9 dB (A), 70.5 dB (A), 70.3 dB (A) and 70.3 dB (A) respectively, which comply with the limit level in accordance with the EIAO-TM. Soil nailing, excavation and rock breaking were observed during monitoring period.</li> </ul> |        |

| Complaint No. | Log Ref. | Date/Location                            | Complainant        | Details of Complaint   | Investigation / Mitigation Action  | Status                          |
|---------------|----------|--|--------------------|--|--|---------------------------------|
|               |          |  |                    |  | The measures were well in place and seemed effective during the measurement.   |                                 |
| 4             | CIR-004  | 10 July 2009 at Outfall                  | Public through EPD | EPD has received a complaint (EPD ref: EP3/N22/RW/15137-09) regarding to construction dust from the outfall construction site on 10 July 2009.         | <p><u>Findings/ Observations</u><br/>                     1-hour TSP concentration monitoring was on 10 July 2009 at Greenview Terrace, ASR9. Soil nailing works, concrete breaking, excavation and loading &amp; unloading excavated materials were observed during monitoring. All 1-hour TSP concentrations at ASR9 were below the established Action and Limit Levels. No exceedance was recorded on 10 July 2009.</p> <p>The contractor and the environmental team were also undertaken site investigation on the subject area in response to the complaint. It was confirmed that the air quality mitigation measures as recommended in EIA have been provided by the Contractor. The mitigation measures are as follows:</p> <ul style="list-style-type: none"> <li>• Water spraying was provided to the exposed surface.</li> <li>• Automatic sprinklers were provided at the outfall construction site for water spraying of the haul road.</li> <li>• Water spraying was provided during dust generating works (e.g. rock breaking and soil nailing works).</li> <li>• Tarpaulin was used for covering the dusty works in the Portal area.</li> </ul> <p><u>Conclusion/Remedial Action</u><br/>                     The complaint is considered not justifiable since no action &amp; limit level exceedance on construction dust are identified</p> | Closed                          |
| 5 & 6         | CIR-005  | 29 July 2009 & 11 August 2009 at Outfall | Public through SOR | SOR has received two complaints (SOR ref: (DC/2007/12)/M45/500/02480, 02500) from Greenview Terrace regarding to daytime construction noise exceedance | <p><u>Findings/ Observations</u><br/>                     Soil nailing, excavation, rock breaking and drilling, loading and unloading the materials were generally observed during monitoring period in July and August 2009. According to the noise monitoring results from 6 July 2009 to 31 August 2009 at NSR 9, the measured noise levels complied with the limit level in accordance with the EIAO-TM. All 1-hour TSP concentrations at ASR9 were below the established Action and Limit Levels from 6 July 2009 to 25 August 2009.</p> <p><u>Conclusion/Remedial Action</u><br/>                     The dust complaint on 22 July 2009 was due to the soil nailing works. The</p>  | Same Case with Complaint No. 11 |

| Complaint No. | Log Ref. | Date/Location | Complainant | Details of Complaint   | Investigation / Mitigation Action   | Status |
|---------------|----------|---------------|-------------|--|---|--------|
|               |          |               |             | <p>recorded at NSR9 on 8, 22, 23, 27 and 29 July 2009 and a large amount dust generated at the outfall construction site. The complaint dates were corresponded to 29 July and 11 August 2009.</p> | <p>Contractor was reminded enhance the dust mitigation measures during soil nailing works. A designated staff was provided to spray water continuously during soil nailing. A nylon bag was placed on the drilling hole and keeping wet to suppress dust. A sprinkler was added at the hillside of the site and water spraying was provided continuously during operation of drilling to suppress dust.</p> <p>The documented complaint for noise is considered to trigger the action level and the Contractor was also reminded to enhance the on-site noise mitigation measures continuously. The enhanced mitigation measures are proposed as follows:</p> <ul style="list-style-type: none"> <li>• A staff from the Contractor was designated to take the reading of Leq (5mins) at the roof of Greenview Terrace. In case of the Leq (5min) exceed 73 dB(A), the Contractor would re-schedule the noisy plants to mitigate the escalation of noise level.</li> <li>• The designated staff was reminded to record all the weather condition including raining and wind speed.</li> <li>• Tools box talk for the Contractor's Team was carried out for reminding that the movable barrier should be placed to the breaking activities as much as possible.</li> <li>• Movable noise barriers were placed on site and the movable noise barriers were also modified.</li> <li>• Existing 25 ton rock breaker had been replaced by the another breaker.</li> <li>• The breaking tap of the 25 ton rock breaker had been replaced by another breaking tap.</li> <li>• A joint filler wall was installed at the vertical face of westbound to mitigate the noise rebound from the vertical face to high level of Greenview Terrace.</li> </ul> <p>From the additional monitoring data and monitoring data under regular EM&amp;A requirements, noise level (<math>L_{eq, 30 \text{ min}}</math>) between 6 July to 31 August 2009 was in the range of 71 to 74 dB(A) to the nearest integer. The noise monitoring frequency was maintained in twice per week to check whether the mitigation measures are effective. From the information of the Contractor, all the mitigation measures were implemented on 31 August</p> |        |



| Complaint No. | Log Ref. | Date/Location             | Complainant        | Details of Complaint   | Investigation / Mitigation Action  | Status |
|---------------|----------|---------------------------|--------------------|--|--|--------|
|               |          |                           |                    |  | 2009. Noise levels ( $L_{eq, 30 \text{ min}}$ ) were also re-measured after the implementation of the mitigation measures. Noise level ( $L_{eq, 30 \text{ min}}$ ) from 4 Sep to 28 Sep 2009 was in the range of 70 to 73 dB(A) to the nearest integer after the implementation of the mitigation measures. In our investigation, there was no exceedance of the measured noise level at Greenview Terrace.   |        |
| 7             | CIR-006  | 12 August 2009 at Outfall | Public through SOR | SOR has received a complaint (SOR ref: (DC/2007/12)/M45/5 00/02527) from Greenview Terrace, via Apple Daily regarding to daytime construction noise level ( $L_{eq(30\text{min})}$ ) was sometimes more than 80 dB(A) and a large amount dust generated at the outfall construction site. The complaint date was corresponded to 12 August 2009. | <p><u>Findings/ Observations</u><br/>                     Soil nailing, excavation, rock breaking and drilling, loading and unloading the materials were generally observed during monitoring period in July and August 2009. According to the noise monitoring results from 6 July 2009 to 31 August 2009 at NSR 9, the measured noise levels complied with the limit level in accordance with the EIAO-TM. All 1-hour TSP concentrations at ASR9 were below the established Action and Limit Levels from 6 July 2009 to 25 August 2009.</p> <p><u>Conclusion/Remedial Action</u><br/>                     The dust complaint was considered not justifiable since no action &amp; limit level exceedance on construction dust were identified. However, it was a recurrent case from Greenview Terrace. The Contractor was recommended to enhance water spraying continuously especially in rock breaking activities.<br/>                     On the other hand, there was no noise levels (<math>L_{eq(30\text{min})}</math>) from the measurement taken from ET was more than 80 dB(A). However, it was a recurrent case from Greenview Terrace. The Contractor was reminded to enhance the on-site noise mitigation measures. The enhanced mitigation measures are proposed as follows:</p> <ul style="list-style-type: none"> <li>• A staff from the Contractor was designated to take the reading of <math>L_{eq}</math> (5mins) at the roof of Greenview Terrace. In case of the <math>L_{eq}</math> (5min) exceed 73 dB(A), the Contractor would re-schedule the noisy plants to mitigate the escalation of noise level.</li> <li>• The designated staff was reminded to record all the weather condition including raining and wind speed.</li> <li>• Tools box talk for the Contractor's Team was carried out for reminding that the movable barrier should be placed to the breaking activities as</li> </ul> | Closed |

| Complaint No. | Log Ref. | Date/Location             | Complainant        | Details of Complaint   | Investigation / Mitigation Action  | Status                          |
|---------------|----------|---------------------------|--------------------|--|--|---------------------------------|
|               |          |                           |                    |  | <p>much as possible.</p> <ul style="list-style-type: none"> <li>• Movable noise barriers were placed on site and the movable noise barriers were also modified.</li> <li>• Existing 25 ton rock breaker had been replaced by the another breaker.</li> <li>• The breaking tap of the 25 ton rock breaker had been replaced by another breaking tap.</li> <li>• A joint filler wall was installed at the vertical face of westbound to mitigate the noise rebound from the vertical face to high level of Greenview Terrace.</li> </ul> <p>From the additional monitoring data and monitoring data under regular EM&amp;A requirements, noise level (<math>L_{eq, 30 \text{ min}}</math>) from 6 July to 31 August 2009 was in the range of 71 to 74 dB(A) to the nearest integer. The noise monitoring frequency was maintained in twice per week to check whether the mitigation measures are effective. From the information of the Contractor, all the mitigation measures were implemented on 31 August 2009. Noise levels (<math>L_{eq, 30 \text{ min}}</math>) were also re-measured after the implementation of the mitigation measures. Noise level (<math>L_{eq, 30 \text{ min}}</math>) from 4 Sep to 28 Sep 2009 was in the range of 70 to 73 dB(A) to the nearest integer after the implementation of the mitigation measures.</p> |                                 |
| 8             | CIR-007  | 14 August 2009 at Outfall | Public through EPD | <p>EPD has received a complaint (EPD ref: EP3/N22/RW/17978-09) from Greenview Terrace regarding to daytime construction noise from the outfall construction site. The complaint date was corresponded to 14 August 2009.</p> | <p><u>Findings/ Observations</u><br/>                     Soil nailing, excavation, rock breaking and drilling, loading and unloading the materials were generally observed during monitoring period in July and August 2009. According to the noise monitoring results from 6 July 2009 to 31 August 2009 at NSR 9, the measured noise levels complied with the limit level in accordance with the EIAO-TM.</p> <p><u>Conclusion/Remedial Action</u><br/>                     This was a recurrent case from Greenview Terrace. The documented complaint for noise is considered to trigger the action level and the Contractor was reminded to enhance the on-site noise mitigation measures continuously. The enhanced mitigation measures are proposed as follows:</p> <ul style="list-style-type: none"> <li>• A staff from the Contractor was designated to take the reading of <math>L_{eq}</math></li> </ul>   | Same Case with Complaint No. 11 |

| Complaint No. | Log Ref. | Date/Location                           | Complainant        | Details of Complaint  | Investigation / Mitigation Action  | Status |
|---------------|----------|---|--------------------|---|--|--------|
|               |          |   |                    |   | <p>(5mins) at the roof of Greenview Terrace. In case of the Leq (5min) exceed 73 dB(A), the Contractor would re-schedule the noisy plants to mitigate the escalation of noise level.</p> <ul style="list-style-type: none"> <li>• The designated staff was reminded to record all the weather condition including raining and wind speed.</li> <li>• Tools box talk for the Contractor's Team was carried out for reminding that the movable barrier should be placed to the breaking activities as much as possible.</li> <li>• Movable noise barriers were placed on site and the movable noise barriers were also modified.</li> <li>• Existing 25 ton rock breaker had been replaced by the another breaker.</li> <li>• The breaking tap of the 25 ton rock breaker had been replaced by another breaking tap.</li> <li>• A joint filler wall was installed at the vertical face of westbound to mitigate the noise rebound from the vertical face to high level of Greenview Terrace.</li> </ul> <p>From the additional monitoring data and monitoring data under regular EM&amp;A requirements, noise level (<math>L_{eq, 30 \text{ min}}</math>) from 6 July to 31 August 2009 was in the range of 71 to 74 dB(A) to the nearest integer. The noise monitoring frequency would be maintained in twice per week to check whether the mitigation measures are effective. From the information of the Contractor, all the mitigation measures were implemented on 31 August 2009. Noise levels (<math>L_{eq, 30 \text{ min}}</math>) were also re-measured after the implementation of the mitigation measures. Noise level (<math>L_{eq, 30 \text{ min}}</math>) from 4 Sep to 28 Sep 2009 was in the range of 70 to 73 dB(A) to the nearest integer after the implementation of the mitigation measures.</p> |        |
| 9             | CIR-008  | 17 August 2009 at Portion D of the Site | Public through SOR | SOR has received a complaint (SOR ref:(DC/2007/12)/M4 5/500/02546) from Long Bench Garden | <p><u>Findings/ Observations</u></p> <p>Soil nailing, excavation, rock breaking and drilling, loading and unloading the materials were generally observed during monitoring period in August 2009. The monitoring results from 3 August 2009 to 31 August 2009 at NSR 8 showed the measured noise levels complied with the limit level in accordance with the EIAO-TM. The contractor and the environmental</p>  | Closed |

| Complaint No. | Log Ref. | Date/Location             | Complainant        | Details of Complaint   | Investigation / Mitigation Action  | Status                          |
|---------------|----------|---------------------------|--------------------|--|--|---------------------------------|
|               |          |                           |                    | regarding to noise nuisance generated from the daytime construction work (rock-breaking) in Portion D of the Site. The complaint date was corresponded to 17 August 2009.        | team were also undertaken site investigation on the subject area in response to the complaint. Noise mitigation measures should be enhanced continuously due to this complaint.<br><u>Conclusion/Proposed Action</u><br>The documented complaint for noise is considered to trigger the action level and the Contractor was reminded to enhance the on-site noise mitigation measures continuously. The enhanced mitigation measures are recommended as follows: <ul style="list-style-type: none"> <li>• Movable noise barriers had been placed towards the direction of Long Bench Garden, particular for the pipe pile works in the portal.</li> <li>• Tools box talk for construction team was carried out for reminding that the movable barrier should be placed to the breaking activities as much as possible.</li> <li>• The existing noisy 25 ton rock breaker had been replaced by the other breaker.</li> <li>• A joint filler wall had been fixed on the vertical face of west bound to absorb the noise generated towards Long Beach Garden.</li> </ul> Noise monitoring frequency was increased twice per week by ET due to this complaint. The measured noise levels were complied with the limit level in accordance with the EIAO-TM. No further complaint was received from Long Bench Garden within the reporting month. |                                 |
| 10            | CIR-009  | 22 August 2009 at Outfall | Public through SOR | A complaint (SOR ref: (DC/2007/12)/M45/500/02628) was received from Greenview Terrace regarding to daytime construction noise level (Leq(30min)) was sometimes exceeded 75 dB(A) | <u>Findings/ Observations</u><br>Soil nailing, excavation, rock breaking and drilling, loading and unloading the materials were generally observed during monitoring period in July and August 2009. The monitoring results from 6 July 2009 to 31 August 2009 at NSR 9 showed the measured noise levels complied with the limit level in accordance with the EIAO-TM. The contractor and the environmental team were also undertaken site investigation on the subject area in response to the complaint. Noise mitigation measures should be enhanced continuously due to this complaint.<br><u>Conclusion/Proposed Action</u><br>The documented complaint for noise is considered to trigger the action level and the Contractor was reminded to enhance the on-site noise  | Same Case with Complaint No. 11 |

| Complaint No. | Log Ref. | Date/Location | Complainant | Details of Complaint  | Investigation / Mitigation Action  | Status |
|---------------|----------|---------------|-------------|---|--|--------|
|               |          |               |             | at the outfall construction site.<br>The complaint date was corresponded to 22 August 2009. | mitigation measures continuously. The enhanced mitigation measures are recommended as follows: <ul style="list-style-type: none"> <li>• A staff from the Contractor was designated to take the reading of Leq (5mins) at the roof of Greenview Terrace. In case of the Leq (5min) exceed 73 dB(A), the Contractor would re-schedule the noisy plants to mitigate the escalation of noise level.</li> <li>• The designated staff was reminded to record all the weather condition including raining and wind speed.</li> <li>• Tools box talk for the Contractor's Team was carried out for reminding that the movable barrier should be placed to the breaking activities as much as possible.</li> <li>• Movable noise barriers were placed on site and the movable noise barriers were also modified.</li> <li>• Existing 25 ton rock breaker had been replaced by the another breaker.</li> <li>• The breaking tap of the 25 ton rock breaker had been replaced by another breaking tap.</li> <li>• A joint filler wall was installed at the vertical face of westbound to mitigate the noise rebound from the vertical face to high level of Greenview Terrace.</li> </ul> From the additional monitoring data and monitoring data under regular EM&A requirements, noise level ( $L_{eq, 30 \text{ min}}$ ) from 6 July to 31 August 2009 was in the range of 71 to 74 dB(A) to the nearest integer. The noise monitoring frequency was maintained in twice per week to check whether the mitigation measures are effective. From the information of the Contractor, all the mitigation measures were implemented on 31 August 2009. Noise levels ( $L_{eq, 30 \text{ min}}$ ) were also re-measured after the implementation of the mitigation measures. Noise level ( $L_{eq, 30 \text{ min}}$ ) from 4 Sep to 28 Sep 2009 was in the range of 70 to 73 dB(A) to the nearest integer after the implementation of the mitigation measures. In our investigation, there was no exceedance of the measured noise level at Greenview Terrace. |        |

| Complaint No. | Log Ref. | Date/Location                | Complainant        | Details of Complaint   | Investigation / Mitigation Action  | Status |
|---------------|----------|------------------------------|--------------------|--|--|--------|
| 11            | CIR-010  | 24 September 2009 at Outfall | Public through SOR | A complaint (SOR ref: (DC/2007/12)/M45/500/02749) was received from Greenview Terrace regarding to daytime construction noise level (Leq(30min)) was sometimes exceeded 75 dB(A) at the outfall construction site. | <p><u>Findings/ Observations</u><br/>                     Soil nailing, excavation, rock breaking and drilling, loading and unloading the materials were generally observed during monitoring period in July and September 2009. The monitoring results from 6 July 2009 to 29 October 2009 at NSR 9 showed the measured noise levels complied with the limit level in accordance with the EIAO-TM. The contractor and the environmental team were also undertaken site investigation on the subject area in response to the complaint. Noise mitigation measures have been enhanced continuously due to this complaint.</p> <p><u>Conclusion/Proposed Action</u><br/>                     The documented complaint for noise is considered to trigger the action level and the Contractor was reminded to enhance the on-site noise mitigation measures continuously. The enhanced mitigation measures were implemented as follows:</p> <ul style="list-style-type: none"> <li>• A staff from the Contractor was designated to take the reading of Leq (5mins) at the roof of Greenview Terrace. In case of the Leq (5min) exceed 73 dB(A), the Contractor would re-schedule the noisy plants to mitigate the escalation of noise level.</li> <li>• The designated staff was reminded to record all the weather condition including raining and wind speed.</li> <li>• Tools box talk for the Contractor's Team was carried out for reminding that the movable barrier should be placed to the breaking activities as much as possible.</li> <li>• Movable noise barriers were placed on site and the movable noise barriers were also modified.</li> <li>• Existing 25 ton rock breaker had been replaced by the another breaker.</li> <li>• The breaking tap of the 25 ton rock breaker had been replaced by another breaking tap.</li> <li>• A joint filler wall was installed at the vertical face of westbound to mitigate the noise rebound from the vertical face to high level of Greenview Terrace.</li> </ul> | Closed |

| Complaint No. | Log Ref. | Date/Location         | Complainant        | Details of Complaint   | Investigation / Mitigation Action  | Status |
|---------------|----------|-----------------------|--------------------|--|--|--------|
|               |          |                       |                    |  | <p>From the additional monitoring data above and the regular monitoring under EM&amp;A requirements, the measured noise levels were complied with the limit level in accordance with the EIAO-TM. From the noise level on 25 September 2009 and 2 October 2009, the trend of noise level seemed to be increased since the decoration work at 14/F Greenview Terrace was the domain noise source during the monitoring. The noise level during that time would be considered for reference only. There was no exceedance of the measured noise level at Greenview Terrace in our investigation.</p>   |        |
| 12            | CIR-011  | 2 October 2009 at I-3 | Public through EPD | <p>EPD has received a complaint (EPD ref: EP3/N22/RW/22016-09) regarding to construction dust at the Intake-3 on 2 October 2009.</p> | <p><u>Findings/ Observations</u></p> <p>There is no representative air monitoring location as stated in the EM&amp;A Manual. The contractor and the environmental team were undertaken site investigation on the subject area at 08-Oct-09 in response to the complaint. Air quality mitigation measures as recommended in EIA have been implemented by the Contractor. However, the dust impact by exposed area could be further improved. The mitigation measures during the site investigation were observed as follows:</p> <ul style="list-style-type: none"> <li>• Water spraying was provided to the exposed surface.</li> <li>• Wheel washing facilities for dump trucks was provided at the site exit.</li> <li>• Water spraying was provided during excavation and loading/unloading works</li> </ul> <p><u>Conclusion/Proposed Action</u></p> <p>Based on our site inspection, the complaint for dust is considered justifiable as it is due to windy erosion on the exposed surface. Air quality mitigation measures as recommended in EIA have also been implemented in order to control and minimise the air quality impact arising from the construction activities. In view of the recent dry season, the haul road and the exposed area would be dry very quickly. The Contractor was recommended to provide water spraying more frequently especially in the dry season.</p> | Closed |

| Complaint No. | Log Ref.   | Date/Location                                 | Complainant                   | Details of Complaint  | Investigation / Mitigation Action   | Status  |
|---------------|--|---|-------------------------------|---|---|---------|
| 13            | (DC/2007/12)/M45/500/2923 & email on 11 November 2009 from MCSJV | 9 November 2009 at Outfall                    | Greenview Terrace through EPD | Movable noise barrier was not placed close enough to the piling machine.  | <p><u>Immediate Action</u><br/>                     The rig was re-orientated and the barrier was placed closed to the drilling head.</p> <p><u>Follow-up Action</u></p> <ul style="list-style-type: none"> <li>• Training was conducted to the operator to ensure that the workers aware that the barrier should be placed closed not the drilling head not the machine itself.</li> <li>• In order to prevent future occurrence, a permit to dig system was adopted. It should be checked by the Contractor and endorsed by the SOR before starting the drilling rig.</li> </ul> <p>The follow up action was checked and a permit to dig system has been implemented.</p> | Closed  |
| 14            | (DC/2007/12)/M45/500/2978 & email on 19 November 2009 from MCSJV | 18 November 2009 at Outfall                   | Greenview Terrace through EPD | Rock-breaking activity carried out in the eastern area of Portion D, closest to Greenview Terrace, was not totally screened and line of sight of the breaker was observed from the NSR. | <p><u>Follow up Action</u></p> <ul style="list-style-type: none"> <li>• The bamboo scaffold was extended further away from stage 3 scaffold to further screen off the activities to the Greenview. The length of the extension was about 8 to 10 m.</li> <li>• A strong reminded was given to the relevant staff and sub-contractor and the barrier should be placed in the right orientation before breaking.</li> <li>• The mitigation measures were strictly followed as stated in the proposal.</li> </ul> <p>The follow up action and relevant records was checked.</p>  | Closed  |
| 15.           | CIR-12   | 19 January 2010 at Intake-3 construction site | Public through EPD            | EPD has received a public complaint (EPD ref: EP3/N22/RW/01270-10) regarding effluent discharge at Intake-3 construction site on 19 January 2010.                                       | <p><u>Findings/ Observations</u><br/>                     The effluent discharge on 19 January 2010 was due to the leakage of Gabion wall at I3. The water from the rock drilling work was flowing through the gap of the Gabion Wall to the watercourses at I3.</p> <p><u>Immediate Action</u><br/>                     The contractor had sealed the gap at the Gabion Wall immediately after the incident.</p> <p><u>Conclusion/Proposed Action</u><br/>                     Based on our site inspection, the complaint was due to leakage of Gabion</p>  | Closed. |



| Complaint No. | Log Ref. | Date/Location                                 | Complainant        | Details of Complaint  | Investigation / Mitigation Action   | Status  |
|---------------|----------|---|--------------------|---|---|---------|
|               |          |   |                    |   | wall. The area would be checked and maintained continuously to avoid recurrence case. The above identified mitigation measures have been implemented by the Contractor on 22 January 2010 and ET has also checked the implementation on 31 January 2010. The ET will closely inspect the watercourses during the routine site inspections and provide advice to the Contractor.   |         |
| 16            | CIR-13   | 19 January 2010 at Intake-3 construction site | Public through EPD | EPD has received a public complaint (EPD ref: EP3/N22/RW/01319-10) regarding daytime construction noise at Intake-3 construction site on 19 January 2010. | <p><u>Findings/ Observations</u></p> <p>The monitoring station concerned is NSR6 (i.e. at Squatter facing to the construction site). Excavation, soil nailing, rock drilling and breaking, loading and unloading the materials were generally observed during monitoring period in mid-January 2010. The measured noise levels in January 2010 complied with the limit level in accordance with the EM&amp;A Manual. These cases would also be treated as two action level exceedances on noise. The Contractor and the Environmental Team were also undertaken site investigation on the subject area in response to complaint. The noise mitigation measures during the site investigation were recommended as follows:</p> <ul style="list-style-type: none"> <li>• Sound insulation sheets were installed covering the working area during breaking and rock drilling in order to block the line of sight to the NSR.</li> <li>• Noise insulation materials were used to enclose the drilling rig tightly.</li> </ul> <p><u>Conclusion/Proposed Action</u></p> <p>Based on the site inspection and monitoring results, the complaint was due to noise generated by rock breaking work. The identified mitigation measures have been discussed with the Contractor and the Contractor has submitted the remedial proposal. The proposal was implemented by the Contractor on 25 January 2010 and ET has also checked the implementation on 31 January 2010. The Contractor was also advised to review the mitigation measures from time to time near the NSR at I3. The ET will closely inspect the area during the routine site inspections and provide advice to the Contractor.</p> | Closed. |
| 17            | CIR-13   | 21 January 2010 at Intake-3                   | Public through     | EPD has received a public complaint (EPD ref:   | Refers to Investigation /Mitigation Action for Complaint No. 16.  | Closed  |

| Complaint No. | Log Ref. | Date/Location                                  | Complainant        | Details of Complaint  | Investigation / Mitigation Action  | Status |
|---------------|----------|--|--------------------|---|--|--------|
|               |          | construction site                              | EPD                | EP3/N22/RW/01444-10) regarding daytime construction noise at Intake-3 construction site on 21 January 2010.                   |  |        |
| 18            | CIR-14   | 27 August 2010 near Intake-2 construction site | Public through DSD | DSD has received a public complaint regarding choked sewage manhole (MH1) at Lo Wai Road construction site on 27 August 2010. | <p><u>Findings/ Observations</u><br/>                     During DSD inspection on 30 August 2010, improper discharge from the site to manhole, MH3, which is located downstream of MH1 was observed. ET had received those information from the Contractor on 09 September 2010. Site investigation was also carried out by SOR's representative with the Contractor on 01 September 2010. Checking with the site log, the construction activity at Lo Wai on 27 August 2010 was pipe jacking only. No site formation works was undertaken. The contractor and SOR's representative have undertaken site investigation on the subject area on 01 September 2010. On-site flow test at Portion G had conducted.</p> <ul style="list-style-type: none"> <li>● Maeda works area is located at the lower section of Lo Wai Road and manhole MH3 is adjacent to the works area. MH1 (choked sewage manhole) is located at the upper section of Lo Wai Road. MH2 manhole is located middle section of Lo Wai Road. MH1 and MH2 are outside the works area.</li> <li>● Water flow test for manhole MH2 and MH3 and no blockage was observed.</li> <li>● Sewage overflow was found at MH1 during the joint site inspection on 01 September 2010</li> <li>● It was reported that there were water pipes connected between the site and the MH3. Discharge was found in MH3 during DSD inspection.</li> <li>● The contractor claimed that the purpose of the water pipes was to direct the storm water and underground water inside the concrete pipe "pipe jacking".</li> <li>● There was no discharge license for that portion. The Contractor had stopped on 01 September 2010 the water pumping to MH3 and</li> </ul> | Closed |

| Complaint No. | Log Ref. | Date/Location                                 | Complainant        | Details of Complaint  | Investigation / Mitigation Action  | Status |
|---------------|----------|---|--------------------|---|--|--------|
|               |          |   |                    |   | <p>apply the discharge license for the Lo Wai site.</p> <p><u>Conclusion/Proposed Action</u><br/>                     Based on the joint site inspection, the choked manhole MH1 was not due to works activities. The Contractor had clean up the choked manhole MH1 and no sewage overflow from MH1 was observed. The Contractor was requested to divert the storm water to desilting system prior to discharge while no such discharge can be made until a valid discharge license is granted. The ET will closely inspect the vicinity area during the routine site inspections and provide advice to the Contractor as necessary.</p>  |        |
| 19&20         | CIR-15   | 17 November 2010 at outfall construction site | Public through EPD | EPD has received a public complaint (EPD ref: EP3/N22/RW/24002-10 and EP3/N22/RW/24006-10) regarding daytime construction noise about derrick barge squeaking and rock breaking at Outfall construction site on 17 November 2010. | <p><u>Findings/ Observations</u><br/>                     Drilling, excavation, marine mud dredging, rock breaking, mucking-out process and crane operation were observed during site inspections on 2 and 17 December 2010. The monitoring results measured on 15 November 2010 and 25 November at NSR 9 showed that the measured noise levels complied with the limit level (75 dB(A)) in accordance with the EIAO-TM. As part of the investigation of the noise complaints, the Contractor and the ET conducted additional site inspections and reviewed and audited the current noise mitigation practices and the Contractor's environmental performance on-site.</p> <p><u>Conclusion / Proposed Action</u><br/>                     The documented complaints for noise triggered the action level of the noise monitoring. The Contractor had implemented the following on-site noise mitigation measures:</p> <ul style="list-style-type: none"> <li>● Erection of temporary noise insulation sheet at the rim of the spiral ramp construction site;</li> <li>● Moveable barriers for rock breaker;</li> <li>● Wrapping noise absorptive material at the rock breaker head;</li> <li>● Tailor made noise enclosure for drilling rig;</li> <li>● Semi-enclosed muck out process at muck hopper;</li> <li>● Use of rock splitter (which is a relatively quieter method in contrast to rock breaker); and</li> <li>● Noise insulation blanket enclosing the crane engine of derrick barge.</li> </ul> <p>Noise monitoring was increased to twice per week and the results were</p> | Closed |

| Complaint No. | Log Ref. | Date/Location                                | Complainant        | Details of Complaint   | Investigation / Mitigation Action  | Status |
|---------------|----------|--|--------------------|--|--|--------|
|               |          |  |                    |  | reported in the Complaint Investigation Report submitted on 24 December 2010. The measured noise level after implementation of the noise mitigation measures ranged from 69 to 73 dB(A) to the nearest integer and complied with the limit level in accordance with the EIAO-TM. The results showed that noise mitigation measures were effective. The contractor was advised to review the mitigation measures from time to time near the NSR 9. The ET would closely inspect the area during the routine site inspections and provide advice to the Contractor.  |        |
| 21            | CIR-16   | 10 January 2011 at outfall construction site | Public through EPD | EPD has received a public complaint (EPD ref: EP3/N22/RW/00484-11) regarding dark smoke emission from derrick barge and construction noise and dust at Outfall construction site on 10 January 2011. | <p><u>Findings/ Observations</u></p> <p>1. <u>Dark Smoke Emission from Derrick Barge</u><br/>                     Dark smoke emitted from the derrick barge was promptly investigated after the receipt of the complaint. The issue was found specific to the mechanical operation of the barge working at the site at that moment. The derrick barge being complained was then replaced by another barge without the relevant mechanical issue. No further complaint was received since then.</p> <p>2. <u>Construction Dust</u><br/>                     Regular 1-hour TSP monitoring, in accordance with EM&amp;A Manual, was carried out by the Environmental Team (ET). The monitoring station concerned is ASR 9, located at the podium level of Greenview Terrace facing the construction site. In January, 1 hour TSP concentration monitoring had been conducted on 4, 10, 14, 20 and 26 January 2011 at Greenview Terrace (ASR). Rock breaking, drilling and excavation were observed during monitoring. No exceedance was recorded.<br/>                     The contractor and the environmental team were also undertaken site investigation at the subject area on 21 January 2011 in response to the complaint. It was confirmed that the air quality mitigation measures as recommended in EIA had been provided by the Contractor. The mitigation measures are as follows:</p> <ul style="list-style-type: none"> <li>● Water spraying surrounding the spiral ramp;</li> <li>● Water spraying for rock drilling and rock breaking;</li> <li>● Water spraying for C&amp;D material before loading and unloading to</li> </ul> | Closed |

| Complaint No. | Log Ref. | Date/Location | Complainant | Details of Complaint | Investigation / Mitigation Action  | Status |
|---------------|----------|---------------|-------------|----------------------|--|--------|
|               |          |               |             |                      | <p>derrick barge;</p> <ul style="list-style-type: none"> <li>● Water spraying for the exposed surface and the haul road;</li> <li>● Water spraying for trucks and vehicles at the site exit.</li> </ul> <p>3. <u>Construction Noise</u></p> <p>The documented complaints for noise triggered the action level of the noise monitoring. The Contractor had implemented the following on-site noise mitigation measures:</p> <ul style="list-style-type: none"> <li>● Extension of Temporary noise insulation barrier (made of noise blanket) at the rim of the spiral ramp construction site facing Greenview Terrace;</li> <li>● Movable noise barriers to surround the rock breaking activities at the spiral ramp where it is in safe ground condition;</li> <li>● Tailor made noise enclosure for rock drilling machine;</li> <li>● Semi-enclosed muck out process at muck hopper (with noise curtain underneath);</li> <li>● Use of temporary noise enclosure for piling work at Castle Peak Road;</li> <li>● Noise insulation blanket enclosing the crane engine of derrick barge;</li> <li>● Additional noise blanket along the railings of the spiral ramp; and</li> <li>● Use of rock splitter (which is a relatively quieter method in contrast to rock breaker).</li> </ul> <p>Noise monitoring has been increased to twice per week and the results will be reported in the Complaint Investigation Report to be submitted in mid-February 2011. The measured noise level after implementation of the noise mitigation measures ranged from 71 to 74 dB(A) to the nearest integer and complied with the limit level in accordance with the EIAO-TM. The results showed that noise mitigation measures were effective. The contractor was advised to review the mitigation measures from time to time near the NSR 9. The ET would closely inspect the area during the routine site inspections and provide advice to the Contractor.</p> <p><u>Conclusion / Proposed Action</u></p> <p>1. <u>Dark Smoke Emission from Derrick Barge</u><br/>                     Dark smoke emitted from the derrick barge was considered a stand-alone</p> |        |

| Complaint No. | Log Ref. | Date/Location                              | Complainant        | Details of Complaint   | Investigation / Mitigation Action  | Status |
|---------------|----------|--|--------------------|--|--|--------|
|               |          |  |                    |  | <p>incident and was specific to the derrick barge being complained. No further complaint was received after the barge was replaced by another.</p> <p>2. <u>Construction Dust</u><br/>                     Based on our site inspection and monitoring results, the complaint was considered not justifiable since no action and limit level exceedance on construction dust were identified. Air quality mitigation measures as recommended in EIA were implemented in order to control and minimize the air quality impact and nuisance arising from the construction activities. Nevertheless, the Contractor was reminded to enhance the air quality mitigation measures such as increasing the water spraying frequency and ensure proper functioning of the automatic sprinklers at the Outfall construction site.</p> <p>3. <u>Construction Noise</u><br/>                     Noise measurement results between 10 and 28 January 2011 were below the limit level (75 dB(A)) and complied with the noise criterion. The Contractor had implemented various mitigation measures on site to alleviate the construction noise impact. The ET will remind the Contractor to enhance and maintain the normal functioning of the measures continuously to minimize the impact. The Contractor should also closely liaise with the nearby residents and inform the progress of the construction and the implementation of the environmental mitigation measures at the Outfall construction site.</p> |        |
| 22            | CIR-17   | 30 June 2011 at Intake-3 construction site | Public through EPD | EPD has received a public complaint (EPD ref: EP3/N22/RW/12759-11) regarding construction dust and daytime construction noise from the Intake-3 construction site on 30 June | <p>1. <u>Findings / Observations</u><br/>                     Checking with the site log, construction activities conducted at I-3 were breaking / mucking out and rock splitting inside the shaft, curing of planter wall, backfilling at tree pit, slope reinstatement and backfilling at PB wall, monitoring of de-deformation monitoring point, and general site cleaning and housekeeping. The Contractor and ET undertook site investigations on the subject area on 8 and 20 July 2011. The following dust and noise mitigation measures were implemented during site investigations:<br/> <u>Dust Mitigation Measures (implemented prior to the complaint)</u></p> <ul style="list-style-type: none"> <li>● All the main haul road was paved;</li> </ul>   | Closed |

| Complaint No. | Log Ref. | Date/Location | Complainant | Details of Complaint | Investigation / Mitigation Action  | Status |
|---------------|----------|---------------|-------------|----------------------|--|--------|
|               |          |               |             | 2011.                | <ul style="list-style-type: none"> <li>● Material transported by a dump truck was covered with impervious sheeting;</li> <li>● Exposed soil slope surface near the PB wall was covered by tarpaulin sheets;</li> <li>● Hoardings (with 2.4 m high) were provided along the site boundary next to the access road;</li> <li>● Regular watering on haul roads by sprinklers was observed;</li> <li>● Vehicle speed limit of 5 km per hour was implemented within the construction site;</li> <li>● Water spraying for dust suppression of on-going “dusty” activities (essentially including drilling and rock breaking within the shaft of about 16.5 m below ground) was observed;</li> </ul> <p><u>Construction Noise Mitigation Measures (implemented prior to the complaint)</u></p> <ul style="list-style-type: none"> <li>● Temporary noise barriers (about 4 m high) were erected on the shaft concrete block wall;</li> <li>● Quiet plant (rock splitter) was employed for shaft excavation;</li> <li>● Noise from generator was screened by a temporary noise barrier; and</li> <li>● Breaker heads of rock breaking machine were wrapped with sound insulating materials.</li> </ul> <p>2. <u>Conclusion / Proposed Action</u></p> <p>As there are no substantial noise sources at I-3 other than the project construction activities, it is considered that the noise complaint is project-related. In accordance with the Event / Action Plan for Construction Noise specified in the EM&amp;A Manual, noise monitoring frequency at the squatters (NSR 6) near I-3 were increased to twice per week (from 11 July 2011 to 30 July 2011) due to this complaint. The measured noise levels (<math>L_{eq, 30 \text{ min}}</math>) are shown in the following table. The measured noise levels, ranged from 60.0 dB(A) to 68.9 dB(A), are well below the limit level (75 dB(A)) in accordance with the EIAO-TM. During the site investigations on 8 and 20 July 2011, the above noise mitigation measures were continuously implemented. No further noise complaint was received in July 2011. Thus, with the consideration of the noise measurement results</p> |        |

| Complaint No. | Log Ref.   | Date/Location | Complainant             | Details of Complaint | Investigation / Mitigation Action  | Status |            |          |                         |                    |                                  |          |       |       |      |    |                 |           |       |       |      |    |                            |           |       |       |      |    |                            |           |       |       |      |    |                              |           |       |       |      |    |                            |           |       |       |      |    |                         |           |       |       |      |    |                              |  |
|---------------|------------|---------------|-------------------------|----------------------|--|--------|------------|----------|-------------------------|--------------------|----------------------------------|----------|-------|-------|------|----|-----------------|-----------|-------|-------|------|----|----------------------------|-----------|-------|-------|------|----|----------------------------|-----------|-------|-------|------|----|------------------------------|-----------|-------|-------|------|----|----------------------------|-----------|-------|-------|------|----|-------------------------|-----------|-------|-------|------|----|------------------------------|--|
|               |            |               |                         |                      | <p>and implementation of the above noise mitigation measures, the construction noise is considered acceptable. The Contractor will maintain the noise mitigation measures mentioned above to minimise noise nuisance.</p> <table border="1" data-bbox="1088 453 1957 1059"> <thead> <tr> <th>Date</th> <th>Start Time</th> <th>End Time</th> <th>L<sub>eq</sub>, dB(A)</th> <th>Limit Level, dB(A)</th> <th>Major Construction Noise Sources</th> </tr> </thead> <tbody> <tr> <td>6-Jul-11</td> <td>11:17</td> <td>11:47</td> <td>60.0</td> <td>75</td> <td>Crane operation</td> </tr> <tr> <td>14-Jul-11</td> <td>16:00</td> <td>16:30</td> <td>67.0</td> <td>75</td> <td>Drilling and rock breaking</td> </tr> <tr> <td>15-Jul-11</td> <td>17:00</td> <td>17:30</td> <td>68.9</td> <td>75</td> <td>Drilling and rock breaking</td> </tr> <tr> <td>18-Jul-11</td> <td>13:30</td> <td>14:00</td> <td>65.7</td> <td>75</td> <td>Drilling and crane operation</td> </tr> <tr> <td>20-Jul-11</td> <td>13:10</td> <td>13:40</td> <td>68.1</td> <td>75</td> <td>Drilling and rock breaking</td> </tr> <tr> <td>28-Jul-11</td> <td>13:35</td> <td>14:05</td> <td>64.9</td> <td>75</td> <td>Drilling and excavation</td> </tr> <tr> <td>30-Jul-11</td> <td>09:10</td> <td>09:40</td> <td>63.6</td> <td>75</td> <td>Drilling and crane operation</td> </tr> </tbody> </table> <p>Remark:<br/>                     The location of powered mechanical equipment (PME) will change occasionally and the utilization time for each PME may not be constant.</p> <p>As observed during the site investigation on 8 July 2011, dust suppression measures aforementioned were implemented on site. Additional dust control measures have been implemented at I-3 by the Contractor in early July 2011 to further suppress dust emission:</p> <ol style="list-style-type: none"> <li>1) Tailor-made frame with blankets has been installed for the drilling rig;</li> <li>2) Water hoses have been installed to the drilling rig within the tailor-made frame during drilling; and</li> <li>3) Water smog device installed at the edge of intermediate platform of</li> </ol> | Date   | Start Time | End Time | L <sub>eq</sub> , dB(A) | Limit Level, dB(A) | Major Construction Noise Sources | 6-Jul-11 | 11:17 | 11:47 | 60.0 | 75 | Crane operation | 14-Jul-11 | 16:00 | 16:30 | 67.0 | 75 | Drilling and rock breaking | 15-Jul-11 | 17:00 | 17:30 | 68.9 | 75 | Drilling and rock breaking | 18-Jul-11 | 13:30 | 14:00 | 65.7 | 75 | Drilling and crane operation | 20-Jul-11 | 13:10 | 13:40 | 68.1 | 75 | Drilling and rock breaking | 28-Jul-11 | 13:35 | 14:05 | 64.9 | 75 | Drilling and excavation | 30-Jul-11 | 09:10 | 09:40 | 63.6 | 75 | Drilling and crane operation |  |
| Date          | Start Time | End Time      | L <sub>eq</sub> , dB(A) | Limit Level, dB(A)   | Major Construction Noise Sources   |        |            |          |                         |                    |                                  |          |       |       |      |    |                 |           |       |       |      |    |                            |           |       |       |      |    |                            |           |       |       |      |    |                              |           |       |       |      |    |                            |           |       |       |      |    |                         |           |       |       |      |    |                              |  |
| 6-Jul-11      | 11:17      | 11:47         | 60.0                    | 75                   | Crane operation  |        |            |          |                         |                    |                                  |          |       |       |      |    |                 |           |       |       |      |    |                            |           |       |       |      |    |                            |           |       |       |      |    |                              |           |       |       |      |    |                            |           |       |       |      |    |                         |           |       |       |      |    |                              |  |
| 14-Jul-11     | 16:00      | 16:30         | 67.0                    | 75                   | Drilling and rock breaking   |        |            |          |                         |                    |                                  |          |       |       |      |    |                 |           |       |       |      |    |                            |           |       |       |      |    |                            |           |       |       |      |    |                              |           |       |       |      |    |                            |           |       |       |      |    |                         |           |       |       |      |    |                              |  |
| 15-Jul-11     | 17:00      | 17:30         | 68.9                    | 75                   | Drilling and rock breaking   |        |            |          |                         |                    |                                  |          |       |       |      |    |                 |           |       |       |      |    |                            |           |       |       |      |    |                            |           |       |       |      |    |                              |           |       |       |      |    |                            |           |       |       |      |    |                         |           |       |       |      |    |                              |  |
| 18-Jul-11     | 13:30      | 14:00         | 65.7                    | 75                   | Drilling and crane operation   |        |            |          |                         |                    |                                  |          |       |       |      |    |                 |           |       |       |      |    |                            |           |       |       |      |    |                            |           |       |       |      |    |                              |           |       |       |      |    |                            |           |       |       |      |    |                         |           |       |       |      |    |                              |  |
| 20-Jul-11     | 13:10      | 13:40         | 68.1                    | 75                   | Drilling and rock breaking   |        |            |          |                         |                    |                                  |          |       |       |      |    |                 |           |       |       |      |    |                            |           |       |       |      |    |                            |           |       |       |      |    |                              |           |       |       |      |    |                            |           |       |       |      |    |                         |           |       |       |      |    |                              |  |
| 28-Jul-11     | 13:35      | 14:05         | 64.9                    | 75                   | Drilling and excavation  |        |            |          |                         |                    |                                  |          |       |       |      |    |                 |           |       |       |      |    |                            |           |       |       |      |    |                            |           |       |       |      |    |                              |           |       |       |      |    |                            |           |       |       |      |    |                         |           |       |       |      |    |                              |  |
| 30-Jul-11     | 09:10      | 09:40         | 63.6                    | 75                   | Drilling and crane operation   |        |            |          |                         |                    |                                  |          |       |       |      |    |                 |           |       |       |      |    |                            |           |       |       |      |    |                            |           |       |       |      |    |                              |           |       |       |      |    |                            |           |       |       |      |    |                         |           |       |       |      |    |                              |  |



| Complaint No. | Log Ref. | Date/Location                                     | Complainant            | Details of Complaint  | Investigation / Mitigation Action  | Status |
|---------------|----------|---|------------------------|---|--|--------|
|               |          |   |                        |   | <p>the shaft.</p> <p>The Contractor have continuously applied all the above mentioned dust suppression measures to minimise airborne dust generation, as observed during the site investigation on 20 July 2011. No dust dispersion from the construction site was observed during the site investigations on 8 and 20 July 2011. In addition, no further construction dust complaint is received in July 2011. As such, it is considered that the dust suppression measures implemented on site are adequate to minimise dust nuisance. The Contractor will maintain these measures on site for construction dust control.</p> <p>3. <u>Follow Up Action(s)</u></p> <p>For this complaint, the Contractor has implemented adequate mitigation measures for construction dust and noise control. As no further complaint is received in July 2011, it is considered that the complaint is closed. Nevertheless, the ET will continuously review the condition of the site during the routine site inspections, inspect proper functioning of the aforementioned construction dust and noise mitigation measures, and provide advice to the Contractor to be vigilant and tailor mitigation measures in advance of future planned site work activities.</p> |        |
| 23            | CIR-18   | 2 September 2011 at Sheung Kok Shan near Intake 2 | Mr. Cheung through EPD | EPD have received a complaint from Mr. Cheung, who lived in Sheung Kok Shan, concerning construction noise arising from the use of the TBM at night time. He alleged that the noise emanated from the tunnelling works had caused | <p>1. <u>Findings / Observations</u></p> <p>According to the approved EIA Report, it is recommended to restrict the tunnel boring machine (TBM) operation in the non-restricted period for tunnel section from chainage 1295 m to 1449 m. Checking with the site log, the Contractor has strictly followed the EIA recommendation for the TBM operation within the non-restricted period between the chainage 1295 m to 1449 m. TBM moved from CH1449 on 11 August 2011 and passed through CH1295 on 23 August 2011, and the Contractor resumed night time TBM operation afterwards. TBM was operating at night time (from 01:10 to 07:00) on 26 August 2011 (about 55 m away from the EIA restricted zone and about 22 m away from Mr. Cheung's house, which is located near CH1218).</p>   | Closed |

| Complaint No.    | Log Ref.                          | Date/Location  | Complainant | Details of Complaint                  | Investigation / Mitigation Action  | Status |                                   |        |                  |                              |  |                  |   |                             |                  |   |                             |                  |   |                             |                  |   |                             |  |
|------------------|-----------------------------------|--|-------------|---------------------------------------|--|--------|-----------------------------------|--------|------------------|------------------------------|--|------------------|---|-----------------------------|------------------|---|-----------------------------|------------------|---|-----------------------------|------------------|---|-----------------------------|--|
|                  |                                   |  |             | nuisance to him since 26 August 2011. | <p>First verbal complaint from Mr. Cheung was received in the morning of 26 August 2001 by the Contractor. The Contractor had stopped TBM night time operation from 26 August to 01 September 2011 accordingly. On 01 September 2011, TBM was located 38 m away from Mr. Cheung's house and the Contractor attempted to resume the night time operation.</p> <p>Second verbal complaint from Mr. Cheung was received on 02 September 2011 by EPD. The Contractor took immediate measure to stop the night time operation from 02 to 07 September 2011. On 08 September 2011, TBM moved 109 m away from Mr. Cheung's house. The Contractor attempted to resume night time operation and no further complaint was received after that.</p> <p>2. <u>Mitigation Measure Implemented after Receiving the Complaints</u></p> <p>Night time operation of the TBM was restricted as shown in the following table:</p> <table border="1" data-bbox="1086 826 1944 1420"> <thead> <tr> <th data-bbox="1086 826 1281 906">Period</th> <th data-bbox="1281 826 1489 906">Night Time Operation<sup>1</sup></th> <th data-bbox="1489 826 1944 906">Remark</th> </tr> </thead> <tbody> <tr> <td data-bbox="1086 906 1281 1109">25 - 26 Aug 2011</td> <td data-bbox="1281 906 1489 1109">From 01:10 to 07:00 (26 Aug)</td> <td data-bbox="1489 906 1944 1109">The Contractor received a verbal complaint in the morning (26 Aug 2011). The Contractor began to stop night time TBM operation. TBM was located about 22 m away from Mr. Cheung's house.</td> </tr> <tr> <td data-bbox="1086 1109 1281 1189">26 - 27 Aug 2011</td> <td data-bbox="1281 1109 1489 1189">-</td> <td data-bbox="1489 1109 1944 1189">No night time TBM operation</td> </tr> <tr> <td data-bbox="1086 1189 1281 1268">27 - 28 Aug 2011</td> <td data-bbox="1281 1189 1489 1268">-</td> <td data-bbox="1489 1189 1944 1268">No night time TBM operation</td> </tr> <tr> <td data-bbox="1086 1268 1281 1348">28 - 29 Aug 2011</td> <td data-bbox="1281 1268 1489 1348">-</td> <td data-bbox="1489 1268 1944 1348">No night time TBM operation</td> </tr> <tr> <td data-bbox="1086 1348 1281 1420">29 - 30 Aug 2011</td> <td data-bbox="1281 1348 1489 1420">-</td> <td data-bbox="1489 1348 1944 1420">No night time TBM operation</td> </tr> </tbody> </table> | Period | Night Time Operation <sup>1</sup> | Remark | 25 - 26 Aug 2011 | From 01:10 to 07:00 (26 Aug) | The Contractor received a verbal complaint in the morning (26 Aug 2011). The Contractor began to stop night time TBM operation. TBM was located about 22 m away from Mr. Cheung's house. | 26 - 27 Aug 2011 | - | No night time TBM operation | 27 - 28 Aug 2011 | - | No night time TBM operation | 28 - 29 Aug 2011 | - | No night time TBM operation | 29 - 30 Aug 2011 | - | No night time TBM operation |  |
| Period           | Night Time Operation <sup>1</sup> | Remark   |             |                                       |  |        |                                   |        |                  |                              |  |                  |   |                             |                  |   |                             |                  |   |                             |                  |   |                             |  |
| 25 - 26 Aug 2011 | From 01:10 to 07:00 (26 Aug)      | The Contractor received a verbal complaint in the morning (26 Aug 2011). The Contractor began to stop night time TBM operation. TBM was located about 22 m away from Mr. Cheung's house. |             |                                       |  |        |                                   |        |                  |                              |  |                  |   |                             |                  |   |                             |                  |   |                             |                  |   |                             |  |
| 26 - 27 Aug 2011 | -                                 | No night time TBM operation  |             |                                       |  |        |                                   |        |                  |                              |  |                  |   |                             |                  |   |                             |                  |   |                             |                  |   |                             |  |
| 27 - 28 Aug 2011 | -                                 | No night time TBM operation  |             |                                       |  |        |                                   |        |                  |                              |  |                  |   |                             |                  |   |                             |                  |   |                             |                  |   |                             |  |
| 28 - 29 Aug 2011 | -                                 | No night time TBM operation  |             |                                       |  |        |                                   |        |                  |                              |  |                  |   |                             |                  |   |                             |                  |   |                             |                  |   |                             |  |
| 29 - 30 Aug 2011 | -                                 | No night time TBM operation  |             |                                       |  |        |                                   |        |                  |                              |  |                  |   |                             |                  |   |                             |                  |   |                             |                  |   |                             |  |

| Complaint No. | Log Ref. | Date/Location | Complainant | Details of Complaint | Investigation / Mitigation Action  |                                       |  | Status |
|---------------|----------|---------------|-------------|----------------------|--|---------------------------------------|--|--------|
|               |          |               |             |                      | 30 - 31 Aug 2011   | -                                     | No night time TBM operation  |        |
|               |          |               |             |                      | 31 Aug - 01 Sep 2011   | --                                    | No night time TBM operation. TBM was located about 38 m away from Mr. Cheung's house.  |        |
|               |          |               |             |                      | 01 - 02 Sep 2011   | From 23:00 (01 Sep) to 04:50 (02 Sep) | The Contractor attempted to resume night time TBM operation on 01 Sep 2011. ET received a complaint via EPD in the morning (2 Sep 2011). The Contractor began to stop night time TBM operation on 02 Sep 2011. |        |
|               |          |               |             |                      | 02 - 03 Sep 2011   | -                                     | No night time TBM operation  |        |
|               |          |               |             |                      | 03 - 04 Sep 2011   | -                                     | No night time TBM operation  |        |
|               |          |               |             |                      | 04 - 05 Sep 2011   | -                                     | No night time TBM operation  |        |
|               |          |               |             |                      | 05 - 06 Sep 2011   | -                                     | No night time TBM operation  |        |
|               |          |               |             |                      | 06 - 07 Sep 2011   | -                                     | No night time TBM operation  |        |
|               |          |               |             |                      | 07 - 08 Sep 2011   | From 06:00 to 07:00 (08 Sep 2011)     | TBM was located about 109 m away from Mr. Cheung's house. The Contractor attempted to resume TBM night time operation and no further complaint was received.   |        |
|               |          |               |             |                      | Remark: 1. "Night Time" refers to 23:00 to 07:00 of the following day.<br>3. <u>Conclusion / Proposed Action</u><br>Having reviewed the timing of the complaints and periods of TBM operation during the night time on 25 - 26 August 2011 and 1 - 2 |                                       |  |        |

| Complaint No. | Log Ref. | Date/Location                                 | Complainant           | Details of Complaint   | Investigation / Mitigation Action   | Status |
|---------------|----------|---|-----------------------|--|---|--------|
|               |          |   |                       |  | <p>September 2011, it is believed that the complaints are related to the TBM operation during the night time. The Contractor has undertaken swift and appropriate action in response to Mr. Cheung's complaints. The night time operation of the TBM was restricted following the complaint. As the TBM continues to operate during the day time and moves further away from Mr. Cheung's house, the ground-borne noise nuisance upon Mr. Cheung gradually fades away. It is considered that the nuisance caused by TBM night time operation is then imperceptible from the complainant. No further complaint is received after 2 September 2011. As such, no further action is required.</p> <p>4. <u>Follow Up Action(s)</u></p> <p>For this complaint, the Contractor has implemented adequate mitigation measure (that is, restricting the TBM to operate during the day time only) for ground-borne noise control. The TBM has moved further away from Mr. Cheung's house and no further complaint is received after the Contractor resumed the TBM night time operation (08 September 2011). Thus, it is considered that the complaint is closed.</p> |        |
| 24            | CIR-19   | 8 February 2012 at Intake-3 Construction Site | Mr. Cheng through SOR | SOR has received a public complaint regarding daytime construction noise from the Intake-3 construction site on 8 February 2012. | <p>1) <u>Findings / Observations</u></p> <p>Checking with the site log, construction activities conducted at I-3 in that morning was rock breaking by hydraulic breaker at the proposed access road. The Contractor and ET undertook site investigations on the subject area on 9 February 2012. The following noise mitigation measures were implemented during site investigations:</p> <p><u>Construction Noise Mitigation Measures (implemented prior to the complaint)</u></p> <p>1) Noise barrier on the top of vortex shaft was maintained;<br/>                 2) Silent type breaker tip was utilized; and<br/>                 3) Breaker tip was wrapped by acoustic insulating material.</p>   | Closed |

| Complaint No. | Log Ref.   | Date/Location | Complainant      | Details of Complaint | Investigation / Mitigation Action  | Status |            |          |                  |                    |                                  |            |       |       |      |    |                                   |             |       |       |      |    |                                      |             |       |       |      |    |                                   |  |
|---------------|------------|---------------|------------------|----------------------|--|--------|------------|----------|------------------|--------------------|----------------------------------|------------|-------|-------|------|----|-----------------------------------|-------------|-------|-------|------|----|--------------------------------------|-------------|-------|-------|------|----|-----------------------------------|--|
|               |            |               |                  |                      | <p>2) <u>Conclusion / Proposed Action</u></p> <p>As there are no substantial noise sources at I-3 other than the project construction activities, it is considered that the noise complaint is project-related. In accordance with the Event / Action Plan for Construction Noise specified in the EM&amp;A Manual, noise monitoring frequency at the squatters (NSR 6) near I-3 were increased to twice per week (from 10 February 2012 to 29 February 2012) due to this complaint. The measured noise levels (<math>L_{eq, 30 \text{ minutes}}</math>) are shown in the following table. The measured noise levels, ranged from 59.5 dB(A) to 68.1 dB(A), are well below the limit level (75 dB(A)) in accordance with the EIAO-TM. During the site investigations on 9 and 23 February 2012, the above noise mitigation measures were continuously implemented. No further noise complaint was received in February 2012. Thus, with the consideration of the noise measurement results and implementation of the above noise mitigation measures, the construction noise is considered acceptable. The Contractor will maintain the noise mitigation measures mentioned above to minimise noise nuisance.</p> <table border="1" data-bbox="1093 946 1944 1406"> <thead> <tr> <th>Date</th> <th>Start Time</th> <th>End Time</th> <th><math>L_{eq}</math>, dB(A)</th> <th>Limit Level, dB(A)</th> <th>Major Construction Noise Sources</th> </tr> </thead> <tbody> <tr> <td>7-Feb-2012</td> <td>13:28</td> <td>13:58</td> <td>60.2</td> <td>75</td> <td>Crane operation and rock breaking</td> </tr> <tr> <td>10-Feb-2012</td> <td>15:15</td> <td>15:45</td> <td>62.1</td> <td>75</td> <td>Crane operation and excavation works</td> </tr> <tr> <td>13-Feb-2012</td> <td>13:35</td> <td>14:05</td> <td>68.1</td> <td>75</td> <td>Crane operation and rock breaking</td> </tr> </tbody> </table> | Date   | Start Time | End Time | $L_{eq}$ , dB(A) | Limit Level, dB(A) | Major Construction Noise Sources | 7-Feb-2012 | 13:28 | 13:58 | 60.2 | 75 | Crane operation and rock breaking | 10-Feb-2012 | 15:15 | 15:45 | 62.1 | 75 | Crane operation and excavation works | 13-Feb-2012 | 13:35 | 14:05 | 68.1 | 75 | Crane operation and rock breaking |  |
| Date          | Start Time | End Time      | $L_{eq}$ , dB(A) | Limit Level, dB(A)   | Major Construction Noise Sources   |        |            |          |                  |                    |                                  |            |       |       |      |    |                                   |             |       |       |      |    |                                      |             |       |       |      |    |                                   |  |
| 7-Feb-2012    | 13:28      | 13:58         | 60.2             | 75                   | Crane operation and rock breaking  |        |            |          |                  |                    |                                  |            |       |       |      |    |                                   |             |       |       |      |    |                                      |             |       |       |      |    |                                   |  |
| 10-Feb-2012   | 15:15      | 15:45         | 62.1             | 75                   | Crane operation and excavation works   |        |            |          |                  |                    |                                  |            |       |       |      |    |                                   |             |       |       |      |    |                                      |             |       |       |      |    |                                   |  |
| 13-Feb-2012   | 13:35      | 14:05         | 68.1             | 75                   | Crane operation and rock breaking  |        |            |          |                  |                    |                                  |            |       |       |      |    |                                   |             |       |       |      |    |                                      |             |       |       |      |    |                                   |  |

| Complaint No. | Log Ref. | Date/Location | Complainant | Details of Complaint | Investigation / Mitigation Action  |       |       |      |    |                                      | Status |
|---------------|----------|---------------|-------------|----------------------|--|-------|-------|------|----|--------------------------------------|--------|
|               |          |               |             |                      |  |       |       |      |    |                                      |        |
|               |          |               |             |                      | 17-Feb-2012  | 16:20 | 16:50 | 60.2 | 75 | Crane operation and excavation works |        |
|               |          |               |             |                      | 20-Feb-2012  | 13:33 | 14:03 | 66.4 | 75 | Crane operation and rock breaking    |        |
|               |          |               |             |                      | 23-Feb-2012  | 14:30 | 15:00 | 64.3 | 75 | Crane operation and rock breaking    |        |
|               |          |               |             |                      | 27-Feb-2012  | 11:10 | 11:40 | 63.4 | 75 | Crane operation and rock breaking    |        |
|               |          |               |             |                      | 29-Feb-2012  | 13:26 | 13:56 | 59.5 | 75 | Crane operation and rock breaking    |        |
|               |          |               |             |                      | Remark:<br>The location of powered mechanical equipment (PME) will change occasionally and the utilization time for each PME may not be constant.<br><br>Additional noise mitigation measures have been implemented at I-3 by the Contractor to further reduce the construction noise: <ul style="list-style-type: none"> <li>Noise barrier comprised of acoustic blankets installed close to the rock breaking area was erected on the site.</li> </ul> The Contractor have continuously applied all the above mentioned noise mitigation measures to minimise construction noise, as observed during the site investigation on 9 and 23 February 2012. No further construction noise complaint was received in February 2012. As such, it is considered that the noise mitigation measures implemented on site are adequate to minimise construction noise nuisance. The Contractor will maintain these measures on site for construction noise control. |       |       |      |    |                                      |        |

| Complaint No. | Log Ref.                | Date/Location                                | Complainant           | Details of Complaint   | Investigation / Mitigation Action  | Status |            |            |  |              |             |            |              |                 |               |                        |      |      |   |   |   |    |      |      |   |   |   |                         |      |      |      |      |    |        |
|---------------|-------------------------|--|-----------------------|--|--|--------|------------|------------|--|--------------|-------------|------------|--------------|-----------------|---------------|------------------------|------|------|---|---|---|----|------|------|---|---|---|-------------------------|------|------|------|------|----|--------|
|               |                         |  |                       |  | <p>3) <u>FOLLOW UP ACTION(S)</u></p> <p>For this complaint, the Contractor has implemented adequate mitigation measures for construction noise control. As no further complaint is received in February 2012, it is considered that the complaint is closed. Nevertheless, the ET will continuously review the condition of the site during the routine site inspections, inspect proper functioning of the aforementioned construction noise mitigation measures, and provide advice to the Contractor to be vigilant and tailor mitigation measures in advance of future planned site work activities. This case will be reported as an action level exceedance on noise and also in the complaint log in the monthly EM&amp;A Report (February 2012).</p>   |        |            |            |  |              |             |            |              |                 |               |                        |      |      |   |   |   |    |      |      |   |   |   |                         |      |      |      |      |    |        |
| 25            | CIR-20                  | 10 August 2012 at Intake-3 Construction Site | Mr. Cheng through ICC | 1823 Call Centre (ICC) received a verbal complaint regarding the deterioration of water quality at Tso Kung Tam due to the construction works at Intake 3 construction site on 10 August 2012. | <p>1) <u>Findings / Observations</u></p> <p>Routine water quality monitoring upstream (I-3-C) and downstream (I-3) of the construction site at Intake 3 has been carried out since the commencement of construction works. Monitoring was conducted on 8 August 2012 and 10 August 2012. The results, as presented in the following table, indicate full compliance of water quality at I-3 with the action / limit levels of the water quality monitoring programme.</p> <table border="1"> <thead> <tr> <th rowspan="2">Date</th> <th rowspan="2">Parameters</th> <th colspan="2">Stations</th> <th rowspan="2">Action Level</th> <th rowspan="2">Limit Level</th> <th rowspan="2">Exceedance</th> </tr> <tr> <th>Impact (I-3)</th> <th>Control (I-3-C)</th> </tr> </thead> <tbody> <tr> <td rowspan="3">8 August 2012</td> <td>Water Temperature (°C)</td> <td>31.6</td> <td>31.7</td> <td>-</td> <td>-</td> <td>-</td> </tr> <tr> <td>pH</td> <td>7.91</td> <td>7.92</td> <td>-</td> <td>-</td> <td>-</td> </tr> <tr> <td>Dissolved Oxygen (mg/L)</td> <td>6.89</td> <td>6.85</td> <td>3.65</td> <td>3.51</td> <td>No</td> </tr> </tbody> </table> | Date   | Parameters | Stations   |  | Action Level | Limit Level | Exceedance | Impact (I-3) | Control (I-3-C) | 8 August 2012 | Water Temperature (°C) | 31.6 | 31.7 | - | - | - | pH | 7.91 | 7.92 | - | - | - | Dissolved Oxygen (mg/L) | 6.89 | 6.85 | 3.65 | 3.51 | No | Closed |
| Date          | Parameters              | Stations                                     |                       | Action Level   | Limit Level  |        |            | Exceedance |  |              |             |            |              |                 |               |                        |      |      |   |   |   |    |      |      |   |   |   |                         |      |      |      |      |    |        |
|               |                         | Impact (I-3)                                 | Control (I-3-C)       |  |  |        |            |            |  |              |             |            |              |                 |               |                        |      |      |   |   |   |    |      |      |   |   |   |                         |      |      |      |      |    |        |
| 8 August 2012 | Water Temperature (°C)  | 31.6   | 31.7                  | -  | -  | -      |            |            |  |              |             |            |              |                 |               |                        |      |      |   |   |   |    |      |      |   |   |   |                         |      |      |      |      |    |        |
|               | pH                      | 7.91   | 7.92                  | -  | -  | -      |            |            |  |              |             |            |              |                 |               |                        |      |      |   |   |   |    |      |      |   |   |   |                         |      |      |      |      |    |        |
|               | Dissolved Oxygen (mg/L) | 6.89   | 6.85                  | 3.65   | 3.51   | No     |            |            |  |              |             |            |              |                 |               |                        |      |      |   |   |   |    |      |      |   |   |   |                         |      |      |      |      |    |        |





| Complaint No. | Log Ref. | Date/Location   | Complainant | Details of Complaint   | Investigation / Mitigation Action  | Status |
|---------------|----------|---|-------------|--|--|--------|
|               |          |   |             |  | <p>Clear flowing stream water was visually observed during the monitoring at I-3 on 10 August 2012. No significant water pollution source from the construction site was identified.</p> <p>2) <u>Conclusion / Proposed Action</u><br/>                     Based on the site observation and the water quality monitoring data collected at I-3 and I-3-C on 8 and 10 August 2012, it is concluded that the construction works at I-3 did not generate unacceptable water quality impact at Tso Kung Tam. As such, the concerned complaint is not considered related to the construction works at Intake 3. No further action is, therefore, required.</p> <p>3) <u>FOLLOW UP ACTION(S)</u><br/>                     Prior to the receipt of this complaint, the Contractor has already implemented adequate mitigation measures for construction effluent discharge. As no unacceptable water quality impact from the construction works was identified during the investigation, the complaint is considered as non-project related and is closed. Nevertheless, the ET will continuously monitor the water quality at Intake 3 under the current EM&amp;A programme, review the condition of the site during the routine site inspections, and inspect proper functioning of the waste water treatment facilities.</p> |        |
| 26            | CIR-21   | 5 September 2012<br>at Chung Kee Store at Lo Wai Road (NSR 3) | Through ICC | 1823 Call Center (ICC) received a complaint (5 September 2012) regarding daytime construction noise nuisance generated by the power supply | <p>1) <u>Findings / Observations</u><br/>                     Checking with the site log, an air compressor was located opposite to Chung Kee Store on 5 September 2012. As there was no other powered mechanical equipment located nearby and the construction was only undertaken during the daytime, it is considered that the complaint is about the noise nuisance generated from the air compressor during the daytime operation.</p>  | Closed |


| Complaint No. | Log Ref.   | Date/Location | Complainant      | Details of Complaint                                | Investigation / Mitigation Action  | Status |            |          |                  |                    |                        |          |       |       |      |    |          |           |       |       |      |    |                            |  |
|---------------|------------|---------------|------------------|---|--|--------|------------|----------|------------------|--------------------|------------------------|----------|-------|-------|------|----|----------|-----------|-------|-------|------|----|----------------------------|--|
|               |            |               |                  | machine opposite to Chung Kee Store at Lo Wai Road. | <p>In response to the complaint, the Contractor has implemented the following measures:</p> <ul style="list-style-type: none"> <li>The concerned air compressor (AC1) located opposite to Chung Kee Store near the Vortex Drop Shaft (VDS) entrance (as "L1" shown in the attached I-2 layout plan) was de-mobilised for maintenance on 7 September 2012 and replaced by another air compressor (AC2);</li> <li>A layer of acoustic sheet was installed next to AC2 at L1 to minimise the noise nuisance, as observed during the site investigation on 11 September 2012;</li> <li>A third air compressor (AC3) was mobilized on site and placed behind the sub-contractor's office container (as "L2" shown in the attached I-2 layout plan) that screened off the noise from AC3 and minimised potential noise nuisance to the public. AC3 had been operated for another stage of construction activities since 14 September 2012 (as observed during the site investigation on 20 September 2012); and</li> <li>AC2 at L1 had ceased operation since 14 September 2012 and was demobilised off-site on 18 September 2012. As observed during the site investigation on 20 September 2012, no air compressor or other mechanical equipment was located at L1.</li> </ul> <p>Regular daytime construction noise monitoring is currently undertaken by the ET at NSR 3 (that is, Hong Hoi Chee Hong Temple) in accordance with the contract specific EM&amp;A Manual. According to the Manual, the complaint was considered as an exceedance of action level of construction air-borne noise. Following the Event / Action Plan for air-borne noise in the Manual, the noise monitoring frequency at NSR 3 was increased from once to twice per week between 10 September and 26 September 2012. The noise measurement results (as <math>L_{eq(30-minute)}</math>) at NSR 3 in September 2012 were presented in the following table:</p> <table border="1"> <thead> <tr> <th>Date</th> <th>Start Time</th> <th>End Time</th> <th><math>L_{eq}</math>, dB(A)</th> <th>Limit Level, dB(A)</th> <th>Dominant Noise Sources</th> </tr> </thead> <tbody> <tr> <td>4-Sep-12</td> <td>15:50</td> <td>16:20</td> <td>62.6</td> <td>75</td> <td>Drilling</td> </tr> <tr> <td>10-Sep-12</td> <td>14:05</td> <td>14:35</td> <td>62.2</td> <td>75</td> <td>Drilling and concrete work</td> </tr> </tbody> </table> | Date   | Start Time | End Time | $L_{eq}$ , dB(A) | Limit Level, dB(A) | Dominant Noise Sources | 4-Sep-12 | 15:50 | 16:20 | 62.6 | 75 | Drilling | 10-Sep-12 | 14:05 | 14:35 | 62.2 | 75 | Drilling and concrete work |  |
| Date          | Start Time | End Time      | $L_{eq}$ , dB(A) | Limit Level, dB(A)                                  | Dominant Noise Sources   |        |            |          |                  |                    |                        |          |       |       |      |    |          |           |       |       |      |    |                            |  |
| 4-Sep-12      | 15:50      | 16:20         | 62.6             | 75  | Drilling   |        |            |          |                  |                    |                        |          |       |       |      |    |          |           |       |       |      |    |                            |  |
| 10-Sep-12     | 14:05      | 14:35         | 62.2             | 75  | Drilling and concrete work   |        |            |          |                  |                    |                        |          |       |       |      |    |          |           |       |       |      |    |                            |  |

| Complaint No. | Log Ref. | Date/Location                 | Complainant | Details of Complaint  | Investigation / Mitigation Action   |       |       |      |    |                            | Status |
|---------------|----------|-------------------------------|-------------|---|---|-------|-------|------|----|----------------------------|--------|
|               |          |                               |             |   |   |       |       |      |    |                            |        |
|               |          |                               |             |   | 14-Sep-12   | 11:00 | 11:30 | 64.1 | 75 | Drilling                   |        |
|               |          |                               |             |   | 17-Sep-12   | 15:20 | 15:50 | 64.3 | 75 | Drilling                   |        |
|               |          |                               |             |   | 20-Sep-12   | 14:02 | 14:32 | 64.8 | 75 | Drilling and concrete work |        |
|               |          |                               |             |   | 24-Sep-12   | 13:20 | 13:50 | 63.7 | 75 | Drilling and concrete work |        |
|               |          |                               |             |   | 26-Sep-12   | 16:00 | 16:30 | 64.6 | 75 | Drilling and concrete work |        |
|               |          |                               |             |   | <p>The measured noise levels, ranged from 62.2 dB(A) to 64.8 dB(A), are below the limit level (75 dB(A)) in accordance with the approved EIA Report and the Contract Specific EM&amp;A Manual.</p> <p>2) <u>Conclusion / Proposed Action</u><br/>                     With the consideration of the noise measurement results and implementation of the above noise mitigation measures, construction noise nuisance is considered minimised with no further complaint received. As the concerned air compressor has been demobilised and the air compressor currently deployed on site is screened by a site container to minimise construction noise nuisance to the public, no further action is considered necessary.</p> <p>3) <u>Follow Up Actions</u><br/>                     As the noise source of complaint was removed from the site and no further complaint was received, it is considered that the complaint is closed. Nevertheless, the ET will continuously review the condition of the site during the routine site inspections, inspect proper functioning of the construction noise mitigation measures implemented on site, and provide advice to the Contractor to be vigilant and tailor mitigation measures in advance of future planned site work activities. This case will be reported as an action level exceedance on construction noise.</p> |       |       |      |    |                            |        |
| 27            | CIR-22   | 5 April 2013 at Outfall Basin | Through EPD | The incident was referred to the Contractor by EPD by phone on 5 April 2013 regarding | <p>1) <u>Findings / Observations</u><br/>                     After throughout investigation (including checking the source of chemical containers, type of chemical, and existence of chemical containers left behind the tunnel, associated structures and intakes), it was considered</p>  |       |       |      |    |                            | Closed |

| Complaint No. | Log Ref. | Date/Location | Complainant | Details of Complaint   | Investigation / Mitigation Action   | Status |
|---------------|----------|---------------|-------------|--|---|--------|
|               |          |               |             | <p>chemical stain and containers observed at the Outfall Basin and on the sea in the vicinity. The ET was informed on 8 April 2013. As advised by the EPD, the incident was filed as a formal complaint on 9 April 2013.</p> | <p>that some used chemical containers, which contained residual chemical and were accidentally retained in the Man Access Adit at Intake 1-2 (Lo Wai), were not properly stored and secured. The chemical was used for backfill grouting of the Adit Tunnel. According to the Contractor's record, the grouting was completed and all unused chemical containers were removed from the Adit Tunnel before the incident. Nevertheless, the used containers were mistakenly left inside on the site. When heavy rainfall occurred on 5 April 2013, the used chemical containers were flowed with the runoff along the Tunnel towards the Outfall. They were then stuck on the Outfall Basin by the rocks known as anti-pedestrian measure. Chemical stains were observed at the Outfall Basin and floating on the sea in the vicinity.</p> <p>In response to the event, the Contractor has implemented the following measures:</p> <ul style="list-style-type: none"> <li>• Removed the chemical drums at the Outfall Basin in the afternoon of 5 April 2013;</li> <li>• Checked out any chemical drums left and retained in the Man Access Adit at Intake 2 on 6 April 2013 under safe weather condition;</li> <li>• Double checked the sea condition on 6 April 2013 and no more plume was found on the sea;</li> <li>• Inspected the tunnel and other intakes on 6 April 2013 and confirmed that there was no chemical container retained elsewhere within the Tunnel, associate structures and intakes; and</li> <li>• Conducted tool box talk to all site personnel in connection with tunnel works to remind them to check and remove any chemical or diesel containers or drums from the tunnel and all associated structures to prevent potential leakage right after the incident.</li> </ul> <p>Site investigation at the Outfall Basin was undertaken by the ET on 9 April 2013. No containers and stain were observed on the Basin and no chemical plume was observed on the sea in the vicinity. The pre-event environmental condition of the site has been reinstated.</p> <p>2) <u>Conclusion / Proposed Action</u><br/>                     Taking account of the corrective and preventive measures undertaken and</p> |        |

| Complaint No. | Log Ref. | Date/Location | Complainant | Details of Complaint | Investigation / Mitigation Action   | Status |
|---------------|----------|---------------|-------------|----------------------|---|--------|
|               |          |               |             |                      | <p>the findings of site investigation, the pollution sources (residual chemical) have been removed and there is no further impact of chemical stains on site. The event is considered as an accidental incident and the Contractor has undertaken proper measures to rectify the incident and prevent future recurrence.</p> <p>3) <u>Follow Up Actions</u><br/>           As the pollution source of the complaint was removed from the site and the pre-event environmental condition has been reinstated, it is considered that the complaint is closed. Nevertheless, the ET will continuously review the condition of the site during the routine site inspections, inspect proper site management and implementation of preventive measures against accidental chemical spillage, and provide advice to the Contractor to be vigilant and tailor mitigation measures in advance of future planned site work activities.</p> |        |

Signed by Environmental Team Leader:



Date:

31 May 2013