REPORT

CLP Power Hong Kong Ltd

Renewable Energy Supply on Town Island (Construction Phase): 14th Monthly Environmental Site Audit Report

May 2012

Environmental Resources Management

21/F Lincoln House 979 King's Road Taikoo Place Island East, Hong Kong Telephone: (852) 2271 3000 Facsimile: (852) 2723 5660 E-mail: post.hk@erm.com http://www.erm.com

CLP Power Hong Kong Ltd

Renewable Energy Supply on Town Island (Construction Phase): 14th Monthly Environmental Site Audit Report

May 2012

Reference 0129569

For and on behalf of ERM-Hong Kong, Limited			
Approved	by: Frank Wan		
Signed:	Wardish T.		
Position:	Partner		
Certified b	y: Winnie Ko		
Signed :	Marie		
Position:	Independent Environmental Checker		
Date :	23 May 2012		

CONTENTS

1	ENVIRO	NMENTAL SITE AUDIT	1
1.1	BACKGRO	UND	1
1.2	SITE AUDI	T FINDINGS AND OBSERVATIONS	1
	Annex A	Environmental Site Audit Checklist	
	Annex B	Photo Records	

1 ENVIRONMENTAL SITE AUDIT

1.1 BACKGROUND

The construction works of *Renewable Energy Supply on Town Island* (the Project) has commenced in March 2011.

To fulfill Condition 2.2 of the Environmental Permit (EP-397/2010) and environmental audit requirements stated in Section 5.7.1 of the approved Project Profile (PP) submitted for direct application of an Environmental Permit under EIA Ordinance (EIAO) (PP-413/2010), monthly environmental site audits should be undertaken to ensure that the mitigation measures recommended in PP are properly implemented.

This is the fourteenth *Monthly Environmental Site Audit Report* presenting the key findings and observations of the site audit conducted on 11 May 2012.

1.2 SITE AUDIT FINDINGS AND OBSERVATIONS

The fourteenth monthly environmental site audit was conducted on 11 May 2012. The construction works conducted during the site audit included superstructure works at Site 1 and foundation formation works at Site 2. All the temporary worksites have been reinstated. Two observations have been recorded during the site audit and are described below:

- An oil drum was observed without a drip tray at Site 1 (Photo 1). The Contractor was reminded to provide a drip tray for the oil drum within 3 working days.
- Construction materials were observed storing outside the site boundary at Site 1 (Photo 2). The Contractor was reminded to keep those construction materials within the site boundary.

The remedial actions for the three environmental deficiencies which were recorded during the previous reporting period has been taken and verified during the site inspection:

- A drip tray has been provided for the oil drum stored next to the site office.
- Stagnant waters inside a bucket and on tarpaulin sheet at Site 2 have been removed.
- A bund has been provided for the haul road crossing the stream (Photo 3).

The environmental site audit checklist is appended in *Annex A*.

Photos of the site audit are given in *Annex B*.

Annex A

Environmental Site Audit Checklist



Renewable Energy Supply on Town Island Construction Phase - Environmental Site Audit



E	KM							
ir	spection Date:	11-05-2012	Time:	10:30	10		12:30	
	Inspected By:	IEC Representative : CLP Representative : Contractor :	Andrew Fung Raymond Ho / Lee Tin Yar Rebel Hul (3Tech Corpora					
Cor	· <u>-</u>	Sunny Fine 23 °C Calm VLight	V Overcast Drizz Humidity V High Breeze Stron	Modera	Sto		Hazy	
A	General			Yes	Yes, but need Improvemen		N/A or lot observed	Photo/Remarks
A1	Is the Environ	mentsi Permit displayed at t	the entrances / exits?	1				
6	Air Quality		·····	Yes	Yes, but need improvemen		N/A or not abserved	Photo/Remarks
81	is open burning	g avoided?		T	\Box			
82	Are exposed s	- Oil surfaces regularly weten	ed to evoid generation of dus	u? 🔽	一	Ħ		
B 3	Are plent and of	equipment well maintained? plant)	(le without black smoke				7	
B4	Are stockpiles	of dusty material covered o	or regularly watered?	[₹]				
85	is watering imp	plemented during excavatio	n?	V				
B6	la generation d	of dust svoided during loadi	ng/unleading/excavation?	4				
C	Noise	-		Yes	Yes, but need improvemen		N/A or not observed	Photo/Remarks
C1	is the Construct (If any)	ction Noise Permit displaye	d at the entrançes / exits?				7	
C2	Are si plant ar condition?	nd equipment well maintain	ed end in good operating	1				
C3	ls idle equipme	ent turned off or throttled do	wn?	4				
C4	Are powered in acoustic mater	nechanical equipment cove rials?	red or shielded by				7	
		quipment used where pract		Y				
C8		of contstruction plant being		1	닏	닏	片	
C7 C8	•	saors have valid noise lebe es operate with doors class			뭐	님	끍	
~	Do complesso	** operate with goods close	g r	لــا	L	لــا		
O	Water Qualit	Y	- <u> </u>	Yes	Yes, trut need imprevemen		N/A ar not a bser ved	Photo/Remerks
D1	ls wastewater (discharge license, if any, e	reliable for inepaction?	[]		\Box	(T)	
D2		stem adequate?	· · · · · · · · · · · · · · · · · · ·	H	Ħ		1	
D3	la drainage sys	stem well maintained?				靣	₹	
D4	is debris and n disposed of pro	ubbish in the drainage syst openly?	em collected and				1	

D5	Are there temporary ditches for runoff discharge into appropriate Watercourse?				V	
	With silt retention pond?					
D6	Are there sedimentation tanks for settling runoff prior to disposal?				V.	
D7	is the capacity of sedimentation tank adequate?				$\overline{}$	
D8	is the sedimentation free from slif and sediment?					
D9	Are the temporary stockpiles located away from stream or coastline?	S				
D18	Are treaching carried out for the section of cable in the vicinity of and crossing the stream between Sites 1 and 2?	<u> </u>			□ .	
D11	is cable trenching works scheduled to be carried out during dry season?	7				
E	Waste/Chemical Management	Yes	Yes, but need improvemen		N/A or ot observed	Photo/Remarks
E1	General refuse Accumulation avoided?	7				
E2	Receptacles (e.g. rubbish bins) aveilable?	<u> </u>				
E3	Disposed of regularly and properly?	$\overline{\Box}$				
E4	Chemical waste, waste oil Is the Chemical Waste Producer Registration available for inspection?	T				
E5	Stored properly in designated area?		\Box			
E8	Labelled properly?	7		百		
E7	Disposed of properly?	<u> </u>				
E6	Trip tickets/ chits available for inspection?				7	
EĐ	Chemical/fuel storage area Are all apillage containment provided for all chemicals, oils and fuels storad on site, those equipment which potentially have oil leakage and for the area where maintenance works carrying out?		V			Note 1
E10	is storage area bunded?	V				
E11	Adequate bund capacity? (>110% of the largest tank)	7				
E12	Are storage areas provided with locks and located on sealed areas?				7	
E13	Construction Waste Reused where practicable?	T.				
	is sorting conducted on site?	벌	닏	닠	닠	
E14	Transported offsits by boat for proper disposal?		Ш	لـــا		
E15	Are surplus inert materials being reused where practical as an alternative to ordering imported fill material? Excevated Material	1				
E16	Appears uncontaminated? (colour, adour)	4				
E17	If suspected conteminated, appropriate procedures followed?				7	
E18	Relevant license/permit/trip tickets/chits for disposal of construction waste or excevated meterials available for inspection?	7				
F	General / Housekeeping	Yes	Yes, but need Improveme		N/A or not observed	Photo/Remarks
F1	Are potential stagnant pools cleared and mosquito breeding prevented?	¥				
ढ	Ecology	Yes	Yes, but need Improveme		N/A or not observed	Photo/Remarks
	is demage and disturbance to the remaining and surrounding natural shrubby gressiand and yound woodland habitets evoided? (perticularly those caused by filing and Megal dumping)		7			Note 2

ance to streams avoided during works? In a struction site. In the struction materials were observed storing outside the site boundary at Site 1. Instruction materials were observed storing outside the site boundary at Site 1. Instruction materials were observed storing outside the site boundary at Site 1. Instruction materials were observed storing outside the site boundary at Site 1. In a struction materials were observed storing outside the site boundary at Site 1. In a struction was reminded to provide drip trap for the oil drum within 3 working days. Contractor was reminded to relocate those construction materials and to store within the alta boundary.		Is damage to surrounding areas avoided?
Inspection construction site. Inspection Contractor was remainded to provide drip trap for the oil drum within 3 working days. Contractor was remainded to provide drip trap for the oil drum within 3 working days. Contractor was remainded to relocate those construction materials and to store within the site boundary. Contractor was remainded to relocate those construction materials and to store within the site boundary. Contractor: 3 Lech Corporate Rebuil		Are temporary work sites/disturbed areas reinstated?
in Inspection construction alte. contractor materials were observed storing without drip tray at Site 1. contractor materials were observed storing outside the site boundary at Site 1. contractor was reminded to provide drip trap for the oil drum within 3 working days. Contractor was reminded to relocate those construction materials and to store within the alte boundary. contractor was reminded to relocate those construction materials and to store within the alte boundary. Contractor was reminded to relocate those construction materials and to store within the alte boundary. Contractor was reminded to relocate those construction materials and to store within the alte boundary. Contractor was reminded to relocate those construction materials and to store within the alter boundary.		Is disturbance to streams avoided during works?
Issues Recorded On Site Issues Recorded On Site oil drum was observed storing without drip tray at Site 1. Instruction materials were observed storing outside the site boundary at Site 1. Investigations Contractor was reminded to provide drip trap for the oil drum within 3 working days. Contractor was reminded to relocate those construction materials and to store within the site boundary. See: The Representative: Contractor: 3 Tech Composite Rebuil Rebuil		Is any alternative method adopted for laying ceble across stream between Sites 1 and 2?
Issues Recorded On Site oil drum was observed storing without drip tray at Site 1. istruction materials were observed storing outside the site boundary at Site 1. ive Actions Contractor was reminded to provide drip trap for the oil drum within 3 working days. Contractor was reminded to relocate those construction materials and to store within the site boundary. we: resentative: Cut P Representative: Contractor: 3 [Luch Companda]	1	items for inspection
issues Recorded On Site oil drum was observed storing without drip tray at Site 1. instruction materials were observed storing outside the site boundary at Site 1. Ive Actions Contractor was reminded to provide drip trap for the oil drum within 3 working days. Contractor was reminded to relocate those construction materials and to store within the alta boundary. The contractor was reminded to relocate those construction materials and to store within the alta boundary. The contractor: Stech Composite Rebuil	I	- Site 1 construction site.
instruction materials were observed storing outside the site boundary at Site 1. Instruction materials were observed storing outside the site boundary at Site 1. Instruction materials were observed storing outside the site boundary at Site 1. Instruction materials were observed storing outside the site boundary at Site 1. Instruction materials were not site of the site boundary at Site 1. Instruction materials were observed storing outside the site boundary at Site 1. Instruction materials were observed storing outside the site boundary at Site 1. Instruction materials were observed storing outside the site boundary at Site 1. Instruction materials were observed storing outside the site boundary at Site 1. Instruction materials were observed storing outside the site boundary at Site 1.		- Site 2 construction site.
instruction materials were observed storing outside the site boundary at Site 1. Instruction materials were observed storing outside the site boundary at Site 1. Instruction materials were observed storing outside the site boundary at Site 1. Instruction materials were observed storing outside the site boundary at Site 1. Instruction materials were not site of the site boundary at Site 1. Instruction materials were observed storing outside the site boundary at Site 1. Instruction materials were observed storing outside the site boundary at Site 1. Instruction materials were observed storing outside the site boundary at Site 1. Instruction materials were observed storing outside the site boundary at Site 1. Instruction materials were observed storing outside the site boundary at Site 1.	İ	
instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed at Sife 1. Instruct		
instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed storing outside the site boundary at Sife 1. Instruction materials were observed at Sife 1. Instruct	1	Notes / Issues Recorded On Site
ive Actions Contractor was reminded to provide drip trap for the oil drum within 3 working days. Contractor was reminded to relocate those construction materials and to store within the site boundary. The secondarity of the construction construction materials and to store within the site boundary. The secondarity of the construction cons		
ive Actions Contractor was reminded to provide drip trap for the oil drum within 3 working days. Contractor was reminded to relocate those construction materials and to store within the alte boundary. The secondary of the oil drum within 3 working days. Contractor was reminded to relocate those construction materials and to store within the alte boundary. The secondary of the oil drum within 3 working days. Contractor was reminded to provide drip trap for the oil drum within 3 working days. Contractor was reminded to provide drip trap for the oil drum within 3 working days. Contractor was reminded to relocate those construction materials and to store within the alte boundary.	Ì	An oil drum was observed storing without drip tray at Site 1.
Contractor was reminded to provide drip trap for the oil drum within 3 working days. Contractor was reminded to relocate those construction materials and to store within the alte boundary. The state boundary of the state boundary of the state boundary. CLP Representative: CLP R		
Contractor was reminded to provide drip trap for the oil drum within 3 working days. Contractor was reminded to relocate those construction materials and to store within the site boundary. The search of the oil drum within 3 working days. Contractor was reminded to relocate those construction materials and to store within the site boundary. Contractor was reminded to relocate those construction materials and to store within the site boundary. Contractor was reminded to relocate those construction materials and to store within the site boundary. Contractor was reminded to relocate those construction materials and to store within the site boundary. Contractor was reminded to relocate those construction materials and to store within the site boundary.		
Contractor was reminded to provide drip trap for the oil drum within 3 working days. Contractor was reminded to relocate those construction materials and to store within the site boundary. The search of the oil drum within 3 working days. Contractor was reminded to relocate those construction materials and to store within the site boundary. Contractor was reminded to relocate those construction materials and to store within the site boundary. Contractor was reminded to relocate those construction materials and to store within the site boundary. Contractor was reminded to relocate those construction materials and to store within the site boundary. Contractor was reminded to relocate those construction materials and to store within the site boundary.	1	Corrective Actions
Contractor was reminded to relocate those construction materials and to store within the site boundary. The image is a contractor of the	ļ	***************************************
Dec. CLP Representative: Contractor: 3 Tech Composeda Rebuil		1) The Contractor was reminded to provide drip trap for the oil drum within 3 working days.
CLP Representative: Gontractor: 3 Tech Composeda Relati	l	2) The Contractor was reminded to relocate those construction materials and to store within the site boundary.
CLP Representative: Contractor: 3 Tech Corporate Relati	1	
CLP Representative: Contractor: 3 Tech Composeda Rela.1		
CLP Representative: Contractor: 3 Tech Composeda Rela.1		
CLP Representative: Contractor: 3 Tech Composeda Rela.1	- 1	
Reb. L		
Rebell Rebell		Signaturee:
Marrie: Raymond Ho) (Name: Rebel Hul)		Signatures: IEC Representative: CLP Representative: Contractor: 3 Tech Composite
Middly Fung (Name: Raymond Ho) (Name: Rebel Hul)		Signatures: IEC Representative: CLP Representative: Contractor: 3 Tech Corporate
• 1		Signatures: IEC Representative: CLP Representative: Contractor: 3 Tech Corpo

Annex B

Photo Records

Photo Records on 11 May 2012



Photo 1 – An oil drum was observed without a drip tray at Site 1.



Photo 2 – Construction materials were observed storing outside the site boundary at Site 1.



Photo 3-A bund has been provided for the haul road crossing the stream.