-CCECC & CRWJ Joint Venture

Contract No. HY/2003/19

Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha

Monthly EM&A Report (Version2.0)

June 2009

Certified By

(Environmental Team IJeader)

REMARKS:

The information supplied and contained within this report is, to the best of our knowledge, correct at the time of printing.

CINOTECH accepts no responsibility for changes made to this report by third parties.

CINOTECH CONSULTANTS LTD

Room 1710, Technology Park, 18 On Lai Street, Shatin, NT, Hong Kong Tel: (852) 2151 2083

Fax: (852) 3107 1388

Email: info@cinotech.com.hk

TABLE OF CONTENTS

EX	ECUTIVE SUMMARY	1
1.	INTRODUCTION	4
Ba	ckground	4
	oject Organizations	
	nstruction Programme	
Su	mmary of EM&A Requirements	5
2.	AIR QUALITY	6
Mo	onitoring Requirements	6
Mo	onitoring Locations	6
	onitoring Equipment	
	onitoring Parameters, Frequency and Duration	
	onitoring Methodology and QA/QC Procedure	
Re	sults and Observations	8
3.	NOISE	9
Mo	onitoring Requirements	Q
	onitoring Locations	
	onitoring Equipment	
	onitoring Parameters, Frequency and Duration	
	onitoring Methodology and QA/QC Procedures	
	intenance and Calibration	
Re	sults and Observations	11
4.	WATER QUALITY	12
Mo	onitoring Requirements	12
	onitoring Equipment	
Mo	onitoring Parameters, Frequency and Duration	12
	onitoring Locations	
	onitoring Methodology, Calibration Details and QA/QC Procedures	
	intenance and Calibration	
	sults and Observations	
5.	ENVIRONMENTAL AUDIT	16
Sit	e Audits	16
	view of Environmental Monitoring Procedures	
	tus of Environmental Licensing and Permitting	
	tus of Waste Management	
	plementation Status of Environmental Mitigation Measures	
	n-compliance Recorded during Site Inspections	
	mmary of Mitigation Measures Implemented	
	mmary of Exceedances of the Environmental Quality Performance Limit plementation Status of Event Action Plans	
	mmary of Complaint, Warning, Notification of any Summons and Successful Prosecuti	
6.	FUTURE KEY ISSUES	
	y Issues for the Coming Month	
VG	y issues for the Commis information with the commission of the com	∠٥

	g Schedule for the Next Month
	on Program for the Project (Construction Program for the Next Month)28
7. CON	CLUSIONS AND RECOMMENDATIONS29
Conclusion	ns29
Recommen	ndations
LIST OF	TARLES
Table I	Summary Table for Non-compliance Recorded in the Reporting Month
Table II	Summary Table for Key Information in the Reporting Month
Table 2.1	Locations for Air Quality Monitoring
Table 2.2	Air Quality Monitoring Equipment
Table 2.3	Impact Dust Monitoring Parameters, Frequency and Duration
Table 3.1	Noise Monitoring Stations
Table 3.2	Noise Monitoring Equipment
Table 3.3	Noise Monitoring Parameters, Frequency and Duration
Table 4.1	Water Quality Monitoring Equipment
Table 4.2	Frequency and Parameters of Water Quality Monitoring
Table 4.3	Water Quality Monitoring Locations
Table 4.4	Summary of Water Quality Exceedances in the reporting month
Table 5.1	Summary of Environmental Licensing and Permit Status
Table 5.2	Observations and Recommendations of Site Inspections
	• • • • • • • • • • • • • • • • • • •
LIST OF	FIGURES
Figure 1	Layout Plan of the Project
Figure 2	Organization Chart
Figure 3	Monitoring Locations (7 sheets total)
-	
	APPENDICES
A	Action and Limit Levels for Air Quality, Noise and Water Quality
В	Copies of Calibration Certificates
C	Environmental Monitoring Schedules
D	24-hour TSP Monitoring Results, Graphical Presentations and Wind Data
E	Noise Monitoring Results and Graphical Presentations
F	Water Quality Monitoring Results and Graphical Presentations
G	Quality Control Reports for Laboratory Analysis
H	Summary of Exceedances
I	Site Audit Summary
J	Environmental Mitigation Implementation Schedule (EMIS)
K	Event Action Plans
L	Complaint Logs
M	Summary of Warnings/Direction issued by the EPD and Prosecution
N	Construction Programme
O	Waste Generated Quantity

ABBREVIATION AND ACRONYM

AL Levels Action and Limit Levels

E / ER Engineer/Engineer's Representative

EIA Environmental Impact Assessment

EM&A Environmental Monitoring and Audit

EMIS Environmental Mitigation Implementation Schedule

EP Environmental Permit

EPD Environmental Protection Department

ET Environmental Team

HVS High Volume Sampler

HyD Highways Department

IEC Independent Environmental Checker

NOE Notification of Exceedance

QA/QC Quality Assurance / Quality Control

RE Resident Engineer

RH Relative Humidity

SLM Sound Level Meter

TSP Total Suspended Particulates

WMP Waste Management Plan

EXECUTIVE SUMMARY

Introduction

- 1. This is the 56th monthly Environmental Monitoring and Audit (EM&A) Report prepared by Cinotech Consultants Limited for the project "Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha" (the Project). This report documents the findings of EM&A Works conducted in June 2009.
- 2. The construction activities undertaken in the reporting month included:
 - Landscaping works;
 - Street furniture installation;
 - Utilities installation;
 - Construction of drainage;
 - Reinstatement works of the footpath;
 - Construction of the baffle wall and stepped channel; and
 - Construction of retaining wall.

Environmental Monitoring Works

- 3. Environmental monitoring for the Project was performed regularly as stipulated in the Updated EM&A Manual (Revision C) and the results were checked and reviewed. Site audits were conducted once per week. The implementation of the environmental mitigation measures, Event Action Plans and environmental complaint handling procedures were also checked.
- 4. Summary of exceedance of noise, air and water quality monitoring for the reporting month is tabulated in Table I.

Table I Summary Table for Exceedance Recorded in the Reporting Month

Parameter	Number of Exc the Project	ceedances due to	Action Taken	Results of Action
	Action Level	Limit Level	Taken	Taken
Air Quality	0	0	N.A.	N.A.
Noise	0	0	N.A.	N.A.
Water Quality	0	0	N.A.	N.A.

Air Quality

5. 24-hr TSP monitoring at 3 monitoring stations, AM1, AM2 and AM4, were conducted as scheduled in the reporting month. No Action/Limit Level exceedance was recorded for 24-hr TSP monitoring in the reporting month.

Construction Noise

6. Noise monitoring at 7 designated monitoring stations, namely NM1, NM2, NM3, NM4, NM5, NM6 and NM8, were conducted as scheduled in the reporting month. No Action/Limit Level exceedance was recorded in the reporting month.

Water Quality

- 7. Water quality monitoring was conducted as scheduled at designated monitoring stations (Streams 15, 18, 21, 23, 26, 27, 40, Cheung Sha Stream, Tung Chung Stream and Tung Chung Bay) which are under the influence of the works in the reporting month. No water monitoring was conducted at the streams which were observed dry in the reporting month. As the water depth of Tung Chung Bay was less than 3m, only the mid-depth level was monitored.
- 8. Exceedances of suspended solids (SS) were recorded in the reporting month. No direct evidence demonstrated that the exceedances were caused by the Project.

Environmental Licensing and Permitting

9. License/Permits granted to the Project include Environmental Permit (License No.: EP-170/2003/C), Registration of Chemical Waste Producer (License: WPN5214-950-C1213-01), Water Discharge License (License No.: EP890/W7/XP089, EP890/W7/XP090 and EP890/W2/XG013).

Key Information in the Reporting Month

10. Summary of key information in the reporting month is tabulated in Table II.

Table II Summary Table for Key Information in the Reporting Month

	Event De	tails	Action Taken	Status	Remark
Event	Number	Nature			
Complaint received	1	Water Quality	Complaint investigation	Investigation report was submitted	
Changes to the assumptions and key construction / operation activities recorded	0		N.A.	N.A.	
Notifications of any summons received	0		N.A.	N.A.	
Notifications of any successful prosecution received	0		N.A.	N.A.	

Complaints and Prosecutions

- 11. A total of 1 environmental complaint was received in the reporting month.
- 12. No warning and summon or notification of successful prosecution was received in the reporting month.

Future Key Issues

- 13. Key issues to be considered in the coming month include:
 - Runoff from exposed slope;
 - Wastewater and runoff discharge from site;
 - Regular removal of silt, mud and sand along u-channels, culverts and gullies;
 - Review and implementation of temporary drainage system for the surface runoff;
 - Proper storage of construction materials near streams;
 - Noise from operation of the equipment, especially for rock-breaking activities and machinery on-site;
 - Dust generation from stockpiles of dusty materials, exposed retain wall, excavation works and rock breaking activities;
 - Storage of chemicals/fuel and chemical waste/waste oil on site;
 - Watering for rock breaking activity, soil nailing and on haul road;
 - Accumulation of general and construction waste near stream and on site;
 - Proper sorting and segregation of C&D materials in designated areas; and
 - Provide wheel washing facilities at the site entrance/exit.

1. INTRODUCTION

Background

- 1.1 The Project "Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha" involves the widening and realignment of Tung Chung Road between Lung Tseng Tau in North Lantau and Cheung Sha in South Lantau. The layout plan of the Project is shown in Figure 1.
- 1.2 The scope of the Project includes:
 - a) widening and realignment of a 3.6 km section of Tung Chung Road (TCR) between Lung Tseng Tau and Pak Kung Au from a single-lane road for two-way traffic to a single two-lane road for two-way traffic with a footpath having a minimum width of 1.6 m, and construction of a 2.6 km long single two-lane road between Pak Kung Au and Cheung Sha, including elevated highway structures of a total length of 750 m, with a footpath of a minimum width of 1.6 m;
 - b) provision of 21 passing bays/bus-bays along the road and a roundabout at Cheung Sha; and
 - c) associated works including road rehabilitation, drainage, utility, environmental mitigation measures, landscaping, slope stabilization, traffic aids, road safety enhancement measures, lighting, traffic control and surveillance system, and electrical and mechanical (E&M) works.
- 1.3 The Environmental Impact Assessment (EIA) Report for the Project was approved on 4 July 2002 under the Environmental Impact Assessment Ordinance (EIAO). An Environmental Permit (EP- 170/2003) for the works was also granted on 27 June 2003. Two varied Environmental Permits (EP) (EP-170/2003/B and EP-170/2003/C) were issued in June 2006 and July 2007 respectively. Environmental Monitoring and Audit (EM&A) Manual for the Project was also included as part of the EIA reports in the register. An updated EM&A Manual (Revision C) has been issued on 28 April 2006.
- 1.4 Highways Department awarded the construction of the Project to CCECC & CRWJ Joint Venture (being a joint venture of China Civil Engineering Construction Corporation & China Railway Wuju Group Corporation) (hereinafter called "the Contractor") in June 2004. The construction works commenced on 4 November 2004 and are scheduled to be completed by September 2007.
- 1.5 Cinotech Consultants Limited (Cinotech) was commissioned by the Contractor to undertake the Environmental Team (ET) Services for the Project since 1 September 2006. All environmental and audit works were conducted by Cinotech and the laboratory testing works were conducted by a HOKLAS laboratory, Wellab Limited. This is the 56th monthly EM&A report summarizing the EM&A works for the Project in July 2009.

Project Organizations

- 1.6 Different parties with different levels of involvement in the project organization include:
 - Project Proponent Major Works Project Management Office (MWPMO) of Highways Department (HyD)
 - Engineer (E) / Engineer's Representative (ER) Mott Connell Limited
 - Contractor CCECC & CRWJ Joint Venture
 - Environmental Team (ET) Cinotech Consultants Limited
 - Independent Environmental Checker (IEC) ENSR Asia (HK) Limited
- 1.7 The responsibilities of respective parties are detailed in Section 1.5 of the Updated EM&A Manual (Revision C, issued on 28 April 2006) of the Project. The project organization chart is presented in Figure 2.

Construction Programme

1.8 The construction activities undertaken in the reporting month were:

Northern Section

- Street furniture installation at Zone A to Zone F;
- Utilities installation at Zone A to Zone F; and
- Construction of DT and S&D Structure.

Southern Section

• Slope reinstatement works from STR010 to STR013.

Summary of EM&A Requirements

- 1.9 The EM&A programme requires construction phase monitoring for air quality and construction noise, water quality and environmental site audit. The EM&A requirements for each parameter are described in the following sections, including:
 - All monitoring parameters;
 - Action and Limit levels for all environmental parameters;
 - Event Action Plans;
 - Environmental mitigation measures, as recommended in the project EIA report;
 and
 - Environmental requirements in contract documents.
- 1.10 The advice on the implementation status of environmental protection and pollution control/mitigation measures is summarized in Section 5 of this report.
- 1.11 This report presents the environmental monitoring results, observations, locations, equipment, period, methodology and QA/QC procedures of the required monitoring parameters, namely air quality, noise levels, water quality and audit works for the Project in the reporting month.

2. AIR QUALITY

Monitoring Requirements

2.1 Monitoring of 1-hour and 24-hour TSP was conducted to monitor the air quality. Appendix A shows the established Action/Limit Levels for the environmental monitoring works.

Monitoring Locations

- 2.2 In accordance with the updated EM&A Manual, 24-hour TSP monitoring shall only be conducted at the monitoring location when there are Project related construction activities being undertaken within a radius of 500 m from the monitoring location.
- 2.3 Five designated monitoring stations, AM1 to AM5 were selected for impact dust monitoring for the Project. Table 2.1 describes the air quality monitoring locations and Figure 3 shows their locations.

Table 2.1 Locations for Air Quality Monitoring

Monitoring Station	Description	Location
AM1	YMCA of Hong Kong Christian College	Rooftop
AM2	D 68 Leyburn Villas	House
$AM3^{(1)}$	Butterfly Crest	House
AM4	No. 31 South Lantau Road	House
AM5 ⁽²⁾	YWCA	To be confirmed

Remarks:

Monitoring Equipment

2.4 Table 2.2 summarizes the equipment used for the air quality monitoring. Copies of calibration certificates are attached in Appendix B.

Table 2.2 Air Quality Monitoring Equipment

Equipment	Model and Make	Quantity
Calibrator	GMW25; S/N: 1536	1
HVS Sampler	Graseby GMW Model GS2310 High Volume TSP Sampler and associated equipment and shelter	3

⁽¹⁾ Monitoring at AM3 will be conducted when the Project related construction activities are being undertaken within a radius of 500 m from the monitoring location.

⁽²⁾ Monitoring at AM5, YWCA, will be resumed when YWCA re-open.

Monitoring Parameters, Frequency and Duration

2.5 Table 2.3 summarizes the monitoring parameters and frequencies of impact dust monitoring for the whole construction period. The air quality monitoring schedule for the reporting period is shown in Appendix C.

 Table 2.3
 Impact Dust Monitoring Parameters, Frequency and Duration

Parameters	Frequency
1-hr TSP ^(a)	Three times / 6 days
24-hr TSP	Once / 6 days

Note:

(a) 1-hour TSP monitoring will be carried out in case that an exceedance of 24-hour TSP level is identified to be due to the Project.

Monitoring Methodology and QA/QC Procedure

Instrumentation

2.6 Graseby GMW Model GS2310 TSP High Volume Sampler (HVS) was employed for 1-hour & 24-hour TSP monitoring. The sampler was composed of a motor, a filter holder, a flow controller and a sampling inlet and its performance specification complied with that required by USEPA Standard Title 40, Code of Federation Regulations Chapter 1 (Part 50). Moreover, the HVS also met all the requirements in Section 3.2 of the Updated EM&A Manual.

Operating/Analytical Procedures

- 2.7 Operating/analytical procedures for the operation of HVS were as follows:
 - A horizontal platform was provided with appropriate support to secure the samplers against gusty wind.
 - No two samplers were placed less than 2 meters apart.
 - The distance between the sampler and an obstacle, such as buildings, was at least twice the height that the obstacle protrudes above the sampler.
 - A minimum of 2 meters of separation from walls, parapets and penthouses was required for rooftop samples.
 - A minimum of 2 meters separation from any supporting structure, measured horizontally was required.
 - No furnaces or incineration flues were nearby.
 - Airflow around the sampler was unrestricted.
 - The sampler was more than 20 meters from the drip line.
 - Any wire fence and gate, to protect the sampler, should not cause any obstruction during monitoring.
- 2.8 Prior to the commencement of the dust sampling, the flow rate of the high volume sampler was properly set (between 1.1 m³/min. and 1.4 m³/min.) in accordance with the manufacturer's instruction to within the range recommended in USEPA Standard Title 40, CFR Part 50. For TSP sampling, fiberglass filters (G810) were used.

- 2.9 The power supply was checked to ensure the sampler worked properly. On sampling, the sampler was operated for 5 minutes to establish thermal equilibrium before placing any filter media at the designated air monitoring station.
- 2.10 The filter holding frame was then removed by loosening the four nuts and a weighted and conditioned filter was carefully centered with the stamped number upwards, on a supporting screen.
- 2.11 The filter was aligned on the screen so that the gasket formed an airtight seal on the outer edges of the filter. Then the filter holding frame was tightened to the filter holder with swing bolts. The applied pressure should be sufficient to avoid air leakage at the edges.
- 2.12 The shelter lid was closed and secured with the aluminum strip. The timer was then programmed. Information was recorded on the record sheet, which included the starting time, the weather condition and the filter number (the initial weight of the filter paper can be found out by using the filter number). After sampling, the filter was removed and sent to the laboratory for weighing. The elapsed time was also recorded.
- 2.13 Before weighing, all filters were equilibrated in a conditioning environment for 24 hours. The conditioning environment temperature should be between 25°C and 30°C and not vary by more than ±3°C; the relative humidity (RH) should be < 50% and not vary by more than ±5%. A convenient working RH is 40%.

Maintenance/Calibration

- 2.14 The following maintenance/calibration was required for the HVS:
 - The high volume motors and their accessories were properly maintained. Appropriate maintenance such as routine motor brushes replacement and electrical wiring checking were made to ensure that the equipment and necessary power supply are in good working condition.
 - High volume samplers were calibrated at bi-monthly intervals using GMW-25 Calibration Kit throughout all stages of the air quality monitoring.

Wind Data

2.15 Wind data was required to be taken from the Hong Kong Observatory Weather Stations including HK International Airport and Cheung Chau.

Results and Observations

- 2.16 24-hr TSP monitoring at 3 monitoring stations, AM1, AM2 and AM4, were conducted as scheduled in the reporting month.
- 2.17 The monitoring data, graphical presentations and wind data for the reporting month are summarized in Appendix D. No Action/Limit Level exceedance was recorded for 24-hr TSP monitoring in the reporting month.

3. NOISE

Monitoring Requirements

- 3.1 Monitoring and audit of construction noise levels is required to be conducted, in accordance with the Updated EM&A Manual, to ensure that any unacceptable noise impacts could be readily detected and timely and appropriate action be undertaken to rectify the situation.
- 3.2 The construction noise levels shall be measured in terms of the A-weighted equivalent continuous sound pressure level (Leq). Leq (30min) shall be used as the monitoring parameter for the time period between 0700-1900 hours on normal weekdays. For all other time periods, Leq (5min) shall be employed for comparison with the Noise Control Ordinance (NCO) criteria. As supplementary information for data auditing, statistical results such as L₁₀ and L₉₀ shall also be obtained for reference.

Monitoring Locations

- 3.3 In accordance with the Updated EM&A Manual, noise monitoring shall only be conducted at the monitoring location when there are Project related construction activities being undertaken within a radius of 300m from the monitoring location.
- 3.4 Eight designated noise monitoring stations, NM1 to NM8 were selected for noise impact monitoring. Appendix A shows the established Action and Limit Levels for the environmental monitoring works. Table 3.1 describes the noise monitoring locations and Figure 3 shows their locations.

Table 3.1 Noise Monitoring Stations

Stations	Description	Location
NM1	No. 28 Lung Tseng Tau	Ground Floor
NM2	YMCA of Hong Kong Christian College	Rooftop
NM3	No. 37 Shek Lau Po	Ground Floor
NM4	No. 1 Shek Mun Kap	Ground Floor
NM5	Tung Chung Au Country Parks Management Centre	Ground Floor
NM6	D75 Leyburn Villa	Ground Floor
NM7 ⁽¹⁾	House in Butterfly Crest House 22	Rooftop
NM8	No. 31 South Lantau Road	Ground Floor

Remarks:

⁽¹⁾ Monitoring at NM7 will be conducted when the Project related construction activities are being undertaken within a radius of 300 m from the monitoring location.

Monitoring Equipment

3.5 Table 3.2 summarizes the noise monitoring equipment model being used. Copies of calibration certificates are attached in Appendix B.

Table 3.2 Noise Monitoring Equipment

Equipment	Model and Make	Quantity
Integrating Sound Level Meter	B&K Model 2238	4
Calibrator	K 4231	3
Wind Speed Anemometer	RS232 Integral Vane Digital Anemometer	1

Monitoring Parameters, Frequency and Duration

3.6 Table 3.3 summarizes the monitoring parameters, frequency and total duration of monitoring. The noise monitoring schedule is attached in Appendix C.

Table 3.3 Noise Monitoring Parameters, Frequency and Duration

Station	Parameter	Period ¹	Frequency	Measurement
NM1				Façade ⁽¹⁾
NM2				Façade ⁽¹⁾
NM3		(a) 0700-1900 hrs. on weekdays		Façade ⁽¹⁾
NM4	$L_{10}(30 \text{ min.})dB(A)$	(b) 1900-2300 hrs. on weekdays	Once every 6 working	Façade ⁽¹⁾
NM5	$\begin{array}{c} L_{90}(30 \text{ min.})dB(A) \\ L_{eq}(30 \text{ min.})dB(A) \end{array}$	(c) 0700-2300 hrs. on holidays	6 working days	Façade ⁽¹⁾
NM6		(d) 2300-0700 hrs on any days		Façade ⁽¹⁾
NM7				Façade ⁽¹⁾
NM8				Façade ⁽¹⁾

Remarks:

Monitoring Methodology and QA/QC Procedures

- The Sound Level Meter was generally set on a tripod at a height of 1.2 m above the ground, depending to the actual monitoring condition.
- For free field measurement (if any), the meter was positioned away from any nearby reflective surfaces. All records for free field noise levels were adjusted with a correction of +3 dB(A).
- The battery condition was checked to ensure the correct functioning of the meter.
- Parameters such as frequency weighting, the time weighting and the measurement time were set as follows:

⁽¹⁾ Noise measurements were taken at 1m from the exterior of the building facade.

⁽b), (c) and (d) will only be conducted if construction works are undertaken during these periods.

frequency weighting : Atime weighting : Fast

time measurement : 30 minutes / 5 minutes

- Prior to and after each noise measurement, the meter was calibrated using a
 Calibrator for 94.0 dB at 1000 Hz. If the difference in the calibration level before
 and after measurement was more than 1.0 dB, the measurement would be
 considered invalid and repeat of noise measurement would be required after recalibration or repair of the equipment.
- The wind speed was frequently checked with the portable wind meter.
- At the end of the monitoring period, the L_{eq}, L₉₀ and L₁₀ were recorded. In addition, site conditions and noise sources were recorded on a standard record sheet.
- Noise measurement was paused during periods of high intrusive noise if possible and observation was recorded when intrusive noise was not avoided.
- Noise monitoring was cancelled in the presence of fog, rain, and wind with a steady speed exceeding 5 m/s, or wind with gusts exceeding 10 m/s.

Maintenance and Calibration

3.7 The microphone head of the sound level meter and calibrator was cleaned with soft cloth regularly. The meters were sent to the supplier to check and calibrate on a yearly interval.

Results and Observations

- 3.8 Noise monitoring was conducted as scheduled at the seven designated stations NM1, NM2, NM3, NM4, NM5, NM6 and NM8, in this reporting month.
- 3.9 Noise monitoring results and graphical presentations are shown in Appendix E.
- 3.10 No Action/Limit Level exceedance was recorded in the reporting month.

4. WATER QUALITY

Monitoring Requirements

4.1 Water quality monitoring was conducted in accordance with the Updated EM&A Manual. Appendix A shows the established Action Limit Levels for the environmental monitoring works.

Monitoring Equipment

4.2 Table 4.1 summarizes the equipment used in the impact water quality monitoring program. All the monitoring equipment complied with the specifications stipulated in the EM&A Manual. Copies of the calibration certificates of the equipment are attached in Appendix B.

Table 4.1 Water Quality Monitoring Equipment

Equipment	Model and Make	Qty.
Multi-parameter Water Quality System	YSI 6820	2

Monitoring Parameters, Frequency and Duration

- 4.3 Table 4.2 summarizes the monitoring parameters, monitoring period and frequencies of water quality monitoring. The water quality monitoring schedule is attached in Appendix C.
- 4.4 In-situ measurements were taken at designated monitoring stations which are under the influence of the works at least three times per week during the course of the construction period. In addition, water samples for suspended solid analysis have been collected at the designated stations and delivered to Wellab for further laboratory analysis.

Table 4.2 Frequency and Parameters of Water Quality Monitoring

Parameters	Frequency	No. of Depth
DO Saturation (%), DO (mg/L), Turbidity (NTU), SS (mg/L), Temperature (°C), & pH	3 times per week	Sub-surface

Monitoring Locations

4.5 The water quality monitoring locations are shown in Figure 3 and their details are provided in Table 4.3.

Table 4.3 Water Quality Monitoring Locations

Monitoring Station	Туре	Easting	Northing
(Stream No.)	J 1 -		
T Cl C4	Reference	811853	813289
Tung Chung Stream	Impact	811601	813716
Charma Cha Ctuanu	Reference	812525	811980
Cheung Sha Stream	Impact	812447	811165
Stream 15	Reference	811853	813289
Sueam 13	Impact	811781	813298
Stream 18	Reference	811889	813107
Sueam 18	Impact	811836	813138
Stream 19	Reference	811920	812927
Sueam 19	Impact	811858	812987
Stream 21	Reference	811994	812695
Sueam 21	Impact	811873	812723
	Reference1	811980	812589
Stream 23	Reference 2	812079	812386
	Impact	811894	812658
Stream 25	Reference	812353	812052
Sucam 25	Impact	812324	812017
Stream 26	Reference	812525	811980
Stream 20	Impact	812456	811895
Stream 27	Reference	812658	811770
Sucain 27	Impact	812604	811747
Stream 32	Reference	812980	811410
Sucain 32	Impact	812988	811327
Stream 35	Reference	813231	811275
Sucalli 33	Impact	813218	811218
Stream 40	Reference	813686	811311
Sucain 40	Impact	813690	811211
Tung Chung Bay	Reference	810679	816038
Tung Chung Day	Impact	810787	815706

Monitoring Methodology, Calibration Details and QA/QC Procedures

Instrumentation

4.6 A multi-parameter meter (Model YSI 6820 CE-C-M-Y) was used to measure DO, turbidity, salinity, pH and temperature.

Operating/Analytical Procedures

- 4.7 At each monitoring location, two consecutive measurements were taken for water samples being collected on site. The probes were retrieved out of the water after the first measurement and then re-deployed for the second measurement. Where the difference in the value between the first and second readings of each set was more than 25% of the value of the first reading, the reading was discarded and further readings were taken.
- 4.8 For SS, measurement and grab samples of surface water were collected. Water samples of about 1,000 ml were collected and stored in polyethylene bottles. Following collection, water samples were stored in high density polythene bottles with preservative appropriately added, packed in ice and cooled to 4°C (without being frozen), delivered to the HOKLAS accredited laboratory, Wellab Limited and analyzed.

Maintenance and Calibration

4.9 Before each round of monitoring, a zero check in distilled water was performed with the turbidity probe of YSI 6820. The probe was then calibrated with a solution of known NTU.

Results and Observations

- 4.10 Water quality monitoring was conducted as scheduled at designated monitoring stations (Streams 15, 18, 21, 23, 26, 27, 40, Cheung Sha Stream, Tung Chung Stream and Tung Chung Bay), which are under the influence of the works, in the reporting month. No water monitoring was conducted at the streams which were observed dry in the reporting month.
- 4.11 During monitoring, the weather conditions were generally sunny. The monitoring data and graphical presentations of the monitoring results are shown in Appendix F and the Quality Control reports for the laboratory analysis are provided in Appendix G.
- 4.12 Exceedances of suspended solids (SS) were recorded in water samples in the reporting month. The exceedance reports are attached in Appendix H. The summary of exceedances for each water quality parameters are provided in Table 4.4.

Table 4.4 Summary of Water Quality Exceedances in the reporting month

Station	DO		pН	Turbidit	y	SS	
No.	Action	Limit	Limit	Action	Limit	Action	Limit
15_I	0	0	0	0	0	0	0
18_I	0	0	0	0	0	0	0
19_I*	0	0	0	0	0	0	0
21_I	0	0	0	0	0	0	0
23_I	0	0	0	0	0	0	0
25-I*	0	0	0	0	0	0	0
26_I	0	0	0	0	0	0	0
27_I	0	0	0	0	0	14	0
32_I*	0	0	0	0	0	0	0
35_I*	0	0	0	0	0	0	0
40_I	0	0	0	0	0	0	0
CSS_I	0	0	0	0	0	0	0
TCB_I	0	0	0	0	0	0	0
TCS_I	0	0	0	0	0	0	0

Remarks: * indicates the stream was not sampled in the reporting month.

- 4.13 As shown in the exceedance reports attached in Appendix H, all exceedances for water quality parameters recorded in the reporting month were not due to the Project based on the following observations:
 - ♦ No construction activity was observed in the vicinity of the sampling locations.
 - ♦ No pollution discharge from construction activity was observed.
 - ♦ Measured value at the reference station was higher than at the impact monitoring stations.
- 4.14 According to the ET's investigation, no direct evidence demonstrated the exceedances of Action/Limit level for water monitoring parameters were caused by the Project.

5. ENVIRONMENTAL AUDIT

Site Audits

- 5.1 Site audits were carried out on a weekly basis to monitor the timely implementation of proper environmental management practices and mitigation measures in the Project site.
- 5.2 ET site audits were conducted on 4th, 10th, 18th and 25th June 2009 in the reporting month. IEC site inspection was conducted on 10th June 2009. The summaries of site audits are attached in Appendix I.

Review of Environmental Monitoring Procedures

5.3 The monitoring works conducted by the monitoring team were inspected regularly. The following observations were recorded for the monitoring works:

Air Quality Monitoring

- The monitoring team recorded all observations around the monitoring stations within and outside of the construction site.
- The monitoring team recorded the temperature, air pressure and weather conditions on the monitoring day.

Noise Monitoring

- The monitoring team recorded all observations around the monitoring stations, which might affect the monitoring result.
- Major noise sources were identified and recorded. Other intrusive noise attributing to the result was trimmed off by pausing the monitoring temporarily.

Water Quality Monitoring

- The monitoring team recorded all observations around the monitoring stations, which might affect the monitoring result.
- The monitoring team recorded the weather and river conditions on the monitoring day.

Status of Environmental Licensing and Permitting

5.4 All permits/licenses obtained for the Project are summarized in Table 5.1.

Table 5.1 Summary of Environmental Licensing and Permit Status

Permit No.	Valid Period		Details	Status
Permit No.	From	To	Details	Status
Environmental Peri				
EP-170/2003/C	31/7/07	N/A	Construction of	Valid
			(a) Widening and realignment of an approximate	
			3.6 kilometre long section of Tung Chung Road	
			between Lung Tseng Tau and Pak Kung Au from	
			a single-lane road for two-way traffic to a single	
			two-lane road with footpath;	
			(b) Construction of an approximate 2.6 kilometre	
			long single two-lane road between Pak Kung Au	
			and Cheung Sha with footpath and elevated highway structures; and	
			© Provision of passing bays/bus lay-bys along	
			Tung Chung Road.	
Registration of Che	mical Waste	Producer		
WPN5214 – 950-		N/A	Chemical waste types:	Valid
C1213-01			spent Indication oil, surplus paint, spent diesel,	
			spent thinner, mixing residue containing	
			pesticides, spent mineral oil	
Water Discharge Li	cense			
EP890/W7/XP089		N/A	Discharge from Sewage Treatment System	Valid
			(Northern Section)	
EP890/W7/XP090		N/A	Industrial discharge (Northern Section)	Valid
EP890/W2/XG013		N/A	Industrial discharge (Southern Section)	Valid

Status of Waste Management

- 5.5 The waste management of the Project has to follow the requirements and procedures stated in the Waste Management Plan which was prepared by the Contractor.
- 5.6 The solid waste generated from the Project was mainly general refuse that was collected by a licensed collector on an as need basis.
- 5.7 The monthly summary of waste flow table and the timber summary for June 2009 are provided in Appendix O.

Implementation Status of Environmental Mitigation Measures

5.8 During site inspections in the reporting month, no non-conformance was identified. The observations and recommendations are summarized in Table 5.2.

 Table 5.2
 Observations and Recommendations of Site Inspections

Parameters	Date	Observations and Recommendations	Follow-up
Water Quality		Silt and sediment was observed discharging to the catchwater from the exposed slope especially at underneath STR 17, 18. The Contractor was reminded to cover/hydroseed the exposed slope immediately especially during rainstorm.	the follow-up audit session.
	04/06/09	Stream water at Stream 20 was observed not diverted properly around the works. The Contractor was reminded to review and re-arrange the stream diversion to prevent any wastewater discharging out.	the follow-up audit session.
		Seepage of silty water from the hole of concrete bund was observed at SD5-11. The Contractor was reminded to provide mitigation measures to prevent any wastewater from discharging to the downstream.	the follow-up audit session.
		Concrete debris was observed at Steam 21 due to the concrete breaking before. The Contractor was reminded to clear the debris and ensure the stream water in good condition	the follow-up audit session.
	04/06/09	The Contractor was reminded of the followings: - Provide sand bag at the culvert at Shan Shek Wan.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	04/06/09	 The Contractor was reminded of the followings: Clear the construction waste, silt, debris and sediment in the culvert and U-channel along Tung Chung Road (Southern and Northern Sections) especially at STR17, Shan Shek Wan, CH7000, near Stream 20, Pak Kung Au, SD7-13, SD6-12, SD5-11, SD4-7 and underneath STR7. 	Follow-up action was needed for the outstanding item.
	04/06/09	The Contractor was reminded of the followings: - Properly cover/compact the exposed area at between Stream 20 and 19, near stream 21, SD4-7, SD6-12 and underneath STR 14 when the works were not undertaken.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	04/06/09	The Contractor was reminded of the followings: - Clear the stagnant water at the wheel washing bay (abandoned) at Site Office, pit area at near SD7-13 and the hole for handrail along Southern Section of Tung Chung Road.	Follow-up action was needed for the outstanding item
		Silt and sediment was observed discharging to the catchwater from the exposed slope due to the soil erosion especially at underneath STR 16, 17 and 18. The Contractor was reminded to provide mitigation measures to protect the slope (In-progress).	the follow-up audit session. Follow-up action was needed for
		Stream water at Stream 20 was observed not diverted properly around the works. The Contractor was reminded to review and re-arrange the stream diversion to prevent any wastewater discharging out.	the follow-up audit session.

Parameters	Date	Observations and Recommendations	Follow-up
		Seepage of silty water from the hole of concrete bund was observed at SD5-11 . The Contractor was reminded to provide mitigation measures to prevent any silty water from discharging to the downstream.	observed during the follow-up
		Concrete debris was observed at Steam 21 due to the concrete breaking before. The Contractor was reminded to clear the debris and ensure the stream water in good condition	observed during the follow-up
	10/06/09	The Contractor was reminded of the followings: - Provide sand bag at the culvert at Shan Shek Wan.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	10/06/09	 The Contractor was reminded of the followings: Clear the construction waste, silt, debris and sediment in the culvert and U-channel along Tung Chung Road (Southern and Northern Sections) especially at STR17, Shan Shek Wan, CH7000, near Stream 20, Pak Kung Au, SD7-13, SD6-12, SD5-11, SD4-7 and underneath STR7. 	Follow-up action was needed for the outstanding item.
	10/06/09		This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	10/06/09	The Contractor was reminded of the followings: - Clear the standing water at the wheel washing bay (abandoned) at Site Office , pit area at near SD7-13 and the hole for handrail along Southern Section of Tung Chung Road .	Follow-up action was needed for the outstanding item
	10/06/09	20	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	10/06/09	Shan Shek Wan	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
			II ~
		Stream water at Stream 20 was observed not diverted properly around the works. The Contractor was reminded to review and re-arrange the stream diversion to prevent any wastewater discharging out.	the follow-up audit session.
		Sediment was observed from discharging to the culverts at SD5-11and SD6-12. The Contractor was reminded to clear the culvert and provide mitigation measures to prevent further sediment from discharging to the culvert.	observed during the follow-up

Parameters	Date	Observations and Recommendations	Follow-up
	18/06/09	The Contractor was reminded of the followings: - Provide sand bag at the culvert at Shan Shek Wan.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	18/06/09	The Contractor was reminded of the followings: - Clear oil stain at underneath STR7 .	Rectification/improvement was observed during the follow-up audit session.
	18/06/09	The Contractor was reminded of the followings: - Clear the construction waste, silt, debris and sediment in the culvert and U-channel along Tung Chung Road (Southern and Northern Sections) especially at STR17, Shan Shek Wan, CH7000, near Stream 20, Pak Kung Au, SD7-13, SD6-12, SD5-11, SD4-7 and underneath STR7.	Follow-up action was needed for the outstanding item.
	18/06/09	The Contractor was reminded of the followings: - Properly cover/compact the exposed area at between Stream 20 and 19, near stream 21, SD4-7, SD6-12 and underneath STR 7 and STR 14 after the works.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	18/06/09	The Contractor was reminded of the followings: - Clear the standing water at the wheel washing bay (abandoned) at Site Office , pit area at near SD7-13 .	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	18/06/09	The Contractor was reminded of the followings: - Properly maintain the sand bag bund at near Stream 20.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	18/06/09	The Contractor was reminded of the followings: - Provide mosquito larvicide for the stagnant water at Shan Shek Wan.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
		Soil erosion was observed at STR 16, 17, 18 and near Stream 35. The Contractor was reminded to provide mitigation measures to protect the slope. (In – progress).	the follow-up audit session.
		Stream water at Stream 20 was observed not diverted properly around the works. The Contractor was reminded to review and re-arrange the stream diversion to prevent any wastewater discharging out.	the follow-up audit session.
		Silty water was observed at Stream 23 . However, the silty water was due to the broken water pipe from other construction site at old Tung Chung Road . The item was also observed to be rectified during the site inspection.	observed during the follow-up audit session.
	25/06/09	The Contractor was reminded of the followings: - Provide sand bag at the culvert at Shan Shek Wan.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.

Parameters	Date	Observations and Recommendations	Follow-up
	25/06/09	The Contractor was reminded of the followings:	This item was not rectified during
		- Clear the construction waste, silt, debris and sediment	the follow-up audit session.
		in the culvert and U-channel along Tung Chung Road	the outstanding item.
		(Southern and Northern Sections) especially at STR17,	the outstanding term.
		Shan Shek Wan, CH7000, near Stream 20, Pak Kung	
		Au, SD7-13, SD6-12, SD5-11, SD4-7 and underneath	
		STR7.	
	25/06/09	The Contractor was reminded of the followings:	This item was not rectified during
		- Properly cover/compact the exposed area at between	the follow-up audit session.
		50 can 20 and 17, near sucam 17, 21, 3D4-7, 3D3-11,	Follow-up action was needed for the outstanding item.
		SD6-12 and underneath STR 7 and STR 14 after the	the outstanding term.
		works.	
	25/06/09	The Contractor was reminded of the followings:	This item was not rectified during
		- Clear the standing water at the wheel washing bay	the follow-up audit session.
		(abandoned) at Site Office and Stream 21.	Follow-up action was needed for the outstanding item.
	25/06/09	The Contractor was reminded of the followings:	This item was not rectified during
	23/00/07	 Properly maintain the sand bag bund at near Stream 20. 	_
		(In-progress)	Follow-up action was needed for
		, 1 C	the outstanding item.
	25/06/09	The Contractor was reminded of the followings:	This item was not rectified during
		- Provide mosquito larvicide for the stagnant water at	the follow-up audit session.
		Shan Shek Wan.	Follow-up action was needed for the outstanding item.
	25/06/09	The Contractor was reminded of the followings:	This item was not rectified during
		- Provide mitigation measures to prevent silty water	the follow-up audit session.
		flowing to the culvert at SD4-7.	Follow-up action was needed for
Air On alita		The Contractor was reminded of the followings:	the outstanding item.
Air Quality		The Contractor was reminded of the followings: - Properly maintain the slopes which have been	This item was not rectified during the follow-up audit session.
	04/06/09	hydroseeded along Tung Chung Road (Southern and	Follow-up action was needed for
		Northern Section) especially after the rainstorm.	the outstanding item.
		The Contractor was reminded of the followings:	This item was not rectified during
		=	the follow-up audit session.
	10/06/09	hydroseeded along Tung Chung Road (Southern and	Follow-up action was needed for
		Northern Section) especially after the rainstorm.	the outstanding item.
		The Contractor was reminded of the followings:	This item was not rectified during
		- Provide mitigation measures to prevent dust emission	the follow-up audit session.
	10/06/09	during cement de-bagging works and clean the	Follow-up action was needed for
		remaining cement after the works at SD 4-7.	the outstanding item.
		The Contractor was reminded of the followings:	This item was not rectified during
		- Properly maintain the slopes which have been	the follow-up audit session.
	18/06/09	hydroseeded along Tung Chung Road (Southern and	Follow-up action was needed for
		Northern Section) especially after the rainstorm.	the outstanding item.
	18/06/09	The Contractor was reminded of the followings:	This item was not rectified during
		- Provide mitigation measures to prevent dust emission	
		during cement de-bagging works and clean the	Follow-up action was needed for
		remaining cement after the works at SD 4-7.	the outstanding item.
		remaining cement after the works at SD 4-7.	Ü

Parameters	Date	Observations and Recommendations	Follow-up
	25/06/09	The Contractor was reminded of the followings: - Properly maintain the slopes which have been hydroseeded along Tung Chung Road (Southern and Northern Section) especially after the rainstorm.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	25/06/09	 The Contractor was reminded of the followings: Provide mitigation measures to prevent dust emission during cement de-bagging works and clean the remaining cement after the works at SD 4-7. 	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
Waste / Chemical Management	04/06/09	Empty oil containers were observed at underneath STR 7, near Stream 20, 21 and SD4-7 . The Contractor was reminded to dispose them as chemical waste.	the follow-up audit session. Follow-up action was needed for the outstanding item.
	04/06/09	Discarded hose were observed at Shan Shek Wan . The Contractor was reminded to clear them.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	04/06/09	The Contractor was reminded of the followings: - Clear C&D waste and discarded cement bags at underneath STR7.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	04/06/09	The Contractor was reminded of the followings: - Clear general refuse at underneath STR7.	Rectification/improvement was observed during the follow-up audit session.
	04/06/09	The Contractor was reminded of the followings: - Clear the discarded "protection material for hydroseed" that was hanging on the trees along Southern Section of Tung Chung Road.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	04/06/09	The Contractor was reminded of the followings: - Clear C&D waste at near SD7-13, SD6-12, SD5-11 and SD4-7.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	04/06/09	The Contractor was reminded of the followings: - Clear vegetation waste along Tung Chung Road especially near the catchwater.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	04/06/09	The Contractor was reminded of the followings: - Keep clear and sort C&D waste at Shan Shek Wan.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
		Empty oil containers were observed at underneath STR 7, near Stream 20, 21 and SD4-7. The Contractor was reminded to dispose them as chemical waste.	
	10/06/09	Discarded hose were observed at Shan Shek Wan . The Contractor was reminded to clear them.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	10/06/09	The Contractor was reminded of the followings: - Clear C&D waste and discarded cement bags at underneath STR7.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.

Parameters	Date	Observations and Recommendations	Follow-up
	10/06/09	The Contractor was reminded of the followings: - Clear oil stain at underneath STR7.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	10/06/09	The Contractor was reminded of the followings: - Clear the discarded "protection material for hydroseed" that was hanging on the trees along Southern Section of Tung Chung Road.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	10/06/09	The Contractor was reminded of the followings: - Clear C&D waste at near SD7-13, SD6-12, SD5-11 and SD4-7.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	10/06/09	The Contractor was reminded of the followings: - Clear vegetation waste along Tung Chung Road especially near the catchwater.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	10/06/09	recep cical and soft coep waste at blight stick wan.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
		Empty oil containers were observed at underneath STR 7, near Stream 20, 21 and SD4-7. The Contractor was reminded to dispose them as chemical waste.	
	18/06/09	Discarded hose were observed at Shan Shek Wan . The Contractor was reminded to clear them.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	18/06/09	The Contractor was reminded of the followings: - Clear C&D waste and discarded cement bags at underneath STR7.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
		The Contractor was reminded of the followings: - Clear oil stain at underneath STR7.	Rectification/improvement was observed during the follow-up audit session.
	18/06/09	- Clear the discarded "protection material for	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	18/06/09	The Contractor was reminded of the followings: - Clear C&D waste and sediment at SD6-12, SD5-11 and SD4-7.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	18/06/09	especially lical the calcilwater and underlication of in 7.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	18/06/09	The Contractor was reminded of the followings: - Keep clear and sort C&D waste at Shan Shek Wan.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.

Parameters	Date	Observations and Recommendations	Follow-up
	25/06/09	Empty oil containers were observed at underneath STR 7, near Stream 20, 21 and SD4-7. The Contractor was reminded to dispose them as chemical waste.	
	25/06/09	Discarded hose were observed at Shan Shek Wan. The Contractor was reminded to clear them.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	25/06/09	The Contractor was reminded of the followings: - Discarded cement bag's at underneath STR7.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	25/06/09		This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	25/06/09	The Contractor was reminded of the followings: - Clear C&D waste and sediment at SD6-12, SD5-11, SD4-7 and Stream 20.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	25/06/09	The Contractor was reminded of the followings: - Clear vegetation waste along Tung Chung Road especially near the catchwater and underneath STR 7 .	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	25/06/09	The Contractor was reminded of the followings: - Keep clear and sort C&D waste at Shan Shek Wan.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	25/06/09	The Contractor was reminded of the followings: - Clear the stockpile at underneath STR 7.	Rectification/improvement was observed during the follow-up audit session.
	04/06/09	27, 30, 34 and 36-38.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
Ecology	10/06/09	Clear Coeb waste and general relate at bir cam 21, 22,	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
Ecology	18/06/09	The Contractor was reminded of the followings: - Clear C&D waste and general refuse at Stream 21 , 22 , 27 , 30 , 34 and 36-38 .	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	25/06/09	The Contractor was reminded of the followings: - Clear C&D waste and general refuse at Stream 21 , 22 , 27 , 30 , 34 and 36-38 .	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
General	04/06/09	The Contractor was reminded of the followings: - Provide mitigation measures at between the outstanding construction area and paved road to prevent any mud from carrying to the public road.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.

Parameters	Date	Observations and Recommendations	Follow-up
	10/06/09	- Provide mitigation measures at between the	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	18/06/09	- Provide mitigation measures at between the	
	25/06/09	outstanding construction area and paved road to at	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.

Non-compliance Recorded during Site Inspections

5.9 No non-compliance was recorded in the reporting period.

Summary of Mitigation Measures Implemented

5.10 The Contractor has implemented the mitigation measures as recommended in the EIA and the Updated EM&A Manual. The mitigation measures implemented by the Contractor in the reporting month are summarized as follow:

Water Quality

- (1) Provided mitigation measures to prevent any silty water from discharging to the downstream at SD5-11.
- (2) Cleared the debris and ensure the stream water in good condition at Steam 21.
- (3) Cleared the culvert and provide mitigation measures to prevent further sediment from discharging to the culvert at SD5-11 and SD6-12.

Waste/Chemical Management

- (1) Cleared general refuse at underneath STR7.
- (2) Cleared oil stain at underneath STR7.
- (3) Cleared the stockpile at underneath STR 7.
- 5.11 According to the Updated EM&A Manual, mitigation measures are required to be implemented. An updated summary of the EMIS is provided in Appendix J.

Summary of Exceedances of the Environmental Quality Performance Limit

24-hr TSP Monitoring

5.12 No Action/Limit Level exceedance was recorded in the reporting month.

Construction Noise Monitoring

5.13 No Action/Limit Level exceedance was recorded in the reporting month.

Water Quality Monitoring

- 5.14 Exceedances of suspended solids (SS) were recorded in water samples in the reporting month. The summary of exceedances is provided in Table 4.4.
- 5.15 All exceedances recorded for water quality parameters in the reporting month were not considered due to the Project due to the following observations:
 - ♦ No construction activity was observed in the vicinity of the sampling locations.
 - ♦ No pollution discharge from construction activity was observed.
 - ♦ Measured value at the reference station was higher than at the impact monitoring stations.
- 5.16 No direct evidence demonstrated the exceedances of Action/Limit level for water monitoring parameters in the reporting month were caused by the Project.

Implementation Status of Event Action Plans

- 5.17 The Event Action Plans for air quality, noise and water quality are presented in Appendix K.
- 5.18 No valid exceedance of Action and Limit levels for air quality, noise and water quality monitoring due to the Project was recorded. No action was required to be carried out.

Summary of Complaint, Warning, Notification of any Summons and Successful Prosecution

- 5.19 A total of 1 environmental complaint was received in the reporting month.
- 5.20 The complaint was raised by the WSD on 1st June 2009. WSD concerned about the soiled water had been collected from New Tung Chung Road and soil erosion was found at Cheung Sha Catchwater. The ETL of the Project was informed of the complaint by CCJV through the e-mail on 5th June 2009 and initiated the complaint investigation procedures. The Complaint letter from WSD (Ref: (21)in WSD (HK) 1743/664/01 Pt.18 TJ(5).
- 5.21 Base on the information collected, the complaint was considered justifiable as heavy downpour of rain had caused soil erosion on exposed slopes leading to Cheung Sha Catchwater.
- 5.22 The Contractor was recommended to take sufficient mitigation measures to minimize the exposed areas to rain by covering the exposed area with tarpaulin or soil erosion control mat, as well as to carry out slope reinstatement works as soon as practicable.
- 5.23 The environmental conditions of the site will be continuously reviewed by the Resident Site Staff, IEC and the Environmental Team through regular and ad hoc site

- inspections and monitoring exercises.
- 5.24 No warning and summon or notification of successful prosecution was received in the reporting month.
- 5.25 There were a total of 55 environmental complaints, 13 warnings, 3 summons and 2 successful prosecutions received since the commencement of the Project.
- 5.26 The Complaint Log is attached in Appendix L and the summary of warnings issued by the EPD and prosecution is attached in Appendix M.

6. FUTURE KEY ISSUES

Key Issues for the Coming Month

- 6.1 Key issues to be considered in the coming month include:
 - Runoff from exposed slope;
 - Wastewater and runoff discharge from site;
 - Regular removal of silt, mud and sand along u-channels, culverts and gullies;
 - Review and implementation of temporary drainage system for the surface runoff;
 - Proper storage of construction materials near streams;
 - Noise from operation of the equipment, especially for rock-breaking activities and machinery on-site;
 - Dust generation from stockpiles of dusty materials, exposed retain wall, excavation works and rock breaking activities;
 - Storage of chemicals/fuel and chemical waste/waste oil on site;
 - Watering for rock breaking activity, soil nailing and on haul road;
 - Accumulation of general and construction waste near stream and on site;
 - Proper sorting and segregation of C&D materials in designated areas; and
 - Provide wheel washing facilities at the site entrance/exit.

Monitoring Schedule for the Next Month

6.2 The tentative monitoring schedule for the next month is given in Appendix C.

Construction Program for the Project (Construction Program for the Next Month)

6.3 The major construction activities in the coming month include:

Northern Section

- Installation of street furniture at Zone A to F;
- Construction of baffle wall and stepped channel; and
- Reinstatement works of the footpath.

Southern Section

- Reinstatement works of footpath at Zone 1 to 3; and
- Street furniture installation at Zone 1 to 3.

7. CONCLUSIONS AND RECOMMENDATIONS

Conclusions

- 7.1 Air quality, noise and water quality monitoring works were performed in the reporting month and all monitoring results were checked and reviewed.
- 7.2 24-hour TSP monitoring was conducted as scheduled in the reporting month. No Action/Limit Level exceedance was recorded in the reporting month.
- 7.3 Construction noise monitoring was conducted as scheduled in the reporting month. No Action/Limit Level exceedance was recorded in the reporting month.
- 7.4 Water quality monitoring was conducted as scheduled in the reporting month.
- 7.5 No valid Action/Limit Level exceedance for water quality was recorded in the reporting month.
- 7.6 A total of 1 environmental complaint was received in the reporting month.
- 7.7 No warning and summon and notification of successful prosecution was received in the reporting month.

Recommendations

7.8 According to the environmental audit performed in the reporting month, the following recommendations were made:

Dust Impact

- To implement dust suppression measures on all haul roads, stockpiles and dry surfaces in dry weather.
- To implement dust control measures for the dust generation work such as cement mixing, soil nailing, excavation, piling works and rock breaking.
- To ensure water spray being applied for the dust emissive works, such as soil nail
 installation, loading and unloading of soil materials, excavation works and rock
 dowel installation.
- To cover soil stockpiles and exposed slope surface by impervious tarpaulin sheets or other means.
- To ensure that all vehicles carrying dusty material are properly covered before leaving the site.
- To maintain the machinery and vehicles in a good working condition on site.

Noise Impact

• To implement appropriate mitigation measures, such as cover the tip of the hammer,

in order to minimize the noise emitted during rock-breaking activities.

- To review the works sequence of site activities so as to reduce the number of noisy equipment in concurrent operation.
- To follow up any exceedance caused by the construction works.
- To employ quiet powered mechanical equipment if possible.
- To ensure compliance of CNP conditions during restricted-hour works.
- To space out noisy equipment and position as far away as possible from sensitive receivers.


Water Quality Impact


- To prevent any surface runoff discharge into any stream course.
- To avoid accumulation of stagnant and ponding water on site.
- To clear the silt and sediment in the sedimentation tanks.
- To ensure properly maintenance for de-silting facilities.
- To divert all the water generated from construction site to de-silting facilities with enough handling capacity before discharge.
- To review the capacity of de-silting facilities for discharge.
- To review and implement temporary drainage system.
- To identify any wastewater discharges from site.
- To follow up any exceedance caused by the construction works.

Waste / Chemical Management

- To ensure no sediment and debris in the drainage system (U-Channel, culvert, gullies and underground channel) after the rainstorm.
- To avoid any discharge or accidental spillage of chemical waste directly from the site.
- To remove ponding water regularly in drip trays on site.
- To carry out inspection of dump truck at site exit to ensure inert and non-inert C&D materials are properly segregated before removing off site.
- To ensure proper collection and disposal of rubbish generated on site.
- To avoid storage of oil container within the Country Park.
- To ensure the performance of sorting of C&D materials at source (during generation).
- To avoid storage of construction materials at any stream.
- To check for any accumulation of waste materials or rubbish on site.
- To sort and segregate C&D materials in designated areas properly.

FIGURES










Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha


Organization Chart


SCALE	N.T.S.	DATE	200	7	
CHECK	KL	DRAWN	FL		
JOB NO.		DRAWING	No.	Rev	
	MA6030	2		1	

















APPENDIX A
ACTION AND LIMIT LEVELS FOR AIR
QUALITY, NOISE AND WATER
QUALITY

Appendix A - Action and Limit Levels

Table A-1 Action and Limit Levels for 1-Hour TSP

Location	Action Level, μg/m ³	Limit Level, μg/m ³
AM1	312	
AM2	328	
AM3	302	500
AM4	305	
AM5	342	

Table A-2 Action and Limit Levels for 24-Hour TSP

Location	Action Level, μg/m ³	Limit Level, µg/m ³
AM1	155	
AM2	151	
AM3	141	260
AM4	145	
AM5	153	

Table A-3 Action and Limit Levels for Construction Noise

Period	Action Level (2)	Limit	Level
0700-1900 hrs on normal weekdays		75 dB(A)	70 dB(A)
1900-2300 hrs on holidays & 0700-2300 hrs on all other days	When one documented complaint is received	- '	(1)
2300-0700 hrs of next day		_ '	(1)

^{*}Free field noise levels were adjusted with a correction of +3 dB(A)

Notes:

- (1) The noise limits shall be determined by EPD during the application of the construction noise permit (CNP).
- (2) Stated in the "Environmental Monitoring and Audit Guidelines for Development Projects in Hong Kong", Appendix D2, Section 2.6, Table 2.1

Table A-4 Compliance Level for Water Quality

Table N-4 Compliance Devel for Water Quality												
Monitoring	DO, 1	mg/L		рН		Turbidit	ty, NTU			SS, r	ng/L	
Stations	Action	Limit	Action	Limit	A	Action]	Limit	A	action	I	Limit
TCS_I	6.10	4.00	-	<6.5 or >8.5	5.95		13.30		10.30		12.00	
CSS_I	6.40	4.00	-	<6.5 or >8.5	7.91		10.50		9.90		16.00	
15_I	5.94	4.00	-	<6.5 or >8.5	11.00		16.10		6.10		8.20	
18_I	6.43	4.00	ı	<6.5 or >8.5	6.84	or 120% of	11.10	or 130% of	14.00	or 120% of	16.00	or 130% of
19_I	6.55	4.00	=	<6.5 or >8.5	7.52	the upstream control	9.03	the upstream control	14.00	the upstream control	18.00	the upstream control
21_I	6.73	4.00	-	<6.5 or >8.5	7.70	station's Tby	8.30	station's Tby	6.60	station's SS	20.00	station's SS
23_I	6.55	4.00	ı	<6.5 or >8.5	6.37	(at the sme tide on the	6.62	(at the sme tide on the	8.50	(at the sme tide on the	17.00	(at the sme tide on the
26_I	6.49	4.00	ı	<6.5 or >8.5	7.53	same day if	8.10	same day if	6.70	same day if	15.00	same day if
27_I	5.33	4.00	ı	<6.5 or >8.5	6.05	appropriate)	6.76	appropriate)	2.10	appropriate)	3.00	appropriate)
32_I	5.94	4.00	-	<6.5 or >8.5	10.30		14.20		15.00		18.00	
40_I	6.42	4.00	=	<6.5 or >8.5	9.38		10.60		14.00		15.00	
TCB_I	6.31	4.00	-	<6.5 or >8.5	17.10		41.40		19.00		20.00	

APPENDIX B COPIES OF CALIBRATION CERTIFCATES

High-Volume TSP Sampler 5-POINT CALIBRATION DATA SHEET

CINOTECH

File No. MA6030/46/0016 Station AM1 - YMCA of HK Christian College Operator: CH 5-Jun-09 Date: Next Due Date: 1315 Equipment No.: A-01-46 Serial No. Ambient Condition 764.6 Temperature, Ta (K) 290.5 Pressure, Pa (mmHg) Orifice Transfer Standard Information 0.0395 A-04-06 Slope, mc 0.0575 Intercept, be Equipment No.: mc x Qstd + bc = $[\Delta H \times (Pa/760) \times (298/Ta)]^{1/2}$ Last Calibration Date: 6-Mar-09 Qstd = $\{ [\Delta H \times (Pa/760) \times (298/Ta)]^{1/2} -bc \} / mc$ Next Calibration Date: 5-Mar-10 Calibration of TSP Sampler Orfice HVS Calibration [ΔW x (Pa/760) x (298/Ta)]^{1/2} Y-ΔH (orifice), Qstd (CFM) ΔW $[\Delta H \times (Pa/760) \times (298/Ta)]^{1/2}$ Point (HVS), in. of oil in. of water X - axis axis 12.2 3.55 61.02 8.6 2.98 1 2.71 10.8 3.34 57.37 7.1 2.80 48.02 5.0 2.27 3 7.6 39.99 3.3 1.85 4 5.3 2.34 1.47 3.2 1.82 30,92 2.1 By Linear Regression of Y on X Slope, mw = 0.0495 Intercept, bw: -0.0964 Correlation coefficient* == *If Correlation Coefficient < 0.990, check and recalibrate. Set Point Calculation From the TSP Field Calibration Curve, take Qstd = 43 CFM From the Regression Equation, the "Y" value according to mw x Qstd + bw = $[\Delta W \times (Pa/760) \times (298/Ta)]^{1/2}$ Therefore, Set Point; W = $(\text{mw x Qstd} + \text{bw})^2 \times (760 / \text{Pa}) \times (\text{Ta}/298) =$ Remarks: Conducted by: Thi) CHING MANG Signature: Date: Checked by: Signature: Date:

High-Volume TSP Sampler 5-POINT CALIBRATION DATA SHEET



File No. MA6030/46/0017 AM1 - YMCA of HK Christian College CH Station Operator: 4-Aug-09 Date: 5-Jun-09 Next Due Date: Equipment No.: A-01-46 Serial No. 1315 **Ambient Condition** 754.4 Temperature, Ta (K) 303 Pressure, Pa (mmHg) Orifice Transfer Standard Information A-04-06 Slope, mc 0.0575 Intercept, be 0.0395 Equipment No.: mc x Qstd + bc = $[\Delta H \times (Pa/760) \times (298/\Gamma a)]^{1/2}$ 6-Mar-09 Last Calibration Date: Qstd = $\{ |\Delta H \times (Pa/760) \times (298/Ta) \}^{1/2} - bc \} / mc$ Next Calibration Date: 5-Mar-10 Calibration of TSP Sampler Orfice Calibration Qstd (CFM) $[\Delta W \times (Pa/760) \times (298/Ta)]^{1/2} \text{ Y-}$ ΔH (orifice), ΔW Point [AH x (Pa/760) x (298/Ta)]1/2 in. of water X - axis (HVS), in. of oil axis 12.5 3.49 60.07 8.7 2.91 1 7.2 2.65 2 10.6 3.22 55.26 2,23 3 7.4 2.69 46.06 5.1 1.71 5.2 2.25 38.50 3.0 1,36 30.53 1.9 5 3.3 1.79 By Linear Regression of Y on X Intercept, bw Slope, mw = ______0.0533 -0.2820 Correlation coefficient* = 0.9978 *If Correlation Coefficient < 0.990, check and recalibrate. Set Point Calculation From the TSP Field Calibration Curve, take Qstd = 43 CFM From the Regression Equation, the "Y" value according to may x Qstd + bay = $[\Delta W \times (Pa/760) \times (298/Ta)]^{1/2}$ Therefore, Set Point; $W = (mw \times Qstd + bw)^2 \times (760 / Pa) \times (Ta / 298) =$ Remarks: Conducted by: The CHINA Men Signature: Date:

High-Volume TSP Sampler 5-POINT CALIBRATION DATA SHEET

CINOTECH

Date:

File No. MA6030/11/0016 Operator: CH Station AM2 - Leyburn Villas Date: Next Due Date: 5-Jun-09 6-Apr-09 Equipment No.: A-01-11 Serial No. _____1805 Ambient Condition 764.6 Temperature, Ta (K) 290.5 Pressure, Pa (mmHg) Orifice Transfer Standard Information 0.0575 Intercept, bc 0.0395 A-04-06 Slope, mc Equipment No.: mc x Qstd + bc = $[\Delta H \times (Pa/760) \times (298/Ta)]^{1/2}$ Last Calibration Date: 6-Mar-09 Qstd = $\{[\Delta H \times (Pa/760) \times (298/Ta)]^{1/2} - bc\} / mc$ Next Calibration Date: 5-Mar-10 Calibration of TSP Sampler Orfice HVS Calibration Qstd (CFM) ΔW $[\Delta W \times (Pa/760) \times (298/Ta)]^{1/2} Y$ ΔH (orifice), Point [AH x (Pa/760) x (298/Ta)]1/2 in. of water (HVS), in. of oil X - axis axis 11.5 59.23 8.4 2.94 3.45 1 3.01 2,55 2 8.8 51.72 6.3 3 7.6 2.80 48.02 5.0 2.27 2.36 40.37 3.2 1.82 4 5.4 1.32 29.91 1.7 3.0 1.76 By Linear Regression of Y on X Intercept, bw : ______-0.3949 Slope, mw = ______0.0562 Correlation coefficient* = *If Correlation Coefficient < 0.990, check and recalibrate. **Set Point Calculation** From the TSP Field Calibration Curve, take Qstd = 43 CFM From the Regression Equation, the "Y" value according to mw x Qstd + bw = $[\Delta W \times (Pa/760) \times (298/Ta)]^{1/2}$ Therefore, Set Point; $W = (mw \times Qstd + bw)^2 \times (760 / Pa) \times (Ta / 298) =$ 3.96 Remarks: Conducted by: Tan CHNG Hung Signature; Date: Checked by: Signature:

High-Volume TSP Sampler 5-POINT CALIBRATION DATA SHEET



File No. MA6030/11/0017 Operator: CH Station AM2 - Leyburn Villas Next Due Date: 4-Aug-09 5-Jun-09 Date: Serial No. 1805 Equipment No.: A-01-11 Ambient Condition 754.4 Pressure, Pa (mmHg) Temperature, Ta (K) 303 Orifice Transfer Standard Information 0.0395 A-04-06 0.0575 Intercept, bc Equipment No.: Slope, mc mc x Qstd + bc = $[\Delta H \times (Pa/760) \times (298/\Gamma a)]^{1/2}$ Last Calibration Date: 6-Mar-09 Qstd = $\{[\Delta H \times (Pa/760) \times (298/Ta)]^{1/2} - bc\} / mc$ Next Calibration Date: 5-Mar-10 Calibration of TSP Sampler HVS Orfice Calibration $[\Delta W \times (Pa/760) \times (298/Ta)]^{1/2} \text{ Y-}$ Qstd (CFM) ΔW ΔH (orifice), [AH x (Pa/760) x (298/Ta)]1/2 Point (HVS), in. of oil X - axis in, of water 12.2 3.45 59.33 8.4 2.86 1 2.58 54.73 6.8 2 10.4 3.19 2,23 5.1 2.71 46.37 3 7.5 1.77 5.3 2.27 38.87 3.2 4 30.05 2.0 1.40 1.77 5 3.2 By Linear Regression of Y on X Intercept, bw: -0.1306 Slope, mw = 0.0501Correlation coefficient* = *If Correlation Coefficient < 0.990, check and recalibrate. Set Point Calculation From the TSP Field Calibration Curve, take Qstd = 43 CFM From the Regression Equation, the "Y" value according to mw x Qstd + bw = $[\Delta W \times (Pa/760) \times (298/Ta)]^{1/2}$ Therefore, Set Point; $W = (mw \times Qstd + bw)^2 \times (760 / Pa) \times (Ta / 298) =$ Remarks: Conducted by: The CHING HANGSignature: Date: Checked by: Signature: Date:

High-Volume TSP Sampler 5-POINT CALIBRATION DATA SHEET



MA6030/AM4/0016 File No. Station CH No. 31 South Lantau Road (AM4) Operator: Date: Next Due Date: 5-Jun-09 6-Apr-09 Equipment No.: A-01-06 10576 Serial No. **Ambient Condition** 290.5 764.6 Temperature, Ta (K) Pressure, Pa (mmHg) Orifice Transfer Standard Information A-04-06 Slope, mc 0.0575 Intercept, be 0.0395 Equipment No.: me x Qstd + be = $[\Delta H \times (Pa/760) \times (298/Ta)]^{1/2}$ Last Calibration Date: 6-Mar-09 Qstd = $\{ [\Delta H \times (Pa/760) \times (298/Ta)]^{1/2} -bc \} / mc$ Next Calibration Date: 5-Mar-10 Calibration of TSP Sampler Orfice HVS Calibration Qstd (CFM) [ΔW x (Pa/760) x (298/Ta)]^{1/2} ΔW ΔH (orifice), [ΔH x (Pa/760) x (298/Γa)]^{1/2} Point in. of water X - axis (HVS), in. of oil Y-axis 2.82 3.43 58.97 11.4 7.7 1 3.03 52.02 6.2 2.53 2 8.9 3 7.4 2.76 47.37 5.1 2.29 4 2.34 39.99 3.2 1.82 5.3 5 29.91 1.8 1.36 3.0 1.76 By Linear Regression of Y on X Slope, mw = 0.0516 Intercept, bw : -0.1924 Correlation coefficient* = *If Correlation Coefficient < 0.990, check and recalibrate. Set Point Calculation From the TSP Field Calibration Curve, take Qstd = 43 CFM From the Regression Equation, the "Y" value according to mw x Qstd + bw = $[\Delta W \times (Pa/760) \times (298/Ta)]^{1/2}$ Therefore, Set Point; W = $(mw \times Qstd + bw)^2 \times (760 / Pa) \times (Ta / 298) =$ 3.98 Remarks: Conducted by: 100 CHING HANG Signature: Checked by: 4 Signature: Date: Date:

High-Volume TSP Sampler 5-POINT CALIBRATION DATA SHEET

CINOTECH

File No. MA6030/AM4/0017 CH Operator: No. 31 South Lantau Road (AM4) Station Next Due Date: 4-Aug-09 Date: 5-Jun-09 10576 Equipment No.: A-01-06 Serial No. **Ambient Condition** 754.4 Temperature, Ta (K) 303 Pressure, Pa (mmHg) Orifice Transfer Standard Information 0.0395 0.0575 Intercept, be A-04-06 Slope, mc Equipment No.: me x Qstd + be = $[\Delta H \times (Pa/760) \times (298/Ta)]^{1/2}$ 6-Mar-09 Last Calibration Date: Qstd = $\{ [\Delta H \times (Pa/760) \times (298/Ta)]^{1/2} - bc \} / mc$ Next Calibration Date: 5-Mar-10 Calibration of TSP Sampler HVS Orfice Calibration [AW x (Pa/760) x (298/Ta)]1/2 ΔW Qstd (CFM) ΔH (orifice), [ΔH x (Pa/760) x (298/Ta)]^{1/2} Point (HVS), in. of oil Y-axis X - axis in, of water 2.81 58.84 8.1 12.0 3.42 2.56 3.09 53.11 6.7 9.8 2,25 46.68 5.2 2.72 3 7.6 1.79 2,30 39.24 3.3 5.4 1.9 1,36 30.05 1.77 3.2 By Linear Regression of Y on X Slope , mw = _______0.0514 Intercept, bw : -0.1853 Correlation coefficient* = 0.9986 *If Correlation Coefficient < 0.990, check and recalibrate. Set Point Calculation From the TSP Field Calibration Curve, take Qstd = 43 CFM From the Regression Equation, the "Y" value according to mw x Qstd + bw = $|\Delta W \times (Pa/760) \times (298/\Gamma a)|^{1/2}$ Therefore, Set Point; $W = (mw \times Qstd + bw)^2 \times (760 / Pa) \times (Ta / 298) =$ Remarks: Date: 5/6/09
Date: 5 June 2009 Conducted by: 40 and signature: 4. Signature: 4.





APPLICANT: **Cinotech Consultants Limited**

Room 1710, Technology Park,

18 On Lai Street,

Shatin, NT, Hong Kong

Test Report No.: C/09/90430 Date of Issue: 2009-05-02 Date Received: 2009-04-30 Date Tested: 2009-04-30

Date Completed: 2009-05-01

Next Due Date:

2010-05-01

ATTN:

Mr. Henry Leung

Page:

1 of 1

Certificate of Calibration

Item for calibration:

Description

: RS232 Integral Vane Digital Anemometer

Manufacturer

: AZ Instrument

Model No.

: 451104

Serial No.

: 9020746

Equipment No.

: A-03-01

Test conditions:

Room Temperature

: 21 degree Celsius

Relative Humidity

: 67%

Pressure

: 101.5 kPa

Methodology:

The anemometer has been calibrated in accordance with the documented procedures and using standard(s) and instrument(s) which are recommended by the manufacturer, or equivalent.

Results:

	Reference Set Point	Instrument Readings
Measuring Air Velocity, m/s	2.00	2.00
Temperature, °C	21.0	21.0

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE



TISCH ENVIROMENTAL, INC. 145 SOUTH MIAMI AVE. VILLAGE OF CLEVES, OH 45002 513.467,9000 877.283.7610 TOLL FREE 513.467,9009 FAX WWW.TISCH-ENV.COM

AIR POLLUTION MONITORING EQUIPMENT

ORIFICE TRANSFER STANDARD CERTIFICATION WORKSHEET TE-5025A

	*	**********	:=====================================	* ** * * * * * * * * * * * * * * * *	METER	ORFICE
CLATE	VOLUME	VOLUME	DIFF	DIFF	DIFF Hg (mm)	DIFF
OR	START	STOP	VOLUME	TIME		H20
on #	(m3)	(m3)	(m3)	(min)		(in.)
1 2	AN AN	NA NA	1.00	1.3890	3.2	2,0
3	NA	NA	1.00	0.8810	7.8	5.0
4	NA	NA		0.8410	8.6	5.5
5	NA	NA		0.6950	12.5	8.0

DATA TABULATION

Vstd	(x axis) Qstd	(y axis)	Va	(x axis) Qa	(y axis)
0,9917 0,9876 0,9854 0,9844 0,9792	0.7139 1.0026 1.1185 1.1706 1.4090	1.4113 1.9959 2.2315 2.3405 2.8227	0.9957 0.9916 0.9894 0.9884 0.9832	0.7168 1.0067 1.1231 1.1753 -1.4147	0.8874 1.2549 1.4030 1.4715 1.7747
Cstd slop intercept coefficie	t (b) = ent (r) =	2.03154 -0.03970 0.99999 Pa/760) (298/Ta)}	Qa slop intercep coeffici	t (b) =	1.27212 -0.02496 0.99999

CALCULATIONS

Vstd = Diff. Vol((Pa-Diff. Hg)/760)(298/Ta)
Qstd = Vstd/Time

Va = Diff Vol [(Pa-Diff Hg)/Pa]
Qa = Va/Time


For subsequent flow rate calculations:

Qstd = $1/m\{[SQRT(H2O(Pa/760)(298/Ta))] - b\}$ Qa = $1/m\{[SQRT H2O(Ta/Pa)] - b\}$



TISCH ENVIROMENTAL, INC. 145 SOUTH MIAMI AVE. VILLAGE OF CLEVES, OH 45002 513.467.9000 877.263.7610 TOLL FREE 513.467.9009 FAX WWW.TISCH-ENV.COM

AIR POLLUTION MONITORING EQUIPMENT



y-axis equations;

Ostd series:

$$\sqrt{\Delta H \left(\frac{Pa}{Pstd}\right) \left(\frac{Tstd}{Ta}\right)}$$

Qa series:

$$\sqrt{(\Delta H (Ta/Pa))}$$



Rms 816, 1516 & 1701, Technology Park 18 On Lai Street, Stattu, N T., Hong Kong Tel: 2898 7388 Fax: 2898 7076 Website, http://www.wellab.com.lik E-mail: wellab@wellab.com.lik

TEST REPORT

APPLICANT: Cinotech Consultants Limited

Room 1710, Technology Park,

18 On Lai Street,

Shatin, NT, Hong Kong

Test Report No.: C/N/81215/1
Date of Issue: 2008-12-16
Date Received: 2008-12-15
Date Tested: 2008-12-15
Date Completed: 2008-12-16
Next Due Date: 2009-12-15

ATTN:

Mr. Henry Leung

Page:

1 of 1

Certificate of Calibration

Item for calibration:

Description

: Integrating Sound Level Meter

Manufacturer Model No.

: Brüel & Kjær : B&K 2238

Serial No.
Microphone No.

: 2337665 : 2289749

Equipment No.

: N-01-01

Test conditions:

Room Temperatre

: 20 degree Celsius

Relative Humidity

: 60%

Test Specifications:

Performance checking at 94 and 114 dB

Methodology:

In-house method, according to manufacturer instruction manual

Results:

Reference Set Point, dB	Instrument Readings, dB
94	94.0
114	114.0

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE



Room 1516 & 816, Technology Park 18 On Lai Street, Shatin, N.T., Hong Kong Tel: 2898 7338 Fay: 2898 7076 Websile http://www.wellab.com.hk E-mail: wellab@wellab.com.hk

TEST REPORT

APPLICANT: Cinotech Consultants Limited

Room 1710, Technology Park,

18 On Lai Street,

Shatin, NT, Hong Kong

Test Report No.: C/N/80903-1

Date of Issue: 2008-09-03

Date Received: 2008-09-02 Date Tested: 2008-09-02

Date Tested: 2008-09-02

Date Completed: 2008-09-03

Next Due Date:

2008-09-03

ATTN:

Mr. Henry Leung

Page:

1 of 1

Certificate of Calibration

Item for calibration:

Description

: Integrating Sound Level Meter

Manufacturer

: Brüel & Kjær

Model No.

: B&K 2238

Serial No.

: 2359311

Microphone No.

: 2346382

Equipment No.

: N-01-03

Test conditions:

Room Temperatre

: 21 degree Celsius

Relative Humidity

: 61%

Test Specifications:

Performance checking at 94 and 114 dB

Methodology:

In-house method, according to manufacturer instruction manual

Results:

Reference Set Point, dB	Instrument Readings, dB
94	94.0
114	114.0

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE



APPLICANT: Cinotech Consultants Limited

Room 1710, Technology Park,

18 On Lai Street,

Shatin, NT, Hong Kong

Test Report No.: C/N/80903-2

Date of Issue: 2008-09-03 Date Received: 2008-09-02

Date Tested: 2008-09-02

Date Completed: 2008-09-03

Next Due Date:

2009-09-02

ATTN:

Mr. Henry Leung

Page:

1 of 1

Certificate of Calibration

Item for calibration:

Description

: Integrating Sound Level Meter

Manufacturer

: Brüel & Kjær

Model No.

: B&K 2238 : 2359303

Serial No. Equipment No.

: N-01-04

Test conditions:

Room Temperatre

: 21 degree Celsius

Relative Humidity

: 61%

Test Specifications:

Performance checking at 94 and 114 dB

Methodology:

In-house method, according to manufacturer instruction manual

Results:

Reference Set Point, dB	Instrument Readings, dB
94	94.0
114	114.0

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE



Room 1516 & 816, Technology Park 18 On Lai Street, Shatin, N.T., Hong Kong Tel: 2898 7388 Fax: 2898 7076 Website: http://www.wellab.com.hk E-mail: wellab@wellab.com.lik

TEST REPORT

APPLICANT: Cinotech Consultants Limited

Room 1710, Technology Park,

18 On Lai Street,

Shatin, NT, Hong Kong

Test Report No.:	C/N/81013/1
Date of Issue:	2007-10-15
Date Received:	2008-10-13
Date Tested:	2008-10-13
Date Completed:	2008-10-14
Next Due Date:	2009-10-14

ATTN:

Mr. Henry Leung

Page:

1 of 1

Certificate of Calibration

Item for calibration:

: Integrating Sound Level Meter Description

: Brüel & Kjær Manufacturer : B&K 2238 Model No. : 2394976 Serial No. Microphone No. : 2407349 Equipment No. : N-01-05

Test conditions:

: 21 degree Celsius Room Temperatre

Relative Humidity : 60%

Test Specifications:

Performance checking at 94 and 114 dB

Methodology:

In-house method, according to manufacturer instruction manual

Results:

Reference Set Point, dB	Instrument Readings, dB	
94	94.0	
114	114.0	

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

Laboratory Manager

This report may not be reproduced except with prior written approval from WELLAB LIMITED and the results relate only to the items calibrated or tested,



Room 1516 & 816, Technology Park 18 On Lai Street, Shatin, N.T., Hong Kong. Tel: 2898 7388 Fax: 2898 7076 Website http://www.wellab.com.hk E-mail: wellab@wellab.com.hk

TEST REPORT

APPLICANT:

Cinotech Consultants Limited

Room 1710, Technology Park,

18 On Lai Street,

Shatin, NT, Hong Kong

C/N/81115/1 Test Report No.: Date of Issue: 2008-11-15 Date Received: 2008-11-14 Date Tested: 2008-11-14 Date Completed: 2008-11-15

Page:

Next Due Date:

1 of 1

2009-11-14

ATTN:

Mr. Henry Leung

Item for calibration:

Description

: Acoustical Calibrator

Manufacturer

: Brüel & Kjær

Model No.

: 4231

Serial No.

: 2326353

Project No.

: C13

Equipment No.

: N-02-01

Test conditions:

Room Temperatre

: 20 degree Celsius

Relative Humidity

: 59%

Pressure

: 1015.2 hPa

Methodology:

The sound calibrator has been calibrated in accordance with the documented procedures and using standard(s) and instrument(s) which are recommended by the manufacturer, or equivalent.

Results:

Sound Pressure Level	Measured SPL	Tolerance
At 94 dB SPL	94.0	94.0 ± 0.1 dB

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE Laboratory Manager

This report may not be reproduced except with prior written approval from WELLAB LIMITED and the results relate only to the items calibrated or tested.





Rms 816, 1516 & 1701, Technology Park 18 On Lai Street, Shatin, N.T., Hong Kong Tel: 2898-7388 Fax: 2898-7076 Website: http://www.wellab.com.hk B-mail: wellab@wellab.com.hk

TEST REPORT

APPLICANT: Cinotech Consultants Limited

Room 1710, Technology Park,

18 On Lai Street,

Shatin, NT, Hong Kong

Test Report No.:	C/06/90305
Date of Issue:	2009-03-05
Date Received:	2009-03-04
Date Tested:	2009-03-04
Date Completed:	2009-03-05
Next Due Date:	2010-03-04

ATTN:

Mr. Henry Leung

Page:

1 of 1

Item for calibration:

Description

: Acoustical Calibrator

Manufacturer

: Brüel & Kjær

Model No.
Serial No.
Project No.

: 4231 : 2343007

Project No. Equipment No.

: C13 : N-02-02

Test conditions:

Room Temperatre

: 20 degree Celsius

Relative Humidity

: 65%

Pressure

: 1020.1hPa

Methodology:

The sound calibrator has been calibrated in accordance with the documented procedures and using standard(s) and instrument(s) which are recommended by the manufacturer, or equivalent.

Results:

Sound Pressure Level	Measured SPL	Tolerance
At 94 dB SPL	94.0	$94.0 \pm 0.2 \text{ dB}$

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

This report may not be reproduced except with prior written approval from WELLAB LIMITED and the results relate only to the items calibrated or tested.



APPLICANT:

Cinotech Consultants Limited

Room 1710, Technology Park,

18 On Lai Street,

Shatin, NT, Hong Kong

Test Report No.:	C/N/80903-3	
Date of Issue:	2008-09-03	
Date Received:	2008-09-02	
Date Tested:	2008-09-02	
Date Completed:	2008-09-03	
Next Due Date:	2009-09-02	

ATTN:

Mr. Henry Leung

Page:

1 of 1

Item for calibration:

Description

: Acoustical Calibrator

Manufacturer

: Brüel & Kjær

Model No.

: 4231

Serial No.

: 2412367

Equipment No.

: N-02-03

Test conditions:

Room Temperatre

: 21 degree Celsius

Relative Humidity

: 61%

Methodology:

The Sound Level Calibrator has been calibrated in accordance with the documented procedures and using standard(s) and instrument(s) which are recommended by the manufacturer, or equivalent.

Results:

Sound Pressure Level (1kHz)	Measured SPL	Tolerance
At 94 dB SPL	94.0	94.0 ± 0.1 dB
At 114 dB SPL	114.0	114.0 ± 0.1 dB

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

This report may not be reproduced except with prior written approval from WELLAB LIMITED and the results relate only to the items calibrated or tested.



Room 1516 & 816, Technology Park 18 On Lai Steet, Shatin, N.T., Hong Kong Tel. 2898 7388 Fav. 2898 7076 Website: http://www.wellab.com.hk B-mail_wellab@wellab.com.hk

TEST REPORT

APPLICANT: Cinotech Consultants Limited

Room 1710, Technology Park,

18 On Lai Street,

Shatin, NT, Hong Kong

Test Report No.: C/W/90430-1
Date of Issue: 2009-05-04
Date Received: 2009-04-30
Date Tested: 2009-04-30
Date Completed: 2009-04-30
Next Due Date: 2009-08-03

ATTN:

Mr. Henry Leung

Page:

1 of 2

Certificate of Calibration

Item for calibration:

Description : Sonde Environmental Monitoring System

Manufacturer

er : YSI

Model No. Serial No. : 6820-C-M : 02D0126AA

Equipment No. Project No.

: W.03.01 : C013

Test conditions:

Room Temperature

: 23 degree Celsius

Relative Humidity

: 63%

Test Specifications:

Conductivity & Salinity Sensor, Model: 6560, S/N: 05A1209

- 1. Conductivity performance check with Potassium Chloride standard solution
- 2. Salinity performance check with Sodium Chloride standard solution

Dissolved Oxygen Sensor, Model: 6562, S/N: 04A0145

1. Performance check against Winkler titration

Turbidity Sensor, Model: 6136, S/N: 05A1610AJ

1. Calibration check with Formazin standard solution

pH Meter, Model: 6561, S/N: 01J

1. Calibration check with standard pH buffer

Depth Meter

1. Calibration check at 1m water level depth

Methodologies:

- 1. YSI 6-Series Sonde Environmental Monitoring System Instruction Manual
- 2. In-house method with reference to APHA and ISO standards

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE



Test Report No.:	C/W/90430-1
Date of Issue:	2009-05-04
Date Received:	2009-04-30
Date Tested:	2009-04-30
Date Completed:	2009-04-30
Next Due Date:	2009-08-03

Page:

2 of 2

Results:

1. Conductivity performance check

Specific Conductivity, µS/cm		Correction, µS/cm	Acceptable range
Salinity Meter (C1)	Theoretical Value (C2)	D = C1 - C2	
1421	1420	2	1420 ± 20

2. Salinity Performance check

Salinity, ppt		Correction, ppt	Acceptable range
Instrument Reading	Theoretical Value		
30.0	30.0	0.0	30.0 ± 3

3. Dissolved Oxygen check

Oxygen level in	Dissolved Oxygen, mg O ₂ /L		Correction, mg	Acceptable
water at 20°C	D.O. Meter	Winkler Titration	O ₂ /L	range
Saturated	9.1	9.1	0.0	± 0.2
Half-saturated	5.6	5.6	0.0	± 0.2
Zero	0.0	0.0	0.0	± 0.2

4. Turbidity check

Turbidity value in solution, NTU	Calibration Value, NTU	Correction, NTU	Acceptable range
0.00	0.00	0.00	0.00 ± 0.05
100	100	0	100 ± 5

5. pH Meter check

Test Parameters	Performance characteristic	Acceptable range
Liquid junction error ΔpH _i , pH unit	0.01	Less than 0.05
Shift on stirring ΔpH _s , pH unit	0.01	Less than 0.02
Noise ΔpH _n , pH unit	0.00	Less than 0.02

6. Depth Meter check

Instrument Reading, m	Calibration Value, m	Correction, m	Acceptable range
1,0	1.00	0.00	1.00 ± 0.05



APPLICANT: Cinotech Consultants Limited

Room 1710, Technology Park,

18 On Lai Street,

Shatin, NT, Hong Kong

Test Report No.:	C/W/90430-2	
Date of Issue:	2009-05-04	
Date Received:	2009-04-30	
Date Tested:	2009-04-30	
Date Completed:	2009-04-30	
Next Due Date:	2009-08-03	

ATTN:

Mr. Henry Leung

Page:

1 of 2

Certificate of Calibration

Item for calibration:

Description

: Sonde Environmental Monitoring System

Manufacturer

; YSI

Model No.

: 6820-C-M

Serial No.

: 02D0293AA : W.03.02

Equipment No. Project No.

: C013

Test conditions:

Room Temperature

: 23 degree Celsius

Relative Humidity

: 63%

Test Specifications:

Conductivity & Salinity Sensor, Model: 6560, S/N: 02C0886

- 1. Conductivity performance check with Potassium Chloride standard solution
- 2. Salinity performance check with Sodium Chloride standard solution

Dissolved Oxygen Sensor, Model: 6562, S/N: 0261137

1, Performance check against Winkler titration

Turbidity Sensor, Model: 6136, S/N: 05F2030AQ

1. Calibration check with Formazin standard solution

pH Meter, Model: 6561, S/N: 02A

1. Calibration check with standard pH buffer

Depth Meter

1. Calibration check at 1m water level depth

Methodologies:

- 1. YSI 6-Series Sonde Environmental Monitoring System Instruction Manual
- 2. In-house method with reference to APHA and ISO standards

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE



Test Report No.: C/W/90430-2
Date of Issue: 2009-05-04
Date Received: 2009-04-30
Date Tested: 2009-04-30
Date Completed: 2009-04-30
Next Due Date: 2009-08-03

Page:

2 of 2

Results:

1. Conductivity performance check

Specific Conductivity, µS/cm Salinity Meter (C1) Theoretical Value (C2)		Correction, µS/cm	Acceptable range	
		D = C1 - C2		
1420	1420	0	1420 ± 20	

2. Salinity Performance check

Salinity, ppt		Correction, ppt	Acceptable range
Instrument Reading	Theoretical Value	5	41
30.1	30.0	0.1	30.0 ± 3

3. Dissolved Oxygen check

Oxygen level in	Dissolved O	xygen, mg O ₂ /L	Correction, mg	Acceptable
water at 20°C	D.O. Meter	Winkler Titration	O ₂ /L	range
Saturated	9.0	9.0	0.0	± 0.2
Half-saturated	5.8	5.8	0.0	± 0.2
Zero	0.0	0.0	0.0	± 0.2

4. Turbidity check

Turbidity value in solution, NTU	Calibration Value, NTU	Correction, NTU	Acceptable range
0.00	0.00	0.00	0.00 ± 0.05
100	100	0	100 ± 5

5. pH Meter check

Test Parameters	Performance characteristic	Acceptable range	
Liquid junction error ΔpH _i , pH unit	0.01	Less than 0.05	
Shift on stirring ΔpH_s , pH unit	0.01	Less than 0.02	
Noise ΔpH _n , pH unit	0.01	Less than 0.02	

6. Depth Meter check

Instrument Reading, m	Calibration Value, m	Correction, m	Acceptable range
1.0	1.00	0.00	1.00 ± 0.05

APPENDIX C ENVIRONMENTAL MONITORING SCHEDULES

Contract No. HY/2003/19 - Improvement to Tung chung Road between Lung Tseng Tau and Cheung Sha Tentative Air, Noise and Water Quality Monitoring Schedule for June 2009

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
31-五月	1-六月	2-六月	3-六月	4-六月	5-六月	6-六月
	Water Quality		Water Quality Noise	24 hr TSP	Water Quality	
7-六月	8-六月	9-六月	10-六月	11-六月	12-六月	13-六月
	Water Quality		Water Quality Noise 24 hr TSP		Water Quality	
14-六月	15-六月	16-六月	17-六月	18-六月	19-六月	20-六月
	Water Quality	24 hr TSP	Water Quality Noise		Water Quality	
21-六月	22-六月	23-六月	24-六月	25-六月	26-六月	27-六月
	Water Quality 24 hr TSP		Water Quality Noise		Water Quality	24 hr TSP
28-六月	29-六月	30-六月	1-七月	2-七月	3-七月	4-七月
	Water Quality	Water Quality Noise				

The schedule may be changed due to unforeseen circumstances (adverse weather, etc)

Remarks: * Construction Noise Levels will be monitored when construction works perform at 19:00 - 23:00 and within a radius of 300m from the noise monitoring locaitons.

Contract No. HY/2003/19 - Improvement to Tung chung Road between Lung Tseng Tau and Cheung Sha Tentative Air, Noise and Water Quality Monitoring Schedule for July 2009

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
			1-七月	2-七月	3-七月	4-七月
					Water Quality	
					24 hr TSP	
5-七月	6-七月	7-七月	8-七月	9-七月	10-七月	11-七月
	Water Quality		Water Quality Noise	24 hr TSP	Water Quality	
12-七月	13-七月	14-七月	15-七月	16-七月	17-七月	18-七月
	Water Quality		Water Quality Noise 24 hr TSP		Water Quality	
19-七月	20-七月	21-七月	22-七月	23-七月	24-七月	25-七月
	Water Quality	24 hr TSP	Water Quality Noise		Water Quality	
26-七月	27-七月	28-七月	29-七月	30-七月	31-七月	1-八月
	Water Quality 24 hr TSP		Water Quality Noise		Water Quality	

The schedule may be changed due to unforeseen circumstances (adverse weather, etc)

Remarks: * Construction Noise Levels will be monitored when construction works perform at 19:00 - 23:00 and within a radius of 300m from the noise monitoring locaitons.

APPENDIX D 24-HOUR TSP MONITORING RESULTS ,GRAPHICAL PRESENTATION AND WIND DATA

Appendix D - 24-hour TSP Monitoring Results

Location AM1 - YMCA of Hong Kong Christian College

Date	Filter W	eight (g)	Flow Rate	e (m³/min.)	Elaps	se Time	Sampling	Conc.	Weather	Air	Atmospheric	Particulate	Av. flow	Total vol.
	Initial	Final	Initial	Final	Initial	Final	Time(hrs.)	(µg/m ³)	Condition	Temp. (K)	Pressure(Pa)	weight(g)	(m ³ /min)	(m ³)
4-Jun-09	2.7666	2.8130	1.19	1.19	5189.7	5213.7	24.0	27.1	Cloudy	299.3	752.6	0.0464	1.19	1714.3
10-Jun-09	2.8385	2.8747	1.22	1.22	5213.7	5237.7	24.0	20.6	Cloudy	301.1	757.8	0.0362	1.22	1753.5
16-Jun-09	2.7975	2.8554	1.22	1.22	5237.7	5261.7	24.0	32.9	Cloudy	299.2	758.4	0.0579	1.22	1759.0
22-Jun-09	2.8195	2.9002	1.21	1.21	5261.7	5285.7	24.0	46.2	Cloudy	303.2	755.1	0.0807	1.21	1745.4
27-Jun-09	2.8908	2.9442	1.22	1.22	5285.7	5309.7	24.0	30.4	Cloudy	299.7	755.1	0.0534	1.22	1754.3
			-				Min	20.6						
							Max	46.2						
							Average	31.5						


Location AM2 - House in Leyburn Villas


Date	Filter W	eight (g)	Flow Rate	(m³/min.)	Elaps	e Time	Sampling	Conc.	Weather	Air	Atmospheric	Particulate	Av. flow	Total vol.
	Initial	Final	Initial	Final	Initial	Final	Time(hrs.)	$(\mu g/m^3)$	Condition	Temp. (K)	Pressure(Pa)	weight(g)	(m ³ /min)	(m ³)
4-Jun-09	2.8543	2.8954	1.20	1.20	9983.3	10007.3	24.0	23.8	Cloudy	299.3	752.6	0.0411	1.20	1726.3
10-Jun-09	2.8106	2.8604	1.22	1.22	10007.3	10031.3	24.0	28.3	Cloudy	301.1	757.8	0.0498	1.22	1762.2
16-Jun-09	2.8221	2.8602	1.23	1.23	10031.3	10055.3	24.0	21.5	Cloudy	299.2	758.4	0.0381	1.23	1768.1
22-Jun-09	2.7904	2.8340	1.22	1.22	10055.3	10079.3	24.0	24.9	Cloudy	303.2	755.1	0.0436	1.22	1753.5
27-Jun-09	2.8709	2.9102	1.22	1.22	10079.3	10103.3	24.0	22.3	Cloudy	299.7	755.1	0.0393	1.22	1763.1
							Min	21.5						
							Max	28.3						
							Average	24.2						


Location AM4 - No.31 South Lantau Road

Date	Filter W	eight (g)	Flow Rate	e (m³/min.)	Elaps	e Time	Sampling	Conc.	Weather	Air	Atmospheric	Particulate	Av. flow	Total vol.
	Initial	Final	Initial	Final	Initial	Final	Time(hrs.)	$(\mu g/m^3)$	Condition	Temp. (K)	Pressure(Pa)	weight(g)	(m ³ /min)	(m ³)
4-Jun-09	2.8584	2.9221	1.19	1.19	9838.5	9862.5	24.0	37.0	Cloudy	299.3	752.6	0.0637	1.19	1720.3
10-Jun-09	2.7868	2.8689	1.22	1.22	9862.5	9886.5	24.0	46.6	Cloudy	301.1	757.8	0.0821	1.22	1761.0
16-Jun-09	2.8512	2.8932	1.23	1.23	9886.5	9910.5	24.0	23.8	Cloudy	299.2	758.4	0.0420	1.23	1766.7
22-Jun-09	2.8846	2.9552	1.22	1.22	9910.5	9934.5	24.0	40.3	Cloudy	303.2	755.1	0.0706	1.22	1752.5
27-Jun-09	2.8739	2.9334	1.22	1.22	9934.5	9958.5	24.0	33.8	Cloudy	299.7	755.1	0.0595	1.22	1761.9
	-		-				Min	23.8						-
							Max	46.6						
							Average	36.3						

24-hour TSP Levels









Title	Contract No. HY/2003/19
	Improvement to Tung Chung Road between Lung Tseng Tau and
	Cheung Sha
	Graphical Presentation of 24-hour TSP Monitoring Results


Scale		Project
	N.T.S	No. MA6030
Date		Appendix
	Jun 09	D







Wind Data (HK International Airport)




Title


Contract No. HY/2003/19
Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha


Wind Data Extracted from the Hong Kong Observatory (HK International Airport)

Scale		Project	
	N.T.S	No.	MA6030
Date		Append	iv
Date		Append	IX









cen

⑥ 香港天文台 Hong Kong Observatory

Title

Contract No. HY/2003/19
Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha

Wind Data Extracted from the Hong Kong Observatory (Cheung Chau)

Scale		Project	
	N.T.S	No.	MA6030
Date		Append	ix
	Jun 09		D



APPENDIX E NOISE MONITORING RESULTS AND GRAPHICAL PRESENTATION

Appendix E - Noise Monitoring Results

Location NM1 - No. 28 Lung Tseng Tau										
Dete	Times	\\/aatbar	dB (A) (30-min)							
Date	Time	Weather	L _{eq}	L ₁₀	L 90					
3-Jun-09	09:40	Cloudy	64.3	66.5	61.0					
10-Jun-09	09:40	Fine	64.2	66.0	61.0					
17-Jun-09	09:40	Fine	63.5	65.5	60.5					
24-Jun-09	09:40	Fine	63.6	66.0	61.0					
30-Jun-09	09:40	Fine	63.2	65.5	60.0					
		Average	63.8	65.9	60.7					
		Minimum	63.2	65.5	60.0					
		Maximum	64.3	66.5	61.0					

Location NM2	Location NM2 - YMCA of HK Christian College										
Data	Time	\\/ootbox	dB (A) (30-min)								
Date	Time	Weather	L _{eq}	L ₁₀	L 90						
3-Jun-09	09:00	Cloudy	52.3	54.5	49.5						
10-Jun-09	09:00	Fine	53.1	54.5	50.5						
17-Jun-09	09:00	Fine	52.1	54.0	49.5						
24-Jun-09	09:00	Fine	51.8	52.5	48.0						
30-Jun-09	09:00	Fine	52.2	55.0	50.0						
		Average	52.3	54.2	49.6						
		Minimum	51.8	52.5	48.0						
		Maximum	53.1	55.0	50.5						

Location NM3 - No. 37 Shek Lau Po										
Data	Time	\\/aathar	dB (A) (30-min)							
Date	Time	Weather	L _{eq}	L ₁₀	L 90					
3-Jun-09	10:20	Cloudy	40.0	41.0	39.0					
10-Jun-09	10:20	Fine	40.1	41.0	39.0					
17-Jun-09	10:20	Fine	40.0	41.0	39.0					
24-Jun-09	10:20	Fine	40.1	41.5	39.0					
30-Jun-09	10:20	Fine	40.2	41.5	39.5					
-		Average	40.1	41.2	39.1					
		Minimum	40.0	41.0	39.0					
		Maximum	40.2	41.5	39.5					

Location NM4 - No.1 Shek Mun Kap										
D-4-	Ti	\\\	dB (A) (30-min)							
Date	Time	Weather	L _{eq}	L ₁₀	L 90					
3-Jun-09	11:00	Cloudy	52.6	54.5	48.5					
10-Jun-09	11:00	Fine	52.6	54.5	50.0					
17-Jun-09	11:00	Fine	51.5	53.5	49.0					
24-Jun-09	11:00	Fine	51.3	52.5	48.0					
30-Jun-09	11:00	Fine	51.2	52.5	49.0					
		Average	51.9	53.6	49.0					
		Minimum	51.2	52.5	48.0					
		Maximum	52.6	54.5	50.0					


Appendix E - Noise Monitoring Results


Location NM5	Location NM5 - Tung Chung Au Country Parks Management Centre										
Dete	Times	\\/aathar	dB (A) (30-min)								
Date	Time	Weather	L _{eq}	L ₁₀	L 90						
3-Jun-09	13:00	Cloudy	51.2	52.5	48.0						
10-Jun-09	13:00	Fine	51.2	52.5	48.5						
17-Jun-09	13:00	Fine	51.1	52.5	48.0						
24-Jun-09	13:00	Fine	51.7	52.5	47.5						
30-Jun-09	13:00	Fine	50.8	52.0	48.0						
		Average	51.2	52.4	48.0						
		Minimum	50.8	52.0	47.5						
		Maximum	51.7	52.5	48.5						


Location NM6	- D75 Leybu	ırn Villa			
Data	Time	\A/a atla an	dB	3 (A) (30-min))
Date	Time	Weather	L _{eq}	L ₁₀	L 90
3-Jun-09	13:45	Cloudy	39.6	41.0	38.5
10-Jun-09	13:45	Fine	39.8	41.0	39.0
17-Jun-09	13:45	Fine	40.2	41.5	39.5
24-Jun-09	13:45	Fine	40.0	41.0	39.0
30-Jun-09	13:45	Fine	40.0	41.0	39.0
		Average	39.9	41.1	39.0
		Minimum	39.6	41.0	38.5
		Maximum	40.2	41.5	39.5

Location NM8	- No. 31 Sou	ıth Lantau Roa	ad		
Data	Time	\A/a atla an	dB	3 (A) (30-min))
Date	Time	Weather	L _{eq}	L ₁₀	L 90
3-Jun-09	14:25	Cloudy	61.7	63.5	58.5
10-Jun-09	14:25	Fine	61.3	63.5	58.5
17-Jun-09	14:25	Fine	61.7	63.5	58.5
24-Jun-09	14:25	Fine	61.1	62.5	58.0
30-Jun-09	14:25	Fine	60.7	62.5	58.5
		Average	61.3	63.1	58.4
		Minimum	60.7	62.5	58.0
		Maximum	61.7	63.5	58.5

Noise Levels







Title Contract No. HY/2003/19
Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha
Graphical Presentation of Construction Noise Monitoring

Results


 Scale
 Project No.


 N.T.S
 MA6030


 Date
 Appendix

Jun 09

CINOTECH








litie	Contract No. HY/2003/19
	Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha
	Graphical Presentation of Construction Noise Monitoring

Results

Scale		Droject	
Scale		Project	
	N.T.S	No. MA6030)
Date		Appendix	
	Jun 09	E	



Noise Levels



Title

Contract No. HY/2003/19

Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha

Graphical Presentation of Construction Noise Monitoring Results

Scale		Project	
	N.T.S	No.	MA6030

Date Appendix
Jun 09 E



APPENDIX F
WATER QUALITY MONITORING
RESULTS AND GRAPHICAL
PRESENTATION

Water Quality Monitoring Results at 15_I

Date	Weather	Sea	Sampling	Dept	h (m)	Tempera	ature (°C)	р	Н	Salin	ity ppt	DO Satu	ration (%)	Dissolved O	kygen (mg/L)	Turbidi	ty(NTU)	Suspended	Solids (mg/L
Date	Condition	Condition*	Time	Бері	11 (111)	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average
1-Jun-09	Sunny	Calm	13:00	Middle	0.09	19.1 19.2	19.2	7.5 7.5	7.5	0.02 0.02	0.02	96.2 96.0	96.1	7.6 7.6	7.6	1.9 1.9	1.9	<2.5 <2.5	<2.5
3-Jun-09	Cloudy	Calm	11:42	Middle	0.09	19.1 19.1	19.1	7.5 7.5	7.5	0.02 0.02	0.02	94.9 94.7	94.8	7.6 7.6	7.6	1.7 1.7	1.7	<2.5 <2.5	<2.5
5-Jun-09	Sunny	Calm	11:53	Middle	0.09	19.1 19.1	19.1	7.5 7.5	7.5	0.02 0.02	0.02	95.6 95.4	95.5	7.6 7.6	7.6	1.6 1.6	1.6	<2.5 <2.5	<2.5
8-Jun-09	Cloudy	Calm	12:20	Middle	0.09	19.1 19.1	19.1	7.5 7.5	7.5	0.02 0.02	0.02	96.8 96.6	96.7	7.7 7.6	7.7	1.7 1.7	1.7	<2.5 <2.5	<2.5
10-Jun-09	Cloudy	Calm	11:46	Middle	0.09	19.1 19.1	19.1	7.5 7.5	7.5	0.02 0.02	0.02	96.3 96.1	96.2	7.6 7.6	7.6	1.6 1.6	1.6	<2.5 <2.5	<2.5
12-Jun-09	Cloudy	Calm	11:41	Middle	0.09	19.0 19.0	19	7.5 7.5	7.5	0.02 0.02	0.02	95.5 95.3	95.4	7.6 7.6	7.6	1.7 1.7	1.7	<2.5 <2.5	<2.5
15-Jun-09	Cloudy	Calm	12:02	Middle	0.09	19.1 19.1	19.1	7.5 7.5	7.5	0.02 0.02	0.02	96.6 96.4	96.5	7.7 7.6	7.7	1.6 1.6	1.6	<2.5 <2.5	<2.5
17-Jun-09	Sunny	Calm	11:36	Middle	0.09	19.0 19.1	19.1	7.5 7.5	7.5	0.02 0.02	0.02	95.8 95.6	95.7	7.6 7.6	7.6	1.7 1.7	1.7	<2.5 <2.5	<2.5
19-Jun-09	Cloudy	Calm	11:52	Middle	0.09	19.0 19.0	19	7.6 7.5	7.6	0.02 0.02	0.02	96.7 96.5	96.6	7.7 7.6	7.7	1.6 1.7	1.7	<2.5 <2.5	<2.5
22-Jun-09	Cloudy	Calm	12:13	Middle	0.09	19.0 19.0	19	7.5 7.5	7.5	0.02 0.02	0.02	95.4 95.2	95.3	7.6 7.6	7.6	1.5 1.6	1.6	<2.5 <2.5	<2.5
24-Jun-09	Rainy	Calm	11:29	Middle	0.09	19.0 19.0	19	7.6 7.6	7.6	0.02 0.02	0.02	96.1 95.9	96	7.6 7.6	7.6	1.6 1.7	1.7	<2.5 <2.5	<2.5
26-Jun-09	Rainy	Calm	11:57	Middle	0.09	19.0 19.0	19	7.6 7.6	7.6	0.02 0.02	0.02	97.2 97.0	97.1	7.7 7.7	7.7	1.5 1.6	1.6	<2.5 <2.5	<2.5
29-Jun-09	Fine	Calm	14:25	Middle	0.09	18.9 18.9	18.9	7.6 7.6	7.6	0.02 0.02	0.02	96.6 96.4	96.5	7.7 7.6	7.7	1.6 1.7	1.7	<2.5 <2.5	<2.5
30-Jun-09	Cloudy	Calm	12:10	Middle	0.09	19.0 19.0	19	7.6 7.6	7.6	0.02 0.02	0.02	94.9 94.7	94.8	7.6 7.6	7.6	1.6 1.7	1.7	<2.5 <2.5	<2.5

Water Quality Monitoring Results at 15_R

Date	Weather	Sea	Sampling	Dept	h (m)	Tempera	ature (°C)	ŗ	Н	Salin	ity ppt	DO Satu	ration (%)	Dissolved O	xygen (mg/L)	Turbidi	ty(NTU)	Suspended	Solids (mg/L
Date	Condition	Condition*	Time	Бері	11 (111)	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average
1-Jun-09	Sunny	Calm	12:53	Middle	0.08	19.1 19.1	19.1	7.6 7.6	7.6	0.02 0.02	0.02	91.0 90.9	91	7.1 7.1	7.1	1.9 2.0	2	<2.5 <2.5	<2.5
3-Jun-09	Cloudy	Calm	11:35	Middle	0.08	19.1 19.1	19.1	7.6 7.6	7.6	0.02 0.02	0.02	89.7 89.6	89.7	7.1 7.1	7.1	1.7 1.8	1.8	<2.5 <2.5	<2.5
5-Jun-09	Sunny	Calm	11:47	Middle	0.08	19.0 19.1	19.1	7.6 7.6	7.6	0.02 0.02	0.02	90.4 90.3	90.4	7.1 7.1	7.1	1.6 1.7	1.7	<2.5 <2.5	<2.5
8-Jun-09	Cloudy	Calm	12:13	Middle	0.08	19.1 19.1	19.1	7.6 7.6	7.6	0.02 0.02	0.02	91.6 91.5	91.6	7.2 7.2	7.2	1.7 1.8	1.8	<2.5 <2.5	<2.5
10-Jun-09	Cloudy	Calm	11:39	Middle	0.08	19.1 19.1	19.1	7.6 7.6	7.6	0.02 0.02	0.02	91.1 91.0	91.1	7.1 7.1	7.1	1.6 1.7	1.7	<2.5 <2.5	<2.5
12-Jun-09	Cloudy	Calm	11:34	Middle	0.08	19.0 19.0	19	7.6 7.6	7.6	0.02 0.02	0.02	90.3 90.2	90.3	7.1 7.1	7.1	1.7 1.8	1.8	<2.5 <2.5	<2.5
15-Jun-09	Cloudy	Calm	11:56	Middle	0.08	19.0 19.0	19	7.6 7.6	7.6	0.02 0.02	0.02	91.4 91.3	91.4	7.1 7.1	7.1	1.6 1.7	1.7	<2.5 <2.5	<2.5
17-Jun-09	Sunny	Calm	11:29	Middle	0.08	19.0 19.0	19	7.6 7.6	7.6	0.02 0.02	0.02	90.6 90.5	90.6	7.1 7.1	7.1	1.7 1.8	1.8	<2.5 <2.5	<2.5
19-Jun-09	Cloudy	Calm	11:45	Middle	0.08	19.0 19.0	19	7.7 7.7	7.7	0.02 0.02	0.02	91.5 91.4	91.5	7.2 7.2	7.2	1.7 1.7	1.7	<2.5 <2.5	<2.5
22-Jun-09	Cloudy	Calm	12:07	Middle	0.08	18.9 18.9	18.9	7.6 7.6	7.6	0.02 0.02	0.02	90.2 90.1	90.2	7.1 7.1	7.1	1.6 1.6	1.6	<2.5 <2.5	<2.5
24-Jun-09	Rainy	Calm	11:22	Middle	0.08	18.9 18.9	18.9	7.7 7.7	7.7	0.02 0.02	0.02	90.9 90.8	90.9	7.1 7.1	7.1	1.7 1.7	1.7	<2.5 <2.5	<2.5
26-Jun-09	Rainy	Calm	11:51	Middle	0.08	18.9 18.9	18.9	7.7 7.7	7.7	0.02 0.02	0.02	92.0 91.9	92	7.2 7.2	7.2	1.6 1.6	1.6	<2.5 <2.5	<2.5
29-Jun-09	Fine	Calm	14:18	Middle	0.08	18.9 18.9	18.9	7.7 7.7	7.7	0.02 0.02	0.02	91.4 91.3	91.4	7.1 7.1	7.1	1.7 1.7	1.7	<2.5 <2.5	<2.5
30-Jun-09	Cloudy	Calm	12:03	Middle	0.08	18.9 18.9	18.9	7.7 7.7	7.7	0.02 0.02	0.02	89.7 89.6	89.7	7.1 7.1	7.1	1.7 1.7	1.7	<2.5 <2.5	<2.5

Water Quality Monitoring Results at 18_I

Date	Weather	Sea	Sampling	Dept	h (m)	Tempera	ature (°C)	р	Н	Salin	ity ppt	DO Satu	ration (%)	Dissolved O	xygen (mg/L)	Turbidi	ty(NTU)	Suspended	Solids (mg/L
Date	Condition	Condition*	Time	Бері	11 (111)	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average
1-Jun-09	Sunny	Calm	12:45	Middle	0.1	19.0 19.0	19	7.9 7.8	7.9	0.02 0.02	0.02	94.6 94.9	94.8	7.5 7.5	7.5	1.8 1.8	1.8	<2.5 <2.5	<2.5
3-Jun-09	Cloudy	Calm	11:27	Middle	0.1	18.9 19.0	19	7.8 7.8	7.8	0.02 0.02	0.02	93.3 93.6	93.5	7.4 7.5	7.5	1.7 1.7	1.7	<2.5 <2.5	<2.5
5-Jun-09	Sunny	Calm	11:38	Middle	0.1	18.9 18.9	18.9	7.8 7.8	7.8	0.02 0.02	0.02	94.0 94.3	94.2	7.5 7.5	7.5	1.7 1.7	1.7	<2.5 <2.5	<2.5
8-Jun-09	Cloudy	Calm	12:05	Middle	0.1	18.9 19.0	19	7.8 7.8	7.8	0.02 0.02	0.02	95.2 95.5	95.4	7.5 7.6	7.6	1.7 1.7	1.7	<2.5 <2.5	<2.5
10-Jun-09	Cloudy	Calm	11:31	Middle	0.1	19.0 19.0	19	7.8 7.8	7.8	0.02 0.02	0.02	94.7 95.0	94.9	7.5 7.5	7.5	1.7 1.7	1.7	<2.5 <2.5	<2.5
12-Jun-09	Cloudy	Calm	11:26	Middle	0.1	18.9 18.9	18.9	7.8 7.8	7.8	0.02 0.02	0.02	93.9 94.2	94.1	7.5 7.5	7.5	1.8 1.8	1.8	<2.5 <2.5	<2.5
15-Jun-09	Cloudy	Calm	11:48	Middle	0.1	18.9 18.9	18.9	7.8 7.8	7.8	0.02 0.02	0.02	95.0 95.3	95.2	7.5 7.6	7.6	1.6 1.7	1.7	<2.5 <2.5	<2.5
17-Jun-09	Sunny	Calm	11:21	Middle	0.1	18.9 18.9	18.9	7.8 7.8	7.8	0.02 0.02	0.02	94.2 94.5	94.4	7.5 7.5	7.5	1.7 1.8	1.8	<2.5 <2.5	<2.5
19-Jun-09	Cloudy	Calm	11:37	Middle	0.1	18.8 18.9	18.9	7.9 7.9	7.9	0.02 0.02	0.02	95.1 95.4	95.3	7.5 7.6	7.6	1.6 1.7	1.7	<2.5 <2.5	<2.5
22-Jun-09	Cloudy	Calm	11:58	Middle	0.1	18.8 18.8	18.8	7.8 7.8	7.8	0.02 0.02	0.02	93.8 94.1	94	7.5 7.5	7.5	1.5 1.6	1.6	<2.5 <2.5	<2.5
24-Jun-09	Rainy	Calm	11:14	Middle	0.1	18.8 18.8	18.8	7.9 7.9	7.9	0.02 0.02	0.02	94.5 94.8	94.7	7.5 7.5	7.5	1.5 1.6	1.6	<2.5 <2.5	<2.5
26-Jun-09	Rainy	Calm	11:43	Middle	0.1	18.8 18.8	18.8	7.9 7.9	7.9	0.02 0.02	0.02	95.6 95.9	95.8	7.6 7.6	7.6	1.4 1.5	1.5	<2.5 <2.5	<2.5
29-Jun-09	Fine	Calm	14:10	Middle	0.1	18.7 18.8	18.8	7.9 7.9	7.9	0.02 0.02	0.02	95.0 95.3	95.2	7.5 7.6	7.6	1.5 1.6	1.6	<2.5 <2.5	<2.5
30-Jun-09	Cloudy	Calm	11:55	Middle	0.1	18.8 18.8	18.8	7.9 7.9	7.9	0.02 0.02	0.02	93.3 93.6	93.5	7.4 7.5	7.5	1.6 1.7	1.7	<2.5 <2.5	<2.5

Water Quality Monitoring Results at 18_R

Date	Weather	Sea	Sampling	Dept	h (m)	Tempera	ature (°C)	р	Н	Salin	ity ppt	DO Satu	ration (%)	Dissolved O	xygen (mg/L)	Turbidi	ty(NTU)	Suspended	Solids (mg/L
Date	Condition	Condition*	Time	Бері	11 (111)	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average
1-Jun-09	Sunny	Calm	12:41	Middle	0.175	19.0 19.0	19	7.9 7.9	7.9	0.02 0.02	0.02	94.4 94.5	94.5	7.5 7.5	7.5	1.9 1.9	1.9	<2.5 <2.5	<2.5
3-Jun-09	Cloudy	Calm	11:23	Middle	0.175	18.9 18.9	18.9	7.8 7.8	7.8	0.02 0.02	0.02	93.1 93.2	93.2	7.4 7.4	7.4	1.8 1.8	1.8	<2.5 <2.5	<2.5
5-Jun-09	Sunny	Calm	11:35	Middle	0.175	18.9 18.9	18.9	7.8 7.8	7.8	0.02 0.02	0.02	93.8 93.9	93.9	7.5 7.5	7.5	1.7 1.8	1.8	<2.5 <2.5	<2.5
8-Jun-09	Cloudy	Calm	12:01	Middle	0.175	18.9 18.9	18.9	7.9 7.8	7.9	0.02 0.02	0.02	95.0 95.1	95.1	7.5 7.5	7.5	1.7 1.8	1.8	<2.5 <2.5	<2.5
10-Jun-09	Cloudy	Calm	11:27	Middle	0.175	18.9 18.9	18.9	7.8 7.8	7.8	0.02 0.02	0.02	94.5 94.6	94.6	7.5 7.5	7.5	1.7 1.8	1.8	<2.5 <2.5	<2.5
12-Jun-09	Cloudy	Calm	11:22	Middle	0.175	18.8 18.8	18.8	7.8 7.8	7.8	0.02 0.02	0.02	93.7 93.8	93.8	7.5 7.5	7.5	1.8 1.9	1.9	<2.5 <2.5	<2.5
15-Jun-09	Cloudy	Calm	11:44	Middle	0.175	18.9 18.9	18.9	7.9 7.8	7.9	0.02 0.02	0.02	94.8 94.9	94.9	7.5 7.5	7.5	1.7 1.7	1.7	<2.5 <2.5	<2.5
17-Jun-09	Sunny	Calm	11:17	Middle	0.175	18.9 18.9	18.9	7.8 7.8	7.8	0.02 0.02	0.02	94.0 94.1	94.1	7.5 7.5	7.5	1.8 1.8	1.8	3.0 3.0	3
19-Jun-09	Cloudy	Calm	11:33	Middle	0.175	18.8 18.8	18.8	7.9 7.9	7.9	0.02 0.02	0.02	94.9 95.0	95	7.5 7.5	7.5	1.7 1.7	1.7	<2.5 <2.5	<2.5
22-Jun-09	Cloudy	Calm	11:55	Middle	0.175	18.8 18.8	18.8	7.9 7.8	7.9	0.02 0.02	0.02	93.6 93.7	93.7	7.5 7.5	7.5	1.6 1.6	1.6	<2.5 <2.5	<2.5
24-Jun-09	Rainy	Calm	11:10	Middle	0.175	18.8 18.8	18.8	7.9 7.9	7.9	0.02 0.02	0.02	94.3 94.4	94.4	7.5 7.5	7.5	1.6 1.6	1.6	<2.5 <2.5	<2.5
26-Jun-09	Rainy	Calm	11:39	Middle	0.175	18.8 18.8	18.8	7.9 7.9	7.9	0.02 0.02	0.02	95.4 95.5	95.5	7.5 7.5	7.5	1.5 1.5	1.5	<2.5 <2.5	<2.5
29-Jun-09	Fine	Calm	14:06	Middle	0.175	18.7 18.7	18.7	7.9 7.9	7.9	0.02 0.02	0.02	94.8 94.9	94.9	7.5 7.5	7.5	1.6 1.6	1.6	<2.5 <2.5	<2.5
30-Jun-09	Cloudy	Calm	11:51	Middle	0.175	18.8 18.8	18.8	7.9 7.9	7.9	0.02 0.02	0.02	93.1 93.2	93.2	7.4 7.4	7.4	1.7 1.7	1.7	<2.5 <2.5	<2.5

Water Quality Monitoring Results at 21_I

Date	Weather	Sea	Sampling	Dept	h (m)	Tempera	ature (°C)	р	Н	Salin	ity ppt	DO Satu	ration (%)	Dissolved O	xygen (mg/L)	Turbidi	ty(NTU)	Suspended	Solids (mg/L
Date	Condition	Condition*	Time	Бері	11 (111)	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average
1-Jun-09	Sunny	Calm	12:37	Middle	0.14	18.9 18.9	18.9	7.7 7.7	7.7	0.02 0.02	0.02	96.3 96.3	96.3	7.7 7.7	7.7	1.8 1.9	1.9	<2.5 <2.5	<2.5
3-Jun-09	Cloudy	Calm	11:19	Middle	0.14	18.9 18.9	18.9	7.6 7.6	7.6	0.02 0.02	0.02	95.0 95.0	95	7.6 7.6	7.6	1.7 1.8	1.8	<2.5 <2.5	<2.5
5-Jun-09	Sunny	Calm	11:31	Middle	0.14	18.9 18.9	18.9	7.6 7.6	7.6	0.02 0.02	0.02	95.7 95.7	95.7	7.6 7.6	7.6	1.7 1.7	1.7	<2.5 <2.5	<2.5
8-Jun-09	Cloudy	Calm	11:57	Middle	0.14	18.9 18.9	18.9	7.6 7.7	7.7	0.02 0.02	0.02	96.9 96.9	96.9	7.7 7.7	7.7	1.7 1.7	1.7	<2.5 <2.5	<2.5
10-Jun-09	Cloudy	Calm	11:23	Middle	0.14	18.9 18.9	18.9	7.6 7.6	7.6	0.02 0.02	0.02	96.4 96.4	96.4	7.7 7.7	7.7	1.6 1.6	1.6	<2.5 <2.5	<2.5
12-Jun-09	Cloudy	Calm	11:18	Middle	0.14	18.8 18.8	18.8	7.6 7.6	7.6	0.02 0.02	0.02	95.6 95.6	95.6	7.6 7.6	7.6	1.7 1.7	1.7	<2.5 <2.5	<2.5
15-Jun-09	Cloudy	Calm	11:40	Middle	0.14	18.8 18.9	18.9	7.6 7.7	7.7	0.02 0.02	0.02	96.7 96.7	96.7	7.7 7.7	7.7	1.6 1.6	1.6	<2.5 <2.5	<2.5
17-Jun-09	Sunny	Calm	11:13	Middle	0.14	18.8 18.8	18.8	7.6 7.6	7.6	0.02 0.02	0.02	95.9 95.9	95.9	7.7 7.7	7.7	1.7 1.7	1.7	<2.5 <2.5	<2.5
19-Jun-09	Cloudy	Calm	11:29	Middle	0.14	18.8 18.8	18.8	7.7 7.7	7.7	0.02 0.02	0.02	96.8 96.8	96.8	7.7 7.7	7.7	1.5 1.5	1.5	<2.5 <2.5	<2.5
22-Jun-09	Cloudy	Calm	11:51	Middle	0.14	18.7 18.7	18.7	7.6 7.7	7.7	0.02 0.02	0.02	95.5 95.5	95.5	7.6 7.6	7.6	1.5 1.5	1.5	<2.5 <2.5	<2.5
24-Jun-09	Rainy	Calm	11:06	Middle	0.14	18.7 18.7	18.7	7.7 7.7	7.7	0.02 0.02	0.02	96.2 96.2	96.2	7.7 7.7	7.7	1.6 1.6	1.6	<2.5 <2.5	<2.5
26-Jun-09	Rainy	Calm	11:35	Middle	0.14	18.7 18.7	18.7	7.7 7.7	7.7	0.02 0.02	0.02	97.3 97.3	97.3	7.7 7.7	7.7	1.5 1.5	1.5	<2.5 <2.5	<2.5
29-Jun-09	Fine	Calm	14:02	Middle	0.14	18.7 18.7	18.7	7.7 7.7	7.7	0.02 0.02	0.02	96.7 96.7	96.7	7.7 7.7	7.7	1.6 1.6	1.6	<2.5 <2.5	<2.5
30-Jun-09	Cloudy	Calm	11:47	Middle	0.14	18.7 18.7	18.7	7.7 7.7	7.7	0.02 0.02	0.02	95.0 95.0	95	7.6 7.6	7.6	1.7 1.7	1.7	<2.5 <2.5	<2.5

Water Quality Monitoring Results at 21_R

Date	Weather	Sea	Sampling	Dent	h (m)	Tempera	ature (°C)	ŗ	Н	Salin	ity ppt	DO Satu	ration (%)	Dissolved O	xygen (mg/L)	Turbidi	ty(NTU)	Suspended	Solids (mg/L
Date	Condition	Condition*	Time	Бері	11 (111)	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average
1-Jun-09	Sunny	Calm	12:32	Middle	0.1	18.9 18.9	18.9	7.7 7.7	7.7	0.02 0.02	0.02	96.7 96.5	96.6	7.7 7.7	7.7	2.0 1.9	2	<2.5 <2.5	<2.5
3-Jun-09	Cloudy	Calm	11:15	Middle	0.1	18.8 18.9	18.9	7.6 7.6	7.6	0.02 0.02	0.02	95.4 95.2	95.3	7.6 7.6	7.6	1.9 1.8	1.9	<2.5 <2.5	<2.5
5-Jun-09	Sunny	Calm	11:26	Middle	0.1	18.8 18.8	18.8	7.6 7.6	7.6	0.02 0.02	0.02	96.1 95.9	96	7.7 7.7	7.7	1.9 1.8	1.9	<2.5 <2.5	<2.5
8-Jun-09	Cloudy	Calm	11:53	Middle	0.1	18.8 18.9	18.9	7.7 7.7	7.7	0.02 0.02	0.02	97.3 97.1	97.2	7.7 7.7	7.7	1.8 1.7	1.8	<2.5 <2.5	<2.5
10-Jun-09	Cloudy	Calm	11:19	Middle	0.1	18.9 18.9	18.9	7.6 7.6	7.6	0.02 0.02	0.02	96.8 96.6	96.7	7.7 7.7	7.7	1.7 1.6	1.7	<2.5 <2.5	<2.5
12-Jun-09	Cloudy	Calm	11:14	Middle	0.1	18.8 18.8	18.8	7.6 7.6	7.6	0.02 0.02	0.02	96.0 95.8	95.9	7.7 7.7	7.7	1.8 1.7	1.8	<2.5 <2.5	<2.5
15-Jun-09	Cloudy	Calm	11:35	Middle	0.1	18.8 18.8	18.8	7.7 7.7	7.7	0.02 0.02	0.02	97.1 96.9	97	7.7 7.7	7.7	1.8 1.7	1.8	<2.5 <2.5	<2.5
17-Jun-09	Sunny	Calm	11:09	Middle	0.1	18.8 18.8	18.8	7.6 7.6	7.6	0.02 0.02	0.02	96.3 96.1	96.2	7.7 7.7	7.7	1.9 1.8	1.9	<2.5 <2.5	<2.5
19-Jun-09	Cloudy	Calm	11:25	Middle	0.1	18.7 18.8	18.8	7.7 7.7	7.7	0.02 0.02	0.02	97.2 97.0	97.1	7.7 7.7	7.7	1.7 1.6	1.7	<2.5 <2.5	<2.5
22-Jun-09	Cloudy	Calm	11:46	Middle	0.1	18.7 18.7	18.7	7.7 7.7	7.7	0.02 0.02	0.02	95.9 95.7	95.8	7.7 7.7	7.7	1.6 1.5	1.6	<2.5 <2.5	<2.5
24-Jun-09	Rainy	Calm	11:01	Middle	0.1	18.7 18.7	18.7	7.7 7.7	7.7	0.02 0.02	0.02	96.6 96.4	96.5	7.7 7.7	7.7	1.7 1.6	1.7	<2.5 <2.5	<2.5
26-Jun-09	Rainy	Calm	11:30	Middle	0.1	18.7 18.7	18.7	7.7 7.7	7.7	0.02 0.02	0.02	97.7 97.5	97.6	7.8 7.7	7.8	1.6 1.5	1.6	<2.5 <2.5	<2.5
29-Jun-09	Fine	Calm	13:58	Middle	0.1	18.6 18.7	18.7	7.7 7.7	7.7	0.02 0.02	0.02	97.1 96.9	97	7.7 7.7	7.7	1.7 1.6	1.7	<2.5 <2.5	<2.5
30-Jun-09	Cloudy	Calm	11:43	Middle	0.1	18.7 18.7	18.7	7.7 7.7	7.7	0.02 0.02	0.02	95.4 95.2	95.3	7.6 7.6	7.6	1.8 1.7	1.8	<2.5 <2.5	<2.5

Water Quality Monitoring Results at 23_I

Date	Weather	Sea	Sampling	Dept	h (m)	Tempera	ature (°C)	р	Н	Salin	ity ppt	DO Satu	ration (%)	Dissolved O	xygen (mg/L)	Turbidi	ty(NTU)	Suspended	Solids (mg/L
Date	Condition	Condition*	Time	Бері	11 (111)	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average
1-Jun-09	Sunny	Calm	12:26	Middle	0.09	19.0 19.0	19	7.5 7.5	7.5	0.02 0.02	0.02	96.3 96.1	96.2	7.7 7.7	7.7	1.8 1.7	1.8	<2.5 <2.5	<2.5
3-Jun-09	Cloudy	Calm	11:08	Middle	0.09	19.0 19.0	19	7.5 7.5	7.5	0.02 0.02	0.02	95.0 94.8	94.9	7.6 7.6	7.6	1.7 1.6	1.7	<2.5 <2.5	<2.5
5-Jun-09	Sunny	Calm	11:20	Middle	0.09	19.0 19.0	19	7.5 7.5	7.5	0.02 0.02	0.02	95.7 95.5	95.6	7.6 7.6	7.6	1.7 1.6	1.7	<2.5 <2.5	<2.5
8-Jun-09	Cloudy	Calm	11:47	Middle	0.09	19.0 19.0	19	7.5 7.5	7.5	0.02 0.02	0.02	96.9 96.7	96.8	7.7 7.7	7.7	1.6 1.5	1.6	<2.5 <2.5	<2.5
10-Jun-09	Cloudy	Calm	11:13	Middle	0.09	19.0 19.0	19	7.5 7.5	7.5	0.02 0.02	0.02	96.4 96.2	96.3	7.7 7.7	7.7	1.6 1.5	1.6	<2.5 <2.5	<2.5
12-Jun-09	Cloudy	Calm	11:08	Middle	0.09	18.9 18.9	18.9	7.5 7.5	7.5	0.02 0.02	0.02	95.6 95.4	95.5	7.6 7.6	7.6	1.7 1.6	1.7	<2.5 <2.5	<2.5
15-Jun-09	Cloudy	Calm	11:29	Middle	0.09	19.0 19.0	19	7.5 7.5	7.5	0.02 0.02	0.02	96.7 96.5	96.6	7.7 7.7	7.7	1.7 1.6	1.7	<2.5 <2.5	<2.5
17-Jun-09	Sunny	Calm	11:03	Middle	0.09	18.9 18.9	18.9	7.5 7.5	7.5	0.02 0.02	0.02	95.9 95.7	95.8	7.7 7.6	7.7	1.8 1.7	1.8	<2.5 <2.5	<2.5
19-Jun-09	Cloudy	Calm	11:18	Middle	0.09	18.9 18.9	18.9	7.5 7.6	7.6	0.02 0.02	0.02	96.8 96.6	96.7	7.7 7.7	7.7	1.6 1.5	1.6	<2.5 <2.5	<2.5
22-Jun-09	Cloudy	Calm	11:40	Middle	0.09	18.9 18.9	18.9	7.5 7.5	7.5	0.02 0.02	0.02	95.5 95.3	95.4	7.6 7.6	7.6	1.6 1.5	1.6	<2.5 <2.5	<2.5
24-Jun-09	Rainy	Calm	10:55	Middle	0.09	18.8 18.8	18.8	7.6 7.6	7.6	0.02 0.02	0.02	96.2 96.0	96.1	7.7 7.7	7.7	1.7 1.6	1.7	<2.5 <2.5	<2.5
26-Jun-09	Rainy	Calm	11:24	Middle	0.09	18.9 18.9	18.9	7.6 7.6	7.6	0.02 0.02	0.02	97.3 97.1	97.2	7.7 7.7	7.7	1.5 1.4	1.5	<2.5 <2.5	<2.5
29-Jun-09	Fine	Calm	13:52	Middle	0.09	18.8 18.8	18.8	7.6 7.6	7.6	0.02 0.02	0.02	96.7 96.5	96.6	7.7 7.7	7.7	1.6 1.5	1.6	<2.5 <2.5	<2.5
30-Jun-09	Cloudy	Calm	11:37	Middle	0.09	18.8 18.8	18.8	7.6 7.6	7.6	0.02 0.02	0.02	95.0 94.8	94.9	7.6 7.6	7.6	1.7 1.6	1.7	<2.5 <2.5	<2.5

Water Quality Monitoring Results at 23_R1

Date	Weather	Sea	Sampling	Dept	h (m)	Tempera	ature (°C)	р	Н	Salin	ity ppt	DO Satu	ration (%)	Dissolved O	xygen (mg/L)	Turbidi	ty(NTU)	Suspended	Solids (mg/L
Date	Condition	Condition*	Time	Бері	11 (111)	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average
1-Jun-09	Sunny	Calm	12:13	Middle	0.09	19.0 19.0	19	7.5 7.5	7.5	0.02 0.02	0.02	96.7 96.4	96.6	7.7 7.7	7.7	1.9 1.8	1.9	<2.5 <2.5	<2.5
3-Jun-09	Cloudy	Calm	10:55	Middle	0.09	18.9 19.0	19	7.5 7.5	7.5	0.02 0.02	0.02	95.4 95.1	95.3	7.7 7.6	7.7	1.8 1.7	1.8	<2.5 <2.5	<2.5
5-Jun-09	Sunny	Calm	11:07	Middle	0.09	18.9 18.9	18.9	7.5 7.5	7.5	0.02 0.02	0.02	96.1 95.8	96	7.7 7.7	7.7	1.8 1.7	1.8	<2.5 <2.5	<2.5
8-Jun-09	Cloudy	Calm	11:34	Middle	0.09	18.9 19.0	19	7.5 7.5	7.5	0.02 0.02	0.02	97.3 97.0	97.2	7.7 7.7	7.7	1.7 1.6	1.7	3.0 <2.5	2.8
10-Jun-09	Cloudy	Calm	11:00	Middle	0.09	18.9 19.0	19	7.5 7.5	7.5	0.02 0.02	0.02	96.8 96.5	96.7	7.7 7.7	7.7	1.7 1.6	1.7	<2.5 <2.5	<2.5
12-Jun-09	Cloudy	Calm	10:55	Middle	0.09	18.8 18.9	18.9	7.5 7.5	7.5	0.02 0.02	0.02	96.0 95.7	95.9	7.7 7.7	7.7	1.8 1.7	1.8	<2.5 <2.5	<2.5
15-Jun-09	Cloudy	Calm	11:16	Middle	0.09	18.9 18.9	18.9	7.5 7.5	7.5	0.02 0.02	0.02	97.1 96.8	97	7.7 7.7	7.7	1.8 1.7	1.8	<2.5 <2.5	<2.5
17-Jun-09	Sunny	Calm	10:50	Middle	0.09	18.9 18.9	18.9	7.5 7.5	7.5	0.02 0.02	0.02	96.3 96.0	96.2	7.7 7.7	7.7	1.9 1.8	1.9	<2.5 <2.5	<2.5
19-Jun-09	Cloudy	Calm	11:06	Middle	0.09	18.8 18.9	18.9	7.5 7.5	7.5	0.02 0.02	0.02	97.2 96.9	97.1	7.7 7.7	7.7	1.7 1.6	1.7	<2.5 <2.5	<2.5
22-Jun-09	Cloudy	Calm	11:27	Middle	0.09	18.8 18.8	18.8	7.5 7.5	7.5	0.02 0.02	0.02	95.9 95.6	95.8	7.7 7.7	7.7	1.7 1.6	1.7	<2.5 <2.5	<2.5
24-Jun-09	Rainy	Calm	10:42	Middle	0.09	18.8 18.8	18.8	7.5 7.5	7.5	0.02 0.02	0.02	96.6 96.3	96.5	7.7 7.7	7.7	1.8 1.7	1.8	<2.5 <2.5	<2.5
26-Jun-09	Rainy	Calm	11:11	Middle	0.09	18.8 18.8	18.8	7.6 7.6	7.6	0.02 0.02	0.02	97.7 97.4	97.6	7.8 7.7	7.8	1.6 1.5	1.6	<2.5 <2.5	<2.5
29-Jun-09	Fine	Calm	13:39	Middle	0.09	18.7 18.8	18.8	7.5 7.5	7.5	0.02 0.02	0.02	97.1 96.8	97	7.7 7.7	7.7	1.7 1.6	1.7	<2.5 <2.5	<2.5
30-Jun-09	Cloudy	Calm	11:24	Middle	0.09	18.8 18.8	18.8	7.6 7.6	7.6	0.02 0.02	0.02	95.4 95.1	95.3	7.7 7.6	7.7	1.8 1.7	1.8	<2.5 <2.5	<2.5

Water Quality Monitoring Results at 23_R2

Date	Weather	Sea	Sampling	Dent	th (m)	Tempera	ature (°C)	р	Н	Salin	ity ppt	DO Satu	ration (%)	Dissolved O	xygen (mg/L)	Turbidi	ity(NTU)	Suspended	Solids (mg/L
Date	Condition	Condition*	Time	Бері	ui (iii <i>)</i>	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average
1-Jun-09	Sunny	Calm	12:19	Middle	0.1	19.0 19.0	19	7.5 7.5	7.5	0.02 0.02	0.02	96.9 96.8	96.9	7.7 7.7	7.7	1.8 1.9	1.9	<2.5 <2.5	<2.5
3-Jun-09	Cloudy	Calm	11:01	Middle	0.1	19.0 19.0	19	7.5 7.5	7.5	0.02 0.02	0.02	95.6 95.5	95.6	7.7 7.7	7.7	1.7 1.8	1.8	<2.5 <2.5	<2.5
5-Jun-09	Sunny	Calm	11:13	Middle	0.1	18.9 18.9	18.9	7.5 7.5	7.5	0.02 0.02	0.02	96.3 96.2	96.3	7.7 7.7	7.7	1.7 1.8	1.8	<2.5 <2.5	<2.5
8-Jun-09	Cloudy	Calm	11:40	Middle	0.1	19.0 19.0	19	7.5 7.5	7.5	0.02 0.02	0.02	97.5 97.4	97.5	7.8 7.8	7.8	1.6 1.7	1.7	<2.5 <2.5	<2.5
10-Jun-09	Cloudy	Calm	11:06	Middle	0.1	19.0 19.0	19	7.5 7.5	7.5	0.02 0.02	0.02	97.0 96.9	97	7.7 7.7	7.7	1.6 1.7	1.7	<2.5 <2.5	<2.5
12-Jun-09	Cloudy	Calm	11:01	Middle	0.1	18.9 18.9	18.9	7.5 7.5	7.5	0.02 0.02	0.02	96.2 96.1	96.2	7.7 7.7	7.7	1.7 1.8	1.8	<2.5 <2.5	<2.5
15-Jun-09	Cloudy	Calm	11:22	Middle	0.1	18.9 18.9	18.9	7.5 7.5	7.5	0.02 0.02	0.02	97.3 97.2	97.3	7.8 7.7	7.8	1.7 1.8	1.8	<2.5 <2.5	<2.5
17-Jun-09	Sunny	Calm	10:56	Middle	0.1	18.9 18.9	18.9	7.5 7.5	7.5	0.02 0.02	0.02	96.5 96.4	96.5	7.7 7.7	7.7	1.8 1.9	1.9	<2.5 <2.5	<2.5
19-Jun-09	Cloudy	Calm	11:11	Middle	0.1	18.9 18.9	18.9	7.5 7.5	7.5	0.02 0.02	0.02	97.4 97.3	97.4	7.8 7.8	7.8	1.6 1.7	1.7	<2.5 <2.5	<2.5
22-Jun-09	Cloudy	Calm	11:33	Middle	0.1	18.8 18.8	18.8	7.5 7.5	7.5	0.02 0.02	0.02	96.1 96.0	96.1	7.7 7.7	7.7	1.6 1.7	1.7	<2.5 <2.5	<2.5
24-Jun-09	Rainy	Calm	10:48	Middle	0.1	18.8 18.8	18.8	7.5 7.5	7.5	0.02 0.02	0.02	96.8 96.7	96.8	7.7 7.7	7.7	1.7 1.8	1.8	<2.5 <2.5	<2.5
26-Jun-09	Rainy	Calm	11:17	Middle	0.1	18.8 18.8	18.8	7.6 7.6	7.6	0.02 0.02	0.02	97.9 97.8	97.9	7.8 7.8	7.8	1.5 1.6	1.6	<2.5 <2.5	<2.5
29-Jun-09	Fine	Calm	13:45	Middle	0.1	18.8 18.8	18.8	7.6 7.6	7.6	0.02 0.02	0.02	97.3 97.2	97.3	7.8 7.7	7.8	1.6 1.7	1.7	<2.5 <2.5	<2.5
30-Jun-09	Cloudy	Calm	11:30	Middle	0.1	18.8 18.8	18.8	7.6 7.6	7.6	0.02 0.02	0.02	95.6 95.5	95.6	7.7 7.7	7.7	1.7 1.8	1.8	<2.5 <2.5	<2.5

Water Quality Monitoring Results at 26_I

Date	Weather	Sea	Sampling	Dept	h (m)	Tempera	ature (°C)	р	Н	Salin	ity ppt	DO Satu	ration (%)	Dissolved O	xygen (mg/L)	Turbidi	ity(NTU)	Suspended	Solids (mg/L
Date	Condition	Condition*	Time	Бері	11 (111)	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average
1-Jun-09	Sunny	Calm	11:39	Middle	0.14	18.9 18.9	18.9	7.8 7.8	7.8	0.03 0.03	0.03	97.0 96.9	97	7.7 7.7	7.7	1.8 1.7	1.8	<2.5 <2.5	<2.5
3-Jun-09	Cloudy	Calm	10:21	Middle	0.14	18.9 18.9	18.9	7.7 7.7	7.7	0.03 0.03	0.03	95.7 95.6	95.7	7.7 7.6	7.7	1.8 1.7	1.8	<2.5 <2.5	<2.5
5-Jun-09	Sunny	Calm	10:33	Middle	0.14	18.9 18.9	18.9	7.7 7.7	7.7	0.03 0.03	0.03	96.4 96.3	96.4	7.7 7.7	7.7	1.8 1.7	1.8	<2.5 <2.5	<2.5
8-Jun-09	Cloudy	Calm	10:59	Middle	0.14	18.9 18.9	18.9	7.8 7.8	7.8	0.03 0.03	0.03	97.6 97.5	97.6	7.7 7.7	7.7	1.7 1.6	1.7	<2.5 <2.5	<2.5
10-Jun-09	Cloudy	Calm	10:25	Middle	0.14	18.9 18.9	18.9	7.7 7.7	7.7	0.03 0.03	0.03	97.1 97.0	97.1	7.7 7.7	7.7	1.7 1.6	1.7	<2.5 <2.5	<2.5
12-Jun-09	Cloudy	Calm	10:20	Middle	0.14	18.8 18.8	18.8	7.7 7.7	7.7	0.03 0.03	0.03	96.3 96.2	96.3	7.7 7.7	7.7	1.8 1.7	1.8	<2.5 <2.5	<2.5
15-Jun-09	Cloudy	Calm	10:42	Middle	0.14	18.9 18.9	18.9	7.8 7.8	7.8	0.03 0.03	0.03	97.4 97.3	97.4	7.7 7.7	7.7	1.7 1.6	1.7	<2.5 <2.5	<2.5
17-Jun-09	Sunny	Calm	10:15	Middle	0.14	18.8 18.8	18.8	7.7 7.7	7.7	0.03 0.03	0.03	96.6 96.5	96.6	7.7 7.7	7.7	1.8 1.7	1.8	<2.5 <2.5	<2.5
19-Jun-09	Cloudy	Calm	10:31	Middle	0.14	18.8 18.8	18.8	7.8 7.8	7.8	0.03 0.03	0.03	97.5 97.4	97.5	7.7 7.7	7.7	1.7 1.6	1.7	<2.5 <2.5	<2.5
22-Jun-09	Cloudy	Calm	10:53	Middle	0.14	18.8 18.8	18.8	7.8 7.8	7.8	0.03 0.03	0.03	96.2 96.1	96.2	7.7 7.7	7.7	1.6 1.5	1.6	<2.5 <2.5	<2.5
24-Jun-09	Rainy	Calm	10:08	Middle	0.14	18.7 18.7	18.7	7.8 7.8	7.8	0.03 0.03	0.03	96.9 96.8	96.9	7.7 7.7	7.7	1.7 1.6	1.7	<2.5 <2.5	<2.5
26-Jun-09	Rainy	Calm	10:37	Middle	0.14	18.8 18.8	18.8	7.8 7.8	7.8	0.03 0.03	0.03	98.0 97.9	98	7.8 7.7	7.8	1.6 1.5	1.6	<2.5 <2.5	<2.5
29-Jun-09	Fine	Calm	13:04	Middle	0.14	18.7 18.7	18.7	7.8 7.8	7.8	0.03 0.03	0.03	97.4 97.3	97.4	7.7 7.7	7.7	1.7 1.6	1.7	<2.5 <2.5	<2.5
30-Jun-09	Cloudy	Calm	10:49	Middle	0.14	18.7 18.7	18.7	7.8 7.8	7.8	0.03 0.03	0.03	95.7 95.6	95.7	7.7 7.6	7.7	1.7 1.6	1.7	<2.5 <2.5	<2.5

Water Quality Monitoring Results at 26_R

Date	Weather	Sea	Sampling	Dept	h (m)	Tempera	ature (°C)	р	Н	Salin	ity ppt	DO Satu	ration (%)	Dissolved Ox	kygen (mg/L)	Turbidi	ty(NTU)	Suspended	Solids (mg/L
Date	Condition	Condition*	Time	Бері	11 (111)	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average
1-Jun-09	Sunny	Calm	12:03	Middle	0.09	19.0 19.0	19	7.7 7.7	7.7	0.02 0.02	0.02	96.9 96.7	96.8	7.7 7.7	7.7	1.9 1.8	1.9	<2.5 <2.5	<2.5
3-Jun-09	Cloudy	Calm	10:45	Middle	0.09	19.0 19.0	19	7.7 7.7	7.7	0.02 0.02	0.02	95.6 95.4	95.5	7.7 7.6	7.7	1.9 1.8	1.9	<2.5 <2.5	<2.5
5-Jun-09	Sunny	Calm	10:57	Middle	0.09	19.0 19.0	19	7.6 7.6	7.6	0.02 0.02	0.02	96.3 96.1	96.2	7.7 7.7	7.7	1.8 1.7	1.8	<2.5 <2.5	<2.5
8-Jun-09	Cloudy	Calm	11:23	Middle	0.09	19.0 19.0	19	7.7 7.7	7.7	0.02 0.02	0.02	97.5 97.3	97.4	7.8 7.7	7.8	1.7 1.6	1.7	<2.5 <2.5	<2.5
10-Jun-09	Cloudy	Calm	10:50	Middle	0.09	19.0 19.0	19	7.7 7.7	7.7	0.02 0.02	0.02	97.0 96.8	96.9	7.7 7.7	7.7	1.7 1.7	1.7	<2.5 <2.5	<2.5
12-Jun-09	Cloudy	Calm	10:45	Middle	0.09	18.9 18.9	18.9	7.6 7.6	7.6	0.02 0.02	0.02	96.2 96.0	96.1	7.7 7.7	7.7	1.8 1.7	1.8	<2.5 <2.5	<2.5
15-Jun-09	Cloudy	Calm	11:06	Middle	0.09	19.0 19.0	19	7.7 7.7	7.7	0.02 0.02	0.02	97.3 97.1	97.2	7.7 7.7	7.7	1.8 1.7	1.8	<2.5 <2.5	<2.5
17-Jun-09	Sunny	Calm	10:40	Middle	0.09	18.9 18.9	18.9	7.6 7.6	7.6	0.02 0.02	0.02	96.5 96.3	96.4	7.7 7.7	7.7	1.9 1.8	1.9	<2.5 <2.5	<2.5
19-Jun-09	Cloudy	Calm	10:55	Middle	0.09	18.9 18.9	18.9	7.7 7.7	7.7	0.02 0.02	0.02	97.4 97.2	97.3	7.8 7.7	7.8	1.8 1.7	1.8	<2.5 <2.5	<2.5
22-Jun-09	Cloudy	Calm	11:17	Middle	0.09	18.9 18.9	18.9	7.7 7.7	7.7	0.02 0.02	0.02	96.1 95.9	96	7.7 7.7	7.7	1.7 1.7	1.7	<2.5 <2.5	<2.5
24-Jun-09	Rainy	Calm	10:32	Middle	0.09	18.8 18.9	18.9	7.7 7.7	7.7	0.02 0.02	0.02	96.8 96.6	96.7	7.7 7.7	7.7	1.8 1.7	1.8	<2.5 <2.5	<2.5
26-Jun-09	Rainy	Calm	11:01	Middle	0.09	18.9 18.9	18.9	7.7 7.7	7.7	0.02 0.02	0.02	97.9 97.7	97.8	7.8 7.8	7.8	1.7 1.6	1.7	<2.5 <2.5	<2.5
29-Jun-09	Fine	Calm	13:29	Middle	0.09	18.8 18.8	18.8	7.7 7.7	7.7	0.02 0.02	0.02	97.3 97.1	97.2	7.7 7.7	7.7	1.8 1.7	1.8	<2.5 <2.5	<2.5
30-Jun-09	Cloudy	Calm	11:14	Middle	0.09	18.8 18.9	18.9	7.7 7.7	7.7	0.02 0.02	0.02	95.6 95.4	95.5	7.7 7.6	7.7	1.8 1.7	1.8	<2.5 <2.5	<2.5

Water Quality Monitoring Results at 27_I

Date	Weather	Sea	Sampling	Dept	h (m)	Tempera	ature (°C)	р	Н	Salin	ity ppt	DO Satu	ration (%)	Dissolved O	xygen (mg/L)	Turbidi	ty(NTU)	Suspended	Solids (mg/L
Date	Condition	Condition*	Time	Бері	11 (111)	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average
1-Jun-09	Sunny	Calm	11:57	Middle	0.08	18.9 19.0	19	7.7 7.7	7.7	0.02 0.02	0.02	96.9 96.7	96.8	7.7 7.7	7.7	1.8 1.9	1.9	<2.5 <2.5	<2.5
3-Jun-09	Cloudy	Calm	10:39	Middle	0.08	18.9 18.9	18.9	7.7 7.7	7.7	0.02 0.02	0.02	95.6 95.4	95.5	7.7 7.6	7.7	1.8 1.9	1.9	<2.5 <2.5	<2.5
5-Jun-09	Sunny	Calm	10:51	Middle	0.08	18.9 18.9	18.9	7.7 7.6	7.7	0.02 0.02	0.02	96.3 96.1	96.2	7.7 7.7	7.7	1.8 1.9	1.9	<2.5 <2.5	<2.5
8-Jun-09	Cloudy	Calm	11:17	Middle	0.08	18.9 18.9	18.9	7.7 7.7	7.7	0.02 0.02	0.02	97.5 97.3	97.4	7.7 7.7	7.7	1.7 1.8	1.8	<2.5 <2.5	<2.5
10-Jun-09	Cloudy	Calm	10:44	Middle	0.08	18.9 19.0	19	7.7 7.7	7.7	0.02 0.02	0.02	97.0 96.8	96.9	7.7 7.7	7.7	1.7 1.8	1.8	<2.5 <2.5	<2.5
12-Jun-09	Cloudy	Calm	10:39	Middle	0.08	18.8 18.9	18.9	7.7 7.6	7.7	0.02 0.02	0.02	96.2 96.0	96.1	7.7 7.7	7.7	1.8 1.9	1.9	<2.5 <2.5	<2.5
15-Jun-09	Cloudy	Calm	11:00	Middle	0.08	18.9 18.9	18.9	7.7 7.7	7.7	0.02 0.02	0.02	97.3 97.1	97.2	7.7 7.7	7.7	1.7 1.8	1.8	<2.5 <2.5	<2.5
17-Jun-09	Sunny	Calm	10:33	Middle	0.08	18.8 18.9	18.9	7.7 7.7	7.7	0.02 0.02	0.02	96.5 96.3	96.4	7.7 7.7	7.7	1.8 1.9	1.9	<2.5 <2.5	<2.5
19-Jun-09	Cloudy	Calm	10:49	Middle	0.08	18.8 18.8	18.8	7.7 7.7	7.7	0.02 0.02	0.02	97.4 97.2	97.3	7.7 7.7	7.7	1.7 1.8	1.8	<2.5 <2.5	<2.5
22-Jun-09	Cloudy	Calm	11:11	Middle	0.08	18.8 18.8	18.8	7.7 7.7	7.7	0.02 0.02	0.02	96.1 95.9	96	7.7 7.7	7.7	1.6 1.7	1.7	<2.5 <2.5	<2.5
24-Jun-09	Rainy	Calm	10:26	Middle	0.08	18.8 18.8	18.8	7.7 7.7	7.7	0.02 0.02	0.02	96.8 96.6	96.7	7.7 7.7	7.7	1.6 1.7	1.7	<2.5 <2.5	<2.5
26-Jun-09	Rainy	Calm	10:55	Middle	0.08	18.8 18.8	18.8	7.8 7.8	7.8	0.02 0.02	0.02	97.9 97.7	97.8	7.8 7.8	7.8	1.5 1.6	1.6	<2.5 <2.5	<2.5
29-Jun-09	Fine	Calm	13:22	Middle	0.08	18.7 18.7	18.7	7.7 7.7	7.7	0.02 0.02	0.02	97.3 97.1	97.2	7.7 7.7	7.7	1.6 1.7	1.7	<2.5 <2.5	<2.5
30-Jun-09	Cloudy	Calm	11:07	Middle	0.08	18.8 18.8	18.8	7.8 7.8	7.8	0.02 0.02	0.02	95.6 95.4	95.5	7.7 7.6	7.7	1.6 1.7	1.7	<2.5 <2.5	<2.5

Water Quality Monitoring Results at 27_R

Date	Weather	Sea	Sampling	Dept	h (m)	Tempera	ature (°C)	р	Н	Salin	ity ppt	DO Satu	ration (%)	Dissolved O	xygen (mg/L)	Turbidi	ty(NTU)	Suspended	Solids (mg/L
Date	Condition	Condition*	Time	Бері	11 (111)	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average
1-Jun-09	Sunny	Calm	11:47	Middle	0.13	18.9 18.9	18.9	7.7 7.7	7.7	0.02 0.02	0.02	97.8 97.5	97.7	7.8 7.8	7.8	1.9 1.9	1.9	<2.5 <2.5	<2.5
3-Jun-09	Cloudy	Calm	10:29	Middle	0.13	18.9 18.9	18.9	7.7 7.7	7.7	0.02 0.02	0.02	96.5 96.2	96.4	7.8 7.7	7.8	1.9 1.9	1.9	<2.5 <2.5	<2.5
5-Jun-09	Sunny	Calm	10:41	Middle	0.13	18.9 18.9	18.9	7.7 7.7	7.7	0.02 0.02	0.02	97.2 96.9	97.1	7.8 7.8	7.8	1.9 1.9	1.9	<2.5 <2.5	<2.5
8-Jun-09	Cloudy	Calm	11:08	Middle	0.13	18.9 18.9	18.9	7.7 7.7	7.7	0.02 0.02	0.02	98.4 98.1	98.3	7.8 7.8	7.8	1.8 1.8	1.8	3.0 <2.5	2.8
10-Jun-09	Cloudy	Calm	10:34	Middle	0.13	18.9 18.9	18.9	7.7 7.7	7.7	0.02 0.02	0.02	97.9 97.6	97.8	7.8 7.8	7.8	1.8 1.8	1.8	<2.5 <2.5	<2.5
12-Jun-09	Cloudy	Calm	10:29	Middle	0.13	18.8 18.8	18.8	7.7 7.7	7.7	0.02 0.02	0.02	97.1 96.8	97	7.8 7.8	7.8	1.9 1.9	1.9	<2.5 <2.5	<2.5
15-Jun-09	Cloudy	Calm	10:50	Middle	0.13	18.9 18.9	18.9	7.7 7.7	7.7	0.02 0.02	0.02	98.2 97.9	98.1	7.8 7.8	7.8	1.8 1.8	1.8	<2.5 <2.5	<2.5
17-Jun-09	Sunny	Calm	10:24	Middle	0.13	18.8 18.8	18.8	7.7 7.7	7.7	0.02 0.02	0.02	97.4 97.1	97.3	7.8 7.8	7.8	1.9 1.9	1.9	<2.5 <2.5	<2.5
19-Jun-09	Cloudy	Calm	10:39	Middle	0.13	18.8 18.8	18.8	7.7 7.7	7.7	0.02 0.02	0.02	98.3 98.0	98.2	7.8 7.8	7.8	1.8 1.8	1.8	<2.5 <2.5	<2.5
22-Jun-09	Cloudy	Calm	11:01	Middle	0.13	18.8 18.8	18.8	7.7 7.7	7.7	0.02 0.02	0.02	97.0 96.7	96.9	7.8 7.8	7.8	1.7 1.7	1.7	<2.5 <2.5	<2.5
24-Jun-09	Rainy	Calm	10:16	Middle	0.13	18.7 18.7	18.7	7.7 7.7	7.7	0.02 0.02	0.02	97.7 97.4	97.6	7.8 7.8	7.8	1.7 1.7	1.7	<2.5 <2.5	<2.5
26-Jun-09	Rainy	Calm	10:45	Middle	0.13	18.8 18.8	18.8	7.8 7.8	7.8	0.02 0.02	0.02	98.8 98.5	98.7	7.9 7.8	7.9	1.6 1.6	1.6	<2.5 <2.5	<2.5
29-Jun-09	Fine	Calm	13:13	Middle	0.13	18.7 18.7	18.7	7.7 7.7	7.7	0.02 0.02	0.02	98.2 97.9	98.1	7.8 7.8	7.8	1.7 1.7	1.7	<2.5 <2.5	<2.5
30-Jun-09	Cloudy	Calm	10:58	Middle	0.13	18.7 18.7	18.7	7.8 7.8	7.8	0.02 0.02	0.02	96.5 96.2	96.4	7.8 7.7	7.8	1.7 1.7	1.7	<2.5 <2.5	<2.5

Water Quality Monitoring Results at 40_I

Date	Weather	Sea	Sampling	Dept	h (m)	Tempera	ature (°C)	р	Н	Salin	ity ppt	DO Satu	ration (%)	Dissolved O:	kygen (mg/L)	Turbidi	ty(NTU)	Suspended	Solids (mg/L
Date	Condition	Condition*	Time	Бері	11 (111)	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average
1-Jun-09	Sunny	Calm	11:19	Middle	0.09	19.2 19.2	19.2	7.7 7.7	7.7	0.06 0.06	0.06	97.7 97.5	97.6	7.7 7.7	7.7	2.2 2.2	2.2	<2.5 <2.5	<2.5
3-Jun-09	Cloudy	Calm	10:01	Middle	0.09	19.1 19.1	19.1	7.7 7.7	7.7	0.06 0.06	0.06	96.4 96.2	96.3	7.6 7.6	7.6	2.1 2.1	2.1	<2.5 <2.5	<2.5
5-Jun-09	Sunny	Calm	10:13	Middle	0.09	19.1 19.1	19.1	7.6 7.6	7.6	0.05 0.05	0.05	97.1 96.9	97	7.6 7.6	7.6	2.0 2.0	2	<2.5 <2.5	<2.5
8-Jun-09	Cloudy	Calm	10:39	Middle	0.09	19.1 19.1	19.1	7.7 7.7	7.7	0.05 0.05	0.05	98.3 98.1	98.2	7.7 7.7	7.7	1.9 1.9	1.9	<2.5 <2.5	<2.5
10-Jun-09	Cloudy	Calm	10:06	Middle	0.09	19.1 19.2	19.2	7.7 7.7	7.7	0.05 0.05	0.05	97.8 97.6	97.7	7.7 7.7	7.7	2.0 2.0	2	<2.5 <2.5	<2.5
12-Jun-09	Cloudy	Calm	10:01	Middle	0.09	19.0 19.1	19.1	7.6 7.6	7.6	0.05 0.05	0.05	97.0 96.8	96.9	7.6 7.6	7.6	2.1 2.1	2.1	<2.5 <2.5	<2.5
15-Jun-09	Cloudy	Calm	10:22	Middle	0.09	19.1 19.1	19.1	7.7 7.7	7.7	0.05 0.05	0.05	98.1 97.9	98	7.7 7.7	7.7	2.1 2.1	2.1	<2.5 <2.5	<2.5
17-Jun-09	Sunny	Calm	9:55	Middle	0.09	19.1 19.1	19.1	7.7 7.6	7.7	0.05 0.05	0.05	97.3 97.1	97.2	7.7 7.6	7.7	2.2 2.2	2.2	<2.5 <2.5	<2.5
19-Jun-09	Cloudy	Calm	10:11	Middle	0.09	19.0 19.0	19	7.7 7.7	7.7	0.05 0.05	0.05	98.2 98.0	98.1	7.7 7.7	7.7	2.2 2.2	2.2	<2.5 <2.5	<2.5
22-Jun-09	Cloudy	Calm	10:33	Middle	0.09	19.0 19.0	19	7.7 7.7	7.7	0.05 0.05	0.05	96.9 96.7	96.8	7.6 7.6	7.6	2.1 2.1	2.1	<2.5 <2.5	<2.5
24-Jun-09	Rainy	Calm	9:48	Middle	0.09	19.0 19.0	19	7.7 7.7	7.7	0.05 0.05	0.05	97.6 97.4	97.5	7.7 7.7	7.7	2.1 2.1	2.1	<2.5 <2.5	<2.5
26-Jun-09	Rainy	Calm	10:17	Middle	0.09	19.0 19.0	19	7.8 7.7	7.8	0.05 0.05	0.05	98.7 98.5	98.6	7.7 7.7	7.7	2.0 2.0	2	<2.5 <2.5	<2.5
29-Jun-09	Fine	Calm	12:45	Middle	0.09	18.9 18.9	18.9	7.7 7.7	7.7	0.05 0.05	0.05	98.1 97.9	98	7.7 7.7	7.7	2.1 2.1	2.1	<2.5 <2.5	<2.5
30-Jun-09	Cloudy	Calm	10:29	Middle	0.09	19.0 19.0	19	7.8 7.7	7.8	0.05 0.05	0.05	96.4 96.2	96.3	7.6 7.6	7.6	2.2 2.2	2.2	<2.5 <2.5	<2.5

Water Quality Monitoring Results at 40_R

Date	Weather	Sea	Sampling	Dept	h (m)	Tempera	ature (°C)	ŗ	Н	Salin	ity ppt	DO Satu	ration (%)	Dissolved O	xygen (mg/L)	Turbidi	ty(NTU)	Suspended	Solids (mg/L
Date	Condition	Condition*	Time	Бері	11 (111)	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average
1-Jun-09	Sunny	Calm	11:14	Middle	0.2	19.2 19.2	19.2	7.8 7.8	7.8	0.06 0.06	0.06	98.2 98.2	98.2	7.7 7.7	7.7	2.1 2.2	2.2	<2.5 <2.5	<2.5
3-Jun-09	Cloudy	Calm	9:56	Middle	0.2	19.1 19.1	19.1	7.8 7.7	7.8	0.06 0.06	0.06	96.9 96.9	96.9	7.7 7.7	7.7	2.1 2.1	2.1	<2.5 <2.5	<2.5
5-Jun-09	Sunny	Calm	10:07	Middle	0.2	19.1 19.1	19.1	7.7 7.7	7.7	0.05 0.05	0.05	97.6 97.6	97.6	7.7 7.7	7.7	2.1 2.0	2.1	<2.5 <2.5	<2.5
8-Jun-09	Cloudy	Calm	10:34	Middle	0.2	19.1 19.1	19.1	7.8 7.8	7.8	0.05 0.05	0.05	98.8 98.8	98.8	7.8 7.8	7.8	2.0 1.9	2	<2.5 <2.5	<2.5
10-Jun-09	Cloudy	Calm	10:00	Middle	0.2	19.1 19.1	19.1	7.8 7.7	7.8	0.05 0.05	0.05	98.3 98.3	98.3	7.7 7.7	7.7	2.0 1.9	2	<2.5 <2.5	<2.5
12-Jun-09	Cloudy	Calm	9:55	Middle	0.2	19.0 19.0	19	7.7 7.7	7.7	0.05 0.05	0.05	97.5 97.5	97.5	7.7 7.7	7.7	2.1 2.0	2.1	<2.5 <2.5	<2.5
15-Jun-09	Cloudy	Calm	10:17	Middle	0.2	19.1 19.1	19.1	7.8 7.8	7.8	0.05 0.05	0.05	98.6 98.6	98.6	7.8 7.8	7.8	2.1 2.1	2.1	<2.5 <2.5	<2.5
17-Jun-09	Sunny	Calm	9:50	Middle	0.2	19.1 19.1	19.1	7.7 7.7	7.7	0.05 0.05	0.05	97.8 97.8	97.8	7.7 7.7	7.7	2.2 2.2	2.2	7.0 6.0	6.5
19-Jun-09	Cloudy	Calm	10:06	Middle	0.2	19.0 19.0	19	7.8 7.8	7.8	0.05 0.05	0.05	98.7 98.7	98.7	7.8 7.8	7.8	2.2 2.1	2.2	<2.5 <2.5	<2.5
22-Jun-09	Cloudy	Calm	10:27	Middle	0.2	19.0 19.0	19	7.8 7.8	7.8	0.05 0.05	0.05	97.4 97.4	97.4	7.7 7.7	7.7	2.1 2.0	2.1	<2.5 <2.5	<2.5
24-Jun-09	Rainy	Calm	9:43	Middle	0.2	19.0 19.0	19	7.8 7.8	7.8	0.05 0.05	0.05	98.1 98.1	98.1	7.7 7.7	7.7	2.1 2.0	2.1	<2.5 <2.5	<2.5
26-Jun-09	Rainy	Calm	10:12	Middle	0.2	19.0 19.0	19	7.8 7.8	7.8	0.05 0.05	0.05	99.2 99.2	99.2	7.8 7.8	7.8	2.0 1.9	2	<2.5 <2.5	<2.5
29-Jun-09	Fine	Calm	12:39	Middle	0.2	18.9 18.9	18.9	7.8 7.8	7.8	0.05 0.05	0.05	98.6 98.6	98.6	7.8 7.8	7.8	2.1 2.0	2.1	<2.5 <2.5	<2.5
30-Jun-09	Cloudy	Calm	10:24	Middle	0.2	19.0 19.0	19	7.8 7.8	7.8	0.05 0.05	0.05	96.9 96.9	96.9	7.7 7.7	7.7	2.2 2.1	2.2	<2.5 <2.5	<2.5

Water Quality Monitoring Results at CSS_I

Date	Weather	Sea	Sampling	Dept	h (m)	Tempera	ature (°C)	р	Н	Salin	ity ppt	DO Satu	ration (%)	Dissolved O	xygen (mg/L)	Turbidi	ty(NTU)	Suspended	Solids (mg/L
Date	Condition	Condition*	Time	Бері	11 (111)	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average
1-Jun-09	Sunny	Calm	11:26	Middle	0.19	19.0 19.0	19	7.7 7.7	7.7	0.03 0.03	0.03	97.9 97.9	97.9	7.8 7.7	7.8	2.1 2.2	2.2	<2.5 <2.5	<2.5
3-Jun-09	Cloudy	Calm	10:08	Middle	0.19	19.0 19.0	19	7.7 7.7	7.7	0.03 0.03	0.03	96.6 96.6	96.6	7.7 7.7	7.7	2.0 2.1	2.1	<2.5 <2.5	<2.5
5-Jun-09	Sunny	Calm	10:19	Middle	0.19	19.0 19.0	19	7.7 7.7	7.7	0.03 0.03	0.03	97.3 97.3	97.3	7.7 7.7	7.7	2.0 2.1	2.1	<2.5 <2.5	<2.5
8-Jun-09	Cloudy	Calm	10:46	Middle	0.19	19.0 19.0	19	7.7 7.7	7.7	0.03 0.03	0.03	98.5 98.5	98.5	7.8 7.8	7.8	1.9 2.0	2	<2.5 <2.5	<2.5
10-Jun-09	Cloudy	Calm	10:12	Middle	0.19	19.0 19.0	19	7.7 7.7	7.7	0.03 0.03	0.03	98.0 98.0	98	7.8 7.8	7.8	2.0 2.0	2	<2.5 <2.5	<2.5
12-Jun-09	Cloudy	Calm	10:07	Middle	0.19	18.9 18.9	18.9	7.7 7.7	7.7	0.03 0.03	0.03	97.2 97.2	97.2	7.7 7.7	7.7	2.0 2.1	2.1	<2.5 <2.5	<2.5
15-Jun-09	Cloudy	Calm	10:28	Middle	0.19	18.9 19.0	19	7.7 7.7	7.7	0.03 0.03	0.03	98.3 98.3	98.3	7.8 7.8	7.8	2.0 2.0	2	<2.5 <2.5	<2.5
17-Jun-09	Sunny	Calm	10:02	Middle	0.19	18.9 18.9	18.9	7.7 7.7	7.7	0.03 0.03	0.03	97.5 97.5	97.5	7.7 7.7	7.7	2.1 2.2	2.2	<2.5 <2.5	<2.5
19-Jun-09	Cloudy	Calm	10:18	Middle	0.19	18.9 18.9	18.9	7.7 7.7	7.7	0.03 0.03	0.03	98.4 98.4	98.4	7.8 7.8	7.8	2.0 2.1	2.1	<2.5 <2.5	<2.5
22-Jun-09	Cloudy	Calm	10:39	Middle	0.19	18.8 18.8	18.8	7.7 7.7	7.7	0.03 0.03	0.03	97.1 97.1	97.1	7.7 7.7	7.7	2.0 2.0	2	<2.5 <2.5	<2.5
24-Jun-09	Rainy	Calm	9:55	Middle	0.19	18.8 18.8	18.8	7.7 7.7	7.7	0.03 0.03	0.03	97.8 97.8	97.8	7.8 7.7	7.8	2.0 2.0	2	<2.5 <2.5	<2.5
26-Jun-09	Rainy	Calm	10:24	Middle	0.19	18.8 18.8	18.8	7.8 7.8	7.8	0.03 0.03	0.03	98.9 98.9	98.9	7.8 7.8	7.8	1.9 1.9	1.9	<2.5 <2.5	<2.5
29-Jun-09	Fine	Calm	12:51	Middle	0.19	18.8 18.8	18.8	7.7 7.7	7.7	0.03 0.03	0.03	98.3 98.3	98.3	7.8 7.8	7.8	2.0 2.0	2	<2.5 <2.5	<2.5
30-Jun-09	Cloudy	Calm	10:36	Middle	0.19	18.8 18.8	18.8	7.8 7.8	7.8	0.03 0.03	0.03	96.6 96.6	96.6	7.7 7.7	7.7	2.1 2.1	2.1	<2.5 <2.5	<2.5

Water Quality Monitoring Results at TCB_I


Date	Weather	Sea	Sampling	Dept	h (m)	Tempera	ature (°C)	р	Н	Salin	ity ppt	DO Satu	ration (%)	Dissolved O:	kygen (mg/L)	Turbidi	ty(NTU)	Suspended	Solids (mg/L
Date	Condition	Condition*	Time	Бері	11 (111)	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average
1-Jun-09	Sunny	Calm	13:29	Middle	0.35	21.2 21.2	21.2	7.4 7.4	7.4	9.04 9.01	9.03	96.0 95.8	95.9	7.4 7.4	7.4	3.2 3.1	3.2	<2.5 <2.5	<2.5
3-Jun-09	Cloudy	Calm	12:11	Middle	0.35	21.1 21.1	21.1	7.4 7.4	7.4	9.01 8.98	9	94.7 94.5	94.6	7.4 7.4	7.4	3.4 3.3	3.4	<2.5 <2.5	<2.5
5-Jun-09	Sunny	Calm	12:23	Middle	0.35	21.1 21.1	21.1	7.4 7.4	7.4	8.98 8.95	8.97	95.4 95.2	95.3	7.4 7.4	7.4	3.4 3.4	3.4	<2.5 <2.5	<2.5
8-Jun-09	Cloudy	Calm	12:49	Middle	0.35	21.1 21.1	21.1	7.4 7.4	7.4	9.06 9.03	9.05	96.6 96.4	96.5	7.5 7.5	7.5	3.2 3.2	3.2	<2.5 <2.5	<2.5
10-Jun-09	Cloudy	Calm	12:15	Middle	0.35	21.2 21.2	21.2	7.4 7.4	7.4	9.09 9.06	9.08	96.1 95.9	96	7.4 7.4	7.4	3.1 3.1	3.1	<2.5 <2.5	<2.5
12-Jun-09	Cloudy	Calm	12:10	Middle	0.35	21.1 21.1	21.1	7.4 7.4	7.4	9.05 9.02	9.04	95.3 95.1	95.2	7.4 7.4	7.4	3.3 3.3	3.3	<2.5 <2.5	<2.5
15-Jun-09	Cloudy	Calm	12:32	Middle	0.35	21.1 21.1	21.1	7.4 7.4	7.4	9.02 8.99	9.01	96.4 96.2	96.3	7.5 7.4	7.5	3.0 3.1	3.1	<2.5 <2.5	<2.5
17-Jun-09	Sunny	Calm	12:05	Middle	0.35	21.1 21.1	21.1	7.4 7.4	7.4	8.99 8.96	8.98	95.6 95.4	95.5	7.4 7.4	7.4	3.2 3.3	3.3	<2.5 <2.5	<2.5
19-Jun-09	Cloudy	Calm	12:21	Middle	0.35	21.0 21.0	21	7.4 7.4	7.4	9.03 9.00	9.02	96.5 96.3	96.4	7.5 7.5	7.5	3.0 3.1	3.1	<2.5 <2.5	<2.5
22-Jun-09	Cloudy	Calm	12:43	Middle	0.35	21.0 21.0	21	7.4 7.4	7.4	9.05 9.02	9.04	95.2 95.0	95.1	7.4 7.4	7.4	2.8 2.9	2.9	<2.5 <2.5	<2.5
24-Jun-09	Rainy	Calm	11:58	Middle	0.35	21.0 21.0	21	7.5 7.5	7.5	9.12 9.09	9.11	95.9 95.7	95.8	7.4 7.4	7.4	3.2 3.3	3.3	<2.5 <2.5	<2.5
26-Jun-09	Rainy	Calm	12:27	Middle	0.35	21.0 21.0	21	7.5 7.5	7.5	9.24 9.21	9.23	97.0 96.8	96.9	7.5 7.5	7.5	3.5 3.5	3.5	<2.5 <2.5	<2.5
29-Jun-09	Fine	Calm	14:54	Middle	0.35	20.9 20.9	20.9	7.5 7.5	7.5	9.16 9.13	9.15	96.4 96.2	96.3	7.5 7.4	7.5	3.4 3.4	3.4	<2.5 <2.5	<2.5
30-Jun-09	Cloudy	Calm	12:39	Middle	0.35	21.0 21.0	21	7.5 7.5	7.5	9.24 9.21	9.23	94.7 94.5	94.6	7.4 7.4	7.4	3.7 3.6	3.7	<2.5 <2.5	<2.5


Water Quality Monitoring Results at TCB_R


Date	Weather	Sea	Sampling	Dept	h (m)	Tempera	ature (°C)	р	Н	Salin	ity ppt	DO Satu	ration (%)	Dissolved O	xygen (mg/L)	Turbidi	ty(NTU)	Suspended	Solids (mg/L
Date	Condition	Condition*	Time	Бері	11 (111)	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average
1-Jun-09	Sunny	Calm	13:24	Middle	0.2	21.2 21.2	21.2	7.2 7.2	7.2	19.08 19.10	19.09	97.6 97.5	97.6	7.4 7.4	7.4	4.4 4.3	4.4	<2.5 <2.5	<2.5
3-Jun-09	Cloudy	Calm	12:06	Middle	0.2	21.2 21.2	21.2	7.2 7.2	7.2	19.05 19.07	19.06	96.3 96.2	96.3	7.3 7.3	7.3	4.5 4.4	4.5	<2.5 <2.5	<2.5
5-Jun-09	Sunny	Calm	12:18	Middle	0.2	21.2 21.2	21.2	7.2 7.2	7.2	19.02 19.04	19.03	97.0 96.9	97	7.4 7.4	7.4	4.4 4.3	4.4	<2.5 <2.5	<2.5
8-Jun-09	Cloudy	Calm	12:44	Middle	0.2	21.2 21.2	21.2	7.2 7.2	7.2	19.10 19.12	19.11	98.2 98.1	98.2	7.4 7.4	7.4	4.2 4.1	4.2	<2.5 <2.5	<2.5
10-Jun-09	Cloudy	Calm	12:10	Middle	0.2	21.2 21.2	21.2	7.2 7.2	7.2	19.13 19.15	19.14	97.7 97.6	97.7	7.4 7.4	7.4	4.0 3.9	4	<2.5 <2.5	<2.5
12-Jun-09	Cloudy	Calm	12:05	Middle	0.2	21.1 21.1	21.1	7.2 7.2	7.2	19.09 19.11	19.1	96.9 96.8	96.9	7.4 7.4	7.4	4.1 4.0	4.1	<2.5 <2.5	<2.5
15-Jun-09	Cloudy	Calm	12:27	Middle	0.2	21.2 21.2	21.2	7.2 7.2	7.2	19.03 19.05	19.04	98.0 97.9	98	7.4 7.4	7.4	3.8 3.7	3.8	<2.5 <2.5	<2.5
17-Jun-09	Sunny	Calm	12:00	Middle	0.2	21.1 21.1	21.1	7.2 7.2	7.2	19.00 19.02	19.01	97.2 97.1	97.2	7.4 7.4	7.4	4.1 4.0	4.1	<2.5 <2.5	<2.5
19-Jun-09	Cloudy	Calm	12:16	Middle	0.2	21.1 21.1	21.1	7.2 7.2	7.2	19.02 19.04	19.03	98.1 98.0	98.1	7.4 7.4	7.4	4.0 3.9	4	<2.5 <2.5	<2.5
22-Jun-09	Cloudy	Calm	12:38	Middle	0.2	21.1 21.1	21.1	7.2 7.2	7.2	19.04 19.06	19.05	96.8 96.7	96.8	7.4 7.4	7.4	3.9 3.8	3.9	<2.5 <2.5	<2.5
24-Jun-09	Rainy	Calm	11:53	Middle	0.2	21.0 21.1	21.1	7.2 7.2	7.2	19.11 19.13	19.12	97.5 97.4	97.5	7.4 7.4	7.4	4.1 4.0	4.1	<2.5 <2.5	<2.5
26-Jun-09	Rainy	Calm	12:22	Middle	0.2	21.1 21.1	21.1	7.3 7.3	7.3	19.15 19.17	19.16	98.6 98.5	98.6	7.4 7.4	7.4	4.3 4.3	4.3	<2.5 <2.5	<2.5
29-Jun-09	Fine	Calm	14:49	Middle	0.2	21.0 21.0	21	7.2 7.3	7.3	19.07 19.09	19.08	98.0 97.9	98	7.4 7.4	7.4	4.1 4.1	4.1	<2.5 <2.5	<2.5
30-Jun-09	Cloudy	Calm	12:34	Middle	0.2	21.0 21.1	21.1	7.3 7.3	7.3	19.15 19.17	19.16	96.3 96.2	96.3	7.3 7.3	7.3	4.3 4.4	4.4	<2.5 <2.5	<2.5


Water Quality Monitoring Results at TCS_I


Date	Weather	Sea	Sampling	Dept	h (m)	Tempera	ature (°C)	р	Н	Salin	ity ppt	DO Satu	ration (%)	Dissolved O	xygen (mg/L)	Turbidi	ty(NTU)	Suspended	Solids (mg/L
Date	Condition	Condition*	Time	Бері	11 (111)	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average	Value	Average
1-Jun-09	Sunny	Calm	13:06	Middle	0.2	19.0 19.0	19	7.4 7.5	7.5	0.02 0.02	0.02	97.0 96.6	96.8	7.7 7.6	7.7	1.9 1.8	1.9	<2.5 <2.5	<2.5
3-Jun-09	Cloudy	Calm	11:48	Middle	0.2	18.9 18.9	18.9	7.4 7.4	7.4	0.02 0.02	0.02	95.7 95.3	95.5	7.6 7.6	7.6	1.7 1.6	1.7	<2.5 <2.5	<2.5
5-Jun-09	Sunny	Calm	12:00	Middle	0.2	18.9 18.9	18.9	7.4 7.4	7.4	0.02 0.02	0.02	96.4 96.0	96.2	7.6 7.6	7.6	1.6 1.5	1.6	<2.5 <2.5	<2.5
8-Jun-09	Cloudy	Calm	12:26	Middle	0.2	18.9 18.9	18.9	7.4 7.4	7.4	0.02 0.02	0.02	97.6 97.2	97.4	7.7 7.7	7.7	1.6 1.5	1.6	<2.5 <2.5	<2.5
10-Jun-09	Cloudy	Calm	11:53	Middle	0.2	18.9 19.0	19	7.4 7.4	7.4	0.02 0.02	0.02	97.1 96.7	96.9	7.7 7.7	7.7	1.5 1.4	1.5	<2.5 <2.5	<2.5
12-Jun-09	Cloudy	Calm	11:48	Middle	0.2	18.8 18.9	18.9	7.4 7.4	7.4	0.02 0.02	0.02	96.3 95.9	96.1	7.6 7.6	7.6	1.6 1.5	1.6	<2.5 <2.5	<2.5
15-Jun-09	Cloudy	Calm	12:09	Middle	0.2	18.9 18.9	18.9	7.4 7.4	7.4	0.02 0.02	0.02	97.4 97.0	97.2	7.7 7.7	7.7	1.6 1.5	1.6	<2.5 <2.5	<2.5
17-Jun-09	Sunny	Calm	11:42	Middle	0.2	18.9 18.9	18.9	7.4 7.4	7.4	0.02 0.02	0.02	96.6 96.2	96.4	7.7 7.6	7.7	1.7 1.6	1.7	<2.5 <2.5	<2.5
19-Jun-09	Cloudy	Calm	11:58	Middle	0.2	18.8 18.8	18.8	7.5 7.5	7.5	0.02 0.02	0.02	97.5 97.1	97.3	7.7 7.7	7.7	1.6 1.5	1.6	<2.5 <2.5	<2.5
22-Jun-09	Cloudy	Calm	12:20	Middle	0.2	18.8 18.8	18.8	7.4 7.4	7.4	0.02 0.02	0.02	96.2 95.8	96	7.6 7.6	7.6	1.5 1.4	1.5	<2.5 <2.5	<2.5
24-Jun-09	Rainy	Calm	11:35	Middle	0.2	18.8 18.8	18.8	7.5 7.5	7.5	0.02 0.02	0.02	96.9 96.5	96.7	7.7 7.6	7.7	1.6 1.5	1.6	<2.5 <2.5	<2.5
26-Jun-09	Rainy	Calm	12:04	Middle	0.2	18.8 18.8	18.8	7.5 7.5	7.5	0.02 0.02	0.02	98.0 97.6	97.8	7.7 7.7	7.7	1.5 1.4	1.5	<2.5 <2.5	<2.5
29-Jun-09	Fine	Calm	14:32	Middle	0.2	18.7 18.7	18.7	7.5 7.5	7.5	0.02 0.02	0.02	97.4 97.0	97.2	7.7 7.7	7.7	1.6 1.5	1.6	<2.5 <2.5	<2.5
30-Jun-09	Cloudy	Calm	12:16	Middle	0.2	18.8 18.8	18.8	7.5 7.5	7.5	0.02 0.02	0.02	95.7 95.3	95.5	7.6 7.6	7.6	1.7 1.6	1.7	<2.5 <2.5	<2.5















Dissolved Oxygen



Title Contract No. HY/2003/19
Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha


Graphical Presentation of Water Quality


Monitoring Results


N.T.S Project
No. MA6030


Date Appendix
F


















Turbidity




Title Contract No. HY/2003/19
Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha


Graphical Presentation of Water Quality
Monitoring Results


Scale N.T.S Project
No. MA6030


Date
Jun 09


F















Suspended Solids



Title Contract No. HY/2003/19
Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha

Graphical Presentation of Water Quality

Monitoring Results

N.T.S Project
No. MA6030

Date Appendix
F



APPENDIX G QUALITY CONTROL REPORTS FOR LABORATORY ANALYSIS





APPLICANT: Cinotech Consultants Limited

RM 1710, Technology Park,

18 On Lai Street,

Shatin, N.T., Hong Kong

Laboratory No.: 08653

Date of Issue: 2009/06/02 Date Received: 2009/06/01

Date Tested: 2009/06/01 Date Completed: 2009/06/02

1 of 1

Page:

ATTN: Mr. Henry Leung

Sampling Site: Tung Chung Road

Project No.: MA6030 Sampling Date: 2009/06/01

Number of Sample: 38

Custody No.: MA6030/90601

Total Suspended Solids	Duplicate Analysis			QC Recovery, %
Sampling Point	Trial 1, mg/L	Trial 2, mg/L	Difference,	
26_I	<2.5	<2.5	N/A	101

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

Laboratory Manager





APPLICANT: Cinotech Consultants Limited

RM 1710, Technology Park,

18 On Lai Street,

Shatin, N.T., Hong Kong

Laboratory No.: 08670

Date of Issue: 2009/06/04 Date Received: 2009/06/03

Date Tested: 2009/06/03 Date Completed: 2009/06/04

1 of 1

Page:

ATTN: Mr. Henry Leung

Sampling Site: Tung Chung Road

Project No.: MA6030 Sampling Date: 2009/06/03

Number of Sample: 38

Custody No.: MA6030/90603

Total Suspended Solids	Duplicate Analysis			QC Recovery, %
Sampling Point	Trial 1, mg/L	Trial 2, mg/L	Difference,	
26_I	<2.5	<2.5	N/A	106

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

Laboratory Manager





APPLICANT: Cinotech Consultants Limited

RM 1710, Technology Park,

18 On Lai Street,

Shatin, N.T., Hong Kong

Laboratory No.: 08683

Date of Issue: 2009/06/08 Date Received: 2009/06/05

Date Tested: 2009/06/05 Date Completed: 2009/06/08

Page: 1 of 1

ATTN: Mr. Henry Leung

Sampling Site: Tung Chung Road

Project No.: MA6030 Sampling Date: 2009/06/05

Number of Sample: 38

Custody No.: MA6030/90605

Total Suspended Solids	Duplicate Analysis			QC Recovery, %
Sampling Point	Trial 1, mg/L	Trial 2, mg/L	Difference, %	
26_I	<2.5	<2.5	N/A	103

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

Laboratory Manager





APPLICANT: Cinotech Consultants Limited

RM 1710, Technology Park,

18 On Lai Street,

Shatin, N.T., Hong Kong

Laboratory No.: 08696

Date of Issue: 2009/06/09 Date Received: 2009/06/08

Date Tested: 2009/06/08 Date Completed: 2009/06/09

Page: 1 of 1

ATTN: Mr. Henry Leung

Sampling Site: Tung Chung Road

Project No.: MA6030 Sampling Date: 2009/06/08

Number of Sample: 38

Custody No.: MA6030/90608

Total Suspended Solids	Duplicate Analysis			QC Recovery, %
Sampling Point	Trial 1, mg/L	Trial 2, mg/L	Difference,	
26 I	<2.5	<2.5	N/A	88

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

Laboratory Manager





APPLICANT: Cinotech Consultants Limited

RM 1710, Technology Park,

18 On Lai Street,

Shatin, N.T., Hong Kong

Laboratory No.: 08707

Date Tested:

Page:

Date of Issue: 2009/06/11 Date Received: 2009/06/10

Date Completed: 2009/06/11

2009/06/10

1 of 1

ATTN: Mr. Henry Leung

Sampling Site: Tung Chung Road

Project No.: MA6030 Sampling Date: 2009/06/10

Number of Sample: 38

Custody No.: MA6030/90610

Total Suspended Solids	Duplicate Analysis			QC Recovery, %
Sampling Point	Trial 1, mg/L	Trial 2, mg/L	Difference, %	
26_I	<2.5	<2.5	N/A	95

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

Laboratory Manager





APPLICANT: Cinotech Consultants Limited

RM 1710, Technology Park,

18 On Lai Street,

Shatin, N.T., Hong Kong

Laboratory No.: 08722

Date of Issue: 2009/06/15 Date Received: 2009/06/12

Date Tested: 2009/06/12 Date Completed: 2009/06/15

Page: 1 of 1

ATTN: Mr. Henry Leung

Sampling Site: Tung Chung Road

Project No.: MA6030 Sampling Date: 2009/06/12

Number of Sample: 38

Custody No.: MA6030/90612

Total Suspended Solids	Duplicate Analysis			QC Recovery, %
Sampling Point	Trial 1, mg/L	Trial 2, mg/L	Difference, %	
26_I	<2.5	<2.5	N/A	98

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

Laboratory Manager

Patrablee





APPLICANT: Cinotech Consultants Limited

RM 1710, Technology Park,

18 On Lai Street,

Shatin, N.T., Hong Kong

Laboratory No.: 08740

Date of Issue: 2009/06/16 Date Received: 2009/06/15

Date Tested: 2009/06/15 2009/06/16

Page: 1 of 1

Date Completed:

ATTN: Mr. Henry Leung

Sampling Site: Tung Chung Road

Project No.: MA6030 2009/06/15 Sampling Date:

Number of Sample: 38

Custody No .: MA6030/90615

Total Suspended Solids	Duplicate Analysis			QC Recovery, %
Sampling Point	Trial 1, mg/L	Trial 2, mg/L	Difference,	
26_I	<2.5	<2.5	N/A	89

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

Laboratory Manager





APPLICANT: Cinotech Consultants Limited

RM 1710, Technology Park,

18 On Lai Street,

Shatin, N.T., Hong Kong

Laboratory No.: 08755

Date of Issue: 2009/06/18 Date Received: 2009/06/17

Date Tested: 2009/06/17

2009/06/18

Page: 1 of 1

Date Completed:

ATTN: Mr. Henry Leung

Sampling Site: Tung Chung Road

Project No.: MA6030 Sampling Date: 2009/06/17

Number of Sample: 38

Custody No.: MA6030/90617

Total Suspended Solids	Duplicate Analysis			QC Recovery, %
Sampling Point	Trial 1, mg/L	Trial 2, mg/L	Difference,	
26_I	<2.5	<2.5	N/A	98

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

Laboratory Manager





APPLICANT: Cinotech Consultants Limited

RM 1710, Technology Park,

18 On Lai Street,

Shatin, N.T., Hong Kong

Laboratory No.: 08773

Date of Issue: 2009/06/22 Date Received: 2009/06/19

2009/06/22

Date Tested: 2009/06/19

Page: 1 of 1

Date Completed:

ATTN: Mr. Henry Leung

Sampling Site: Tung Chung Road

Project No.: MA6030 Sampling Date: 2009/06/19

Number of Sample: 38

Custody No.: MA6030/90619

Total Suspended Solids	Duplicate Analysis			QC Recovery, %
Sampling Point	Trial 1, mg/L	Trial 2, mg/L	Difference,	
26_I	<2.5	<2.5	N/A	94

PREPARED AND CHECKED BY:

atiablese

For and On Behalf of WELLAB Ltd.

PATRICK TSE

Laboratory Manager





APPLICANT: Cinotech Consultants Limited

RM 1710, Technology Park,

18 On Lai Street,

Shatin, N.T., Hong Kong

Laboratory No.: 08778

Page:

Date of Issue: 2009/06/23 Date Received: 2009/06/22

Date Tested: 2009/06/22 Date Completed: 2009/06/23

1 of 1

ATTN: Mr. Henry Leung

Sampling Site: Tung Chung Road

Project No.: MA6030 Sampling Date: 2009/06/22

Number of Sample: 38

Custody No.: MA6030/90622

Total Suspended Solids	Duplicate Analysis			QC Recovery, %
Sampling Point	Trial 1, mg/L	Trial 2, mg/L	Difference, %	
26_I	<2.5	<2.5	N/A	99

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

Laboratory Manager





APPLICANT: Cinotech Consultants Limited

RM 1710, Technology Park,

18 On Lai Street,

Shatin, N.T., Hong Kong

Laboratory No.: 08788

Date of Issue: 2009/06/24 Date Received: 2009/06/24

Date Tested: 2009/06/24 Date Completed: 2009/06/24

ATTN: Mr. Henry Leung Page: 1 of 1

Sampling Site: Tung Chung Road

Project No.: MA6030 Sampling Date: 2009/06/24

Number of Sample: 38

Custody No.: MA6030/90624

Total Suspended Solids	Duplicate Analysis			QC Recovery, %
Sampling Point	Trial 1, mg/L	Trial 2, mg/L	Difference, %	
26_I	<2.5	<2.5	N/A	96

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

Laboratory Manager





APPLICANT: Cinotech Consultants Limited

RM 1710, Technology Park,

18 On Lai Street,

Shatin, N.T., Hong Kong

Laboratory No.: 08808

Page:

Date of Issue: 2009/06/29 Date Received: 2009/06/26

Date Tested: 2009/06/26 Date Completed: 2009/06/29

1 of 1

ATTN: Mr. Henry Leung

Sampling Site: Tung Chung Road

Project No.: MA6030 Sampling Date: 2009/06/26

Number of Sample: 38

Custody No.: MA6030/90626

Total Suspended Solids	Duplicate Analysis			QC Recovery, %
Sampling Point	Trial 1, mg/L	Trial 2, mg/L	Difference,	
26_I	<2.5	<2.5	N/A	91

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

Laboratory Manager





APPLICANT: Cinotech Consultants Limited

RM 1710, Technology Park,

18 On Lai Street,

Shatin, N.T., Hong Kong

Laboratory No.: 08818

Date of Issue: 2009/06/30 Date Received: 2009/06/29

Date Tested: 2009/06/29 Date Completed: 2009/06/30

1 of 1

Page:

ATTN: Mr. Henry Leung

Sampling Site: Tung Chung Road

Project No.: MA6030 Sampling Date: 2009/06/29

Number of Sample: 38

Custody No.: MA6030/90629

Total Suspended Solids	Du	plicate Anal	QC Recovery, %		
Sampling Point	Trial 1, mg/L	Trial 2, mg/L	Difference, %		
26_I	<2.5	<2.5	N/A	92	

PREPARED AND CHECKED BY: For and On Behalf of WELLAB Ltd.

PATRICK TSE

Laboratory Manager

Patrile





APPLICANT: Cinotech Consultants Limited

RM 1710, Technology Park,

18 On Lai Street,

Shatin, N.T., Hong Kong

Laboratory No.: 08826

Page:

Date of Issue: 2009/07/02 Date Received: 2009/06/30

Date Tested: 2009/06/30 Date Completed: 2009/07/02

1 of 1

ATTN: Mr. Henry Leung

Sampling Site: Tung Chung Road

Project No.: MA6030 Sampling Date: 2009/06/30

Number of Sample: 38

Custody No.: MA6030/90630

Total Suspended Solids	Du	plicate Anal	QC Recovery, %		
Sampling Point	Trial 1, mg/L	Trial 2, mg/L	Difference,		
26_I	<2.5	<2.5	N/A	87	

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

Laboratory Manager

APPENDIX H SUMMARY OF EXCEEDANCES

Contract No. HY/2003/19

Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha - Exceedance Report Report No. $90605W_90601_S$

Part A – Exceedance Summary Tables

Table 1: Parameter – Suspended Solids (mg/L)

		Exceedances Criteria						Action	
Location	Measured Value	Action value	120% of Reference value*	Limit Value	130% of Reference Value*	Action / Limit Levels	Justification [*]	Validity (Y/N)	Taken (Y/N)
27_I	2.5	2.1	3.0	3.0	3.25	Action	(2) & (4)	N	N

*Remarks (1) – No cons

(1) – No construction activity was observed.

- (2) No pollution discharge from construction activity was observed.
- (3) Natural humus or mosses was observed.
- $(4) Reference\ point\ value\ already\ exceeded\ either\ the\ Action\ or\ Limit\ Levels.$

Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha - Exceedance Report Report No. $90605W_90603_S$

Part A – Exceedance Summary Tables

Table 1: Parameter – Suspended Solids (mg/L)

			Exceedan	ces Criteri	ia				Action
Stream Location	Measured Value	Action value	120% of Reference value*	Limit Value	130% of Reference Value*	Action / Limit Levels	Justification [*]	Validity (Y/N)	Taken (Y/N)
27_I	2.5	2.1	3.0	3.0	3.25	Action	(2) & (4)	N	N

*Remarks (1) - No

(1) – No construction activity was observed.

- (2) No pollution discharge from construction activity was observed.
- (3) Natural humus or mosses was observed.
- $(4) Reference\ point\ value\ already\ exceeded\ either\ the\ Action\ or\ Limit\ Levels.$

Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha - Exceedance Report Report No. $90609W_90605_S$

Part A – Exceedance Summary Tables

Table 1: Parameter – Suspended Solids (mg/L)

			Exceedan	ces Criteri	ia				Action
Stream Location	Measured Value	Action value	120% of Reference value*	Limit Value	130% of Reference Value*	Action / Limit Levels	Justification*	Validity (Y/N)	Taken (Y/N)
27_I	2.5	2.1	3.0	3.0	3.25	Action	(2) & (4)	N	N

*Remarks (1) – No construction activity was observed.

- (2) No pollution discharge from construction activity was observed.
- (3) Natural humus or mosses was observed.
- $(4) Reference\ point\ value\ already\ exceeded\ either\ the\ Action\ or\ Limit\ Levels.$

Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha - Exceedance Report Report No. $90615W_90608_S$

Part A – Exceedance Summary Tables

Table 1: Parameter – Suspended Solids (mg/L)

			Exceedan	ces Criteri	ia				Action
Stream Location	Measured Value	Action value	120% of Reference value*	Limit Value	130% of Reference Value*	Action / Limit Levels	Justification*	Validity (Y/N)	Taken (Y/N)
27_I	2.5	2.1	3.0	3.0	3.25	Action	(2) & (4)	N	N

*Remarks (1) - No c

(1) – No construction activity was observed.

- (2) No pollution discharge from construction activity was observed.
- (3) Natural humus or mosses was observed.
- $(4) Reference\ point\ value\ already\ exceeded\ either\ the\ Action\ or\ Limit\ Levels.$

Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha - Exceedance Report Report No. $90615W_90610_S$

Part A – Exceedance Summary Tables

Table 1: Parameter – Suspended Solids (mg/L)

			Exceedan	ces Criteri	ia				Action
Stream Location	Measured Value	Action value	120% of Reference value [*]	Limit Value	130% of Reference Value [*]	Action / Limit Levels	Justification [*]	Validity (Y/N)	Taken (Y/N)
27_I	2.5	2.1	3.0	3.0	3.25	Action	(2) & (4)	N	N

*Remarks

- (1) No construction activity was observed.
- (2) No pollution discharge from construction activity was observed.
- (3) Natural humus or mosses was observed.
- $(4) Reference\ point\ value\ already\ exceeded\ either\ the\ Action\ or\ Limit\ Levels.$

Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha - Exceedance Report Report No. $90619W_90612_S$

Part A – Exceedance Summary Tables

Table 1: Parameter – Suspended Solids (mg/L)

			Exceedan	ces Criteri	ia				Action
Stream Location	Measured Value	Action value	120% of Reference value*	Limit Value	130% of Reference Value*	Action / Limit Levels	Justification [*]	Validity (Y/N)	Taken (Y/N)
27_I	2.5	2.1	3.0	3.0	3.25	Action	(2) & (4)	N	N

*Remarks (1) – No construction activity was observed.

- (2) No pollution discharge from construction activity was observed.
- (3) Natural humus or mosses was observed.
- (4) Reference point value already exceeded either the Action or Limit Levels.

Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha - Exceedance Report Report No. $90619W_90615_S$

Part A – Exceedance Summary Tables

Table 1: Parameter – Suspended Solids (mg/L)

			Exceedan	ces Criteri	ia				Action
Stream Location	Measured Value	Action value	120% of Reference value*	Limit Value	130% of Reference Value*	Action / Limit Levels	Justification [*]	Validity (Y/N)	Taken (Y/N)
27_I	2.5	2.1	3.0	3.0	3.25	Action	(2) & (4)	N	N

*Remarks

- (1) No construction activity was observed.
- (2) No pollution discharge from construction activity was observed.
- (3) Natural humus or mosses was observed.
- $(4) Reference\ point\ value\ already\ exceeded\ either\ the\ Action\ or\ Limit\ Levels.$

Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha - Exceedance Report Report No. $90622W_90617_S$

Part A – Exceedance Summary Tables

Table 1: Parameter – Suspended Solids (mg/L)

			Exceedan	ces Criteri	ia				Action
Stream Location	Measured Value	Action value	120% of Reference value*	Limit Value	130% of Reference Value*	Action / Limit Levels	Justification [*]	Validity (Y/N)	Taken (Y/N)
27_I	2.5	2.1	3.0	3.0	3.25	Action	(2) & (4)	N	N

*Remarks (1) - No

(1) – No construction activity was observed.

- (2) No pollution discharge from construction activity was observed.
- (3) Natural humus or mosses was observed.
- (4) Reference point value already exceeded either the Action or Limit Levels.

Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha - Exceedance Report Report No. $90624W_90619_S$

Part A – Exceedance Summary Tables

Table 1: Parameter – Suspended Solids (mg/L)

			Exceedan	ces Criteri	ia				Action
Stream Location	Measured Value	Action value	120% of Reference value*	Limit Value	130% of Reference Value*	Action / Limit Levels	Justification [*]	Validity (Y/N)	Taken (Y/N)
27_I	2.5	2.1	3.0	3.0	3.25	Action	(2) & (4)	N	N

*Remarks $(1) - No \ cons$

(1) – No construction activity was observed.

- (2) No pollution discharge from construction activity was observed.
- (3) Natural humus or mosses was observed.
- $(4) Reference\ point\ value\ already\ exceeded\ either\ the\ Action\ or\ Limit\ Levels.$

Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha - Exceedance Report Report No. $90624W_90622_S$

Part A – Exceedance Summary Tables

Table 1: Parameter – Suspended Solids (mg/L)

				Exceedan	ces Criteri	ia				Action
	tream cation	Measured Value	Action value	120% of Reference value*	Limit Value	130% of Reference Value*	Action / Limit Levels	Justification*	Validity (Y/N)	Taken (Y/N)
2	27_I	2.5	2.1	3.0	3.0	3.25	Action	(2) & (4)	N	N

*Remarks

- (1) No construction activity was observed.
- (2) No pollution discharge from construction activity was observed.
- (3) Natural humus or mosses was observed.
- $(4) Reference\ point\ value\ already\ exceeded\ either\ the\ Action\ or\ Limit\ Levels.$

Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha - Exceedance Report Report No. $90703W_90624_S$

Part A – Exceedance Summary Tables

Table 1: Parameter – Suspended Solids (mg/L)

			Exceedan	ces Criteri	ia				Action
Stream Location	Measured Value	Action value	120% of Reference value*	Limit Value	130% of Reference Value*	Action / Limit Levels	Justification [*]	Validity (Y/N)	Taken (Y/N)
27_I	2.5	2.1	3.0	3.0	3.25	Action	(2) & (4)	N	N

*Remarks (1) – No construction activity was observed.

- (2) No pollution discharge from construction activity was observed.
- (3) Natural humus or mosses was observed.
- $(4) Reference\ point\ value\ already\ exceeded\ either\ the\ Action\ or\ Limit\ Levels.$

Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha - Exceedance Report Report No. $90703W_90626_S$

Part A – Exceedance Summary Tables

Table 1: Parameter – Suspended Solids (mg/L)

			Exceedan	ces Criteri	ia				Action
Stream Location	Measured Value	Action value	120% of Reference value*	Limit Value	130% of Reference Value*	Action / Limit Levels	Justification [*]	Validity (Y/N)	Taken (Y/N)
27_I	2.5	2.1	3.0	3.0	3.25	Action	(2) & (4)	N	N

*Remarks (1) - No co

(1) – No construction activity was observed.

- (2) No pollution discharge from construction activity was observed.
- (3) Natural humus or mosses was observed.
- (4) Reference point value already exceeded either the Action or Limit Levels.

Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha - Exceedance Report Report No. $90707W_90629_S$

Part A – Exceedance Summary Tables

Table 1: Parameter – Suspended Solids (mg/L)

			Exceedan	ces Criteri	ia				Action
Stream Location	Measured Value	Action value	120% of Reference value*	Limit Value	130% of Reference Value*	Action / Limit Levels	Justification [*]	Validity (Y/N)	Taken (Y/N)
27_I	2.5	2.1	3.0	3.0	3.25	Action	(2) & (4)	N	N

*Remarks (1) – No construction activity was observed.

- (2) No pollution discharge from construction activity was observed.
- (3) Natural humus or mosses was observed.
- $(4) Reference\ point\ value\ already\ exceeded\ either\ the\ Action\ or\ Limit\ Levels.$

Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha - Exceedance Report Report No. $90707W_90630_S$

Part A – Exceedance Summary Tables

Table 1: Parameter – Suspended Solids (mg/L)

				Exceedan	ces Criteri	ia				Action
Stream Location	Measured Value	Action value	120% of Reference value*	Limit Value	130% of Reference Value*	Action / Limit Levels	Justification*	Validity (Y/N)	Taken (Y/N)	
27_I	2.5	2.1	3.0	3.0	3.25	Action	(2) & (4)	N	N	

*Remarks (1) – No construction activity was observed.

(2) – No pollution discharge from construction activity was observed.

- (3) Natural humus or mosses was observed.
- $(4) Reference\ point\ value\ already\ exceeded\ either\ the\ Action\ or\ Limit\ Levels.$

APPENDIX I SITE AUDIT SUMMARY

Inspection Information

Checklist Reference Number	90604
Date	04 June 2009 (Thursday)
Time	09:00 – 13:15

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-
Ref. No.	Remarks/Observations	Related Item No.
90604-O03	A. Water Quality Silt and sediment was observed discharging to the catchwater from the exposed slope especially at underneath STR 17, 18. The Contractor was reminded to cover/hydroseed the exposed slope immediately especially during rainstorm.	В8
90604-O04	 Stream water at Stream 20 was observed diverted properly around the works. The Contractor was reminded to review and re-arrange the stream diversion to prevent any wastewater discharging out. 	B15
90604-O05	 Seepage of silty water from the hole of concrete bund was observed at SD5-11. The Contractor was reminded to provide mitigation measures to prevent any wastewater from discharging to the downstream. 	B15
90604-O06	Concrete debris was observed at Steam 21 due to the concrete breaking before. The Contractor was reminded to clear the debris and ensure the stream water in good condition	B15
	B. Air Quality	
	No environmental deficiency was identified during site inspection.	
	C. Noise	
	No environmental deficiency was identified during site inspection.	
	D. Waste / Chemical Management	
90604 - O01	• Empty oil containers were observed at underneath STR 7, near Stream 20, 21 and SD4-7. The Contractor was reminded to dispose them as chemical waste.	E2ii.
90604-O02	• Discarded hose were observed at Shan Shek Wan . The Contractor was reminded to clear them.	E4ii.
	E. Ecology	
	No environmental deficiency was identified during site inspection.	
	F. Others	
	 All environmental deficiencies identified in previous audit session were not improved/rectified by the Contractor. Follow-up action is needed for the outstanding items. Item 90527-R19 was not observed during the site inspection. 	

	Reminders	Related Item No.
	The Contractor was reminded to implement the following preventive measures:	
	A. Water Quality	
90604-R07	Provide sand bag at the culvert at Shan Shek Wan.	B2
90604-R12	• Clear the construction waste, silt, debris and sediment in the culvert and U-channel along Tung Chung Road (Southern and Northern Sections) especially at STR17, Shan Shek Wan, CH7000, near Stream 20, Pak Kung Au, SD7-13, SD6-12, SD5-11, SD4-7 and underneath STR7.	BI and B18
90604-R17	• Properly cover/compact the exposed area at between Stream 20 and 19, near stream 21, SD4-7, SD6-12 and underneath STR 14 when the works were not undertaken.	В8
90604-R18	• Clear the stagnant water at the wheel washing bay (abandoned) at Site Office, pit area at near SD7-13 and the hole for handrail along Southern Section of Tung Chung Road.	B11

	B. Air Quality	
90604-R10	• Properly maintain the slopes which have been hydroseeded along Tung Chung Road (Southern and Northern Section) especially after the rainstorm.	C13
	C. Waste / Chemical Management	
90604-R08	Clear C&D waste and discarded cement bags at underneath STR7.	E4ii.
90604-R09	Clear general refuse at underneath STR7.	Eliii
	• Clear the discarded "protection material for hydroseed" that was hanging on the trees along	E4ii
90604-R11	Southern Section of Tung Chung Road.	15411
90604-R13	• Clear C&D waste at near SD7-13, SD6-12, SD5-11 and SD4-7.	E4ii.
90604-R15	Clear vegetation waste along Tung Chung Road especially near the catchwater.	E4ii.
90604-R16	Keep clear and sort C&D waste at Shan Shek Wan.	E4ii
	D. Ecology	
90604-R14	Clear C&D waste and general refuse at Stream 21, 22, 27, 30, 34 and 36-38.	FI
	E. General	
90604-G19	Provide mitigation measures at between the outstanding construction area and paved road to prevent any mud from carrying to the public road.	B2 and C2

Ref. No.	Proposed Completion Date	Completion Date	Remarks
90604-001			
90604-O02			
90604-O03			
90604-O04			
90604-O05			
90604-O06	·		
90604-R07			
90604_R08			
90604-R09			
90604-R10	10 June 2009		
90604-R11			
90604-R12			
90604-R13			
90604-R14			
90604-R15			
90604-R16			
90604-R17			
90604-R18			
90604-G19			

	Name	Signature	Date
Recorded by	Ivy Tam	Turk	4 June 2009
Checked by	Dr. Priscilla Choy	127	4 June 2009

Inspection Information

Inspection into matter	
Checklist Reference Number	90610
Date	10 June 2009 (Wednesday)
Time	09:00 – 13:15

		Related
Ref. No.	Non-Compliance	Item No.
	None identified	Dulated
		Related
Ref. No.	Remarks/Observations	Item No.
	A. Water Quality	
90610-003	• Silt and sediment was observed discharging to the catchwater from the exposed slope due to the soil erosion especially at underneath STR 16, 17 and 18. The Contractor was reminded to provide mitigation measures to protect the slope (In-progress).	В8
90610-004	• Stream water at Stream 20 was observed not diverted properly around the works. The Contractor was reminded to review and re-arrange the stream diversion to prevent any wastewater discharging out.	B15
90610-O05	 Seepage of silty water from the hole of concrete bund was observed at SD5-11. The Contractor was reminded to provide mitigation measures to prevent any silty water from discharging to the downstream. 	B15
90610-006	Concrete debris was observed at Steam 21 due to the concrete breaking before. The Contractor was reminded to clear the debris and ensure the stream water in good condition	B15
	B. Air Quality No environmental deficiency was identified during site inspection.	
	C. Noise No environmental deficiency was identified during site inspection.	
	D. Waste / Chemical Management	
90610-001	Empty oil containers were observed at underneath STR 7, near Stream 20, 21 and SD4-7. The Contractor was reminded to dispose them as chemical waste.	E2ii.
90610-O02	Discarded hose were observed at Shan Shek Wan. The Contractor was reminded to clear them.	E4ii.
	E. Ecology No environmental deficiency was identified during site inspection.	
	 F. Others All environmental deficiencies identified in previous audit session were not improved/ rectified by the Contractor except item 90604-R09. Follow-up action is needed for the outstanding items. 	

•	Reminders	Related Item No.
	The Contractor was reminded to implement the following preventive measures:	
90610-R07	A. Water Quality Provide sand bag at the culvert at Shan Shek Wan.	B2
90610-R12	 Clear the construction waste, silt, debris and sediment in the culvert and U-channel along Tung Chung Road (Southern and Northern Sections) especially at STR17, Shan Shek Wan, CH7000, near Stream 20, Pak Kung Au, SD7-13, SD6-12, SD5-11, SD4-7 and underneath STR7. 	B1 and B18

90610-R17	 Properly cover/compact the exposed area at between Stream 20 and 19, near stream 21, SD4-7, SD6-12 and underneath STR 14 after the links. 	В8
90610-R18	• Clear the standing water at the wheel washing bay (abandoned) at Site Office, pit area at near SD7-13 and the hole for handrail along Southern Section of Tung Chung Road.	B11
90610-R19	Properly maintain the sand bag bund at near stream 20.	B15
90610-R21	Provide mosquito larvicide for the stagnant water at Shan Shek Wan	
	B. Air Quality	
90610-R10	 Properly maintain the slopes which have been hydroseeded along Tung Chung Road (Southern and Northern Section) especially after the rainstorm. 	C13
90610-R20	 Provide mitigation measures to prevent dust emission during cement de-bagging works and clean the remaining cement after the works at SD 4-7. 	C7
	C. Waste / Chemical Management	
90610-R08	Clear C&D waste and discarded cement bags at underneath STR7.	E4ii.
90610-R09	Clear oil stain at underneath STR7.	Eliii
90610-R11	• Clear the discarded "protection material for hydroseed" that was hanging on the trees along Southern Section of Tung Chung Road.	E4ii
90610-R13	• Clear C&D waste at near SD7-13, SD6-12, SD5-11 and SD4-7.	E4ii.
90610-R15	Clear vegetation waste along Tung Chung Road especially near the catchwater.	E4ii.
90610-R16	Keep clear and sort C&D waste at Shan Shek Wan.	E4ii
	D. Ecology	T1
90610-R14	Clear C&D waste and general refuse at Stream 21, 22, 27, 30, 34 and 36-38.	F1
	E. General	DO and
90610-G22	 Provide mitigation measures at between the outstanding construction area and paved road to prevent any mud from carrying to the public road. 	B2 and C3

Ref. No.	Proposed Completion Date	Completion Date	Remarks
90604-R09	10 June 2009	10 June 2009	
90610-001			
90610-O02			
90610-O03		·	
90610-004			
90610-005			
90610-006			
90610-R07			
90610-R08			
90610-R09			
90610-R10			
90610-R11	40.7		
90610-R12	18 June 2009		
90610-R13			
90610-R14			
90610-R15			
90610-R16			
90610-R17			
90610-R18			
90610-R19			
90610-R20			
90610-R21			
90610-G22			

	Name	Signature	Date
Recorded by	Tony Ng	Kun	10 June 2009
Checked by	Dr. Priscilla Choy	W7.	10 June 2009
Checked by	Dr. Trisenta Chey		

90610

Inspection Information

anoptenon into minutes	
Checklist Reference Number	90618
Date	18 June 2009 (Thursday)
Time	09:00 – 13:30

		Related
Ref. No.	Non-Compliance	Item No.
-	None identified	-
Ref. No.	Remarks/Observations	Related Item No.
	A. Water Quality	
90618-O03	• Soil erosion was observed at STR 16, 17, 18 and near Stream 35. The Contractor was reminded to provide mitigation measures to protect the slope. (In – progress).	В8
9061 8- O04	• Stream water at Stream 20 was observed not diverted properly around the works. The Contractor was reminded to review and re-arrange the stream diversion to prevent any wastewater discharging out.	B15
90618-005	 Sediment was observed from discharging to the culverts at SD5-11and SD6-12. The Contractor was reminded to clear the culvert and provide mitigation measures to prevent further sediment from discharging to the culvert. 	B18
	B. Air Quality	
	No environmental deficiency was identified during site inspection.	
	C. Noise	
	No environmental deficiency was identified during site inspection.	
	D. Waste / Chemical Management	
90618-001	• Empty oil containers were observed at underneath STR 7, near Stream 20, 21 and SD4-7. The Contractor was reminded to dispose them as chemical waste.	E2ii.
90618-O02	• Discarded hose were observed at Shan Shek Wan. The Contractor was reminded to clear them.	E4ii.
	E. Ecology	
	No environmental deficiency was identified during site inspection.	
	F. Others	
	• All environmental deficiencies identified in previous audit session were not improved/ rectified by the Contractor except item 90610-R05 and R06. Follow-up action is needed for the outstanding items.	

	Reminders	Related Item No.
	The Contractor was reminded to implement the following preventive measures:	
	A. Water Quality	
90618-R06	Provide sand bag at the culvert at Shan Shek Wan.	B2
90618-R08	Clear oil stain at underneath STR7.	B8
90618-R11	• Clear the construction waste, silt, debris and sediment in the culvert and U-channel along Tung Chung Road (Southern and Northern Sections) especially at STR17, Shan Shek Wan, CH7000, near Stream 20, Pak Kung Au, SD7-13, SD6-12, SD5-11, SD4-7 and underneath STR7.	BI and B18
90618-R16	• Properly cover/compact the exposed area at between Stream 20 and 19, near stream 21, SD4-7, SD6-12 and underneath STR 7 and STR 14 after the works.	В8
90618-R17	• Clear the standing water at the wheel washing bay (abandoned) at Site Office, pit area at near SD7-13.	B11
90618-R18	Properly maintain the sand bag bund at near Stream 20.	B15

90618-R20	Provide mosquito larvicide for the stagnant water at Shan Shek Wan.	B11
	B. Air Quality	
90618-R09	Properly maintain the slopes which have been hydroseeded along Tung Chung Road (Southern and Northern Section) especially after the rainstorm.	C13
90618-R19	Provide mitigation measures to prevent dust emission during cement de-bagging works and clean the remaining cement after the works at SD 4-7.	С7
	C. Waste / Chemical Management	
90618-R07	Clear C&D waste and discarded cement bags at underneath STR7.	E4ii.
90618-R08	Clear oil stain at underneath STR7.	E7i
90618-R10	• Clear the discarded "protection material for hydroseed" that was hanging on the trees along Southern Section of Tung Chung Road.	E4ii
90618-R12	Clear C&D waste and sediment at SD6-12, SD5-11 and SD4-7.	E4ii.
90618-R14	Clear vegetation waste along Tung Chung Road especially near the catchwater and underneath STR 7.	
90618-R15	Keep clear and sort C&D waste at Shan Shek Wan.	E4ii
	D. Ecology	
90618-R13	Clear C&D waste and general refuse at Stream 21, 22, 27, 30, 34 and 36-38.	F1
· · · · · · · · · · · · · · · · · · ·	E. General	
90618-G21	• Provide mitigation measures at between the outstanding construction area and paved road to at SD6-12, Stream 20 and 21, site office to prevent any mud from carrying to the public road.	B2 and C3

Ref. No.	Proposed Completion Date	Completion Date	Remarks
90610-005	18 June 2009	18 June 2009	
90610-O06			
90618-O01			
90618-002			
90618-O03			
90618-004			
90618-O05			
90618-R06			
90618-R07			
90618-R08			
90618-R09			
90618-R10			
90618-R11	25 June 2009		
90618-R12			į
90618-R13			
90618-R14			
90618-R15			
90618-R16			
90618-R17	•		
90618-R18			
90618-R19			
90618-R20			
90618-G21			

Contract No. HY/2003/19 Improvement to Tung Chung Road Between Lung Tseng Tau and Cheung Sha

	Name	Signature	Date
Recorded by	Tony Ng	Warray	18 June 2009
Checked by	Dr. Priscilla Choy	WI	18 June 2009
*	•		

Inspection Information

Checklist Reference Number	90625
Date	25 June 2009 (Thursday)
Time	09:00 - 13:30

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-
Ref. No.	Remarks/Observations	Related Item No.
	A. Water Quality	
90625-O03	• Soil erosion was observed at STR 16, 17, 18 and near Stream 35. The Contractor was reminded to provide mitigation measures to protect the slope. (In – progress).	В8
90625-004	 Stream water at Stream 20 was observed not diverted properly around the works. The Contractor was reminded to review and re-arrange the stream diversion to prevent any wastewater discharging out. 	B15
9062 5- O05	• Silty water was observed at Stream 23. However, the silty water was due to the broken water pipe from other construction site at old Tung Chung Road. The item was also observed to be rectified during the site inspection.	В3
	B. Air Quality	
	No environmental deficiency was identified during site inspection.	
	C. Noise	
	No environmental deficiency was identified during site inspection.	
	D. Waste / Chemical Management	
90625-001	• Empty oil containers were observed at underneath STR 7, near Stream 20, 21 and SD4-7. The Contractor was reminded to dispose them as chemical waste.	E2ii.
90625-O02	Discarded hose were observed at Shan Shek Wan. The Contractor was reminded to clear them.	E4ii.
	E. Ecology	
	No environmental deficiency was identified during site inspection.	
	F. Others	
	 All environmental deficiencies identified in previous audit session were not improved/ rectified by the Contractor except item 90618-O05 and R08. Follow-up action is needed for the outstanding items. 	

	Reminders	Related Item No.
	The Contractor was reminded to implement the following preventive measures:	
	A. Water Quality	
90625-R06	Provide sand bag at the culvert at Shan Shek Wan.	B2
90625-R10	• Clear the construction waste, silt, debris and sediment in the culvert and U-channel along Tung Chung Road (Southern and Northern Sections) especially at STR17, Shan Shek Wan, CH7000, near Stream 20, Pak Kung Au, SD7-13, SD6-12, SD5-11, SD4-7 and underneath STR7.	B1 and B18
90625-R15	• Properly cover/compact the exposed area at between Stream 20 and 19, near stream 19, 21, SD4-7, SD5-11, SD6-12 and underneath STR 7 and STR 14 after the works.	В8
90625-R16	• Clear the standing water at the wheel washing bay (abandoned) at Site Office and Stream 21.	B11
90625-R17	Properly maintain the sand bag bund at near Stream 20. (In-progress)	B15
90625-R19	Provide mosquito larvicide for the stagnant water at Shan Shek Wan.	B11
90625-R20	Provide mitigation measures to prevent silty water flowing to the culvert at SD4-7.	B4

	B. Air Quality	
90625-R08	 Properly maintain the stopes which have been hydroseeded along Tung Chung Road (Southern and Northern Section) especially after the rainstorm. 	C13
90625-R18	 Provide mitigation measures to prevent dust emission during cement de-bagging works and clean the remaining cement after the works at SD 4-7. 	C7
	C. Waste / Chemical Management	
90625-R07	Discarded cement bag's at underneath STR7.	E4ii.
90625-R09	• Clear the discarded "protection material for hydroseed" that was hanging on the trees along Southern Section of Tung Chung Road.	E4ii
90625-R11	Clear C&D waste and sediment at SD6-12, SD5-11, SD4-7 and Stream 20.	E4ii.
90625-R13	• Clear vegetation waste along Tung Chung Road especially near the catchwater and underneath STR 7.	E4ii.
90625-R14	Keep clear and sort C&D waste at Shan Shek Wan.	E4ii
90625-R21	Clear the stockpile at underneath STR 7.	E4ii
	D. Ecology	
90625-R12	Clear C&D waste and general refuse at Stream 21, 22, 27, 30, 34 and 36-38.	<u>F1</u>
	E. General	
90625-G22	 Provide mitigation measures at between the outstanding construction area and paved road to at SD6-12, Stream 20 and 21, site office to prevent any mud from carrying to the public road. 	B2 and C3

Ref. No.	Proposed Completion Date	Completion Date	Remarks
90618-O05	25 June 2009	25 June 2009	
90618-R08			
90625-O01			
90625-O02			
90625-O03			
90625-O04			
90625-O05			
90625-R06			
90625-R07			
90625-R08			
90625-R09			
90625-R10			
90625-R11	22.1.222		
90625-R12	02 July 2009		
90625-R13			
90625-R14			
90625-R15			
90625-R16			
90625-R17			
90625-R18			
90625-R19			
90625-R20			
90625-R21			
90625-G22			1

	Name	Signature	Date
Recorded by	Tony Ng	This	25 June 2009
Checked by	Dr. Priscilla Choy	W.Z.	25 June 2009

APPENDIX J ENVIRONMENTAL MITIGATION IMPLEMENTATION SCHEDULE (EMIS)

Appendix J - Summary of Environmental Mitigation Implementation Schedule

Types of Impacts	Mitigation Measures	Status
	 A stockpile of dusty materials should not extend beyond the pedestrian barriers, fencing or traffic cones. 	^
	 Vehicle washing facilities should be provided at every exit point. 	*
	• The area where vehicle washing takes place and the section of the road between the washing facilities and the exit point should be paved with concrete, bituminous materials or hardcores.	*
	• Where a site boundary adjoins a road, street, service lane or other area accessible to the public, hoarding of not less than 2.4m high from ground level should be provided along the entire length of that portion of the site boundary except for a site entrance or exit.	N/A
	• Every main haul road should be sprayed with water or a dust suppression chemical so as to maintain the entire road surface wet.	^
	• The portion of any road leading only to a construction site that is within 30m of a discernible or designated vehicle entrance or exit should be kept clear of dusty materials.	*
Construction Dust	• Any stockpile of dusty materials should be either covered entirely be impervious sheeting, placed in an area sheltered on the top and the 3 sides or sprayed with water or a dust suppression chemical so as to maintain the entire surface wet.	^
	• During cement debagging or concrete batching operation in an area sheltered on top and 3 sides.	*
	 All dusty materials should be sprayed with water or a dust suppression chemical immediately prior to any loading, unloading or transfer operation so as to maintain the dusty materials wet. 	*
	• Every vehicle should be washed to remove any dusty materials from its body and wheels immediately before leaving a construction site.	*
	• The working area of any excavation should be sprayed with water or a dust suppression chemical immediately before, during and immediately after the operation so as to maintain the entire surface wet.	*
	 Proper enclosures and water spraying should be implemented for the main dust-generating activities, such as soil nailing or piling works. 	*
	Proper plant maintenance should be provided to avoid black smoke emission from plants/equipment.	^

Types of Impacts	Mitigation Measures	Status
	 Only well-maintained plant should be operated on –site and plant should be serviced regularly during the construction works. Machines and plant that may be in intermittent use should be shut down between work periods or should be throttled down to a minimum. 	^ ^
	 Plant know to emit noise strongly in one direction, should where possible, be orientated to direct noise away from the NSRS. Mobile plant should be sited as far away from NSRs as possible. 	^ ^
Construction Noise	 Material stockpiles and other structures should be effectively utilised, where practicable, to screen noise from on-site construction activities. 	
	Use quite plant and Working Method	^
	 Reduce the number of plant operating in critical areas close NSRs. Construct temporary and movable noise barriers 	N/A
	Construction Runoff and Drainage	
	• Discharges to natural water courses shall only take place when the effluent can be shown to comply with the standards specified in the Technical Memorandum, Standards for Effluents Discharged in to Drainage and Sewerage Systems, Inland and Coastal Waters. Discharges in the water gathering grounds should meet Group A standard for inland waters.	*
	Use of sediment traps and the adequate maintenance of drainage systems to prevent flooding and overflow.	*
	• Boundaries of critical areas of earthworks should be marked and surrounded by dykes or embankments for flood protection. Temporary ditches should be provided to facilities runoff discharge into the appropriate watercourses, via a silt retention pond. Permanent drainage channels should incorporate sediment basins or traps and baffles to enhance deposition rates.	^
Water Quality	 All temporary and permanent drainage pipes and culverts provided to facilitate runoff discharge should be adequately designed for the controlled release of storm flows. All sediment traps should be regularly cleaned and maintained. The temporarily diverted drainage should be reinstated to its original condition when the construction works has finished or the temporary diversion is no longer required 	*
	• Sand silt in the wash water from the wheel washing facilities, which ensure no earth, mud and debris is deposited on roads, should be settled out the removed before discharging into storm drains. A section of the road between the wheel washing bay and the public road should be paved with backfill to prevent wash water or other site runoff form entering public road drains.	^
	• Oil interceptors should be provided in the drainage system and regularly emptied to prevent the release of oils and grease into the storm water drainage system after accidental spillage. The interceptor should have a bypass to prevent flushing during periods of heavy rain.	N/A
	 Catchpits and perimeter channels shall be constructed in advance of site formation works and earthworks. 	^
	• Silt removal facilities, channels and manholes shall be suitably maintained with the deposited silt and grit being removed at least once a week, and at the onset of and after each rainstorm to ensure that these facilities are functioning properly at all times.	*

Types of Impacts	Mitigation Measures	Status
_	 system via appropriate sediment traps. Ground water pumped out of tunnels should be discharged into the drainage channels which incorporated sediment traps to enhance deposition rates and to remove silt. Spend grouts used in diaphragm wall construction should be collected in a separate slurry collection system, reconditioned and raused wherever practicable. The disposal of used grouting materials will only be permitted if it is treated to the TM. 	*
		*
	Tunnelling Work	
	washout of construction or excavated materials form the drill and blast tunnelling work should be diverted to the drainage	N/A
	enhance deposition rates and to remove silt.	N/A
	and reused wherever practicable. The disposal of used grouting materials will only be permitted if it is treated to the TM	N/A
	General Construction Activities	
	• Debris and rubbish on site should be collected, handled and disposed of properly to avoid entering the water column and cause water quality impacts.	*
	• All fuel tanks and storage areas will be provided with locks and be located on sealed areas (within bunds of a capacity equal to 110% of the storage capacity of the largest tank or 20% by volume of the fuel stored in that areas, whichever in the greatest).	٨
	Sewage Effluent	
	• Construction work force sewage discharges form fixed toilet facilities on-site should be connected to the nearby existing trunk sewer wherever feasible. However, for areas where existing trunk sewer is not available, it is recommended that appropriate and adequate on site portable chemical toilets should be provided by a licensed contractor who will be responsible for appropriate disposal and maintenance of these facilities.	٨
	• It is considered that sewage discharges could also be treated by on-site septic tanks and soakaway. Minimum clearance away form streams and catchments and other requirements for the proposed septic tank and soakaway should be referred to EPD's Practice Note for Professional Persons, Drainage Plans.	
		N/A

Types of Impacts	Mitigation Measures	Status					
•	General	•					
	 Training and instruction shall be given at a site to construction staff to increase awareness and draw attention to waste management issues and the need to minimise waste generation. The training requirement shall be included in the site waste management plan. 	^					
	Storage, Collection and Transportation of Waste						
	Wastes shall be handled and stored in a manner to ensure that they are held securely without loss or leakage.	*					
	 Authorised or licensed waste hauliers shall be used and they shall only collect wastes prescribed by their permits. 	^					
	Waste shall be removed on a daily basis.	*					
	Waste storage area shall be maintained and cleaned on a daily basis.	*					
	 Windblown litter and dust during transportation shall be minimised by either covering trucks or transporting wastes in enclosed containers. 	٨					
	Obtain necessary waste disposal permits from the appropriate authorities if they are required.	^					
	Wastes shall be disposed of at licensed waste disposal facilities.	^					
Waste /	• Develop procedure such as ticketing system to facilitate tracking of loads, particularly for chemical waste, and to ensure that illegal disposal of wastes does not occur.	^					
vv aste / Chemical	Maintain records of the quantities of wastes generated, recycled and disposed.	^					
Chemicai	Surplus Excavated Materials						
	Due to the high risk of loose material being washed into the existing nullah, stockpile materials should be properly compacted and covered from water erosion and located at least 10m away from the nullah wall.	^					
	Construction and Demolition (C&D) Waste						
	 Careful design, planning and good site management shall be adopted to minimise over-ordering and generation of waste materials such as concrete grouts. 	*					
	• The handling and disposal of bentonite slurries shall be undertaken in accordance with Practice Note for Professional Persons – Construction Site Drainage (ProPECC PN 1/94) on construction site drainage.	N/A					
	• Construction and demolition (C&D) material shall be segregated to inert and non-inert parts. The inert portion shall re-used at areas of reclamation or land formation, or to public filling area shall such allocation is deemed necessary. The non-inert portion shall be disposed of to landfill.	*					
	Chemical Waste						
	 Chemical waste that is produce during construction shall be handled in accordance with the Code of Practice on the Packaging, Handling and Storage of Chemical Wastes. 	٨					

Types of Impacts	Mitigation Measures	Status
	 Containers used for the storage of chemical wastes should: a. Be suitable for the substance they are holding, resistant to corrosion, maintained in a good condition, and securely closed; b. Have a capacity of less than 450 litres unless the specifications have been approved by the EPD; c. Display a label in English and Chinese in accordance with instructions prescribed in Schedule 2 of the Chemical Waste Regulations. 	۸
	 The storage area for chemical wastes should: a. Be clearly labelled and used solely for the storage of chemical waste; b. Be enclosed on at least 3 sides; c. Have an impermeable floor and bunding of capacity to accommodate 110% of the volume of the largest container or 20% by volume of the chemical waste stored in the area, whichever is largest; d. Have adequate ventilation; 	۸
	e. Be covered to prevent rainfall entering (water collected within the bund must be tested and disposed as chemical waste if necessary);f. Be arranged so that incompatible materials are adequately separated.	
	• Disposal of chemical waste shall be via a licensed waste collector; and to a facility licensed to receive chemical waste; or a reuser of the waste (under approval from EPD).	۸
	General Refuse	
	 General refuse generated on-site shall be stored in enclosed bins or compaction unit separate from C&D and chemical wastes. A reputable waste collector shall be employed by the contractor to remove general refuse from the site, separately from C&D and chemical wastes, on a daily for every second day basis to minimise odour, pest and litter impacts. The burning of refuse on construction sites is prohibited by law. 	*
	Reusable rather than disposable dishware shall be used if feasible.	^
	Oil and Fuel	
	• The storage area for chemical wastes should have an impermeable floor and bunding of capacity to accommodate 110% of the volume of the largest container;	۸
	No storage of oil or fuel should be stored within the Country Park or the water gathering ground.	۸
	 Refinement of the route alignment and design of associated structures to minimise loss of woodland and other landscape resources; 	۸
Landscape	 Minimising working areas as far as possible; 	^
and Visual	Protection and retention of existing vegetation where possible;.	^
Impact	Transplanting of trees where appropriate	^
	• Protection and retention of existing natural rocky outcrops, slope profiles, vegetation, landscape features;	^
	Advance planting and visual screening, where possible;	^

Types of Impacts	Mitigation Measures	Status
	Compensatory planting;	٨
	• Sensitively designed site hoarding, where possible (ie the sensitive design of site hoarding will be disrupted by hoarding panels showing the Highways Department logo, at regular intervals as per the approved engineering design); and	٨
	Grassing and woodland planting of soil slopes and disturbed areas	٨
Ecology	Construction activities in the stream and other disturbances to it should be avoided.	*

Remarks: ^ Compliance of mitigation measure; N/A Not Applicable; * Recommendation was made during site audit but improved/rectified by the contractor.	X • #	Non-compliance of mitigation measure; Non-compliance but rectified by the contractor; Non-compliance but rectified/improved by the contractor and awaiting IEC's further comment;
---	-------------	--

APPENDIX K EVENT ACTION PLANS

Appendix K – Event Action Plans

Event /Action Plan for Air Quality

EVENT		ACTION							
	ET		ΙE	IEC		ER		ntractor	
Action Level									
Excee dance for one sample	2.	Inform the IEC and the Contractor about the exceedance within 24 hours of identification of exceedance; Identify the source, investigate the causes of exceedance and propose remedial measures; Report the results of the investigation to the Contractor; Prepare Notification of Exceedance (NOE) to inform the Contractor, the IEC, the ER and the EPD within 24 hours of identification of exceedance. Repeat measurement to confirm finding. If excee dance is indicated due to the Project construction works, increase 24-hour TSP monitoring frequency to 1- hour monitoring with 3 times every six days until no exceedance is recorded.	3.	submitted by the ET. Confirm the ET assessment regarding the action and/or limit level exceedance during the impact monitoring;	2.	Confirm receipt of NOE in writing. Notify EPD and other relevant Government departments within 24 hours of identification of exceedance.	1. 2. 3.	Inform IEC and ER within 24 hours of identification of exceedance; Submit proposals for remedial to ER within 3 working days of notification ET if exceedance is due to the Project construction works; Rectify any unacceptable practice; Amend working methods if appropriate and within reasonable time scale if exceedance is due to the Project construction works.	

EVENT	ACTION			
	ET	IEC	ER	Contractor
Action Level				
2. Excee dance for two or more consecutive samples	 Inform the IEC and the Contractor about the exceedance within 24 hours of identification of exceedance; Identify the source. Supervise implementation of remedial measures; Report the results of the investigation to the Contractor; Advise the ER on the effectiveness of the proposed remedial measures; Repeat measurements to confirm findings; Increase monitoring frequency to daily; Discuss with the IEC and the Contractor on remedial actions required; If exceedance continues, arrange meeting with the IEC and the ER. If exceedance stops, cease additional monitoring. 	 Check monitoring data submitted by the ET; Check the Contractor's working method; Discuss with the ET and the Contractor on possible remedial measures; Advise the ER on the effectiveness of the proposed remedial measures; Supervisor implementation of remedial measures. 	 Confirm receipt of NOE in writing. Notify the EPD and other relevant Government departments within 24 hours of identification of exceedance; Ensure remedial measures properly implemented. 	 Inform IEC and ER within 24 hours of identification of exceedance; Submit proposals for remedial actions to IEC within 3 working days of notification; Implement the agreed proposals; Amend proposal if appropriate.

EVENT	ACTION			
	ET	IEC	ER	Contractor
LimitLevel				
1. Exceedance for one sample The sample sa	 Notify the IEC and the Contractor within 24 hours of identification of exceedance; Identify the source, investigate the causes of exceedance and propose remedial measures; Prepare Notification of Exceedance (NOE) to inform the Contractor, the IEC, the ER and the EPD within 24 hours of identification of exceedance. Repeat measurement to confirm finding. If exceedance is indicated due to the Project construction works, increase 24-hour TSP monitoring frequency to 1-hour monitoring with 3 times every six days until no exceedance is recorded; Assess effectiveness of Contractor's remedial actions and keep the IEC, the DEP and the ER informed of the results. 	 Check monitoring data submitted by the ET. Check Contractor's working method. Discuss with the ET, the Contractor and the ER on possible remedial measures. Advise the ER on the effectiveness of the proposed remedial measures. Supervise implementation of remedial measures. 	 Confirm receipt of notification of exceedance in writing; Notify EPD and other relevant Government departments within 24 hours of identification of exceedance; Ensure remedial measures are properly implemented. 	 Inform ER and IEC within 24 hours of identification of exceedance; Take immediate action to avoid further exceedance; Submit proposals for remedial actions to ER and IEC within 3 working day of notification by ET; Implement the agreed proposals; Report effectiveness of remedial actions to IEC and ER; Amend proposal if appropriate.

EVENT	ACTION			
	ET	IEC	ER	Contractor
2. Exceedance for two or more consecutive samples	 Notify the IEC and the Contractor within 24 hours of identification of exceedance; Identify the source; Repeat measurements to confirm findings if the exceedance is due to the Project construction works; Increase monitoring frequency to daily; Carry out analysis of the Contractor's working procedures to determine possible mitigation to be implemented; Arrange meeting with the IEC and the ER to discuss the remedial actions to be taken; Assess effectiveness of the Contractor's remedial actions and keep the IEC, the DEP and the ER informed of the results; If exceedance stops, cease additional monitoring. 	1. Discuss amongst the ER, ET and the Contractor on the potential remedial actions; 2. Review the Contractor's remedial actions whenever necessary to assure their effectiveness and advise the ER accordingly; 3. Supervise the implementation of remedial measures.	notification of failure in writing; 2. Notify the EPD and other relevant Government departments within 24 hours of identification of exceedance; 3. In consultation with the	 Inform ER and IEC within 24 hours of identification of exceedance; Take immediate action to avoid further exceedance; Submit proposals for remedial actions to IEC within 3 working days of notification by ET; Arrange meeting with IEC and ER to discuss the remedial actions to be taken; Implement the agreed proposals; Resubmit proposals if problem still not under control; Report effectiveness of remedial actions to IEC and ER; Stop the relevant activity of works as determined by the ER until the exceedance is abated.

Note: ET - Environmental Team, IEC - Independent Environmental Checker, ER - Engineer's Representative

Event Action Plan for Construction Noise

EVENT	ACTION							
	ET	IEC	ER	Contractor				
Action Level	 Notify the IEC and the Contractor within 24 hours of identification of exceedance. Carry out investigation. Report the results of investigation to the IEC and the Contractor. Prepare Notification of Exceedance (NOE) to inform the Contractor, the IEC, the ER and the EPD within 24 hours of identification of exceedance. Discuss with the Contractor and formulate remedial measures. Increase monitoring frequency to check mitigation effectiveness. 	1. Review the analysed results submitted by the ET. 2. Review the proposed remedial measures by the Contractor and advise the ER accordingly. 3. Supervise the implementation of remedial measures.	1. Confirm receipt of NOE in writing. 2. Notify the EPD and other relevant Government departments within 24 hours of identification of exceedance. 3. Require the Contractor to propose remedial measures for the analysed noise problem. 4. Ensure remedial measures are properly implemented.	Submit noise mitigation proposals to IEC Implement noise mitigation proposals				

EVENT	ACTION				
	ET	IEC	ER	Contractor	
Limit Level	 Notify the IEC and the Contractor within 24 hours of identification of exceedance. Identify the source. Repeat measurement to confirm findings. Increase monitoring frequency. Prepare Notification of Exceedance (NOE) to inform the Contractor, the IEC, the ER and the EPD within 24 hours of identification of exceedance. Carry out analysis of Contractor's working procedures to determine possible mitigation to be implemented. Inform the IEC, the ER and the DEP the causes & actions taken for the exceedances. Assess effectiveness of the Contractor's remedial actions and keep the IEC, the DEP and the ER informed of the results. If exceedance stops, cease additional monitoring. 	 Discuss amongst the ER, the ET and the Contractor on the potential remedial actions. Review the Contractor's remedial actions whenever necessary to assure their effectiveness and advise the ER accordingly. Supervise the implementation of remedial measures. 	1. Confirm receipt of NOE in writing. 2. Notify the EPD and other relevant Government departments within 24 hours of identification of exceedance. 3. Require the Contractor to propose remedial measures for the analysed noise problem. 4. Ensure remedial measures are properly implemented. 5. If exceedance continues, consider what activity of the work is responsible and instruct the Contractor to stop that activity of work until the exceedance is abated.	 Take immediate action to avoid further exceedance Submit proposals for remedial actions to IEC within 3 working days of notification Implement the agreed proposals Resubmit proposals if problem still not under control Stop the relevant activity of works as determined by the ER until the exceedance is abated. 	

Note: ET - Environmental Team, IEC - Independent Environmental Checker, ER - Engineer's Representative

Event / Action Plan for Water Quality

EVENT	ACTION							
	ET		IEC	3	ER		Co	ntractor
Action Level being excee ded by one sampling day	confirm find 2. Identify sour 3. Inform the II 4. Prepare Note (NOE) to inform the ER at thours of identify 5. Check monities equipment at working met 6. Discuss mitigated and the orthogonal sources.	re(s) of impact; EC and the Contractor; ification of Exceedance form the Contractor, the and the EPD with 24 attification of exceedance, oring data, all plant, and the Contractor's chods; gation measures with the	2.	Discuss with the ET and the Contractor on the mitigation measures; Review proposals on mitigation measures submitted by the Contractor and advise the ER accordingly; Access the effectiveness of the implemented mitigation measures.	2.	Discuss with the IEC on the proposed mitigation measures; Make agreement on the mitigation measures to be implemented.	2. 3. 4. 5.	Inform the ER and confirm notification of the non-compliance in writing; Rectify unacceptable practice; Check all plant and equipment; Consider changes of working methods; Discuss with the ET and the IEC and propose mitigation measures to the IEC and the ER; Implement the agreed mitigation measures.
Action Level being exceeded by more than one consecutive sampling days	confirm finding. 2. Identify sources. 3. Inform the IE. 4. Check monitor equipment and methods; 5. Discuss mitigned and the Conference of the Conference	ce(s) of impact; C and the Contractor; oring data, all plant, ad Contractor's working ation measures with the contractor; tion measures are ; crease the monitoring	2.	Discuss with the ET and the Contractor on the mitigation measures; Review proposals on mitigation measures submitted by the Contractor and advise the ER accordingly; Access the	pro me Ma mi im Ac the	scuss with IEC on the opposed mitigation easures; ake agreement on the tigation measures to be plemented; cess the effectiveness of e implemented mitigation easures.	1. 2. 3. 4. 5.	Inform the ER and confirm notification of the non-compliance in writing; Rectify unacceptable practice; Check all plant and equipment; Consider changes of working methods; Discuss with the ET and the IEC and propose mitigation measures to the IEC and ER within 3 working days; Implement the agreed mitigation measures.

EVENT	ACTION			
	ET	IEC	ER	Contractor
	Repeat measurement on next day of exceedance.	effectiveness of the implemented mitigation measures.		
Limit Level being exceeded by one consecutive sampling day	 Repeat in-situ measurement to confirm findings; Identify source(s) of impact; Inform the IEC and the Contractor; Prepare Notification of Exceedance (NOE) to inform the Contractor, the IEC, the ER and the EPD with 24 hours of identification of exceedance. Check monitoring data, all plant, equipment and the Contractor's working methods; Discuss mitigation measures with the IEC, the ER and the Contractor; Ensure mitigation measures are implemented; Increase the monitoring frequency to daily until no exceedance of Limit Level. 	1. Discuss with the ET and the Contractor on the mitigation measures; 2. Review proposals on mitigation measures submitted by the Contractor and advise the ER accordingly; 3. Access the effectiveness of the implemented mitigation measures.	1. Discuss with the IEC, the ET and the Contractor on the proposed mitigation measures; 2. Request the Contractor to critically review the working methods; 3. Make agreement on the mitigation measures to be implemented; 4. Access the effectiveness of the implemented mitigation measures.	 Inform the Engineer and confirm notification of the noncompliance in writing; Rectify unacceptable practice; Check all plant and equipment; Consider changes of working methods; Discuss with the ET, the IEC and the ER and propose mitigation measures to the IEC and the ER within 3 working days; Implement the agreed mitigation measures.

EVENT	ACTION			
	ET	IEC	ER	Contractor
Limit Level being exceeded by more than one consecutive sampling days	 Repeat in-situ measurement to confirm findings; Identify source(s) of impact; Inform the IEC, the Contractor and DEP; Check monitoring data, all plant, equipment and Contractor's working methods; Discuss mitigation measures with the IEC, the ER and the Contractor; Ensure mitigation measures are implemented; Increase the monitoring frequency to daily until no exceedance of Limit Level for two consecutive days. 	1. Discuss with ET and Contractor on the mitigation measures; 2. Review proposals on mitigation measures submitted by the Contractor and advise the ER accordingly; 3. Access the effectiveness of the implemented mitigation measures.	 Discuss with the IEC, the ET and the Contractor on the proposed mitigation measures; Request Contractor to critically review the working methods; Make agreement on the mitigation measures to be implemented; Access the effectiveness of the implemented mitigation measures; Consider and instruct, if necessary, the Contractor to slow down orto stop all or part of the works until no exceedance of Limit Level. 	 Inform the ER and confirm notification of the noncompliance in writing; Rectify unacceptable practice; Check all plant and equipment; Consider changes of working methods; Discuss with the ET, the IEC and the ER and propose mitigation measures to the IEC and the ER within 3 working days; Implement the agreed mitigation measures; As directed by the ER, slow down or stop all or part of the construction activities.

APPENDIX L COMPLAINT LOGS

Appendix L - Complaint Log

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S63	Tung Chung Road and Cheung Sha Stream	14 Sep 06	The complaint, which was lodged by Green Lantau Association on 13th September 2006, accused the failure of the site drainage system to check the discharge of silt-laden surface water from the site on that day.	ETL is of the view that the complaint is justifiable but the accusation is not substantiated by scientific data in that the rainstorm event was 1 in 25 years. It is therefore beyond the Contractor's terms of contract to design, operate and maintain the carrier pipe and the sedimentation tank to cater for this rainstorm. The Contractor has a defendable case under this increment weather condition.	Closed
S65-S69	Tung Chung Road Southern Section; Cheung Sha Stream;	19 Sep 06	Five complaints, which were lodged by Green Lantau Association on 15th September 2006, accused the failure of the drainage system for the Project on 13th September 2006. The subject of complaints are listed as below: (i) Failed Filtration System (ii) Contaminated Stream (iii) Polluted Cheung Sha Stream (iv) Polluted Cheung Sha Stream (v) Site Debris on Road	ETL is of the view that the complaints are justifiable but the accusation is not substantiated by scientific data in that the rainstorm event was 1 in 25 years. It is therefore beyond the Contractor's terms of contract to design, operate and maintain the carrier pipe and the sedimentation tank to cater for this rainstorm. The Contractor has a defendable case under this increment weather condition.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S71	Northern Section, Tung Chung Road	3 Nov 06	The complaint, which was referred by Resident Site Staff (RSS) to ET on 3 rd November 2006, was raised by a resident living Lantau Island on 17 th October 2006 concerning the Tung Chung Road condition on 16 th October 2006.	Based on the meteorological data extracted from HKO, the total rainfall between 0:45 and 6:45 hours in Lantau was 196 mm with an average intensity of 32.67 mm/hr on 16 th October. Based on the results derived from Table 2 "the Intensity-Duration-Frequency (IDF) for various return periods" and Table 4 "Depth-Duration-Frequency (DDF) for durations of than 4 hours" of the "Stormwater Drainage Manual", the return period should be less than 1 in 10 years. Therefore, the complaint was considered justifiable since the EIA report has recommended the provision of site drainage system shall be 1 in 10 years. The Contractor has implemented remedial measures and preventive measures.	Closed
S72	Lung Tseng Tau Village, Tung Chung	3 Nov 06	The public complaint, which was referred by RSS to ET on 3 rd November 2006, was received by the Integrated Complaint Centre (ICC) on 26 th October 2006 regarding dust nuisance generated from the Project.	Based on the information collected and the monitoring results, the complaint was considered not justifiable due to the following since no exceedance of the air quality monitoring results was recorded in October 2006. During site inspections in the month, dust mitigation measures have been implemented by the Contractor; and no observation was recorded during the site inspections. According to the information provided by the Contractor and the RSS, the Contractor has implemented additional mitigation measures, including increased water spraying on the public road to more than once a day and covered the stockpiling materials.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S73	Southern Section of the Project	3 Nov 06	The complaint, which was referred by RSS to ET on 3 rd November 2006, was raised by a resident living at Cheung Sha on 24 th October 2006 concerning noise generated from rock breaking in Southern Section of the Project.	According to the EM&A records, no exceedance of noise level and no non-compliance were recorded in the month. As advised by the Contractor and RSS, silent rock breaking equipment has been used and noise insulation materials have been used to minimize the noise impact generated from the rock breaking activity. Based on the provided information and the monitoring results, the complaints are considered not justifiable. The Contractor has implemented the mitigation measures to minimize the noise generation from construction activities and was still reminded to continuously implement their practice to prevent noise nuisance generation from the construction works.	Closed
S74	Tung Chung Stream	24 Nov 06	Highways Department (HyD) of HKSAR received a complaint for Agriculture, Fisheries and Conservation (AFCD) regarding untreated site runoff discharged to Tung Chung Stream during the site visit on 21 st November 2006. The Resident Site Staff (RSS) subsequently referred the complaint to the Environmental Team (ET) Leader of the Project on 24 th November 2006.	The investigation revealed that, based on the meteorological data extracted from HKO, the highest rainfall recorded was between 13:45 and 15:45, with a total of 93mm in two hours. With the above rainfall intensities extracted from HKO, together with the Intensity-Duration-Frequency (IDF) for various return periods derived from Table 2 of the "Stormwater Drainage Manual", the return period should be less than 10 years. Therefore, the complaint was considered justifiable and the Contractor has implemented remedial measures and preventive measures.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S75	West of the new Tung Chung Road Southern Section Discharge Point	21 Nov 06	Both Environmental Protection Department (EPD) and China Civil Engineering Construction Corporation and China Railway Wuju Joint Venture (the Contractor) received the same public complaint, regarding muddy water discharged to Chueng Sha on 21st November 2006. The Contractor subsequently referred the complaint to the Environmental Team (ET) Leader of the Project on the same day.	The complainant considered that this stream was muddy and discharging muddy water into the sea. As stated in the above paragraph, the investigation revealed that the return period for the rainfall between 13:45 and 15:45 was 41 years. As the complaint was lodged at 14:58 on 21 st November 2006, it is reasonable to consider the rainfall recorded in the hour between 13:45 to 14:45 which was 57mm. According to "Stormwater Drainage Manual", the return period should be less than 10 years. Therefore, the complaint was considered justifiable and the Contractor has implemented remedial measures and preventive measures.	Closed
\$76	Pui O Wan	27 Nov 06	China Civil Engineering Construction Corporation and China Railway Wuju Joint Venture (the Contractor) received the same public complaint, regarding muddy water discharged into Pui O Wan on 23 rd November 2006. According to the complainant, muddy water was discharged into Pui O Wan from the new Tung Chung Road Southern Section Discharge Point (near proposed round about on South Lantau Road) in the morning of 23 rd November 2006. The complainant suspected that the muddy water was being pumped off site through failed filtration systems into the sea as there had been no recent rainfall on that day.	The investigation revealed that the complaint was considered not justifiable since (1) no muddy water was generated due to the construction activities in the vicinity of the discharged point; and (2) no surface runoff as no rainfall was recorded on 23 rd November 2006.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S77	Sheung Ling Pei, Ha Ling Pei, Wong Ka Wai & Lung Tseng Tau Villages	18 Dec 06	Highways Department (HyD) and the Resident Engineer received a complaint against Water Quality Supply (Muddy Water) at Sheung Ling Pei, Ha Ling Pei, Wong Ka Wai & Lung Tseng Tau Villages via District Office (Islands) on 29 th November 2006. The complainants claimed that subject villages were suffering from muddy water supplied from the water main on the past few days before 29 th November 2006.	Upon receipt of the complaint, the Contractor inspected all streams (above AFCD entrance) in the Northern Section. Muddy water was observed at Stream 13 which was believed the source of muddy water. However, no water flow was found at the stream. The muddy water was considered probably due to the seepage of underground water mixed with excavated soil to Stream 13. Furthermore, an ad-hoc meeting between DO/WSD/AFCD/MOTT/CCJV/IEC/ET was held on 14 December 2006 to discuss this issue. The complaint was considered due to the construction activities of the Project. Emergency remedial works had been taken by the Contractor to rectify the situation and preventive measures had also been implemented.	Closed
S80	Tung Chung Road near Lung Tseng Tau Village	3 Jan 07	The complaint was lodged by a resident at Lung Tseng Tau Village regarding dust nuisance at Tung Chung Road near Lung Tseng Tau Village. According to the complainant, the dust was generated by vehicle movements (about 5 to 7 per day). The complainant noticed that there was only once per day for water spraying on the road. She suggested that the frequency of water spraying should be increased to 1 to 2 per hour. In addition, she requested to provide more water-spraying practice for the concerned area.	According to the Contractor and the RSS, the main dust emission in the vicinity of Lung Tseng Tau Village was due to the vehicle movements on Tung Chung Road. Base on the information collected and the monitoring results, the complaint was considered not justifiable since (1) no exceedance of the air quality monitoring results was recorded in December 2006; (2) dust mitigation measures have been implemented by the Contractor; and (3) no observation was recorded during the site inspections. In response to the complaint, the Contractor had stepped up the dust suppression control immediately. A water truck was mobilized to spray water at Tung Chung Road within particular in the vicinity of the complainant's house from once per day to at least 3 times per day.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S81	Lung Tseng Tau	20 Dec 06	The Contractor, CCECC and CRWJ Joint Venture (CCJV) and Highways Department (HyD) of HKSAR received a complaint regarding dust control at Lung Tseng Tau from the Office of Islands District Councilor, Wong Fukkan on 6 th December 2006. According to the complainant, he had received a number of complaints from residents in South Lantau regarding the dust nuisance when their vehicles passing through Tung Chung Road near Lung Tseng Tau. The residents said their vehicles were full of dust whenever they had passed through Tung Chung Road.	Base on the site inspection records and information collected from the RSS and the Contractor, the complaint was considered due to due to the vehicle movements on Tung Chung Road. In response to the complaint, the RSS has conducted site inspection in the afternoon on 18 th December 2006. The Contractor had immediately mobilized labors to clear the mud trail on Tung Chung Road between ch.3700-4000 using sweepers. In order to maintain the condition of Tung Chung Road, the Contractor has mobilized more staff to clear the mud deposits on the whole Northern Section of Tung Chung Road on 23 rd December 2006. The Contractor has provision wheel washing facilities at each site exit/entrance. In order to maintain Tung Chung Road condition, the Contractor has mobilized a water truck solely for wheel washing purpose at the site entrance near RW37 between ch.3700-4000 since 23 rd December 2006. The location is the most busy site exit/entrance for soil removal as wheel washing facilities. Wheels of each vehicle shall be washed before leaving the site. The wastewater after wheel washing at each site exit/entrance shall be collected and treated before discharge at designated location. also mobilized water trucks	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S82	The nullah near the Yat Tung Estate	15 Jan 07	The complaint was lodged by the Legislative Councillor Hon. Albert W.Y. Chan regarding frequent discharge of muddy water from the Tung Chung Road improvement project on 15 th December 2006. According to Mr. Chan's letter, the complainant was a resident living in Tung Chung. The DSD letter pointed out that muddy water was being frequently discharged to the nullah near the Yat Tung Estate, and confirmed that the site of Tung Chung Road improvement project was the source of such discharge.	After investigation, the discharge of muddy water was largely due to the deposited silts caused by previous heavy rainstorms in November. The contractor has responded promptly in deploying a number of actions to remedy the matter. These include de-silting operation at Wong Lung Hang nullah on 23 rd December 2006 to remove the accumulated soil and silt materials washed down by the discharges, of which photographs are provided. In addition, several intermediate sedimentation ponds along the temporary drainage system south of Shek Mun Kap to improve de-silting capacity have been installed, and that the site condition will be closely monitored so that advice on any practical measures in improving the quality of water discharge to Wong Lung Hang nullah can be given. In addition, the Contractor is also undergoing continual inspections and monitoring on the conditions of the concerned discharge of the construction site, and is in close liaison with the ET to cap exceeding levels of future discharge.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S86	Slope opposite to the AFCD's Office at Tung Chung Road near mileage M2.5	8 Feb 07	The complaint was lodged by a resident in Lantau Island regarding the construction noise generated from the road works at the slope opposite to the AFCD's Office at Tung Chung Road near mileage M2.5.	The site of concern is most likely at the RW6 of the Project. According to the Contractor, soil nailing works was conducted at RW6 and the first stage of soil nailing works at RW6 has been completed before 8th February 2007. According to the noise monitoring results at monitoring station NM5, Tung Chung Au Country Parks Management Centre, which is located near the AFCD's Office, there was no exceedance recorded from 2nd January to 14th February 2007. As advised by the Contractor, the following mitigation measures will be implemented as far as possible to reduce the noise nuisance to the nearby residents when soil nailing works carry out in the future: To cover the soil nailing works area with tarpaulin; To reduce the number of machines for soil nailing; To orientate the machines for soil nailing works so that the major noise generating part will not directly face the Noise Sensitive Receiver; and To scatter the plants so that the noise being generated will not be centralized in certain direction.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S90	Northern and Southern Section of Tung Chung Road	20 May 07	The complaint was lodged by the Green Lantau Association at on 20 May 2007 regarding failed drainage for the Project on that day.	According to the Contractor, the main concern in the Northern Section is that a large amount of seepage from the permanent slope near the Stream 18 and Stream 21 was observed. The permanent hinterland u-channel was not able to collect most of the hinterland water which ultimately collected by the carrier pipe and increased the loading of the treatment facilities at Shek Mun Kap. As advised by the Contractor, the main problem in Southern Section was due to the fact that the silt is too fine to be settled within a short time, i.e. 3 minutes, as stated in the EIA Report. Due to the large catchments of the site, muddy water could not be completely settled or treated before discharged or overflowed. No bigger sedimentation tank can be constructed due to the site constraint to retain all surface water in heavy rainy days. The complaint was considered justifiable. However, it is beyond the Contractor's capability to completely avoid muddy water discharging or overflowing to sea due to the site conditions and constraints under increment weather conditions.	The complaint investigation report was commented

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S91	Zone 4 (STR 14)	1 June 07	The complaint was lodged by a resident in Butterfly Crest, Lantau Island regarding the construction noise generated from the Project on Sunday, which is likely to be 27 th May 2007.	According to the Contractor, construction works were undertaken near STR 14 in the morning of 27 th May 2007 and the Powered Mechanical Equipment (PME) used on that day included 2 excavators and 1 dump truck at STR 14. The concerned site was covered under the construction noise permit (CNP) no. GW-RS0281-07. As advised by the Contractor, the 2 excavators and 1 dump truck, which categorized separately as Group A and Group E of the abovementioned CNP, were utilized alternatively during the operation in order to comply with the conditions stipulated in the CNP. Base on the information collected, the complaint was considered not justifiable as the equipment used comply with the CNP conditions.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S93	Western Section of Pui O Bay	22 May 07	The complaint was lodged by the Green Lantau Association at on 22 May 2007 regarding muddy water was observed at 50m west of the Tung Chung Road southern section around 11am on 22 May 2007.	As advised by the Contractor, the main problem in Southern Section was due to the fact that the silt is too fine to be settled within a short time, i.e. 3 minutes, as stated in the EIA Report. Due to the large catchments of the site, muddy water could not be completely settled or treated before discharged or overflowed. No bigger sedimentation tank can be constructed due to the site constraint to retain all surface water in heavy rainy days. In the site near Pui O Wan, the Contractor has exhausted their efforts including to pump the water from sedimentation tanks back to the stockpile area. Unfortunately, one of the pumps was out of order in the early days of that rainy period. However, the pump has been rectified on 22 May 2007. The complaint was considered justifiable. However, it is beyond the Contractor's capability to completely avoid muddy water discharging or overflowing to sea due to the site conditions and constraints under increment weather conditions.	The complaint investigation report was commented

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S100	Stream water behind WSD's weir	27 July 07	The complaint was lodged by a resident living at Lung Tseng Tau area during the meeting between RSS and the representatives from the villages at Lung Tseng Tau area on 17 th July 2007 regarding turbid water supply from DO main to the village houses at Lung Tseng Tau area.	The RSS and the Contractor had a site investigation with the complainant at his household water supply, the WSD weir and a work area immediately upstream of the weir (STR02 near the Stream 12) on the same day. It was observed that the water directly from the household supply was found with low degree of turbidity when comparing it with portable water supply. According to the visual inspection of the RSS and the Contractor, the stream water behind the WSD's weir, which is the source of water supply to the villagers via a DO main, was found clear and there was no sign of contamination. Inspection of the work site at STR02 upstream of the weir indicated no activities affecting the upstream water quality. By reviewing the water quality monitoring data at Tung Chung Stream during early of July 2007, the turbidity and SS values are considered to be low and the data revealed that the Tung Chung Stream and the WSD weir were not contaminated during the above mentioned period. Nevertheless, In order to minimize the water quality impacts, the Contractor has implemented following mitigation measures: • To erect sand bag bund in the vicinity of STR02; • To shotcrete the soil surface near Stream 12.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S104	Tung Chung Road and Tung Chung Au near AFCD's Office	Road and Tung Chung Au near AFCD's The complaint was lodged by Wil. Ho on 6 th August 2007 regarding a suspected case of silty runoff and muddy water generated from	No non-compliance or environmental deficiency related to or in the vicinity of the concerned area was identified during these site audits. According to Hong Kong Observatory, Hong Kong was under the effect of the tropical storm over the central part of the South China Sea which brought heavy showers with 100.4 millimeters of total rainfall recorded on 6 August. The amber rainstorm warning was hoisted between 15:55pm to 17:30pm.		
				The Contractor has confirmed there was no construction activity in the concerned area on 6 th August 2007 due to heavy rainfall. According to the Contractor, muddy water was the silty runoff from nearby work sites due to the heavy rainfall on the day.	Closed
			 The Contractor has implemented following mitigation measures: To desilt temporary drainage channels and sedimentation tank. To clear the silt and mud in the surface of haul road at RW06 ad RW07. To cover exposed slope with tarpaulin at RW06 and RW07. 		
				According to the RSS and the Contractor, no further report of silt and muddy water runoff from concerned area was received after implementation of the aforesaid mitigation measures.	

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S113	Upper and Lower Cheung Sha Village	12 December 2007	The complaint was lodged by Mr. Liu on 12 December 2007 regarding dust nuisance at Upper and Lower Cheung Sha Village.	According to the Contractor, the main dust emission in the vicinity of Cheung Sha Village was due to the road works and associated vehicle movements on Tung Chung Road.	
				The Contractor has implemented following mitigation measures:	
				 Cleared the silts on the haul road; Applied watering on the road by water hose at San Shek Wan; Increased the number of water browsers; and Covered the exposed slope and stockpiles with tarpaulin sheets. 	Closed
				By reviewing the air quality monitoring data, there was no exceedance of air quality monitoring results on 8 th and 14 th December 2007 and dust mitigation measures have been implemented by the Contractor.	
				According to the RSS and the Contractor, no further complaint regarding dust nuisance from concerned area was received after implementation of the aforesaid mitigation measures.	

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S147	Zone 1 Tung Chung Road November 2008	Chung Road November from EPD by Mr. Peter Tang on 14	According to the Contractor, there are two major stockpile areas within the construction premise which are located at San Shek Wan and Tung Chung Road. The location specified in the complaint was the stockpile area at San Shek Wan. This location was used for stockpiling reusable materials. Base on the information collected, the complaint was considered not justifiable as San Shek Wan is one of the designated C&D materials sorting areas of the Project and no direct evidence shows there was land-filling activity by this project at the specified location.		
				However, as a follow up of the complaint, the Contractor has implemented mitigation measures as follows:	Cl. 1
				Preliminary segregation of waste was enhanced; and	Closed
				Water was sprayed on the stockpiles more frequently to further suppress dust generation.	
				The Contractor was recommended to continue the following mitigation measures :	
				To provide dust suppression measures to the stockpiles at San Shek Wan, especially during dry season, to minimize dust generation;	
				To carry out continuous segregation of materials on site;	
				To avoid accumulation of stockpiles; and	
			L-15	To dispose of non-reusable material to designated outlets as soon as possible.	

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S152 and S154	Zone 1 Tung Chung Road	3 rd and 8 th April 2009	EPD received a public complaint about suspected land- filling of non-inert construction waste in early 2009 at Zone 1 of Tung Chung Road for the Project and a similar verbal complaint regarding illegal land filling of construction waste on the same site (Zone 1) was received from Lands Department.	Base on the information collected, the complaint was considered not justifiable as San Shek Wan is one of the designated C&D materials sorting areas of the Project and no direct evidence shows there was land-filling activity by this project at the specified location. Sorting and disposal of C&D materials were conducted in accordance with WMP.	
				Nevertheless, the Contractor was recommended to continue the following mitigation measures in order to minimize the environmental impact on the nearby community and the amount of waste produced:	Closed
				Stockpiled material shall be covered by tarpaulins and/or watered as appropriate to prevent windblown dust and/or surface run-off. Storage of material on site shall be kept to a minimum to avoid nuisance to local residents;	
				excavated material in trucks shall be covered by tarpaulins to reduce the potential for spillage and dust generation; and	
				good site practice shall be implemented to avoid waste generation and promote waste minimization.	

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S157	New Tung Chung Road and near-by soil erosion in Cheung Sha Catchwater	1 st June 2009	The complaint was raised by the WSD on 1 st June 2009. WSD concerned about the soiled water had been collected from New Tung Chung Road and soil erosion was found at Cheung Sha Catchwater. The ETL of the Project was informed of the complaint by CCJV through the e-mail on 5 th June 2009 and initiated the complaint investigation procedures.	complaint was considered justifiable as heavy downpour of rain had caused soil erosion on exposed slopes leading to Cheung Sha Catchwater. The Contractor was recommended to take sufficient mitigation measures to minimize the exposed areas to rain by covering the	Closed

APPENDIX M SUMMARY OF WARNING / DIRECTION ISSUED BY THE EPD AND PROSECUTION

Appendix M - Summary of Warnings / Direction Issued by the EPD and Prosecution

Summary of Warnings / Direction Issued by the EPD

Date of Letter	Warnings/Direction
3 February 2005	The Contractor was requested to construct catch pits and perimeter channels in
	advance of site formation and earth works
17 May 2005	The Contractor was requested to immediately re-provide the on-site wastewater
	management systems to adequately cater the rainwater runoff and to submit the
	detail proposal for runoff management and treatment systems.
4 October 2005	The Contractor was requested to rectify the situation in order to comply with EP
	Conditions 2.4 & 2.5 regarding the provision of drainage systems, EP Condition
	3.16 regarding site runoff mitigation measures and EP Condition 3.6 regarding
	no works of the Project shall be carried out outside the "limit of works area".
15 December 2005	The Contractor was requested to rectify the situation of Zone D where fuel oil
	was found spilled onto ground of the works area in contravention to Section
	7.5.2.1 of the Waste Management Plan (WMP). The Section stipulates
	provisions against spillage of fuels to prevent contamination of the construction
2437 1 2007	site.
24 March 2006	The Contractor was requested to rectify the situation in order to comply with EP
	Condition 3.9 regarding the stipulated span of temporary bridges used during
12 4 21 2006	construction to cross the stream.
13 April 2006	The Contractor was requested to rectify the situation of Zone E where fuel oil
20.1	was stored within the Country Park in contravention to condition 3.14 of the EP.
29 June 2006	The Contractor was requested to rectify the situation that site runoff will not be
26.0 1 2006	discharged into Tung Chung Stream in order to comply with EP Condition 2.4.
26 September 2006	The Contractor was requested to rectify the situation that excessive dust
	emission occurred. Watering programme shall maintain to ensure that all
	exposed road surfaces and dust sources are wet in order to comply with EP Condition 1.7.
4 October 2006	-The Contractor was requested to rectify the situation that site runoff will not be
4 October 2000	discharged into Tung Chung Stream in order to comply with EP Condition 2.4.
	-The Contractor was requested to rectify the situation in order to comply with
	EP Condition 3.9 regarding the stipulated span of temporary bridges used
	during construction to cross the stream 28
	The Contractor was requested to rectify the situation in order to comply with
	EP Condition 3.9 regarding the stipulated span of temporary bridges used
	during construction to cross the stream 32.
	- The Contractor was requested to rectify the situation in order to comply with
	EP Condition 3.9 regarding the stipulated span of temporary bridges used
	during construction to cross the stream 33.
13 February 2007	The Contractor was requested to rectify the situation that site runoff will not be
-	discharged into Tung Chung Stream in order to comply with EP Condition 2.4.
19 February 2008	The Contractor was requested to take all necessary actions to rectify the
	situation that surface run-off from the construction site discharged into storm
	drain without treatment in order to comply with EP Condition 3.16.
14 April 2008	The Contractor was required to take all necessary actions to rectify the situation

Date of Letter	Warnings/Direction
	that a section of the site near Pak Kung Au was not provided with vehicle
	washing facilities including high pressure water jet at vehicular exit points so as
	not to contravene the statutory requirement.
8 December 2008	The Contractor was required to take all necessary actions to rectify the situation
	that a suspected chemical waste (mineral oil) was found improperly packed and
	stored at Zone 1 Tung Chung Road on 4 December 2008, so as not to
	contravene the statutory requirement of the Waste Disposal (Chemical Waste)
	(General) Regulation (Cap. 354).

Summary of Notification of Summons

Date of Summons	Details of the Summons	Status
25 January 2007	Construction works at a slope next to Stream no. 28	Withdrawn by
	along Tung Chung Road, Cheung Sha, Lantau Island	EPD
	which contrary to EP Condition 3.9 concerning works at	
	Stream 28 on 26 July 2006	
16 February 2007	Construction works near Stream no. 8 along Tung Chung	The Contractor
	Road, Cheung Sha, Lantau Island which contrary to EP	was fined \$7500
	Condition 2.4 by discharging runoff during construction	on 4 June 2007.
	into Tung Chung Stream on 16 August 2006	
17 May 2007	Construction works near Stream no. 8 along Tung Chung	The Contractor
	Road, Cheung Sha, Lantau Island which contrary to EP	was fined \$7500
	Condition 2.4 by discharging runoff during construction	on 4 June 2007.
	into Tung Chung Stream on 21 November 2006	

Summary of Notification of Successful Prosecution

Date of Successful	Details of the Successful Prosecution	Status
Prosecution		
4 June 2007	Construction works near Stream no. 8 along Tung Chung	The Contractor
	Road, Cheung Sha, Lantau Island which contrary to EP	was fined \$7500
	Condition 2.4 by discharging runoff during construction	on 4 June 2007
	into Tung Chung Stream on 16 August 2006	
4 June 2007	Construction works near Stream no. 8 along Tung Chung	The Contractor
	Road, Cheung Sha, Lantau Island which contrary to EP	was fined \$7500
	Condition 2.4 by discharging runoff during construction	on 4 June 2007
	into Tung Chung Stream on 21 November 2006	

APPENDIX N CONSTRUCTION PROGRAMME

J. delike i						<u> </u>		
				or the other last	SERVICE SERVICE			THE RESIDENCE OF STATES OF
AVECTOR OF THE		Orle				Units in interesting		THE RESIDENCE OF THE PROPERTY
	Wood Designed to the Control of the	Dur 3	Comp	CHEST THE LEGISLA	H I SHITLE SHE	以外,所有其实的证明的	新城市的	
etaining Wall R	WOO 法影響學并在自然學者的學術學的不能要的學者	1.15 (A) 14 A	e tance	-4			144 0000	□ Additional Toe Wall
		26	0	02MAR09 *	31MAR09	49d		{
\$1-3590	Additional Toe Wall	<u></u> _		DIAPROS	15APR09	494 \$1-3890	\$1-3633, \$1-3810	□ Backfiling
\$1-3900	Backfiling	9				494 \$1-3900	ZAKD001	O Slope drainage
64.30(0	Stope dialnege 可能的可能是好多少少可能的能够可能是证据。	13	0 _	15APR09	30APROS	S.A. Harrist Interest Interest		
1 21-74-0	- What with the start of Saint of the life bath in	y May by	1.71	15 日本	统制和目的	September 1991 Septem		a a sa
ORTHODA FIRST	di-lactoria and a sure			Faringer 1	25APR09	49d S1-3631, S1-3900	3[-3634, 31-3635	
31-3833	Outstanding parapet blw RW005 and RW006	8	<u> </u>	18APRC9			ZAK0001) Street Aurulius o Fermodiais works
	Street humbure remedial works	4	[0	27APR09	30APR09	464 \$1-3033	ZANDXII	I Footpath and Verge remedial works
81-3634	SUBS. ILLINGS FROM MARKET	<u> </u>	0	27APR09	3CAPRO9	401 51-3833	20000	
\$1-3535	Focipath and Verge comedial works 5 3100, 5210 Supply 12 December	<u> </u>		Salania.		Carta Maria Carta Ca		
D (CH. 272	FOOTER # 14	a lide	W 684	2012年12	11. 13.14	的物质型型 地址 地址	THE THE WASHINGTON TO SERVE	-
eterbig Val	RW07。自然是在是证明,并是一种的证明,是一个工作。	4 1 1			`		51-4260	Additional Drainage Works
		28	0	02MAR09	31114R09	434		□ Backtiling (Remaining)
31-4241	Addhonal Orainaga. Works	Ιδ	0	01APR09	25APR09	494 51-4241	\$1,4421, \$1,4430	
\$1-4250	Backhiling (Remarking)	<u>.</u>	<u> </u>	الله الله الله الله الله الله الله الله	STATE OF THE PARTY	THE SECOND OF THE PARTY.	Pring his requirement	1
loadworks	Continues of a pit in the second			<u> </u>			ZAKDOOI	1 Foolpeth Remodial Works
<u> </u>		: 4	į D	27APR09	30APRO9	496 51-4260	_1	I Street Furniture remedial works
\$1-4421	Footpath Remedial Works	- 4-		27APR09	30APR09	49d S1-4260	ZAXCOOI · · · ·	
\$1-4430	Street Furchuse remedial works		<u></u>	1	1 3435 (1958)	- 10 3 (No. 10 a) - 12 (No. 10	。 1887年中的中央教育的	<u> </u>
E (CH. 310	00 - 4010) 10 10 10 10 10 10 10 10 10 10 10 10 10			10 K 10 S 2 WA	30 VI 1	Busher a marining		-{
Slope Works							ZAVDAN	₩
		163	42	020EC08 A	BEHILDE		ZAKDO01	
\$1-5151	V.O. 202			the second	V 54 35		· 特別 (2017年) 12 (1017年)	31
Retairing Wal	RW10					. 		☐ Additional drainage who @ ch 3400
		22	0	GIAPRO9	30APR09	45d	ZAKD001	<u></u>
St-5390	Additional drainage was @ ch 3400	_!					4, 300 100	11 - ()
Retaining Wa	LRW11					·	\$1-5838, \$1-5847	Additional drainage works
·		96	25	01FE8097	3CHAY09] •		Bacirling
[81-5450	Additional drainage works			GIFEB39	30MAY09	0	\$1-5838, \$1-5847	
\$1-5463	Backfilling				٠		र के कि एक कि इंदेश अंदर्श	
Readworks								Additional drainage works
Road work		29	1 76	D2JUNDS.	A 30MAY09	1 0	\$1.5838, \$1.5847	11
\$1-5645	Additional drainage works	_ -		CIJUNOS		0 \$1-5450, \$1-5483, \$1-5846	ZAKD001	and Footpath and verge terredial works
\$1-5847	Footpash and verge remedial works	28		VIJONO		.L.		
	l			at the ex-	30JUN09	0 \$1-5450, \$1-5463, \$1-5848	ZAKDOGI	mat Additional street furniture
\$1-5838	Additional alrest fundants	26	i 0	0110403				
<u> </u>							and the second second	<u> </u>
Zone FifCH. 4								
1,41.02 11 73 77			4 7 0	16MAROS	31MAR09	716	ZAK0001	O Additional noting
51-6365	Additional nost/g		<u>' </u>		ــــــــــــــــــــــــــــــــــــــ			-
Retaining V	(All 8K/)38				<u> </u>		<u> </u>	- Landard dishard with a world
[<u> </u>		2 7 3	3 DIFEBOS	A 30APROS	450	ZAKD001	Adothoral drainage works
\$1-5530	Additional drainage works	i'	<u>i_</u> `		_L			<u> </u>
Culvert at C								SED 1050mm dia, pipeline under existing TCR
1		·- <u>;</u> -	- i - o	5 LAFEBOS	A 16MAROS	9 B-ld	ZAKD001	281 Incoust any thems man serve d 1 and
\$1-6615	1050mm da. pipeline under existing TCR		.9					
Roadworks			<u></u>					
1111111111								Deta Radskin Checked Approved
++							•	27MAROS Revision (5
Start dela	12J-1404 Early bed 30AUG12 Progress tell							
Firish dele Dete dele	CILLAROS Critical bar				-	🛥 🛴 Contract No. HY/200	1/19	
Aumber Version	Revision 10 Summary bas					Improvement to Tung Ch	ung Road	
Project names	9V18A Start missions point					Works Programme Re	ev. 16	
p Primavers	Systems, Inc. Start missions point							

A CONTRACTOR OF THE STATE OF TH

٠	JUNEOUS A		#87533	358 3 3	zirege sz		icae,	a de la companya de l				FROM
Ļ	100	Leithing Cheminion	Dur	Com	3 ST 13	Pine	100	Prescripto	No. Carette	1	SECTION OF THE PROPERTY OF THE	9
H	\$1-6722	Road Junctions (g. ch4300	54	35	D7FEB09 /	I5APR09	4	60	91-6724, 51-6725	B	Road function @ ch4000	
;†	51-8723	Read Junction & chie570	54	35	O7FEB09 A	15APR09	4	24	91-8724, 91-8725	_	Royd Lington & ch4570	—8
IJ	81-6724	Additional feelpath & verge	13	0	18APR09	30APR09	46	9d 81-8722, \$1-8723	ZAKDOOI	\neg	O Additional (cotpath & verga	—
	61-6725	Adultional street furnitures	13	10	16APRC9	30APR09	4	9d S1-4722, S1-8723	ZAKD001		D'Aticktional street fumbures	
٠.	Pump House	or Fire Hydrant @ CH. 4398	4	. / :- }	.e. 1744.02.	44 FEE	13.	(44) (44) (44) (44)		22	Dynosouth tassi intuities	δo
1	81-6922	Yesting & congresioning								•		SR EL
	\$1-6923	Fencing & ground level works	65	50	O1JAHO9 A		46		\$1-8923	_ <u> </u>	Testing & commissioning	Ξ
Ή	الله	1	j 48	<u> </u>	02MAR09	30APR09		M S1-8922	ZAKDOOL		Fencing & ground level works	
1	Transformer n	oom al CH. 4850 \$ 10 7 10 10 10 10 10 10 10 10 10 10 10 10 10		<u>: :</u>	10 74 17	अन्ति होते होते.	310	rajest i vice de la	社群的特別的問題[1]			Ö
4	\$1-6903	Fending & ground level works	22	0	01APR00*	30APR09	49	н	21120001	4		JOINI
8.							865.0		ZAKDOOI	_	☐ Fencing & ground level works	
1,	DOME F. LUTT. 401	V = 4000) (100)(80) (40) (40) (40) (40) (40) (40) (40) (4			v - 1555	$(a_{i,j}, a_{i,j}) \in \mathcal{M}_{i}$	20.0	PRESENTA INFORMACIONAL PROPER	Silvers and a cross of a party of the con-			VENTURE —
IJ	Language Sci	hydris (1) 7 print (1) to the control of the contro		· · ·	11 14 1 1 2	روغ، لوبية في	4 <u>()</u>	401000000000000000000000000000000000000	对为有"统治和法律的数据"。			Ę
li	81-6010	Landecape Softmorie	123	1 1	UTAPRO9*	31AUG09	1	· · · · · · · · · · · · · · · · · · ·	C4 cana	4		
\parallel	Establishment	morks the state of	1				il. Sagar	a damenta se de a teledo el ales	\$1-6920	4	tandacepe Sorthorida	
							- 4 - 1	2014 - 42 Shitting \$ 17 1 75 30	-4-2-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-	<u> </u>		
Щ	\$1-6920	Establishment Works for Section (A(ctain no.084)	710	0	01SEP09*			DIS1-8810	ZáKD003	┨ .		
<u>د</u> د	1000 2 m 15 0 0 0		SE(3)(3)	建物液	THE STATE	多 多数	T C				Examplement	F A X
lî	Remaining Wo					- 54545 (CAS	· · · · · · · · · · · · · · · · · · ·		Contraction of the second] [×
.							• •	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	the season of the coast	- [공
	92-1250	Completion of section 2	0	100		06FE809 A			ZAKO002	-[] - -	ompisition of section 2	٠
ij	S2-(300	Defects and Outstanding Works	300	9	07FEB09 A	06FE810	7831					:
	tion 24 (6.2%) one 1-6	报籍的人的人的证据 的证据,但是一种,但是一种,但是一种的	43.44	.((2y		\$ 100 PM		terbilita a teachi		5	Defects and Outstanding Weeks	χ̈́
1 ~	Landscape Soft	works	·		. 1, /4.			<u>在</u> 有品牌的企业的企业的基础的	Alfafraid Carlott and Antaria.			Ю
$\ $	77.7			· · · ·	···			Contract of the T	TOTAL TO ENGINEERS	11		Ŋ
Ш	52-8730	Landscape Softworks	+22	65	CIAPROS A	31AUG09	ō		\$2-6740	Ш		ŭ
!	Establishment v	rorks						 	10 T T T T T T T T T T T T T T T T T T T	ŦŦ	Landscape Schwicke	
Н	\$2-6740	Eslabishment Works for Section 2A	aio!					<u> </u>	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	11		[601
LL Sm	I I		710		DISEPO9	31AUG11	D	\$2-8730	ZAKD004	1 [٦į
	Service Control		Sance of	ingle und	o objektivate:	arder seri),d.t.ve	维护的 的关系。为1955户被	2000年100年100日		Establishmer	- 1
П	Feebure Ho. 131	IE-B/C65		_ :				temasi in ny taona ao	Topic Constitutions Report	11		į
Ш	S3-3030	Insiat sot nail (199 nos.)								$\ \cdot \ $		- 1
$\ \ $	\$3-3040	Slope surface protection	29	66	A 60HYFIE	05MAR09	3961	\$3-3010	\$3-3040, \$3-3050	,	Install soil neil (199 nos.)	.
ااا	Feature No. 13h	<u></u>	14		DSMARO9	21MAR09	813d	\$3-3020, 83-3030	\$3-3070		D Slope surface protection.	ĮĢ
Ш	waxaa 190, 190	LWCQ				:						 [₹
	\$3-3050	Install soll nati (127 nos.)	20	G	C6MAR09	28MAROS	39801	\$3-3030	23 2000	 		(A 20 20 20 20 20 20 20 20 20 20 20 20 20
	\$3-3060	Full out tests (4 nos.)	-3		30MAR09				33-3060		□ Install soli neil {(27 nce.}	Į.
Ш	\$3-3065	300rum U-channel at tyesh & toe	20				-		33-3065	1	GPut out leate (4 nos.)	5009 5000
Ш	\$3-3070	Slope surface protection	 ;	- 1					\$3-3070, \$3-3090	Ī	CD300mm U-channel at creal & los	[8
۱¦	Braire No. 13N	<u> </u>	14		08MAY09	23MAY09	3180	\$3-3040, \$3-3065	3-3110	-	O Stope surface protection	₽ ⊢
İ							·			- -		17:38
∐i	63-3383	instalt solinal (111 nos.)	19	3	COLLA VOS	30MAY09	3950 5	\$3-3065 I _S	3-3090			- ₽₩
		Brill F	l.			<u> : -</u>	- #				. Joseph (111) Isal Mos listeni □	Įσ
inla	الذ العلم	MAC4 Emily ter MG11 Semily ter										P 3/7
	dele Diki er/Version Revi	ARDS LIN MARK Critical car						• •	•		Date Revision Checked Approved 27MAR09 Revision 15	F 3
444	Number 14 Aparto RV1	Summuly bay			-	• <u>:</u>	, c	Contract No. HY/2003/19				
	Timesera System	Line Start militations point				, tr	npro	vement to Tuna Chuna Ro	pad			
	;	First influsions point					NA4	orks Programme Rev. 16				

33-3090	Pull out feet (5 nos.)	8 5:63% [576]	# <u>\$_000</u>	OUNURCO	COULT CO		Production 98 80 83-3080	22.0482		Purious and the second
53-3100	SCORDA Mapped & U-channel	20	10	1000000	0370408		36d S3-3090			
83-3110	Slope surface protection	14	1 0	DAJULOS	2010109	┿┈		53-3110, 53-3120		300mm stepped & u-channel
Feeture Ha. (:	SHE-ELC62			_l .	Д.		84 S3-3070, S3-3100	\$3-3150		☐ Slope surface protection
						7	第二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十	1. 2. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.		
53-3120	Instal sofinal (144 pos.)	22	0	04JUL09	29101.09	30	64 53-3100	\$3-3130	-	☐ Iraiat sot not (144 nos.)
\$3-3133	Pull out leate (5 tice.)	В	0	30JUL09	07AUG09	36	ed \$3-3120	\$3-3140		O Pull out tests (5 nos.)
\$3-3140	300mm slapped S u channel	20	0	08AUG09	31AUG09	36	6d \$3-3130	\$3-3150, \$3-3160		□ 300mm Hepped & u channel
\$3-3150	Slope startece protection	1+	10	01SEP09	(6SEP09	51	0d S3-3110, S3-3140	\$3-3220		· F
pettre Ho. 13	HE-B.58476 李雪新是海上市企业。 1975年3月	电子数字类	(२५)	12 1931	建筑型制度	3.0	1476212 2013 121	I BESTVERE	37 15.	☐ Slope surface protection
\$3-3160	Recompact slope	14	Τ ο	01\$EP09	16SEPC9		7			
\$3-3176	Reconstruct 750mm elepped channel & stakway	23	T G	175EF09	1000109	—-	31 33-3140	\$3-3170	_]	O Recompact slope
\$3-3150	[300mm u change]		ļ		<u>. </u>	├	3d 53-3160	\$3-31,60, \$3-3160		☐ Reconstruct 750mm slepped channel & etainway
	NE-BACRO 5	14	0	12GCT09	280CT09		rd \$3-3170			C) 300mm ti channel
			- :	* * * *	. 77 74 5 TE 3	7. (81)	<u>1996-40-56-03</u>	102 403 3 3 3 4 6 7 2	2.5	
\$3-3190	Install coll rad (42 sce.)	12	0	1200709	240CT09	396	kd S3-3170	\$3-3200		□ Insial acĕ nai (42 nos.)
\$3-3200	Pull out leat (1 nos.)	8	0	27 GCT09	04HOV08	396	d 83-3190	\$3-3210		
\$3-3210	300mm te channel	14	0	05NOV09	20NOV09	396	d 53-3700	53-3220, 53-3230	[OPul out lest (1 ros.)
\$3-3220	Slope surface protectors	14	G.	21NOV09	07DEC09	458	d \$3-3150, \$3-3210	\$3-3260		O 300mm u chunnel
azura No. 134	NE-B/C233	·	<u>' </u>		'	. ن		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	 -	C) Siepe surface protection
83-3231	tretall soi rall (14 nos.)	110	<u> </u>	Athial ba	2400000					
83-3240	Full out losis (2 rice.)	12	0	21NOV09	04DEC09		d 53-3210	\$3-3240		□ instal sof nail (44 nos.)
\$3-3250	Reconstruct 300 mm u channel	B	0	C5DEC09	140EC09		83-3230	\$3-3250	_	OPul cut tests [2 nos.]
\$3-3260	· _ ·	14	0	150EC09	02JAN10	398	53-3240	\$3-3260, \$3-3270		□ Reconstruct 300mm u change
esture No. 13h	Slops surface protection	20	0	DHAKED	28JAW10	436	\$3-3220, \$3-3250	\$3-3300	\neg	☐ Reconstruct 300mm u channel ☐ Slope sturface protection
·	TE-S/CH/2		-							Political
\$3-3270	inetal sol rall (413 nes.)	20	0.	04JAN10	26JAN10	396	\$3-3250	53-3280]	
\$3-3380	Pull out leafs (3 ros.)	- B	G	27,141110	04FEB10	398	 	_ -		□ Inelal soil mai (113 nos.)
\$3-3290	300mm u channel	14	0	C6FEB10	23FEB10	3960		53-3250		@Pud out tests (3 nos.)
\$3-3300	Slope surface protection	20	0	24FEB10	18MAR10		S3-3260, S3-3290	\$3-3300, \$3-3310	_	☐ 300mm u channel
ethre Ho. (3)	IE-B/FR68		لــــــــا				L	ZAKD005	$\perp \perp \mid$	☐ Slope surface protection
45.00.4						·		<u> </u>	! i	
\$3-3310	Remove existing subble wall	10	0	24FEB10	COMARIO	3560	\$3-3290	S3-3320	┤	ORanous syletten autotic
\$3-3320	Recompact slope	14	0	OSMARIO .	23MARIO	3984	83-3310	\$3-3330	-	O Remove existing rubble wat
83-3330	390mm u channel al los	-14-	-0-	2#14.7(10	12APR10	356:	53-3320	ZAK0005	╧╀╂	☐ Recompact slope
alure No. 134	E-B/CI15								╼┼┼	□ 300mm is channel al toe
\$3-3370	Slope surface protection	£4	36	24FEB09A	11MAR09	SUD-1	63 3120		$\exists 1$	
ature No. 13N				- 11 2203 7	- Invalva	2003	\$3-3360	S3-3410		O Stope surface protection
							<u> </u>		$\dashv T$	
\$3,3360	Sistal sel nail (75 nes.)	14	0	O2APR09	22APR09	0	\$3-3690	83-3390	- 	■ instal voli naii (75 noo.)
	Full out tests (4 pcs.)	8	- †	23APR09	O-HALAYD9	0	53-3380	\$3-3400		· · · · · · · · · · · · · · · · · · ·
\$3-3400	30Cmm u channel at lee	14	0	CSHLAYOS	20MAYT9	D	\$3-3390	\$3-3410, \$3-3420	-11	II Pul out tests (4 nos.)
KG 33 4	€ Summary point		<u>_</u>		ور	lmpro	Contract No. HY/2803/19 Ivement to Tung Chung Torks Programme Rev. 1	Road		Date Revision Checked Approved Date Revision Checked Approved

FROS

:0000

çο

SPE

JOINT

VENTURE

F E E

ž

8

Ň

2988

1601

ع

60007

4

T

62-A000	Description Landscape Softworks in Undefined Section	Orfg F(96] : Nor : Camp 148 0	Start (1) Flogali DIAPRO9 31AUGO9	Total Predection in Float 15 15 15 15 15 15 15 15 15 15 15 15 15	52-8010	EMARIO AND NIB OF MARI	Mile Section	वास
S2-8010	Establishment Works for Undefined Section	713 0	O1SEP09 31AUGII	0 \$2-8000	ZAKDS68		Eslab	dahmer ramidak
						\$:		
								İ
						•		
						•		
			•		·			
-				·		1 1 1		
			·	•				
				·	. ·			
							i	
-								
					•			
								ŀ
	·					·····		
				: !	-			
				. A				
			4	:	-			
ŧ	JNO4 Eath ber				•			

uri data 25JUN04
dah data 50AUG12
da data 01MARD9
mbathferios Redalon 16
spe stabber TA
spe stabber RV16A
4 Primereus Systems, Inc.
347
1585

Surretary point

Size and external point

Figure in the state point

Contract No. HY/2003/19
Improvement to Tung Chung Road
Works Programme Rev. 16

Date 27MANGE Redska Redska ja Checked Approved

APPENDIX O WASTE GENERATED QUANTITY

Contract No. HY/2003/19 - Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha

Name of Department: Highways Department Project Commencement Date: June 2004

Construction Completion Date: December 2009

Approved Project Cost: \$688.5 Million

Monthly Summary Waste Flow Table for Year 2007

Year	Ac	tual Quantities	s of inert C&D	Materials (in 10	³ m ³)	Actual Quantities of C&D Wastes (in 10 ³ Kg)											
	Total Quantity Generated	Broken Concrete ⁽¹	Reused in the Contract	Reused in other Projects	Disposed as Public Fill	М	Metals Disposal Recycle		Paper/cardboard packaging		Plastic ⁽²⁾		Site clearance waste ⁽³⁾	Others, e.g. g (in 10			
	(a)	(b)	(c)	(d)	(e)	Disposal			Recycle	Disposal Recycle		Disposal	Disposal	Disposal	Timber Waste		
Jan	4.937	0	14.520	0.540	1.397	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	73.61	1.5	0		
Feb	4.135	0	8.746	3.540	1.496	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	34.21	1.5	0		
Mar	4.954	0	9.978	3.560	2.975	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	173.27	2.0	0		
Apr	2.976	0	9.010	0	0.911	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	84.83	2.2	0		
May	3.513	0	10.156	0	1.555	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	101.24	1.3	0		
Jun	5.882	0	11.020	0	8.588	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	52.51	1.7	0		
Sub-Total	26.397	0	63.430	7.640	16.922	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	519.67	10.2	0		
July	3.458	0	10.240	0	1.287	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	85.11	1.140	0.060		
Aug	3.627	0	11.144	0	0.946	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	91.00	1.710	0.090		
Sept	4.350	0	13.336	0	1.165	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	54.58	1.615	0.085		
Oct	4.122	0	12.242	0	1.497	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	72.81	1.710	0.090		
Nov	3.116	0	8.747	0	1.640	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	180.53	1.995	0.105		
Dec	3.392	0	10.234	0	1.072	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	63.99	2.090	0.110		
Total	48.462	0	129.373	7.640	24.529	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	1003.70	16.260	0.540		

Note:

^{*} Very small quantity of aluminum can, cardboard package and plastic bottle generated from site office were collected by the local resident.

⁽¹⁾ Broken concrete for recycling into aggregates

⁽²⁾ Plastics refer to plastic bottles/containers, plastic sheets/foam from package material.

⁽³⁾ Site clearance waste refers to vegetation and construction debris.

⁽⁴⁾ Please note that the total quality generated is not equivalent to the summation of the items in column (b) to (e) as part of the quality of the reused material (column c) had been counted already.

Contract No. HY/2003/19 - Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha

Name of Department: Highways Department Project Commencement Date: June 2004

Construction Completion Date: December 2009

Approved Project Cost: \$688.5 Million

Monthly Summary Waste Flow Table for Year 2008

Year	Ac	tual Quantities	s of inert C&D	Materials (in 10	³ m ³)		Actual Quantities of C&D Wastes (in 10 ³ Kg)											
	Total Quantity Generated	Broken Concrete ⁽¹	Reused in the Contract	Reused in other Projects	Disposed as Public Fill	М	Metals Disposal Recycle		Paper/cardboard packaging		Plastic ⁽²⁾		Site clearance waste ⁽³⁾	Others, e.g. g (in 10				
	(a)	(b)	(c)	(d)	(e)	Disposal			Recycle	Disposal Recycle		Disposal	Disposal	Disposal	Timber Waste			
Jan	1.230	0	1.128	0	0.102	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	73.61	1.235	0.065			
Feb	1.875	0	0.762	0	1.113	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	34.21	1.425	0.075			
Mar	1.064	0	0.858	0	0.206	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	56.82	1.520	0.080			
Apr	0.994	0	0.765	0	0.229	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	84.54	1.900	0.100			
May	1.335	0	1.020	0	0.315	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	78.21	1.752	0.095			
Jun	0.755	0	0.467	0	0.288	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	86.76	1.895	0.124			
Sub-Total	7.253	0	4.997	0	2.253	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	414.15	9.727	0.539			
July	0.953	0	0.685	0	0.268	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	96.88	2.036	0.098			
Aug	2.875	0	5.978	0	0.758	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	89.33	2.189	0.127			
Sept	1.954	0	1.628	0	0.985	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	85.66	2.078	0.213			
Oct	2.543	0	1.829	0	1.075	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	95.67	2.457	0.478			
Nov	3.158	0	1.954	0	1.652	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	128.21	2.738	0.389			
Dec	2.878	0	1.862	0	1.877	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	120.54	2.548	0.326			
Total	21.609	0	18.925	0	8.854	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	1030.44	23.773	2.163			

Note:

^{*} Very small quantity of aluminum can, cardboard package and plastic bottle generated from site office were collected by the local resident.

⁽¹⁾ Broken concrete for recycling into aggregates

⁽²⁾ Plastics refer to plastic bottles/containers, plastic sheets/foam from package material.

⁽³⁾ Site clearance waste refers to vegetation and construction debris.

⁽⁴⁾ Please note that the total quality generated is not equivalent to the summation of the items in column (b) to (e) as part of the quality of the reused material (column c) had been counted already.

Contract No. HY/2003/19 - Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha

Name of Department: Highways Department Project Commencement Date: June 2004

Construction Completion Date: December 2009

Approved Project Cost: \$688.5 Million

Monthly Summary Waste Flow Table for Year 2009

Year	Ac	tual Quantities	s of inert C&D	Materials (in 10	³ m ³)	Actual Quantities of C&D Wastes (in 10 ³ Kg)											
	Total Quantity Generated	Broken Concrete ⁽¹	Reused in the Contract	Reused in other Projects	Disposed as Public Fill	М	Metals Disposal Recycle		Paper/cardboard packaging		Plastic ⁽²⁾		Site clearance waste ⁽³⁾	Others, e.g. g (in 10			
	(a)	(b)	(c)	(d)	(e)	Disposal			Recycle	Disposal Recycle		Disposal	Disposal	Disposal	Timber Waste		
Jan	2.130	0	2.130	0	0	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	0	0	0		
Feb	3.158	0	1.954	0	1.652	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	128.21	2.738	0.389		
Mar	3.408	0	1.267	0	2.564	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	96.57	2.546	0.234		
Apr	7.562	0	1.874	0	3.638	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	135.66	4.388	0.504		
May	1.743	0	1.743	0	0	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	0	0	0		
Jun	1.054		1.257	0	0.355	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	38.66	0.865	0.128		
Sub-Total	19.055	0	10.225	0	8.209	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	399.1	10.537	1.255		
July																	
Aug																	
Sept																	
Oct																	
Nov																	
Dec																	
Total	19.055	0	10.225	0	8.209	N/A*	N/A*	N/A*	N/A*	N/A*	N/A*	0	399.1	10.537	1.255		

Note:

^{*} Very small quantity of aluminum can, cardboard package and plastic bottle generated from site office were collected by the local resident.

⁽¹⁾ Broken concrete for recycling into aggregates

⁽²⁾ Plastics refer to plastic bottles/containers, plastic sheets/foam from package material.

⁽³⁾ Site clearance waste refers to vegetation and construction debris.

⁽⁴⁾ Please note that the total quality generated is not equivalent to the summation of the items in column (b) to (e) as part of the quality of the reused material (column c) had been counted already.