## Dragages-Nishimatsu Joint Venture

# Contract No. DC/2007/10 Design and Construction of Hong Kong West Drainage Tunnel

Quarterly EM&A Report

April to June 2011 (version 2.0)

Certified By

(Environmental Team Leader)

REMARKS:

The information supplied and contained within this report is, to the best of our knowledge, correct at the time of printing.

CINOTECH accepts no responsibility for changes made to this report by third parties

#### CINOTECH CONSULTANTS LTD

Room 1710, Technology Park,
18 On Lai Street,
Shatin, NT, Hong Kong
Tel: (852) 2151 2083 Fax: (852) 3107 1388

Email: info@cinotech.com.hk

## TABLE OF CONTENTS

		Page
E	XECUTIVE SUMMARY	1
	KEY ISSUES FOR THE COMING MONTH	9
1.	INTRODUCTION	11
2.	PROJECT CHARACTERISTICS	12
	PROJECT ORGANIZATION AND CONTACTS OF KEY MANAGEMENT	
3.	ENVIRONMENTAL MONITORING AND AUDIT REQUIREMENTS	14
	MONITORING PARAMETERS AND MONITORING LOCATIONS	14 14
4.	MONITORING RESULTS	15
	WEATHER CONDITIONS	15 15 16
5.	ENVIRONMENTAL AUDIT	19
	IMPLEMENTATION STATUS OF ENVIRONMENTAL MITIGATION MEASURES SITE AUDIT SUMMARY EFFECTIVENESS OF MITIGATION MEASURES STATUS OF ENVIRONMENTAL LICENSING AND PERMITTING STATUS OF WASTE MANAGEMENT	
6. P	NON-COMPLIANCE (EXCEEDANCES) OF THE ENVIRONMENTAL QUALITY ERFORMANCE LIMITS (ACTION AND LIMIT LEVELS)	23
	SUMMARY OF EXCEEDANCES	
	CONSTRUCTION IMPACTS ON SUSPENDED SOLIDS	
	REVIEW OF THE REASONS FOR AND THE IMPLICATIONS OF NON-COMPLIANCE	
7.	ENVIRONMENTAL COMPLAINTS AND PROSECUTIONS	24
8.	COMMENTS, CONCLUSIONS AND RECOMMENDATIONS	25

## LIST OF TABLE

Table I	Summary Table for Non-compliance Recorded in the Reporting Quarter
Table II	Summary Table for Key Information in the Reporting Quarter
Table 2.1	Key Project Contacts
Table 4.1	Ground Water Level Monitoring Data in Reporting Quarter

## LIST OF FIGURES

Figure 1	Layout Plan of the Project
Figure 2	Organization Chart
Figure 3.1a	Locations of Air Quality and Construction Noise Monitoring Stations at
-	Eastern Portal
Figure 3.1b	Locations of Air Quality and Construction Noise Monitoring Stations at
C	Western Portal
Figure 3.1c	Locations of Construction Noise Monitoring Stations at Intake E7
Figure 3.1d	Locations of Construction Noise Monitoring Stations at Intake PFLR1
Figure 3.1e	Locations of Construction Noise Monitoring Stations at Intake W0
Figure 3.1f	Locations of Construction Noise Monitoring Stations at Intake RR1
Figure 3.1g	Locations of Construction Noise Monitoring Stations at Intake W5
Figure 3.1h	Locations of Construction Noise Monitoring Stations at Intake E5A
Figure 3.1i	Locations of Construction Noise Monitoring Stations at Intake THR2
Figure 3.1j	Locations of Construction Noise Monitoring Stations at Intake P5
Figure 3.1k	Locations of Construction Noise Monitoring Stations at Intake W8
Figure 3.11	Locations of Construction Noise Monitoring Stations at Intake DG1
Figure 3.1m	Locations of Construction Noise Monitoring Stations at Intake MA14
Figure 3.1n	Locations of Construction Noise Monitoring Stations at Intake BR6
Figure 3.1o	Location of Construction Ground Borne Noise Monitoring Station
Figure 4.1a-b	Locations of Water Quality Monitoring Stations
Figure 4.2a-e	Location of Ground Water Level Monitoring Stations

## LIST OF APPENDICES

A	Construction Programme
В	Monitoring Requirements
C	Action and Limit Levels for Air Quality, Noise and Water Quality
D	Graphical Presentation of Air Quality Monitoring Results
E	Graphical Presentation of Noise Monitoring Results
F	Environmental Mitigation Implementation Schedule (EMIS)
G	Site Audit Summary
Н	Summary Status of Environmental Licences and Permits
I	Waste Generated Quantity
J	Summary of Exceedances
K	Complaint Log

#### **EXECUTIVE SUMMARY**

#### Introduction

- 1. This is the 13<sup>th</sup> Quarterly Environmental Monitoring and Audit (EM&A) Report prepared by Cinotech Consultants Limited for the "Drainage Improvement in Northern Hong Kong Island Hong Kong West Drainage Tunnel" (the Project). This summary report presents EM&A works performed in the period between April and June 2011.
- 2. The construction activities undertaken in the reporting quarter were:
  - Adit excavation and outfall excavation at Western Portal, Adit excavation and River Channel construction at Eastern Portal;
  - West TBM dismantling;
  - Dropshaft pilot hole and reaming at intake DG1, HR1, W10, E5A, M3, MA15 and HKU1;
  - Dropshaft reaming completed at Intake HR1, E5A, E5B, DG1, HKU1 and MA15;
  - Cofferdam construction at Intakes W8, CR1 and P5;
  - P5 dropshaft remedial measure works;
  - Dropshaft Mechanical excavation at BR6, W5 and E7;
  - Excavation of intake structure at Intakes E7, W3, BR6, HR1, W1, W5, E5A, BR4, B2, MA14, DG1, MA15, RR1 and MA17;
  - Permanent Intake structure works at MBD2, THR2, W10, TP5, BR4, BR5, PFLR1,GL1, MB16, TP789 and E5B;
  - Dropshaft Lining Works at MBD2, TP4, TP5 and THR2;
  - Resumption of works at Intake W0;
  - Permanent Adit Lining works at W0, MB16, MBD2, TP4 and THR2;
  - Still Chamber lining works at TP4, TP5, TP789, THR2, HKU1 and E5B;
  - DDA submissions for Adit/Main Tunnel Intersection, Adits, Stilling Chambers and Turning Bays;
  - DDA submissions for temporary works, slope works and permanent works for Intake Structures;
  - DDA submissions for temporary and permanent works for Dropshafts;
  - Environmental impact monitoring;
  - Casting of dropshaft precast rings;
  - Reinstatement works at Intake SM1; and
  - Temporary Leaky cable to start installation.

#### **Environmental Monitoring Works**

3. Environmental monitoring for the Project was performed regularly as stipulated in the Updated EM&A Manual and the results were checked and reviewed. Site audits were conducted once per week. The implementation of the environmental mitigation measures, Event Action Plans and environmental complaint handling procedures were also checked.

- 4. Proposal for Temporary Suspension of Water Quality Monitoring Western Portal was submitted on 15<sup>th</sup> September 2009 and approved by EPD on 30<sup>th</sup> October 2009. Marine water quality monitoring was temporary suspended starting from 31<sup>st</sup> October 2009 until there is marine-based construction activities resumed at the Western Portal. There is no marine-based construction activity to be conducted in reporting quarter.
- 5. In order to assess the effectiveness of the implementation of water quality mitigation measures at Western Portal, site inspections/audits were conducted at least twice per week at Western Portal starting from November 2009.
- 6. Summary of the non-compliance of the reporting month is tabulated in Table I.

Table I Summary Table for Non-compliance Recorded in the Reporting Quarter

D	Number of Exceedances due to the Project			Results of
Parameter	Action Level	Limit Level	Taken	<b>Action Taken</b>
Eastern Portal				
April 2011				
1-hr TSP	0	0	N.A.	N.A.
24-hr TSP	0	0	N.A.	N.A.
Noise	0	0	N.A.	N.A.
May 2011				
1-hr TSP	0	0	N.A.	N.A.
24-hr TSP	0	0	N.A.	N.A.
Noise	0	0	N.A.	N.A.
June 2011				
1-hr TSP	0	0	N.A.	N.A.
24-hr TSP	0	0	N.A.	N.A.
Noise	0	0	N.A.	N.A.
Western Portal				
April 2011				
1-hr TSP	0	0	N.A.	N.A.
24-hr TSP	0	0	N.A.	N.A.
Noise	0	0	N.A.	N.A.
May 2011			•	
1-hr TSP	0	0	N.A.	N.A.
24-hr TSP	0	0	N.A.	N.A.
Noise	0	0	N.A.	N.A.
June 2011				
1-hr TSP	0	0	N.A.	N.A.
24-hr TSP	0	0	N.A.	N.A.
Noise	0	0	N.A.	N.A.
Intake E5A				
April 2011				
Noise	0	0	N.A.	N.A.
May 2011			•	
Noise	0	0	N.A.	N.A.
June 2011				
Noise	0	0	N.A.	N.A.
Intake E7				
April 2011				
Noise	0	0	N.A.	N.A.
May 2011				
Noise	0	0	N.A.	N.A.
June 2011				
Noise	0	0	N.A.	N.A.
Intake MA14				
April 2011				
Noise	0	0	N.A.	N.A.
May 2011		•		
Noise	0	0	N.A.	N.A.
June 2011		•	•	•
Noise	0	0	N.A.	N.A.

Intake PFLR1				
April 2011				
Noise	0	0	N.A.	N.A.
May 2011		1	1	
Noise	0	0	N.A.	N.A.
June 2011				
Noise	0	0	N.A.	N.A.
Intake THR2				
April 2011				
Noise	0	0	N.A.	N.A.
May 2011				
Noise	0	0	N.A.	N.A.
June 2011			<u> </u>	
Noise	0	0	N.A.	N.A.
Intake W0				
April 2011				
Noise	0	0	N.A.	N.A.
May 2011		•	·	
Noise	0	0	N.A.	N.A.
June 2011		•		
Noise	0	0	N.A.	N.A.
Intake RR1				
April 2011				
Noise	0	0	N.A.	N.A.
May 2011				
Noise	0	0	N.A.	N.A.
June 2011				
Noise	0	0	N.A.	N.A.
Intake W5				
April 2011				
Noise	0	0	N.A.	N.A.
May 2011				
Noise	0	0	N.A.	N.A.
June 2011				
Noise	0	0	N.A.	N.A.
Intake P5				
April 2011				
Noise	0	0	N.A.	N.A.
May 2011				
Noise	0	0	N.A.	N.A.
June 2011				
Noise	1	0	N.A.	N.A.

Intake W8				
April 2011				
Noise	0	0	N.A.	N.A.
May 2011				
Noise	0	0	N.A.	N.A.
June 2011		T-		
Noise	0	0	N.A.	N.A.
Intake BR6				
April 2011				
Noise	0	0	N.A.	N.A.
May 2011				
Noise	0	0	N.A.	N.A.
June 2011		1		
Noise	0	0	N.A.	N.A.
Intake TP5&TP78	39			
April 2011				
Noise	0	0	N.A.	N.A.
May 2011		_		
Noise	0	0	N.A.	N.A.
June 2011		1		
Noise	0	0	N.A.	N.A.
Intake GL1				
April 2011				
Noise	0	0	N.A.	N.A.
May 2011				
Noise	1	0	N.A.	N.A.
June 2011				
Noise	0	0	N.A.	N.A.
Intake B2				
April 2011		_		
Noise	0	0	N.A.	N.A.
May 2011		T		
Noise	0	0	N.A.	N.A.
June 2011				<b></b>
Noise	0	0	N.A.	N.A.
Intake CR1				
April 2011		T -	<u> </u>	
Noise	0	0	N.A.	N.A.
May 2011			<u> </u>	
Noise	1	0	N.A.	N.A.
June 2011				
Noise	0	0	N.A.	N.A.

#### Air Quality

#### 1-hour TSP Monitoring

7. 1-hour TSP monitoring at 2 monitoring stations, AQ1 and AQ2, was conducted as scheduled in the reporting period. No Action/Limit Level exceedance was recorded for 1-hr TSP monitoring in the reporting quarter.

#### 24-hour TSP Monitoring

8. 24-hr TSP monitoring at 2 monitoring station, AQ1 and AQ3, was conducted as schedule in the reporting period. No Action/Limit Level exceedance was recorded for 24-hr TSP monitoring in the reporting quarter.

#### Construction Airborne Noise

9. Noise monitoring at 19 monitoring stations, at NC1, NC2, NC3, NC4, NC5, NC6, NC7, NC8, NC9, NC10, NC11, NC12, NC13, NC14, NC15, NC16, NC17, NC18 and NC19 were conducted as schedule in the reporting period.

#### Eastern Portal

10. No Action/Limit Level exceedance was recorded during the reporting period.

#### Western Portal

11. No Action/Limit Level exceedance was recorded during the reporting period.

#### Intake DG1

12. No Action/Limit Level exceedance was recorded during the reporting period.

#### Intake F5A

13. No Action/Limit Level exceedance was recorded during the reporting period.

#### Intake E7

14. No Action/Limit Level exceedance was recorded during the reporting period.

#### Intake MA14

15. No Action/Limit Level exceedance was recorded during the reporting period.

#### Intake PFLR1

16. No Action/Limit Level exceedance was recorded during the reporting period.

#### Intake THR2

17. No Action/Limit Level exceedance was recorded during the reporting period.

#### Intake RR1

18. No Action/Limit Level exceedance was recorded during the reporting period.

#### Intake W0

19. No Action/Limit Level exceedance was recorded during the reporting period.

#### Intake W5

20. No Action/Limit Level exceedance was recorded during the reporting period.

#### Intake P5

21. One Action Level exceedance was recorded due to the complaints received on 2<sup>nd</sup> June 2011 during the reporting period.

#### Intake W8

22. No Action/Limit Level exceedance was recorded during the reporting period.

#### Intake BR6

23. No Action/Limit Level exceedance was recorded during the reporting period.

#### Intake TP5&TP789

24. No Action/Limit Level exceedance was recorded during the reporting period.

#### Intake GL1

25. One Action Level exceedance was recorded due to the complaints received on 30<sup>th</sup> May 2011 during the reporting period.

#### Intake B2

26. No Action/Limit Level exceedance was recorded during the reporting period.

#### Intake CR1

27. One Action Level exceedance was recorded due to the complaints received on 30<sup>th</sup> May 2011 during the reporting period.

#### Construction Ground Borne Noise

- 28. Construction Ground Borne Noise Monitoring at GNC3 was temporary suspended since 7<sup>th</sup> May 2009 as the ISS EastPoint Property Management Ltd. received an instruction from the Incorporated Owners of Aegean Terrace that we are not permitted to conduct any noise monitoring inside Aegean Terrace for the Project.
- 29. According to the approved EIA report, noise monitoring should be performed at NSR1a (i.e. Crane Court) when TBM is operating through the tunnel section between points A and B). Therefore, Ground borne noise monitoring has been conducted at Crane Court (GNC4) since 3<sup>rd</sup> June 2009 during the TBM operated.
- 30. Ground borne noise monitoring at GNC1 True Light Middle School, GNC2 The Legend and GNC4 Crane Court were completed by end of August 2009 accordingly.
- 31. Ground borne noise monitoring at GNC5 was completed by end of November 2009.
- 32. Ground borne noise monitoring was conducted at GNC6 French International School in the reporting month during the TBM operation and completed by end of June 2010.

33. Ground borne noise monitoring was conducted at GNC7 – Hong Villa was conducted as scheduled in the reporting period. No exceedance was recorded.

Water Quality

34. Proposal for Temporary Suspension of Water Quality Monitoring Western Portal was submitted on 15<sup>th</sup> September 2009 and approved by EPD on 30<sup>th</sup> October 2009. Marine water quality monitoring was temporary suspended starting from 31<sup>st</sup> October 2009 until there is marine-based construction activities resumed at the Western Portal. There is no marine-based construction activity to be conducted in reporting quarter.

#### **Environmental Licensing and Permitting**

- 35. Licenses/Permits granted to the Project include the Environmental Permit (EP) for the Project, An Environmental Permit No. EP-272/2007 was issued on 26 April 2007 and Environmental Permit No. EP-272/2007/A was issue on 26 October 2007. Later, the further Environmental Permit (FEP-01/272/2007/A) and (FEP-01/272/2007/B) was issued on 28 January 2008 and 25 June 2009 to Dragages-Nishimatsu Joint Venture.
- 36. Registration of Chemical Waste Producer (License: 5213-148-D2393-02 for Eastern Portal and No. 5213-172-D2393-01 for Western Portal).
- Water Discharge License (License No.: EP860/W10/XY0175 for Area of Mount Butler Office, EP860/W10/XY0177 for Eastern Portal, EP820/W9/XT086 and WT00005864-2010 for Western Portal, EP860/W10/XY0183 for Intake W0, WT00003372-2009 for Intake SM1, WT00003737-2009 for Intake MB16, WT00004126-2009 for Intake HKU1, WT00003738-2009 for THR2, WT00004270-2009 for PFLR1, WT00004806-2009 for Intake E7, WT00004808-2009 for MBD2, WT00004885-2009 for Intake RR1, WT00005135-2009 for Intake W10, WT00005357-2009 for Intake W5, WT00005374-2009 for Intake P5, WT00005376-2009 for Intake TP4, WT00005588-2009 for Intake TP5, WT00005643-2009 for Intake E5A, WT00005754-2010 for Intake W8, WT00005954 for Intake TP789, WT00005915 for Intake E5B, WT00006102-2010 for Intake M3, WT00006415-2010 for Intake MA15, WT00006420-2010 for Intake MA17, WT00006428-2010 for Intake BR6, WT00006609-2010 for Intake HR1, WT00006559-2010 for Intake CR1, WT00006929-2010 for Intake W1, WT00006418-2010 for Intake MA14, WT00006865-2010 for Intake BR5, WT00007039-2010 for Intake DG1 WT00007042-2010 for Intake W3, WT00007043-2010 for Intake GL1, WT00007130-2010 for Intake BR4, WT00007139-2010 for Intake BR6 - SNH17 and WT00007319-2010 for Intake B2).
- 38. Construction Noise Permit (License No.: GW-RS0125-11 for Eastern Portal, GW-RS0066-11, GW-RS0295-11, GW-RS0380-11 and GW-RS0483-11 for Western Portal, GW-RS0244-11 for Eastern Adits, GW-RS0149-11 and GW-RS0540-11 for Intake W0, GW-RS0167-11 for Intake PFLR1, GW-RS0995-10 and GW-RS0456-11 for Intake W3, GW-RS1071-10 and GW-RS0514-11 for Intake MA17, GW-RS0341-11 for Intake SMH17, GW-RS0441-11 for Intake BR4, GW-RS0443-11 for Intake W1, GW-RS0374-11 and GW-RS0566-11 for adits and tunnel section in Central-Western District.

#### Key Information in the Reporting Quarter

39. Summary of key information in the reporting quarter is tabulated in Table II.

Table II Summary Table for Key Information in the Reporting Quarter

Event Details		Action Taken	Status	Remark	
Event	Number	Nature			
Complaint received (April 2011)	0	-	-	-	
Complaint received (May 2011)	1	Construction noise at Intake CR1	Investigation	Classif	
	1	Construction noise at Intake GL1	Report submitted	Closed	
Complaint received (June 2011)	1	Construction noise at Intake P5	Investigation Report submitted	Closed	
Changes to the assumptions and key construction / operation activities recorded	0		N.A.	N.A.	
Notifications of any summons & prosecutions received	0		N.A.	N.A.	

#### Complaints and Prosecutions

- 40. 3 environmental complaints were received and investigated during the reporting quarter.
- 41. No warning, summon and notification of successful prosecution was received in the reporting period.

#### Future Key Issues

#### **Key Issues for the Coming Month**

- 42. Key environmental issues at Eastern and Western Portals, Intake MA16, MBD2, E5A, E5B, E7, PFLR1, RR1, THR2, SM1, W0, W5, P5, M3, TP4, TP5, TP789, HKU1, W10, W3, W8, MA15, MA17, GL1, HR1, W1, DG1, CR1, BR4, BR5, GL1, MA14 and BR6 in the coming month include:
  - Noise from operation of the equipment, especially for rock-breaking activities, piling

works and machinery on-site;

- Dust generation from stockpiles of dusty materials, excavation works and rock breaking activities;
- Runoff from exposed slope;
- Wastewater and runoff discharge from site;
- Regular removal of silt, mud and sand along u-channels and sedimentation tanks;
- Review and implementation of temporary drainage system for the surface runoff;
- Proper storage of construction materials on site;
- Storage of chemicals/fuel and chemical waste/waste oil on site;
- Watering for rock breaking activity, soil nailing and on haul road;
- Accumulation of general and construction waste on site.

#### 1. INTRODUCTION

- 1.1 The Project "Drainage Improvement in Northern Hong Kong Island Hong Kong West Drainage Tunnel" involves the construction of a drainage tunnel deep into the ground in Mid-levels of the Northern Hong Kong Island from Tai Hang to Pokfulam to intercept and convey the stormwater from the upper catchment directly to the sea near Cyberport. The Drainage tunnel alignment starts from the Eastern Portal near Haw Par Mansion in Tai Hang and ends at the Western Portal located to the north of Cyberport running underneath the Pok Fu Lam, Tai Tam, Aberdeen and Lung Fu Shan Country Parks. The underground main drainage tunnel is 6.25m-7.25m in diameter and about 11km long. Two portals and a series of connecting adits and drop shafts are also been constructed. The layout plan of the Project is shown in **Figure 1**.
- 1.2 The Environmental Impact Assessment (EIA) Report for the Project was approved on 7 April 2006 under the Environmental Impact Assessment Ordinance (EIAO). An Environmental Permit (EP-272/2007) for the works was also granted on 26 April 2007. A varied Environmental Permit (EP) (EP-272/2007/A) was issued in 26 October 2007. Later, the further Environmental Permit (FEP-01/272/2007/A) and (FEP-01/272/2007/B) was issued on 28 January 2008 and 25 June 2009 to Dragages-Nishimatsu Joint Venture. Environmental Monitoring and Audit (EM&A) Manual for the Project was also included as part of the EIA reports in the register. An updated EM&A Manual has been issued on 7 May 2008.
- 1.3 Drainage Services Department awarded the construction of the Project to Dragages-Nishimatsu Joint Venture (hereinafter called "the Contractor"). The construction works commenced on 30 November 2007 and are scheduled to be completed by 2012.
- 1.4 Cinotech Consultants Limited (Cinotech) was commissioned by the Contractor to undertake the Environmental Team (ET) Services for the Project. All environmental and audit works were conducted by Cinotech and the laboratory testing works were conducted by a HOKLAS laboratory, Wellab Limited. This is the 13<sup>th</sup> quarterly EM&A report summarizing the EM&A works for the Project in the period between April and June 2011.

#### 2. PROJECT CHARACTERISTICS

#### **Project Organization and Contacts of Key Management**

- 2.1 Different parties with different levels of involvement in the project organization include:
  - Project Proponent Drainage Services Department (DSD).
  - The Supervising Officer or Supervising Officer's Representative (SO or SOR) Ove Arup & Partners (ARUP).
  - Environmental Team (ET) Cinotech Consultants Limited (CCL).
  - Independent Environmental Checker (IEC) Allied Environmental Consultants Limited (AEC).
  - Contractor Dragages-Nishimatsu Joint Venture (DNJV).
- 2.2 The responsibilities of respective parties are detailed in Sections 1.14 to 1.28 of the Updated EM&A Manual of the Project. The project organization chart is presented in **Figure 2**.
- 2.3 The key contacts of the Project are shown in Table 2.1.

**Table 2.1** Key Project Contacts

Party	Role	Name	Position	Phone No.	Fax No.
DNJV	Permit Holder	Mr. ALTIER Daniel	Project Manager	2671 7333	2671 0200
Divi v Perinit Holder		Mr. UETAKE H.	Deputy Project Manager	2071 7333	2671 9300
	Supervising Mr. Jackson Wong		CRE	6117 6639	
ARUP	Officer	Ms. Angela Yan	RE	3961 5206	2436 1012
		Dr. Priscilla Choy	ET Leader	2151 2089	
Cinotech Environmental Team		Ms. Ivy Tam	Project Coordinator and Audit Team Leader	2151 2090	3107 1388
		Mr. Henry Leung	Monitoring Team Leader	2151 2087	
AEC	Independent Environmental Checker	Ms. Grace Kwok	Independent Environmental Checker	2815 7028	2815 5399
DNJV	Contractor	Mr. Chu Chung Sing	Environmental Officer	3476 0753	2671 9300

## Construction Programme and Synopsis of Work

2.4 The construction programme is presented in **Appendix A**.

## Quarterly EM&A Report – April to June 2011

#### 3. ENVIRONMENTAL MONITORING AND AUDIT REQUIREMENTS

#### **Monitoring Parameters and Monitoring Locations**

3.1 The EM&A Manual designates locations for the ET to monitor environmental impacts in terms of air quality, noise and water quality due to the Project. When alternative monitoring locations are proposed, the criteria listed in Section 2.4.3 of the updated EM&A Manual shall be followed and the updated monitoring locations shall be approved by ER and agreed with IEC. The Project area and monitoring locations are depicted in **Figures 3a-o and 4a-e**. **Appendix B** gives details of monitoring requirements.

#### **Monitoring Methodology and Calibration Details**

3.2 Monitoring works/equipments were conducted/calibrated regularly in accordance with the EM&A Manual. Copies of calibration certificates are attached in the appendices of the Monthly Reports.

#### **Environmental Quality Performance Limits (Action and Limit Levels)**

3.3 The environmental quality performance limits, i.e. Action and Limit Levels were derived from the baseline monitoring results. Should the measured environmental quality parameters exceed the Action/Limit Levels, the respective action plans would be implemented. The Action/Limit Levels for each environmental parameter are given in **Appendix C**.

#### **Environmental Mitigation Measures**

3.4 Relevant mitigation measures as recommended in the project EIA report have been stipulated in the EM&A Manual for the Contractor to implement. A list of mitigation measures is given in **Appendix F**.

#### 4. MONITORING RESULTS

#### **Weather Conditions**

4.1 The weather during monitoring sessions was mainly sunny and cloudy. The weather conditions for each individual monitoring session were presented in the field record sheets.

#### **Air Quality**

1-hour TSP Monitoring

4.2 1-hour TSP monitoring at 2 monitoring stations, AQ1 and AQ2, was conducted as schedule in the reporting period. No Action/Limit Level exceedance was recorded for 1-hr TSP monitoring in the reporting quarter.

24-hour TSP Monitoring

- 4.3 24-hr TSP monitoring at 2 monitoring station, AQ1 and AQ3 was conducted as schedule in the reporting period. No Action/Limit Level exceedance was recorded for 24-hr TSP monitoring in the reporting quarter.
- 4.4 The graphical presentations of the air quality monitoring results are shown in **Appendix D**.

#### **Construction Airborne Noise**

4.5 Noise monitoring at 19 monitoring stations, NC1, NC2, NC3, NC4, NC5, NC6, NC7, NC8, NC9, NC10, NC11, NC12, NC13, NC14, NC15, NC16, NC17, NC18 and NC19 were conducted as schedule in the reporting period.

Eastern Portal

4.6 No Action/Limit Level exceedance was recorded during the reporting period.

Western Portal

4.7 No Action/Limit Level exceedance was recorded during the reporting period.

Intake DG1

4.8 No Action/Limit Level exceedance was recorded during the reporting period.

Intake E5A

4.9 No Action/Limit Level exceedance was recorded during the reporting period.

Intake E7

4.10 No Action/Limit Level exceedance was recorded during the reporting period.

Intake MA14

4.11 No Action/Limit Level exceedance was recorded during the reporting period.

Intake PFLR1

4.12 No Action/Limit Level exceedance was recorded during the reporting period.

Intake THR2

4.13 No Action/Limit Level exceedance was recorded during the reporting period.

Intake RR1

4.14 No Action/Limit Level exceedance was recorded during the reporting period.

Intake W0

4.15 No Action/Limit Level exceedance was recorded during the reporting period.

Intake W5

4.16 No Action/Limit Level exceedance was recorded during the reporting period.

Intake P5

4.17 One Action Level exceedance was recorded due to the complaints received on 2<sup>nd</sup> June 2011 during the reporting period.

Intake W8

4.18 No Action/Limit Level exceedance was recorded during the reporting period.

Intake BR6

4.19 No Action/Limit Level exceedance was recorded during the reporting period.

Intake TP5&TP789

4.20 No Action/Limit Level exceedance was recorded during the reporting period.

Intake GL1

4.21 One Action Level exceedance was recorded due to the complaints received on 30<sup>th</sup> May 2011 during the reporting period.

Intake B2

4.22 No Action/Limit Level exceedance was recorded during the reporting period.

Intake CR1

4.23 One Action Level exceedance was recorded due to the complaints received on 30<sup>th</sup> May 2011 during the reporting period.

#### **Construction Ground Borne Noise**

- 4.24 Construction Ground Borne Noise Monitoring at GNC3 was temporary suspended since 7<sup>th</sup> May 2009 as the ISS EastPoint Property Management Ltd. received an instruction from the Incorporated Owners of Aegean Terrace that we are not permitted to conduct any noise monitoring inside Aegean Terrace for the Project.
- 4.25 According to the approved EIA report, noise monitoring should be performed at NSR1a (i.e. Crane Court) when TBM is operating through the tunnel section between

- points A and B). Therefore, Ground borne noise monitoring has been conducted at Crane Court (GNC4) since 3<sup>rd</sup> June 2009 during the TBM operated.
- 4.26 Ground borne noise monitoring at GNC1 True Light Middle School, GNC2 The Legend and GNC4 Crane Court were completed by end of August 2009 accordingly.
- 4.27 Ground borne noise monitoring at GNC5 was completed by end of November 2009.
- 4.28 Ground borne noise monitoring was conducted at GNC6 French International School in the reporting month during the TBM operation and completed by end of June 2010.
- 4.29 Ground borne noise monitoring was conducted at GNC7 Hong Villa was conducted as scheduled in the reporting period. No exceedance was recorded.

#### Water Quality

4.30 Proposal for Temporary Suspension of Water Quality Monitoring Western Portal was submitted on 15<sup>th</sup> September 2009 and approved by EPD on 30<sup>th</sup> October 2009. Marine water quality monitoring was temporary suspended starting from 31<sup>st</sup> October 2009 until there is marine-based construction activities resumed at the Western Portal. There is no marine-based construction activity to be conducted in reporting quarter.

#### **Underground water level**

- 4.31 Ground water levels were measured once per month during the construction phase in order to ensure the water levels at those intakes near to the natural stream courses and thus on the surrounding habitats will not be significantly affected.
- 4.32 Locations of designated ground water level (borehole with piezometer) monitoring station UC1 at Eastern Portal has been changed to ADH48 which was verified by IEC on 5<sup>th</sup> June 2008. The updated ground water level monitoring stations, TP789\_DH2, TP5\_DH2, THR2\_DH7 and PFLR1\_DH2 were also verified by IEC on 19<sup>th</sup> June 2010. Monitoring data are shown in Table 4.1.

**Table 4.1 Ground Water Level Monitoring Data in Reporting Quarter** 

Date	Water Level (from ground)/m			
Location: ADH48 (Eastern Portal)				
21 April 2011	9.1			
24 May 2011	8.43			
7 June 2011	7.9			
Location: TP789 DH2				

21 April 2011	Dry		
18 May 2011	Dry		
25 June 2011	15.30		
Location: TP5_DH2			
21 April 2011	3.19		
18 May 2011	3.18		
20 June 2011	3.25		
Location: THR2_DH7			
19 April 2011	3.14		
6 May 2011	3.20		
3 June 2011	3.12		
Location:PFLR1_DH2			
21 April 2011	11.75		
18 May 2011	11.75		
16 June 2011	11.75		

#### 5. ENVIRONMENTAL AUDIT

#### **Implementation Status of Environmental Mitigation Measures**

5.1 The implementation status of environmental mitigation measures (EMIS) is given in **Appendix G**.

#### **Site Audit Summary**

- 5.2 During site inspections in the reporting period, no non-conformance was identified. The observations and recommendations made during the reporting period are summarized in **Appendix G**.
- 5.3 The major deficiencies identified by ET in the reporting quarter are summarized as follow:

Water Quality

- The sedimentation tank was observed full of deposited mud at Intake E5A.
- The green water at the sedimentation tank at Intake HKU1 was observed.
- Sedimentation tank at Intake W10 and E5A was observed full of silty water.
- Sedimentation tank was observed full of silty water and cannot function properly at Intake W5.
- Milky water was observed discharging to the public drain at Intake B2.
- The sedimentation tank at Intake HR1 was observed full of wastewater and grease water.

#### Waste/Chemical Management

- The oil drum was observed to be disposed of above the drainage channel without drip tray at Intake HR1.
- The oil stain was observed to be disposed from excavator because of rain at Intake BR6

5.4 The major deficiencies identified by IEC in the reporting quarter are summarized as follow:

## 28<sup>th</sup> April 2011

#### Follow Up Observations:

• As advised by the Contractor, grease water near discharge outlet of sedimentation tank at BR5 was cleared and chemical containers were removed.

#### Observations:

- Drip tray without plug was observed at W10. The Contractor was requested to provide plug to prevent grease water overflow.
- Stagnant water was observed at I-BEAM at HKU1, the Contractor was requested to clear stagnant water.

#### Reminder:

- The Contractor was reminded to regularly clear rubbish or leaves deposited in uchannel, surface channel to prevent blockage.
- The Contractor was reminded to remove unused C&D materials such as cement bags.

### 26<sup>th</sup> May 2011

#### Follow Up Observations:

- Based on photo provided by the Contractor on 24 May 2011, plug was provided for drip tray at W10.
- Based on photo provided by the Contractor on 24 May 2011, stagnant water observed at I-BEAM at HKU1 was cleared.

#### Observations:

- Oil drums without drip tray were observed at EP near Wetsep. The Contractor was requested to provide rectification measures.
- Drip tray provided for generator was observed without plug at E5A. The Contractor was requested to plug to prevent overflow of grease water.
- Some leaves and construction equipment were observed deposited at u-channel at THR2. The Contractor was requested to clear stuff to prevent channel blockage.
- Some retained trees at THR2 were surrounded by construction materials and equipment. The Contractor was requested to remove the stuff.

## 30<sup>th</sup> June 2011

#### Follow Up Observations:

- Oil drums without drip tray observed at EP near wetsep were removed by the Contractor..
- Drip tray with plug was observed at E5A.
- No leaves and construction equipment were observed at u-channel at THR2.
- C&D material near retained trees at THR2 were removed.

#### Observations:

- Oil stains were observed near BR6 entrance. The Contractor was requested to clear the stains.
- Effluent was observed milky at sedimentation tank at BR6. The Contractor was requested to clear materials/substances deposited in the effluent tank to ensure the discharge quality in compliance with discharge permit requirement.

#### Reminder:

• The Contractor was reminded to keep the sites tidiness.

#### **Effectiveness of Mitigation Measures**

5.5 The mitigation measures recommended in the EIA report and required by the EP are considered effective in minimizing environmental impacts. The Contractor has implemented the recommended mitigation measures except those mitigation measures not applicable at this stage, it is however considered that the Contractor could put greater efforts into proper implementation of these measures, especially for the construction of noise enclosure and use of quiet PME, to ensure their intended effects are fully achieved.

#### **Status of Environmental Licensing and Permitting**

- 5.6 Licenses/Permits granted to the Project include the Environmental Permit (EP) for the Project, An Environmental Permit No. EP-272/2007 was issued on 26 April 2007 and Environmental Permit No. EP-272/2007/A was issue on 26 October 2007. Later, the further Environmental Permit (FEP-01/272/2007/A) and (FEP-01/272/2007/B) was issued on 28 January 2008 and 25 June 2009 to Dragages-Nishimatsu Joint Venture.
- 5.7 Registration of Chemical Waste Producer (License: 5213-148-D2393-02 for Eastern Portal and No. 5213-172-D2393-01 for Western Portal).
- 5.8 Water Discharge License (License No.: EP860/W10/XY0175 for Area of Mount Butler Office, EP860/W10/XY0177 for Eastern Portal, EP820/W9/XT086 and WT00005864-2010 for Western Portal, EP860/W10/XY0183 for Intake W0, WT00003372-2009 for Intake SM1, WT00003737-2009 for Intake MB16, WT00004126-2009 for Intake HKU1, WT00003738-2009 for THR2, WT00004270-2009 for PFLR1, WT00004806-2009 for Intake E7, WT00004808-2009 for MBD2, WT00004885-2009 for Intake RR1, WT00005135-2009 for Intake W10, WT00005357-2009 for Intake W5, WT00005374-2009 for Intake P5, WT00005376-2009 for Intake TP4, WT00005588-2009 for Intake TP5, WT00005643-2009 for Intake E5A, WT00005754-2010 for Intake W8, WT00005954 for Intake TP789, WT00005915 for Intake E5B, WT00006102-2010 for Intake M3, WT00006415-2010 for Intake MA15, WT00006420-2010 for Intake MA17, WT00006428-2010 for Intake BR6, WT00006609-2010 for Intake HR1, WT00006559-2010 for Intake CR1, WT00006929-2010 for Intake W1, WT00006418-2010 for Intake MA14, WT00006865-2010 for Intake BR5, WT00007039-2010 for Intake DG1 WT00007042-2010 for Intake W3, WT00007043-2010 for Intake GL1, WT00007130-2010 for Intake BR4, WT00007139-2010 for Intake BR6 - SNH17 and WT00007319-2010 for Intake B2).

- 5.9 Construction Noise Permit (License No.: GW-RS0125-11 for Eastern Portal, GW-RS0066-11, GW-RS0295-11, GW-RS0380-11 and GW-RS0483-11 for Western Portal, GW-RS0244-11 for Eastern Adits, GW-RS0149-11 and GW-RS0540-11 for Intake W0, GW-RS0167-11 for Intake PFLR1, GW-RS0995-10 and GW-RS0456-11 for Intake W3, GW-RS1071-10 and GW-RS0514-11 for Intake MA17, GW-RS0341-11 for Intake SMH17, GW-RS0441-11 for Intake BR4, GW-RS0443-11 for Intake W1, GW-RS0374-11 and GW-RS0566-11 for adits and tunnel section in Central-Western District.
- 5.10 The status of these licenses and permits obtained for the Project is summarized in **Appendix H**.

#### **Status of Waste Management**

- During this reporting quarter, a total 51 nos. of dump trucks of waste were delivered to SENT, 6 trips of C&D waste were delivered to Tuen Mun Fill Bank. 590 and 18 trips of C&D waste were delivered to Chai Wan Public Barging Point and TKO Fill Bank respectively. Both the trip ticket system and chit accounting system for disposal of waste were operating smoothly to date. 10 trucks overloading case was recorded during this reporting period (all cases were within the 105% allowable buffer weight). No disposal of inert C&D material to public sorting facilities and no dump truck without cover were reported from CEDD. In respect of the dump truck cover, DNJV keeps on take record photos and inspection to ensure that all dump trucks have fully covered the skip before leaving the site.
- 5.12 The rock materials from the Eastern Portal and Western Portal were received by the alternative disposal sites at ZhongShan. Some of the tunnel spoils from Eastern Tunnel and adits were also received by Leighton site at Ocean Park and in a residential development site at No. 1 Gough Hill Road, the Peak which was started from 24<sup>th</sup> September 2010.
- 5.13 The monthly summary of waste flow table for April June 2011 are provided in **Appendix I**.

## 6. NON-COMPLIANCE (EXCEEDANCES) OF THE ENVIRONMENTAL QUALITY PERFORMANCE LIMITS (ACTION AND LIMIT LEVELS)

#### **Summary of Exceedances**

6.1 Environmental monitoring works were performed in the reporting period and all monitoring results were checked and reviewed. A summary of exceedances is attached in **Appendix J**. The details of each exceedance were attached in the Monthly Reports.

Air Quality

6.2 No Action/ Limit Level exceedance was recorded in the reporting quarter.

Construction Airborne Noise

Intake P5

One Action Level exceedance was recorded due to the complaints received on 2<sup>nd</sup> June 2011 during the reporting period.

Intake GL1

One Action Level exceedance was recorded due to the complaints received on 30<sup>th</sup> May 2011 during the reporting period.

Intake CR1

One Action Level exceedance was recorded due to the complaints received on 30<sup>th</sup> May 2011 during the reporting period.

Construction Ground Borne Noise

6.6 No ground borne noise monitoring was conducted in the reporting period.

#### **Construction Impacts on Suspended Solids**

6.7 Water quality monitoring was temporary suspended starting from 31<sup>st</sup> October 2009.

#### Review of the Reasons for and the Implications of Non-compliance

6.8 There was no non-compliance from the site audits in the reporting quarter. The observations and recommendations made in each individual site audit session were attached in the Monthly Reports.

#### 7. ENVIRONMENTAL COMPLAINTS AND PROSECUTIONS

- 7.1 3 environmental complaints, including 2 for May 2011 and 1 for June 2011, were received and investigated during the reporting quarter. The updated Complaint Log is attached in **Appendix K**.
- 7.2 No warning, summon and notification of successful prosecution was received in the reporting period.
- 7.3 There were a total of 89 project related environmental complaints, no warnings, summons and successful prosecutions received since the commencement of the Project.

#### 8. COMMENTS, CONCLUSIONS AND RECOMMENDATIONS

- 8.1 The major construction activities in the coming month include:
  - Adit excavation, outfall excavation at West Portal and Adit excavation & river channel works at East Portals.
  - Permanent Adit lining works at MB16, W0, MBD2, THR2, TP4, TP5, TP789, E7 and HKU1.
  - Stilling chamber lining works at E5B, GL1, DG1, HKU1, MA15, TP789, SM1 and M3.
  - Permanent Intake Structure Construction at Intake DG1, PFLR1, BR5 GL1, HKU1, MB16, MBD2, THR2, HR1 and BR4.
  - Excavation of dropshaft at Intakes M3, W1 & W10, PFLR1 and B2 by Raise Boring method.
  - Excavation of intake structure at Intakes E7, W1, MA17, BR6, RR1, W3, and W8.
  - Excavation of Dropshaft at Intake W5 by HDC on-going.
  - Cofferdam construction at Intakes CR1, P5 and W8.
  - Casting dropshaft precast rings.
  - Permanent dropshaft lining works at TP4, TP5, TP789, E5B and HKU1.
- 8.2 According to the environmental audit performed in the reporting period, the following recommendations were made:

#### Air Quality Impact

- To prohibit any open burning on site.
- To regularly maintain the machinery and vehicles on site.
- To implement dust suppression measures on all haul roads, stockpiles, dry surfaces and excavation works.
- To provide hoarding

#### Noise Impact

- To inspect the noise sources inside the site.
- To space out noisy equipment and position the equipment as far away as possible from sensitive receivers.
- To provide temporary noise barriers for operations of noisy equipment near the noise sensitive receivers in an appropriate location.

#### Water Impact


- To prevent any surface runoff discharge into any stream course.
- To review and implement temporary drainage system.
- To identify any wastewater discharges from site.
- To ensure properly maintenance for de-silting facilities.


- To clear the silt and sediment in the sedimentation tanks.
- To review the capacity of de-silting facilities for discharge.
- To divert all the water generated from construction site to de-silting facilities with enough handling capacity before discharge.
- To avoid accumulation of stagnant and ponding water on site.


#### Waste/Chemical Management


- To check for any accumulation of waste materials or rubbish on site.
- To ensure the performance of sorting of C&D materials at source (during generation);
- To carry out inspection of dump truck at site exit to ensure inert and non-inert C&D materials are properly segregated before removing off site.
- To avoid any discharge or accidental spillage of chemical waste or oil directly from the site.
- To avoid improper handling or storage of oil drum on site.


## **FIGURES**



















































Paint No	Co-ordinates			
FOIRT NO.	Easting	Westing		
CE	830026	814956		
I1	831088	813654		
15	831105	813582		
CF	831778	812420		
Intake A	831603	813044		
Intake B	830606	814583		



Title


Contract No. DC/2007/10


Design and Construction of Hong Kong West Drainage Tunnel


Locations of Water Quality Monitoring Stations


Scale		Project	
	N.T.S	No.	MA8001
Date		Figure	
	Jun-08		4.1

























## APPENDIX A CONSTRUCTION PROGRAMME























Act ID	Activity Description	Orig Dur	Rem Dur	Anticipated Start	Anticipated Finish		Actual Duration	WP6B				2011		
								EF Variance	м	APR	MAY	JUN	JUL	AUG
Intakes - Inte	ernal Structures (Stage 2)												1	•
QHS321633	Penstock Delivery (SM1)	0	0	15JUL11*		0	0	0					<b>•</b>	
QHS321634	Penstock/Finish/PSBW/RI - Intake Stage 2 (SM1)	19	19	25JUL11	15AUG11	0	0	-9					1	
Milestone														
General									1				 	
M381070	38.07-Section32 - SM1 Handover to SO	0	0		15AUG11	0	0	-11	1				] 	<b>♦</b>
Section 32 (F	Portion SM1)								1				 	
M381030	38.03-Lining (Dropshaft)	0	0		03AUG11	0	0	14	1				 	<b>♦</b>
M381050	38.05-Concrete Structure (Intake)	0	0		15AUG11	0	0	-11	1				I I	<b>♦</b>
M381060	38.06-Slopeworks, Backfilling & Reinstatement	0	0		15AUG11	0	0	-11	1 :				] [	<b>♦</b>



itart Date inish Date iata Date tun Date	30NOV07 03AUG12 24MAY11 27MAY11 11:15	Early Ba Last Mor Progress Critical A	r nth Progress 104A s Bar	1
© Primavera	Systems, Inc.			

Design & Construction of HK. West Drainage Tunnel Contract No. DC/2007/10 3 MONTH ROLLING PROGRAMME MAY /2011 MONTHLY REPORT

Sheet 10 of 10

	WORKS PROGRAMME APPROVAL HISTORY					
Date	Revision	Checked	Approved			
13JAN09	Approved Works Programme # 1	SOR	804B			
27MAR09	Approved Works Programme # 2	SOR	9032			
10DEC10	Approved Works Programme # 3	SOR	9116			
01MAR10	Approved Works Programme # 4	SOR	003A			
25MAR11	Approved Works Programme # 5	SOR	301F			

## APPENDIX B MONITORING REQUIREMENTS

 $\label{lem:appendix B - Environmental Impact Monitoring Requirements} \ \ \,$ 

Type of Monitoring	Parameter	Frequency	Location	Measurement Conditions
	1 hour TSP	Three times / 6 days	<ul> <li>AQ1 (True Light         Middle School of         Hong Kong)</li> <li>AQ2 (Outside         Aegean Terrace)</li> </ul>	AQ1 – Canopy AQ2 – Roadside
Air Quality	24 hour TSP	Once / 6 days	<ul> <li>AQ1 (True Light         Middle School of         Hong Kong)</li> <li>AQ3 (Outside Site         Office at Western         Portal)</li> </ul>	AQ3 – Roadside

Type of Monitoring	Parameter	Frequency	Location	Measurement Conditions
Airborne Noise	$L_{eq}$ , $L_{90}$ & $L_{10}$ at 30 minute intervals during (0700 to 1900 on normal weekdays)	Once per week	<ul> <li>NC1 (True Light Middle School of Hong Kong)</li> <li>NC2 (The Legend)</li> <li>NC3 (Outside Aegean Terrace)</li> <li>NC7 (Buddist Li Ka Shing Care &amp; Attention Home for the Elderly)</li> <li>NC8 (Marymount Secondary School)</li> <li>NC9 (117 Blue Pool Road)</li> <li>NC11 (Honey Court)</li> <li>NC12 (Ying Wa Girl's School)</li> <li>NC13 (Peaksville Court)</li> <li>NC14 (Hong Kong Japanese School)</li> <li>NC15 (Hong Kong Academy)</li> <li>NC16 (Raimondi College)</li> <li>NC17 (Hong Kong Institute of Technology)</li> <li>NC18 (Blk A, 80 Robinson Road)</li> <li>NC19 (Villa Veneto)</li> </ul>	<ul> <li>NC1 - Facade measurement</li> <li>NC1a - Façade measurement</li> <li>NC2 - Facade measurement</li> <li>NC3 - Facade measurement</li> <li>NC7 - Facade measurement</li> <li>NC8 - Facade measurement</li> <li>NC9 - Facade measurement</li> <li>NC11 - Free field measurement</li> <li>NC12 - Facade measurement</li> <li>NC12 - Facade measurement</li> <li>NC13 - Facade measurement</li> <li>NC13 - Facade measurement</li> </ul>

Type of Monitoring	Parameter	Frequency	Location	Measurement Conditions
				<ul> <li>MC15 – Free field measurement</li> <li>NC16 - Facade measurement</li> <li>NC17- Facade measurement</li> <li>NC18- Facade measurement</li> <li>NC19 - Facade measurement</li> </ul>

## Remarks:

<sup>(1) —</sup> Conduct noise monitoring only when construction work is carried out.

Type of Monitoring	Parameter	Frequency	Location	Measurement Conditions
Ground Borne Noise	$L_{\rm eq}, L_{\rm 90}$ & $L_{\rm 10}$ at 30 minute intervals during (0700 to 1900 on normal weekdays)	Once per week	GNC7 (Hong Villa)	Ground floor     inside the nearest     building during     the TBM     construction work

## Remarks:

<sup>(1) -</sup> Conduct noise monitoring only when TBM construction work is carried out.

Type of Monitoring	Parameter	Frequency	Location	Measurement Conditions
Water Quality	<ul> <li>Temperature (oC)</li> <li>pH (pH unit)</li> <li>Turbidity (NTU)</li> <li>Water depth (m)</li> <li>Salinity (mg/L)</li> <li>Dissolved oxygen (DO) (mg/L and % of saturation)</li> <li>Suspended solids (SS) (mg/L)</li> </ul>	Three times per week	<ul> <li>CE (830026E, 814956N)</li> <li>CF (831778E, 812420N)</li> <li>I1 (831088E, 813654N)</li> <li>I2 (831105E, 813582N)</li> <li>Intake A (831603E, 813044N)</li> <li>Intake B (830606E, 814583N)</li> </ul>	3 water depths except CF, omit mid-depth sampling.

APPENDIX C ACTION AND LIMIT LEVELS FOR AIR QUALITY, NOISE AND WAER QUALITY

# **Appendix C - Action and Limit Levels**

Table C-1 **Action and Limit Levels for 1-Hour TSP** 

Location	Action Level, μg/m <sup>3</sup>	Limit Level, μg/m <sup>3</sup>
AQ1	345	500
AQ2	321	500

Table C-2 **Action and Limit Levels for 24-Hour TSP** 

Location	Action Level, μg/m <sup>3</sup>	Limit Level, μg/m <sup>3</sup>
AQ1	201	260
AQ3	156	260

Table C-3 **Action and Limit Levels for Construction Noise** 

Time Period	Action Level	Limit Level
0700-1900 hrs on normal weekdays		75* dB(A)
0700-2300 hrs on holidays; and 1900- 2300 hrs on all other days	When one documented complaint is received	60/65/70** dB(A)
2300-0700 hrs of next day	T	45/50/55** dB(A)


<sup>(\*)</sup> reduce to 70 dB(A) for schools and 65 dB(A) c (\*\*) to be selected based on Area Sensitivity Rating. reduce to 70 dB(A) for schools and 65 dB(A) during school examination periods.


**Action and Limit Levels for Water Quality** Table C-4

Parameter		Action	Limit	
DO, mg/L	Surface and Middle	6.3	6.2	
	Bottom	6.0	5.8	
SS, mg/L		or 120% of upstream control station's SS at the same tide of the same day	or 130% of SS readings at the upstream control station at the same tide of same day and specific sensitive receiver water quality requirements	
Turbidity, NTU		or 120% of upstream control station's turbidity at the same tide of the same day	or 130% of turbidity at the upstream control station at the same tide of same day	

APPENDIX D GRAPHICAL PRESENTATION OF AIR QUALITY MONITORING RESULTS

### 1-hr TSP Concentration Levels







Title	Contract No. DC/2007/10	5
	Design and Construction of Hong Kong West Drainage Tunnel	
	Graphical Presentation of 1-hour TSP Monitoring Results	Γ

Scale		Project	
	N.T.S	No.	MA8001
Date		Append	ix
	Jun 11		D




### 24-hr TSP Concentration Levels





Title	Contract No. DC/2007/10 Design and Construction of Hong Kong West Drainage Tunnel	Scale	N.T.S	Project No.	MA8001	CINOTECH
	Graphical Presentation of 24-hour TSP Monitoring Results	Date	Jun 11	Appendi	x D	CINOIECU

## APPENDIX E GRAPHICAL PRESENTATION OF NOISE MONITORING RESULTS




Graphical Presentation of Construction Noise Monitoring


Results


N.T.S No. MA8001

Date Appendix E

CINOTECH







Title Contract No. DC/2007/10
Design and Construction of Hong Kong West Drainage Tunnel
Graphical Presentation of Construction Noise Monitoring
Results


 Scale
 Project No.
 MA8001


 Date
 Jun 11
 Appendix

 E
 E











#### **Noise Levels**





Contract No. DC/2007/10 Design and Construction of Hong Kong West Drainage Tunnel
Graphical Presentation of Construction Noise Monitoring Results

Title





APPENDIX F ENVIRONMENTAL MITIGATION IMPLEMENTATION SCHEDULE (EMIS)

Appendix F - Summary of Environmental Mitigation Implementation Schedule

Types of Impacts	Mitigation Measures	Status
Construction Dust	Pust Mitigation Measures  The Contractor shall undertake at all times to prevent dust nuisance as a result of his activities. Effective dust suppression measures should be installed to minimize air quality impacts, at the boundary of the site and at any sensitive receivers.  No blasting shall be carried out when the strong wind signal or tropical cyclone warning signal No. 3 or higher is hoisted (unless prior permission of the Commissioner of Mines is obtained).  Effective water sprays shall be used during the delivery and handling of all raw sand, aggregate and other similar materials, when dust is likely to be created, to dampen all stored materials during dry and windy weather. Watering of exposed surfaces shall be conducted as often as possible depending on the circumstances.  A watering programme of once every 2 hours in normal weather conditions, and hourly in dry/windy conditions.  Any stockpile of dusty material cannot be immediately transported out of the Site shall be either: a) covered entirely by impervious sheeting; b) placed in an area sheltered on the top and the three sides; or c) sprayed with water or a dust suppression chemical so as to maintain the entire surface wet.  Should a conveyor system be used, the Contractor shall implement the following precautionary measures. Conveyor belts shall be fitted within windboards. Conveyor transfer points and hopper discharge areas shall be enclosed to minimize dust emission. All conveyors under control of the Contractor, and carrying materials which have the potential to create dust, shall be totally enclosed and fitted with belt cleaners.  Any dusty materials being discharged to vehicle from a conveying system at fixed transfer point, three-sided roofed enclosed with a flexible curtain across the entry shall be provided. Exhaust fans shall be provided for this enclosure and vented via a suitable fabric filter system.  The heights from excavated spoils are dropped should be minimise to reduce the fugitive dust arising from unloading/loading.  The Contr	*
	<ul> <li>Chemical wetting agents shall only be used on completed cuts and fills to reduce wind erosion.</li> </ul>	N/A

Remarks: ^ Compliance of mitigation measure; X Non-compliance of mitigation measure;

N/A Not Applicable at this stage;

\* Non-compliance but rectified by the contractor;

Recommendation was made during site audit but improved/rectified by the contractor;

<sup>#</sup> Non-compliance but rectified/improved by the contractor and awaiting IEC's further comment.

Types of Impacts	Mitigation Measures	Status
	No vehicle exhausts shall be directed towards the ground or downwards to minimize dust nuisance.	٨
	• Ventilation system, equipped with proprietary filters, should be provided to ensure the safe working environment inside the tunnel. Particular attention should be paid to the location and direction of the ventilation exhausts. The exhausts should not be allowed to face any sensitive receivers directly. Consideration should also be given to the location of windows, doors and direction of prevailing winds in relation to the nearby sensitive receivers.	^
	• In the event of any spoil or debris from construction works being deposited on adjacent land, or stream, or any silt being washed down to any area, then all such spoil, debris or material and silt shall be immediately removed and the affected land and areas restored to their natural state by the Contractor to the satisfaction of the Engineers.	۸
	In addition, based on the Air Pollution Control (Construction Dust) Regulation, any works involved regulatory and notifiable works, such as stockpiling, loading and unloading of dusty materials, shall take precautions to suppress dust nuisance.	
	• The working area of any excavation or earthmoving operation shall spray with water or a dust suppression chemical immediately before, during and immediately after the operation so as to maintain the entire surface wet;	^
	• Exposed earth shall be properly treated by compaction, turfing, hydroseeding, vegetation planting or sealing with latex, vinyl, bitumen or other suitable surface stabiliser within six months after the last construction activity on the construction site or part of the construction site where the exposed earth lies; and	^
	• Any stockpile of dusty materials (greater than 20m³) shall be either covered entirely by impervious sheeting or placed in an area sheltered on the top and three sides; and sprayed with water or a dust suppression chemical so as to maintain the entire surface wet.	^
	• Other suitable dust control measures as stipulated in Air Pollution Control (Construction Dust). Regulation, where appropriate, should be adopted.	^

N/A Not Applicable at this stage; • Non-compliance but rectified by the contractor;

\* Recommendation was made during site audit but improved/rectified by the contractor;

\* Non-compliance but rectified/improved by the contractor and awaiting IEC's further comment.

Remarks: ^ Compliance of mitigation measure; X Non-compliance of mitigation measure;

N/A Not Applicable at this stage; • Non-compliance but rectified by the contractor;

Recommendation was made during site audit but improved/rectified by the contractor;

Non-compliance but rectified/improved by the contractor and awaiting IEC's further comment.

Types of Impacts	Mitigation Measures	Status
-	can also be reduced by construction of temporary noise barriers which screen the lower floors from viewing the sites. Temporary noise barriers should be installed at active parts of construction areas where construction equipment is being operated in close proximity to NSRs.	
	• It is noted that under the WBTC No. 19/2001, all construction sites are required to use metallic site hoarding can be slightly modified (with the addition of steel backings) into temporary noise barriers. These barriers should be gap free and have a surface mass density of at least 7kg/m <sup>2</sup> .	۸
	<ul> <li>All hand-held percussive breakers and air compressors should comply the Noise Control (Hand-held Percussive Breakers) Regulations respectively under the NCO (Ordinance No. 75/88, NCO Amendment 1992 No.6).</li> </ul>	^
	The Contractor shall devise, arrange methods of working and carry out the works in such manner as to minimise noise impacts on the surrounding environment, and shall provide experienced personnel with suitable training to ensure that these measures are implemented properly.	^
	Level 2 Use of Barriers	
	Level 2 mitigation measures include providing movable barriers for sites which have sufficient space for installation, full enclosures during the drilling activities at Eastern Portal and at muck pit areas for Eastern portals and cantilever-typed high rise noise barrier for intake W5 (P) and W8.	^
	Before construction of the full enclosure at muck pit area, the use of full enclosure noise barrier (Stage A) for the drilling activities at the Eastern Portal area is required. A full enclosure for the muck pit area will then be constructed at this later stage (Stage B). The full enclosure shall be gap free apart from necessary entrance/exits, which shall face towards the entrance of eastern portal to minimize the amount of noise generated from affecting the nearest RNSRs especially school (True Light Middle School of Hong Kong).	۸
	5m high cantilever-typed hoarding barrier to be built at W5 (P) and W8. These enclosures/barriers should have no gaps and have a superficial surface density of at least 10kg/m². Good site practice shall also be adopted by the Contractor to ensure the conditions of the hoardings are properly maintained throughout the construction period. To schedule the noise barrier erection and dismantling to the non sensitive periods of school to avoid adverse impact to W8/3.	٨
	Movable barriers of 3 to 5m height with a small cantilevered upper portion and skid footing to be located within about 5 m or more for mobile equipment such that the line of sight is blocked. To provide purposes-built noise barriers or screens constructed of appropriate materials (minimum superficial density of $10 \text{kg/m}^2$ ) located close to the operating PME.	^
	Pre-drilling following by chemical splitting instead of using large excavator mounted breaker should be used as mitigation measure for rock breaking and rock drilling.	۸

Remarks: ^ Compliance of mitigation measure; X Non-compliance of mitigation measure;

N/A Not Applicable at this stage; • Non-compliance but rectified by the contractor;

\* Recommendation was made during site audit but improved/rectified by the contractor;

\* Non-compliance but rectified/improved by the contractor and awaiting IEC's further comment.

Types of Impacts	Mitigation Measures	Status
	No construction activity is recommended during the examination period.	٨
	Ground borne noise	
	The noise level should be measured on the ground floor inside the nearest building during the TBM construction work in the daytime. If the daytime monitored ground borne noise exceeds the relevant evening/night ground borne noise criteria, evening/night construction work would not be carried out for the concerned tunnel section. Evening/night time construction work is subject to CNP application under the control of NCO.	۸
	Public relationship strategy with 24-hour hotline system.	

N/A Not Applicable at this stage; • Non-compliance but rectified by the contractor;

\* Recommendation was made during site audit but improved/rectified by the contractor;

\* Non-compliance but rectified/improved by the contractor and awaiting IEC's further comment.

Impacts	Mitigation Measures	Status
Water Quality	Precautionary measures for construction work near natural streams  The government provides guidelines (ETWB TCW NO. 5/2005 and DSD TC 2/2004) are providing guidelines to minimize impacts when there is construction work carried out at near natural streams course. Relevant mitigation measures for the intakes are summarised as follows:  • Temporary site access to the work sites should be carefully planned and located to minimize disturbance caused to the substrates of streams/rivers and riparian vegetation by construction plant.  • Locations well away from the rivers/streams for temporary storage of materials (e.g equipment, filling materials, chemicals and fuel) and temporary stockpile of construction debris and spoil should be identified before commencement of works.  • Proposed works site areas inside, or in the proximity of, natural rivers and streams should be temporarily isolated to prevent adverse impacts on the stream water qualities.  • Stockpiling of construction materials, if necessary, should be completely properly covered and located away from any natural stream/river.  • Construction debris and spoil should be covered up and/or properly disposed of as soon as possible to avoid being washed into nearby rivers/streams by rain and local runoff.  Construction of temporary berthing point at the Western Portal  A refuse collection vessel shall be provided to collect refuse or materials lost into the sea.  The respective areas of the marine works will be completely enclosed by the silt curtain. The curtain shall be extended from water surface down to the seabed where it is anchored using sinker blocks. The Contractor shall inspect the silt curtain on regular basis to ensure its integrity and it is serviceable for all times.	^ ^ ^ * N/A

Remarks: ^ Compliance of mitigation measure; X Non-compliance of mitigation measure;

N/A Not Applicable at this stage; • Non-compliance but rectified by the contractor;

\* Recommendation was made during site audit but improved/rectified by the contractor;

\* Non-compliance but rectified/improved by the contractor and awaiting IEC's further comment.

Types of Impacts	Mitigation Measures	Status
	Transfer of armour rock onto the seabed from barge at the temporary pier location should be conducted by careful grabbing and unloading to the seabed (to minimize sediment migration).	٨
	The conveyor belt should be completely covered and muddy effluent from the temporary barge should be contained, treated and disposed. Where there is transfer of excavated wastes, the Contractor should provide appropriate measures to ensure that the waste is free from floatables, putrescibes, organic wastes and toxic materials and when required a refuse collection vessel be provided to collect float refuse.	٨
	Construction of stilling basin at Western Portal outfall	
	All construction for the basin should be carried out inside the temporary cofferdam which is a temporary watertight enclosure built in the water and pumped dry to expose the bottom so that construction of stilling basin can be undertaken.	^
	During the dewatering process, appropriate desilting/sedimentation devices should be provided on site for treatment before discharge. The Contractor should ensure discharge water from the sedimentation tank meet the WPCO/TM requirements before discharge.	^
	The cofferdam will remain on site until after the construction of stilling basin has been completed. The coffer dam shall be regularly inspected and maintained to ensure no spillage of waste or wastewater into the sea. Conveyance of dredged materials from the coffer dam shall be carried out cautiously to avoid spillage into the sea.	۸
	The filled material for the stilling basin should be contained inside the temporary cofferdam. The top level of the cofferdam shall be constructed higher than the final backfilled level.	۸
	The Contractor shall be responsible for the design, installation and maintenance of the silt curtains to minimize the impacts on the water quality and the protection of water quality. The design and specification of the silt curtains shall be submitted by the Contractor to the Engineer for approval.	N/A
	Silt curtains shall be formed from tough, abrasion resistant, permeable membranes, suitable for the purpose, supported on floating booms in such a way as to ensure that the sediment plume shall be restricted to within the limit of the works area. The silt curtain shall be formed and installed in such a way that tidal rise and fall are accommodated, with the silt curtains always extending from the surface to the bottom of the water column and held with anchor blocks. The removal and reinstallation of such curtains during typhoon conditions shall be as agreed with the Director of Marine Department. The contractor shall regularly inspect the silt curtains and check that they are moored and marked to avoid danger to marine traffic. Any damage to the silt curtain shall be repaired by the Contractor promptly and the works shall be stopped until the repair is fixed to the satisfaction of the Engineer.	N/A

Remarks: ^ Compliance of mitigation measure; X Non-compliance of mitigation measure;

N/A Not Applicable at this stage; • Non-compliance but rectified by the contractor;

\* Recommendation was made during site audit but improved/rectified by the contractor;

\* Non-compliance but rectified/improved by the contractor and awaiting IEC's further comment.

Types of Impacts	Mitigation Measures	Status
•	Transfer of rock fill material (armour rock) from the barge onto the site location should be conducted by grabbing and placement on the seabed to minimize sediment migration. No free dropping of the material will be allowed.	٨
	Prior to the construction of armor rock based panel, a silt curtain shall also be installed prior to carry out any marine works as a preventive mitigation measure.	N/A
	Construction of TBM tunnel at both portals and intakes	
	Recycled water will be used at the cutter face for cooling purposes. Used water will be collected and discharged to a settling tank for settlement. Excess water from the settling tank will be transferred to the water treatment plant on site where the addition of flocculants will assist in settlement of solids. The Contractor should ensure discharge water from the sedimentation tank meet the WPCO/TM requirements before discharge.	۸
	During the drilling process, all flushing water will be recycled for use. Discharge of the treated water to nearby drainage system shall be allowed provided that it has been treated to a level meeting with statutory requirements.	^
	Water flow at streams should be maintained by a temporary diversion system during the construction phase of intakes and manhole drop shafts.	^
	General Construction Activities and Workforce	
	A. Surface runoff	
	Effluent produced from construction activities are subjected to WPCO control. Effluent produced from sites should be diverted away from stream courses. Construction works near stream course should be scheduled in the dry season as far as practical to avoid excessive site runoff discharge.	*
	Under the <i>Water Pollution Control Ordinance</i> (WPCO), turbid water from construction sites must be treated to minimize the solids content before being discharged into storm drains. The suspended solids load can be reduced by directing the runoff into temporary sand traps or other silt-removal facilities, and other good and appropriate site management practices. Advice on the handling and disposal of construction site discharge is provided in the ProPECC Paper (PN 1/94) on Construction Site Drainage.	*
	A drainage system layout should be prepared by the Contractor for each of the works areas (portals and intakes), detailing the facilities and measures to manage pollution arising from surface runoff from those works areas. The drainage layout and an associated drainage management plan to reduce surface runoff sediments and pollutants entering watercourses, should be submitted to the Engineer for approval and to EPD for agreement.	*

Remarks: ^ Compliance of mitigation measure; X Non-compliance of mitigation measure;

N/A Not Applicable at this stage; • Non-compliance but rectified by the contractor;

\* Recommendation was made during site audit but improved/rectified by the contractor;

<sup>#</sup> Non-compliance but rectified/improved by the contractor and awaiting IEC's further comment.

Types of Impacts	Mitigation Measures	Status
	The system should be capable of handling stormwater from the site and directing it to sediment removal facilities before discharge. If oil and grease is used on the site or brought to the site, the stormwater should pass through oil interceptors before discharge. The interceptors should have a bypass to prevent washout in heavy storms.	۸
	A temporary channel system or earth bunds or sand barriers should be provided in works areas on site to direct stormwater to silt-removal facilities. Stockpiled materials, if susceptible to erosion of rain or wind, should be covered with tarpaulins (or/similar fabric0 or hydroseedings as far as practicable especially during the wet season.	*
	Silt removal facilities should be checked and the deposited silt and grit should be removed regularly to ensure these facilities are in good working condition and to prevent blockages.	*
	Vehicle washing areas should be drained into a settlement into a settlement basin to settle out the suspended solid before discharge to storm water drains. The water should be recycled on site whenever possible. It is suggested that the wash water from the wheel wash basin is either reused for road watering or pumped to the on-site settling tanks for treatment. Water used for dust depression purposes should be minimized and an alternative soil holding agent should be considered.	۸
	B. Spillage, Oil and Solvents Any contractor generating waste oil or other chemicals as a result of his activities should register as a chemical waste producer and provide a safe storage area for chemicals on site. Oil interceptors need to be regularly inspected and cleaned to avoid wash-out of oil during storm conditions. A bypass should be provided to avoid overload of the interceptor's capacity.	٨
	Any spillage should be cleaned up immediately and the resulting contaminated absorbent material should be properly managed according to Waste Disposal Regulations. Spills should be contained to avoid spreading and contaminating the water resources.	۸
	Oil and fuels should be used and stored properly in designated area. All fuel tanks and storage areas should be provided with locks and be sited on within sealed areas within surrounded by bunds of with a capacity equal to 110% of the storage capacity of the largest tank.	*
	Good housekeeping practices are required to minimize careless spillage and keep the work space in a tidy and clean condition. Appropriate training, including safety codes and relevant manuals, should be given to the personnel who regularly handle the chemicals on site.	*

Remarks: ^ Compliance of mitigation measure; X Non-compliance of mitigation measure;

N/A Not Applicable at this stage; • Non-compliance but rectified by the contractor;

\* Recommendation was made during site audit but improved/rectified by the contractor;

\* Non-compliance but rectified/improved by the contractor and awaiting IEC's further comment.

Types of Impacts	Mitigation Measures	Status
•	C. On-Site Effluent Generation	
	Sewage arising from the additional population of workers on site should be collected in a suitable storage facility (chemical mobile toilets). Most of the work site locations are close to the public sewerage system, and therefore the use of septic tanks isare, therefore, not encouraged. Portable toilets should be used coupled with tickering away services provided by a licensed collector. They should be positioned at appropriate locations across the site to ensure no direct discharge of foul water off-site.	۸
	D. Protection of Existing Flora and Fauna	
	The Contractor should provide details of the plant and operation plans at each site for approval by the Engineer before commencing construction. The plans should include how the existing flora and fauna will be protected. Locations required for groundwater levels monitoring are Eastern Portal, PFLR1(P), THR2(P), TP5, TP789 and W12.	^
	The construction and demolition of the temporary pier may create short term impacts on the local marine water quality. The situation will be restored once the work is finished by proper phasing of the works programme and implementation of the adequate mitigation measures (e.g. silt curtain) the impacts will be minimized.	^
	Maintaining Baseflow in Downstream Watercourses	
	The final design will be developed during the detailed design stage. The exact base flow rates to be maintained at each of the intakes will be subject to detailed site investigation at design stage.	
	<ul> <li>Purpose of the by-pass device is to maintain the base-flow of the affected stream course.</li> <li>The by-pass system comprises an approach link and a trapezoidal channel.</li> <li>The approach link is section with inclined profiled surface at a gradient of 1 in 100. It is used to direct the base flow to the bypass trapezoidal channel at its down stream end during the normal days.</li> <li>The trapezoidal channel is sized such that it could handle the base flow in the affected stream course which is estimated to be no more than 20 l/s.</li> <li>Whenever the flow in the stream course exceeding the base flow rate, the excessive flow will overflow into the intake structure via the bottom rack structure. The bottom rack structure has bar screen on the top and inclined channel at the bottom. The top level of the bar screen is level with the by-pass channel with an aim to receive the overflow from the by-pass channel.</li> <li>The by-pass channel is designed requiring minimum maintenance. However, it is recommended that the maintenance authority carry out regular maintenance inspection prior to onset of seasons and after significant rainstorm event to prevent blockage of the by-pass and bottom rack structure.</li> </ul>	N/A N/A N/A N/A N/A

Remarks: ^ Compliance of mitigation measure; X Non-compliance of mitigation measure;

N/A Not Applicable at this stage; • Non-compliance but rectified by the contractor;

\* Recommendation was made during site audit but improved/rectified by the contractor;

\* Non-compliance but rectified/improved by the contractor and awaiting IEC's further comment.

Types of Impacts	Mitigation Measures	Status
Impacts	General  A proper waste management plan should be implemented to promote waste minimisation at source. Where waste generation is unavoidable then the potential for recycling or reuse should be explored and opportunities taken. If wastes cannot be recycled then the recommended disposal routes should be followed.  All waste materials shall be segregated into categories covering:  Excavated material or construction waste suitable for reuse on-site  Excavated material or construction waste suitable for public filling areas  Remaining C&D waste for landfill  Chemical waste, and  General refuse	*
Waste/Chemical	Proper segregation and disposal of construction waste should be implemented. Separate containers for inert and non-inert wastes should be provided. The inert waste should be taken to public filling area and the non-inert waste should be transported to strategic landfills.	۸
	A trip-ticket system on the solid waste transfer/disposal operations should be included as one of the contractual requirements (ETWB TCW No. 31/2004). The Independent Environmental Checker (IEC) should responsible for auditing this system.	۸
	IEC should also responsible for auditing the well-documented record system which includes: (i) quantity of waste generation, (ii) quantity of recycled material, (iii) quantity of disposed material, (iv) disposal methods and (v) sites should be implemented during construction phase.	۸
	Regular cleaning and maintenance of the waste storage area should be conducted throughout the construction stage.	۸
	Excavated spoil  Control measures for soil temporarily stockpiled on-site should be taken in order to minimize the noise, generation of dust, pollution of water and visual impact. Key impacts include:	۸

Remarks: ^ Compliance of mitigation measure; X Non-compliance of mitigation measure;

N/A Not Applicable at this stage; • Non-compliance but rectified by the contractor;

\* Recommendation was made during site audit but improved/rectified by the contractor;

\* Non-compliance but rectified/improved by the contractor and awaiting IEC's further comment.

Types of Impacts	Mitigation Measures	Status
	• Surface of stockpiled soil should be wetted with water when necessary especially during dry season	^
	<ul> <li>Disturbance of stockpiled soil should be minimized</li> <li>Stockpiled soil should be properly covered with tarpaulins especially heavy rain storms</li> </ul>	٨
	<ul> <li>Stockpiled soil should be properly covered with tarpatilitis especially heavy rain storilis</li> <li>Stockpiling areas should be enclosed if possible</li> </ul>	^
	<ul> <li>Stockpling areas should be enclosed if possible</li> <li>Stockpiling location should be away from the shoreline</li> </ul>	٨
	<ul> <li>An independent surface water drainage system equipped with silt traps should be installed at the stockpiling area</li> </ul>	^
	<u>Chemical wastes</u>	
	For those processes that generate chemical waste, it may be possible to find alternatives which generate reduced quantities or even no chemical waste, or less dangerous types of chemical waste.	۸
	Construction processes produce chemical waste, the contractor must register with EPD as a Chemical Waste Producer. Wastes classified as chemical wastes are listed in the Waste Disposal (Chemical Waste) (General) Regulation (CWR). It should be handled in accordance with the Code of Practice on the Packaging, Handling and Storage of Chemical Waste published by the EPD. A producer of chemical wastes should be registered as chemical waste producer and registered with EPD.	۸
	The chemical waste generated shall be properly labelled, stored and disposed of according to the CWR. Proper storage area shall be allocated on site for storage of chemical waste. The chemical waste should only be collected by a licensed collector. An updated list of licensed chemical waste collector can be obtained from EPD.	*
	In case of spillage, spill absorbent material and emulsifiers should be available on site. This material should be replaced on a regular basis and the contaminated material stored in a designated, secure place.	*
	General refuse A reputable waste collector should be employed by the contractor to remove general refuse from the site, separate from C&DM and chemical wastes, and on regular basis in order to minimize odour, pest and litter impacts. The burning of refuse at site is not permitted under the Air Pollution Control Ordinance (Cap 311).	*
	Office waste can be reduced through recycling of paper if volumes are large enough to warrant collection.	٨
	Good management practices should be implemented to ensure that refuse is properly stored and is transported for disposal of at licensed landfills.	٨

Remarks: ^ Compliance of mitigation measure; X Non-compliance of mitigation measure;

N/A Not Applicable at this stage; • Non-compliance but rectified by the contractor;

\* Recommendation was made during site audit but improved/rectified by the contractor;

<sup>#</sup> Non-compliance but rectified/improved by the contractor and awaiting IEC's further comment.

Types of Impacts	Mitigation Measures	Status
Terrestrial Ecology	During the detailed design stage, the following issues should also be considered as possible to further minimise the impacts:  • Adjustment of site boundary to minimise temporary loss of natural stream habitat during construction.  • Adjustment of site boundary to minimise use of mixed woodland as temporary works area. In particular, the woodland habitat in temporary works area of the Eastern Portal will be avoided, thereby greatly reducing the area of temporary loss of woodland habitat.  • Minimizing felling of large trees.  • About 20% of trees within the works area will be transplanted. The individual of Artocarpus hypargyreus recorded within the temporary works area of HKU1, if to be encroached, would also be transplanted.  Standard site practices including the following, should be enforced to minimise the disturbance to the surroundings:  • Treat any damage that may occur to large individual trees in the adjacent area using materials and methods appropriate for tree surgery.  • Reinstate work sites/disturbed areas immediately after completion of the construction works, in particular, through on-site tree/shrub planting along the woodland and shrubland section within the temporary works area. Tree/shrub species used should make reference from those in the surrounding area.  • Regularly check the work site boundaries to ensure that they are not exceeded and that no damage occurs to surrounding areas.  A total of 1.02 ha would be replanted with woodland species, reaching almost a 1.5:1 ratio for compensatory planting.  Tree/shrub species used should be based on those in the surrounding areas, including those which are commonly recorded during the baseline surveys.	^ ^ ^
	A low-flow channel would be provided within the channelised section to maintain a deeper water depth in the expanded channel, in particular during dry season as well as a basin at the end of the channelised section to provide living space for aquatic life. Step chute in the form of a series of descending water pools would be constructed between the low flow channel and the undisturbed stream course. There would also be openings for aquatic fauna between each chute step (pool). These could work like a "ladder" to help avoid isolating the aquatic fauna in the channelised section from natural habitats.	۸
	Measures are also needed to maintain the flow of all affected streams/nullahs during the construction stages. Temporary bypass should be provided if the stream/nullah flows will be cut off by the construction works. After the construction works are finished, sections of temporary loss should be reinstated. Construction materials, wastes, and equipment should be cleared from the sites.	^

Remarks: ^ Compliance of mitigation measure; X Non-compliance of mitigation measure;

N/A Not Applicable at this stage; • Non-compliance but rectified by the contractor;

\* Recommendation was made during site audit but improved/rectified by the contractor;

\* Non-compliance but rectified/improved by the contractor and awaiting IEC's further comment.

Types of Impacts	Mitigation Measures	Status
	Surveys of amphibians at E4(P), PFLR1(P), W12(P), MB16, E5(B)(P), TP789(P) and P5(P) prior to commencement of construction is recommended. Frogs, including Hong Kong Cascade Frog and Lesser Spiny Frog, and tadpoles found at work areas of these proposed intake points will be collected and translocated to nearby streams that will not be affected by the project. These procedures should be performed by experienced herpetologists. A detailed translocation proposal will be submitted during the detailed design stage.	۸
	Measures should also be taken to avoid runoff to streams and marine habitats. Stream/channel which could potentially be affected during construction should be prevented from sedimentation by erection of sediment barriers. Site runoff should be desilted by siltation traps in streams/channels or diverted, to reduce the potential for suspended sediments, organics and other contaminants to enter the local stream environment.	۸
Marine Ecology	Silt curtains will be deployed during the construction and demolition of the temporary berthing point. Deployment of silt curtains around the berthing point area would effectively avoid adverse water quality impacts due to barge filling. No significant ecological impact is anticipated.	N/A
	The invert of the stilling basin would be at -5.4 mPD. A cofferdam in the form of pipe-pile wall is to be constructed outside the stilling basin prior to the construction of basin. The cofferdam will be dewatered to provide a working area for construction of the stilling basin. The boulders from the seawall will then be removed by landbased grabs.	۸
	Although the speed of the working vessels to be used in the Project (mainly barges) would not be high, a speed limit for marine traffic is proposed as a precautionary measure. A speed limit of 10 knots should be strictly enforced in the works area, in particular in the waters between the outfall location and the navigation channel in East Lamma Channel.	٨

N/A Not Applicable at this stage; • Non-compliance but rectified by the contractor;

\* Recommendation was made during site audit but improved/rectified by the contractor;

\* Non-compliance but rectified/improved by the contractor and awaiting IEC's further comment.

Types of Impacts	Mitigation Measures	Status
Impacts  Landscape and Visual	The proposed landscape and visual mitigation measures during the construction phase include:  CM1 - Topsoil, where identified, should be stripped and stored for re-use in the construction of the soft landscape works, where practical.  CM2 - Existing trees to be retained on site should be carefully protected during construction. The detailed proposal for any trees felling and transplantation is subject to Lands Department's approval on tree felling application at the detailed design stage.  CM3 - Trees unavoidably affected by the works should be transplanted where practical.  CM4 - Compensatory tree planting should be provided to compensate for felled trees.  CM5 - The extent of disturbance on the existing stream course should be minimized. Any temporary works areas within the stream course shall be reinstated after construction.  CM7 - Control of night-time lighting  CM8 - Erection of decorative screen hoarding	^ ^ ^ ^ ^ ^ ^ ^ ^ ^ ^ ^ ^ ^ ^ ^ ^ ^ ^ ^

N/A Not Applicable at this stage; • Non-compliance but rectified by the contractor;

\* Recommendation was made during site audit but improved/rectified by the contractor;

\* Non-compliance but rectified/improved by the contractor and awaiting IEC's further comment.

Types of Impacts	Mitigation Measures	Status
	The Cultural Heritage Impact Assessment has identified the following resources which will require mitigation measures during the construction stage;  Haw Par Mansion (including boundary wall and gate) A condition survey must be undertaken by a qualified professional prior to the commencement of construction works for the tunnel portal in order to assess the structural integrity of the mansion, wall and gate (with special attention paid to any fragile architectural features). A report containing description of the types of construction, identification of fragile elements, an appraisal of the condition and a photographic record must be prepared. The report must also provide an assessment indicating whether further precautionary measures will be necessary during the construction phase, and if so provide details for sufficient protective measures, including monitoring for vibration control to ensure that no damage to the structure and fabric of the house, wall and gate results from the	٨
Cultural Heritage	Inomtoring for vibration control to ensure that no damage to the structure and fabric of the nouse, want and gate results from the construction works. The report must be submitted to AMO for approval before construction activities commence. Upon approval the appropriate monitoring and precautionary measures shall be put into place.  A buffer zone with a minimum width of 3 metres and an obstruction free access point must be maintained between the boundary wall/gate and the temporary works area (during construction works associated for both the tunnel portal and the permanent vehicle access ramp). This is to enable access for routine maintenance works on the wall and to ensure that the wall is not damaged by machinery operation or related construction activities. The temporary works area will be enclosed by standard DSD site hoarding.	٨
	Former Explosive Magazine of Victoria Barracks	
	A condition survey must be undertaken by a qualified professional prior to the commencement of construction works in order to assess the structural integrity of the retaining wall and the extent of damage from cracks and vegetation growth. A report containing a description of the wall's construction materials, identification of fragile and/or endangered elements, an appraisal of the condition and a photographic record of the retaining wall must be prepared. The report must also provide an assessment indicating whether further precautionary measures will be necessary during the construction phase, and if so provide details for sufficient protective measures, such as monitoring for vibration control, to ensure that no damage to the retaining wall results from the construction works. The report must be submitted to AMO for approval before construction activities commence. Upon approval the appropriate monitoring and precautionary measures shall be put into place.	٨
	A buffer zone with a minimum width of 3 metres and an obstruction free access point must be maintained between the retaining wall and the temporary works area (for the duration of the construction phase). The works area will be enclosed by standard DSD site hoarding.	٨

Remarks: ^ Compliance of mitigation measure; X Non-compliance of mitigation measure;

N/A Not Applicable at this stage; • Non-compliance but rectified by the contractor;

\* Recommendation was made during site audit but improved/rectified by the contractor;

\* Non-compliance but rectified/improved by the contractor and awaiting IEC's further comment.

Types of Impacts	Mitigation Measures	Status
Fisheries	Silt curtain will be deployed during the construction and demolition of the temporary berthing point. With the deployment of silt curtains around the berthing point area, adverse water quality impact associated with the filling would not be anticipated. No significant fisheries impact is anticipated.	N/A
	The invert of stilling basin will be found at -5.4 mPD. A cofferdam in the form of pipe-pipe wall is to be constructed outside the stilling basin prior to the construction of basin. The cofferdam will be dewatered to provide a working space for the construction of stilling basin. The boulders from the seawall will then be removed by landbased grabs.	۸
Hazard to Life	There will be no overnight storage of explosives for this project. Transportation of explosives to site for the construction of adit will be undertaken on a daily basis. The contractor is required to destroy any unused explosives before nightfall. If contractor wishes to set up magazines for overnight storage of explosives, it is necessary to carry out risk assessment and seek the relevant approval following the EIAO process.	۸

N/A Not Applicable at this stage; • Non-compliance but rectified by the contractor;

\* Recommendation was made during site audit but improved/rectified by the contractor;

\* Non-compliance but rectified/improved by the contractor and awaiting IEC's further comment.

## APPENDIX G SITE AUDIT SUMMARY

Appendix G Summary of Observation and Recommendation Made during Site Inspection

Summary of Observation and Recommendation Made during Site Inspection in April 2011

Parameters	Date	Observations and Recommendations	Follow-up
Water Quality	07/04/2011	The sedimentation tank was observed full of	Rectification/improvement
~ .		deposited mud at Intake E5A. The	was observed during the
		Contractor was reminded to clear the	follow-up audit session.
		deposited mud and ensure the sedimentation	
		tank can function properly at all the time.	
	14/04/2011	The green water at the sedimentation tank at	Rectification/improvement
		Intake HKU1 was observed. The Contractor	was observed during the
		was reminded to pump it out for proper	follow-up audit session.
		treatment.	
	14/04/2011	Sedimentation tank at Intake W10 and E5A	Rectification/improvement
		was observed full of silty water. The	was observed during the
		Contractor was reminded to review the	follow-up audit session.
		capacity of the tank and clear the deposited	
		mud more frequently.	
	21/04/2011	Sedimentation tank was observed full of	Rectification/improvement
		silty water and cannot function properly at	was observed during the
		Intake W5. The Contractor was reminded to	follow-up audit session.
		review the current desilting facilities are	
		sufficient for the works.	
	28/04/2011	Sedimentation tank was observed full of	Rectification/improvement
		silty water and cannot function properly at	was observed during the
		Intake W5. The Contractor was reminded to	follow-up audit session.
		review the current desilting facilities are	
		sufficient for the works.	
Reminders	07/04/2011	The Contractor was reminded of the	Rectification/improvement
		followings:	was observed during the
		- To cover the grouting material with	follow-up audit session.
		tarpaulin, to avoid dust generation at	
		Western Portal.	
	07/04/2011	The Contractor was reminded of the	Rectification/improvement
		followings:	was observed during the
		- Clear the grease water at Western Portal, to	follow-up audit session.
		avoid directing to drainage channel.	
	07/04/2011	The Contractor was reminded of the	Rectification/improvement
		followings:	was observed during the
		- Rock material or deposited mud should be	follow-up audit session.
		avoided to be disposed in public drain. The	
		Contractor was reminded to well-maintain	
		the drainage channel at Intake SM1 and	
	07/04/2014	HKU1.	D 10 1 0
	07/04/2011	The Contractor was reminded of the	Rectification/improvement
		followings:	was observed during the
		- The oil stain should be cleared at Intake	follow-up audit session.
	07/04/2014	P5.	2 12 1 4
	07/04/2011	The Contractor was reminded of the	Rectification/improvement
		followings:	was observed during the
		- Clear the milky water at Intake W3, to	follow-up audit session.
	07/04/2011	avoid directing to public drain.	D .: (5' /
	07/04/2011	The Contractor was reminded of the	Rectification/improvement
		followings:	was observed during the
		- Clear the discarded leaves along the	follow-up audit session.
		drainage channel at Intake THR2.	

Parameters	Date	Observations and Recommendations	Follow-up
	14/04/2011	The Contractor was reminded of the followings: - Clear the discarded leaves at the drainage channel at Intake HKU1 and BR6.	Rectification/improvement was observed during the follow-up audit session.
	14/04/2011	The Contractor was reminded of the followings: - Clear the oil stain at underneath the equipment at Intake P5.	Rectification/improvement was observed during the follow-up audit session.
	14/04/2011	The Contractor was reminded of the followings: - Clear the C&D waste at the sedimentation tank at Intake P5 so that it can function properly.	Rectification/improvement was observed during the follow-up audit session.
	14/04/2011	The Contractor was reminded of the followings: - To repair the water pipe to avoid wastage of water.	Rectification/improvement was observed during the follow-up audit session.
	14/04/2011	The Contractor was reminded of the followings: - Clear the stagnant water/milky water at drip tray and drainage channel at Intake MA15 and W3 respectively.	Rectification/improvement was observed during the follow-up audit session.
	21/04/2011	The Contractor was reminded of the followings: - To repair the water pipe to avoid wastage of water at Intake W10.	Rectification/improvement was observed during the follow-up audit session.
	21/04/2011	The Contractor was reminded of the followings:  - To clear the standing water/silty water at the drip tray and drainage channel at Intake W10, W5 and P5 respectively.	Rectification/improvement was observed during the follow-up audit session.
	28/04/2011	The Contractor was reminded of the followings: - Provide the plug for the drip tray to avoid oil leakage at Intake W10.	Rectification/improvement was observed during the follow-up audit session.
	28/04/2011	The Contractor was reminded of the followings:  - To repair the water pipe to avoid wastage of water at Intake W10.	Rectification/improvement was observed during the follow-up audit session.
	28/04/2011	The Contractor was reminded of the followings: - To clear the discarded leaves within the drainage channel at Intake HKU1.	Rectification/improvement was observed during the follow-up audit session.
	28/04/2011	The Contractor was reminded of the followings: - To clear the deposited silt within the sedimentation tank as soon as possible at Intake W10.	Rectification/improvement was observed during the follow-up audit session.

Summary of Observation and Recommendation Made during Site Inspection in May 2011

Parameters	Date	Observations and Recommendations	Follow-up
Reminders	05/05/2011	The Contractor was reminded of the followings: - Clear the oil spillage at spoil basin and two oil drums at Western Portal.	Rectification/improvement was observed during the follow-up audit session.
	05/05/2011	The Contractor was reminded of the followings: - Clear the oil containers and oil spillage at underneath of mobile crane at Intake W3.	Rectification/improvement was observed during the follow-up audit session.
	05/05/2011	The Contractor was reminded of the followings: - To display CNP and EP at site entrance at SMH17.	Rectification/improvement was observed during the follow-up audit session.
	05/05/2011	The Contractor was reminded of the followings: - To cover the noisy part of the air receiver at Intake W0.	Rectification/improvement was observed during the follow-up audit session.
	05/05/2011	The Contractor was reminded of the followings: - Clear the deposited silt and mud at the public road at Intake MB16.	Rectification/improvement was observed during the follow-up audit session.
	05/05/2011	The Contractor was reminded of the followings: - Clear the stagnant water at H-pile at Intake W10.	Rectification/improvement was observed during the follow-up audit session.
	05/05/2011	The Contractor was reminded of the followings: - Provide the plug for the drip tray to avoid oil leakage at Intake W10.	Rectification/improvement was observed during the follow-up audit session.
	05/05/2011	The Contractor was reminded of the followings: - To repair the water pipe to avoid wastage of water at Intake W10.	Rectification/improvement was observed during the follow-up audit session.
	12/05/2011	The Contractor was reminded of the followings: - Provide the plug for the drip tray to avoid oil leakage at Intake W10.	Rectification/improvement was observed during the follow-up audit session.
	12/05/2011	The Contractor was reminded of the followings: - Clear the deposited silt and mud at the public road at Intake MB16 and drainage channel at MBD2 respectively.	was observed during the follow-up audit session.
	19/05/2011	The Contractor was reminded of the followings: - Clear the water tube which is not in use at Intake HKU1.	Follow-up action was needed for the item.
	19/05/2011	The Contractor was reminded of the followings: - Clear the discarded leaves at the drainage channel at the site entrance of Intake W10.	Rectification/improvement was observed during the follow-up audit session.
	19/05/2011	The Contractor was reminded of the followings: - Provide the plug for the drip tray at Intake MA15.	Rectification/improvement was observed during the follow-up audit session.
	19/05/2011	The Contractor was reminded of the followings: - Clear the deposited mud and silt at the gullies at Intake M3.	Rectification/improvement was observed during the follow-up audit session.

Parameters	Date	Observations and Recommendations	Follow-up
	19/05/2011	The Contractor was reminded of the followings: - To replace the worn sand bags at Intake M3.	Rectification/improvement was observed during the follow-up audit session.
	19/05/2011	The Contractor was reminded of the followings: - To clear the milky water along the uchannel at Intake W3.	Rectification/improvement was observed during the follow-up audit session.
	19/05/2011	The Contractor was reminded of the followings: - To clear the silty water and grease water at Intake DG1.	Rectification/improvement was observed during the follow-up audit session.
	26/05/2011	The Contractor was reminded of the followings: - Provide the plug for the drip tray to avoid oil and grease water leakage at Intake E5A.	Rectification/improvement was observed during the follow-up audit session.
	26/05/2011	The Contractor was reminded of the followings: - To clear the stagnant water and deposited silt along the u-channel at Intake THR2.	Rectification/improvement was observed during the follow-up audit session.
	26/05/2011	The Contractor was reminded of the followings: - The general refuse and C&D waste should be disposed of properly, to avoid storing at near the trees at Intake THR2.	Rectification/improvement was observed during the follow-up audit session.
	26/05/2011	The Contractor was reminded of the followings: - The oil drum should be stored within the drip tray, to avoid oil leakage at Eastern Portal.	Rectification/improvement was observed during the follow-up audit session.

Summary of Observation and Recommendation Made during Site Inspection in June 2011

Parameters	Date	Observations and Recommendations	Follow-up
Water Quality	16/06/2011	Milky water was observed discharging to the public drain at Intake B2. The Contractor was reminded to ensure the site discharge comply with WPCO license.	Rectification/improvement was observed during the follow-up audit session.
	23/06/2011	The sedimentation tank at Intake HR1 was observed full of wastewater and grease water. The Contractor was reminded to remove the sedimentation tank while not be used.	Rectification/improvement was observed during the follow-up audit session.
Waste/Chemical Management	02/06/2011	The oil drum was observed to be disposed of above the drainage channel without drip tray at Intake HR1. The Contractor was reminded to replace it with drip tray.	Rectification/improvement was observed during the follow-up audit session.
	30/06/2011	The oil stain was observed to be disposed from excavator because of rain at Intake BR6. The Contractor was reminded to clear the oil stain, to avoid directing to public stream.	Rectification/improvement was observed during the follow-up audit session.
Reminders	02/06/2011	The Contractor was reminded of the followings: - To direct the wastewater from site to the sedimentation facilities before discharging out at Intake HKU1.	Rectification/improvement was observed during the follow-up audit session.
	02/06/2011	The Contractor was reminded of the followings: - Clear the deposited silt and sediment at the drainage channel at site exit at Intake W10.	Rectification/improvement was observed during the follow-up audit session.
	02/06/2011	The Contractor was reminded of the followings: - Ensure the sedimentation tank at Intake W10 and Intake HR1 is functioning properly.	Rectification/improvement was observed during the follow-up audit session.
	02/06/2011	The Contractor was reminded of the followings: - To replace the worn sand bags at Intake P5.	Rectification/improvement was observed during the follow-up audit session.
	02/06/2011	The Contractor was reminded of the followings: - Provide appropriate sedimentation facilities at Intake W8.	Rectification/improvement was observed during the follow-up audit session.
	02/06/2011	The Contractor was reminded of the followings: - To repair the water pipe at Intake MBD2, to avoid water leakage.	Rectification/improvement was observed during the follow-up audit session.
	02/06/2011	The Contractor was reminded of the followings: - To clear the general refuse and C&D waste at near the trees of Intake THR2.	Rectification/improvement was observed during the follow-up audit session.
	02/06/2011	The Contractor was reminded of the followings: - To clear the stagnant water along drainage channel at Intake HR1.	Rectification/improvement was observed during the follow-up audit session.
	09/06/2011	The Contractor was reminded of the followings:  - To clear the stagnant water within H-pile and drainage channel at Intake PFLR1 and Intake HR1 respectively.	Rectification/improvement was observed during the follow-up audit session.

Parameters	Date	Observations and Recommendations	Follow-up
	09/06/2011	The Contractor was reminded of the followings: - Provide sand bag bunding around the	Rectification/improvement was observed during the follow-up audit session.
	09/06/2011	sedimentation tank at WP, to avoid discharging out to haul road while overflow.  The Contractor was reminded of the	Rectification/improvement
	09/00/2011	followings: - To remove the water pipe while it is not used at Intake HKU1.	was observed during the follow-up audit session.
	09/06/2011	The Contractor was reminded of the followings:  - To clear the general refuse within the rubbish bin of Intake P5, to avoid accumulation of waste.	Rectification/improvement was observed during the follow-up audit session.
	09/06/2011	The Contractor was reminded of the followings: - Ensure the drainage channel and sedimentation tank are functioned properly without blockage at all the time at Intake P5 and Intake HR1 respectively.	Rectification/improvement was observed during the follow-up audit session.
	followings: was observed during		follow-up audit session.
	16/06/2011	The Contractor was reminded of the followings: - Ensure the capacity of the sedimentation facilities that are enough for treating muddy water at Intake MA17.	Rectification/improvement was observed during the follow-up audit session.
	16/06/2011	The Contractor was reminded of the followings: - Provide the plug for the drip tray at Intake M3.	Rectification/improvement was observed during the follow-up audit session.
	16/06/2011	The Contractor was reminded of the followings: - Clear the deposited silt and debris at the site drain at Intake TP4.	Rectification/improvement was observed during the follow-up audit session.
	16/06/2011	The Contractor was reminded of the followings: - Properly clear the general refuse at Intake B2.	Rectification/improvement was observed during the follow-up audit session.
	16/06/2011	The Contractor was reminded of the followings: - Provide sand bag bund around the sedimentation tank to direct surface runoff for treatment at WP.	Rectification/improvement was observed during the follow-up audit session.
	23/06/2011	The Contractor was reminded of the followings:  - The discarded leaves should be cleared along the drainage channel, to avoid the blockage of channel at Intake GL1.	Rectification/improvement was observed during the follow-up audit session.
	30/06/2011	The Contractor was reminded of the followings: - The oil drum at Intake W0 and W3 should be stored within the drip tray at all the time.	Rectification/improvement was observed during the follow-up audit session.

Parameters	Date	Observations and Recommendations	Follow-up
	30/06/2011	followings:	Rectification/improvement was observed during the follow-up audit session.

APPENDIX H
SUMMARY STATUS OF
ENVIRONMENTAL LICENCES AND
PERMITS

**Appendix H - Summary of Environmental Licensing and Permit Status** 

Permit No.	Valid	Period	Details	Status
	From	To	Details	Status
Environmental Permi	t (EP)		Construction of a Casar 7 as in discussion	
			Construction of a 6.25m-7.25m in diameter	
FEP-01/272/2007/B	25/6/09	N/A	and about 11 km long underground main	Valid
			drainage tunnel, 2 portals and a series of	
Econ (D. I. I.			connecting adits and drop shafts.	
Effluent Discharge Lie	cense			
EP860/W10/XY0175	23/06/08	30/06/13	Industrial discharge (Area of Mount Butler Office)	Valid
EP860/W10/XY0177	23/06/08	30/06/13	Industrial discharge (Eastern Portal Site)	Valid
EP820/W9/XT086	22/07/08	31/07/13	Industrial discharge (Western Portal Site)	Valid
WT00005864-2010	20/01/10	31/01/15	Industrial discharge (Western Portal Site)	Valid
ED960/W10/WW0192	19/11/08	30/11/13	Industrial discharge (Intake W0, Stubbs Road,	X7.1: 4
EP860/W10/XY0183	19/11/08	30/11/13	Wan Chai, HK)	Valid
WT00003372-2009	-	30/4/14	Industrial discharge (Intake SM1)	Valid
WT00003737-2009	-	31/5/14	Industrial discharge (Intake MB16)	Valid
WT00004126-2009	-	31/5/14	Industrial discharge (Intake HKU1)	Valid
WT00003738-2009	-	31/5/14	Industrial discharge (Intake THR2)	Valid
WT00004270-2009	-	31/7/14	Industrial discharge (Intake PFLR1)	Valid
WT00004806-2009	-	30/09/14	Industrial discharge (Intake E7)	Valid
WT00004808-2009	-	30/09/14	Industrial discharge (Intake MBD2)	Valid
WT00004885-2009	-	30/09/14	Industrial discharge (Intake RR1)	Valid
WT00005135-2009	-	31/10/14	Industrial discharge (Intake W10)	Valid
WT00005374-2009	-	30/11/14	Industrial discharge (Intake P5)	Valid
WT00005376-2009	-	30/11/14	Industrial discharge (Intake TP4)	Valid
WT00005357-2009	-	30/11/14	Industrial discharge (Intake W5)	Valid
WT00005588-2009	-	31/12/14	Industrial discharge (Intake TP5)	Valid
WT00005643-2009	-	31/12/14	Industrial discharge (Intake E5A)	Valid
WT00005754-2010	-	31/01/15	Industrial discharge (Intake W8)	Valid
WT00005954-2010	-	28/02/15	Industrial discharge (Intake TP789)	Valid
WT00005915-2010	-	31/01/15	Industrial discharge (Intake E5B)	Valid
WT00006102-2010	-	28/02/15	Industrial discharge (Intake M3)	Valid
WT00006415-2010	-	30/04/15	Industrial discharge (Intake MA15)	Valid
WT00006418-2010	-	30/06/15	Industrial discharge (Intake MA14)	Valid
WT00006420-2010	-	30/04/15	Industrial discharge (Intake MA17)	Valid
WT00006428-2010	-	30/04/15	Industrial discharge (Intake BR6)	Valid
WT00006609-2010	-	31/05/15	Industrial discharge (Intake HR1)	Valid

Permit No.	Valid	Period	- Details	Status	
1 et mit 140.	From To		Details	Status	
WT00006559-2010	-	30/04/15	Industrial discharge (Intake CR1)	Valid	
WT00006865-2010	-	30/06/15	Industrial discharge (Intake BR5)	Valid	
WT00006929-2010	-	30/06/15	Industrial discharge (Intake W1)	Valid	
WT00007039-2010	-	31/07/15	Industrial discharge (Intake DG1)	Valid	
WT00007042-2010	-	31/07/15	Industrial discharge (Intake W3)	Valid	
WT00007043-2010	-	31/07/15	Industrial discharge (Intake GL1)	Valid	
WT00007130-2010	-	31/07/15	Industrial discharge (Intake BR4)	Valid	
WT00007139-2010	-	31/07/15	Industrial discharge (Intake BR6) – SNH17	Valid	
WT00007319-2010	-	31/08/15	Industrial discharge (Intake B2)	Valid	
Registration of Chem	ical Waste Pı	roducer	1		
5213-148-D2393-02		N/A	Chemical waste types:	Valid	
			Spent oil	vanu	
5213-172-D2393-01		N/A	Chemical waste types:	V-1: 4	
			Spent oil	Valid	
<b>Construction Noise P</b>	ermit (CNP)	1			
			Construction Noise Permit for the use of		
GW-RS0734-10	25/08/10	24/02/11	powered mechanical equipment for carrying		
			out construction work at Hong Kong West	Valid	
			Drainage Tunnel (Eastern Portal) (DSD	v and	
GW-RS0125-11	24/02/11	23/08/11	Contract No. DC/2007/10), Tai Hang Road,		
			Causeway Bay, Hong Kong.		
			Construction Noise Permit for the use of		
GW-RS1054-10	14/12/10	13/02/11	powered mechanical equipment for carrying		
			out construction work and performing		
			prescribed construction work at Hong Kong	Valid	
			West Drainage Tunnel (Western Portal),		
GW-RS0066-11	14/02/11	13/04/11	Cyberport Road, Cyberport, Hong Kong		
			(DSD Contract No. DC/2007/10).		
			Construction Noise Permit for the use of		
GW-RS0733-10	19/08/10	18/02/11	powered mechanical equipment for carrying		
			out construction work at a construction site of	Valid	
GW PG0140 11	10/02/11	10/00/11	"Hong Kong West Drainage Tunnel" near	, and	
GW-RS0149-11	19/02/11	18/08/11	Stubbs Road Garden, Wan Chai, Hong Kong.		
			Construction Noise Permit for the use of		
CW DC0400 10	22/00/10	21/02/11	powered mechanical equipment for carrying	X71: 1	
GW-RS0699-10	699-10 22/08/10		out construction work at Smithfield Road	Valid	
			outside Mei Wah Mansion, Kennedy Town,		
			Hong Kong.		

Permit No.	Valid	Period	Details Statu	
refillt No.	From	To	Details	Status
GW-RS0710-10	19/08/10	18/02/11	Construction Noise Permit for the use of powered mechanical equipment for carrying out construction work at Section of Pokfulam	Valid
GW-RS0167-11	19/02/11	18/08/11	Road (near Football Field, Pokfulam Road Playground), Hong Kong.	vanu
GW-RS0995-10	30/11/10	30/05/11	Construction Noise Permit for the use of powered mechanical equipment for carrying out construction work at outside Hongkong Electric Centre, Kennedy Road, Hong Kong	Valid
GW-RS1071-10	09/12/10	08/06/11	Construction Noise Permit for the use of powered mechanical equipment for carrying out construction work and performing prescribed construction work at Junction of Magazine Gap Road and May Road, Mid-levels, Hong Kong.	Valid
GW-RS0147-11	20/02/11	27/03/11	Construction Noise Permit for the use of powered mechanical equipment for carrying out construction work at Junction of Magazine Gap Road and May Road, Mid-levels, Hong Kong.	Valid
GW-RS0244-11	22/03/11	20/09/11	Construction Noise Permit for the use of powered mechanical equipment for carrying out construction work and performing prescribed construction work at main tunnel and adits of Hong Kong West Drainage Tunnel under Wan Chai, Hong Kong.	Valid

## APPENDIX I WASTE GENERATED QUANTITY

# **Monthly Waste Flow Table**

		Actual	Quantities of In	ert C&D Materia	ls Generated N	Ionthly	Actual Quantities of C&D Wastes Generated Monthly				
Quarter ending	Total Quantity Generated	Broken Concrete	Reused in the Contract	Reused in other Projects	Disposed as Public Fill	Imported Fill	Metals	Paper/ cardboard packaging	Plastics (see notes 2)	Chemical Waste	Others, e.g. general refuse
	(in m <sup>3</sup> )	(in m <sup>3</sup> )	(in m <sup>3</sup> )	(in m <sup>3</sup> )	(in m <sup>3</sup> )	(in m <sup>3</sup> )	( in Kg)	( in Kg)	( in Kg)	( in Kg)	(in m <sup>3</sup> )
Jan 2011	24478	0	24	22424	1992	38	25905	385	0	0	84
Feb 2011	11114	0	0	10034	1080	0	128470	385	0	4924	73
Mar 2011	14052	0	4	12042	2006	0	273060	700	0	3072	101
Apr 2011	11795	0	0	10441	1354	0	496610	315	0	0	84
May 2011	12099	0	0	11134	965	0	54330	315	0	0	140
Jun 2011	14976	0	0	6929	8047	0	25120	420	0	0	101
Sub-Total	88514	0	28	73004	15444	38	1003495	2520	0	7996	583
July 2011											
Aug 2011											
Sep 2011											
Oct 2011											
Nov 2011											
Dec 2011											
Total											

Notes:

- (1) The waste flow table shall also include C&D materials that are specified in the Contract to be imported for use at the Site.
- (2) Plastics refer to plastic bottles/containers, plastic/foam from packaging material.
- (3) Quantities in April to June 2011 are upto 31 June 2011.
- (4) Assuming the conversion factor from m<sup>3</sup> to ton for rock is 2.5.
- (5) The materials reused in other Project shall not be treated as waste under the Waste Disposal Ordinance (Cap 354).
- (6) The figures are included for the sake of completeness of record.

## APPENDIX J SUMMARY OF EXCEEDANCES

### Contract No. DC/2007/10 - Design and Construction of Hong Kong West Drainage Tunnel

#### **Exceedance Report**

#### **Eastern Portal**

- (A) Exceedance Report for Air Quality (1 hour TSP) (NIL in the reporting quarter)
- (B) Exceedance Report for Air Quality (24 hours TSP) (NIL in the reporting quarter)
- (C) Exceedance Report for Construction Noise (NIL in the reporting quarter)

#### **Western Portal**

- (D) Exceedance Report for Air Quality (1 hour TSP) (NIL in the reporting quarter)
- (E) Exceedance Report for Air Quality (24 hours TSP) (NIL in the reporting quarter)
- (F) Exceedance Report for Construction Noise (NIL in the reporting quarter)

#### **Intakes**

**Intake DG1** 

(G) Exceedance Report for Construction Noise (NIL in the reporting quarter)

#### **Intake E5A**

(H) Exceedance Report for Construction Noise (NIL in the reporting quarter)

#### Intake E7

(I) Exceedance Report for Construction Noise (NIL in the reporting quarter)

#### **Intake MA14**

(J) Exceedance Report for Construction Noise (NIL in the reporting quarter)

#### **Intake PFLR1**

(K) Exceedance Report for Construction Noise (NIL in the reporting quarter)

#### **Intake RR1**

(L) Exceedance Report for Construction Noise (NIL in the reporting quarter)

#### **Intake THR2**

(M) Exceedance Report for Construction Noise (NIL in the reporting quarter)

#### Intake W0

(N) Exceedance Report for Construction Noise (NIL in the reporting quarter)

#### **Intake W5**

(O) Exceedance Report for Construction Noise (NIL in the reporting quarter)

### Intake W8

(P) Exceedance Report for Construction Noise (NIL in the reporting quarter)

#### **Intake P5**

(Q) Exceedance Report for Construction Noise (One Action Level exceedance was recorded for the complaint received on 2 June 2011)

#### **Intake BR6**

(R) Exceedance Report for Construction Noise (NIL in the reporting quarter)

#### Intake GL1

(S) Exceedance Report for Construction Noise (One Action Level exceedance was recorded for the complaint received on 30 May 2011)

#### Intake TP5&TP789

(T) Exceedance Report for Construction Noise (NIL in the reporting quarter)

#### Intake B2

(U) Exceedance Report for Construction Noise (NIL in the reporting quarter)

#### **Intake CR1**

(V) Exceedance Report for Construction Noise (One Action Level exceedance was recorded for the complaint received on 30 May 2011)

## APPENDIX K COMPLAINT LOGS

## APPENDIX K – COMPLAINT LOG

Log Ref.	Location	Received Date	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
Com-2008-05-003	Construction site at Eastern Portal	22 May 2008	The complaint was lodged by a complainant on 22 May 2008 regarding noise nuisance generated from the construction activities at the construction site of Eastern Portal	According to the Contractor, only one excavator and one generator were operated for the excavation works around 8 am on 22 May 2008 at the Eastern portal. No other construction activities were conducted.  In response to the complaint, The Contractor agreed to reschedule their current works activities, with immediate effect from 23 May 2008, that only site preparation works without noise nuisance to the nearby residents will be carried out from 7:00 am to 8:00 am at the Eastern Portal area.  Base on the information collected and the monitoring results, the complaint was considered not justifiable since (1) no exceedance of the noise monitoring results was recorded in May and (2) no noncompliance or observation on noise was recorded.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
Com-2008-05-004	Construction site at Western Portal (Marine Works)	31 May 2008	The complaint was lodged by one of the local resident on 31 May 2008 regarding the noise nuisance generated from the marine works at Western Portal.	Base on the information collected	Closed
Com-2008-07-007	Construction site at Eastern Portal	2 July 2008	The complaint was lodged by a resident of The Legend on 2 July 2008 regarding noise nuisance generated from the construction activities at the construction site of Eastern Portal	(Jumbo) were operated for the preparation works around 7:30a.m on 2 July 2008 at the Eastern portal. Construction noise was found from	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
				In response to the complaint, The Contractor review his forthcoming operations within the Eastern Portal site as previous they agreed, reschedule their current works activities, with immediate effect from 23 May 2008, that only site preparation works without noise nuisance to the nearby residents will be carried out from 7:00 am to 8:00 am at the Eastern Portal area.  Additional noise monitoring was conducted on 16 and 17 July 2008 during the drilling rig (Jumbo), excavator and wheel loader were operated for drilling works.	
				Base on the information collected and the monitoring results, the complaint was considered not justifiable since (1) no exceedance of the noise monitoring results was recorded in June and July 2008 and additional noise monitoring (2) no non-compliance or observation on noise was recorded.	

COM-2008-10-011 Construction site at Western Portal Construction Site at Constructio	
regarding about the noise nuisance generated from the construction works at Western Portal  Western Portal  Additional noise monitoring was conducted on 15 October 2008, drilling works, excavation works and marine works including sheet piling works were also conducted. The construction noise levels measured during the construction noise limit of 75 dB(A)  The Contractor agreed to reschedule the starting time of the construction works to 8:15am on every Saturday that without noise nuisance from the construction works to the nearby residents will be carried out from 7:00 am to 8:15 am at the Western Portal area.  Base on the information collected, the noise level measured at outside Aegean Terrace during the construction works at Western Portal	cission of the cissio

Log Ref.	Location	Received Date	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
				noise limit of 75 dB(A). Also, the Contractor has implemented the remedial measure that reschedule the starting time of the construction works to 8:15am on every Saturday immediately after receiving the complaint to minimize the noise nuisance to the nearby residents.	
COM-2008-10-012	Construction site at Intake TP5	15 October 2008	The complaint was lodged by a complainant on 15 October 2008 regarding about the noise generated from the GI works, which starts from 8:30 hrs to 17:30 hrs next to Aigburth at May Road.	According to the information provided by the Contractor, only rotary type drill rigs and water pumps were operated for the GI works at the time of complaint at	Closed
COM-2008-10-013	Construction site at Intake TP5	31 October 2008	The complaint was lodged by a complainant on 31 October 2008 regarding the black smoke is emitted and noise is generated from the machine at the site (Intake TP5), he needed to close the windows to prevent the black smoke from entering his flat and to attenuate the noise.	conducted on 3 Nov 2008 and 24 Oct, 5 Nov, 7 Nov 2008 respectively.	

Log Ref.	Location	<b>Received Date</b>	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
COM-2008-11-015	Construction site at Intake TP5	4 November 2008	The complaint was lodged by a complainant on 4 November regarding the noise nuisance generated from the construction works at Intake TP5.	without noise nuisance to the nearby residents will be carried out from 7:00 am to 8:00 am at Intake TP5. Acoustic insulating materials have been applied for enclosing water pump and rotary type drill rigs to minimize the noise nuisance to the nearest residents.  Base on the information collected, the noise level measured at the podium of the Valverde at May Road were well below the construction noise limit of 75 dB(A) after the Contractor has implemented the remedial measure.	
COM-2008-11-016	Construction site at Western Portal	17 November 2008	The complaint was lodged by a complainant on 17 November 2008 regarding dust nuisance arising from the soil nailing works at the roadside slope of Cyberport Road.	provided by the Contractor, soil nailing works were conducted and	Closed

Log Ref.	Location	Received Date	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
				Portal (AQ3), the dust levels measured at AQ2 for 1 hour TSP and at AQ3 for 24 hour TSP were well below the Action Level (321µg/m3 for 1 hour TSP and 156µg/m3 for 24 hour TSP). Also, the Contractor has implemented the dust suppression measures to prevent dust nuisance from the construction activities including soil nailing works.	
COM-2008-11-019	Construction site at Western Portal	29 November 2008	The complaint was lodged by a complainant on 1 December 2008 regarding noise nuisance at Western Portal at 08:30 hrs approx on 29 November 2008 and 00:30 on 1 December 2008.	provided by The Contractor, no construction works was carried out at the temporary jetty at the time of complaint (00:30 on 1 December	Closed
COM-2008-12-020	Construction site at Western Portal	28 December 2008	The complaint was lodged by a complainant on 28 December 2008 regarding the excavator was found working	The complaint was considered not justifiable as Construction Noise	Closed

Log Ref.	Location	<b>Received Date</b>	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
		TRECORVED BUILD	within Western Portal works area on Sunday.	EPD for carrying out the construction works at Hong Kong West Drainage Tunnel (Western Portal), Cyberport Road, Cyberport, Hong Kong (DSD Contract No. DC/2007/10) between 1 December 2008 at 1900 hours and 28 February 2009 at 2400 hours. The powered mechanical equipment can be operated during the hours as below:  a) Any day not being a general holiday between 1900 – 2300 hours b) General holiday (including Sundays) between 0700 – 1900 hours	
COM-2009-01-021	Muddy Water Discharged into Sea at Western Portal	21 January 2009	Muddy water was observed from discharging into the sea at Western Portal Site	Base on the information collected, the muddy water discharged into the sea is considered due to the operations of excavation of stilling basin and poor condition of the silt curtain.  The Contractor agreed to review their current provisions to prevent any muddy water from discharging into the sea again and close check the	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
				condition of the silt curtain.	
COM-2009-01-022(A)	Construction site at Western Portal	12 January 2009	The complaint was lodged by a complainant, the assistant of Southern District Councillor about the resident in Baguio Villa near Victoria Road, the complainant concerns on the noisy activities carried out at Western Portal site.	Base on the information collected, the noise level measured at outside Aegean Terrace during the construction works at Western Portal site were well below the construction	
COM-2009-01-022(B)		21 January 2009	The complaint was lodged by resident of Aegean Terrace at Sassoon Road about the noise nuisance generated from Western Portal Site.	noise limit of 75 dB(A). Aegean Terrace is at location close to the major site activities compared with Baguio Vila. Also, The Contractor agreed to reschedule their current works activities, no noisy work will	Closed
COM-2009-01-022(C)		21 January 2009	The complaint was lodged by the resident in Baguio Villa near Victoria Road about noisy works at Western Portal Site.	be carried out at Western Portal Site before 8:00a.m.	
COM-2009-02-023	Construction site at Eastern Portal	7 February 2009	Complaint of Construction Noise at Early Morning (07:45hrs) at Eastern Portal Site	the construction noise at about	Closed

Log Ref.	Location	<b>Received Date</b>	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
				The Contractor was reminded to strengthen their site supervision and provide sufficient site-specific environmental training for subcontractor to ensure that such situation would not be recurred.	
COM-2009-03-025	Construction site at Western Portal	2 March 2009 4 March 2009	Complaint of noise generated by midnight works and night- time lighting at Western Portal Site		
COM-2009-03-026		7 March 2009	Complaint of pipe hitting noise at midnight at Western Portal Site.	below the construction noise limit of	
				The Contractor was reminded to strengthen their site supervision and implement necessary noise mitigation measures to minimize and avoid the construction noise impact to the residents nearby especially during the restricted hours.	Closed
				Regarding the complaint of spotlight hanging on the plant at the site portion WP, The Contractor was reminded to implement the	

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
				mitigation measures for Visual during the construction by controlling the night-time lighting so that the residual visual impacts can be accepted.	
COM-2009-04-028	Construction site at Western Portal	7 April 2009	Complaint of noise generated from the construction works conducted till 11:00pm at Western Portal of the Hong Kong West Drainage Tunnel.	provided by The Contractor, TBM, conveyor belt, ventilation fan, tower crane and cherry picker were operated for the construction works	
COM-2009-04-029		10 April 2009	Complaint of noise generated by TBM works at Western Portal.		
				According to the photos taken on 8 April 2009, misplacement of plant was observed at Western Portal Site. Upon advice, The Contractor immediately moved the fan properly.	Closed
				Based on the information collected, the construction noise levels measured were well below the construction noise limit of 75 dB(A) for the period of 0700-1900 hrs on normal weekdays, 65 dB(A) for the	

Log Ref.	Location	Received Date	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
				period of 0700-2300 hrs on holiday;	
				and 1900-2300 hrs on all other days	
				and baseline level for the period of	
				2300-0700 hrs of next day. The	
				ground borne noise levels measured	
				were also well below the	
				construction ground borne noise	
				standards (i.e. 65 dB(A) – Daytime	
				(except General Holiday and	
				Sundays) and 55 dB(A) – Daytime	
				during general holidays and Sunday	
				and all days during Evening (1900 to	
				2300 hrs). No exceedances of noise	
				level have been recorded in March	
				and April 2009.	
				The Contractor was advised to	
				strictly follow the conditions of the	
				permit to avoid any misplacement of	
				plants in the future. Also, The	
				Contractor should take sufficient	
				noise mitigation measures to	
				minimize the environmental impact	
				on the nearby community as	
				recommended in the approved EIA	
				report.	
				In addition DNIV almosty among ad	
				In addition, DNJV already arranged	
				tailors made training for the	
				Production Team including the	

Log Ref.	Location	<b>Received Date</b>	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
				senior management and foreman to explain the conditions and requirements listed on the CNP and delegated one Engineer to ensure all construction activities and PMEs to be used are fully complying with CNP and legislation requirements before the commencement of the construction activities during the restricted hour.	
				Base on the information collected, regular noise Monitoring was conducted during the night time to check the noise levels are complying with the construction noise criteria. The noise levels measured at NC3 during the construction works at night time were well below the construction noise limit.	
				The Contractor was reminded to strengthen their site supervision by delegated Engineer to ensure all construction activities and PMEs to be used are fully complying with CNP and legislation requirements and implement necessary noise mitigation measures as	

Log Ref.	Location	<b>Received Date</b>	Details of Complaint	Investigation/Mitigation Action	Status
				recommended in the Approved EIA report to minimize and avoid the construction noise impact to the residents nearby especially during the restricted hours.	
COM-2009-04-030	Construction site at Western Portal	30 April 2009	Complaint of Construction Noise Generated at Night at Western Portal.	_	
COM-2009-05-031		4 May 2009	Complaint of low frequency noise emitted from the construction site at Western Portal.	gantries were the activities conducted in the night of 30 April 2009.  In accordance with the night time	
		11 May 2009	Complaint of Construction Noise nuisance generated from the Western Portal Site from day to night.	visit on 15 May 2009, the noise levels at Aegean Terrace was not high but with occasionally sound of locomotive and tower crane operations.	Closed
				No exceedance of noise level was recorded since the commencement of the project works at Western Portal Site. The noise levels measured at NC3 during the construction works were well below the construction noise limit.	
				The Contractor will continue	

Log Ref.	Location	Received Date	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
				implementing their mitigation measures (e.g. Instruct workers not to shout during work in the evening; no horn signal of locomotive after 6:55 pm).	
COM-2009-05-032	Construction site at Eastern Portal	13 May 2009	The complaint was lodged by a resident regarding the Construction Noise Nuisance from the construction works that were carried out from early morning till night time at Eastern Portal Site Area.	Based on the information collected, the noise levels measured at NC1/NC1a and NC2 during the	Closed
COM-2009-06-035	Hong Kong West Drainage Tunnel Construction Site at Cyberport	3 June 2009	EPD received a public complaint raised by local resident regarding the transportation and disposal of construction wastes from Hong Kong West Drainage Tunnel Construction Site at Cyberport on 3 June 2009.	alternative disposal ground is proposed by The Contractor and they have been submitted the relevant information and sought the approval from Supervising Officer. The	Closed

Log Ref.	Location	<b>Received Date</b>	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
COM-2009-06-038	Construction site at Eastern Portal	23 June 2009	The few noise complaints were lodged by a resident of The Legend and Ronsdale Garden regarding the Construction Noise Nuisance from the construction works at Eastern Portal Site Area since 7:00a.m and in the afternoon.  The complaint was raised by a representative of Goodwell Property Management, she wrote on behalf of the Estate Owner Committe of Legend at Tai Hang about noise nuisance arising from the excacvation works at Eastern Portal site portion. The Committe requested the Contractor to provide mitigation measures to mininise the impact.	Based on the information collected, the noise levels measured at NC1 and NC2 during the construction works were well below the construction noise limit or baseline level.  In response to the complaints, the head of hydraulic breaker has been wrapped with sound proof materials and movable noise barriers were provided for rock excavation to reduce noise.	Closed
COM-2009-08-040	Construction site at Intake PFLR1	26 August 2009	the noise generated from the construction activities of breaking of the existing boundary wall of Pokfulam	Honey Court for the Intake PFLR1 was submitted and no exceedance	Closed

Log Ref.	Location	Received Date	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
			the hand-held electric breaker.	at Intake PFLR1, no observation/non-compliance on air quality was identified. The environmental conditions of the site will be continuously reviewed and monitored.  DNJV had installed tarpaulin shielding and cover to mitigate not only the potential emission of exhausted smoke, but also the visual impact to the residents nearby.	
COM-2009-09-042	Construction site at Eastern Portal	21 September 2009	The complaint was raised by a resident of The Legend regarding poor housekeeping and construction noise nuisance from the Eastern Portal Site Area.	Based on the information gathered in the Investigation, the Contractor had taken action immediately to rectify the complaint of poor housekeeping. The white site office was painted green in harmony with the surrounding environment and the site was maintained in a clean and tidy condition. All materials required for temporary works were stored in an orderly manner.  Regarding the complaint of construction noise impact, the noise levels measured at The Legend	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
				(NC2) during the construction works in the normal working hours were well below the construction noise limit level.  Nevertheless, the Contractor is also committed to implementing sufficient noise mitigation measures as recommended in the approved	
				EIA report to minimize the nuisance caused to the nearby residents and provide training for the workers to increase awareness of their environmental responsibilities.	
COM-2009-10-044  COM-2009-10-045	Construction site at Eastern Portal	6 and 7 October 2009	The complaint was raised by a resident of The Legend and Ronsdale Garden regarding the construction noise nuisance from the Eastern Portal Site Area.	Based on the information gathered in the Investigation, the noise levels measured (additional noise monitoring) at The Legend (NC2) and Ronsdale Garden during the construction works including rock breaking works and soil nailing works were ranged from 68.4dB(A) to 75.3 dB(A) in the normal working hours.	Closed
				The Contractor is committed to implementing sufficient noise mitigation measures as	

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
				recommended in the approved EIA report to minimize the nuisance caused to the nearby residents and provide training for the workers to increase awareness of their environmental responsibilities.  It is recommended to increase the construction noise monitoring frequency for Eastern Portal Site to check the mitigation effectiveness.	
COM-2009-11-054	Construction site at Western Portal	23 and 29 November 2009	The complaint was raised by a resident of Aegean Terrace regarding the construction noise nuisance from the Western Portal Site Area.	the noise levels measured at NC3 during the construction works were	Closed

Log Ref.	Location	Received Date	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
COM-2009-12-059	Construction site at Intake MB16	27 November 2009	The complaint was received on 2 November 2009 regarding the dust nuisance caused by the works at the Construction Site at Mount Butler Road near Clementi Road (Intake MB16). EPD subsequently issued a notice of complaint.	Based on the information collected, the Contractor has implemented the dust suppression measures to prevent dust nuisance from the construction activities.  During the site inspection in November 2009, slope improvement works including soil nailing works were observed from other construction site adjacent to DNJV's construction works at Mount Butler Road.	Closed
COM-2009-12-061	Construction site at Intake PFLR1	23 and 28 December 2009	Two public complaints were received from the resident of Pok Fu Lam Road on 23rd and 28th December 2009 respectively about the construction noise nuisance from the construction site at Intake PFLR 1.	Based on the information gathered in the Investigation, the noise levels measured at Honey Court (NC11) during the construction works were well below the construction noise limit.  The location of the designated noise monitoring station (NC11 – Honey Court) is at location close to the construction site compared with Pok Fu Lam Height.  In addition, a large scale innovation works being undertaken at a resident building adjacent to the Pok Fu Lam Height was observed during the	Closed

Log Ref.	Location	Received Date	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
				routine site inspection. The innovation works included hammering and drilling on the outer walls of the building and contributed significantly to the noisy environment.	
COM-2010-01-062	Construction site at Western Portal	3 January 2010	The public complaint was received from the resident of Bel-Air through the project hotline on 3rd January 2010 about "wooing" sound heard after midnight, and he suspected that the sound was coming the construction sites at Cyberport.	Base on the information collected, the noise levels measured at NC3 during the construction works were well below the baseline level. The	Closed
COM-2010-01-063 COM-2010-01-066(1), (2) and (3)	Intake MB16	20 January 2010 23, 25, 27 January and 2 February 2010	The first complaint was raised by the resident at No. 58 Mount Butler Road about the noise and vibration generated from the works on 20 January 2010.  Three complaints were raised	Based on the EIA assessment results, No. 58 Mount Butler Road and Amber Lodge are not the potential ground borne noise sensitive receivers as they are not within the influence zone near the Main Tunnel alignments from Cyberport to Tai	Closed

Log Ref.	Location	<b>Received Date</b>	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
			by the resident of Amber Lodge through the Project Hotline regarding the low frequent vibration from underground on 23, 25, 27 January and 2 February 2010.	The additional ground borne noise levels measured at inside Amber	
				The Contractor volunteered to stop the operation of the East TBM between midnight and 07:00 hours in Week 6 and 7 after which the machine has moved far away from these premises	
COM-2010-02-073	Western Portal	3 February 2010	Complaint of noise generated by the operation of plants, rock falling and flash lighting within Western Portal site area.	the noise levels measured at NC3 during the construction works were	
				The Contractor will continue implementing the existing noise mitigation measures at the Western Portal to minimize the environmental impact to the nearby residents.	Closed
COM-2010-03-080	Intake PFLR1	1 March 2010		the Investigation, the noise levels	Closed

Log Ref.	Location	<b>Received Date</b>	Details of Complaint	Investigation/Mitigation Action	Status
			noise nuisance from the construction site at Intake PFLR 1	dB(A). The noise levels were marginally below the 75dB (A) limit level.	
				The contractor was reminded to implement necessary mitigation measures to curb inducing contribution to the surrounding noise environment.	
COM-2010-03-081	Intake TP789	5 March 2010	The complaint was received from Kerry Management Ltd. on 5th March 2010 about the construction noise complaints raised by some tenants of Tavistock. They complained about the noisy activities being carried out at Intake TP789 on Saturday.	Based on the information gathered in the investigation, the noise levels measured at Tregunter Path near Tavistock were below the construction noise limit and the Contractor has already implemented the noise mitigation measures to reduce noise impact to the residents arising from the construction works.  Nevertheless, we reminded the Contractor to closely monitor the effective implementation of the existing noise mitigation measures at Intake TP789. Review the effectiveness of the implemented noise mitigation measures from time to time during different construction phases.	Closed

Log Ref.	Location	Received Date	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
COM-2010-03-082 and COM-2010-03-087	Western Portal	6 March 2010 15 March 2010	Two public complaints were received from the residents of Bel-Air at Western Portal on 6th and 15th March 2010 about the Construction Noise and Dust Nuisance from Hong Kong West Drainage Tunnel Construction Site at Cyberport (i.e. Western Portal Site) respectively.	Based on the information collected, the noise and air quality levels measured at NC3 and AQ2/AQ3 during the construction works were below the noise and air quality criteria respectively. Also, the Contractor has implemented appropriate environmental mitigation measures on site to reduce noise and dust impact to the residents arising from the construction works.  Nevertheless, the Contractor was reminded to review the effectiveness of the implemented noise and air quality mitigation measures from time to time during different construction phases.	Closed
COM-2010-04-094	Western Portal	9 April 2010	The public complaint was received by EPD hotline on 9 <sup>th</sup> April 2010 regarding construction dust nuisance from the Hong Kong West Drainage Tunnel construction site at Cyberport (i.e. Western Portal Site)	the air quality levels measured at AQ2 and AQ3 during the construction works were below the	Closed

Log Ref.	Location	<b>Received Date</b>	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
				AQ3 were below the air quality criteria, we advised the Contractor to maintain the existing air quality mitigation measures, to reduce the environmental impact on the nearby residents.  Nevertheless, the Contractor was reminded to review the existing measures if such measures are enough and appropriate to suit the site condition from time to time during different construction phases to minimize the dust nuisance.	
COM-2010-04-097	Intake TP789/TP4	22 April 2010	The complaint was received from resident of Tregunter Tower on 22 <sup>nd</sup> April 2010 about the noisy activities being carried out at Intake TP789/TP4 in the morning.	Based on the information gathered in the investigation, the noise levels measured at Tregunter Path near Tavistock were below the construction noise limit and the Contractor has further improved the noise mitigation measures to reduce noise impact to the residents arising from the noise generation works.  The Contractor agreed to reschedule the starting time of the noisy works to 9:00am on in the morining that no noisy works such as rock breaking	Closed

Log Ref.	Location	<b>Received Date</b>	Details of Complaint	Investigation/Mitigation Action	Status
				will be conducted before 9:00am. In addition, enclosures consist of noise absorption blankets have been applied for enclosing Intakes construction areas to minimize the noise nuisance to the nearest residents.	
COM-2010-04-100	Western Portal	30 April 2010	The public complaint was received from the resident of Bel-Air on 30 <sup>th</sup> April 2010 regarding the dust nuisance generated during loading / unloading operation from two barges at pier of Cyberport. Dark smoke was also emitted from the two barges.	Based on the information collected, the air quality levels measured at	Closed

Log Ref.	Location	<b>Received Date</b>	Details of Complaint	Investigation/Mitigation Action	Status
COM-2010-05-105	Western Portal	7 May 2010	The second complaint was received via EPD Hotline on 7 May 2010. The anonymous complainant concerned about the dark smoke emitted from the barges on 4 May 2010 and many dump trucks parking outside the Western Portal Site on 5, 6 and 7 May	air quality criteria.  Although the air quality levels measured at AQ2 and AQ3 were below the air quality	
COM-2010-05-105 (2)		17 May 2010	The complaint was received via EPD Hotline on 17 May 2010. The anonymous complainant complaint about the open stockpile of dusty materials without covered entirely.	mitigation measures and review the existing measures if such measures are enough and appropriate to suit the site condition from time to time during different construction phases to minimize the dust nuisance.  Other suitable dust control measures as stipulated in the Air Pollution Control (Construction Dust) Regulation, where appropriate,	Closed
				Nevertheless, the Contractor is also committed to take sufficient dust mitigation measures as recommended in the approved EIA report including	

Log Ref.	Location	<b>Received Date</b>	Details of Complaint	Investigation/Mitigation Action	Status
				installation of 3-sided curtain-like enclosure at the conveyor discharge point to the barge to minimize the dust nuisance on the nearby residents.	
COM-2010-06-113	Intake PFLR1	2 June 2010	The complaint was received by DSD on 2 June 2010 regarding siren sound was generated from the site throughout the day which caused nuisance.	the alert system of the backhoe during operation. The backhoe was	Closed
	Western Portal	15 June 2010	A public complaint was received by EPD hotline on 15th June 2010 complained about the construction works from Hong Kong West Drainage Tunnel construction site at Cyberport (i.e. Western Portal Site) affect their health of respiratory system	the air quality levels measured at AQ2 and AQ3 during the construction works were below the Action Level (321µg/m3 for 1 hour TSP and 156µg/m3 for 24 hour TSP). Also, the Contractor has	Closed
COM-2010-07-121	Western Portal	15 July 2010	Cyberport Management Office lodged a complaint in	DNJV has delivered the reply letter to Cyberport Management Office on	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
			writing regarding the sands and mud left by the dump	, ,	
			trucks on Cyberport road	liquid of granite powder. Stain on the	
				road was caused by heavy rainstorm	
				which brings moisture to granite	
				powder in trucks.	
				The trucks have been equipped with	
				tailor-made tanks to receive the	
				liquid of granite powder. To prevent	
				reoccurrence, DNJV will reinforce	
				checking of these tanks and other truck conditions at work site to	
				ensure no dripping before departure.	
				ensure no dripping before departure.	
				In this regard, the Contractor was	
				reminded that all vehicles and plant	
				should be cleaned before leaving the	
				construction site to ensure no earth,	
				mud and debris or other wastes is	
				deposited on roads. Proper	
				maintenance of the tailor-made tanks	
				equipped at the trucks is also needed to avoid any leakage.	
COM-2010-07-123 (1)	Eastern Portal	2 August 2010	The complaint was received		
CON1-2010-07-123 (1)	Lastelli Foltal	2 August 2010	through the Project Hotline	· ·	Closed
			regarding the noise generated		C105 <b>C4</b>
			from construction vehicles.	construction works were well below	

Log Ref.	Location	<b>Received Date</b>	Details of Complaint	Investigation/Mitigation Action	Status
COM-2010-07-123 (2)		2 August 2010	The complaint was received by DSD concerning the noise generated from construction site at 19:00.		
COM-2010-08-125		3 August 2010	The complaint was received by DSD concerning the noise generated from construction site until 8:00 pm every night.	implement sufficient noise mitigation measures as recommended in the approved EIA report to minimize the nuisance caused to the nearby residents especially during the restricted hours.	
COM-2010-08-124	Intake TP789/TP4	2 August 2010	The complaint was received by DSD regarding the construction works at Tregunter Path is extremely noisy and diminishes the ability of residents of the neighborhood to enjoy outdoor facilities	the investigation, the noise levels at Tregunter Tower was within the construction noise limit of 75dB(A).	Closed
COM-2010-08-124 (con'd)		5 August 2010	The complaint was received by DSD regarding the construction works at Tregunter Path is extremely noisy and diminishes the ability of residents of the neighborhood to enjoy outdoor facilities	as below:  - Properly maintained and operated the construction plant (well-greased, damage and worn parts promptly replaced)	
COM-2010-08-129		12 August 2010	The complaint was raised by the resident of Tregunter Path for the noisy works which	mitigate noise generated by the	

Log Ref.	Location	<b>Received Date</b>	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
			was carried out after 18:00hrs at Intake TP4	working period at Tregunter Path starting from 13th August 2010 as below:	
COM-2010-08-129		12 August 2010	The complaint was received from Protech Property Management Limited (the building manager of Tregunter Tower, 14 Tregunter Path, Mid-Levels, Hong Kong) regarding the noisy construction works at Tregunter Path	Monday – Friday: 08:00hrs to 18:00hrs Saturday: 08:30hrs to 18:00hrs Sunday and Public Holiday: No Works	
COM-2010-08-129 (2)		13 August 2010	The complaint was received by RSS concerning the noisy work from the construction site on Saturday		
COM-2010-10-151	Eastern Portal	15 October 2010	A complaint was received from the resident of The Legend through the supervising officer on 15th October 2010 about the construction dust nuisance from Eastern Portal Site Area.	Based on the information gathered in the investigation, no exceedance of air quality level was recorded at AQ1 since the commencement of the project works for Eastern Portal Site.  The potential source of air quality impact arising from the removal of tunneling spoils from the tunnel portals as well as the vehicular emissions is minimized as all TBM excavation works have been completed since 5 October 2010.	Closed

Log Ref.	Location	Received Date	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
COM-2010-10-154	Eastern Portal	18 October 2010	A complaint was received from the resident of Ronsdale Garden through the DSD on 18th October 2010 about the construction noise nuisance from Eastern Portal Site Area.  According to the complainant, the noise seems to be generated by a pump.	Based on the information gathered in the investigation, the noise levels measured at The Legend (NC2) and outside True Light Middle School of Hong Kong (NC1) were well below the limit level.  The Contractor agreed to terminate the operation of pump during the evening (1900 – 2300) and night	Closed
COM-2010-10-155	Intake RR1	11 October 2010	A letter from the Property Management of Peaksville Court - Hong Yip Service Company Ltd was received by DNJV on 11th October 2010 about the construction noise nuisance and wastewater generated from Intake RR1 Site Area.	the investigation, the noise levels measured at Peaksville Court (NC13) and Ying Wa Girl's School (NC12) were below the baseline/limit level. In addition, water runoff was observed leaked out to the public	Closed

Log Ref.	Location	<b>Received Date</b>	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
				with sandbag as early as possible.	
COM-2010-11-160	Intake TP789	5 November 2010	The complaint was received from Kerry Property Management and advised that some complaints from the residents of Tavistock about low frequency noise generated by the power pack within Site Portion TP789.	Based on the information gathered in the investigation, the noise levels measured at near Intake TP789 were	Closed
COM-2010-11-160(2)	Intake TP789	9 November 2010	Some residents complained the low frequency noise after the addition of sound proof sheets on the power pack at Intake TP789.	generation activities.	
COM-2010-11-163	Western Portal	6 November 2010	A complaint was received from a complainant regarding noise nuisance caused by spoils dropping directly from conveyor belt into barge (rock hitting sound) at Western Portal.	Based on the information gathered in the investigation, the noise levels	Closed
COM-2010-11-163(2)	Western Portal	7 November 2010	A complaint was received from a complainant regarding noise nuisance caused by spoils dropping from conveyor belt into storage basin (rock hitting sound).  The complainant also		Closed

Log Ref.	Location	<b>Received Date</b>	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
			complained the noise of ventilation fans at the Western Portal area.		
COM-2010-11-164	Intake TP5  Intake TP5	10 November 2010  15 and 17 November 2010	Kerry Property Management Services received several complaints from the residents of Valverde on 10 November 2010 morning regarding working noise emitted from the Intake TP5 work site in early morning (before 7:30am).  Kerry Property Management Ltd phoned DSD at about 17:08 hrs on 15 November 2010 relaying some complaints from the residents of Valverde about the noise/vibration due to the blasting works in past weeks. Jennifer also requested DNJV not to carry out blasting works at nights.	Base on the information collected, the ad-hoc noise monitoring results measured at near Valverde was met the acceptable noise levels. Drill and blast is not considered with respect to noise annoyance, as the duration of blasting is very short and infrequent.  The Contractor volunteered to cancel late blasts and scheduling all blasts	Closed
COM-2010-12-170	Intake DG1	7 December 2010	The complaint was received regarding the noise arising from the excavation works, starting from 9:00 hrs, in the construction site near Evergreen Villa of Stubbs	the Investigation, the noise levels measured at NC4 and NC6 in November and December 2010 were below the construction noise limit	Closed

Log Ref.	Location	<b>Received Date</b>	Details of Complaint	Investigation/Mitigation Action	Status
			Road.	The Contractor has taken initiative to erect noise absorption blankets at the site boundary to minimize noise nuisance to the nearby residents.  The Contractor was reminded to review the effectiveness of the implemented noise mitigation measures from time to time during	
COM-2010-12-171	Intake MB16	8 December 2010	The complainant complained the works near Mount Butler Road generated dust, thus affecting the air quality in the vicinity.	different construction phases.  DNJV would arrange water spraying at the entrance of Area B. In addition, Environmental Team and RSS would closely monitor to ensure relevant measures are effectively implemented.	Closed
COM-2010-12-173	Intake W5	14 December 2010	A complaint was received from a complainant regarding noisy construction activities at Site Portion W5 had affected her niece's study to prepare for examination.	DSD are now constructing an intake at the subject site under Hong Kong West Drainage Tunnel project. The construction work at Site Portion is expected for completion in end 2011. At the moment, the pipe piling works have been completed and the Contractor will carry out grouting work in this week and then excavation work afterwards. The noise generated by excavation works should be less than that of pipe piling	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
				works. Nevertheless, DSD would closely monitor the works in order to mitigate the noise impact to the nearby residents.	
COM-2010-12-178	Intake TP5	22 December 2010	Kerry Property Management Ltd notified that some complaints from the residents regarding the early commencement of the noise works at Intake Ste TP5 (earlier than 08:00hrs) in the past few days.	December 2010, they would carry out the work at site portion TP5 from 08:00 hrs to 19:00 hrs. Eddie Yau, DNJV Public Relation Manager had already explained to Kerry about the	Closed
COM-2010-12-179	Eastern Portal	24 December 2010	The Property Management Office of The Legend referred the complaint from the resident to DSD regarding the intermediate noise from Eastern Portal site portion in the morning and at night.	Based on the information gathered in the investigation, the noise levels measured at NC1 and NC2 were below the limit level.	Closed
COM-2011-01-181	Eastern Portal	21 January 2011	The Property Management Office of Legend called DNJV to reflect a resident's concern on early construction noise at 8:30am on Saturday.	Based on the information gathered in the investigation, the noise levels measured at NC1 and NC2 were below the limit level.  The breaking work to be completed by that day.	Closed
COM-2011-02-186	Intake GL1	18 February 2011	A complaint was received from the resident of Green Lane through the ICC on 18th February 2011 about the	Based on the information gathered in the investigation, the noise levels	

Log Ref.	Location	Received Date	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
			construction noise generated from the plant equipments being operated at Intake GL1 from early in the morning and ends at around 19:00 at night.	noise limit. However, the Contractor has already implemented the noise mitigation measures to reduce noise impact. The major noise source due to the raise boring works has been finished since 26th February 2011	
COM-2011-02-188	Western Portal	25 February 2011	The complaint was received from the resident of Bel Air who called hotline at 3am and 4pm on 25 Feb 2011 to complaint about noise. The complainant refuses to give details on the nosie. He claims that he will report this to the Police and requested DNJV to provide him with copy of CNP.	Based on the information gathered in the investigation, the noise levels measured at NC3 was below the limit level.	Closed
COM-2011-03-189	Western Portal	7 March 2011	Property management office of Aigburth and Valverde transferred noise complaints of residents about the vibration and early working noise emitting from the TP5 and TP789. DNJV replied to explain to the PMO.	Aigburth and Valverde about the	Closed
COM-2011-03-190	Western Portal	7 March 2011	The complaint was received from the resident of Aegean	Based on the information gathered in the investigation, the noise levels	Closed

Log Ref.	Location	<b>Received Date</b>	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
COM-2011-03-193 (1)	Western Portal	14 March 2011	Terrace who complained about the night-time noise of		
COM-2011-03-193 (2)	Western Portal	16 March 2011	Western Portal. DNJV would review the works during the restricted hours and further improve the enclosure where necessary.	However, the Contractor has already implemented the noise mitigation measures to reduce noise impact.	
COM-2011-03-192	Intake B2	14 March 2011	The PMO of Grand House at Macdonnell Road complained about the construction noise at the intake B2. In the site portion, rock excavation works was being carried out. The works was anticipated to complete in end April 2011.	$\mathcal{E}$	Closed
COM-2011-03-195	Intake CR1	28 March 2011	The complaint was received from the resident of Conduit Tower, who complained about the construction noise at the intake CR1.	Based on the information gathered in the investigation, the noise levels	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
				The Contractor was reminded to	
				review the effectiveness of the	
				implemented noise mitigation	
				measures from time to time during	
				different construction phases.	
COM-2011-05-210	Intake GL1	30 May 2011	The complaint was raised	Based on the information gathered in	
			from the resident of Green	the investigation, the noise levels	
			Lane, who complained about	measured at near Green Lane was	
			the construction noise at the	well below the construction noise	Closed
			intake GL1.	limit.	Closed
				However, the Contractor has already	
				implemented the noise mitigation	
				measures to reduce noise impact.	
COM-2011-05-211	Intake CR1	30 May 2011	The complaint was received	_	
			from the resident of Conduit	2 ,	
			Tower, who complained		
			about the construction noise		
			at the intake CR1. The	The Contractor has taken initiative to	
			complainant mainly	-	
			concerned that the noisy	whole site boundary to minimize	Closed
			works at Intake CR1 started		010500
			at 8:00 hrs everyday is too		
			early. He requested to defer		
			the working hours later.	review the effectiveness of the	
				implemented noise mitigation	
				measures from time to time during	
				different construction phases.	

Log Ref.	Location	<b>Received Date</b>	<b>Details of Complaint</b>	Investigation/Mitigation Action	Status
COM-2011-06-214	Intake P5	2 June 2011		Based on the information gathered in	
			raised on 2 <sup>nd</sup> June 2011 via	the investigation, the noise levels	
			Environmental Protection	measured at near P5 was well below	
			Department (EPD) regarding	the construction noise limit.	
			the construction noise	In addition, the pipe-piling work has	
			nuisance from the Hong	been stopped until the end of July	
			Kong West Drainage Tunnel	2011. However, the Contractor has	
			construction site at Intake P5.	prepared the remedial action that	Closed
				should be taken while starting the	
				pipe-piling work.	
				The Contractor was reminded to	
				review the effectiveness of the	
				implemented noise mitigation	
				measures from time to time during	
				different construction phases.	