
REPORT



Contract No. HY/2017/10 Tuen Mun – Chek Lap Kok Link – Northern Connection Tunnel Buildings, Electrical and Mechanical Works

Twenty-ninth Monthly EM&A Report

11 November 2020

Environmental Resources Management 2507, 25/F One Harbourfront 18 Tak Fung Street Hunghom, Kowloon Hong Kong Telephone 2271 3000



www.erm.com

Facsimile 2723 5660



Contract No. HY/2017/10 Tuen Mun – Chek Lap Kok Link – Northern Connection Tunnel Buildings, Electrical and Mechanical Works

Environmental Resources Management

2507, 25/F One Harbourfront 18 Tak Fung Street Hunghom, Kowloon Hong Kong Telephone: (852) 2271 3000 Facsimile: (852) 2723 5660 E-mail: post.hk@erm.com http://www.erm.com

Twenty-ninth Monthly EM&A Report

Document Code: 0463091_29th Monthly EM&A_20201111.doc

Client:		Project No	0:			
Gammo	n	046309 ⁻	1			
Summary:		Date:				
		11 Nove	ember 20	20		
		Approved	by:			
This document presents the Twenty-ninth Monthly EM&A Report for Tuen Mun – Chek Lap Kok Link – Northern Connection Tunnel Buildings, Electrical and Mechanical Works.			Cif A			
		Mr Crai	g Reid			
		Partner				
		Certified b	oy:			
		Jam				
		Dr Jasn	nine Ng			
		ET Leade	er		1	
	Twenty-ninth Monthly EM&A Report	CW	JN	CAR	11/11/20	
Revision	Description	Ву	Checked	Approved	Date	
This report has been prepared by Environmental Resources Management the trading name of 'ERM Hong-Kong, Limited', with all reasonable skill, care and diligence within the terms of the Contract with the client, incorporating our General Terms and Conditions of Business and taking account of the resources devoted to it by agreement with the client. We disclaim any responsibility to the client and others in respect of any matters outside			Distribution Distribution Internal Public			
the scope of the above.			nfidential		0001 : 2008 e No. FS 32515	





Ref.: HYDHZMBEEM00_0_8267L.20.doc

12 November 2020

By Fax (2783 0155) and By Post

AECOM Asia Company Limited Supervising Officer's Representative Office No. 8 Mong Fat Street, Tuen Mun, New Territories, Hong Kong

Attention: Mr. Desmond Fung

Dear Mr. Fung,

Re: Agreement No. CE 48/2011 (EP) Environmental Project Office for the HZMB Hong Kong Link Road, HZMB Hong Kong Boundary Crossing Facilities, and Tuen Mun-Chek Lap Kok Link – Investigation

Contract No. HY/2017/10 TM-CLKL – Northern Connection Tunnel Buildings, E&M Works 29th Monthly EM&A Report for October 2020

Reference is made to the Environmental Team's submission of the monthly EM&A report for October 2020 (ET's ref.: "0463091_29th Monthly EM&A_20201111.doc" dated 11 November 2020) certified by the ET Leader and provided to us via e-mail on 11 November 2020.

Please be informed that we have no adverse comments on the captioned submission. We write to verify the captioned submission in accordance with Condition 4.4 of EP-354/2009/D.

Thank you for your attention. Please feel free to contact the undersigned or the ENPO Leader, Mr. Y H Hui, should you require further information.

Yours sincerely, For and on behalf of Ramboll Hong Kong Limited

Manson Yeung Independent Environmental Checker Tuen Mun-Chek Lap Kok Link

c.c.

HyD	Mr. Patrick Ng	(By Fax: 3188 6614)
HyD	Mr. Francis Chan	(By Fax: 3188 6614)
AECOM	Mr. Conrad Ng	(By Fax: 3922 9797)
ERM	Dr. Jasmine Ng	(By Fax: 2723 5660)
Gammon	Mr. Max Poon	(By Fax: 3520 0486)

Internal: DY, YH, ENPO Site

 $\label{eq:projects} Q:\Projects\HYDHZMBEEM00\02_Proj_Mgt\02_Corr\HYDHZMBEEM00_0_8267L.20.doc.doc$

TABLE OF CONTENTS

EXECUTIVE SUMMARY

1	INTRODUCTION	1
1.1	BACKGROUND	1
1.2	Scope of Report	2
1.3	ORGANIZATION STRUCTURE	2
1.4	SUMMARY OF CONSTRUCTION WORKS	2
2	EM&A RESULTS	4
2.1	AIR QUALITY	4
2.2	LANDFILL GAS HAZARD MONITORING	5
2.3	EM&A SITE INSPECTION	6
2.4	WASTE MANAGEMENT STATUS	7
2.5	ENVIRONMENTAL LICENSES AND PERMITS	8
2.6	IMPLEMENTATION STATUS OF ENVIRONMENTAL MITIGATION MEASURES	10
2.7	SUMMARY OF EXCEEDANCES OF THE ENVIRONMENTAL QUALITY PERFORMAN	ICE
	Limit	10
2.8	SUMMARY OF COMPLAINTS, NOTIFICATION OF SUMMONS AND SUCCESSFUL	
	PROSECUTIONS	10
3	FUTURE KEY ISSUES	11
3.1	CONSTRUCTION ACTIVITIES FOR THE COMING MONTH	11
3.2	Key Issues for the Coming Month	11
4	CONCLUSIONS AND RECOMMENDATIONS	12
4.1	Conclusions	12

I

List of Appendices

- Appendix A Project Organization for Environmental Works
- Appendix B Construction Programmes
- Appendix C Implementation Schedule of Environmental Mitigation Measures (EMIS)
- Appendix D Summary of Action and Limit Levels
- Appendix E Event Action Plan
- Appendix F EM&A Monitoring Schedule
- Appendix G Calibration Certificate of Monitoring Equipment
- Appendix H Landfill Gas Monitoring Results and Graphical Presentation
- Appendix I Monthly Summary of Waste Flow Table
- Appendix J Cumulative Statistics on Exceedances, Complaints, Notifications of Summons and Successful Prosecutions

Under *Contract No. HY/2017/10*, Gammon Construction Limited (GCL) is commissioned by the Highways Department (HyD) to undertake Northern Connection Tunnel Buildings, Electrical and Mechanical Works of the Tuen Mun – Chek Lap Kok Link Project (TM-CLK Link Project) while AECOM Asia Company Limited was appointed by HyD as the Engineer. For implementation of the environmental monitoring and audit (EM&A) programme under the Contract, ERM-Hong Kong, Limited (ERM) has been appointed as the Environmental Team (ET) in accordance with *Environmental Permit No. EP-354/2009/A*. Ramboll Hong Kong Ltd. was employed by HyD as the Independent Environmental Checker (IEC) and Environmental Project Office (ENPO). Subsequent applications for variation of environmental permits (VEP), *EP-354/2009/B*, *EP-354/2009/C* and *EP-354/2009/D*, were granted on 28 January 2014, 10 December 2014 and 13 March 2015, respectively.

The construction phase of the Contract commenced on 7 June 2018 and will tentatively be completed by 2021. The impact monitoring of the EM&A programme, including air quality and environmental site inspections, were commenced on 7 June 2018.

This is the Twenty-ninth Monthly EM&A report presenting the EM&A works carried out during the period from 1 to 31 October 2020 for the *Contract No. HY*/2017/10 Northern Connection Tunnel Buildings, Electrical and Mechanical Works (the "Contract") in accordance with the Updated EM&A Manual of the TM-CLK Link Project. As informed by the Contractor, major activities in the reporting period included:

Land-based Works

- Handover Inspection at Main Control Building;
- Handover Inspection at Ventilation Plant Room;
- Handover Inspection at North Ventilation Building;
- Handover Inspection at Administration Building;
- Handover Inspection at Maintenance Depot;
- Handover Inspection at Fire Services Department Building;
- Handover Inspection at Customs and Excise Department Building;
- Handover Inspection at N1;
- Handover Inspection at Kiosk N2;
- T&C and FSI at the Tunnel;

- Handover Inspection at underpass at C3 area;
- Handover Inspection at Satellite Control Building;
- Handover Inspection at Kiosk S2;
- Handover Inspection at South Ventilation Building; and
- Landscape Works at Northern Landfall and Southern Landfall.

A summary of monitoring and audit activities conducted in the reporting period is listed below ⁽¹⁾:

24-hour TSP Monitoring	5 sessions
1-hour TSP Monitoring	5 sessions
Landfill Gas Hazard Monitoring	24 days
Joint Environmental Site Inspection	4 sessions

Summary of Breaches of Action/Limit Levels

Breaches of Action and Limit Levels for Air Quality

Four (4) Action Level exceedances for 1-hour TSP were recorded by the Environmental Team of Contract No. *HY/2012/08* during the reporting period. No exceedance of Action and Limit Levels for 24-hour TSP were recorded.

Breaches of Action Level for Landfill Gas Hazard Montioring

Results of landfill gas hazard monitoring in the reporting month complied with the Action Level.

Environmental Complaints, Non-compliance & Summons

There was no environmental complaint, notification of summons or successful prosecution recorded in the reporting period.

Reporting Change

Landscape and visual monitoring for 24-month establishment period conducted by Contract No. HY/2012/07 and HY/2013/12 was not reported in the EM&A report for this Contract in this reporting period.

Upcoming Works for the Next Reporting Month

Works to be undertaken in the next monitoring period of November 2020 include the following:

ET justification on the Contract Specific Environmental Monitoring and Audit activities under this Contract was submitted to ENPO on 11 September 2018

Land-based Works

- Handover Inspection at Main Control Building;
- Handover Inspection at Ventilation Plant Room;
- Handover Inspection at North Ventilation Building;
- Handover Inspection at Administration Building;
- Handover Inspection at Maintenance Depot;
- Handover Inspection at Fire Services Department Building;
- Handover Inspection at Customs and Excise Department Building;
- Handover Inspection at N1;
- Handover Inspection at Kiosk N2;
- T&C and FSI at the Tunnel;
- Handover Inspection at underpass at C3 area;
- Handover Inspection at Satellite Control Building;
- Handover Inspection at Kiosk S2;
- Handover Inspection at South Ventilation Building; and
- Landscape Works at Northern Landfall and Southern Landfall.

Future Key Issues

Potential environmental impacts arising from the above upcoming construction activities in the next reporting month of November 2020 are mainly associated with dust, waste management and landfill gas monitoring issues.

1.1 BACKGROUND

According to the findings of the Northwest New Territories (NWNT) Traffic and Infrastructure Review conducted by the Transport Department, Tuen Mun Road, Ting Kau Bridge, Lantau Link and North Lantau Highway would be operating beyond capacity after 2016. This forecast has been based on the estimated increase in cross boundary traffic, developments in the Northwest New Territories (NWNT), and possible developments in North Lantau, including the Airport developments, the Lantau Logistics Park (LLP) and the Hong Kong – Zhuhai – Macao Bridge (HZMB). In order to cope with the anticipated traffic demand, two new road sections between NWNT and North Lantau – Tuen Mun – Chek Lap Kok Link (TM-CLKL) and Tuen Mun Western Bypass (TMWB) are proposed.

An Environmental Impact Assessment (EIA) of TM-CLKL (the Project) was prepared in accordance with the EIA Study Brief (No. ESB-175/2007) and the *Technical Memorandum of the Environmental Impact Assessment Process (EIAO-TM*). The EIA Report was submitted under the Environmental Impact Assessment Ordinance (EIAO) in August 2009. Subsequent to the approval of the EIA Report (EIAO Register Number AEIAR-146/2009), an Environmental Permit (EP-354/2009) for TM-CLKL was granted by the Director of Environmental Protection (DEP) on 4 November 2009, and EP variation (VEP) (EP-354/2009/A) was issued on 8 December 2010. Subsequent applications for variation of environmental permits (VEPs), *EP-354/2009/B, EP-354/2009/C* and *EP-354/2009/D*, were granted on 28 January 2014, 10 December 2014 and 13 March 2015, respectively.

Under *Contract No. HY/2017/10*, Gammon Construction Limited (GCL) is commissioned by the Highways Department (HyD) to undertake the Northern Connection Tunnel Buildings, Electrical and Mechanical Works of TM-CLKL while AECOM Asia Company Limited was appointed by HyD as the Engineer. For implementation of the environmental monitoring and audit (EM&A) programme under the Contract, ERM-Hong Kong, Limited (ERM) has been appointed as the Environmental Team (ET). Ramboll Hong Kong Ltd. was employed by HyD as the Independent Environmental Checker (IEC) and Environmental Project Office (ENPO).

The construction phase of the Contract commenced on 7 June 2018 and will be tentatively completed by 2021. The impact monitoring phase of the EM&A programme, including air quality and environmental site inspections, commenced on 7 June 2018.

The general layout plan of the Contract components is presented in *Figures 1.1* & *1.2a to c.*





PROJECT

TUEN MUN -CHEK LAP KOK LINK

CONTRACT TITLE TUEN MUN - CHEK LAP KOK LINK - NORTHERN CONNECTION TUNNEL BUILDINGS, ELECTRICAL AND MECHANICAL WORKS CLIENT





CONSULTANT

AECOM Asia Company Ltd. www.aecom.com

SUB-CONSULTANTS 分月工作新闻公司

Figure 1.1

ISSUE/REVISION

-			Kul
Α	JAN.18	TENDER ADDENDUM NO.1	SYLC
	DEC.17	TENDER DRAWING	SYLC
I/R	DATE	DESCRIPTION 内容摘要	CHK.

STATUS

SCALE

DIMENSION UNIT

A1 1:40000

MILLIMETRES

KEY PLAN

PROJECT NO.

CONTRACT NO.

60240249

HY/2017/10

SHEET TITLE

OVERALL SITE PLAN

SHEET NUMBER

60240249/C4/7051A





PROJECT

TUEN MUN -CHEK LAP KOK LINK

CONTRACT TITLE

TUEN MUN - CHEK LAP KOK LINK - NORTHERN CONNECTION TUNNEL BUILDINGS, ELECTRICAL AND MECHANICAL WORKS

CLIENT



CONSULTANT

AECOM Asia Company Ltd. www.aecom.com

SUB-CONSULTANTS 公用工程即開会可

Figure 1.2a

ISSUE/REVISION

			<u> </u>
			-
			Kerl
А	JAN.18	TENDER ADDENDUM NO.1	SYLC
-	DEC.17	TENDER DRAWING	SYLC
/R 修訂	DATE 山翔	DESCRIPTION 內容摘要	CHK. 後株

STATUS

SCALE

DIMENSION UNIT

KEY PLAN

MILLIMETRES

PROJECT NO.

CONTRACT NO. HY/2017/10

60240249


SHEET TITLE

ZONING PLAN

(SHEET 1)

SHEET NUMBER

60240249/C4/7061A





 \wedge

Ν

TUEN MUN -CHEK LAP KOK LINK

CONTRACT TITLE

TUEN MUN - CHEK LAP KOK LINK - NORTHERN CONNECTION TUNNEL BUILDINGS, ELECTRICAL AND MECHANICAL WORKS

CLIENT ^{業主}



■▲■ 路 政 署 HIGHWAYS DEPARTMENT 港珠澳大橋香港工程管理處 Hong Kong - Zhuhai - Macao Bridge Hong Kong Project Management Office

CONSULTANT 工程顧問公司

AECOM Asia Company Ltd. www.aecom.com

SUB-CONSULTANTS 分判工程顧問公司

Figure 1.2b

ISSUE/REVISION

修訂	日期	内容摘要	複核
I/R	DATE	DESCRIPTION	СНК.
-	DEC.17	TENDER DRAWING	SYLC
А	JAN.18	TENDER ADDENDUM NO.1	SYLC
			sterel

STATUS 階段

SCALE ^{比例}	DIMENSION UNIT ^{尺寸單位}
1 1:2500	MILLIMETRES

KEY PLAN 索引圖

PROJECT NO. 項目編號

CONTRACT NO. ^{合約編號}

60240249

HY/2017/10

SHEET TITLE 圖紙名稱

ZONING PLAN (SHEET 2)

SHEET NUMBER 圖紙編號

60240249/C4/7062A





PROJECT

Ν

TUEN MUN -CHEK LAP KOK LINK

CONTRACT TITLE

TUEN MUN - CHEK LAP KOK LINK - NORTHERN CONNECTION TUNNEL BUILDINGS, ELECTRICAL AND MECHANICAL WORKS

CLIENT ^{業主}



■▲■ 路政署 HIGHWAYS DEPARTMENT 港珠澳大橋香港工程管理處 Hong Kong - Zhuhai - Macao Bridge Hong Kong Project Management Office

CONSULTANT 工程顧問公司

AECOM Asia Company Ltd. www.aecom.com

SUB-CONSULTANTS 分判工程顧問公司

Figure 1.2c

ISSUE/REVISION

			sterel
А	JAN.18	TENDER ADDENDUM NO.1	SYLC
-	DEC.17	TENDER DRAWING	SYLC
I/R 修訂	DATE 日期	DESCRIPTION 內容摘要	CHK. 複核

STATUS 階段

SCALE ^{比例}	DIMENSION UNIT 尺寸單位
1 1:2500	MILLIMETRES

KEY PLAN 索引圖

PROJECT NO. 項目編號

CONTRACT NO. ^{合約編號}

HY/2017/10

60240249

SHEET TITLE 圖紙名稱

ZONING PLAN (SHEET 3)

SHEET NUMBER 圖紙編號

60240249/C4/7063A

1.2 SCOPE OF REPORT

This is the Twenty-ninth Monthly EM&A Report under the *Contract No. HY*/2017/10 *Tuen Mun* – *Chek Lap Kok Link* – *Northern Connection Tunnel Buildings, Electrical and Mechanical Works.* This report presents a summary of the environmental monitoring and audit works in October 2020.

1.3 ORGANIZATION STRUCTURE

The organization structure of the Contract is shown in *Appendix A*. The key personnel contact names and contact details are summarized in *Table 1.1* below.

Party	Position	Name	Telephone	Fax
HyD (Highways Department)	Project Coordinator	Joseph Lee	2762 4958	3188 6614
. ,	Senior Engineer	Cheng Pan	2762 3383	3188 6614
ER (AECOM Asia Company Limited)	Principle Resident Engineer	S. W. Fok	2293 6200	2293 6300
	Resident Engineer	Desmond Fung	2293 6200	2293 6300
ENPO / IEC (Ramboll Hong Kong	ENPO Leader	Y.H. Hui	3465 2850	3465 2899
Ltd.)	IEC	Manson Yeung	9700 6767	3465 2899
Contractor (Gammon	Site Agent	H. H. Lee	6096 6281	-
Construction Limited)	Environmental Officer	Phoebe Ng	9869 1105	-
ET (ERM-HK)	ET Leader	Dr. Jasmine Ng	2271 3311	2723 5660

Table 1.1Contact Information of Key Personnel

1.4 SUMMARY OF CONSTRUCTION WORKS

The construction phase of the Contract commenced on 7 June 2018. The three-month rolling construction programme is shown in Appendix B.

As informed by the Contractor, details of the major works carried out in this reporting month are listed below:

Land-based Works


- Handover Inspection at Main Control Building;
- Handover Inspection at Ventilation Plant Room;
- Handover Inspection at North Ventilation Building;


- Handover Inspection at Administration Building;
- Handover Inspection at Maintenance Depot;
- Handover Inspection at Fire Services Department Building;
- Handover Inspection at Customs and Excise Department Building;
- Handover Inspection at N1;
- Handover Inspection at Kiosk N2;
- T&C and FSI at the Tunnel;
- Handover Inspection at underpass at C3 area;
- Handover Inspection at Satellite Control Building;
- Handover Inspection at Kiosk S2;
- Handover Inspection at South Ventilation Building; and
- Landscape Works at Northern Landfall and Southern Landfall.

The locations of the construction activities are shown in *Figure 1.3*. The Environmental Sensitive Receivers in the vicinity of the Contract are shown in *Figure 1.4*.

The implementation schedule of environmental mitigation measures is presented in *Appendix C*.

Figure 1.3 Locations of Major Construction Activities in the Reporting Month





2 EM&A RESULTS

The EM&A programme required environmental monitoring for air quality and environmental site inspections for air quality, water quality and waste management. The EM&A requirements and related findings for each component are summarized in the following sections

2.1 AIR QUALITY

2.1.1 Monitoring Requirements and Equipment

In accordance with the Updated EM&A Manual and the Enhanced TSP Monitoring Plan, impact 1-hour TSP monitoring was conducted three (3) times every six (6) days and impact 24-hour TSP monitoring was carried out once every six (6) days when the highest dust impact was expected. 1-hr and 24hr TSP monitoring frequency was increased to three times per day every three days and daily every three days, respectively, as excavation works for launching shaft under *Contract No. HY/2012/08 Tuen Mun-Chek Lap Kok Link – Northern Connection Sub-sea Tunnel Section* commenced on 24 October 2014.

Informed by the Environmental Team of *Contract No. HY/2012/08 Tuen Mun-Chek Lap Kok Link – Northern Connection Sub-sea Tunnel Section*, excavation works for lauching shaft were completed and notification of change on air quality monitoring frequency was submitted to EPD on 14 September 2020. 1-hr and 24-hr TSP monitoring frequency was changed to three times per day every six days and daily every six days, respectively, since 14 September 2020.

Results of air quality monitoring were adopted from the published EM&A data of *Contract No. HY/2012/08 Tuen Mun-Chek Lap Kok Link – Northern Connection Sub-sea Tunnel Section* ⁽¹⁾.

The Action and Limit Levels of the air quality monitoring were adopted from the published EM&A reports of *Contract No. HY/2012/08 Tuen Mun-Chek Lap Kok Link – Northern Connection Sub-sea Tunnel Section* ⁽²⁾. The Action and Limit Levels are provided in *Appendix D*.

The locations of the monitoring stations overlapped with Contract No. HY/2012/08 are shown in *Figure 2.1* and presented in *Table 2.1*.

Table 2.1Locations of Impact Air Quality Monitoring Stations and its Corresponding
Monitoring Requirements

Monitoring Station Monitoring Dates Location Description Parameters & Frequency

 Published EM&A data for impact air quality monitoring by Contract No. HY/2012/08 are available at: http://www.hzmbenpo.com/

(2) Published EM&A reports of Contract No. HY/2012/08 are available at: http://www.hzmbenpo.com/

Monitoring Station	Monitoring Dates	Location	Description	Parameters & Frequency
ASR1	5, 9, 15, 21 and 27	Tuen Mun	Office	TSP monitoring
	October 2020	Fireboat Station		 1-hour Total Suspended
				Particulates (1-hour TSP,
ASR5		Pillar Point Fire	Office	μ g/m ³), 3 times in every 6 days
		Station		• 24-hour Total Suspended
				Particulates (24-hour TSP,
AQMS1		Previous River	Bare ground	μ g/m ³), daily for 24-hour in
		Trade Golf		every 6 days
				Enhanced TSP monitoring
ASR6		Butterfly Beach	Office	(commenced on 24 October 2014
		Laundry		under Contract No. HY/2012/08)
				 1-hour Total Suspended
ASR10		Butterfly Beach	Recreational	Particulates (1-hour TSP,
		Park	uses	μ g/m ³), 3 times in every 3 days
				• 24-hour Total Suspended
				Particulates (24-hour TSP,
				μ g/m ³), daily for 24-hour in
				every 3 days

2.1.2 Results and Observations

Results of air quality monitoring were adopted from the published EM&A data of *Contract No. HY/2012/08 Tuen Mun-Chek Lap Kok Link – Northern Connection Sub-sea Tunnel Section* ⁽¹⁾.

Four (4) Action Level exceedances for 1-hour TSP were recorded by the Environmental Team of Contract No. *HY/2012/08* during the reporting period. No exceedance of Action and Limit Levels for 24-hour TSP were recorded. The exceedance was considered not related to this Contract upon further investigation and the investigation report is presented in *Appendix J*. No action is required to be undertaken in accordance with the Event Action Plan as presented in *Appendix E*.


2.2 LANDFILL GAS HAZARD MONITORING

In accordance with the Updated EM&A Manual of the TM-CLK Link Project, landfill gas hazard monitoring should be perform to ensure that the works area at Pillar Point Valley (PPV) Landfill is free of landfill gas. A total of 24 days of landfill gas hazard monitoring was conducted at Main Control Building during 1 to 31 October 2020 (*Appendix F*).

The landfill gas hazard monitoring was conducted in accordance to the Upated EM&A Manual with a Altair 5X Gas Detector. The calibration certificate for the equipment is presented in *Appendix G*.

The Action Level of the landfill gas hazard monitoring was adopted from the Updated EM&A Manual of the TM-CLK Link Project and are provided in Appendix D.

 Published EM&A data for impact air quality monitoring by *Contract No. HY/2012/08* are available at: http://www.hzmbenpo.com/
 ENVIRONMENTAL RESOURCES MANAGEMENT



2.2.1 **Results and Observations**

Results for landfill gas hazard monitoring are summarized in Table 2.2 and the monitoring data is provided in *Appendix H*.

Results of methane, oxygen and carbon dioxide in the reporting month complied with the Action Level. No action as stated in the Updated EM&A Manual of the TM-CLK Link Project and presented in Appendix D is required to be undertaken.

Table 2.2 Summary of Landfill Gas Hazard Monitoring Results in the Reporting Period

	Average (%)	Range (%)	Action Level (%) (a)
Methane	0	0	10/20
Oxygen	20.8	20.8-20.8	19/18
Carbon Dioxide	0.03	0.03-0.03	0.5/1.5

Notes

(a) Depending on the results of the measurements, actions required will vary. Actions in the event of landfill gas being detected in excavation/confined area was adopted from the Updated EM&A Manual of the TM-CLK Link Project.

2.3 EM&A SITE INSPECTION

Site inspections were carried out on a weekly basis to monitor the implementation of proper environmental pollution control and mitigation measures under the Contract. In the reporting month, four (4) site inspections were carried out on 9, 16, 23 and 30 October 2020.

Key observations and recommendations during the site inspections in this reporting period are summarized in Table 2.3.

Table 2.3 Specific Observations and Recommendations during the Weekly Site Inspection in this Reporting Month

Inspection Date	Observations	Recommendations/ Remarks
9 October 2020	 Satellite Control Building Chemical was observed not placed in trip tray. Cement was not properly covered. Accumulated residual was observed on site. Tunnel Chemical was observed not placed in trip tray. Container Village Accumulated residual was observed on site. Contstruction site should be watered regularly to reduce dust emission. 	 Satellite Control Building The Contractor was reminded to place chemical in trip tray. The Contractor was reminded to cover the cement properly. The Contractor was reminded to clear accumulated residuals. Tunnel The Contractor was reminded to place chemical in trip tray. Container Village The Contractor was reminded to clear accumulated residuals.
16 October 2020	Administration BuildingAccumulated general refuse was observed on site.	Administration BuildingThe Contractor was reminded to clear accumulated refuse.

Inspection Date	Observations	Recommendations/ Remarks
23 October 2020	Northern Landfall	Northern Landfall
	 Chemicals were observed not placed in trip 	The Contractor was reminded to place
	tray.	chemicals in trip tray.
	 General residuals were observed on site. 	 The Contractor was reminded to keep
	Satellite Control Building	better housekeeping.
	 Chemicals were observed not placed in trip 	Satellite Control Building
	tray.	 The Contractor was reminded to place
	 Excessive dust emission was observed on 	chemicals in trip tray
	site.	 The Contractor was reminded to water
	Administration Building	the road more frequently.
	 Chemicals were observed not placed in trip 	Administration Building
	tray.	 The Contractor was reminded to place
		chemicals in trip tray.
30 October 2020	Southern Landfall	Southern Landfall
	• Nil.	• Nil.

The Contractor has rectified all of the observations as identified during environmental site inspections in the reporting month.

2.4 WASTE MANAGEMENT STATUS

The Contractor had submitted application form for registration as chemical waste producer under the Contract. Sufficient numbers of receptacles were available for general refuse collection and sorting.

Wastes generated during this reporting period included mainly construction wastes (inert and non-inert). Reference has been made to the waste flow table prepared by the Contractor (*Appendix I*). The quantities of different types of wastes are summarized in *Table 2.4*.

Table 2.4Quantities of Different Waste Generated in the Reporting Month

Month/Year	Inert C&D Materials ^(a) (m ³)	Inert Construction Waste Re- used (m ³)	Non-inert Construction Waste ^(b) (kg)	Imported Fill (m³)	Recyclable Materials ^(c) (kg)	Chemical Wastes (kg)
October 2020	210	0	184,460	0	0	0
	Notes:					
	• •			and large broken co al refuse disposed a	-	s public fill.

(c) Recyclable materials include metals, paper, cardboard, plastics, timber and others.

The Contractor was advised to properly maintain on site C&D materials and waste collection, sorting and recording system, dispose of C&D materials and wastes at designated ground and maximize reuse/ recycle of C&D materials and wastes. The Contractor was also reminded to properly maintain the site tidiness and dispose of the wastes accumulated on site regularly and properly.

For chemical waste containers, the Contractor was reminded to treat properly and store temporarily in designated chemical waste storage area on site in accordance with the *Code of Practice on the Packaging, Labelling and Storage of Chemical Wastes.*

2.5 Environmental Licenses and Permits

The status of environmental licensing and permit is summarized in *Table 2.5* below.

License/ Permit	License or Permit No.	Date of Issue	Date of Expiry	License/ Permit Holder	Remarks
Environmental Permit	EP-354/2009/D	13 March 2015	N/A	HyD	Tuen Mun- Chek Lap Kok Link
APCO Construction Dust	433493	14 May 2018	N/A	GCL	For Tuen Mun working area
Notification					
Construction Waste Billing	7030836	15 May 2018	N/A	GCL	N/A
Account					
Chemical Waste Producer	5213-422-G2827-01	13 June 2018	N/A	GCL	N/A
Registration					
Discharge License under	WT00031783-2018	22 October 2018	31 October 2023	GCL	Sampling Frequency: Bimonthly
WPCO for Buildings at C2					
area					
Discharge License under	WT00032062-2018	30 October 2018	31 October 2023	GCL	Sampling Frequency: Quarterly
WPCO for Buildings at C3					
area					
Discharge License under	WT00034878-2019	1 April 2020	31 March 2025	GCL	Sampling Frequency: Quarterly
WPCO for Southern					
Landfall					
Construction Noise Permit	GW-RW0351-20	3 August 2020	29 January 2021	GCL	For Northern Landfall and Tunnel
Construction Noise Permit	GW-RS0413-20	19 June 2020	15 December 2020	GCL	For HKBCF Area

Table 2.5Summary of Environmental Licensing and Permit Status

2.6 IMPLEMENTATION STATUS OF ENVIRONMENTAL MITIGATION MEASURES

In response to the site audit findings, the Contractors carried out all corrective actions.

A summary of the Implementation Schedule of Environmental Mitigation Measures (EMIS) is presented in *Appendix C*. The necessary mitigation measures relevant to this Contract were implemented properly.

The landscape and visual (L&V) mitigation measures were also monitored on weekly basis in the reporting period. The monitoring status is summarized in *Appendix C*.

2.7 SUMMARY OF EXCEEDANCES OF THE ENVIRONMENTAL QUALITY PERFORMANCE LIMIT

One (1) Action Level exceedance for 1-hour TSP was recorded by the Environmental Team of Contract No. *HY*/2012/08 during the reporting period. No exceedance of Action and Limit Levels for 24-hour TSP were recorded.

Results of landfill gas hazard monitoring in the reporting month complied with the Action Level.


Cumulative statistics are provided in *Appendix J*.

2.8 SUMMARY OF COMPLAINTS, NOTIFICATION OF SUMMONS AND SUCCESSFUL PROSECUTIONS

The Environmental Complaint Handling Procedure is provided in Figure 2.2.

There was no environmental complaint, notification of summons or successful prosecution recorded in the reporting period.

Statistics on complaints, notifications of summons, successful prosecutions are summarized in *Appendix J*.



3 FUTURE KEY ISSUES

3.1 CONSTRUCTION ACTIVITIES FOR THE COMING MONTH

As informed by the Contractor, the major works for the Contract in November 2020 will be:

Land-based Works

- Handover Inspection at Main Control Building;
- Handover Inspection at Ventilation Plant Room;
- Handover Inspection at North Ventilation Building;
- Handover Inspection at Administration Building;
- Handover Inspection at Maintenance Depot;
- Handover Inspection at Fire Services Department Building;
- Handover Inspection at Customs and Excise Department Building;
- Handover Inspection at N1;
- Handover Inspection at Kiosk N2;
- T&C and FSI at the Tunnel;
- Handover Inspection at underpass at C3 area;
- Handover Inspection at Satellite Control Building;
- Handover Inspection at Kiosk S2;
- Handover Inspection at South Ventilation Building; and
- Landscape Works at Northern Landfall and Southern Landfall.

3.2 KEY ISSUES FOR THE COMING MONTH

Potential environmental impacts arising from the above upcoming construction activities in the next reporting month of November 2020 are mainly associated with dust, waste management and landfill gas monitoring issues.

4 CONCLUSIONS AND RECOMMENDATIONS

4.1 CONCLUSIONS

This Twenty-ninth Monthly EM&A Report presents the findings of the EM&A activities undertaken during the period from 1 to 31 October 2020, in accordance with the Updated EM&A Manual and the requirements of EP-354/2009/D.

Air quality (including 1-hour TSP and 24-hour TSP) monitoring were carried out in this reporting month.

Four (4) Action Level exceedances for 1-hour TSP were recorded by the Environmental Team of Contract No. *HY/2012/08* during the reporting period. No exceedance of Action and Limit Levels for 24-hour TSP were recorded.

Results of landfill gas hazard monitoring in the reporting month complied with the Action Level.


Environmental site inspection was carried out four (4) times in October 2020. Remedial actions recommended for the deficiencies identified during the site audits were properly implemented by the Contractor.

Landscape and visual monitoring for 24-month establishment period conducted by Contract No. HY/2012/07 and HY/2013/12 was not reported in the EM&A report for this Contract in this reporting period.

There was no environmental complaint, notification of summons or successful prosecution recorded in the reporting period.

The ET will keep track on the construction works to confirm compliance of environmental requirements and the proper implementation of all necessary mitigation measures. Appendix A

Project Organization for Environmental Works




Appendix B

Construction Programme

ID		Activity	Duration	Activity %	Start	Finish	Total					•				
			(Days)	Complete			Float	2018		on Oct		Ion E	Mor Apr N	201		
	UV2017/10 Works Drogromme	Phree Month Rolling Programme 20-Oct-20						/ay Jun Ju		ep Ocl		Jan F	Mar Apr N	/ay Jun	Jui Au	g 5 00
		e Three Month Rolling Programme 20-Oct-20														
	Contract Dates											-				
	Key Dates											-				
	KD08	KD08 - All Other Works for Tunnel Comissioning & Opening	0	0%			0									
	KD09	KD09 - C&ED Building, E&M Works, & FSD Inspection	0	0%			-72									
	KD10	KD10 - FSD Building, E&M Works, & FSD Inspection	0	0%			-133									
	KD11	KD11 - Landscape Soft Works & Trees Protection	0	0%			-30									
	Portion Possession Dates															
	P325	Possession to Portion XXII (Day 483)	0	0%			-73									
	P335	Possession to Portion XXIII (Day 483)	0	0%			-73					-				
	Portion Handover Dates															
	H120	Vacate Portion XVIb (KD10+28)	0	0%			-106									
	H130	Vacate Portion XVIa (KD10+28)	0	0%			-106									
	H140	Vacate Portion XVb (KD9+28)	0	0%			-45									
	H150	Vacate Portion XVa (KD9+28)	0	0%			-45									
	H160	Vacate Portion XXIa (KD8+28)	0	0%			0									
	H170	Vacate Portion XXIb (KD8+28)	0	0%			0									
	H180	Vacate Portion XXII (KD8+28)	0	0%			0									
	H190	Vacate Portion XXIII (KD8+28)	0	0%			0									
	H200	Vacate Portion XII (KD8+28)	0	0%			0					-				
	H210	Vacate Portion XIII (KD8+28)	0	0%			0									
	H220	Vacate Portion XIV (KD8+28)	0	0%			0					-				
	H230	Vacate Portion XVIIa (KD8+28)	0	0%			0									
	H240	Vacate Portion Ve (KD8+28)	0	0%			0									
	H250	Vacate Portion Vc (KD8+28)	0	0%			0									
	H260	Vacate Portion VIb (KD8+28)	0	0%			0									
	H270		0	0%			0									
		Vacate Portion VIII (KD8+28)	-	0%			0									
	H280	Vacate Portion XI (KD8+28)	0	0%			0									
	H290	Vacate Portion VII (KD8+28)	-													
	H300	Vacate Portion IX (KD8+28)	0	0%			0									
	H310	Vacate Portion X (KD8+28)	0	0%			0									
	H320	Vacate Portion XXIc (KD8+28)	0	0%			0					1				
	H330	Vacate Portion WA6 (KD8+28)	0	0%			0									
	H340	Vacate Portion XIX (KD11+28)	0	0%			-3									
	Major Design Submission & Ap															
	Major Material Submission & A	pproval										1				
	Drawing Submission & Approv	al								: :		1				
	General Procurement											-				
-	Key Date 1 - Toll Control Buildin	g (TCB) & TCSS Provision														
í	ABWF Works (for All)															
	ATCB1130	ABWF second fix & final fix	90	95%			-15									
		ilding, Maintenance Depot, Kiosk N2, TCSS Provision														
	Administration Building (ADB)															
	ABWF Works (for All)															
	AADB1200	ABWF second fix & final fix	90	98%			1									_
	Maintenance Depot		50	50%			'									
	· ·															
	ABWF Works (for All) AMD1070	ABWF second fix & final fix	80	97%			1					-				
			00	97%			1									
		Iministration Building, Maintenance Depot, North Vent Building, Kiosk N2														
	Remaining Works											·····	·			
	KD6-OSW-1000	Remaining Works (Non FSI related)	42	95%			-16									
	Key Date 3 - Satellite Control Bu	illding & TCSS Provision														
	ABWF Works (for All)															
	ASCB1020	ABWF Works to Plant Rooms G/F	60	100%			1									
	ASCB1070	ABWF second fix & final fix	56	95%			1									
	Key Date 5 - E&M Works for TC	B, Toll Area, Kiosk N1, Underpass, Plant Rm, and Approach Roads														
	E&M Works for TCB															
	Remaining Works for TCB (N	Ion-FSI related)														
	KD5-OSW-1000	Remaining Works (Non FSI related)	42	95%			-15									
								i	· · ·	i	· · ·					
					CONTRA	ACT NO. HY201	7/10									Р
1																

TM-CLKL NORTHERN CONNECTION TUNNEL BUILDINGS, E&M WORKS

THREE MONTHLY PROGRAMME AS OF 20 Oct 2020




ID	Activity	Duration	Activity % S	tart Finish	Total										
		(Days)	Complete		Float		2018							2019	
						Vlay J	n Jul	Aug Se	p Oct	N Dec	Jan	F Mar A	pr May J	un Jul /	Aug S Oc
Approach Roads															
Under Portions IX, XI, XX						-									
AR150	T&C of Roading Lighting	30	80%		-1										
Under Portion X															
AR200	T&C of Roading Lighting in portion X	30	80%		-1										
Key Date 7 - E&M Works for Sa	atellite Control Building and Kiosks S1&S2														
E&M Works for Satellite Control	ol Building														
E&M Works															
Remaining Works for SC	CB (Non-FSI related)														
KD7-OSW-1010	Remaining Works (Non-FSI related)	42	95%		1										
Key Date 6C - E&M Works for S	South Ventilation Building														
Remaining Works for SVB (Nor	n-FSI related)														
KD6C-OSW-1000	Remaining Works (Non-FSI related)	42	95%		-24										
Key Date 6A - E&M Works for A	Approach Roads at North Side														
Approach Roads															
EAR140	T&C & Miscellaneous Works for Statutory Inspection	12	0%		-75										
Key Date 10 - FSD Building Stru		12	0,0		10										
ABWF Works	ADIME Motion to Office and Carridom O/F	404	000/		450	-									
AFSD1030	ABWF Works to Office and Corridors G/F	124	99%		-158										
AFSD1031	ABWF Works to Office and Corridors 1/F	124	99%		-158										
AFSD1060	External Cladding and Wall Plastering	101	95%		-114										
AFSD1070	ABWF second fix & final fix	73	90%		-114										
E&M Works															
Testing and Commissioning															
FSDB-TC1030	Non-Essential T&C	30	100%			1									
Statutory Inspections and ap	oprovals														
FSDB-SI1060	WSD inspection of Plumbing Installation (PL)	4	0%		-162										
FSDB-SI1080	Water Samples Test	24	0%		-162	-									
FSDB-SI1100	Obtain Water Certificate and water supply connection - PL	4	0%		-162										
FSDB-SI1140	KD10 Achieved	0	0%		-162										
Key Date 7A - E&M Works for A			0,0		102	1									
	Approach Noaus at south side														
Approach Roads	740	10	50%		0										
EAR200	T&C	12	50%		0										
Tunnel															
Remaining Works for Tunne															
A1010	Remaining Works (Non FSI related)	98	90%		-24										
Key Date 9 - C&ED Building & E	&M Works														
ABWF Works															
ACED1020	ABWF Works to Plant Rooms G/F	60	85%		-84										
ACED1021	ABWF Works to Plant Rooms 1/F	60	85%		-84										
ACED1022	ABWF Works to Plant Rooms 2/F	60	85%		-84										
ACED1023	ABWF Works to Plant Rooms 3/F	60	85%		-84										
ACED1030	ABWF Works to Office and Corridors G/F	133	95%		-73										
ACED1031	ABWF Works to Office and Corridors 1/F	118	85%		-73										
ACED1031	ABWF Works to Office and Corridors 2/F	130	85%		-70	-									
ACED1032 ACED1033	ABWF Works to Office and Corridors 3/F	92	85%		-70	-									
ACED1040	ABWF Works to Toilets G/F	142	95%		-68										
ACED1041	ABWF Works to Toilets 2/F	142	95%		-66										
ACED1042	ABWF Works to Toilets 3/F	98	99%		-66										
ACED1060	External Cladding and Wall Plastering	97	80%		-70										
ACED1070	ABWF second fix & final fix	69	80%		-73										
E&M Works															
Testing and Commissioning															
C&EDB-TC1030	Non-Essential T&C	24	95%		-73										
Statutory Inspections and ap															
C&EDB-SI1030	Obtain DG Licence	0	100%												
C&EDB-SI1060	WSD inspection of Plumbing Installation (PL)	4	0%		-84						++				
C&EDB-SI1080	Water Samples Test	24	100%		-04	-									
C&EDB-SI1080	Obtain Water Certificate and water supply connection - FS	4	0%		-70										
	Obtain water Gertindate and water supply connection - FS	4	U%		-70	-	1				<u> </u>				
				CONTRACT NO. HY201	7/10										Р

CONTRACT NO. HY2017/10

TM-CLKL NORTHERN CONNECTION TUNNEL BUILDINGS, E&M WORKS

THREE MONTHLY PROGRAMME AS OF 20 Oct 2020




	Activity	Duration	Activity %	Start Finish	Total		- 00	10				 					2040	
		(Days)	Complete		Float	May	20 Jun	Jul	Aug	Sen	Oct	ec Jar	F	Mar	Apr	Mav	2019 un J	Mu.
C&EDB-SI1100	Obtain Water Certificate and water supply connection - PL	4	0%		-84		ourr	our	/ ug	ocp		0 00		Ivici	1.61	vicy o		ug
C&EDB-SI1110	Final Submission of Form FSI 314 / 501 to FSD	0	100%															
C&EDB-SI1120	FSD Inspection	28	100%									 						
C&EDB-SI1130	Obtain FSI Certificate FS 172	0	0%		-77													
Key Date 11 - Landscape Soft	t Works & Trees Protection																	
Landscape Soft Works																		
SL120	Landscape Soft Works at North Side (wet season)	122	82.79%		-46													
SL140	Landscape Soft Works at South Side (wet season)	102	65.69%		-60							 						
SL550	KD 11 Achieved	0	0%		-58													
	nnel Comissioning & Opening	-																
Statutory Inspections and ap																		
Administration Building											-			-				
ADB-SI1070	Obtain Water Certificate and water supply connection - PL	4	0%		7							 						
ADB-SI1120	EMSD examines site acceptance report and acceptance	36	100%															
Maintenance Depot			10070															
MD-SI1100	Obtain Water Certificate and water supply connection - PL	4	0%		7													
North Ventilation Building			070															
NVB-SI1130	Water Samples Test	24	50%		-17							 						
NVB-SI1140	Obtain Water Certificate and water supply connection - PL	4	0%		-17													
Petrol Filling Station		· · ·	0,0								1							
PFS-SI1030	DG Inspection	18	0%		-13													
PFS-SI1040	Obtain DG Licence	0	0%		-13													
Toll Control Building & Tol			070		10							 						
TCB-SI2020	WSD inspection of Plumbing Installation (PL)	4	0%		-41													
TCB-SI2040	Water Samples Test	24	0%		-41													
TCB-SI2050	Obtain Water Certificate and water supply connection - PL	4	0%		-41													
TCB-SI3010	EMSD examines site acceptance report and acceptance	36	50%		-7													
Satellite Control Building			0070									 						
SCB-SI1100	Obtain Water Certificate and water supply connection - PL	1	100%															
South Ventilation Building		· · ·																
SVB-SI1140	Obtain Water Certificate and water supply connection - PL	4	100%															
Tunnel		•																
TNL-10TC2010	FSD inspection & re-inspection	42	100%									 						
TNL-10TC2020	Obtain Fire Certificate	0	0%		-1									-				
Others Works for Road Oper	ning		-															
OW175	Operation Verifications and Trial	18	0%		-45													
Key Date 12 - Establishment	•																	
EW110	Establishment Works	365	0%		-91							 						

CONTRACT NO. HY2017/10

TM-CLKL NORTHERN CONNECTION TUNNEL BUILDINGS, E&M WORKS

THREE MONTHLY PROGRAMME AS OF 20 Oct 2020



Appendix C

Environmental Mitigation and Enhancement Measure Implementation Schedules

(In reference to CINOTECH (2011) Agreement No. CE35/2011 EP Baseline Environmental Monitoring for Hong Kong-Zhuhai-Macao Bridge Tuen Mun-Chep Lap Kok Link – Investigation. Updated EM&A Manual for Tuen Mun-Chek Lap Kok Link)

Contract No. HY/2017/10 Tuen Mun – Chek Lap Kok Link Northern Connection Tunnel Buildings, Electrical and Mechancial Works Environmental Mitigation and Enhancement Measure Implementation Schedule

EIA Reference	EM&A Manual	Environmental Protection Measures	Location/ Timing	Implementation Agent	Relevant Standard or Requirement	Imp	lementa Stages	tion	Status *
	Reference					D	С	0	
Air Quality 4.8.1	3.8	Watering of the construction sites in Lantau for 8 times/day and in Tuen Mun for 12 times/day to reduce dust emissions by 87.5% and 91.7% respectively and shall be undertaken.		Contractor	TMEIA Avoid dust generation		Y		~
4.8.1	3.8	The Contractor shall, to the satisfaction of the Engineer, install effective dust suppression measures and take such other measures as may be necessary to ensure that at the Site boundary and any nearby sensitive receiver, dust levels are kept to acceptable levels.	construction period	Contractor	TMEIA Avoid dust generation		Y		✓
4.8.1	3.8	The Contractor shall not burn debris or other materials on the works areas.	All areas / throughout construction period	Contractor	TMEIA Avoid dust generation		Y		✓
4.8.1	3.8	In hot, dry or windy weather, the watering programme shall maintain all exposed road surfaces and dust sources wet.	All unpaved haul roads / throughout construction period in hot, dry or windy weather	Contractor	TMEIA Avoid smoke impacts and disturbance		Y		~
4.8.1	3.8	Where breaking of oversize rock/concrete is required, watering shall be implemented to control dust. Water spray shall be used during the handling of fill material at the site and at active cuts, excavation and fill sites where dust is likely to be created.		Contractor	TMEIA Avoid dust generation		Y		N/A
4.8.1	3.8	Open dropping heights for excavated materials shall be controlled to a maximum height of 2m to minimise the fugitive dust arising from unloading.	, 0	Contractor	TMEIA Avoid dust generation		Y		N/A
4.8.1	3.8	During transportation by truck, materials shall not be loaded to a level higher than the side and tail boards, and shall be dampened or covered before transport.		Contractor	TMEIA Avoid dust generation		Y		N/A
4.8.1	3.8	Materials having the potential to create dust shall not be loaded to a level higher than the side and tail boards, and shall be covered by a clean tarpaulin. The tarpaulin shall be properly secured and shall extend at least 300mm over the edges of the side and tail boards.	construction period	Contractor	TMEIA Avoid dust generation		Y		N/A
4.8.1	3.8	No earth, mud, debris, dust and the like shall be deposited on public roads. Wheel washing facility shall be usable prior to any earthworks excavation activity on the site.		Contractor	TMEIA Avoid dust		Y		~

Legend: D=Design, C=Construction, O=Operation

Contract No. HY/2017/10 Tuen Mun – Chek Lap Kok Link Northern Connection Tunnel Buildings, Electrical and Mechancial Works Environmental Mitigation and Enhancement Measure Implementation Schedule

EIA Reference	EM&A	Environmental Protection Measures	Location/ Timing	Implementation	Relevant Standard	-	mentation	Status *
	Manual Reference			Agent	or Requirement	D	tages C O	-
4.8.1	3.8	Areas of exposed soil shall be minimised to areas in which works have been completed shall be restored as soon as is practicable.	All exposed surfaces / throughout construction period	Contractor	TMEIA Avoid dust generation		Ŷ	v
4.8.1	3.8	All stockpiles of aggregate or spoil shall be enclosed or covered and water applied in dry or windy condition.	All areas / throughout construction period	Contractor	TMEIA Avoid dust generation		Y	N/A
4.11	Section 3	EM&A in the form of 1 hour and 24 hour dust monitoring and site audit.	All representative existing ASRs / throughout construction period	Contractor	EM&A Manual		Y	N/A (Results adopted from published EM&A data of Contract No. HY/2012/08)
WATER QUAL	ITY (LAND V							
6.10	-	Wastewater from temporary site facilities should be controlled to prevent direct discharge to surface or marine waters.	construction period	Contractor	TM-EIAO		Y	N/A
6.10	-	Sewage effluent and discharges from on- site kitchen facilities shall be directed to Government sewer in accordance with the requirements of the WPCO or collected for disposal offsite. The use of soakaways shall be avoided.	All areas/ throughout construction period	Contractor	TM-EIAO		Y	*
6.10	-	Storm drainage shall be directed to storm drains via adequately designed sand/silt removal facilities such as sand traps, silt traps and sediment basins. Channels, earth bunds or sand bag barriers should be provided on site to properly direct stormwater to such silt removal facilities. Catchpits and perimeter channels should be constructed in advance of site formation works and earthworks.	All areas/ throughout construction period	Contractor	TM-EIAO		Y	
6.10	-	Silt removal facilities, channels and manholes shall be maintained and any deposited silt and grit shall be removed regularly, including specifically at the onset of and after each rainstorm.	, 0	Contractor	TM-EIAO		Y	1
6.10	-	Temporary access roads should be surfaced with crushed stone or gravel.	All areas/ throughout construction period	Contractor	TM-EIAO		Y	~
6.10	-	Rainwater pumped out from trenches or foundation excavations should be discharged into storm drains via silt removal facilities.	All areas/ throughout construction period	Contractor	TM-EIAO		Y	N/A
6.10	-	Measures should be taken to prevent the washout of construction materials, soil, silt or debris into any drainage system.	All areas/ throughout construction period	Contractor	TM-EIAO		Y	~
6.10	-	Open stockpiles of construction materials (e.g. aggregates and sand) on site should be covered with tarpaulin or similar fabric during rainstorms.	All areas/ throughout construction period	Contractor	TM-EIAO		Y	N/A
6.10	5.8	Manholes (including any newly constructed ones) should always be adequately covered and temporarily sealed so as to prevent silt, construction materials or debris from getting into the drainage system, and to prevent storm run-off from getting into foul sewers.	All areas/ throughout construction period	Contractor	TM-EIAO		Y	

Note: Funding Agent for all mitigation measures will be the Highways Department of the Hong Kong SAR Government

EIA Reference	EM&A Manual	1	Location/ Timing	Implementation Agent	Relevant Standard or Requirement	Imp	olementat Stages	tion	Status *
	Reference					D	С	0	
6.10	-	Discharges of surface run-off into foul sewers must always be prevented in order not to unduly overload the foul sewerage system.	All areas/ throughout construction period	Contractor	TM-EIAO		Y		4
6.10	-	All vehicles and plant should be cleaned before they leave the construction site to ensure that no earth, mud or debris is deposited by them on roads. A wheel washing bay should be provided at every site exit.	construction period	Contractor	TM-EIAO		Y		4
6.10	-	Wheel wash overflow shall be directed to silt removal facilities before being discharged to the storm drain.	All areas/ throughout construction period	Contractor	TM-EIAO		Y		✓
6.10	-	Section of construction road between the wheel washing bay and the public road should be surfaced with crushed stone or coarse gravel.	All areas/ throughout construction period	Contractor	TM-EIAO		Y		√
6.10	-	Wastewater generated from concreting, plastering, internal decoration, cleaning work and other similar activities, shall be screened to remove large objects.	All areas/ throughout construction period	Contractor	TM-EIAO		Y		N/A
6.10	-	Vehicle and plant servicing areas, vehicle wash bays and lubrication facilities shall be located under roofed areas. The drainage in these covered areas shall be connected to foul sewers via a petrol interceptor in accordance with the requirements of the WPCO or collected for off site disposal.	construction period	Contractor	TM-EIAO		Y		N/A
6.10	-	The Contractor shall prepare an oil / chemical cleanup plan and ensure that leakages or spillages are contained and cleaned up immediately.		Contractor	TM-EIAO		Y		*
6.10	-	Waste oil should be collected and stored for recycling or disposal, in accordance with the Waste Disposal Ordinance.	All areas/ throughout construction period	Contractor	TM-EIAO Waste Disposal Ordinance		Y		4

EIA Reference	EM&A Manual		Location/ Timing	Implementation Agent	Relevant Standard or Requirement	Imj	plementa Stages	tion	Status *
	Reference					D	C	0	
6.10	-	All fuel tanks and chemical storage areas should be provided with locks and be sited on sealed areas. The storage areas should be surrounded by bunds with a capacity equal to 110% of the storage capacity of the largest tank.	, 0	Contractor	TM-EIAO		Y		\$
6.10	-	Surface run-off from bunded areas should pass through oil/grease traps prior to discharge to the stormwater system.	All areas/ throughout construction period	Contractor	TM-EIAO		Y		N/A
6.10	-	Roadside gullies to trap silt and grit shall be provided prior to discharging the stormwater into the marine environment. The sumps will be maintained and cleaned at regular intervals.	Roadside/design and operation	Design Consultant/ Contractor	TM-EIAO	Y		Y	N/A
6.10	Section 11	All construction works shall be subject to routine audit to ensure implementation of all EIA recommendations and good working practice.	All areas/ throughout construction period	Contractor	EM&A Manual		Y		✓
WASTE									
12.6		The Contractor shall identify a coordinator for the management of waste.	Contract mobilisation	Contractor	TMEIA		Y		1
12.6		The Contractor shall prepare and implement a Waste Management Plan which specifies procedures such as a ticketing system, to facilitate tracking of loads and to ensure that illegal disposal of wastes does not occur, and protocols for the maintenance of records of the quantities of wastes generated, recycled and disposed. A recording system for the amount of waste generated, recycled and disposed (locations) should be established.		Contractor	TMEIA, Works Branch Technical Circular No. 5/99 for the Trip-ticket System for Disposal of Construction and Demolition Material		Y		~
12.6		The Contractor shall apply for and obtain the appropriate licenses for the disposal of public fill, chemical waste and effluent discharges.	Contract mobilisation	Contractor	TMEIA, Land (Miscellaneous Provisions) Ordinance (Cap 28); Waste Disposal Ordinance (Cap 354); Dumping at Sea Ordinance (Cap 466); Water Pollution Control Ordinance.		Y		~
12.6	8.1	Training shall be provided to workers about the concepts of site cleanliness and appropriate waste management procedures including waste reduction, reuse and recycling.		Contractor	TMEIA		Y		4
12.6	8.1	The extent of cutting operation should be optimised where possible. Earth retaining structures and bored pile walls should be proposed to minimise the extent of cutting.		Contractor	TMEIA		Y		4
12.6	8.1	The site and surroundings shall be kept tidy and litter free.	All areas / throughout construction period	Contractor	TMEIA		Y		<>

Legend: D=Design, C=Construction, O=Operation

EIA Reference	EM&A Manual	Environmental Protection Measures	Location/ Timing	Implementation Agent	Relevant Standard or Requirement	Imj	plementa Stages	tion	Status *
	Reference					D	C	0	
12.6	8.1	No waste shall be burnt on site.	All areas / throughout construction period	Contractor	TMEIA		Y		4
12.6	8.1	The Contractor shall be prohibited from disposing of C&D materials at any sensitive locations. The Contractor should propose the final disposal sites in the EMP and WMP for approval before implementation.	construction period	Contractor	TMEIA		Y		✓
12.6	8.1	Stockpiled material shall be covered by tarpaulin and /or watered as appropriate to prevent windblown dust/ surface run off.	All areas / throughout construction period	Contractor	TMEIA		Y		~
12.6	8.1	Excavated material in trucks shall be covered by tarpaulins to reduce the potential for spillage and dust generation.	All areas / throughout construction period	Contractor	TMEIA		Y		4
12.6	8.1	Wheel washing facilities shall be used by all trucks leaving the site to prevent transfer of mud onto public roads.	All areas / throughout construction period	Contractor	TMEIA		Y		1
12.6	8.1	Standard formwork or pre-fabrication should be used as far as practicable so as to minimise the C&D materials arising. The use of more durable formwork/plastic facing for construction works should be considered. The use of wooden hoardings should be avoided and metal hoarding should be used to facilitate recycling. Purchasing of construction materials should avoid over-ordering and wastage.	construction period	Contractor	TMEIA		Y		~

EIA Reference	EM&A Manual	Environmental Protection Measures	Location/ Timing	Implementation Agent	Relevant Standard or Requirement	Im	plementa Stages	tion	Status *
	Reference					D	C	0	
12.6	8.1	The Contractor should recycle as many C&D materials (this is a waste section) as possible on-site. The public fill and C&D waste should be segregated and stored in separate containers or skips to facilitate the reuse or recycling of materials and proper disposal. Where practicable, the concrete and masonry should be crushed and used as fill materials. Steel reinforcement bar should be collected for use by scrap steel mills. Different areas of the sites should be considered for segregation and storage activities.	construction period	Contractor	TMEIA		Y		✓
12.6	8.1	All falsework will be steel instead of wood.	All areas / throughout construction period	Contractor	TMEIA		Y		✓
12.6	8.1	Chemical waste producers should register with the EPD. Chemical waste should be handled in accordance with the Code of Practice on the Packaging, Handling and Storage of Chemical Wastes as follows: <i>f</i> suitable for the substance to be held, resistant to corrosion, maintained in good conditions and securely closed; <i>f</i> Having a capacity of <450L unless the specifications have been approved by the EPD; and w Chinese according to the instructions prescribed in Schedule 2 of the Regulations. <i>f</i> Clearly labelled and used solely for the storage of chemical wastes; <i>f</i> Enclosed with at least 3 sides; <i>f</i> Impermeable floor and bund with capacity to accommodate 110% of the volume of the largest container or 20% by volume of the chemical waste stored in the area, whichever is greatest; <i>f</i> Adequate ventilation;	construction period	Contractor	TMEIA		Y		V

Legend: D=Design, C=Construction, O=Operation

Manual	EM&A Manual	Environmental Protection Measures	Location/ Timing	Implementation Agent	Relevant Standard or Requirement	Imp	olementa Stages	tion	Status *
	Reference					D	С	0	
		f Sufficiently covered to prevent rainfall							
		entering (water collected within the bund must be tested and disposed of as chemical waste, if necessary); and <i>f</i> Incompatible materials are adequately							
		separated.							
12.6	8.1	1	All areas / throughout construction period	Contractor	TMEIA		Y		✓
12.6	8.1	Adequate numbers of portable toilets should be provided for on- site workers. Portable toilets should be maintained in reasonable states, which will not deter the workers from utilising them.	, 0	Contractor	TMEIA		Y		✓
12.6	8.1	Night soil should be regularly collected by licensed collectors.	All areas / throughout construction period	Contractor	TMEIA		Y		N/A
12.6	8.1	General refuse arising on-site should be stored in enclosed bins or compaction units separately from C&D and chemical wastes. Sufficient dustbins shall be provided for storage of waste as required under the Public Cleansing and Prevention of Nuisances By-laws. In addition, general refuse shall be cleared daily and shall be disposed of to the nearest licensed landfill or refuse transfer station. Burning of refuse on construction sites is prohibited.	construction period	Contractor	TMEIA		Y		✓
12.6	8.1		All areas / throughout construction period	Contractor	TMEIA		Y		~
12.6	8.1	Office wastes can be reduced by recycling of paper if such volume is sufficiently large to warrant collection. Participation in a local collection scheme by the Contractor should be advocated. Waste separation facilities for paper, aluminium cans, plastic bottles, etc should be provided on-site.	construction period	Contractor	TMEIA		Y		✓
12.6 LANDSCAPE A	Section 8	EM&A of waste handling, storage, transportation, disposal procedures and documentation through the site audit programme shall be undertaken.		Contractor	EM&A Manual		Y		~

Legend: D=Design, C=Construction, O=Operation

EIA Reference	EM&A Manual	Environmental Protection Measures	Location/ Timing	Implementation Agent	Relevant Standard or Requirement	Im	plementa Stages	tion	Status *
	Reference					D	C	0	
10.9	7.6	Existing trees on boundary of the Project Area shall be carefully protected during construction. Detailed Tree Protection Specification shall be provided in the Contract Specification. Under this specification, the Contractor shall be required to submit, for approval, a detailed working method statement for the protection of trees prior to undertaking any works adjacent to all retained trees, including trees in contractor's works areas (Tree protection measures will be detailed at Tree Removal Application Stage) (CM1)	during construction	Design Consultant/ Contractor	TMEIA	Y	Y		N/A
10.9	7.6	Trees unavoidably affected by the works shall be transplanted where practical. Trees will be transplanted straight to their final receptor site and not held in a temporary nursery. A detailed Tree Transplanting Specification shall be provided in the Contract Specification. Sufficient time for necessary tree root and crown preparation periods shall be allowed in the project programme (CM2)	during construction	Design Consultant/ Contractor	TMEIA	Y	Y		N/A
.0.9	7.6	Hillside and roadside screen planting to proposed roads, associated structures and slope works (CM3)	All areas/detailed design/ during construction/post construction	Design Consultant/ Contractor	TMEIA	Y	Y		N/A
10.9	7.6	Hydroseeding or sheeting of soil stockpiles with visually unobstrusive material (in earth tone) (CM4)	All areas/detailed design/ during construction/post construction	Design Consultant/ Contractor	TMEIA	Y	Y		N/A
.0.9	7.6	Screening of construction works by hoardings around works area in visually unobtrusive colours, to screen works (CM5)	All areas/detailed design/ during construction	Design Consultant/ Contractor	TMEIA	Y	Y		N/A
.0.9	7.6	Control night-time lighting and glare by hooding all lights (CM6)	All areas/detailed design/ during construction	Design Consultant/ Contractor	TMEIA	Y	Y		N/A
0.9	7.6	Ensure no run-off into water body adjacent to the Project Area (CM7)	All areas/detailed design/ during construction	Design Consultant/ Contractor	TMEIA	Y	Y		N/A
0.9	7.6	Avoidance of excessive height and bulk of buildings and structures (CM8)	All areas/detailed design/ during construction	Design Consultant/ Contractor	TMEIA	Y	Y		1
0.9	7.6	Recycle/ Reuse all felled trees and vegetation, e.g. mulching (CM9)	All areas/detailed design/ during construction	Design Consultant/ Contractor	TMEIA	Y	Y		N/A
0.9	7.6		All areas/detailed design/ during construction	Design Consultant/ Contractor	TMEIA	Y	Y		N/A
0.9	7.6	Re-vegetation of affected woodland/shrubland with native species (OM1)	All areas/detailed design/ during construction/ during operation	Design Consultant/ Contractor	TMEIA	Y	Ŷ		n/a. To be maintained by HyD

Legend: D=Design, C=Construction, O=Operation

EIA Reference	EM&A Manual	Environmental Protection Measures	Location/ Timing	Implementation Agent	Relevant Standard or Requirement	Im	plementa Stages		Status *
	Reference					D	С	0	
10.9	7.6	Tall buffer screen tree / shrub / climber planting should be incorporated to soften hard engineering structures and facilities (OM2)	All areas/detailed design/ during construction/ during operation	Design Consultant/ Contractor	TMEIA	Y	Y		n/a. To be maintained by HyD/LCSD
10.9	7.6	Streetscape elements (e.g. paving, signage, street furniture, lighting etc.) shall be sensitively designed in a manner that responds to the local context, and minimises potential negative landscape and visual impacts. Lighting units should be directional and minimise unnecessary light spill (OM3)	All areas/detailed design/ during construction / during operation	Design Consultant/ Contractor	TMEIA	Y	Y		n/a. To be maintained by HyD
10.9	7.6	Structure, ornamental tree / shrub / climber planting should be provided along roadside amenity strips, central dividers and newly formed slopes to enhance the townscape quality and further greenery enhancement (OM4)	All areas/detailed design/ during construction / during operation	Design Consultant/ Contractor	TMEIA	Y	Y	Y	n/a. To be maintained by HyD/ArchSD
10.9	7.6	Aesthetically pleasing design (visually unobtrusive and non- reflective) as regard to the form, material and finishes shall be incorporated to all buildings, engineering structures and associated infrastructure facilities (OM5)	All areas/detailed design/ during construction / during operation	Design Consultant/ Contractor	TMEIA	Y	Y	Y	n/a. To be maintained by HyD/ArchSD
10.9	7.6	Avoidance of excessive height and bulk of buildings and structures (OM6)	All areas/detailed design/ during construction / during operation	Design Consultant/ Contractor	TMEIA	Y	Y		n/a. To be maintained by HyD/ArchSD

EIA Reference	EM&A	Environmental Protection Measures	Location/ Timing	Implementation	Relevant Standard	Imp	lementat	tion	Status *
	Manual			Agent	or Requirement		Stages		
	Reference					D	С	0	

* Remarks:

<> Compliance of Mitigation but need improvement

x Non-compliance of Mitigation Measures

▲ Non-compliance of Mitigation Measures but rectified by Contractor

 Δ Deficiency of Mitigation Measures but rectified by Contractor

N/A Not Applicable in Reporting Period

Legend: D=Design, C=Construction, O=Operation

[✓] Compliance of Mitigation Measures

Appendix D

Summary of Action and Limit Levels

Parameters	Action	Limit
4 Hour TSP Level in μg/m³	ASR1 = 213	260
	ASR5 = 238	
	AQMS1 = 213	
	ASR6 = 238	
	ASR10 = 214	
Hour TSP Level in µg /m³	ASR1 = 331	500
	ASR5 = 340	
	AQMS1 = 335	
	ASR6 = 338	
	ASR10 = 337	

Table D1Action and Limit Levels for 1-hour and 24-hour TSP

Table D2Actions in the Event of Landfill Gas being Detectedin Excavation / Confined Area

Parameter	Measurement	Action
Oxygen	< 19%	- Ventilate to restore oxygen to > 19%
	< 18%	- Stop work
		- Evacuate personnel / prohibit entry
		- Increase ventilation to restore to > 19%
Methane	>10% LEL (>	- Prohibit hot work
	0.5% v/v)	- Ventilate to restore methane to < 10% LEL
	> 20% LEL	- Stop work
	(>1% v/v)	- Evacuate personnel / prohibit entry
		- Increase ventilation to restore to $< 10\%$
Carbon Dioxide	> 0.5%	- Ventilate to restore oxygen to $< 0.5\%$
	> 1.5%	- Stop work
		- Evacuate personnel / prohibit entry
		- Increase ventilation to restore to $< 0.5\%$

Appendix E

Event Action Plan

Appendix E1Event/Action Plan for Air Quality

	ACTION								
EVENT	ET ⁽¹⁾	IEC ⁽¹⁾	ER ⁽¹⁾	Contractor					
Action Level									
1. Exceedance for one	1. Identify the source.	1. Check monitoring data submitted	1. Notify Contractor.	1. Rectify any unacceptable practice					
sample	2. Inform the IEC and the ER.	by the ET.		2. Amend working methods if					
	Repeat measurement to confirm finding.	Check Contractor's working method.		appropriate					
	 Increase monitoring frequency to daily. 								
2. Exceedance for two	1. Identify the source.	submitted by the ET. f n 2. Check the Contractor's working 2. M method. 3. H to 3. Discuss with the ET and the in Contractor on possible remedial	1. Confirm receipt of notification of	1. Submit proposals for remedial					
or more consecutive	2. Inform the IEC and the ER.		failure in writing.	actions to IEC within 3 working					
samples	3. Repeat measurements to confirm		2. Notify the Contractor.	days of notification					
	findings.		3. Ensure remedial measures properly	2. Implement the agreed proposals					
	 Increase monitoring frequency to daily. 		implemented.	3. Amend proposal if appropriate					
	5. Discuss with the IEC and the	measures.							
	Contractor on remedial actions required.	 Advise the ER on the effectiveness of the proposed remedial measures. 							
	6. If exceedance continues, arrange	5. Supervise implementation of							
	meeting with the IEC and the ER.	remedial measures.							
	If exceedance stops, cease additional monitoring.								

	ACTION								
EVENT	ET ⁽¹⁾	IEC ⁽¹⁾	ER ⁽¹⁾	Contractor					
Limit Level									
1. Exceedance for one sample	 Identify the source. Inform the ER and the DEP. 	1. Check monitoring data submitted by the ET.	 Confirm receipt of notification of failure in writing. 	1. Take immediate action to avoid further exceedance					
	3. Repeat measurement to confirm finding.	2. Check Contractor's working method.	 Notify the Contractor. Ensure remedial measures are 	2. Submit proposals for remedial actions to IEC within 3 working days of notification					
	 Increase monitoring frequency to daily. 	 Discuss with the ET and the Contractor on possible remedial measures. 	properly implemented.	3. Implement the agreed proposals					
	5. Assess effectiveness of Contractor's remedial actions and keep the IEC, the DEP and the ER informed of	 Advise the ER on the effectiveness of the proposed remedial measures. 		4. Amend proposal if appropriate					
	the results.	5. Supervise implementation of remedial measures.							
2. Exceedance for two or more consecutive	1. Notify the IEC, the ER, the DEP and the Contractor.	 the Contractor on the potential remedial actions. 2. Review the Contractor's 3. remedial actions whenever necessary to assure their effectiveness and advise the ER accordingly. 3. Supervise the implementation of remedial measures 	1. Confirm receipt of notification of failure in writing.	1. Take immediate action to avoid further exceedance.					
samples	2. Identify the source.		2. Notify the Contractor.	2. Submit proposals for remedial					
	3. Repeat measurements to confirm findings.		3. In consultation with the IEC, agree with the Contractor on the	actions to IEC within 3 working days of notification.					
	4. Increase monitoring frequency to daily.		remedial measures to be implemented.	3. Implement the agreed proposals.4. Resubmit proposals if problem sti					
	 5. Carry out analysis of the Contractor's working procedures to determine possible mitigation to be implemented. 6. Arrange meeting with the IEC 		 Ensure remedial measures are properly implemented. If exceedance continues, consider what activity of the work is responsible and instruct the Contractor to stop that activity of work until the exceedance is 	not under control. 5. Stop the relevant activity of works as determined by the ER until the exceedance is abated.					
	and the ER to discuss the remedial actions to be taken. 7. Assess effectiveness of the Contractor's remedial actions		work until the exceedance is abated.						

and keep the IEC, the DEP and the ER informed of the results.

8. If the exceedance stops, cease additional monitoring.

Abbreviations: ET - Environmental Team, IEC - Independent Environmental Checker, ER - Engineer's Representative, DEP - Director of Environmental Protection

Appendix F

EM&A Monitoring Schedule

HY/2017/10 Tuen Mun - Chek Lap Kok Link - Northern Tunnel Connection Buildings, E&M Works Landfill Gas Monitoring Schedule (1 to 31 October 2020)

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
Sunday	Wonday	luesuay	Wednesday	01-Oct	02-Oct	03-Oct
				01-061	02-001	LFG Monitoring (a.m. &
						p.m.)
04-Oct	05-Oct	06-Oct	07-Oct	08-Oct	09-Oct	10-Oct
		LFG Monitoring (a.m. &				
					p.m.)	p.m.)
	p)	p)	p)	p)	p.m.)	p.m.)
11-Oct	12-Oct	13-Oct	14-Oct	15-Oct	16-Oct	17-Oct
	LFG Monitoring (a.m. &	LFG Monitoring (a.m. &				
					p.m.)	p.m.)
)	F)	F)	F)	F)	F)
18-Oct	19-Oct	20-Oct	21-Oct	22-Oct	23-Oct	24-Oct
	LFG Monitoring (a.m. &	LFG Monitoring (a.m. &				
	p.m.)	p.m.)	p.m.)	p.m.)	p.m.)	p.m.)
	, ,	,	,	, ,	, ,	, ,
25-Oct	26-Oct	27-Oct	28-Oct	29-Oct	30-Oct	31-Oct
		LFG Monitoring (a.m. &	LFG Monitoring (a.m. &			
					p.m.)	p.m.)
		·	,	. ,	, , , , , , , , , , , , , , , , , , ,	· ,

HY/2017/10 Tuen Mun - Chek Lap Kok Link - Northern Tunnel Connection Buildings, E&M Works Landfill Gas Monitoring Schedule (1 to 30 November 2020)

Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
02-Nov				06-Nov	07-Nov
LFG Monitoring (a.m. &	LFG Monitoring (a.m. &	LFG Monitoring (a.m. &	LFG Monitoring (a.m. &	LFG Monitoring (a.m. &	LFG Monitoring (a.m. 8
p.m.)	p.m.)	p.m.)	p.m.)	p.m.)	p.m.)
					14-Nov
LFG Monitoring (a.m. &	. .	LFG Monitoring (a.m. &	LFG Monitoring (a.m. &	• •	LFG Monitoring (a.m. 8
p.m.)	p.m.)	p.m.)	p.m.)	p.m.)	p.m.)
16-Nov	17-Nov	18-Nov	19-Nov	20-Nov	21-Nov
LFG Monitoring (a.m. &	LFG Monitoring (a.m. &	LFG Monitoring (a.m. &	LFG Monitoring (a.m. &	LFG Monitoring (a.m. &	LFG Monitoring (a.m. &
p.m.)	p.m.)	p.m.)	p.m.)	p.m.)	p.m.)
23-Nov	24-Nov	25-Nov	26-Nov	27-Nov	28-No
LFG Monitoring (a.m. &	LFG Monitoring (a.m. &	LFG Monitoring (a.m. &	LFG Monitoring (a.m. &	LFG Monitoring (a.m. &	LFG Monitoring (a.m. &
p.m.)				p.m.)	p.m.)
30-Nov					
LFG Monitoring (a.m. & p.m.)					
	02-Nov LFG Monitoring (a.m. & p.m.) 09-Nov LFG Monitoring (a.m. & p.m.) 16-Nov LFG Monitoring (a.m. & p.m.) 23-Nov LFG Monitoring (a.m. & p.m.) 30-Nov LFG Monitoring (a.m. & 30-Nov LFG Monitoring (a.m. &	02-Nov03-NovLFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)09-Nov10-NovLFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & 	02-Nov03-Nov04-NovLFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)09-Nov10-Nov11-NovLFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)16-Nov17-Nov18-NovLFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)16-Nov17-Nov18-NovLFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)23-Nov24-Nov25-NovLFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)30-NovLFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)	02-Nov03-Nov04-Nov05-NovLFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)09-Nov10-Nov11-Nov12-NovLFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)16-Nov17-Nov18-Nov19-NovLFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)23-Nov24-Nov25-Nov26-NovLFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)30-Nov16-Nov16-Nov16-Nov16-Nov16-Nov17-Nov18-Nov19-NovLFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)16-Nov17-Nov18-Nov19-NovLFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)	02-Nov03-Nov04-Nov05-Nov06-NovLFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)09-Nov10-Nov11-Nov12-Nov13-NovLFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)16-Nov17-Nov18-Nov19-Nov20-NovLFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)16-Nov17-Nov18-Nov19-Nov20-NovLFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)16-Nov24-Nov25-Nov26-Nov27-NovLFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)17-Nov24-Nov25-Nov26-Nov27-NovLFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)LFG Monitoring (a.m. & p.m.)18-Nov19-Nov19-Nov20-Nov20-Nov20-NovLFG Monitoring (a.m. & p.m.)19-Nov20-No

The schedule is subject to excavation work at Main Control Building. The schedule will be revised after reviewing the progress of the construction works or due to adverse (safety, weather etc) conditions.

Appendix G

Calibration Certificate of Monitoring Equipment



MSA Hong Kong Ltd.

25/F Jupiter Tower, 9 Jupiter Street, Hong Kong Tel 852-22587588 Fax 25478780 Email info.hk@msasafety.com Website www.msasafety.com

Ref.2019/12/009CustomerGammon Constructions Limited

Date: 11-Dec-19

CERTIFICATE FOR CALIBRATION CHECK TEST

Model	Serial No.	Calibration Check Gas	Regulator	Full Scale	Response
		1.45% Methane,		100% LEL	29%LEL
Altair 5XIR 14	145986	15% Oxygen	.25litre/min	30% Vol	15% O2
		2.5% Carbon Dioxide		9.99%	2.5% CO2

Remarks: Regular inspection completed. Calibration passed

MSA Hong Kong Ltd. certify that instrument/s listed above has/have been calibrated check tested on: 11-Dec-19

This instrument was calibrated in accordance with all requirements of the specifications of MSA.

This instrument must be calibration checked prior to use in accordance with the instruction manual.

This instrument was calibrated using NIST traceable equipment and was in accordance with all requirements of the drawings and specifications of MSA.

For and on behalf of MSA Hong Kong Ltd.

Authorised Signature

Appendix H

Landfill Gas Monitoring Results and Graphical Presentation

Landfill Gas Monitoring Results on Methane Level


	-	esults on Methane Level					
Project	Works	Date(yyyy-mm-dd)	Monitoring Location	Time (hh:mm, 24hour)	Results (%)	Action Level (%)	Limit Level (%)
TMCLKL	HY/2017/10	2020-10-03	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-10-03	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-10-05	Main Control Building	8:15	0		
FMCLKL	HY/2017/10	2020-10-05	Main Control Building	13:15	0		
FMCLKL	HY/2017/10	2020-10-06	Main Control Building	8:15	0		
FMCLKL	HY/2017/10	2020-10-06	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-10-07	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-10-07	Main Control Building	13:15	0		
FMCLKL	HY/2017/10	2020-10-08	Main Control Building	8:15	0		
FMCLKL	HY/2017/10	2020-10-08	Main Control Building	13:15	0		
FMCLKL	HY/2017/10	2020-10-09	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-10-09	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-10-10	Main Control Building	8:15	0		
FMCLKL	HY/2017/10	2020-10-10	Main Control Building	13:15	0		
FMCLKL	HY/2017/10	2020-10-12	Main Control Building	8:15	0		
FMCLKL	HY/2017/10	2020-10-12	Main Control Building	13:15	0		
FMCLKL	HY/2017/10	2020-10-13	Main Control Building	8:15	0		
FMCLKL	HY/2017/10	2020-10-13	Main Control Building	13:15	0		
MCLKL	HY/2017/10	2020-10-14	Main Control Building	8:15	0		
FMCLKL	HY/2017/10	2020-10-14	Main Control Building	13:15	0		
FMCLKL	HY/2017/10	2020-10-15	Main Control Building	8:15	0		
MCLKL	HY/2017/10	2020-10-15	Main Control Building	13:15	0		
FMCLKL	HY/2017/10	2020-10-16	Main Control Building	8:15	0		
FMCLKL	HY/2017/10	2020-10-16	Main Control Building	13:15	0	10.0	
TMCLKL	HY/2017/10	2020-10-17	Main Control Building	8:15	0	10.0	20.0
TMCLKL	HY/2017/10	2020-10-17	Main Control Building	13:15	0		
FMCLKL	HY/2017/10	2020-10-19	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-10-19	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-10-20	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-10-20	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-10-21	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-10-21	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-10-22	Main Control Building	8:15	0		
FMCLKL	HY/2017/10	2020-10-22	Main Control Building	13:15	0		
FMCLKL	HY/2017/10	2020-10-23	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-10-23	Main Control Building	13:15	0		
FMCLKL	HY/2017/10	2020-10-24	Main Control Building	8:15	0		
FMCLKL	HY/2017/10	2020-10-24	Main Control Building	13:15	0		
MCLKL	HY/2017/10	2020-10-27	Main Control Building	8:15	0		
MCLKL	HY/2017/10	2020-10-27	Main Control Building	13:15	0		
FMCLKL	HY/2017/10	2020-10-28	Main Control Building	8:15	0		
FMCLKL	HY/2017/10	2020-10-28	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-10-29	Main Control Building	8:15	0		
MCLKL	HY/2017/10	2020-10-29	Main Control Building	13:15	0		
MCLKL	HY/2017/10	2020-10-30	Main Control Building	8:15	0		
FMCLKL	HY/2017/10	2020-10-30	Main Control Building	13:15	0		
TMCLKL	HY/2017/10	2020-10-31	Main Control Building	8:15	0		
TMCLKL	HY/2017/10	2020-10-31	Main Control Building	13:15	0		
				Average	0		
				Min.	0		
				Max.	0		


Landfill Gas Monitoring Results on Oxygen Level

	Mode	Dete/sees mm d-1	Clation	Time (hhumm 24hour)	Desults (9/)	Action Level (9/)	
Project TMCLKL	Works HY/2017/10	Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Results (%)	Action Level (%)	Limit Level (%)
		2020-10-03	Main Control Building	8:15	20.8		
TMCLKL TMCLKL	HY/2017/10	2020-10-03	Main Control Building	13:15	20.8 20.8		
TMCLKL	HY/2017/10	2020-10-05	Main Control Building	8:15			
TMCLKL	HY/2017/10 HY/2017/10	2020-10-05	Main Control Building	13:15	20.8		
TMCLKL	HY/2017/10 HY/2017/10	2020-10-06	Main Control Building	8:15	20.8		
		2020-10-06	Main Control Building	13:15	20.8		
TMCLKL TMCLKL	HY/2017/10 HY/2017/10	2020-10-07	Main Control Building Main Control Building	8:15	20.8		
		2020-10-07	-	13:15	20.8 20.8		
TMCLKL TMCLKL	HY/2017/10 HY/2017/10	2020-10-08 2020-10-08	Main Control Building	8:15 13:15	20.8		
TMCLKL	HY/2017/10 HY/2017/10		Main Control Building Main Control Building				
TMCLKL	HY/2017/10	2020-10-09	Main Control Building	8:15	20.8 20.8		
TMCLKL	HY/2017/10	2020-10-09 2020-10-10	-	13:15 8:15	20.8		
TMCLKL FMCLKL	HY/2017/10 HY/2017/10	2020-10-10	Main Control Building Main Control Building	13:15	20.8		
TMCLKL	HY/2017/10	2020-10-10	Main Control Building	8:15	20.8		
MCLKL	HY/2017/10 HY/2017/10	2020-10-12	Main Control Building	13:15	20.8		
MCLKL	HY/2017/10 HY/2017/10	2020-10-12	Main Control Building	8:15	20.8		
I MCLKL	HY/2017/10 HY/2017/10	2020-10-13	Main Control Building	13:15	20.8		
MCLKL	HY/2017/10	2020-10-13	Main Control Building	8:15	20.8		
MCLKL	HY/2017/10	2020-10-14	Main Control Building	13:15	20.8		
MCLKL	HY/2017/10	2020-10-14	Main Control Building	8:15	20.8		
MCLKL	HY/2017/10	2020-10-15	Main Control Building	13:15	20.8		
MCLKL	HY/2017/10	2020-10-15	Main Control Building	8:15	20.8		
MCLKL	HY/2017/10	2020-10-16	Main Control Building	13:15	20.8		
MCLKL	HY/2017/10	2020-10-18	Main Control Building	8:15	20.8	19.0	18.0
TMCLKL	HY/2017/10	2020-10-17	-	13:15	20.8		
MCLKL	HY/2017/10 HY/2017/10	2020-10-17	Main Control Building Main Control Building	8:15	20.8		
FMCLKL	HY/2017/10		Main Control Building		20.8		
TMCLKL	HY/2017/10	2020-10-19 2020-10-20	Main Control Building	13:15 8:15	20.8		
TMCLKL	HY/2017/10	2020-10-20	Main Control Building	13:15	20.8		
MCLKL	HY/2017/10	2020-10-20	Main Control Building	8:15	20.8		
FMCLKL	HY/2017/10	2020-10-21	Main Control Building	13:15	20.8		
TMCLKL	HY/2017/10	2020-10-21	Main Control Building	8:15	20.8		
MCLKL	HY/2017/10	2020-10-22	Main Control Building	13:15	20.8		
MCLKL	HY/2017/10	2020-10-22	Main Control Building	8:15	20.8		
MCLKL	HY/2017/10	2020-10-23	Main Control Building	13:15	20.8		
MCLKL	HY/2017/10	2020-10-23	Main Control Building	8:15	20.8		
MCLKL	HY/2017/10	2020-10-24	Main Control Building	13:15	20.8		
MCLKL	HY/2017/10	2020-10-24	Main Control Building	8:15	20.8		
MCLKL	HY/2017/10	2020-10-27	Main Control Building	13:15	20.8		
MCLKL	HY/2017/10	2020-10-27	Main Control Building	8:15	20.8		
MCLKL	HY/2017/10	2020-10-28	Main Control Building	13:15	20.8		
MCLKL	HY/2017/10	2020-10-20	Main Control Building	8:15	20.8		
MCLKL	HY/2017/10	2020-10-29	Main Control Building	13:15	20.8		
MCLKL	HY/2017/10	2020-10-29	Main Control Building	8:15	20.8		
MCLKL	HY/2017/10	2020-10-30	Main Control Building	13:15	20.8		
MCLKL	HY/2017/10	2020-10-30	Main Control Building	8:15	20.8		
MCLKL	HY/2017/10	2020-10-31	Main Control Building	13:15	20.8		
WIGERE	111/2017/10	2020-10-31	Main Control Bulluing	Average	20.8		1
				Average Min.	20.8		
				IVIII I.	20.0		

Landfill Gas Monitoring Results on Carbon Dioxide Level

Project	Works	tesults on Carbon Dioxide Date(yyyy-mm-dd)	Station	Time (hh:mm, 24hour)	Results (%)	Action Level (%)	Limit Level (%)
TMCLKL	HY/2017/10	2020-10-03	Main Control Building	8:15	0.03		
FMCLKL	HY/2017/10	2020-10-03	Main Control Building	13:15	0.03		
FMCLKL	HY/2017/10	2020-10-05	Main Control Building	8:15	0.03		
TMCLKL	HY/2017/10	2020-10-05	Main Control Building	13:15	0.03		
TMCLKL	HY/2017/10	2020-10-05	Main Control Building	8:15	0.03		
TMCLKL	HY/2017/10	2020-10-06	Main Control Building	13:15	0.03		
TMCLKL	HY/2017/10	2020-10-00	Main Control Building	8:15	0.03		
TMCLKL	HY/2017/10	2020-10-07	Main Control Building	13:15	0.03		
TMCLKL	HY/2017/10	2020-10-07	Main Control Building	8:15	0.03		
TMCLKL	HY/2017/10	2020-10-08	Main Control Building	13:15	0.03		
TMCLKL	HY/2017/10	2020-10-00	Main Control Building	8:15	0.03		
TMCLKL	HY/2017/10	2020-10-09	Main Control Building	13:15	0.03		
TMCLKL	HY/2017/10	2020-10-09	Main Control Building	8:15	0.03		
TMCLKL	HY/2017/10	2020-10-10	Main Control Building	13:15	0.03		
FMCLKL	HY/2017/10	2020-10-10	Main Control Building	8:15	0.03		
TMCLKL	HY/2017/10	2020-10-12	Main Control Building	13:15	0.03		
TMCLKL	HY/2017/10	2020-10-12	Main Control Building	8:15	0.03		
MCLKL	HY/2017/10 HY/2017/10	2020-10-13	Main Control Building	13:15	0.03		
MCLKL	HY/2017/10	2020-10-13	Main Control Building	8:15	0.03		
MCLKL	HY/2017/10	2020-10-14	Main Control Building	13:15	0.03		
TMCLKL	HY/2017/10	2020-10-14	Main Control Building	8:15	0.03		
TMCLKL	HY/2017/10	2020-10-15	Main Control Building	13:15	0.03		
MCLKL	HY/2017/10		-	8:15	0.03		
TMCLKL	HY/2017/10	2020-10-16	Main Control Building Main Control Building		0.03		
MCLKL	HY/2017/10	2020-10-16 2020-10-17	Main Control Building	13:15 8:15	0.03	0.5	1.5
			-				
TMCLKL TMCLKL	HY/2017/10 HY/2017/10	2020-10-17	Main Control Building Main Control Building	13:15	0.03		
TMCLKL	HY/2017/10	2020-10-19	-	8:15	0.03		
		2020-10-19	Main Control Building	13:15	0.03		
TMCLKL TMCLKL	HY/2017/10 HY/2017/10	2020-10-20	Main Control Building Main Control Building	8:15	0.03		
TMCLKL		2020-10-20	-	13:15	0.03		
	HY/2017/10	2020-10-21	Main Control Building	8:15	0.03		
TMCLKL	HY/2017/10	2020-10-21	Main Control Building	13:15	0.03		
TMCLKL	HY/2017/10	2020-10-22	Main Control Building	8:15	0.03		
TMCLKL	HY/2017/10	2020-10-22	Main Control Building	13:15	0.03		
TMCLKL	HY/2017/10	2020-10-23	Main Control Building	8:15	0.03		
FMCLKL	HY/2017/10	2020-10-23	Main Control Building	13:15	0.03		
	HY/2017/10	2020-10-24	Main Control Building	8:15	0.03		
MCLKL	HY/2017/10	2020-10-24	Main Control Building	13:15	0.03		
	HY/2017/10	2020-10-27	Main Control Building	8:15	0.03		
MCLKL	HY/2017/10	2020-10-27	Main Control Building	13:15	0.03		
	HY/2017/10	2020-10-28	Main Control Building	8:15	0.03		
	HY/2017/10	2020-10-28	Main Control Building	13:15	0.03		
MCLKL	HY/2017/10	2020-10-29	Main Control Building	8:15	0.03		
MCLKL	HY/2017/10	2020-10-29	Main Control Building	13:15	0.03		
MCLKL	HY/2017/10	2020-10-30	Main Control Building	8:15	0.03		
FMCLKL	HY/2017/10	2020-10-30	Main Control Building	13:15	0.03		
FMCLKL	HY/2017/10	2020-10-31	Main Control Building	8:15	0.03		
TMCLKL	HY/2017/10	2020-10-31	Main Control Building	13:15	0.03		
				Average	0.03		
				Min.	0.03		
				Max.	0.03		






Weather condition within the reporting period was sunny to rainy

Major construction works undertaken within the reporting period include

- Handover Inspection at Main Control Building;
- Electrical and Mechanical Works at Ventilation Plant Room;
- Handover Inspection at North Ventilation Building;
- Handover Inspection at Administration Building;
- Handover Inspection at Maintenance Depot;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes at Fire Services Department Building;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes at Customs and Excise Department Building;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes at N1;
- Electrical and Mechanical Works at Kiosk N2;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes at the Tunnel;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes at underpass at C3 area;
- Handover Inspection at Satellite Control Building;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes at Kiosk S2;
- Handover Inspection at South Ventilation Building; and
- Soil Mix and Landscape Works at Northern Landfall and Southern Landfall.



Weather condition within the reporting period was sunny to rainy

- Major construction works undertaken within the reporting period include
- Handover Inspection at Main Control Building;
- Electrical and Mechanical Works at Ventilation Plant Room;
- Handover Inspection at North Ventilation Building;
- Handover Inspection at Administration Building;
- Handover Inspection at Maintenance Depot;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes at Fire Services Department Building;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes at Customs and Excise Department Building;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes at N1;
- Electrical and Mechanical Works at Kiosk N2;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes at the Tunnel;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes at underpass at C3 area;
- Handover Inspection at Satellite Control Building;
- Electrical and Mechanical Works and Architectural Builder's Work and Finishes at Kiosk S2;
- Handover Inspection at South Ventilation Building; and
- Soil Mix and Landscape Works at Northern Landfall and Southern Landfall.

Appendix I

Monthly Summary of Waste Flow Table

Contract No. : HY/2017/10 Tuen Mun Chek Lap Kok Link – Northern Connection Tunnel Buildings, Electrical and Mechanical Works Monthly Summary Waste Flow Table for 2020 (Year)

		Actual	Quantities of Inert C	&D Materials Genera	tion		Actual Quantities of 0	C&D wastes Generation	Actu	al Quantities of F	Recyclables Genera	tion
Month\Material	Total Quantity Generated	Hard Rock and Large Broken Concrete	Reused in the Contract	Reused in other Projects	Disposed as Public Fills	Imported Fill	Chemical Waste	General Refuse	Metals	Felled trees	Paper/ cardboard packaging	Plastics
Unit	('000m ³)	('000m ³)	('000m ³)	('000m ³)	('000m ³)	('000m ³)	('000Kg)	('000Kg)	('000Kg)	('000Kg)	('000Kg)	('000Kg)
Jan	0.025	0.000	-	-	0.025	-	-	187.500	-	-	0.070	-
Feb	0.074	0.026	-	-	0.074	-	-	176.100	-	-	0.084	-
Mar	0.650	0.117	-	-	0.366	0.284	-	237.850	-	-	0.042	-
Apr	0.139	0.000	-	-	0.139	-	-	167.820	-	-	-	-
May	6.429	0.000	-	1.975	0.023	4.431	-	252.730	-	-	0.056	-
Jun	17.715	0.053	-	0.421	0.034	17.260	-	255.300	-	-	-	-
SUB-TOTAL	25.032	0.196	0.000	2.396	0.661	21.975	0.000	1277.300	0.000	0.000	0.252	0.000
Jul	41.044	0.008	-	6.284	0.035	34.725	-	134.530	-	-	0.056	-
Aug	10.705	0.007	-	-	0.163	10.541	-	132.420	-	-	0.035	-
Sep	0.033	0.005	-	-	0.033	-	-	89.120	-	-	-	-
Oct	0.210	0.011	-	-	0.210	-	-	184.460	-	-	-	-
Nov	-	-	-	-	-	-	-	-	-	-	-	-
Dec	-	-	-	-	-	-	-	-	-	-	-	-
TOTAL	77.023	0.227	0.000	8.680	1.102	67.241	0.000	1,817.830	0.000	0.000	0.343	0.000

Notes :

1 - The waste flow table shall also include C&D materials that are specified in the Contract to be imported for use at the Site.

2 - Plastics refer to plastic bottles/containers, plastic sheets/foam from packaging material.

3 - Broken concrete for recycling into aggregates.

4 - Assumed 5 kg per damaged water-filled barrier.

5 - Disposed as Public Fills includes Hard Rock and Large Broken Concrete.

Appendix J

Cumulative Statistics on Exceedances, Complaints, Notifications of Summons and Successful Prosecutions

Appendix J1 Cumulative Statistics on Exceedances

		Total No. recorded in this reporting month	Total No. recorded since contract commencement
1-Hr TSP	Action	4	50
	Limit	0	10
24-Hr TSP	Action	0	2
	Limit	0	0
Landfill gas hazar	d monitoring		
Methane		0	0
 Oxygen 		0	0
Carbon Dioxi	de	0	0

Appendix J2 Cumulative Statistics on Complaints, Notifications of Summons and Successful Prosecutions

Reporting Period		Cumulative Statistics	
	Complaints	Notifications of Summons	Successful Prosecutions
This Reporting Month (October 2020)	0	0	0
Total No. received since contract commencement	1	0	0

Email message		Environmental Resources Management
То	Ramboll Hong Kong Limited (ENPO)	2507, 25/F One Harbourfront, 18 Tak Fung Street,
From	ERM- Hong Kong, Limited	Hung Hom, Hong Kong Telephone: (852) 2271 3113 Facsimile: (852) 2723 5660
Ref/Project number	Contract No. HY/2017/10	E-mail: jasmine.ng@erm.com
	Tuen Mun - Chek Lap Kok Link - Northern	
	Connection Tunnel Buildings, Electrical and	
	Mechanical Works	1
Subject	Notification of Exceedance for Air Quality Impact Monitoring	ERM
Date	22 October 2020	

Dear Sir/ Madam,

Please find attached the Notification of Exceedance (NOE) of the following Log no.:

Action Level Exceedance 0463091_9October2020_1hrTSP_Station ASR5

One (1) exceedance was recorded on 9 October 2020.

Regards,

Jamin

Dr Jasmine Ng Environmental Team Leader

CONFIDENTIALITY NOTICE

This facsimile transmission is intended only for the use of the addressee and is confidential. If you are not the addressee it may be unlawful for you to read, copy, distribute, disclose or otherwise use the information in this facsimile. If you are not the intended recipient, please telephone or fax us immediately.



ERM-Hong Kong, Limited

CONTRACT NO. HY/2017/10 TUEN MUN – CHEK LAP KOK LINK – Northern Connection Tunnel Buildings, Electrical and Mechanical Works

Air Quality Impact Monitoring

Notification of Exceedance

22 October 2020 (Results obtained from ENPO Website) Monitoring Station ASR5 Parameter(s) with Exceedance(s) 1 -hr TSP (µg/m³) ASR1 = 331 ASR5 = 340 ASR6 = 338 ASR10 = 335 AQMS1 = 337 24-hr TSP (µg/m³) ASR1 = 213 ASR5 = 238 ASR10 = 214 AQMS1 = 213 ASR6 = 238 ASR0 = 238 ASR10 = 214 AQMS1 = 213 Unit Levels 1-hr TSP (µg/m³) 260 Measured Levels Refer to Appendix A (Data are source from Contract No. HY/2012/08). Works undertaken under this Contract on 9 October 2020 included Indoor defect rectification at Fire Services Department Building; event) The exceedance is unlikely to be due to the Contract, in view of the following; Action or Limit Level Exceedance(s) Work undertaken under this Contract on 9 October 2020 included Indoor defect rectification at Kine Contract, in view of the following; Notice defect rectification at Main Control Building Possible Reason for Action or Limit Level Kecee	Log No.		Action Level Exceedance				
Date 9 October 2020 (Measured) 22 October 2020 (Results obtained from ENPO Website) Monitoring Station ASR5 Parameter(s) with Exceedance(s) 1- hr TSP Action Levels 1-hr TSP (µg/m³) ASR1 = 331 ASR5 = 340 ASR5 = 338 ASR10 = 335 AQMS1 = 337 Action Levels 1-hr TSP (µg/m³) ASR1 = 213 ASR5 = 238 ASR10 = 213 ASR5 = 238 ASR10 = 214 AQMS1 = 213 Limit Levels 1-hr TSP (µg/m³) 260 Measured Levels Refer to Appendix A (Data are source from Contract No. HY/2012/08). Works Undertaken (at the time of monitoring event) The exceedance is unlikely to be due to the Contract, in view of the following: Indoor defect rectification at Fire Services Department Building; The exceedance is unlikely to be due to the Contract, in view of the following: Network with reference to the recorded wind direction (ranged betweens ³ and 34 ²), blowing from a northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generators or used as material storage area are seated by machines such as crane machines and generators or used as material storage area are seated by machines such as crane machines and generators or used as material storage area are seated by machines such as crane machines and generators or used as material storage area are seated by machines such as crane machines and generatarea or used area are seated by machines such as		046	63091_9October2020_1hr1SP_Station ASR5				
Monitoring Station ASR5 Parameter(s) with Exceedance(s) 1-hr TSP Action Levels 1-hr TSP (µg/m³) ASR1 = 331 ASR5 = 340 ASR6 = 338 ASR10 = 335 AQM51 = 337 Action Levels 1-hr TSP (µg/m³) ASR1 = 311 ASR5 = 288 ASR10 = 238 ASR10 = 213 ASR5 = 238 ASR6 = 238 ASR10 = 214 AQM51 = 213 Limit Levels 1-hr TSP (µg/m³) 500 24-hr TSP (µg/m³) 260 Measured Levels Refer to Appendix A (Data are source from Contract No. HY/2012/08). Works Undertaken (at the time of monitoring event) Works undertaken under this Contract on 9 October 2020 included • Indoor defect rectification at Fire Services Department Building; • Indoor defect rectification at Fire Services Department Building; • Indoor defect rectification at Main Control Building • Works undertaken under this Contract on 9 October 2020 included • Indoor defect rectification at Fire Services Department Building; • Indoor defect rectification at Main Control Building Possible Reason for Action or Limit Levels • With reference to the recorded wind direction (ranged between 3° and 34°), blowing from a northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works. The exposed area are covered with tarpaulin sheet or designated for landscaping works. The exposed area are covered with tar			[Total No. of Exceedances = 1]				
Monitoring Station ASR5 Parameter(s) with 1- hr TSP Exceedance(s) 1-hr TSP (µg/m³) Action Levels 1-hr TSP (µg/m³) ASR5 = 340 ASR6 = 338 ASR0 = 335 AQMS1 = 337 24-hr TSP (µg/m³) ASR5 = 238 ASR6 = 238 ASR6 = 238 ASR6 = 213 Limit Levels 1-hr TSP (µg/m³) 260 Measured Levels Refer to Appendix A (Data are source from Contract No. HY/2012/08). Works Undertaken (at the time of monitoring Indoor defect rectification at Fire Services Department Building; • Indoor defect rectification at Fire Services Department Building; • Indoor defect rectification at Ain Control Building The exceedance is unlikely to be due to the Contract, in view of the following: • With reference to the recorded wind direction (ranged between 3° and 34°), blowing from a northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works. • The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators	Date	9 October 2020 (Measured)					
Parameter(s) with Exceedance(s) 1- hr TSP Action Levels 1-hr TSP (µg/m³) ASR1 = 331 ASR5 = 340 ASR6 = 338 ASR10 = 335 AQMS1 = 337 24-hr TSP (µg/m³) ASR1 = 213 ASR5 = 228 ASR6 = 238 ASR10 = 214 AQMS1 = 213 Limit Levels 1-hr TSP (µg/m³) 500 24-hr TSP (µg/m³) 260 Measured Levels Refer to Appendix A (Data are source from Contract No. HY/2012/08). Works Undertaken (at the time of monitoring event) Works undertaken under this Contract on 9 October 2020 included 9 Indoor defect rectification at Fire Services Department Building; • Undoor defect rectification at Main Control Building • Norther Levels • With reference to the recorded wind direction (ranged between 3° and 34°), blowing from a northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification are northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification are are seated by machines such as crane machines and generators or used as material storage area are seated by machines such as crane machines and generators or used as material storage area are covered with tarpaulin sheet / vegetation. Dust are not anticipated (<i>Appendix B</i>). Based on the above, the exceedance is unlikely to be due to the Contract. Actions Taken/To Be Taken No immediate action is considered necessa		22 Octo	ober 2020 (Results obtained from ENPO Website)				
Exceedance(s)1- hr TSPAction Levels1-hr TSP (µg/m³)ASR1 = 331 ASR5 = 340 ASR5 = 334 ASR1 = 335 AQMS1 = 337 AQMS1 = 337Limit Levels24-hr TSP (µg/m³)ASR1 = 213 ASR5 = 238 ASR6 = 238 ASR6 = 238 ASR6 = 238 ASR6 = 238 ASR6 = 214 AQMS1 = 213Limit Levels1-hr TSP (µg/m³)500 24-hr TSP (µg/m³)Works Undertaken (at the time of monitoring event)Refer to Appendix A (Data are source from Contract No. HY/2012/08).Works Undertaken (at the time of monitoring event)The exceedance is unlikely to be due to the Contract, in view of the following: • Indoor defect rectification at Fire Services Department Building; • Indoor defect rectification at Main Control BuildingPossible Reason for Action or Limit Level Exceedance(s)The exceedance is unlikely to be due to the Contract, in view of the following: • The exceedance is unlikely direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works.• The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators or used as material storage area with proper cover of tarpaulin sheet / vegetation. Dust are not anticipated (Appendix B). Based on the above, the exceedance is unlikely to be due to the Contract.Actions Taken/To Be TakenNo immediate action is considered necessary. The ET will monitor for future trends in exceedances.	Monitoring Station		ASR5				
Action Levels 1-hr TSP (μg/m³) ASR1 = 331 ASR5 = 340 ASR5 = 340 ASR5 = 338 ASR1 = 337 AQMS1 = 337 AQMS1 = 337 ACtion Levels 24-hr TSP (μg/m³) ASR = 213 ASR5 = 238 ASR6 = 238 ASR10 = 214 AQMS1 = 213 AQMS1 = 213 AQMS1 = 213 Limit Levels 1-hr TSP (μg/m³) 500 24-hr TSP (μg/m³) 260 Measured Levels Refer to Appendix A (Data are source from Contract No. HY/2012/08). Works Undertaken (at the time of monitoring event) Works undertaken under this Contract on 9 October 2020 included • Indoor defect rectification at Fire Services Department Building; • Indoor defect rectification at Main Control Building Possible Reason for Action or Limit Level The exceedance is unlikely to be due to the Contract, in view of the following: • With reference to the recorded wind direction (ranged between 3° and 34°), blowing from a northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works. • The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators or used as material storage area with	Parameter(s) with		1 1 000				
ASR5 = 340 ASR5 = 340 ASR6 = 338 ASR10 = 335 AQMS1 = 33724-hr TSP (μg/m3)ASR1 = 213 ASR5 = 238 ASR10 = 214 AQMS1 = 213Limit Levels1-hr TSP (μg/m3)500 24-hr TSP (μg/m3)500 24-hr TSP (μg/m3)Measured LevelsRefer to Appendix A (Data are source from Contract No. HY/2012/08).Works Undertaken (at the time of monitoring event)Works undertaken under this Contract on 9 October 2020 included • Indoor defect rectification at Fire Services Department Building; • Indoor defect rectification at Fire Services Department Building; • Indoor defect rectification at Main Control BuildingPossible Reason for Action or Limit LevelThe exceedance is unlikely to be due to the Contract, in view of the following: • Works undertaken under this Contract on 9 October 2020 included • Indoor defect rectification at Main Control BuildingPossible Reason for Action or Limit Level Exceedance(s)The exceedance is unlikely to be due to the Contract, in view of the following: • With reference to the recorded wind direction (ranged between 3° and 34°), blowing from a northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works. • The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators or used as material storage area with proper cover of tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet or designated for landscaping works. The expo	Exceedance(s)		1- hr 151'				
ASR6 = 338 ASR10 = 335 AQMS1 = 33724-hr TSP (μg/m³)ASR1 = 213 ASR5 = 238 ASR6 = 238 ASR0 = 214 AQMS1 = 213Limit Levels1-hr TSP (μg/m³)24-hr TSP (μg/m³)50024-hr TSP (μg/m³)260Measured LevelsRefer to Appendix A (Data are source from Contract No. HY/2012/08).Works Undertaken (at the time of monitoring event)Works undertaken under this Contract on 9 October 2020 includedIndoor defect rectification at Fire Services Department Building; • Indoor defect rectification at Fire Services Department Building;Possible Reason for Action or Limit Level Exceedance(s)The exceedance is unlikely to be due to the Contract, in view of the following: • With reference to the recorded wind direction (ranged between 3° and 34°), blowing from a northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works.• The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators or used as material storage area with proper cover of tarpaulin sheet/vegetation. Dust are not anticipated (Appendix B). Based on the above, the exceedance is unlikely to be due to the Contract.Actions Taken/To Be TakenNo immediate action is considered necessary. The ET will monitor for future trends in exceedances.	Action Levels	1-hr TSP (μg/m³)	ASR1 = 331				
ASR10 = 335 AQMS1 = 337 24-hr TSP (µg/m³) ASR1 = 213 ASR5 = 238 ASR6 = 238 ASR0 = 214 AQMS1 = 213 Limit Levels 1-hr TSP (µg/m³) 500 24-hr TSP (µg/m³) 260 Measured Levels Refer to Appendix A (Data are source from Contract No. HY/2012/08). Works Undertaken (at the time of monitoring event) Works undertaken under this Contract on 9 October 2020 included • Indoor defect rectification at Fire Services Department Building; • Indoor defect rectification at Main Control Building Possible Reason for Action or Limit Level The exceedance is unlikely to be due to the Contract, in view of the following: • With reference to the recorded wind direction (ranged between 3° and 34°), blowing from a northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works. • The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators or used as material storage area with proper cover of tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sh							
AQMS1 = 33724-hr TSP (μg/m³)ASR1 = 213 ASR5 = 238 ASR6 = 238 ASR10 = 214 AQMS1 = 213Limit Levels1-hr TSP (μg/m³)260Measured LevelsRefer to Appendix A (Data are source from Contract No. HY/2012/08).Works Undertaken (at the time of monitoring event)Works undertaken under this Contract on 9 October 2020 included • Indoor defect rectification at Fire Services Department Building; • Indoor defect rectification at Main Control BuildingPossible Reason for Action or Limit Level Exceedance(s)The exceedance is unlikely to be due to the Contract, in view of the following: • With reference to the recorded wind direction (ranged between 3° and 34°), blowing from a northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works. • The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators or used as material storage area with proper cover of tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet or designated for landscaping works. The exp							
24-hr TSP (μg/m ³) ASR1 = 213 ASR5 = 238 ASR6 = 238 ASR10 = 214 AQMS1 = 213 Limit Levels 1-hr TSP (μg/m ³) 500 24-hr TSP (μg/m ³) 260 Measured Levels Refer to Appendix A (Data are source from Contract No. HY/2012/08). Works Undertaken (at the time of monitoring event) Works undertaken under this Contract on 9 October 2020 included • Indoor defect rectification at Fire Services Department Building; • Indoor defect rectification at Main Control Building Possible Reason for Action or Limit Level Exceedance(s) The exceedance is unlikely to be due to the Contract, in view of the following: • With reference to the recorded wind direction (ranged between 3° and 34°), blowing from a northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works. • The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators or used as material storage area with proper cover of tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet/vegetation. Dust are not anticipated (Appendix B). Based on the above, the exceedance is unlikely to be due to the Contract. Actions Taken/To Be Taken No immediate action is considered necessary. The ET will monitor for future trends in exceedances.							
ASR5 = 238 ASR6 = 238 ASR10 = 214 AQMS1 = 213Limit Levels1-hr TSP (μg/m³)50024-hr TSP (μg/m³)260Measured LevelsRefer to Appendix A (Data are source from Contract No. HY/2012/08).Works Undertaken (at the time of monitoring event)Works undertaken under this Contract on 9 October 2020 included • Indoor defect rectification at Fire Services Department Building; • Indoor defect rectification at Main Control BuildingPossible Reason for Action or Limit Level Exceedance(s)The exceedance is unlikely to be due to the Contract, in view of the following: • With reference to the recorded wind direction (ranged between 3° and 34°), blowing from a northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works. • The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators or used as material storage area with proper cover of tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet/vegetation. Dust are not anticipated (Appendix B). Based on the above, the exceedance is unlikely to be due to the Contract.Actions TakenNo immediate action is considered necessary. The ET will monitor for future trends in exceedances.		$24 \text{ hr TSP}(u \neq m^3)$					
ASR6 = 238 ASR10 = 214 AQMS1 = 213Limit Levels1-hr TSP (μg/m³)50024-hr TSP (μg/m³)260Measured LevelsRefer to Appendix A (Data are source from Contract No. HY/2012/08).Works Undertaken (at the time of monitoring event)Works undertaken under this Contract on 9 October 2020 includedPossible Reason for Action or Limit Level Exceedance(s)The exceedance is unlikely to be due to the Contract, in view of the following: • With reference to the recorded wind direction (ranged between 3° and 34°), blowing from a northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works.• The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators or used as material storage area with proper cover of tarpaulin sheet/vegetation. Dust are not anticipated (Appendix B). Based on the above, the exceedance is unlikely to be due to the Contract.Actions Taken/To Be TakenNo immediate action is considered necessary. The ET will monitor for future trends in exceedances.		24-III 15F (µg/III ⁹)					
ASR10 = 214 AQMS1 = 213 Limit Levels 1-hr TSP (μg/m ³) 24-hr TSP (μg/m ³) 260 Measured Levels Refer to Appendix A (Data are source from Contract No. HY/2012/08). Works Undertaken (at the time of monitoring event) Works undertaken under this Contract on 9 October 2020 included 9 Indoor defect rectification at Fire Services Department Building; Indoor defect rectification at Main Control Building Possible Reason for Action or Limit Level The exceedance is unlikely to be due to the Contract, in view of the following: • With reference to the recorded wind direction (ranged between 3° and 34°), blowing from a northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works. • The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators or used as material storage area with proper cover of tarpaulin sheet/vegetation. Dust are not anticipated (<i>Appendix B</i>). Based on the above, the exceedance is unlikely to be due to the Contract. Actions Taken/To Be Taken No immediate action is considered necessary. The ET will monitor for future trends in exceedances.							
Limit Levels1-hr TSP (μg/m³)500Measured LevelsRefer to Appendix A (Data are source from Contract No. HY/2012/08).Works Undertaken (at the time of monitoring event)Works undertaken under this Contract on 9 October 2020 includedIndoor defect rectification at Fire Services Department Building; • Indoor defect rectification at Main Control BuildingPossible Reason for Action or Limit Level Exceedance(s)The exceedance is unlikely to be due to the Contract, in view of the following: • With reference to the recorded wind direction (ranged between 3° and 34°), blowing from a northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works. • The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators or used as material storage area with proper cover of tarpaulin sheet/vegetation. Dust are not anticipated (Appendix B). Based on the above, the exceedance is unlikely to be due to the Contract.Actions Taken/To Be TakenNo immediate action is considered necessary. The ET will monitor for future trends in exceedances.							
24-hr TSP (µg/m³)260Measured LevelsRefer to Appendix A (Data are source from Contract No. HY/2012/08).Works Undertaken (at the time of monitoring event)Works undertaken under this Contract on 9 October 2020 includedIndoor defect rectification at Fire Services Department Building; • Indoor defect rectification at Main Control BuildingPossible Reason for Action or Limit Level Exceedance(s)With reference to the recorded wind direction (ranged between 3° and 34°), blowing from a northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works.• The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators or used as material storage area with proper cover of tarpaulin sheet/vegetation. Dust are not anticipated (<i>Appendix B</i>). Based on the above, the exceedance is unlikely to be due to the Contract.Actions Taken/To Be TakenNo immediate action is considered necessary. The ET will monitor for future trends in exceedances.							
Measured Levels Refer to Appendix A (Data are source from Contract No. HY/2012/08). Works Undertaken (at the time of monitoring event) Works undertaken under this Contract on 9 October 2020 included Possible Reason for Action or Limit Level Indoor defect rectification at Main Control Building Exceedance(s) The exceedance is unlikely to be due to the Contract, in view of the following: • With reference to the recorded wind direction (ranged between 3° and 34°), blowing from a northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works. • The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators or used as material storage area with proper cover of tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet/vegetation. Dust are not anticipated (<i>Appendix B</i>). Based on the above, the exceedance is unlikely to be due to the Contract. Actions Taken/To Be Taken No immediate action is considered necessary. The ET will monitor for future trends in exceedances.	Limit Levels	1-hr TSP (μg/m³)	500				
Works Undertaken (at the time of monitoring event) Works undertaken under this Contract on 9 October 2020 included Indoor defect rectification at Fire Services Department Building; Indoor defect rectification at Main Control Building Possible Reason for Action or Limit Level The exceedance is unlikely to be due to the Contract, in view of the following: Exceedance(s) With reference to the recorded wind direction (ranged between 3° and 34°), blowing from a northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works. The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators or used as material storage area with proper cover of tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet/vegetation. Dust are not anticipated (<i>Appendix B</i>). Based on the above, the exceedance is unlikely to be due to the Contract. Actions Taken/To Be Taken No immediate action is considered necessary. The ET will monitor for future trends in exceedances.		24-hr TSP (µg/m ³)	260				
 Indoor defect rectification at Fire Services Department Building; Indoor defect rectification at Main Control Building Possible Reason for Action or Limit Level Exceedance(s) With reference to the recorded wind direction (ranged between 3° and 34°), blowing from a northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works. The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators or used as material storage area with proper cover of tarpaulin sheet / vegetation. Dust are not anticipated (<i>Appendix B</i>). Based on the above, the exceedance is unlikely to be due to the Contract. Actions Taken/ToBe Taken 	Measured Levels	Refer to Appendix A (Data are	source from Contract No. HY/2012/08).				
event)Indoor defect rectification at Main Control BuildingPossible Reason for Action or Limit Level Exceedance(s)The exceedance is unlikely to be due to the Contract, in view of the following: • With reference to the recorded wind direction (ranged between 3° and 34°), blowing from a northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works.• The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators or used as material storage area with proper cover of tarpaulin sheet/vegetation. Dust are not anticipated (<i>Appendix B</i>). Based on the above, the exceedance is unlikely to be due to the Contract.Actions Taken/To Be TakenNo immediate action is considered necessary. The ET will monitor for future trends in exceedances.	Works Undertaken (at	Works undertaken under this	Contract on 9 October 2020 included				
Possible Reason for Action or Limit LevelThe exceedance is unlikely to be due to the Contract, in view of the following:Exceedance(s)With reference to the recorded wind direction (ranged between 3° and 34°), blowing from a northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works.• The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators or used as material storage area with proper cover of tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet/vegetation. Dust are not anticipated (<i>Appendix B</i>).Actions Taken/To Be TakenNo immediate action is considered necessary. The ET will monitor for future trends in exceedances.	the time of monitoring	Indoor defect rectification	n at Fire Services Department Building;				
Action or Limit Level Exceedance(s)• With reference to the recorded wind direction (ranged between 3° and 34°), blowing from a northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works. • The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators or used as material storage area with proper cover of tarpaulin sheet/vegetation. Dust are not anticipated (<i>Appendix B</i>). Based on the above, the exceedance is unlikely to be due to the Contract.Actions Taken/To Be TakenNo immediate action is considered necessary. The ET will monitor for future trends in exceedances.	event)						
Exceedance(s)Interference to the recorded with a decision (larged converter claim of)) between growing from a northerly/north-easterly direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works.• The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators or used as material storage area with proper cover of tarpaulin sheet/vegetation. Dust are not anticipated (<i>Appendix B</i>).Based on the above, the exceedance is unlikely to be due to the Contract.Actions Taken/To Be TakenNo immediate action is considered necessary. The ET will monitor for future trends in exceedances.	Possible Reason for	The exceedance is unlikely to	be due to the Contract, in view of the following:				
 is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works. The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators or used as material storage area with proper cover of tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet/vegetation. Dust are not anticipated (<i>Appendix B</i>). Based on the above, the exceedance is unlikely to be due to the Contract. Actions Taken/To Be Taken 	Action or Limit Level	• With reference to the record	rded wind direction (ranged between 3° and 34°), blowing from a				
is located upstream to the work area. However, only minor defect rectification works were conducted which are considered not major dust generating works.• The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators or used as material storage area with proper cover of tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet/vegetation. Dust are not anticipated (<i>Appendix B</i>). Based on the above, the exceedance is unlikely to be due to the Contract.Actions Taken/To Be TakenNo immediate action is considered necessary. The ET will monitor for future trends in exceedances.	Exceedance(s)	northerly/north-easterly c	direction) and wind speed (1.8 m/s) when exceedance recorded, ASR5				
Actions Taken/To Be TakenNo immediate action is considered necessary.The ET will monitor for future trends in exceedances.							
 The construction area under this Contract were mainly paved. The remaining unpaved area are seated by machines such as crane machines and generators or used as material storage area with proper cover of tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet/vegetation. Dust are not anticipated (<i>Appendix B</i>). Based on the above, the exceedance is unlikely to be due to the Contract. Actions Taken/To Be Taken 		-	5				
seated by machines such as crane machines and generators or used as material storage area with proper cover of tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet/vegetation. Dust are not anticipated (<i>Appendix B</i>). Based on the above, the exceedance is unlikely to be due to the Contract.Actions Taken/To Be TakenNo immediate action is considered necessary. The ET will monitor for future trends in exceedances.							
proper cover of tarpaulin sheet or designated for landscaping works. The exposed area are covered with tarpaulin sheet/vegetation. Dust are not anticipated (<i>Appendix B</i>). Based on the above, the exceedance is unlikely to be due to the Contract.Actions Taken/To Be TakenNo immediate action is considered necessary. The ET will monitor for future trends in exceedances.							
Actions Taken/To Be No immediate action is considered necessary. The ET will monitor for future trends in exceedances.		•					
Actions Taken / To Be Taken No immediate action is considered necessary. The ET will monitor for future trends in exceedances.							
Actions Taken / To Be TakenNo immediate action is considered necessary. The ET will monitor for future trends in exceedances.		_					
Taken exceedances.			-				
	Actions Taken / To Be		dered necessary. The ET will monitor for future trends in				
Remarks The monitoring results on 9 October 2020, locations of air quality monitoring stations and wind data	Taken	exceedances.					
· · · ·	Remarks	The monitoring results on 9 C	October 2020, locations of air quality monitoring stations and wind data				
are attached (refer to <i>Appendix A</i>).		are attached (refer to Appendix	x A).				


Appendix A

Results of Air Quality Monitoring, Meteorological Data and Locations of Air Quality Monitoring Stations

		Air qual	ity monito	ring results	on 9/10/20	20		
Project	Contract	Date	Station	Weather	Start time	Parameters	Results	Unit
TMCLKL	HY/2012/08	2020-10-09	ASR10	Sunny	8:10:00	1-hour TSP	94	ug/m3
TMCLKL	HY/2012/08	2020-10-09	ASR10	Sunny	9:12:00	1-hour TSP	64	ug/m3
TMCLKL	HY/2012/08	2020-10-09	ASR10	Sunny	10:14:00	1-hour TSP	85	ug/m3
TMCLKL	HY/2012/08	2020-10-09	ASR6	Sunny	8:20:00	1-hour TSP	178	ug/m3
TMCLKL	HY/2012/08	2020-10-09	ASR6	Sunny	9:22:00	1-hour TSP	91	ug/m3
TMCLKL	HY/2012/08	2020-10-09	ASR6	Sunny	10:24:00	1-hour TSP	109	ug/m3
TMCLKL	HY/2012/08	2020-10-09	ASR5	Sunny	8:32:00	1-hour TSP	<mark>373</mark>	ug/m3
TMCLKL	HY/2012/08	2020-10-09	ASR5	Sunny	9:34:00	1-hour TSP	178	ug/m3
TMCLKL	HY/2012/08	2020-10-09	ASR5	Sunny	10:36:00	1-hour TSP	167	ug/m3
TMCLKL	HY/2012/08	2020-10-09	ASR1	Sunny	8:44:00	1-hour TSP	181	ug/m3
TMCLKL	HY/2012/08	2020-10-09	ASR1	Sunny	9:46:00	1-hour TSP	145	ug/m3
TMCLKL	HY/2012/08	2020-10-09	ASR1	Sunny	10:48:00	1-hour TSP	114	ug/m3
TMCLKL	HY/2012/08	2020-10-09	AQMS1	Sunny	8:55:00	1-hour TSP	80	ug/m3
TMCLKL	HY/2012/08	2020-10-09	AQMS1	Sunny	9:57:00	1-hour TSP	106	ug/m3
TMCLKL	HY/2012/08	2020-10-09	AQMS1	Sunny	10:59:00	1-hour TSP	94	ug/m3
TMCLKL	HY/2012/08	2020-10-09	ASR10	Sunny	11:16:00	24-hour TSP	73	ug/m3
TMCLKL	HY/2012/08	2020-10-09	ASR6	Sunny	11:26:00	24-hour TSP	105	ug/m3
TMCLKL	HY/2012/08	2020-10-09	ASR5	Sunny	11:38:00	24-hour TSP	125	ug/m3
TMCLKL	HY/2012/08	2020-10-09	ASR1	Sunny	11:50:00	24-hour TSP	153	ug/m3
TMCLKL	HY/2012/08	2020-10-09	AQMS1	Sunny	12:01:00	24-hour TSP	82	ug/m3

Action level exceedance
Limit level exceedance

Meteorological Data for Impact Monitoring in the reporting period				
Date (yy-mm-dd) Time (24hrs)		Average of Wind Speed (m/s)	Average of Wind Direction(degree)	
20/10/09	0:00	2.2	29	
20/10/09	1:00	2.2	30	
20/10/09	2:00	2.2	28	
20/10/09	3:00	2.2	20	
20/10/09	4:00	2.2	16	
20/10/09	5:00	2.7	27	
20/10/09	6:00	1.8	15	
20/10/09	7:00	0.9	347	
20/10/09	8:00	1.8	3	
20/10/09	9:00	1.8	34	
20/10/09	10:00	1.8	11	
20/10/09	11:00	1.8	34	
20/10/09	12:00	1.8	31	
20/10/09	13:00	1.8	23	
20/10/09	14:00	1.3	266	
20/10/09	15:00	1.3	332	
20/10/09	16:00	1.3	338	
20/10/09	17:00	1.8	25	
20/10/09	18:00	2.2	332	
20/10/09	19:00	1.8	312	
20/10/09	20:00	2.7	318	
20/10/09	21:00	2.7	331	
20/10/09	22:00	1.8	345	
20/10/09	23:00	0.9	335	



Appendix B

Site Photo



Photo 1 - Fire Services Department Building



Photo 2 - Main Control Building

Email message

message		Resources Management
То	Ramboll Hong Kong Limited (ENPO)	2507, 25/F One Harbourfront, 18 Tak Fung Street,
From	ERM- Hong Kong, Limited	Hung Hom, Hong Kong Telephone: (852) 2271 3113 Facsimile: (852) 2723 5660
Ref/Project number	Contract No. HY/2017/10 Tuen Mun – Chek Lap Kok Link – Northern Connection Tunnel Buildings, Electrical and Mechanical Works	E-mail: jasmine.ng@erm.com
Subject	Notification of Exceedance for Air Quality Impact Monitoring	ERM
Date	10 November 2020	

Environmental

Dear Sir/ Madam,

Please find attached the Notification of Exceedance (NOE) of the following Log no.:

Action Level Exceedance 0463091_21October2020_1hrTSP_Station ASR6 0463091_21October2020_1hrTSP_Station ASR5 0463091_21October2020_1hrTSP_Station ASR1

Three (3) exceedances were recorded on 21 October 2020.

Regards,

famin

Dr Jasmine Ng Environmental Team Leader

CONFIDENTIALITY NOTICE

This facsimile transmission is intended only for the use of the addressee and is confidential. If you are not the addressee it may be unlawful for you to read, copy, distribute, disclose or otherwise use the information in this facsimile. If you are not the intended recipient, please telephone or fax us immediately.



ERM-Hong Kong, Limited

Contract No. HY/2017/10 Tuen Mun – Chek Lap Kok Link – Northern Connection Tunnel Buildings, Electrical and Mechanical Works

Air Quality Impact Monitoring

Notification of Exceedance

Log No.		Action Level Exceedance			
105 110.	0463091_21October2020_1hrTSP_Station ASR6				
	0463091_21October2020_1hrTSP_Station ASR5				
	0463091_21October2020_1hrTSP_Station ASR1				
	[Total No. of Exceedances = 3]				
Date	21 October 2020 (Measured)				
	10 November 2020 (Results obtained from ENPO Website)				
Monitoring Station		ASR6, ASR5, ASR1			
Parameter(s) with					
Exceedance(s)	1- hr TSP				
Action Levels	1-hr TSP (μg/m ³)	ASR1 = 331			
		ASR5 = 340			
		ASR6 = 338			
		ASR10 = 335			
		AQMS1 = 337			
	24-hr TSP (μg/m ³)	ASR1 = 213 ASR5 = 238			
		ASR6 = 238			
		ASR10 = 214			
	AQMS1 = 213				
Limit Levels	1-hr TSP (μg/m ³)	500			
	24-hr TSP (μg/m ³)	260			
Measured Levels	Refer to <i>Appendix A</i> (Data are source from Contract No. HY/2012/08).				
Works Undertaken (at	Works undertaken under this Contract on 21 October 2020 included				
the time of monitoring	 Indoor defect rectification at Northern Landfall; 				
event)	 Indoor defect rectification at Main Control Building 				
Possible Reason for	The exceedance is unlikely to be due to the Contract, in view of the following:				
Action or Limit Level	 With reference to the recorded wind direction (ranged between 322° and 345°), blowing from a 				
Exceedance(s)	north-westerly direction) and wind speed (2.2 m/s) when exceedances recorded, ASR5 and ASR6				
	are located upstream to the work area.				
	 Only minor defect rectification works were conducted which are considered not major dust 				
	generating works, thus result of 1-hour TSP at ASR1 was unlikely impacted by the works under				
	this project.				
	• The construction area under this Contract were mainly paved. The remaining unpaved area are				
	seated by machines such as crane machines and generators or used as material storage area with				
	proper cover of tarpaulin sheet or designated for landscaping works. The exposed area are				
	covered with tarpaulin sheet/vegetation. Dust are not anticipated (<i>Appendix B</i>).				
	Based on the above, the exceedances are unlikely to be due to the Contract.				
Actions Taken / To Be	No immediate action is considered necessary. The ET will monitor for future trends in				
Taken	exceedances.				
Remarks	The monitoring results on 21 October 2020, locations of air quality monitoring stations and wind				
	data are attached (refer to <i>Appendix A</i>).				


Appendix A

Results of Air Quality Monitoring, Meteorological Data and Locations of Air Quality Monitoring Stations

	Air quality monitoring results on 21/10/2020							
Project	Contract	Date	Station	Weather	Start time	Parameters	Results	Unit
TMCLKL	HY/2012/08	2020-10-21	ASR10	Sunny	8:00:00	1-hour TSP	108	ug/m3
TMCLKL	HY/2012/08	2020-10-21	ASR10	Sunny	9:02:00	1-hour TSP	94	ug/m3
TMCLKL	HY/2012/08	2020-10-21	ASR10	Sunny	10:04:00	1-hour TSP	107	ug/m3
TMCLKL	HY/2012/08	2020-10-21	ASR6	Sunny	8:12:00	1-hour TSP	254	ug/m3
TMCLKL	HY/2012/08	2020-10-21	ASR6	Sunny	9:14:00	1-hour TSP	149	ug/m3
TMCLKL	HY/2012/08	2020-10-21	ASR6	Sunny	10:16:00	1-hour TSP	<mark>352</mark>	ug/m3
TMCLKL	HY/2012/08	2020-10-21	ASR5	Sunny	8:23:00	1-hour TSP	<mark>474</mark>	ug/m3
TMCLKL	HY/2012/08	2020-10-21	ASR5	Sunny	9:25:00	1-hour TSP	213	ug/m3
TMCLKL	HY/2012/08	2020-10-21	ASR5	Sunny	10:27:00	1-hour TSP	265	ug/m3
TMCLKL	HY/2012/08	2020-10-21	ASR1	Sunny	8:35:00	1-hour TSP	<mark>494</mark>	ug/m3
TMCLKL	HY/2012/08	2020-10-21	ASR1	Sunny	9:37:00	1-hour TSP	231	ug/m3
TMCLKL	HY/2012/08	2020-10-21	ASR1	Sunny	10:39:00	1-hour TSP	224	ug/m3
TMCLKL	HY/2012/08	2020-10-21	AQMS1	Sunny	8:47:00	1-hour TSP	92	ug/m3
TMCLKL	HY/2012/08	2020-10-21	AQMS1	Sunny	9:49:00	1-hour TSP	114	ug/m3
TMCLKL	HY/2012/08	2020-10-21	AQMS1	Sunny	10:51:00	1-hour TSP	123	ug/m3
TMCLKL	HY/2012/08	2020-10-21	ASR10	Sunny	11:06:00	24-hour TSP	88	ug/m3
TMCLKL	HY/2012/08	2020-10-21	ASR6	Sunny	11:18:00	24-hour TSP	165	ug/m3
TMCLKL	HY/2012/08	2020-10-21	ASR5	Sunny	11:29:00	24-hour TSP	138	ug/m3
TMCLKL	HY/2012/08	2020-10-21	ASR1	Sunny	11:41:00	24-hour TSP	170	ug/m3
TMCLKL	HY/2012/08	2020-10-21	AQMS1	Sunny	11:53:00	24-hour TSP	101	ug/m3

Action level exceedance
Limit level exceedance

Meteorological Data for Impact Monitoring in the reporting period				
Date (yy-mm-dd) Time (24hrs)		Average of Wind Speed (m/s)	Average of Wind Direction(degree)	
20/10/21	0:00	3.1	345	
20/10/21	1:00	2.2	337	
20/10/21	2:00	2.7	348	
20/10/21	3:00	4.9	341	
20/10/21	4:00	1.3	207	
20/10/21	5:00	2.7	320	
20/10/21	6:00	3.6	328	
20/10/21	7:00	2.2	308	
20/10/21	8:00	2.2	339	
20/10/21	9:00	2.2	345	
20/10/21	10:00	2.2	322	
20/10/21	11:00	3.1	303	
20/10/21	12:00	2.7	337	
20/10/21	13:00	2.7	341	
20/10/21	14:00	2.7	320	
20/10/21	15:00	2.2	321	
20/10/21	16:00	2.2	320	
20/10/21	17:00	1.3	323	
20/10/21	18:00	2.2	309	
20/10/21	19:00	3.6	341	
20/10/21	20:00	4	339	
20/10/21	21:00	1.8	315	
20/10/21	22:00	2.7	348	
20-10-21	23:00	1.8	346	



Appendix B

Site Photo



Photo 1 - Northern Landfall



Photo 2 - Main Control Building