

Ref.: HYDHZMBEEM00_0_3831L.16

1 February 2016

By Fax (3698 5999) and By Post

Ove Arup & Partners Chief Resident Engineer's Office 5 Ying Hei Road, Tung Chung, Lantau Hong Kong

Attention: Mr. Paul Appleton

Dear Sir,

Re: Agreement No. CE 48/2011 (EP)

Environmental Project Office for the

HZMB Hong Kong Link Road, HZMB Hong Kong Boundary Crossing Facilities,

and Tuen Mun-Chek Lap Kok Link - Investigation

Contract No. HY/2010/02 - HZMB HKBCF - Reclamation Works Annual EM&A Review Report for March 2013 to February 2014

Reference is made to the Environmental Team's submission of the Annual EM&A Review Report for March 2013 to February 2014 certified by the ET Leader (ET's ref.: "60249820/C/RMKY16012902" dated 29 January 2016) and provided to us via e-mail on 29 January 2016.

We are pleased to inform you that we have no adverse comment on the captioned Annual EM&A Review Report for March 2013 to February 2014.

The ET Leader and the dolphin specialist of the ET are reminded that the EM&A report should never be regarded as a platform to express their own opinions towards a government topic, or to advocate his/her personal ideas, and also our verification to your report does not release any of your obligation in the EM&A Manual under the applicable Environmental Permit(s) for this project.

Thank you very much for your attention and please feel free to contact the undersigned should you require further information.

Yours faithfully, For and on behalf of

Ramboll Environ Hong Kong Limited

Raymond Dai

Independent Environmental Checker

c.c. HyD Mr. Matthew Fung (By Fax: 3188 6614)
HyD Mr. Wai-Ping Lee (By Fax: 3188 6614)
AECOM Ms. Echo Leong (By Fax: 2317 7609)
CHEC Mr. Lim Kim Chuan (By Fax: 2578 0413)

Internal: DY, YH, LP, CL, ENPO Site

Q:\Projects\HYDHZMBEEM00\02_Proj_Mgt\02_Corr\HYDHZMBEEM00_0_3831L.16.doc



China Harbour Engineering Company Limited

Contract No. HY/2010/02

Hong Kong – Zhuhai – Macao Bridge Hong Kong Boundary Crossing Facilities – Reclamation Works

Annual Review Report for March 2013- February 2014

[01/2016]

	Name	Signature
Prepared & Checked:	Y T Tang	Togethain
Reviewed, Approved and Certified:	Echo Leong (ETL)	EchoReon

Version:	Rev. 0	Date: 29 January 20	16

Disclaimer

This report is prepared for China Harbour Engineering Company Limited and is given for its sole benefit in relation to and pursuant to Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing Facilities-Reclamation Works and may not be disclosed to, quoted to or relied upon by any person other than China Harbour Engineering Company Limited without our prior written consent. No person (other than China Harbour Engineering Company Limited) into whose possession a copy of this report comes may rely on this report without our express written consent and China Harbour Engineering Company Limited may not rely on it for any purpose other than as described above.

AECOM Asia Co. Ltd.

15/F, Grand Central Plaza, Tower 1, 138 Shatin Rural Committee Road, Shatin, NT, Hong Kong Tel: (852) 3922 9000 Fax: (852) 2317 7609 www.aecom.com

TABLE OF CONTENTS

			Page
EXE	CUTI	/E SUMMARY	1
1	INTR	ODUCTION	3
		Background Scope of Report Contract Organization Summary of Construction Works	4 4 5 5
2	SUMI	MARY OF EM&A PROGRAMME REQUIREMENTS	7
		Monitoring Parameters Environmental Quality Performance (Action/Limit Levels) Environmental Mitigation Measures	7 8 8
3	MON	ITORING RESULTS	9
	3.2	Air Quality Monitoring Noise Monitoring Water Quality Monitoring Dolphin Monitoring	9 12 16 26
4	ENVI	RONMENTAL SITE INSPECTION AND AUDIT	26
5	ADVI	CE ON THE SOLID AND LIQUID WASTE MANAGEMENT STATUS	40
	5.1	Summary of Solid and Liquid Waste Management	40
6	IMPL	EMENTATION STATUS OF ENVIRONMENTAL MITIGATION MEASURES	41
	6.1	Implementation Status of Environmental Mitigation Measures	41
7	SUMI	MARY OF EXCEEDANCES OF THE ENVIRONMENTAL QUALITY PERFORMANCE LIMIT	42
	7.1	Summary of Exceedances of the Environmental Quality Performance Limit	42
8	SUMI	MARY OF COMPLAINTS, NOTIFICATION OF SUMMONS AND SUCCESSFUL PROSECUT	IONS 43
	8.1	Summary of Environmental Compliants, Notification of Summons and Successful Prosecution	ns 43
9	REVI	EW OF THE VALIDITY OF THE EIA PREDICTION	45
10	REVI	EW OF ENVIRONMENTAL IMPLEMENTATION STATUS	45
11	REVI	EW OF EM&A PROGRAMME	45
12	COM	MENTS, RECOMMENDATIONS AND CONCLUSIONS	46
	12.1 12.2 12.3 12.4 12.5 12.6 12.7	Comments on mitigation measures Air Quality Impact Construction Noise Impact Water Quality Impact Chemical and Waste Management Landscape and Visual Impact Recommendations on EM&A Programme	46 46 46 46 47 47
	12.8	Conclusions	48

List of Tables

Table 1.1	Contact Information of Key Personnel
Table 3.1	Summary of Number of Monitoring Events for 1-hr & 24-hr TSP Concentration
Table 3.2	Summary of Number of Exceedances for 1-hr & 24-hr TSP Monitoring
Table 3.3	Maximum Predicted TSP concentrations under the "Mitigated" scenario
Table 3.4	Summary of Number of Monitoring Events for Impact Noise
Table 3.5	Summary of Number of Monitoring Exceedances for Impact Noise
Table 3.6	Construction Noise Impact at Noise Sensitive Receivers
Table 3.7	Summary of Construction Noise Monitoring Results in the Reporting Period
Table 3.8	Summary of Number of Monitoring Events for Impact Water Quality
Table 3.9	Summary of Water Quality Exceedances in Mar 13-Feb 14
Table 3.10	Summary of number of water quality exceedances per monitoring day
Table 3.11	Comparison of depth averaged dissolved oxygen levels (Surface & Mid-depth, Bottom depth) during baseline and impact monitoring period (mgL ⁻¹)
Table 3.12	Ambient and Tolerance Values for Suspended Sediment Concentrations (mgL ⁻¹) in the Vicinity of Sensitive Receivers adopted in the EIA
Table 3.13	Calculated Elevations in Suspended Sediment Concentrations at Sensitive Receivers (mgL ⁻¹) under the 2012 mitigated scenario from the EIA
Table 3.14	Baseline suspended solids levels and 30% of baseline mean (mgL ⁻¹)
Table 3.15	Average suspended solids levels at sensitive receivers (mgL ⁻¹) in January 2014
Table 3.16	Summary of Dolphin Monitoring Action And Limit Level Exceedances
Figures	

rigures

Figure 1	General Contract Layout Plan
Figure 2	Impact Air Quality and Noise Monitoring Stations and Wind Station
Figure 3	Impact Water Quality Monitoring Stations
Figure 4	Impact Dolphin Monitoring Line Transect Layout Map
Figure 5	Environmental Complaint Handling Procedure

List of Appendices

Appendix A	Contract Organization for Environmental Works
Appendix B	Three Month Rolling Construction Programmes
Appendix C	Implementation Schedule of Environmental Mitigation Measures (EMIS)
Appendix D	Summary of Action and Limit Levels
Appendix E	Graphical Presentation of Impact Air Quality Monitoring Results
Appendix F	Graphical Presentation of Impact Daytime Construction Noise Monitoring Results
Appendix G	Graphical Presentation of Impact Water Quality Monitoring Results
Appendix H	Impact Dolphin Monitoring - Result Tables and Graphical Presentations
Appendix I	Quarterly Summary of Waste Flow Table
Appendix J	Cumulative Statistics on Exceedances, Complaints, Notifications of Summons and Successful
	Prosecutions
Appendix K	Event Action Plan

EXECUTIVE SUMMARY

Contract No. HY/2010/02 – Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing Facilities – Reclamation Work (here below, known as "the Contract") mainly comprises reclamation at the northeast of the Hong Kong International Airport of an area of about 130-hectare for the construction of an artificial island for the development of the Hong Kong Boundary Crossing Facilities (HKBCF), and about 19-hectare for the southern landfall of the Tuen Mun - Chek Lap Kok Link (TMCLKL). It is a designated Project and is governed by the current permits for the Contract, i.e. the amended Environmental Permits (EPs) issued on 17 July 2015 (EP-353/2009/I) and 13 March 2015 (EP-354/2009/D) (for TMCLKL Southern Landfall Reclamation only).

Ove Arup & Partners Hong Kong Limited (Arup) was appointed by Highways Department (HyD) as the consultants for the design and construction assignment for the Contract's reclamation works (i.e. the Engineer for the Contract).

China Harbour Engineering Company Limited (CHEC) was awarded by HyD as the Contractor to undertake the construction work of the Contract.

ENVIRON Hong Kong Ltd. was employed by HyD as the Independent Environmental Checker (IEC) and Environmental Project Office (ENPO) for the Contract.

AECOM Asia Co. Ltd. (AECOM) was appointed by CHEC to undertake the role of Environmental Team for the Contract for carrying out the environmental monitoring and audit (EM&A) works.

The construction phase of the Contract under the EPs was commenced on 12 March 2012 and will be tentatively completed by early Year 2016. The EM&A programme, including air quality, noise, water quality and dolphin monitoring and environmental site inspections, was commenced on 12 March 2012.

This report documents the findings of EM&A works conducted in the period between 1 March 2013 and 28 February 2014. As informed by the Contractor, major activities in the reporting period were:-

Marine-based Works

- Cellular structure installation
- Connecting arc cell installation
- Laying geo-textile
- Sand blanket laying
- Maintenance of silt curtain
- Stone column installation
- Laying stone blanket
- Band drain installation trial
- Band drain installation
- Backfill cellular structure
- Instrumentation works
- Construction of temporary seawall
- Ground investigation
- Installation of silt screen at sea water intake of HKIA
- Cone penetration test;
- Silt curtain deployment and repairing
- Sand blanket trial
- Stone blankets laying.
- Construction of cellular structure

Land-based Works

- Site office erection and construction at Works Area WA2;
- Public Works Regional Laboratory erection and construction at Works Area WA3;
- Maintenance works of Public Works Regional Laboratory at Works Area WA3
- Constructing site access at Works Area WA2 to Ying Hei Road, Tung Chung;
- Drainage works at Works Area WA2 and WA3;
- Geotextile fabrication at Works Area WA2 and WA4; and
 - Stone column installation barges setup and their maintenance works at Works Area WA4.

- Silt curtain fabrication at Works Area WA2 and WA4;
- Maintenance works of Site Office at Works Area WA2
- Maintenance works of Public Works Regional Laboratory at Works Area WA3
- Silt curtain fabrication at Works Area WA4
- Erection of site office for CHEC(GD) at Works Area WA2
- Green roof construction at Works Area WA2
- Construction of Temporary Marine Access at Works Area WA2
- Maintenance of Temporary Marine Access at Works Area WA2

A summary of monitoring and audit activities conducted in the reporting period is listed below:

24-hour Total Suspended Particulates (TSP) monitoring 62 sessions 1-hour TSP monitoring 62 sessions Noise monitoring 48 sessions Impact water quality monitoring 155 sessions Impact dolphin monitoring 24 surveys Joint Environmental site inspection 51 sessions

Breaches of Action and Limit Levels for Air Quality

A total of 15 Action level and 5 Limit Level exceedances were recorded during the 24-hr TSP impact monitoring period. No exceedance of 1-hour TSP exceedance level was recorded at all monitoring station during the 1-hr TSP impact monitoring period. Investigation into the possible causes of each exceedance was undertaken and reported in the respective monthly EM&A reports, the investigations results confirmed that the air quality exceedances were not related to Contract.

Breaches of Action and Limit Levels for Noise

One complains was received and therefore one (1) Action Level Exceedance of construction noise was recorded in the reporting period. Investigation into the possible causes of such exceedance was undertaken and reported in the respective monthly EM&A reports, the investigations results confirmed that the limit level exceedance was not related to Contract.

Breaches of Action and Limit Levels for Water Quality

Fifty-six (56) Action Level exceedances and seven (7) Limit Level exceedances were recorded at measured suspended solids (SS) values (in mg/L), one (1) Action Level exceedances were recorded at measured turbidity (in NTU), six (6) Action Level exceedance was recorded at measured DO (Bottom) (mg/L) and one (1) Limit Level exceedance was recorded at measured DO (S&M) (mg/L) during the reporting period. Investigation result shows that all the exceedances were not due to the Contract works except the Action Level Exceedance recorded at SR5 and Limit Level Exceedance recorded at IS10 on 18 Dec 13 were related to Contract.

Triggering of Event and Action Plan for Impact Dolphin Monitoring

One (1) Limit level exceedance and Six (6) Action Level Exceedances were recorded in the reporting period for impact dolphin monitoring. The investigation results showed that although no unacceptable changes in environmental parameters of this Contract have been measured, at this time it is not possible to make a conclusive assessment of this Contract's specific impact on dolphins. Event and Action Plan for Impact Dolphin Monitoring was triggered. For investigation results please refer to Appendix L of the corresponding quarterly reports.

Implementation Status and Review of Environmental Mitigation Measures

Most of the recommended mitigation measures, as included in the EM&A programme, were implemented properly in the reporting period. Reference is made to ET's proposal of the omission of air monitoring station (AMS 6) dated on 1 November 2012 and EPD's letter dated on 19 November 2012 regarding the conditional approval of the proposed omission of air monitoring station (AMS 6) for Contract No. HY/2010/02. The



aforesaid omission of Monitoring Station AMS6 was effective since 19 November 2012.

The recommended environmental mitigation measures effectively minimize the potential environmental impacts from the Contract. The EM&A programme effectively monitored the environmental impacts from the construction activities and ensure the proper implementation of mitigation measures. No particular recommendation was advised for the improvement of the programme.

Moreover, regular review and checking on the construction methodologies, working processes and plants were carried out to ensure the environmental impacts were kept minimal and recommended environmental mitigation measures were implemented effectively.

Complaint, Notification of Summons and Successful Prosecution

Eleven (11) environmental complaints were received in the reporting period.

One (1) summons and one (1) successful prosecution was received in the reporting period.

1 INTRODUCTION

1.1 Background

- 1.1.1 Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing Facilities Reclamation Work (here below, known as "the Contract") mainly comprises reclamation at the northeast of the Hong Kong International Airport of an area of about 130-hectare for the construction of an artificial island for the development of the Hong Kong Boundary Crossing Facilities (HKBCF), and about 19-hectare for the southern landfall of the Tuen Mun Chek Lap Kok Link (TMCLKL).
- 1.1.2 The environmental impact assessment (EIA) reports (Hong Kong Zhuhai Macao Bridge Hong Kong Boundary Crossing Facilities EIA Report (Register No. AEIAR-145/2009) (HKBCFEIA) and Tuen Mun Chek Lap Kok Link EIA Report (Register No. AEIAR-146/2009) (TMCLKLEIA), and their environmental monitoring and audit (EM&A) Manuals (original EM&A Manuals), for the Contract were approved by Environmental Protection Department (EPD) in October 2009.
- 1.1.3 EPD subsequently issued the Environmental Permit (EP) for HKBCF in November 2009 (EP-353/2009) and the Variation of Environmental Permit (VEP) in June 2010 (EP-353/2009/A), November 2010 (EP-353/2009/B), November 2011 (EP-353/2009/C), March 2012 (EP-353/2009/D), October 2012 (EP-353/2009/E), April 2013 (EP-353/2009/F), August 2013 (EP-353/2009/G), January 2015 (EP-353/2009/H) and July 2015 (EP-353/2009/I). Similarly, EPD issued the Environmental Permit (EP) for TMCLKL in November 2009 (EP-354/2009) and the Variation of Environmental Permit (VEP) in December 2010 (EP-354/2009/A), January 2014 (EP-354/2009/B), December 2014 (EP-354/2009/C) and March 2015 (EP-354/2009/D).
- 1.1.4 The Contract is a designated Project and is governed by the current permits for the Contract, i.e. the amended EPs issued on 17 July 2015 (EP-353/2009/I) and 13 March 2015 (EP-354/2009/D) (for TMCLKL Southern Landfall Reclamation only).
- 1.1.5 A Contract Specific EM&A Manual, which included all Contract-relation contents from the original EM&A Manuals for the Contract, was issued in May 2012.
- 1.1.6 Ove Arup & Partners Hong Kong Limited (Arup) was appointed by Highways Department (HyD) as the consultants for the design and construction assignment for the Contract's reclamation works (i.e. the Engineer for the Contract).
- 1.1.7 China Harbour Engineering Company Limited (CHEC) was awarded by HyD as the Contractor to undertake the construction work of the Contract.
- 1.1.8 ENVIRON Hong Kong Ltd. was employed by HyD as the Independent Environmental Checker (IEC) and Environmental Project Office (ENPO) for the Contract.
- 1.1.9 AECOM Asia Co. Ltd. (AECOM) was appointed by CHEC to undertake the role of Environmental Team for the Contract for carrying out the EM&A works.
- 1.1.10 The construction phase of the Contract under the EPs was commenced on 12 March 2012 and will be tentatively completed by early Year 2016.
- 1.1.11 According to the Contract Specific EM&A Manual, there is a need of an EM&A programme including air quality, noise, water quality and dolphin monitoring and environmental site inspections. The EM&A programme of the Contract commenced on 12 March 2012.

1.2 Scope of Report

1.2.1 This is the second Annual EM&A Review Report under the Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing Facilities – Reclamation Works. This report presents a summary of the environmental monitoring and audit works, list of activities and mitigation measures proposed by the ET for the Contract from 12 March 2012 and 28 February 2013.

1.3 **Contract Organization**

The Contract organization structure is shown in Appendix A. The key personnel contact names and 1.3.1 numbers are summarized in Table 1.1.

Contact Information of Key Personnel Table 1.1

Party	Position	Name	Telephone	Fax
Engineer's Representative (ER) (Ove Arup & Partners Hong Kong Limited)	Chief Resident Engineer	Roger Marechal	2528 3031	2668 3970
IEC / ENPO	Independent Environmental Checker	Raymond Dai	3743 0788	3548 6988
(ENVIRON Hong Kong Limited)	Environmental Project Office Leader	Y.H. Hui	3743 0788	3548 6988
Contractor	General Manager (S&E)	Daniel Leung	3157 1086	2578 0413
(China Harbour Engineering Company Limited)	Environmental Officer	Richard Ng	3693 2253	2578 0413
Company Limited)	24-hour Hotline	Alan C.C. Yeung	9448 0325	-
ET (AECOM Asia Company Limited)	ET Leader	Echo Leong	3922 9280	2317 7609

1.4 **Summary of Construction Works**

- 1.4.1 The construction phase of the Contract under the EP commenced on 12 March 2012.
- 1.4.2 As informed by the Contractor, details of the major works carried out in the reporting period are listed below:-

Marine-based Works

- Cone penetration test;
- Geotextile laying and fabrication;
- Stone column installation trial;
- Silt curtain fabrication and deployment; and
- Stone column installation
- Maintenance of Silt curtain
- Silt curtain deployment and repairing
- Sand blanket trial
- Stone blankets laying.
- Band drain installation trial
- Stone column installation
- Construction of cellular structure
- Backfill cellular structure

Land-based Works

- Site office erection and construction at Works Area WA2;
- Public Works Regional Laboratory erection and construction at Works Area WA3;
- Maintenance works of Public Works Regional Laboratory at Works Area WA3
- Constructing site access at Works Area WA2 to Ying Hei Road, Tung Chung;
- Drainage works at Works Area WA2 and WA3;
- Geotextile fabrication at Works Area WA2 and WA4; and
- Stone column installation barges setup and their maintenance works at Works Area WA4.
- Silt curtain fabrication at Works Area WA2 and WA4;
- Hoarding erection at Work Areas Portion D and Works Area WA2
- Sign board erection at Works Area WA2
- 1.4.3 The construction programme of the Contract is shown in Appendix B.
- 1.4.4 The general layout plan of the Contract site showing the detailed works areas is shown in Figure 1.
- 1.4.5 The environmental mitigation measures implementation schedule are presented in Appendix C.

2 SUMMARY OF EM&A PROGRAMME REQUIREMENTS

2.1 Monitoring Parameters

- 2.1.1 The Contract Specific EM&A Manual designated 4 air quality monitoring stations, 2 noise monitoring stations, 21 water monitoring stations (9 Impact Stations, 7 Sensitive Receiver Stations and 5 Control/Far Field Stations) to monitor environmental impacts on air quality, noise and water quality respectively. Pre-set and fixed transect line vessel based dolphin survey was required in two AFCD designated areas (Northeast and Northwest Lantau survey areas). The impact dolphin monitoring at each survey area should be conducted twice per month.
- 2.1.2 For impact air quality monitoring, monitoring locations AMS2 (Tung Chung Development Pier) and AMS7 (Hong Kong SkyCity Marriott Hotel) were set up at the proposed locations in accordance with Contract Specific EM&A Manual. The conditional omission of Monitoring Station AMS6 was effective since 19 November 2012. For monitoring location AMS3 (Ho Yu College), as proposed in the Contract Specific EM&A Manual, approval for carrying out impact monitoring could not be obtained from the principal of the school. Permission on setting up and carrying out impact monitoring works at nearby sensitive receivers, like Caribbean Coast and Coastal Skyline, was also sought. However, approvals for carrying out impact monitoring works within their premises were not obtained. Impact air quality monitoring was conducted at site boundary of the site office area in Works Area WA2 (AMS3A) respectively. Same baseline and Action Level for air quality, as derived from the baseline monitoring data recorded at Ho Yu College, was adopted for this alternative air quality location. Due to hand over of work site where the AMS3A and NMS3A was located, it was proposed to EPD on 27 December 2014 to relocate both monitoring station to alternative location AMS3B and NMS3B and approval of such relocation was given by the EPD on 2 January 2014. The monitoring stations AMS3A and NMS3A were renamed to monitoring station AMS3B and NMS3B respectively after relocation on 29 January 2014.
- 2.1.3 For impact noise monitoring, monitoring locations NMS2 (Seaview Crescent Tower 1) was set up at the proposed locations in accordance with Contract Specific EM&A Manual. However, for monitoring location NMS3 (Ho Yu College), as proposed in the Contract Specific EM&A Manual, approval for carrying out impact monitoring could not be obtained from the principal of the school. Permission on setting up and carrying out impact monitoring works at nearby sensitive receivers, like Caribbean Coast and Coastal Skyline, was also sought. However, approvals for carrying out impact monitoring works within their premises were not obtained. Impact noise monitoring was conducted at site boundary of the site office area in Works Area WA2 (NMS3A) respectively. Same baseline noise level, as derived from the baseline monitoring data recorded at Ho Yu College was adopted for this alternative noise monitoring location.
- 2.1.4 In accordance with the Contract Specific EM&A Manual, twenty-one stations were designated for impact water quality monitoring. The nine Impact Stations (IS) were chosen on the basis of their proximity to the reclamation and thus the greatest potential for water quality impacts, the seven Sensitive Receiver Stations (SR) were chosen as they are close to the key sensitive receives and the five Control/ Far Field Stations (CS) were chosen to facilitate comparison of the water quality of the IS stations with less influence by the Contract/ ambient water quality conditions.
- 2.1.5 Due to safety concern and topographical condition of the original locations of SR4 and SR10B, alternative impact water quality monitoring stations, naming as SR4(N) and SR10B(N), were adopted, which are situated in vicinity of the original impact water quality monitoring stations (SR4 and SR10B) and could be reachable. Same baseline and Action Level for water quality, as derived from the baseline monitoring data recorded, were adopted for these alternative impact water quality monitoring stations.
- 2.1.6 The monitoring locations used during the reporting period are depicted in Figures 2, 3 and 4 respectively.
- 2.1.7 The Contract Specific EM&A Manual also required environmental site inspections for air quality, noise, water quality, chemical, waste management, marine ecology and landscape and visual impact.

2.2 Environmental Quality Performance (Action/Limit Levels)

- 2.2.1 The environmental quality performance limits (i.e. Action and/or Limit Levels) of air, water quality and Chinese White Dolphin monitoring were derived from the baseline air and water quality monitoring results at the respective monitoring stations, while the environmental quality performance limits of noise monitoring were defined in the EM&A Manual.
- 2.2.2 The environmental quality performance limits of air quality, noise, water and Chinese White Dolphin monitoring are given in Appendix D.

2.3 Environmental Mitigation Measures

2.3.1 Relevant environmental mitigation measures were stipulated in the Particular Specification and EPs (EP-353/2009/I and EP-354/2009/D) (for TMCLKL Southern Landfall Reclamation only) for the Contractor to adopt. A list of environmental mitigation measures and their implementation statuses are given in Appendix C.

3 MONITORING RESULTS

3.1 Air Quality Monitoring

3.1.1 Introduction

- 3.1.1.1. In accordance with the Contract Specific EM&A Manual, impact 1-hour Total Suspended Particulates (TSP) monitoring was conducted for at least three times every 6 days, while impact 24-hour TSP monitoring was carried out for at least once every 6 days at the 4 monitoring stations (AMS2, AMS3A/B¹, AMS6 and AMS7).
- 3.1.1.2. The monitoring locations for impact air quality monitoring are depicted in Figure 2. However, for AMS6 (Dragonair/CNAC (Group) Building), permission on setting up and carrying out impact monitoring works was sought, however, access to the premise has not been granted yet on this report issuing date.
- 3.1.1.3. The weather was mostly sunny, with occasional cloudy and occasional rainy in the reporting period. The major dust source in the reporting period included construction activities from the Contract, as well as nearby traffic emissions.
- 3.1.1.4. The number of monitoring events and exceedances recorded in each month of the reporting period are presented in Table 3.1 and Table 3.2 respectively.
- 3.1.1.5. The baseline and impact air quality monitoring data are provided in the baseline monitoring report and monthly EM&A reports respectively. The graphical plots of the impact air quality monitoring results are provided in Appendix E. No specific trend of the monitoring results or existence of persistent pollution source was noted.

Table 3.1 Summary of Number of Monitoring Events for 1-hr & 24-hr TSP Concentration

Monitoring Parameter	Location	No. of monitoring events
_	Location	Mar 13 – Feb 14
	AMS2	186
1-hr TSP	AMS3A/B1	186
	AMS7	186
	AMS2	62
24-hr TSP	AMS3A/B1	62
	AMS7	62

Table 3.2 Summary of Number of Exceedances for 1-hr & 24-hr TSP Monitoring

Monitoring Location		Level of Exceedance	Level of Exceedance
Parameter	Parameter Location		Mar 13 – Feb 14
	AMS2	Action	0
	AIVIOZ	Limit	0
	AMS3A/B1	Action	0
1-hr TSP	AIVISSA/B	Limit	0
	AMS7	Action	0
	AIVIO	Limit	0
	Total		0
	AMS2	Action	0
24-hr TSP	AIVISZ	Limit	0
24-111 13P	AMS3A/B1	Action	11
	AIVIOSA/D	Limit	5

¹ The monitoring stations AMS3A was renamed to monitoring station AMS3B respectively after relocation on 29 January 2014.

	AMS7	Action	4
		Limit	0
	Total		20

3.1.2 Environmental Mitigation Measures

3.1.2.1 Relevant Air mitigation measures, as recommended in the EIA Report were stipulated in the EM&A Manual for the Contractor to adopt. The implementation status of air quality mitigation measures is depicted in Appendix C.

3.1.3 Summary of Actions Taken in the event of Non-Compliance

3.1.3.1 Other than the mitigation measures implemented as mentioned in Appendix C, in the event of non-compliance, actions were taken in accordance with the Event-Action Plan in the EM&A Manual. The Contractor was notified immediately. Investigation was carried out within three working days of identification of non-compliance such as identifying the air pollution sources, checking the implementation status of the mitigation measures, etc., and measurement was repeated to confirm the investigation findings. Further investigation was carried out to identify the source of pollution when deemed necessary. In summary, no direct evidence between the exceedance at AMS3A/B², AMS7 and the Hong Kong Boundary Crossing Facilities - reclamation works could be established for all non-compliances and therefore no action was required to be taken.

3.1.4 Review of Reasons for and the implications of Non-Compliance

3.1.4.1 A total of 15 Action level and 5 Limit Level exceedances were recorded during the 24-hr TSP impact monitoring period. No exceedance of 1-hour TSP exceedance level was recorded at all monitoring station during the 1-hr TSP impact monitoring period. Investigation into the possible causes of each exceedance was undertaken and reported in the respective monthly EM&A reports.

3.1.5 Environmental Acceptability of the Contract

3.1.5.1 Trend of 1-hour and 24-hour TSP

3.1.5.1.1 The 24-hour TSP monitoring results were well below the Action and Limit levels, despite the exceedance caused by non Contract activities at AMS3A/B² and few isolated events at AMS7. The trend of TSP at AMS2, AMS3A/B² and AMS7 were comparable to the baseline range and showed no noticeable deterioration of air quality during the impact monitoring period.

3.1.5.2 Correlation between exceedances with possible dust generating activities

3.1.5.2.1 Possible dust generating activities of the Contract did not cause any noticeable deterioration in air quality at Hong Kong Boundary Crossing Facilities – Reclamation Works. With proper implementation of air quality mitigation measures, the monitoring results showed no adverse air quality impact.

3.1.5.3 Comparison of EM&A results with EIA predictions

Table 3.3 Maximum Predicted TSP concentrations under the "Mitigated" scenario

ASR	Location	Predicted Daily Concentrations*		Average Impact 1-hour TSP	Average Impact 24-hour TSP Levels, μg/m³
		1-hour	24-hour	Levels, μg/m³	Leveis, μg/iii

² The monitoring station AMS3A was renamed to monitoring station AMS3B respectively after relocation on 29 January 2014.

AMS7	Hong Kong	344	92	80	72
	SkyCity Marriott				
	Hotel				

^{*}Extracted from Table 5-8 of the EIA report

3.1.5.3.1 At 1-hour and 24-hour TSP monitoring station at AMS7, the average 24-hour TSP levels recorded in the EM&A programme were in similar magnitude as the Daily dust level predicted in the EIA.

3.1.6 Practicality and Effectiveness of the EIA process and the EM&A programme

- 3.1.6.1 Monitoring and auditing of air quality was recommended for the construction phase of the Contract in the EIA to ensure no exceedance of the TSP standard at the sensitive receiver.
- 3.1.6.2 The air quality monitoring methodology was effective in monitoring the air quality impacts of the Contract. Baseline monitoring of 1-hour and 24-hour TSP helped to determine the ambient TSP levels at the sensitive receiver prior to commencement of construction works. During periods when there were possible dust generating construction activities, impact monitoring of 24-hour TSP helped to determine whether the Contract caused unacceptable air quality impacts on the sensitive receiver. As the scope of the Contract mainly includes reclamation works during the reporting period and dust generation from the construction activities such as wind erosion and sand filling is the key concern during the construction phase. The monitoring of TSP was therefore considered to be cost effective for the Contract.
- 3.1.6.3 All recommended mitigation measures were applicable to the Contract. As discussed above, the Contract did not cause unacceptable air quality impacts. However, as the nature of the Contract is reclamation works of approximately 130 hectares of land in size, some mitigation measures in practice were generally focused on dust generating activities only. Nevertheless, the mitigation measures implemented were effective and efficient in controlling air quality impacts.
- 3.1.6.4 Monitoring and audit of 24-hour TSP levels had ensured that any deterioration in air quality was readily detected and timely actions taken to rectify any non-compliance. Assessment and analysis of 24-hour TSP results collected throughout the baseline and impact monitoring periods also demonstrated the environmental acceptability of the Contract. Weekly site inspections had ensured that the EIA recommended air quality mitigation measures were effectively implemented. The EM&A program is considered to be cost effective.

3.1.7 Conclusion

- 3.1.7.1 Air quality monitoring for the Contract was conducted during the baseline and impact monitoring periods. Key construction activities including geotextile laying, stone column installation, stone blanket laying, construction of cellular structure and backfill cellular structure. The trend of 1-Hour TSP and 24-hour TSP was comparable to the baseline range and showed no noticeable deterioration of air quality during the monitoring period. Although exceedances were recorded, they were isolated and short-term events. There is no evidence of long-term deteriorating trend.
- 3.1.7.2 The average 24-hour TSP levels recorded at AMS7 in EM&A programme were in similar magnitude with the Daily dust level predicted in the EIA. No TSP level was predicted by the Project EIA at AMS2 and AMS3A/B³ and therefore, no comparison of EM&A data with EIA predictions could be made. Air quality mitigation measures implemented were effective in controlling air quality impacts.



³ The monitoring station AMS3A was renamed to monitoring station AMS3B respectively after relocation on 29 January 2014.

3.2 Noise Monitoring

3.2.1 Introduction

- 3.2.1.1 Impact noise monitoring was conducted at the 2 monitoring stations (NMS2 and NMS3A/B⁴) for at least once per week during 07:00 19:00 in the reporting period.
- 3.2.1.2 The monitoring locations used during the reporting period are depicted in Figure 2.
- 3.2.1.3 Major noise sources during the noise monitoring included construction activities of the Contract and nearby traffic noise.
- 3.2.1.4 The number of impact noise monitoring events and exceedances are summarized in Table 3.4 and Table 3.5 respectively.

Table 3.4 Summary of Number of Monitoring Events for Impact Noise

Menitoring December	Location	No. of monitoring events			
Monitoring Parameter	Location	Mar 13 - Feb 14			
Noise	NMS2	48			
110.00	NMS3A/B⁴	48			

Table 3.5 Summary of Number of Monitoring Exceedances for Impact Noise

Monitoring Parameter	Location Level of Exceedance		No. of Exceedance(s)
	NMS2	Action	0
	INIVISZ	Limit	0
Noise	NMS3A/B ⁴	Action	0
	INIVISSAVE	Limit	0
		Total	0

⁴ The monitoring station NMS3A were renamed to monitoring station NMS3B after relocation on 29 January 2014.

3.2.1.5 The graphical plots of the trends of the monitoring results are provided in Appendix F. No specific trend of the monitoring results or existence of persistent pollution source was noted.

3.2.2 Environmental Mitigation Measures

- 3.2.2.1. Relevant noise mitigation measures, as recommended in the EIA Report were stipulated in the EM&A Manual for the Contractor to adopt. The implementation status of noise mitigation measures is depicted in Appendix C. Construction Noise Permits were applied and complied with when construction works were carried out during restricted hours.
 - 3.2.3 Non-compliance (exceedances) of the Environmental Quality Performance Limits (Action and Limit Levels)

3.2.3.1 Summary of Non-compliance (Exceedances)

- 3.2.3.1.1 Table 3.5 summarised the number exceedance recorded at each monitoring station throughout the impact monitoring period. There was no exceedance recorded at both NMS2 and NMS3A/B⁵.
- 3.2.3.1.2 One complains was received; one (1) Action Level Exceedance of construction noise was recorded in the reporting period. Investigation into the possible causes of such exceedance was undertaken and reported in the respective monthly EM&A reports, the investigations results confirmed that the limit level exceedance was not related to Contract.

3.2.3.2 Summary of Actions Taken in the event of Non-Compliance

3.2.3.2.1 Investigation was carried out within three working days of identification of non-compliance. Assessments showed that all exceedances were not due to the works and therefore no action was required to be taken and these were verified by the IEC.

3.2.3.3 Review of Reasons for and the implications of Non-Compliance

- 3.2.3.3.1 There was one (1) action level exceedance recorded due to one noise complaint was received. Investigation into the possible causes of each exceedance was undertaken and reported in the respective monthly EM&A reports.
- 3.2.3.3.2 In summary, the average impact noise levels recorded in the reporting period were generally within the range of the predicted construction noise levels in the Project EIA.

3.2.4 Environmental Acceptability of the Contract

3.2.4.1 Trend of Measured Noise Level (Leg)

3.2.4.1.1 Other than an isolated event, the noise monitoring results for all monitoring stations were below the Limit levels. The trend showed no noticeable noise impact from the Contract during the impact monitoring period.

3.2.4.2 Correlation between exceedances with possible noise generating activities

- 3.2.4.2.1 No Exceedance was recorded for all monitoring stations. The impact noise levels recorded were generally similar to the predicted construction noise levels in the Project EIA.
- 3.2.4.2.2 For the complaint received during the monitoring period, investigation results confirmed that such exceedance was not related to the major construction activities of the Contract. Field observations indicated that construction activities, like sheet piling, percussive piling and excavation, were carrying out in nearby private developments (which are located at eastern and southern side of the Works Area WA2) during the course of monitoring, which contribute to the measured noise level. Therefore,

⁵ The monitoring station NMS3A were renamed to monitoring station NMS3B after relocation on 29 January 2014

noise generating activities of the Contract did not cause any noticeable noise impact at the sensitive receivers.

3.2.5 Comparison of EM&A results with EIA predictions

3.2.5.1 The EIA predicted that noise emitted by the use of Powered Mechanical Equipment (PME) on site would be the major source of noise impact during construction. The Construction Noise Impact at Noise Sensitive Receivers are summarised in Table 3.6 (extracted from Table 6-9 of the EIA Report).

Table 3.6 Construction Noise Impact at Noise Sensitive Receivers

NSR	Location	Predicted Noise Levels, dB(A)					
		Total Noise Impacts, dB(A)	Criterion, dB(A)				
NMS2	Seaview Crescent Tower 1	74	75				

3.2.5.2 During the construction period of the Contract, one (1) noise complaint was received in the impact monitoring period. The measured impact noise levels of the Contract for each monitoring station are summarised in Table 3.7 for comparison with EIA.

Table 3.7 Summary of Construction Noise Monitoring Results in the Reporting Period

NSR	Location	Average, dB(A),	Range, dB(A),	Limit Level, dB(A),	
		Leq ₃ 30 mins	Leq,30 mins	Leq ₃ 30 mins	
NMS2	Seaview Crescent Tower 1	66	62 - 68*	75	
NMS3A/B ⁴	Site Boundary of Site Office Area at Works Area WA2	65	57 - 69*	70	

^{* +3}dB(A) Façade correction included

3.2.5.3 The average impact noise levels recorded in EM&A during impact monitoring were all within the range of the predicted construction noise levels in the EIA Report. ET's assessment had shown that exceedances recorded were not due to the works of Reclamation Works and this had been verified by the IEC.

3.2.6 Practicality and Effectiveness of the EIA process and the EM&A programme

- 3.2.6.1 Monitoring and auditing of noise was recommended for the construction phase of the Contract in the EIA process to ensure compliance with the appropriate criterion at the receivers.
- 3.2.6.2 The noise monitoring methodology was effective in monitoring the noise impacts of the Contract. Baseline noise monitoring determined the ambient noise levels at the sensitive receivers prior to commencement of construction works. During periods when possible noise generating construction activities were on-going, impact noise monitoring would determine whether the Contract caused adverse noise impacts on the sensitive receivers. The monitoring methodology which focus on L_{eq30} minute therefore considered to be cost effective for the Contract.
- 3.2.6.3 Noise mitigation measures recommended in the EIA Report were stipulated in the EM&A Manual for the Contractor to implement during the construction phase of the Contract. The list of noise mitigation measures is depicted in Appendix C. All recommended mitigation measures were applicable to the Contract. As discussed above, the Contract did not cause adverse noise impacts to the receivers. Therefore, the mitigation measures implemented were effective and efficient in controlling noise impacts.
- 3.2.6.4 Monitoring and audit of noise levels ensured that any noise impact to the receivers would readily be detected and timely actions could be taken to rectify any non-compliance. Assessment and analysis of noise results collected throughout the baseline and impact monitoring periods also demonstrated the environmental acceptability of the Contract. Weekly site inspections ensured that the EIA



recommended noise mitigation measures were effectively implemented. The EM&A program is considered to be cost effective.

3.2.7 Conclusion

3.2.7.1 The trend of L_{eq} was comparable to the baseline range and showed no noticeable noise impact during the impact monitoring period. Although exceedance was recorded, there was no evidence of long-term increasing trend. The average impact noise levels recorded in EM&A programme were all lower than the construction noise levels predicted in the EIA.

3.3 Water Quality Monitoring

3.3.1 Introduction

- 3.3.1.1 Impact water quality monitoring was conducted 3 times per week during mid-ebb and mid-flood tides at 21 water monitoring stations (9 Impact Stations, 7 Sensitive Receiver Stations and 5 Control/Far Field Stations).
- 3.3.1.2 The monitoring locations used during the reporting period are depicted in Figure 3.
- 3.3.1.3 Number of impact water quality monitoring events and exceedances recorded in the reporting period at each impact station are summarized in Table 3.8 and Table 3.9 respectively.

Table 3.8 Summary of Number of Monitoring Events for Impact Water Quality

Menitering Decemptor	Tido	No. of monitoring events					
Monitoring Parameter	Tide	Mar 13 - Feb 14					
Weter Quality	Mid-Ebb	155					
Water Quality	Mid-Flood	155					

Table 3.9 Summary of Water Quality Exceedances in Mar 13-Feb 14

Station	Exceedance Level	DO	(S&M)	DO (E	Bottom)	Turl	bidity		SS	T	otal
	2010.	Ebb	Flood	Ebb	Flood	Ebb	Flood	Ebb	Flood	Ebb	Flood
IS5	Action	0	0	0	1 (10 June 13)	0	0	0	3 (7 Aug 13, 22 Nov 13; 10 Jan14)	0	4
	Limit	0	0	0	0	0	0	0	0	0	0
IS(Mf)6	Action	0	0	0	0	0	0	2 (11 Nov 13 and 16 Sept 13)	4 (8 May 13, 7 Aug 13; 11 & 20 Nov 13)	2	4
	Limit	0	0	0	0	0	0	0	0	0	0
IS7	Action	0	0	0	0	0	0	0	4 (8 May 13; 7 Aug 13; 20 Nov 13 and18 Oct 13)	0	4
	Limit	0	0	0	0	0	0	0	0	0	0
IS8	Action	0	0	0	0	0	0	0	3 (10 Apr and 8 May, 13; 6 Jan14)	0	3
Papart Varaio	Limit	0	0	0	0	0	0	0	1 (20 Dec13)	0	1

Station	Exceedance Level	DO	(S&M)	DO (E	Bottom)	Turl	bidity	;	SS	T	otal
	Levei	Ebb	Flood	Ebb	Flood	Ebb	Flood	Ebb	Flood	Ebb	Flood
IS(Mf)9	Action	0	0	0	0	0	0	1 (8 May 13)	7 (8 May 13, 15 Nov13, 4 Oct 13 and 6 Sept 13; 18 Dec 13; 6 &15 Jan14	1	7
	Limit	0	0	0	0	0	0	0	(1) 17 Jan14	0	1
IS10	Action	0	0	1 (10 June 13)	1 (10 June 13)	0	0	0	4 (26 July 13; 6 Nov13, 7 Oct 13 and 30 Sept 13)	1	5
	Limit	0	0	0	0	0	0	0	(2) 25 Oct 13; 18 Dec13	0	2
IS(Mf)11	Action	0	0	1 (10 June 13)	1 (10 June 13)	0	0	0	0	1	1
	Limit	0	0	0	0	0	0	0	0	0	0 3
IS(Mf)16	Action	0	0	0	0	0	0	5 (29 Mar 13, 23 Aug 13; 4 & 22 Nov 13 and 04 Oct 13)	3 (22 Apr 13; 16 Oct 13; 21 Feb14)	5	
	Limit	0	0	0	0	0	0	2	0	0 2	0
IS17	Action		0		0	0	1 (29 Apr 13)	(4 &15 Nov 13)	0		
	Limit	0	0	0	0	0	0	0	0	0	3
SR3	Action	0	0	0	0	0	0	0	3 (7 Aug 13; 22 Nov13; 10 Jan14)	0	
1	Limit	0	0	0	0	0	0	0	0	0	0

Station	Exceedance Level	DO ((S&M)	DO (E	Bottom)	Tur	bidity	,	SS	Т	otal
	2010.	Ebb	Flood	Ebb	Flood	Ebb	Flood	Ebb	Flood	Ebb	Flood
SR4(N)	Action	0	0	0	0	0	0	0	3 (10 Apr 13; 13 Nov13 and 18 Sept 13)	0	3
	Limit	0	0	0	0	0	0	1 (24 June 13)		1	0
SR5	Action	0	0	0	0	0	0	0	7 (26 Apr 13; 26 and 31 July 13; 6 Nov13, 7 Oct 13 and 30 Sept 13; 18 Dec 13)	0	7
	Limit	0	0	0	0	0	0	0	2 (29 Mar 13; 25 Oct 13)	0	2
SR6	Action	0	0	0	0	0	0	0	2 (6 Nov13; 3 Jan14)	0	2
	Limit	0	0	0	0	0	0	0	0	0	0
SR7	Action	0	0	0	0	0	0	0	0	0	0
J	Limit	0	0	0	0	0	0	0	0	0	0
SR10A	Action	0	0	0	0	0	0	0	1 (6 Dec13)	0	1
	Limit	0	0	0	0	0	0	0	0	0	0
SR10B (N)	Action	0	0	0	1 (10 June 13)	0	0	0	2 (6 Nov13; 21 Oct 13)	0	3
	Limit	0	1 (10 June 13)	0	0	0	0	0	0	0	1
Total	Action	0	0	2	4	0	1	10	46		63
	Limit	0	1	0	0	0	0	1	6		8

Note: S: Surface; M: Mid-depth;

- 3.3.1.4 Please refer to the monthly EM&A report (March 2013 to February 2014) accordingly for the details of the captioned exceedances.
- 3.3.1.5 The graphical plots of the trends of the monitoring results are provided in Appendix G. No specific trend of the monitoring results or existence of persistent pollution source was noted.

3.3.2 Environmental Mitigation Measures

- 3.1.2.1 Relevant water quality mitigation measures, as recommended in the EIA Report were stipulated in the EM&A Manual for the Contractor to adopt. The implementation status of water quality mitigation measure is depicted in Appendix C.
 - 3.3.3 Non-compliance (exceedances) of the Environmental Quality Performance Limits (Action and Limit Levels)

3.3.3.1 Summary of Non-compliance (Exceedances)

3.3.3.1.1 Table 3.9 summarised the number of dissolved oxygen, turbidity and suspended solids exceedances recorded at each sensitive receiver station throughout the impact monitoring period. A total of 71 exceedances were recorded during the entire construction period with 63 Action level exceedances and 8 Limit level exceedances.

3.3.4 Review of Reasons for and the implications of Non-Compliance

- 3.3.4.1 Fifty-six (56) Action Level exceedances and seven (7) Limit Level exceedances were recorded at measured suspended solids (SS) values (in mg/L), one (1) Action Level exceedances were recorded at measured turbidity (in NTU), six (6) Action Level exceedance was recorded at measured DO (Bottom) (mg/L) and one (1) Limit Level exceedance was recorded at measured DO (S&M) (mg/L) during the reporting period. Investigation result shows that all the exceedances were not due to the Contract works except the Action Level Exceedance recorded at SR5 and Limit Level Exceedance recorded at IS10 on 18 Dec 13 were related to Contract.
- 3.3.4.2 The exceedances note at IS10 and SR5 on 18 Dec 13 were considered as Contract related. The silt curtain integrity checking record on 4 January 14 shows that the disconnected silt curtain observed on 18 Dec 13 at northwest of HKBCF were rectified and the Contractor was further reminded to ensure provision of ongoing maintenance to the silt curtains and to carry out maintenance work once defects were found. For details of investigation please refer to monthly EM&A Report December 2014.
- 3.3.4.3 After review of the investigation results of the water quality exceedances (for detail of investigations please refer to section 4 of monthly EM&A report (Mar 13 to Feb 14), ambient conditions were considered to have effects on the water quality monitoring results. Exceedances were considered to be due to a combination of the following potential causes: 1. Rough sea condition caused by adverse weather and relatively strong current experienced during the monitoring period and 2. During the time when exceedances of DO were recorded at monitoring stations, relatively low DO values were also recorded at corresponding upstream Control Stations during ebb tide or flood tides indicating these exceedances of DO were unlikely to be contributed by Contract works. This indicated these exceedances of DO were unlikely to be contributed by Contract works. 3. Local effects in the vicinity of the monitoring station where exceedance was recorded.

3.3.5 Environmental Acceptability of the Contract

3.3.5.1 Trend of water quality

Dissolved Oxygen

3.3.5.1.1 The dissolved oxygen levels recorded in the impact monitoring period showed a seasonal trend in which lower DO levels were recorded during the wet season and higher DO levels were recorded during the dry season. One reason for this seasonal trend may have been the increase in water temperature during the wet season leading to decreases in the solubility of oxygen in water and vice

versa during the dry season. The trend of dissolved oxygen levels was presented in Appendix G. Other than an isolated action level exceedance, the trend of dissolved oxygen levels at each monitoring stations in Appendix G did not show any noticeable deterioration of dissolved oxygen levels.

Turbidity

3.3.5.1.2 The turbidity levels were fairly distributed at most monitoring station during the reporting period. While trend of turbidity levels at impact station IS17, IS(Mf)16, IS(Mf)9 and IS(Mf)6 were more fluctuated and a higher turbidity level were recorded from March 13 to May 13 and from October 13 to December 13. The trend of turbidity levels of each monitoring station was shown in Appendix G. However, despite one isolated event, turbidity levels of all monitoring stations were still lower than the Action Level during the monitoring period.

Suspended Solids

- 3.3.5.1.3 The trend of suspended solid levels of each impact monitoring station was shown similar with the control stations of each tide, i.e , slightly fluctuated between the period from September to December 2012. The trend of suspended solid levels of each monitoring station was shown in Appendix G.
 - 3.3.6 Correlation between exceedances with possible marine construction activities
 - 3.3.6.1 With proper implementation of water quality mitigation measures, marine construction activities of the Contract were not observed to cause any unacceptable water quality impacts to the sensitive receiver stations.

Table 3.10 Summary of number of water quality exceedances per monitoring month

Month	Sand Filling Rate m³/month	Depth averaged DO	Depth averaged Turbidity	Depth averaged SS	Total
Mar-13	52568	0	0	2	2
Apr-13	119967	0	1	4	5
May-13	448159	0	0	5	5
Jun-13	245188.5	7	1	1	9
Jul-13	252327.4	0	0	3	3
Aug-13	287182.6	0	1	5	6
Sep-13	368995	0	0	5	5
Oct-13	602966	0	0	8	8
Nov-13	593481	0	0	15	15
Dec-13	930460	0	0	5	5
Jan-14	952135	0	0	7	7
Feb-14	886830	0	0	1	1

- 3.3.6.2 As shown in Table 3.10, there was no apparent correlation between the dredging and filling rates and the number of water quality exceedances recorded per monitoring day.
- 3.3.6.3 For dissolved oxygen, the numbers of dissolved oxygen exceedances show no noticeable deterioration of dissolved oxygen or correlation between filling rate and dissolve oxygen exceedance.
- 3.3.6.4 For turbidity, the numbers of turbidity exceedances show no noticeable deterioration of turbidity or correlation between filling rate and turbidity exceedance.
- 3.3.6.5 For suspended solids, the numbers of suspended solids exceedances show no noticeable deterioration of suspended solid or correlation between filling rate and suspended exceedance.
- 3.3.6.6 The trend did not show any correlation between water quality impact and the filling rates during the impact monitoring period.
- 3.3.6.7 With proper implementation of water quality mitigation measures, marine construction activities of the Contract were not observed to cause any unacceptable water quality impacts to the sensitive receiver stations.

3.3.7 Comparison of EM&A results with EIA predictions

- 3.3.7.1 Results from the sensitive receiver stations were compared with the EIA predictions for the sensitive receivers in the following manner:
 - WSR 27 San Tau Beach SSSI with SR3
 - WSR 22c- Tai Ho Wan Inlet (outside) with SR4(N)
 - WSR 25 Cooling water intake at HK International Airport with SR5

Dissolved oxygen (DO)

- 3.3.7.2 According to Section 9.10.7.4 of the EIA Report, the dissolved oxygen depletion from the loss of sediment to suspension during the construction of the reclamation for HKBCF was calculated to be 0.4 mg/L at WSR25. Since, as stated in the Table 9.6a of the EIA report the DO of the NW Western water is generally high with average ranges between 5.7 6.8 mg/L and depletion will not be detrimental to the ecological systems of the area. The average Depth averaged DO record at SR5 is 7.8 mg/L in January 2014 when the filling rate/month is the highest during the reporting period and therefore no significant dissolved oxygen depletion from was noted during impact monitoring.
- 3.3.7.3 The baseline dissolved oxygen levels and the level of depletion during impact monitoring at each sensitive receiver are summarised in Tables 5.7.

Table 3.11 Comparison of depth averaged dissolved oxygen levels (Surface & Mid-depth, Bottom depth) during baseline and impact monitoring period (mgL⁻¹)

Sensitive Receiver	Associated Location during	Monitoring	Baselin	ne mean	Impact (Januar	mean y 2014)	Depletion during Impact Monitoring	
in Baseline	Impact	Depth	Mid-ebb	Mid-flood	Mid-ebb	Mid- flood	Mid- ebb	Mid- flood
SR3	SR3*	Surface & mid	6.8	6.7	8.3	8.2	-1.5	-1.5
		Bottom	-	6.2	-	-	-	-
SR4 [^]	SR4(N)**	Surface & mid	6.1	6.3	8.1	8.2	-2	-1.9
		Bottom	6.0	6.2	8.1	8.2	-2.1	-2
SR5	SR5**	Surface & mid	6.4	6.3	7.8	7.8	-1.4	-1.5
		Bottom	6.1	6.1	7.8	7.7	-1.7	-1.6
SR6	SR6**	Surface & mid	6.6	6.5	7.8	7.8	-1.2	-1.3
		Bottom	6.2	6.1	7.8	7.8	-1.6	-1.7
SR7	SR7**	Surface & mid	6.3	6.0	7.8	7.9	-1.5	-1.9

	<u>.</u>							
		Bottom	6.1	5.9	7.8	7.9	-1.7	-2
SR10A	SR10A	Surface & mid	6.0	6.0	7.7	7.7	-1.7	-1.7
		Bottom	5.7	5.8	7.7	7.7	-2	-1.9
SR10B [^]	SR10B(N)**	Surface & mid	6.1	6.0	7.7	7.8	-1.6	-1.8
		Bottom	6.2	5.8	7.7	7.8	-1.5	-2

[^]Due to safety issue, the water quality monitoring location of SR4 has been changed to SR4(N) during impact monitoring. *Only mid-depth station of DO were monitored at SR3 in mid-ebb during baseline monitoring, in both mid-ebb and mid-flood during impact monitoring as the water depth less than 3m.

3.3.7.4 Comparing baseline averaged dissolved oxygen levels with EM&A results; no significant depletion was found at all sensitive receiver locations. There was no adverse effect on dissolved oxygen concentrations as a result of the filling works of the Contract as the depleted dissolved oxygen concentrations did not breach the Water Quality Objectives nor did they exceed the AL levels adopted for the Contract.

Suspended solids (SS)

3.3.7.5 The EIA determined the acceptability of elevations in suspended sediment concentrations based on the Water Quality Objectives. The Water Quality Objectives for suspended sediments for the North Western Water Control Zones were defined as being an allowable elevation of 30% above the background. The ambient and tolerance values for suspended sediment concentrations in the vicinity of sensitive receivers adopted in Table 9.11 of the EIA Report are presented in Table 3.12.

Table 3.12 Ambient and Tolerance Values for Suspended Sediment Concentrations (mgL⁻¹) in the Vicinity of Sensitive Receivers adopted in the EIA

Sensitive			nt value ercentile)	Tolerance value (30% Tolerance)		
Receiver in EIA Report	Associated EPD Station	Dry Season	Wet Season	Dry Season	Wet Season	
WSR 27	NM5,6,8	8.3	5.6	2.5	1.7	
WSR 22c	NM1,2,3	5.5	3.7	1.7	1.1	
WSR 25	NM1,2,3	5.5	3.7	1.7	1.1	

3.3.7.6 The use of single layer silt curtain system has been modelled in the 2012 mitigated scenario. The predicted suspended sediment concentrations under the 2012 mitigated scenario of the Contract as shown in Table 9.21 in the EIA Report are summarised in Table 3.13.

Table 3.13 Calculated Elevations in Suspended Sediment Concentrations at Sensitive Receivers (mgL⁻¹) under the 2012 mitigated scenario from the EIA

Sensitive Receiver in EIA Report	Associated Location during Impact Monitoring	Calculated Elevations		
		Dry Season	Wet Season	
WSR 27	SR3	0.0	0.0	
WSR 22c	SR4(N)	0.1	0.0	
WSR 25	SR5	3.0	2.7	

^{**} The mid-depth station of DO was omitted at SR4(N) during impact monitoring as the water depth is less than 6m.

- 3.3.7.7 For suspended solids, as the baseline monitoring was conducted in October 2011 which is the transitional season or just the start of dry season while no data were recorded in the wet season, direct comparison with the EIA predictions could not be made. The comparison of EM&A results with baseline results in the following paragraphs was based on the criteria of acceptability of 30 percent elevations above the background as defined in the Water Quality Objectives which was also used in scenario predictions in the EIA.
- 3.3.7.8 Baseline water quality monitoring for the Contract was conducted during the transitional season. The mean baseline suspended solids level at each sensitive receiver and 30 percent of the baseline mean are presented in Table 3.14.

Table 3.14 Baseline suspended solids levels and 30% of baseline mean (mgL⁻¹)

Associated Location in Baseline Report	Baseline mean		30% of baseline mean		
	Mid-ebb	Mid-flood	Mid-ebb	Mid-flood	
SR3	14.0	16.3	4.2	4.9	
SR4	11.3	12.2	3.4	3.7	
SR5	10.6	11.9	3.2	3.6	
SR6	11.9	11.9	3.6	3.6	
SR7	11.4	10.4	3.4	3.1	
SR10A	10.2	10.2	3.1	3.1	
SR10B	11.5	11.1	3.5	3.3	

3.3.7.9 The average elevations in suspended solids concentrations of January 2014 were compared with the baseline levels are provided in Table 3.15.

Table 3.15 Average suspended solids levels at sensitive receivers (mgL⁻¹) in January 2014

Sensitive Receiver in	Associated Location during Impact	Impact SS Mean (in January 2014)			
Baseline	Monitoring	Mid-ebb	Elevation	Mid-flood	Elevation
SR3	SR3	9.1	-4.9	11.3	-5.0
SR4	SR4(N)*	7.2	-4.1	8.8	-3.4
SR5	SR5	7.7	-2.9	11.6	-0.3
SR6	SR6	7.4	-4.5	11.4	-0.5
SR7	SR7	8.8	-2.6	9.5	-0.9
SR10A	SR10A	5.1	-5.1	8.0	-2.2
SR10B	SR10B(N)*	5.2	-6.3	7.7	-3.4

^{*}Due to safety issue, the water quality monitoring location of SR4 & SR10b have been changed to SR4(N) & SR10B(N) respectively during impact monitoring.

3.3.7.10 With the highest filling rate in January 2014, the elevations in suspended solids levels were below 30 percent of the baseline suspended solids levels at all stations. Regional influences would have effects on the deterioration in water quality than activities at the work site. A combination of the following potential causes: 1. Rough sea condition caused by adverse weather and relatively strong current experienced during the monitoring period and 2. During the time when exceedances of DO were recorded at monitoring stations, relatively low DO values were also recorded at corresponding upstream Control Stations during ebb tide or flood tides indicating these exceedances of DO were unlikely to be contributed by Contract works. This indicated these exceedances of DO were unlikely to be contributed by Contract works. 3. Local effects in the vicinity of the monitoring station where exceedance was recorded.

3.3.8 Practicality and Effectiveness of the EIA process and the EM&A programme

- 3.3.8.1 Monitoring and audit of water quality was recommended for the construction phase of the Contract in the EIA process to ensure any deterioration in water quality would be readily detected and timely action could be taken to rectify the situation.
- 3.3.8.2 Baseline water quality monitoring determined the ambient water quality in the region prior to commencement of construction works. Impact water quality monitoring helped to determine whether the Contract would cause unacceptable water quality impacts on the sensitive receivers. Post-Contract water quality monitoring upon completion of all marine construction activities helped to demonstrate the return of ambient conditions that existed prior to commencement of the construction works.
- 3.3.8.3 Water quality mitigation measures were recommended in the EIA and a list of water quality mitigation measures were stipulated in the EM&A Manual for the Contractor to implement during the construction phase of the Contract. The list of water quality mitigation measures is depicted in Appendix C. All recommended mitigation measures were applicable to the Contract. Precautionary measures including installation of silt curtains were also implemented to prevent migration of suspended solids towards the sensitive receivers. Monitoring results showed that water quality at sensitive receivers was affected by regional water quality influenced by tidal and climatic conditions, local impacts from the vicinity of the receivers. As discussed above, the Contract was not observed to cause unacceptable water quality impacts to the sensitive receivers. Therefore, the mitigation measures implemented were effective and efficient in controlling water quality impacts.
- 3.3.8.4 Monitoring and audit of water quality ensured that any water quality impacts to the receivers would be readily detected and timely actions could be taken to rectify any non-compliance. Assessment and analysis of water quality results collected throughout the baseline, impact and post-Contract monitoring periods also demonstrated the environmental acceptability of the Contract. Weekly site



inspections ensured that the EIA recommended water quality mitigation measures were effectively implemented.

3.3.9 Conclusion

- 3.3.9.1 Water quality monitoring for the Contract was conducted during the baseline and impact monitoring periods. For dissolved oxygen, turbidity and suspended solids levels, a total of 36 exceedances were recorded. Assessment indicated that there was no correlation between the filling rates and the number of water quality exceedances recorded. Exceedances were considered to be due to a combination of factors including 1. Rough sea condition caused by adverse weather and relatively strong current experienced during the monitoring period and 2. During the time when exceedances of DO were recorded at monitoring stations, relatively low DO values were also recorded at corresponding upstream Control Stations during ebb tide or flood tides indicating these exceedances of DO were unlikely to be contributed by Contract works. This indicated these exceedances of DO were unlikely to be contributed by Contract works. 3. Local effects in the vicinity of the monitoring station where exceedance was recorded.
- 3.3.9.2 The DO and SS levels recorded at SR3, SR4 (N) and SR5 were in similar magnitude as predicted in the Project EIA. No comparison could be made from SR6 to SR10B(N) as predictions were not made in the Project EIA. For turbidity, as no prediction was made in the Project EIA, no comparison could be made. With the implementation of water quality mitigation measures recommended in the EIA and water quality mitigation measures implemented during the EM&A programme, marine construction activities of the Contract did not cause any unacceptable water quality impacts to the sensitive receivers.

3.4 Dolphin Monitoring

3.4.1 Introduction

- 3.4.1.1 In accordance with the requirements specified in Section 9.3 of the EM&A Manuel, monthly vessel-based surveys were conducted to monitor impacts on the Indo-Pacific humpback or Chinese white dolphin (Sousa chinensis). The surveys were conducted in the areas known as NEL and NWL and travelled the transect lines depicted in Figure 4.
- 3.4.1.2 The total transect length for NEL and NWL combined is approximately 111km although some Contract and other works at times have caused temporary truncation of some lines, particularly lines 1.2.9 and 10.
- 3.4.1.3 Surveys were conducted twice per month, using combined line transect and photo-identification techniques. The research team comprised qualified and experienced researchers and Marine Mammal Observers (MMO).
- 3.4.1.4 The mitigation measures for dolphins are included in the Environmental Permit for this Contract are included in Appendix C.

3.4.2 Environmental Mitigation Measures

3.4.2.1 Relevant mitigation measures for dolphins, as recommended in the EIA Report were stipulated in the EM&A Manual for the Contractor to adopt. The implementation status of mitigation measures for dolphins is depicted in Appendix C.

3.4.3 Summary of Actions Taken in the event of Non-Compliance

- 3.4.3.1 Action Level and Limit Level (AL/LL) values were implemented during this reporting period. This Contract reports on AL/LL relevant to NEL and NWL monitoring areas (see Appendix D; Table 5).
- 3.4.3.2 One (1) Limit level exceedance and Six (6) Action Level Exceedances were recorded in the reporting period for impact dolphin monitoring. The investigation results showed that although no unacceptable changes in environmental parameters of this Contract have been measured, at this time it is not possible to make a conclusive assessment of this Contract's specific impact on dolphins. Event and Action Plan for Impact Dolphin Monitoring was triggered. For investigation results please refer to Appendix L of the corresponding quarterly reports.

Table 3.16 Summary of Dolphin Monitoring Limit level and Action level Exceedances

Quarterly period		STG*	ANI**	Level Exceeded	
March 2013- May 2013	NEL	0.0	0.0	Limit Level	
	NWL	3.0	8.6		
June 2013- August 2013	NEL	1.8	1.8	Action	
	NWL	5.7	16.6	Action	
September 2013- November 2013	NEL	0.0	0.0	Action	
_	NWL	6.7	24.7	Action	
December 2013- February 2014	NEL	0.5	0.5	Action	
	NWL	4.5	20.7	Action	

^{*} STG represents groups of dolphins (recorded on effort)

^{**} ANI represents number of individual dolphins (recorded on effort)

3.4.4 Summary of Survey Effort and Dolphin Sightings

3.4.4.1 Vessel-based surveys have been conducted monthly from March 2013 to February 2014, i.e., during the second year of the construction phase. A total of 50 survey days were completed between March 2013-February 2014 (Table 1 of Appendix H). A total of 2667.1km were completed whereas 2595.4km were conducted under favourable conditions (defined as Beaufort Sea State 3 or better and with visibility of >1km) between March 2013-February 2014 (Table 2 of Appendix H). Between March 2013-February 2014, a total of 135 dolphin sightings were recorded, 91 as on effort and 44 as opportunistic (Figure 1 of Appendix H). In the first year of impact monitoring (2012-13), 49 survey days were completed, with a total of 2627.5km completed with 2601.4km were conducted under favourable conditions. In both years, >97% of the total track length covered was under favourable conditions. In the first year of impact monitoring, a total of 203 dolphin sightings were recorded, 145 as on effort and 58 as opportunistic. The total number of sightings has decreased between the first and second year and year two of impact monitoring.

3.4.5 Distribution

3.4.5.1 Sightings of dolphins were divided into quarterly periods and an increase then decrease in the number of sightings is depicted as the year progresses through each quarter, i.e., lowest use in March – May 2013, high use in June – November 2013 and, again, lower use in December 2013-February 2014. NEL is used during the summer and autumn periods when the number of sightings in Hong Kong waters is highest (Figure 2 of Appendix H). This is a similar pattern to the first year of impact monitoring, although the overall number of sightings within NEL during the second year of monitoring is less.

3.4.6 Encounter Rate

3.4.6.1 Encounter rates of "on effort" sightings (i.e., groups) per area per quarter for this reporting period. For NEL, so few sightings occurred that trends are difficult to discern; the highest number of dolphins were encountered in Summer months (June – August) with an encounter rate of < 1 (encounters per 100km surveyed) for the rest of the year. NWL encounter rates show a distinct patterns of increasing rate from spring to summer with the lowest rate recorded in winter. This pattern is also apparent in the long term monitoring data collated by AFCD. Observation of encounter rates for both areas combined indicates that winter and spring encounter rates are reduced when compared to summer and autumn. This trend is apparent in the first year of impact monitoring too. In both years one and two of impact monitoring, no on effort encounters were noted in the quarter March – May in NEL. NEL encounter rates for other quarters are lower in year two, ranging from 2 to 6 dolphins (Year 1) to <1 to 2 dolphins (Year 2) per 100km effort. Within NWL, quarterly encounter rates range from 3 to 6 dolphins (Year 1) and 5 to 9 dolphins (Year 2) per 100km on effort.

3.4.7 Group Size

3.4.7.1 The majority of all sightings recorded were of less than five individual dolphins (75%). Mother and calves were often associated with larger groups (5 or more individual dolphins) and it has been hypothesised that these large groups provide protection and support to calves and mothers. In Hong Kong waters in the past, larger groups have been associated with active fishing trawlers, although trawling was discontinued in Hong Kong prior to the period that this report covers. There is no particular behavioural activity associated with larger group size and the distribution of larger groups is not focused in any particular area (Figure 4 of Appendix H). In the first year of impact monitoring, larger group sizes were associated with fishing vessels. As trawlers are now prohibited in Hong Kong

⁷ The same calculation as implemented in the AFCD Annual Monitoring Reports was used; [(total 'on effort" sightings/total track conducted in Beaufort Sea State 3 or better)*100] for both NEL and NWL separately and for the two areas combined.



⁶ "On effort" sightings are classified as those sightings which are made when the vessel is on the designated trackline and observers are actively searching. "Opportunistic sightings" are those sightings which occur while travelling between tracklines, additional sightings made when travelling back to a transect line after photographing a dolphin group and/or any dolphins noted when transiting between areas or on passage to transect lines.

Annual EM&A Review Report for March 2013- February 2014

waters, there were fewer larger groups recorded between years, may be due to the absence of these trawlers.

3.4.8 Habitat use

- 3.4.8.1 The EM&A Manuel stipulated that surveys be conducted in such a way as to be comparable to the baseline survey for this Contract (September -November 2011) and to the long term annual monitoring conducted by AFCD. As such, analyses of density per survey effort (DPSE) and sightings per survey effort (SPSE) were calculated in accordance with the methodology detailed in AFCD reports (e.g., AFCD 2012⁸). The survey areas are divided into 1km x 1km squares and the relative number of sightings and densities are calculated for each block. NEL has 55 blocks and NWL has 90 blocks (only blocks of more than 0.75km2 are included). For the period March 2013-February 2014, DPSE was calculated in six categories, ranging from low use to high use. NEL and NWL have 0% and 10% of each respective area classified as high use (> 60 DPSE); 0% (NEL) and 14% (NWL) as moderate use (20.1-60 DPSE); and 100% (NEL) and 76% (NWL) as low use (< 20 DPSE). (Figure 5 of Appendix H).
- 3.4.8.2 For the period March 2013-February 2014, SPSE was calculated in six categories, ranging from low use to high use. NEL and NWL have 0% and 8% of each respective area classified as high use (> 15 SPSE); 9% (NEL) and 20% (NWL) as moderate use (5.1-15 SPSE); and 91% (NEL) and 72% (NWL) as low use (< 5 SPSE) (Figure 6 of Appendix H).
- 3.4.8.3 For the period February 2011 January 2012, DPSE was calculated in six categories, ranging from low use to high use. NEL and NWL have 4% and 17% of each respective area classified as high use (> 60 DPSE); 20% (NEL) and 16% (NWL) as moderate use (20.1-60 DPSE); and 76% (NEL) and 68% (NWL) as low use (< 20 DPSE) (Figure 7 of Appendix H). These figures were compared to impact monitoring data for March 2013-February 2014 (Table 3 of Appendix H). For DPSE in NWL, there was an increase in low use grid cells, a decrease in moderate use cells and a decrease in high use cells. Noting the geographical location of the cells between advanced and impact monitoring, (Figures 8 of Appendix H) there are less high use cells in the centre of the NWL area indicating that habitat utilisation of this area has decreased. In NEL, no more high use areas are noted, only low use. The previously most frequented areas adjacent to the Brothers islands are still frequented by dolphins, however, the area along the coast of northern Lantau which was previously frequented by dolphins, has no sightings. This indicates that fewer dolphins occur in NEL and the area they use has reduced. Looking at the pattern observed in year one of impact monitoring, a higher density of dolphins occurred close to HKBCF compared to advanced monitoring, however, by year two, the number and area in which the dolphins occur has reduced.
- 3.4.8.4 For the period February 2011 January 2012, SPSE was calculated in six categories, ranging from low use to high use. NEL and NWL have 9% and 22% of each respective area classified as high use (> 15 SPSE); 31% (NEL) and 27% (NWL) as moderate use (5.1-15 SPSE); and 60% (NEL) and 51% (NWL) as low use (< 5 SPSE) (Figure 7 of Appendix H). These figures were compared to impact monitoring data for March 2013-February 2014 (Table 3 of Appendix H). For SPSE in NWL, there has been an increase in low use grid cells and a reduction in both moderate and high use area. This correlates with that observed for DPSE, unsurprisingly as they are derived from interrelated data (see Figures 3 and 4 of Appendix H). For SPSE in NEL, this is also true, with an observed increase in low use areas and a concomitant decrease in high and moderate use cells, when compared to impact monitoring.
- 3.4.8.5 For March 2012 February 2013, construction activities at HKBCF steadily increased and both DSPE and SPSE, showed a consistent high use of those areas directly adjacent to HKBCF. In March 2013 February 2014, HKBCF peaked in activity and several other Contracts were initiated in the NEL area. Data from the year end of the reporting year indicate that the NEL habitat is being used less than the previous year.

3.4.9 Mother and Calf Pairs

3.4.9.1 Sightings of mothers and calves were made throughout the year mainly in the north of NWL and once, in NEL adjacent to the HKBCF site. (Figure 8 of Appendix H). Although it is often difficult to

⁸ Agriculture, Fisheries and Conservation Department (AFCD) 2012. *Annual Marine Mammal Monitoring Programme April 2011-March 2012.*) The Agriculture, Fisheries and Conservation Department, Government of the Hong Kong SAR.

identify calves, using high resolution images and the identity of mothers, it is sometimes possible to track poorly marked individual calves, while they still stay in close proximity to their mother. Calves were sighted on 25 occasions and comprise a minimum of six individuals using the identity of the mothers to assign identity to the calves. Six known females, HZMB 026, HZMB 044, HZMB 050. HZMB 073, HZMB 098 and HZMB 116 were all photographed with calves. The calf of HZMB 026 was first photographed in January 2013 (outside this reporting year) and again in June 2013. HZMB 026 has not been sighted within this reporting year again. HZMB 044 is a well-known individual and is recorded in AFCD records as NL98. She was first sighted with a calf in September 2012 (outside this reporting year) which was still with her in April 2013. She was sighted again February 2014, and although no calf was closely associated with her, there were two large calves/juvenilles in the group either of which are the correct age class to be a calf born in 2012. HZMB 050 was sighted with a large calf in February 2013 (outside this reporting year) and again in January 2014. Sightings of this individual with a calf have been seen throughout the reporting year. HZMB 073 was first sighted with a calf in October 2012 (outside this reporting year) and again in April 2013. HZNB 073 was also sighted in May 2013, however, there was no calf associated with her during this encounter. Given the behavior of calves to stay closely associated with their mothers for a year plus, it is likely that the calf of HZMB 073 is deceased. No further sightings of HZMB 073 have been recorded since May 2013. HZMB 098 is a well known individual which also features in the AFCD photo identification catalogue (NL104). She was sighted with a calf in May 2013 and most recently in August 2014 (outside the reporting year) still with her calf. HZMB 116 was identified initially in December 2013 when she had a calf. She was subsequently sighted in August 2014 (outside the reporting year) with also with the calf (Figure 9 of Appendix H). In the first year of monitoring, a minimum of 14 individual calves were recorded.

3.4.10 Activities and Associations with Fishing Boats

- 3.4.10.1 Four distinctive behavioural categories were defined; "associated with fishing trawler", "feeding", "travelling" and "surface active". Three other categories were also defined; "multiple" (more than one behaviour was observed at one time), "other" and "unknown". During the spring (March May 2013) and winter (December 2013 February 2014), dolphins were most often engaged in travelling activities (Figure 10 of Appendix H). An increase in travelling activities is noted in Dec 2013-Feb 2014 when compared to Dec 2012-Feb 2013. During the summer and autumn months (June November 2013) foraging activities (both feeding and associated with fishing vessels) was the predominant activity (Figure 11 of Appendix H). This was also the case in June to November 2012 (Figure 12 of Appendix H). Although a ban is in place on commercial trawling, a style of purse seine fishing has become more common in Hong Kong waters and dolphins are often associated with this type of fishing when it occurs in the habitat (Figure 13 of Appendix H).
- 3.4.10.2 During surveys conducted in 2011-12, specific behavioural information was only recorded for approximately 20% of all sightings made. In 2012-13, the area of Lung Kwu Chau in NWL is highlighted as an important feeding area as it is again in 2013-14. The area to the south of NWL is also important for feeding/surface active behaviours (Figure 14 of Appendix H) which highlights the continued importance of this area for multiple activities for all age classes of dolphins, including mother and calf groups.

3.4.11 Photo Identification Catalogue

3.4.11.1 A total of 107 dolphins comprise the photo identification catalogue established specifically for the HZMB Project (Table 4 of Appendix H). Not all dolphins photographed are identifiable as only individuals with unambiguous marks, cuts and/or pigmentation or with uniquely shaped fins can be included in the photo-identification catalogue. Of the identifiable dolphins recorded, the most often sighted dolphins (HZMB 002, HZMB 041; HZMB 044 and HZMB 054) were seen on eleven, nine, nine and fourteen separate days, respectively. Of the 107 dolphins identified during impact monitoring, 53 individuals (just under half) were seen only once between March 2012 and February 2014 (Table 4 of Appendix H). The photo-identification catalogue numbered 94 individuals in year one of impact monitoring. As many of the dolphins that use the waters of NEL and NWL are noted as residents (by other studies, e.g., AFCD annual monitoring) they might therefore, be more likely to be added to the catalogue during the initial effort of the study and thereafter, a lower number of newly identified individuals would be added to the catalogue yearly. This has also been the case in

studies elsewhere of resident delphinid populations. In addition, fewer numbers of dolphins were seen in year one compared to year two of the impact study.

3.4.12 Dolphin Abundance

3.4.12.1 It was not possible to calculate a meaningful abundance estimate for NEL as only 5 on effort sightings were made within the reporting period. For NEL and NWL combined, the overall abundance estimate is 38 [95% CI 6.2, 97.8]).

3.4.13 Environmental Acceptability of the Contract

3.4.13.1 It was recognized in the EIA that the HZMB is adjacent to upon several areas of importance to the dolphin population of Hong Kong. As such, it was stipulated in the EM&A Manuel for the HKBCF that a suitable analytical technique be proposed and implemented so that significant changes could be detected. A multi-parameter spatial (sometimes known as predictive) model was proposed and reviewed by management authorities and analyses developed as and when data has been made available. The purpose of the model was to make predictions of future habitat use, derived from baseline information, and compare these predictions to actual observations. Environmental covariates, such as salinity, temperature, depth, etc., which may also be drivers of dolphin habitat use, are also tested within spatial models so as to either eliminate or incorporate any influence these may have. The model thus incorporated environmental variables salinity, temperature, turbidity, depth, tidal state, time of day, as well as information associated with the sighting, e.g., groups size, behavior, boat association. Following the October 2015 CWD trend meeting, ENPO suggested that the brief information regarding density surface modelling presented in Quarterly EM&A Reports and Annual EM&A Review Reports be provided as a separate report with details for review before incorporating it into the EM&A reports. This ET agreed all such data and results be provided separately for review before incorporating into this and subsequent reports. It is anticipated that the detailed density surface modelling report will be ready for review in early 2016. Following the October 2015 CWD trend meeting, ENPO suggested that the brief information regarding density surface modelling presented in Quarterly EM&A Reports and Annual EM&A Review Reports be provided as a separate report with details for review before incorporating it into the EM&A reports. This ET agreed all such data and results be provided separately for review before incorporating into this and subsequent reports. It is anticipated that the detailed density surface modelling report will be ready for review in early 2016.

3.4.14 **Summary**

- 3.4.14.1 The variable nature of habitat use, group size, behavior, mother and calf occurrence and encounter rates by small delphinids and the ability to detect significant change in small populations is a challenge faced by many research studies. Historical data from AFCD also shows such variability (in AFCD annual monitoring reports). A view of individual distribution and behavioural activities for the reporting year do show that areas of importance, such as Lung Kwu Chau, are still being frequented, behavioural activities appear similar to that known from pre construction information and that several calves have survived throughout the reporting year and beyond. There is an emerging trend for NEL where it seems that fewer sightings are being made and it is likely that data from the third year of activities will confirm this. This is to be expected given that marine construction has been increasing in NEL both with Contract related activities and other marine civil works.
 - 3.4.14.2The modelling approach shows that there has been a significant change in habitat use from baseline to construction phase and areas of previous high density, although still frequented, are still being used by dolphins for many activities. The more spatially explicit model derived from point transect data shows that during the first year of construction, dolphins were shifted, understandably, from the cordoned off HKBCF site itself and, instead, occurred in higher density around the northeast section of the HKBCF site. The modeling approach can be used to test changes in distribution as the works progress whereas the line transect data provides information from the NEL and NWL habitat and the point transect data provides finer scale information on habitat shifts immediately adjacent to the HKBCF site and the Brothers Islands.

3.4.15 Verification of Impact Statements Stated in EIA and Supporting Documentation

- 3.4.15.1The Statements made in the EIA and supporting documents are descriptive and do not provide a quantitative framework against which to compare data gathered the impact monitoring for the purposes of verifying impact on CWD. Further, some statements made pertain only to the operational phase of HZMB (that is, when all in water construction works are completed) and not the explicit impacts of the many different construction activities which are required to construct HZMB. In the interests of thoroughness, any impact statements made in key documents relevant to HKBCF are extracted here and commented on with regards to the data gathered from this the reporting year of construction activities at HKBCF.
- 3.4.15.2The EIA report for HZMB⁹ makes several statements with regards to impact on cetaceans during the construction phase in sections pertaining to water quality and bioaccumulation:
- 3.4.15.3Construction Phase: In section 10.6.4.25 of the EIA report, it is stated that, "Contract has low potential to cause increased sewage discharge, therefore this potential impact is insignificant. The potential water quality impacts due to site runoff, sewage from workforce and wastewater from various construction activities, and accidental spillage would be controlled through the implementation of suitable mitigation measures, including temporary drainage system, chemical toilets, etc"
- 3.4.15.4This Contract has consistently maintained water quality objectives as described in the EM&A Manual except where noted in Section 7.1.5. These exceptions, however, were subsequently found to be unrelated to Contract works.
- 3.4.15.5In Section 10.6.4.37 of the EIA report, it is stated that, "Thus insignificant bioaccumulation impacts from the construction of HKBCF and HKLR are predicted for CWD (except perhaps with the exception of silver as per 10.6.4.32)"
- 3.4.15.6It is noted that for both of the above impact predictions to be investigated more thoroughly, long term trends in pathogens and toxin loads in CWD should be analysed. This has recently been completed for the Pearl River Delta (PRD) population of CWD and it is noted that both bioaccumulation and biomagnification are significantly higher than populations elsewhere (Gui et al 2014¹⁰). In light of this new information, the statements made in the EIA may need to be re-assessed and the allowable limits for water quality parameters revised.
- 3.4.15.7In Section 10.7.2.8 of the EIA report, it is stated that, "164 ha of sea area (138 ha reclamation and 26 ha works area) will be lost during construction due to HKBCF reclamation near the northeast Airport Island. Although the sea area is only utilised by limited number of individual CWD, it is of moderate ecological value due to the close proximity with dolphin hotspot. Moderate impact is anticipated and mitigation measures are required. As the habitat loss due to construction would largely be carried forward to the operational phase and become permanent habitat loss, mitigation measures for operational phase (see Section 10.7.4) will mitigate this impact as well)"
- 3.4.15.8At HKBCF, moderate impact is anticipated but the degree or type of impact is not quantified in any numerical, spatial or temporal scale. In the second year of construction activities at HKBCF there is an emerging pattern of decreased habitat use as indicated by encounter rate and number and type of "high" density cells in NEL. It is anticipated that this trend will become more apparent in 2014-2015 reporting year. Anecdotal information from press reports indicate that a higher than usual mortality has been reported in recent months. Appropriate review of these data should be made by the responsible authority to investigate any possible relationship with both anthropogenic activities and natural processes in the dolphins habitat. The impact of "permanent habitat loss" as a result of the HKBCF reclamation Section 10.7.4. of the EIA), is stated to be fully mitigated by the establishment of a Marine Protected Area after the construction phase of the Contract is completed. This predication

⁹Ove Arup & Partners Hong Kong Ltd 2009 HZMB – HKBCF & HKLR EIA Report. 24037-REP-125-01 Pages 83-5, 97, 115

¹⁰ Gui, D., Yu, R., He, X., Tu, Q., Chen, L. and Wu, Y. Bioaccumulation and biomagnid=fication of persistent organic pollutants in Indo-Pacific humpback dolphins (*Sousa chinensis*) from the Pearl River Estuary, China. *Chemosphere* 114:106-113

- cannot be assessed until the HZMB operational phase starts and the Marine Park Area is established.
- 3.4.15.9The Ecological Baseline Survey¹¹ defines an Impact Index which is used to predict impact for each area through which the HZMB structure passes. HKBCF is located in the area defined as the "Northeast Lantau Section (NELS) - from the eastern edge of the airport platform to its connection to the North Lantau Highway".
- 3.4.15.10 It is noted that this report states (Section 5.7.10) that "it is imperative that cumulative impacts along the whole alignment [of HZMB] are thoroughly assessed".
- 3.4.15.11 A reference to cumulative impacts is made in Section 10.7.6 of the EIA. Section 10.7.6.3 is relevant to HKBCF. This refers only to the cumulative impact of the permanent loss of CWD habitat and no other impacts of either the construction or operational phase of the HZMB Project. Nonetheless, the conclusion of this section states that the setting up of a marine park "effectively mitigates" CWD habitat loss. As such, this prediction cannot be verified until such a time as a marine park is established.
- 3.4.15.12 As a rigorous cumulative assessment has not yet been conducted, there is little quantitative information against which impact survey observations can be made. Further, there are no predictions which deal specifically with the activities at HKBCF and no predictions of direct, temporary or residual impacts on CWD. As such, it is anticipated that impacts to the CWD population which have not been defined in the original EIA will occur as construction activities progress at HKBCF. At this time, a cumulative impact assessment has not yet been conducted

3.4.16 Practicality and Effectiveness of the EM&A Programme

- 3.4.16.1 Monitoring and auditing of marine mammals was recommended for the construction phase of HKBCF to evaluate impact on marine mammals.
- 3.4.16.2Combined line transect and photo-identification methodologies have been used as part of the AFCD long term monitoring programme for over 15 years. As such, a long term data set can be used to establish trends in population distribution and abundance over the long term.
- 3.4.16.3The AFCD annual monitoring reports for the period 2011-2012, 2012-13 and 2013-14 have all stated that a significant decline had been detected in population abundance in the NEL area over the last decade. Only long term inter annual abundance estimates can be used to detect such changes. This decline was noted prior to construction had begun at HKBCF.

3.4.17 Conclusion

- 3.4.17.1Between March 2013 and February 2014, dolphins have not been deterred from the area immediately adjacent to HKBCF although both habitat use and the number of sightings have decreased.
- 3.4.17.2Marine mammal monitoring was conducted between March 2013 and February 2014 in accordance with EM&A Manuel methodologies. These methodologies have been invaluable in the past in determining both broad scale and long term patterns of distribution, abundance, association, habitat use and behavioral activities. There is historically much variation in these parameters and most observations to date have concurred with observations documented previously with the now emerging trend of decreased habitat use within NEL. As AFCD reports have reported a significant decline in this area prior to HKBCF construction activities, it is difficult to distinguish how much HKBCF activities may have influenced this existing decline.

¹¹ Agreement No. MW 01/2003. Hong Kong- Zhuhai- Macao Bridge: Hong Kong Section and the North Lantau Highway Connection: Ecological Baseline Survey. Final 9 Month Ecological Baseline Survey Report the (p 42 - 43)

ENVIRONMENTAL SITE INSPECTION AND AUDIT

Site Inspection 4.1.1

- 4.1.1.1 Site Inspections were carried out on a weekly basis to monitor the implementation of proper environmental pollution control and mitigation measures for the Contract. In the reporting period, 52 site inspections were carried out. Recommendations on remedial actions were given to the Contractors for the deficiencies identified during the site audits.
- 4.1.1.2 Particular observations during the site inspections are described below:

Air Quality

- 4.1.1.3 Stockpile of sand was observed entire surface wet at WA2 and at works area at Portion A. The Contractor was reminded that stockpile of aggregate or dusty materials shall be sprayed with water so as to maintain the entire surface wet; or covered entirely by impervious sheeting or placed in sheltered areas to mitigate potential fugitive dust emission. (Reminder)
- 4.1.1.4 Side curtain attached to the tipping point of a conveyor belt on a filling barge was provided to filling barge but was observed not fully enclosed. The Contractor was reminded to provide a fully enclosed side curtain for filling activities. (Reminder)
- 4.1.1.5 Dark smoke was observed emitted on barges when sand material was being transferred to another barge. The Contractor was reminded to rectify the situation such as to maintain their equipment in good condition to prevent emission of dark smoke. The Contractor maintained their equipment in good condition to prevent emission of dark smoke. (Closed)
- 4.1.1.6 Bags of cement was observed not entirely covered by impervious sheeting, the Contractor was reminded to keep the bags of cement covered entirely by impervious sheeting. The Contractor rectified the situation and kept the bags of cement covered entirely by impervious sheeting. (Closed)

Noise

- 4.1.1.7 An idle air compressor was found without a valid noise emission label on FTB19 and barge Sun Moon Kee. The Contractor was reminded to stick a valid noise emission label onto the compressor prior to operation of the compressor. (Reminder)
- 4.1.1.8 Plants mounted on construction vessels were observed acoustically-decoupled, but a generator was still observed not totally acoustically-decoupled on barge Shang Ho Bo 601 and on barge Fai Yu 3228. The Contractor was advised to continue to provision of enhancement works i.e. to provide sufficient acoustic decoupling measure(s) such as acoustic mat to noisy equipment. The Contractor was reminded that insufficient/inadequate mitigation measures must be swiftly rectified. The Contractor provided sufficient acoustic decoupling measures to generator on Fai Yu 3228. (Reminder)
- 4.1.1.9 Noise Emission Label (NEL) of an air compressor was observed missing. The Contractor was reminded to properly display the NEL on all compressors. The Contractor properly display the NEL the Compressors observed on Kiu Chi. (Closed)

Water Quality

- 4.1.1.10 Disconnected silt curtain was observed at the western side of the silt curtain. The Contractor was advised to provide sufficient mitigation measures and swiftly carry out maintenance once defects of the perimeter silt curtain are found during the daily checking and/or monthly diver inspection. (Closed)
- 4.1.1.11 Defects were observed at portion B (southwest part of the perimeter silt curtain), E2 (northeast part of the perimeter silt curtain) and around portion C2a (northwest part of the perimeter silt curtain) and at portions E1, C2a and C2c. The Contractor rectified the defects of the silt curtain at portion B



(southwest part of the perimeter silt curtain), E2 (northeast part of the perimeter silt curtain) and around portion C2a (northwest part of the perimeter silt curtain) so the silt can be effectively prevented from dispersing from the inside to the outside of the site boundary. Contractor rectified the defects of the localized silt curtain. (Closed)

- 4.1.1.12 Defect was observed within the side of the enclosing silt curtain on barge AP4 and when stone column was installed. The contractor was rectified the defected silt curtain in order to prevent silt plumes from dispersing out from the vicinity of active stone column works. The contractor rectified the defected silt curtain in order to prevent silt plumes from dispersing out from the vicinity of active stone column works.
- 4.1.1.13 A fuel tank which is not in use was observed without drip tray or bunding. The Contractor was reminded to provide mitigation measures such as drip tray or bunding to fuel tank before use. (Reminder)
- 4.1.1.14 Oil drums, chemical containers and generator were observed without the provision of drip trays at Portion, on barge 天駿 3, on barge SHB205, on temporary rock bund and on Portion A. Generator was observed without bunding or drip tray on Sanhang Floating Crane 7, on barge Evershine No.1, barge 401 and FTB17. Machine and generator were observed without drip tray/tarpaulin sheet underneath at rock bund and works area at Portion A and on steel cell. The Contractor provided drip trays to oil drums, chemical container and generator to retain leakage, if any. (Closed)
- 4.1.1.15 Containers of chemical to be used and chemical waste were placed together in Hong Fai. The Contractor should store the chemical and chemical waste separately. Subsequently, the Contractor stored the chemical and chemical waste separately. (Closed)
- 4.1.1.16 Movable lighting machineries were observed to be placed on bare ground of Portion D, on SHB205 and at works area at Portion A without the provision of drip trays. It was observed that drip trays were provided to movable lighting machineries at temporary rock bund and at works area at portion A and on SHB205. The Contractor was advised to continue to provide drip tray or equivalent measures to retain potential oil leakage to movable lighting machineries. (Closed)
- 4.1.1.17 Trays of oil drums were found to be placed near to the shore. The Contractor should secure the oil drums with drip tray away from the shore to ensure no washing off of oil occurs. (Closed)
- 4.1.1.18 One of the existing bunding was found too low on Shang Ho Bo 601, barge FTB 17 and FTB19. The Contractor was reminded to enhance the height of the existing bunding to effectively contain potential oil leakage. The Contractor enhanced the height of the existing bunding to effectively contain potential oil leakage. (Closed)
- 4.1.1.19 The screw at the outlet of a drip tray on barge AP4, FTB20, SHB 208 barge Evershine No.1, FTB17, SHB402, on barge SHB401, on Barge Fai Yu 3228, on barge AP4, on barge Evershine 668, on barge Yat Fai, at works area of portion A and on temporary rock bund was observed missing. The Contractor provided effective mitigation measures to effectively seal the outlet of the drip tray to prevent potential oil seepage in April 2013. The Contractor was advised to provide effective mitigation measures to effectively seal the outlet of the all drip tray to prevent potential oil seepage. (Closed)
- 4.1.1.20 The silt curtain enclosing the stone column installation works was observed removed and as informed by the Contractor, this is due to maintenance of the stone column installation facility. The Contractor was reminded to install a layer of silt curtain near the active stone column installation points. (Reminder)
- 4.1.1.21 Litter and silty plumes were observed when filling material was being used for filling cellular structure number C057. The Contractor stopped the activity to prevent litter and silty plumes from dispersing. The Contractor was advised to provide mitigation measures such as silt curtain to enclose active filling activities at cellular structures to prevent litter and silty plumes from dispersing. (Reminder)

- 4.1.1.22 It was observed that the frame of bunding on barge SHB 401 and on barge Fai Yu 3228 were deformed. The Contractor was reminded to fix the deformed part of frame so that the bunding may have appropriate height to confine potential oil leakage. (Reminder)
- 4.1.1.23 Oil stain was observed on barge FTB19 and SHB205, on barge Fai Yu 3228, Evershine No.1, barge Yat Fat, barge Kiu Chiu and on temporary rock bund. The Contractor was reminded to provide mitigation measures such adsorbents to clean the oil stain. The Contractor immediately provided mitigation measures such as adsorbents to clean the oil stain and treated the used absorbents as chemical waste. (Closed)
- 4.1.1.24 Oil stain was discovered over the sea on 25 July 2013 at 11:20 near the cell K038 at Portion B. The Contractor was advised to follow the actions stated on the Spill Response Plan and clear the oil waste on sea. The Contractor rectified the situation and clear the oil waste on sea using absorption boom according to the Spill Response Plan. The used absorption boom was disposed of as chemical waste. (Closed)
- 4.1.1.25 Turbid water was observed at the southwestern silt curtain entrance area. Refer to the photo taken and site observations, sources of impact likely due to the turbine activities and/or movement of vessel at shallow water (at near the entrance at southwestern of the Construction site and/or when vessel's propeller was turn on at shallow water). The dispersion of turbid water from the inside of the perimeter silt curtain to the outside of the perimeter silt curtain is potentially due to defects of perimeter silt curtain at certain sections and/or insufficient overlapping at entrance/exit of the perimeter silt curtain. The Contractor was advised to regularly evaluate the integrity of the perimeter silt curtain by reviewing the results obtained from daily checking or/and monthly diver inspections specified by the Silt Curtain Deployment Plan. The Contractor was advised to provide sufficient mitigation measures and swiftly carry out maintenance once defects of the perimeter silt curtain are found during the above mentioned daily checking and/or monthly diver inspection. The Contractor was provided mitigation measures and carried out maintenance above mentioned defects of the perimeter silt curtain are found. (Closed)
- 4.1.1.26 The Contractor was advised to regularly evaluate the integrity of the perimeter silt curtain by reviewing the results obtained from daily checking or/and monthly diver inspections specified by the Silt Curtain Deployment Plan. The Contractor was advised to provide sufficient mitigation measures and swiftly carry out maintenance once defects of the perimeter silt curtain are found during the above mentioned daily checking and/or monthly diver inspection. (Closed)
- 4.1.1.27 During site inspection audit, sandfilling seem to be conducted at one end of the temporary rock bund. The Contractor was reminded to conduct sandfilling behind at least 200m leading temporary rock bund/seawall. (Reminder)

Chemical and Waste Management

- 4.1.1.28 Oil drums were found improperly stored on barge Chi Full, Kiu Chi (AP1), FTB20, FTB17, SHB 209, Fai Yui 3228, FTB19, SHB 205, Sun Moon Kee, on barge SHB401, on rock bund, works area at Portion A, on an area outside Contractor's site office. The Contractor immediately provided mitigation measures and put the oil drum inside bunding or remove the oil drum. The Contractor was reminded to provide mitigation measures such as drip tray or bunding to all oil drums. (Reminder)
- 4.1.1.29 Vibratory clamps were found improperly stored on barge SHB305. The Contractor should provide proper measures, like drip trays and tarpaulin sheet coverage, to retain any leaked oil from the plants. Vibratory clamps found improperly stored on barge SHB305 were removed in the reporting month. (Closed)
- 4.1.1.30 Oil drums were found without proper labels on barge FTB 18, FTB 19, FTB17, SHB 209 and Evershine No.1. The Contractor provided mitigation measures and labeled the oil drums. The Contractor was reminded to provide mitigation measures such as labeling to all oil drums. The Contractor provided mitigation measures such as labeling to all oil drums. (Closed)

- 4.1.1.31 General waste was observed uncovered on barge Fai Yui 3228 and SHB305. The Contractor rectified the condition upon notification by providing bin bags to waste and relocated them to a waste collection point. The Contractor was reminded to keep the barge surface clean and tidy. (Reminder)
- 4.1.1.32 Oil stains were observed on the barge surface of barge SHB 208 and FTB 20. The Contractor was reminded to clear the oil stain using absorbent material and dispose of as chemical waste. The Contractor was cleared the oil stain using absorbent material and dispose of as chemical waste. (Closed)
- 4.1.1.33 Oil was observed within the mechanical parts of a machine on FTB18. The Contractor was reminded to prevent oil being transferred from inside the drip tray to the barge surface. (Reminder)
- 4.1.1.34 General waste was observed improperly covered. The Contractor immediately provided mitigation measures such as to remove the general waste via a waste collector. The Contractor was reminded to provide mitigation measures such bin bag(s) or container to properly cover all general waste. (Reminder)
- 4.1.1.35 Waste water was observed accumulated inside bunding on FTB21. The Contractor was reminded to clear the waste oil with water and disposed of as chemical waste. The Contractor cleared the waste oil with water and disposed of as chemical waste. (Closed)
- 4.1.1.36 A battery and chemical container was observed placed on barge FTB20 without drip tray. The Contractor was relocated that battery and chemical container inside the drip tray immediately. (Closed)
- 4.1.1.37 Bags of waste were observed accumulated on barge Four Sea 8, barge Hing Fai, barge AP4 and various locations on a works area at Portion A. The Contractor was reminded to clear the waste regularly to prevent accumulation. (Reminder)
- 4.1.1.38 Litter and general refuse was observed accumulated on sea. The Contractor was reminded to avoid/clear any foam, oil, grease, chemicals, litter, food or other objectionable matter due to the Contract works presented in the water within and adjacent to the works site. The Contractor avoided any foam, oil, grease, chemicals, litter, food or other objectionable matter due to the Contract works presented in the water within and adjacent to the works site. The Contractor was reminded to collect and clear the waste on sea regularly. (Closed)

- 4.1.1.39 General refuse were found on various location of the works area at Portion A. The Contractor was reminded to clear the general refuse regularly. The Contractor was reminded to maintain the site in a clean and tidy condition i.e. to properly store the general refuse at designated waste storage area(s). The Contractor cleared the general maintain the site in a clean and tidy condition. (Closed)
- 4.1.1.40 Rubbish bin was observed without being covered; the Contractor was reminded to properly store general waste and covers all rubbish bins. The Contractor properly store general waste and covers all rubbish bins. (Closed).
- 4.1.1.41 Construction waste such as band drain was observed along the northern edge of works area at Portion A and on edge of temporary rock bund. The Contractor was advice to properly store and dispose construction waste such as band drain. (Closed)

Landscape and Visual Impact

4.1.1.42 No adverse observation was identified in the reporting period.

Others

- 4.1.1.43 The Contractor was reminded to properly display relevant Environmental Permit at an appropriate location i.e. near entrance on barge Kam Shun 368, so that it may be easily noticed. (Reminder)
- 4.1.1.44 Water was observed accumulate inside car tyre on barge Yat Fat. The Contractor was reminded to keep the site clean and tidy and clear the water accumulated inside car to prevent mosquito breeding. The Contractor rectified the situation by clearing the car tyre on barge Yat Fat. (Closed)
- 4.1.1.45 The Contractor has rectified most of the observations as identified during environmental site inspection in the reporting period. Rectifications of remaining identified items are undergoing by the Contractor. Follow-up inspections on the status on provision of mitigation measures will be conducted to ensure all identified items are mitigated properly.

5 ADVICE ON THE SOLID AND LIQUID WASTE MANAGEMENT STATUS

5.1 Summary of Solid and Liquid Waste Management

- 5.1.1 The Contractor registered as a chemical waste producer for this Contract. Sufficient numbers of receptacles were available for general refuse collection and sorting.
- 5.1.2 As advised by the Contractor, 7,540,721.9 m³ of imported fill were imported for the Contract use in the reporting period. 24.3kg of metals, 956kg of paper/cardboard packaging, 550.1kg of plastics, 14,000kg of chemical waste and 312m³ of others, e.g. general refuse were generated and disposed of in the reporting period. Summary of waste flow table is detailed in Appendix I.
- 5.1.3 The Contractor is advised to properly maintain on site C&D materials and wastes collection, sorting and recording system, dispose of C&D materials and wastes at designated ground and maximize reuse / recycle of C&D materials and wastes. The Contractor is reminded to properly maintain the site tidiness and dispose of the wastes accumulated on site regularly and properly.
- 5.1.4 The Contractor is reminded that chemical waste containers should be properly treated and stored temporarily in designated chemical waste storage area on site in accordance with the Code of Practice on the Packaging, Labelling and Storage of Chemical Wastes.

6 IMPLEMENTATION STATUS OF ENVIRONMENTAL MITIGATION MEASURES

6.1 Implementation Status of Environmental Mitigation Measures

- 6.1.1 As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 regarding the suspected violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012. The details of the non-compliance, investigation actions taken including follow-up site inspection conducted out by the ET and rectification actions and preventive actions provided by the Contractor was summarized at section 7 of the Quarterly EM&A summary report for September 2012 November 2012. As informed by the Contractor in August 13, the Contractor was subsequently prosecuted on 21 May 2013 for breaching Cap.400 Noise Control Ordinance.
- 6.1.2 A summary of the Implementation Schedule of Environmental Mitigation Measures (EMIS) is presented in Appendix C. Moreover, regular review and checking on the construction methodologies, working processes and plants were carried out to ensure the environmental impacts were kept minimal and recommended environmental mitigation measures were implemented effectively.
- 6.1.3 Training of marine travel route for marine vessels operator was given to relevant staff and relevant records were kept properly.
- 6.1.4 Regarding the implementation of dolphin monitoring and protection measures (i.e. implementation of Dolphin Watching Plan, Dolphin Exclusion Zone and Silt Curtain integrity Check), regular checking were conducted by the experienced MMOs within the works area to ensure no dolphin was trapped by the enclosed silt curtain systems. Any dolphin spotted within the enclosed silt curtain systems was reported and recorded. Relevant procedures were followed and measures were well implemented. Silt curtain systems were also inspected timely in accordance to the submitted plan. All inspection records were kept properly.
- 6.1.5 Acoustic decoupling measures on noisy plants on construction vessels were checked regularly and these measures were well implemented.
- 6.1.6 The Contractor was reminded to carry out necessary actions to rectify the above deficiencies and the Contractor was reminded not to operate those PME during restricted hours without compliance with the CNP conditions.
- 6.1.7 The Contractor was reminded to strictly comply with the condition of the CNP.

7 SUMMARY OF EXCEEDANCES OF THE ENVIRONMENTAL QUALITY PERFORMANCE LIMIT

7.1 Summary of Exceedances of the Environmental Quality Performance Limit

- 7.1.1. A total of 15 Action level and 5 Limit Level exceedances were recorded during the 24-hr TSP impact monitoring period. No exceedance of 1-hour TSP exceedance level was recorded at all monitoring station during the 1-hr TSP impact monitoring period. Investigation into the possible causes of each exceedance was undertaken and reported in the respective monthly EM&A reports.
- 7.1.2. One complains was received; one (1) Action Level Exceedance of construction noise was recorded in the reporting period. Investigation into the possible causes of such exceedance was undertaken and reported in the respective monthly EM&A reports, the investigations results confirmed that the limit level exceedance was not related to Contract.
- 7.1.3. The Contractor was recommended to continue implementing existing noise mitigation measures.
- 7.1.4. Fifty-six (56) Action Level exceedances and seven (7) Limit Level exceedances were recorded at measured suspended solids (SS) values (in mg/L), one (1) Action Level exceedances were recorded at measured turbidity (in NTU), six (6) Action Level exceedance was recorded at measured DO (Bottom) (mg/L) and one (1) Limit Level exceedance was recorded at measured DO (S&M) (mg/L) during the reporting period. Investigation result shows that all the exceedances were not due to the Contract works except the Action Level Exceedance recorded at SR5 and Limit Level Exceedance recorded at IS10 on 18 Dec 13 were related to Contract.
- 7.1.5. Cumulative statistics on exceedances is provided in Appendix J.

8 SUMMARY OF COMPLAINTS, NOTIFICATION OF SUMMONS AND SUCCESSFUL PROSECUTIONS

- 8.1 Summary of Environmental Compliants, Notification of Summons and Successful Prosecutions
- 8.1.1 Total of eleven (11) environmental complaints were received in the reporting period. The Environmental Complaint Handling Procedure is annexed in Figure 5.
- 8.1.2 One (1) complaint was referred by EPD to ET regarding the construction noise impact from cranes operating from the barges for the Hong Kong –Zhuhai-Macao Bridge Hong Kong Project generating squeak noise in the evening of 1 Mar 2013 causing annoyance to him/her. The investigation results show that the complaint was non-Contract related.
- 8.1.3 One (1) complaint was referred by EPD regarding oil dumping observed from various vessels operating for HZMB HK Contracts near Tung Chung Development Pier over the past few months. The investigation results showed that the complaint was non-Contract related.
- 8.1.4 One (1) complaint referred to the Contractor by EPD on 10 May 2013 regarding the scattered debris of silt curtain noted at Sha Lou Wan and Tung Chung Bay. Immediate inspection and clean up action was taken by the Contractor.
- 8.1.5 One (1) follow-up complaint referred by EPD was received on 23 May 2013 regarding the oil stain noted near Tung Chung Development Pier for past few months.
- 8.1.6 One (1) complaint was logged by the Contractor regarding the leakage from work barges causing water pollution near Tuen Mun Richland Garden received on 26 Sept 13. With refer to the available information such as photo record of the incident cannot indicate that the leakage from work barges was caused by the vessel of this Contract and the complaint could not be concluded as Contract related.
- 8.1.7 As informed by the Contractor on 5 Nov 13, one (1) noise complaint received on 14 Sept 13 was referred to the Contractor of HKBCF on 1 Nov 13. The captioned complaint involves noise generated by a tug boat operating near a pier at Tung Chung around 05:55am-06:45am on 14 Sept 13. After investigation, the complaint is considered not likely to be related to the construction works
- 8.1.8 As informed by the Contractor, complaint received from Penta-Ocean Gitanes Joint Venture (CV/2012/03) mentioned that the formation works of the Contaminated Mud Pit CMP1 to the South of the Brothers (CMP1 of SB) which has been completed in mid-August 2013 and the pit has been commissioned for receiving contaminated marine mud from other Contracts starting from 16 August 2013. However, it was recently observed that some of the Contract vessels of HY/2010/02 had berthed within the said pit and those anchorages would likely cause disruption to the underlying contaminated mud and thus induce unfavourable contamination impact to the surrounding marine environment. In this regard, they reminded the contractor to avoid berthing of their vessels within the boundary of CMP1 of SB thereafter for the sake of environmental concern. After investigation, the complaint is considered not likely to be related to the construction works.
- 8.1.9 As informed by the Contractor on 5 Dec 13, one complaint was noted on 12 Nov regarding a barge moving through the southern channel. After investigation, the noise complaint was considered as non-Contract related.
- 8.1.10 As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract

- 8.1.11 As informed by the Contractor on 6 Jan 14, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen Mun Pierhead Garden which caused disturbance to residence was received on 27 Dec 13. With refer to available information provided, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract.
- 8.1.12 EPD referred a complaint from complainant who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02
- 8.1.13 1 summons and 1 prosecution were recorded in this reporting period. As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 regarding the suspected violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012. The details of the non-compliance, investigation actions taken including follow-up site inspection conducted out by the ET and rectification actions and preventive actions provided by the Contractor was summarized at section 7 of the Quarterly EM&A summary report for September 2012 November 2012. As informed by the Contractor in August 13, the Contractor was subsequently prosecuted on 21 May 2013 for breaching Cap.400 Noise Control Ordinance.
- 8.1.14 Statistics on complaints, notifications of summons and successful prosecutions are summarized in Appendix J.

9 REVIEW OF THE VALIDITY OF THE EIA PREDICTION

- 9.1 A total of 15 Action level and 5 Limit Level exceedances were recorded during the 24-hr TSP impact monitoring in the reporting period and it was considered not related to the Contract works. All the rest of air quality monitoring results in the reporting period were below the Action Levels established in the baseline air quality monitoring carried out in November 2011. The result was in line with the Environmental Impact Assessment (EIA) prediction that dust generation would be controlled and would not exceed the acceptable criteria, with proper implementation of the recommended dust mitigation measures.
- 9.2 Only one (1) construction noise monitoring exceedance was recorded in the reporting period. This is generally in line with the EIA and ERR prediction that with the implementation of noise mitigation measures, the construction noise from the Contract works will meet the stipulated criterion at the residential NSRs and at a majority of the education institutions as predicted by the EIA.
- 9.3 71 water quality monitoring exceedances were recorded in the reporting period and it was considered not related to the Contract works except 1 Action Level exceedance recorded at SR5 and Limit Level Exceedance recorded at IS10 on 18 Dec 13 were considered as related to Contract. As rectification was provided by the Contractor and recurrence of Contract related exceedance was not observed in the subsequent monitoring events. Considering all the rest of water quality monitoring results in the reporting period were below the Action Levels established in the baseline water quality monitoring carried out in November 2011. The result was in line with the Environmental Impact Assessment (EIA) prediction that water quality impact would be controlled and would not exceed the acceptable criteria, with proper implementation of the recommended water quality mitigation measures.

10 REVIEW OF ENVIRONMENTAL IMPLEMENTATION STATUS

- 10.1 The impact air quality, noise and water quality monitoring programme ensured that any environmental impact to the receivers would be readily detected and timely actions could be taken to rectify any non-compliance. The environmental monitoring results indicated that the construction activities in general were in compliance with the relevant environmental requirements and were environmentally acceptable. The weekly site inspection ensured that all the environmental mitigation measures recommended in the EIA were effectively implemented. Despite the minor deficiencies found during site audits, the Contractor had taken appropriate actions to rectify deficiencies within reasonable timeframe. Therefore, the effectiveness and efficiency of the mitigation measures were considered high in most of the time.
- 10.2 For all the parameters under monitoring as mentioned in Section 3, the measured levels were in line with the EIA predictions generally. This indicates that the mitigation measures were effectively implemented.

11 REVIEW OF EM&A PROGRAMME

- 11.1 The environmental monitoring methodology was considered well established as the monitoring results were found in line with the EIA predictions.
- 11.2 As effective follow up actions were promptly taken once exceedances were recorded, no further exceedance occurred for each case. The EM&A programme was considered successfully and

12 COMMENTS, RECOMMENDATIONS AND CONCLUSIONS

12.1 Comments on mitigation measures

12.1.1 According to the environmental site inspections performed in the reporting period, the following recommendations were provided:

12.2 Air Quality Impact

- All working plants and vessels on site should be regularly inspected and properly maintained to avoid dark smoke emission.
- All vehicles should be washed to remove any dusty materials before leaving the site.
- Haul roads should be sufficiently dampened to minimize fugitive dust generation.
- Wheel washing facilities should be properly maintained and reviewed to ensure properly functioning.
- Temporary exposed slopes and open stockpiles should be properly covered.
- Enclosure should be erected for cement debagging, batching and mixing operations.
- Water spraying should be provided to suppress fugitive dust for any dusty construction activity.

12.3 Construction Noise Impact

- Quieter powered mechanical equipment should be used as far as possible.
- Noisy operations should be oriented to a direction away from sensitive receivers as far as possible.
- Proper and effective noise control measures for operating equipment and machinery on-site should be provided, such as erection of movable noise barriers or enclosure for noisy plants. Closely check and replace the sound insulation materials regularly
- Vessels and equipment operating should be checked regularly and properly maintained.
- Noise Emission Label (NEL) shall be affixed to the air compressor and hand-held breaker operating within works area.
- Better scheduling of construction works to minimize noise nuisance.

12.4 Water Quality Impact

- Regular review and maintenance of silt curtain systems, drainage systems and desilting facilities in order to make sure they are functioning effectively.
- Construction of seawall should be completed as early as possible.
- Regular inspect and review the loading process from barges to avoid splashing of material.
- Silt, debris and leaves accumulated at public drains, wheel washing bays and perimeter u-channels and desilting facilities should be cleaned up regularly.
- Silty effluent should be treated/ desilted before discharged. Untreated effluent should be prevented from entering public drain channel.
- Proper drainage channels/bunds should be provided at the site boundaries to collect/intercept the surface run-off from works areas.
- Exposed slopes and stockpiles should be covered up properly during rainstorm.

12.5 Chemical and Waste Management

- All types of wastes, both on land and floating in the sea, should be collected and sorted properly
 and disposed of timely and properly. They should be properly stored in designated areas within
 works areas temporarily.
- All chemical containers and oil drums should be properly stored and labelled.
- All plants and vehicles on site should be properly maintained to prevent oil leakage.
- All kinds of maintenance works should be carried out within roofed, paved and confined areas.
- All drain holes of the drip trays utilized within works areas should be properly plugged to avoid any oil and chemical waste leakage.
- Oil stains on soil surface and empty chemical containers should be cleared and disposed of as chemical waste.
- Regular review should be conducted for working barges and patrol boats to ensure sufficient
 measures and spill control kits were provided on working barges and patrol boats to avoid any
 spreading of leaked oil/chemicals.

12.6 Landscape and Visual Impact

 All existing, retained/transplanted trees at the works areas should be properly fenced off and regularly inspected.


12.7 Recommendations on EM&A Programme


- 12.7.1. The impact monitoring programme for air quality, noise, water quality and dolphin ensured that any deterioration in environmental condition was readily detected and timely actions taken to rectify any non-compliance. Assessment and analysis of monitoring results collected demonstrated the environmental impacts of the Contract. With implementation of recommended effective environmental mitigation measures, the Contract's environmental impacts were considered as environmentally acceptable. The weekly environmental site inspections ensured that all the environmental mitigation measures recommended were effectively implemented.
- 12.7.2. The recommended environmental mitigation measures, as included in the EM&A programme, effectively minimize the potential environmental impacts from the Contract. Also, the EM&A programme effectively monitored the environmental impacts from the construction activities and ensure the proper implementation of mitigation measures. No particular recommendation was advised for the improvement of the programme.


12.8 Conclusions

- 12.8.1 The construction phase and EM&A programme of the Contract commenced on 12 March 2012.
- 12.8.2 A total of 15 Action level and 5 Limit Level exceedances were recorded during the 24-hr TSP impact monitoring period. No exceedance of 1-hour TSP exceedance level was recorded at all monitoring station during the 1-hr TSP impact monitoring period. Investigation into the possible causes of each exceedance was undertaken and reported in the respective monthly EM&A reports, the investigations results confirmed that the air quality exceedances were not related to Contract. Possible dust generating activities of the Contract did not cause any noticeable deterioration in air quality at the area. The average 24-hour TSP level recorded at AMS7 in EM&A programme was lower than the daily dust level predicted in the EIA.
- 12.8.3 There was (1) one action level exceedance recorded due to one noise complaint was received. Noise generating activities of the Contract did not cause any noticeable noise impact at the sensitive receivers. The impact noise levels recorded were generally similar to the predicted construction noise levels in the Project EIA.
- 12.8.4 Fifty-six (56) Action Level exceedances and seven (7) Limit Level exceedances were recorded at measured suspended solids (SS) values (in mg/L), one (1) Action Level exceedances were recorded at measured turbidity (in NTU), six (6) Action Level exceedance was recorded at measured DO (Bottom) (mg/L) and one (1) Limit Level exceedance was recorded at measured DO (S&M) (mg/L) during the reporting period. Investigation result shows that all the exceedances were not due to the Contract works except the Action Level Exceedance recorded at SR5 and Limit Level Exceedance recorded at IS10 on 18 Dec 13 were related to Contract. After review of investigation results of water quality exceedances (for detail of investigations please refer to section 4 of monthly EM&A report (Mar 12 to Feb 13), ambient conditions were considered to have effects on the water quality monitoring results. Exceedances were considered to be due to a combination of the following potential causes 1. Rough sea condition caused by adverse weather and relatively strong current experienced during the monitoring period and 2. During the time when exceedances of DO were recorded at monitoring stations, relatively low DO values were also recorded at corresponding upstream Control Stations during ebb tide or flood tides indicating these exceedances of DO were unlikely to be contributed by Contract works. This indicated these exceedances of DO were unlikely to be contributed by Contract works. 3. Local effects in the vicinity of the monitoring station where exceedance was recorded. With proper implementation of water quality mitigation measures, marine construction activities of the Contract did not cause any unacceptable water quality impacts to the receivers.
- 12.8.5 One (1) Limit level exceedance and six (6) Action Level Exceedances were recorded in the reporting period for impact dolphin monitoring. The investigation results showed that although no unacceptable changes in environmental parameters of this Contract have been measured, at this time it is not possible to make a conclusive assessment of this Contract's specific impact on dolphins. Event and Action Plan for Impact Dolphin Monitoring was triggered. For investigation results please refer to Appendix L of the corresponding quarterly reports.
- 12.8.6 Environmental site inspection was carried out 52 times in the reporting period. Recommendations on remedial actions were given to the Contractors for the deficiencies identified during the site audits.
- 12.8.7 Eleven (11) environmental complaints were received in the reporting period.
- 12.8.8 One (1) summons and one (1) successful prosecution was received in the reporting period.
- 12.8.9 As discussed in the above sections, the Contract did not cause unacceptable environmental impacts or disturbance to air quality, noise, water quality in the vicinity near the reclamation works.
- 12.8.10 Apart from the above mentioned monitoring, most of the recommended mitigation measures, as included in the EM&A programme, were implemented properly in the reporting period.

- 12.8.11 The recommended environmental mitigation measures effectively minimize the potential environmental impacts from the Contract. The EM&A programme effectively monitored the environmental impacts from the construction activities and ensure the proper implementation of mitigation measures. No particular recommendation was advised for the improvement of the programme.
- 12.8.12 Moreover, regular review and checking on the construction methodologies, working processes and plants were carried out to ensure the environmental impacts were kept minimal and recommended environmental mitigation measures were implemented effectively.








HONG KONG - ZHUHAI - MACAO BRIDGE
HONG KONG BOUNDARY CROSSING FACILITIES
- RECLAMATION WORKS
Project No.: 60249820 Date: APR 2012






HONG KONG - ZHUHAI - MACAO BRIDGE HONG KONG BOUNDARY CROSSING FACILITIES - RECLAMATION WORKS

Project No.: 60249820 Date: January 13






HONG KONG - ZHUHAI - MACAO BRIDGE HONG KONG BOUNDARY CROSSING FACILITIES

- RECLAMATION WORKS



Project No.: 60249820 Date: July 2012 Figure 5


Environmental Complaint Handling Procedure



HONG KONG - ZHUHAI - MACAO BRIDGE HONG KONG BOUNDARY CROSSING FACILITIES --RECLAMATION WORKS Project No.: 60249820 Date: March 2013


Project Organisation for Environmental Works





ontra	ct No. HY/	2010/02 Hong Kong - Zhuhai - Macao Bridge	Hong Kong B	oundary Cros	sing Faci	lities -	Reclama	tion Wo	orks							
ivity ID		Activity Name	Original Start Duration	Finish	Mar	Apr	May	Jun	2013 Jul	Aug	Sep	Oct	Nov	Dec		2014 Feb N
	SC0B-1050	PB Stone Columns K013 - K015 4cells 603nrs/1,104nrs (19nrs/day) FTB-20 from 6Sep2013	42 06-Sep-13 A	20-Oct-13 A	16	17	18	19	20	21	22	23	24	25	26	27
		- K20 5cells 1,950Nos		30-Oct-13 A				•		! !			÷		1	
		PB Stone Columns K016 - K020 4cells 203nrs/1,950nrs upto 12Jul2013	16 26-Jun-13 A	12-Jul-13 A	-					1			1 1 1		1	
		PB Stone Columns K016 - K018 3cells 229nrs/1,950nrs upto 23Aug2013 FTB-AP3	29 24-Jul-13 A	23-Aug-13 A				-		<u> </u>					 	
╟		PB Stone Columns K016 - K018 3cells 765nrs/1,950nrs (19nrs/day) FTB19	62 24-Aug-13 A		_		! ! !	!				! ! !	:]:	 		
		- K23 3Cells 1,144Nos	184 26-Apr-13 A	10-Nov-13 A		•	7	1					-			
		PB Stone Columns K021 - K023 3cells 143nrs/1144nrs upto 13Jun2013	46 26-Apr-13 A	13-Jun-13 A	-		į									
		PB Stone Columns K019 - K022 3cells 519nrs/1144nrs	58 14-Jun-13 A	15-Aug-13 A	-										1	
		PB Stone Columns K019 - K022 3cells 342nrs/1144nrs (19nrs/day) FTB19	10 31-Oα-13 A	10-Nov-13 A			 	<u> </u>		<u> </u>		¦ 		 	 	
		PB Stone Columns K019 - K022 3cells 283nrs/1144nrs (14nrs/day) FTB20	19 21-Oct-13 A	10-Nov-13 A	-					 		_			1	
ľ		- K27 4Cells 1,568Nos	138 14-Jun-13 A	10-Nov-13 A			!	_		1			-	1		
		PB Stone Columns K024 - K027 5Cells 850nrs/1568nrs FTB-AP2 from 14Jun to 15Aug2013	58 14-Jun-13 A	15-Aug-13 A	-											
		PB Stone Columns outermost K024 - K027 5Cells 1051nrs/1568nrs (19nrs/day) from 16Aug2013 FTB			-										1	
		113 - C117 5Cells 3,258Nos	419 05-Feb-13 A												 	
╟		PC2A Stone Columns C113 - C117 5cells 329nrs FTB17 upto 20Mar2013	38 05-Feb-13 A							1						
		PC2A Stone Columns C113 - C117 5cells 753nrs (19nrs/day) FTB16 upto 13Jun2013		05-Jun-13 A) 1 1 1						
⊩		PC2A Stone Columns outermost C113 - C117 5cells 613nrs upto 31Jul13'	44 14-Jun-13 A					<u> </u>	!	i.			1		1	
⊩		PC2A Stone Columns outermost C116 - C117 5cells 362nrs (19nrs/day) FTB17 from 5Sep2013	17 05-Sep-13 A			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				*) ; ;		! !	1		1	
		PC2A Stone Columns outermost C113 - C115 5cells 1,614nrs (19nrs/day) FTB17	164 11-Nov-13 A	·						<u> </u>					 	
L		s Inside cellular structures by Marine Plant	101 21-Jan-13 A	12-May-13 A		 	<u> </u>) 				 	! ! !	
		on C2a at C103 - C112 10cells 1100nrs	80 21-Jan-13 A	19-Apr-13 A						1						
		PC2a Stone Columns insdie cells & 2rows 2cells 522nrs/1100nrs (15nrs/day) FTB18	80 21-Jan-13 A	19-Apr-13 A		•				1			1		1	
		on E2 at C060 - C067 8cells @80nrs/cell 640nrs	25 16-Apr-13 A	12-May-13 A		_				 			1		1	
		PE2 Stone Columns inside cells & 2rows 8cells C060 - C067 640nrs (15nrs/day) FTB18	25 16-Apr-13 A							<u>+</u>					 	
L .		s Outside cellular Structures by Marine Plant	311 26-Jun-13 A					•					1		i !	
		on B at K028 - K052 25cells 4,910nrs	233 04-Jul-13 A	15-Mar-14 A												
		PB Stone Columns outermost K028 - K051 17cells 832nrs upto 11Sep2013	65 04-Jul-13 A	11-Sep-13 A	-					!					1	
l		PB Stone Columns beside K028 - K051 24cells 358nrs upto 12Sep13' AP1, 2, 3 & 5	66 04-Jul-13 A	12-Sep-13 A	_	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				!		1	1		1	
⊩		PB Stone Columns outermost K028 - K053 24cells 770nrs from 12Sep13' to 9Nov2013	55 12-Sep-13 A					ļ	-			<u> </u> 	<u> </u>		i !	
⊩		PB Stone Columns beside K028 - K053 24cells 666nrs from 12Sep13' to 9Nov2013	55 12-Sep-13 A		_							 	!			
	K028 - K040	T D Clothe Columnia Docume 1000 2 10000 Columnia 11000 1200p 10 to chevizoro	90 25-Nov-13 A				!			 		! ! !	_		1	
		PB Stone Columns K028 - K031 Row 01-11 61nrs (8nrs/day) FTB16	19 29-Dec-13 A							1						
		PB Stone Columns K028 - K031 Row 12-14 134nrs (8nrs/day) FTB16	38 09-Dec-13 A			 	!			 			1			
		PB Stone Columns K032 - K037 Row 01-11 124 (14nrs/day) FTB20	51 25-Nov-13 A						-	<u>+</u>		<u> </u>	ļ			
		PB Stone Columns K032 - K036 Row 12-14 233nrs (6nrs/day) AP5	23 05-Feb-14 A										-			
		PB Stone Columns K038 - K040 Row 01-11 110 (14nrs/day) FTB19	53 25-Nov-13 A					1	1	1			-			
		PB Stone Columns K037 - K040 Row 12-14 202nrs (6nrs/day) AP6	32 26-Jan-14 A										-			
	K041 - K046		75 21-Dec-13 A				 			1 1 1 1			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	_	-	
			34th Monthly Progress Report Status		Ver EhE		CIN tilt	ET D	roce D	ort N4== 1))))))))	h 204.4	1	-	!	
	Remaining Level of				vei.oiio			•	•		2013 to Fe ne Aggree		n)			
	Actual Level of Actual Work	TEHOIT V Suffilliary	Page 2 of 1	6			-				00 /	, (,			
	Remaining Wo	ork														
	Critical Remain	ning Work													Primavera	Systems,

Contract No. HY/2010/02 Hong Kong - Zhuhai - Macao Bridge	Hor	ng Kong B	oundary Cross	ing Facil	lities - F	Reclamat	ion Wo	rks							
Activity ID Activity Name	Original Duration	Start	Finish	Mar	I Apr	May	2 Jun	013 Jul	Aug	Sep	Oct	Nov	Dec		2014 Feb M
SCOB-B010 PB Stone Columns K041 - K043 Row 01-11 233nrs (14nrs/day) FTB19		21 Feb 14 A	06-Mar-14 A	16	17	18	19	20	21	22	23	24	25	26	27 2
				-	1 1	1	: 		: ! !				_		
SCOB-B020 PB Stone Columns K041 - K043 Row 12-14 168nrs (8nrs/day) FTB16			24-Feb-14 A	_	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1	 	1	 		 	 	_	1	
SCOB-B030 PB Stone Columns K044 - K046 Row 01-11 125nrs (14nrs/day) FTB20			06-Mar-14 A		1 1 1	1 1 1	i 	1	i ! !			1			
SCOB-B040 PB Stone Columns K044 - K046 Row 12-14 142nrs (8nrs/day) FTB16			15-Mar-14 A		1 1 1 1 1	1	! ! !		! ! !					1	
K047 - K052			25-Feb-14 A			ļ 	! ! !	<u> </u>	! ! !		<u> </u>				
SCOB-C020 PB Stone Columns K047 - K052 Row 01-11 28nrs (6nrs/day) AP6	5	21-Feb-14 A	25-Feb-14 A		1	1	! ! !		! ! !						_
SCOB-C030 PB Stone Columns K047 - K052 Row 12-14 174nrs (6nrs/day) AP6	18	03-Dec-13 A	21-Dec-13 A		1	1	! !		! !						
Seawall Portion E2 at K053 - C067 2,252nrs	236	26-Jun-13 A	11-Mar-14 A				▼		1						
K053 - C067	236	26-Jun-13 A	11-Mar-14 A		1	1	•	1	1			1			
SCOE2-0010 PE2 Stone Columns outside K063 - K067 5cells 1395nrs (19nrs/day) FTB19	14	26-Jun-13 A	10-Jul-13 A		 	1		1	 						
SCOE2-0020 PE2 Stone Columns beside K063 - K067 5cells 117nrs upto 9Nov2013	36	12-Sep-13 A	20-Oct-13 A		- 	- 	 	- 	 				 		
SCOE2-A010 PE2 Stone Columns K053 - K056 Row 01-11 251nrs (14nrs/day) FTB20	18	21-Feb-14 A	11-Mar-14 A		1 1 1	1 1 1 1	i 	1	i 						
SCOE2-A020 PE2 Stone Columns K053 - K056 Row 12-14 160nrs (6nrs/day) AP5	93	25-Nov-13 A	08-Mar-14 A		1 1 1 1	1	! ! !		! ! !			_		1	
Seawall Portion E1 at C068 - C091 24cells 6,428nrs	93	21-Feb-14 A	31-May-14 A		1	1	!		!						—
C068 - C079	93	21-Feb-14 A	31-May-14 A		: : : :	1	: 		! !						-
SCOE1-A03(PE1 Stone Columns C072 - C075 Row 01-11 769nrs (14nrs/day) FTB20	93	21-Feb-14 A	31-May-14 A				 		 		¦				
C080 - C091			10-May-14 A		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	! !		1						_
SCOE1-B03(PE1 Stone Columns C084 - C084 Row 01-11 94nrs (8nrs/day) FTB16			26-Feb-14 A		1	1	! ! !		! ! !						
SCOE1-B06(PE1 Stone Columns C079 - C091 Row 12-14 279nrs (6nrs/day) AP7			10-May-14 A		1	1	! ! !		! ! !						
Seawall Portion C at C103 - C112 10cells @197nrs/cell 1970nrs			06-Mar-14 A		: : : :	1	! !		! !				i !		
Beside of front cellular walls C103-C112 985nrs		·	06-Mar-14 A			ļ -	¦ ¦	- 	¦ ¦	ļ <u></u>	<u> </u>	ļ			
						1					!			1	
SCOC-A010 PC2a Stone Columns C112 - C103 10cells 620nrs (19nrs/day) FTB18 upto 9Nov2013			09-Nov-13 A	-	1 1 1 1	1	! ! !		! ! !		1				
SCOC-A020 PC2a Stone Columns C105 - C106 Row 01-11 276nrs (18nrs/day) FTB18			06-Mar-14 A		1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	!		!		1		1	1	1
Stone Columns Inside cells by Land Plant 2,640nrs			30-May-14 A		1	1	! ! !		! ! !		1	1	1	1	
Seawall Portion B at K028 - K051 24cells 1,920nrs			22-May-14 A		 	ļ -	! ! !		 		<u> </u>	ļ		ļ	
SCIB0-005 PB Trial Stone Columns inside cells at K044 57nrs (6nrs/day/plant)	15	02-Sep-13 A	17-Sep-13 A		 	1	; ; ; ;		! !						
SCIB0-010 PB Stone Columns inside cells K028 - K030 191nrs (5nrs/day) LB-AP2	38	25-Nov-13 A	03-Jan-14 A		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1	 		 			_		•	
SCIB0-020 PB Stone Columns inside cells K031 - K032 151nrs (5nrs/day) LB-AP1	30	25-Nov-13 A	26-Dec-13 A		1 1 1	1	! ! !	1	1			_			
SCIB0-030 PB Stone Columns inside cells K033 - K036 274nrs (3nrs/day) LB-BV1	73	25-Nov-13 A	14-Feb-14 A		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1	! ! !		! ! !			_	1	1	_
SCIB0-040 PB Stone Columns inside cells K037 - K039 240nrs (3nrs/day) LB-BC1	67	01-Dec-13 A	14-Feb-14 A		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1	1	1 1 1		1			1	
SCIB0-050 PB Stone Columns inside cells K040 - K040 80nrs (3nrs/day) LB-BV2	39	20-Dec-13 A	04-Feb-14 A	1	; 	·	; !	; 	†		† ! !		_	i	
SCIB0-060 PB Stone Columns inside cells K041 - K043 237nrs (5nrs/day) LB-AP3	68	25-Nov-13 A	09-Feb-14 A		1	1 1 1	1 1 1 1	1 1 1	1 1 1 1		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
SCIB0-070 PB Stone Columns inside cells K044 - K046 136nrs (5nrs/day) LB-AP3	89	15-Feb-14 A	22-May-14 A	†	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	! !	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1		1	1	!	!	
SCIB0-080 PB Stone Columns inside cells K047 - K050 267nrs (5nrs/day) LB-AP1	109	21-Jan-14 A	22-May-14 A		1 1 1 1	1 1 1 1	! ! !	1 1 1 1	! ! !		! ! !	 		_	
SCIB0-090 PB Stone Columns inside cells K051 - K051 23nrs (5nrs/day) LB-AP3	5	10-Feb-14 A	14-Feb-14 A			 		!							
Seawall Portion E2 at K052 - C060 9cells 720nrs	92	21-Feb-14 A	30-May-14 A	 			; ;		; ;	į		į	i	ļ 	· · · · · · · · · · · · · · · · · · ·
SCIE2-020 PE2 Stone Columns inside cells K052 - K055 320nrs (5nrs/day) LB-AP2			30-May-14 A		1	1 1 1	1 1 1 1	1 1 1	1 1 1 1		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	 	1	
SCIE2-040 PE2 Stone Columns inside cells K057 - C059 240nrs (3nrs/day) LB-BV1			27-May-14 A				1 1 1 1		1 1 1 1	1					
Remaining Level of Effort ♦ Milestone	34th Monthly Progress	Report Status	s as on 21Oct2014 \	⊥ <u>I</u> √er.5h5		SK filter: I						!	!		1
Actual Level of Effort Summary		Page 3 of 1	6		Res	source Pr	ofile Filte	er:Aggreg	ate.Ston	ne Aggreç	gate (cum	ገ)			
Actual Work		5													
Remaining Work Critical Remaining Work														D.:	0
Ontical Nemalining Work														Primavera	Systems, I




ID		Activity Name	Original S Duration	Start	Finish	Mar	Apr	May Ju	ın Jul	Aug	Sep	Oct	Nov	Dec	Jan	2014 Fe
1=1						16	17		9 20		22	23	24	25	26	2
		PC Cellular Structure C074			05-Nov-13 A		1 1 1	1 1 1			1 1 1 1			 	1	
		PC Cellular Structure C075			01-Dec-13 A			i 1 1		i ! !	 					
		PC Cellular Structure C076			09-Nov-13 A			 		1	1 1 1 1					
	CS077-000	PC Cellular Structure C077	7	12-Oct-13 A	21-Oct-13 A			 			! ! !		 - -			1
	CS080-000	PC Cellular Structure C080	7	14-Sep-13 A	21-Sep-13 A		1	 	1							
	CS081-000	PC Cellular Structure C081 Type_C 4667m3	11 3	31-Aug-13 A	10-Sep-13 A		1	1		1						
	CS082-000	PC Cellular Structure C082	7	10-Oct-13 A	18-Oct-13 A		; ; ;	; ; ; ;			; ; ; ;		i !			
	CS083-000	PC Cellular Structure C083	7 2	27-Sep-13 A	05-Oct-13 A			 			•	<u> </u>	1			
	CS084-000	PC Cellular Structure C084 Type_C 4094.5m3	12 (07-Sep-13 A	18-Sep-13 A		1	 								-
	CS085-000	PC Cellular Structure C085	8 2	27-Aug-13 A	03-Sep-13 A						;]					
	CS086-000	PC Cellular Structure C086	6 (06-Oct-13 A	12-Oct-13 A		1	1			1 1 1 1					
	CS087-000	PC Cellular Structure C087	16 2	24-Sep-13 A	14-Oct-13 A		; ; ;	; ; ;			_		i !			
	CS088-000	PC Cellular Structure C088 Type_C 3712.5m3	10 (06-Sep-13 A	15-Sep-13 A	1		 					1			
	CS089-000	PC Cellular Structure C089 Type_C 3712.5m3	11	19-Aug-13 A	29-Aug-13 A	-		 			1 1 1					
	CS090-000	PC Cellular Structure C090	12 2	27-Sep-13 A	11-Oct-13 A							ļ 				
		PC Cellular Structure C091 Type_C 3533m3			15-Sep-13 A	-	1	1								
		PC Cellular Structure C092 Type_C 3533m3			25-Aug-13 A	-	1	 			1					
		PC Cellular Structure C093			28-Sep-13 A	-	1	 					1			
		PC Cellular Structure C094 Type_C 3342m3			01-Sep-13 A	-		 			- 					
		PC Cellular Structure C095 Type_C 3342m3			09-Aug-13 A											
						-	1	1		-			1			
		PC Cellular Structure C096 Type_C 3342m3			25-Sep-13 A	-	; ; ;	; ; ;					i !			
		PC Cellular Structure C097 Type_C 3342m3			25-Aug-13 A	-		 			 					
		PC Cellular Structure C098 Type_C 3342m3			05-Aug-13 A		1	 			<u> </u>					
		PC Cellular Structure C099 Type_C 3342m3			08-Sep-13 A						, ,		¦ 			
		PC Cellular Structure C100 Type_C 3342m3			21-Aug-13 A		1	1			1 1 1					-
		PC Cellular Structure C101 Type_C 3338m3	11		23-Jul-13 A		1	1			, , , ,					
	CS102-000	PC Cellular Structure C102 Type_C 3338m3	13 2	26-Jun-13 A	08-Jul-13 A		1	1	<u> </u>		1 1 1					
	CS103-000	PC Cellular Structure C103 Type_C 3338m3	20 (03-Jun-13 A	22-Jun-13 A		1		_		, 		: !			
	CS104-000	PC Cellular Structure C104 Type_C 3338m3	17 (06-Jul-13 A	22-Jul-13 A		1	 			 		1			
	CS105-000	PC Cellular Structure C105 Type_C 3338m3	13 2	22-Jun-13 A	04-Jul-13 A						 			1		
	CS106-000	PC Cellular Structure C106 Type_C 3147m3	36 (08-May-13 A	12-Jun-13 A					1	 					
	CS107-000	PC Cellular Structure C107 Type_C 3147m3	12 2	21-Jul-13 A	01-Aug-13 A		1	1 1 1		_	1 1 1 1	 	1	 	 	
	CS108-000	PC Cellular Structure C108 Type_C 3147m3	11 (03-Jul-13 A	13-Jul-13 A		 	 		1	 	1	1	1	! !	
	CS109-000	PC Cellular Structure C109 Type_C 3147m3	16	15-Jun-13 A	30-Jun-13 A		1 1 1			1	1 1 1 1	 	! ! !	 	 	
	CS110-000	PC Cellular Structure C110 Type_C 3147m3	12	18-Jul-13 A	29-Jul-13 A	 				 		!			-	
	CS111-000	PC Cellular Structure C111 Type_C 2956m3	12 (06-Jul-13 A	17-Jul-13 A	+		 		1	! !					
		PC Cellular Structure C112 Type_C 2956m3			30-Jun-13 A	1				1	 					-
	onnecting A	11	386 2	24-Mar-13 A	14-Apr-14 A	-										-
			34th Monthly Progress F			/er.5h5	İτΔςι	K filter: ET P	rogress Re	nort Mar 20)13 to F4	h 2014		i	i	<u> </u>
	Actual Level	evel of Effort						ource Profile					1)			
	Actual Work	·		Page 5 of 16)											
	Remaining W	Vork														

act No. HY/2010/02 Hong Kong - Zhuhai - Macao Bridge		ong Kong Boundary Cr	ossing Facili	ities - Recl	amation `							004	1.7
Activity Name	Origina Duration	al Start Finish		Apr N	,		Aug	Sep				Jan l	Feb
Portion B between K028/K029 to K050/K051 23arcs	37/	4 24-Mar-13 A 02-Apr-14 A	16	17	18 1	20	21	22	23	24	25	26	27
CA00B-000 PB Connecting Arc K037/K038 lower arcs type_c		5 24-Mar-13 A 04-Jul-13 A											
CA00B-012L PB Connecting Arc K028/K029 - K039/K040 (except K037/K038) Landside lower arcs 11nrs		6 11-Jul-13 A 20-Sep-13 A											
CA00B-012S PB Connecting Arc K028/K029 - K039/K040 (except K037/K038) Seaside lower arcs 11nrs		8 31-Aug-13 A 01-Nov-13 A											
CA00B-014L PB Connecting Arc K029/K030 & K030/K031 Landside upper arcs splicings 2nrs (HF)		0 27-Sep-13 A 22-Oct-13 A											
CA00B-014S PB Connecting Arc K029/K030 & K030/K031 Seaside upper arcs splicings 2nrs (HF)		9 02-Nov-13 A 24-Nov-13 A				1							
<u> </u>		0 30-Oct-13 A 14-Dec-13 A											
CA00B-018 PB Final Backfill Cellular Cells & Arcs K028/K029 - K039/K040 Type_C 40295.5m3									;				
CA00B-022 PB Connecting Arc K045/K046 Landside & Seaside upper arcs splicings 2nrs (HF)		4 25-Nov-13 A 21-Dec-13 A						<u>i </u>					
CA00B-022L PB Connecting Arc K040/K041 - K050/K051 Landside lower arcs 11nrs		4 11-Jul-13 A 18-Sep-13 A			į		:		<u> </u>				
CA00B-022S PB Connecting Arc K040/K041 - K050/K051 Seaside lower arcs 11nrs		2 31-Oct-13 A 13-Nov-13 A				1							
CA00B-025L PB Connecting Arc K049/K050 & K050/K051 Landside upper arcs splicing 2nrs (201)		1 17-Nov-13 A 11-Dec-13 A											
CA00B-028 PB Final Backfill Cellular Cells & Arcs K040/K041 - K050/K051 Type_C 48413m3	9	0 13-Dec-13 A 02-Apr-14 A				1							
Portion E2 between K051/K052 to C066/C067 16arcs	14	7 01-Oct-13 A 29-Mar-14 A		1			1	T					
CAE2-012L PE2 Connecting Arc K051/K052 - K062/K063 Landside lower arcs 12nrs	1:	5 01-Oct-13 A 20-Oct-13 A						•					
CAE2-012S PE2 Connecting Arc K051/K052 - C061/C062 Seaside lower arcs 11nrs	5	5 20-Nov-13 A 25-Jan-14 A									:		
CAE2-014L PE2 Connecting Arc K051/K052 - K053/K054 Landside upper arcs splicing 3nrs (201)	40	0 25-Oct-13 A 10-Dec-13 A				i 1 1					•		
CAE2-014S PE2 Connecting Arc K051/K052 - K053/K054 Seaside upper arcs splicing 3nrs (201) 30Mar2	2014 29	9 25-Feb-14 A 29-Mar-14 A				<u>-</u>							
CAE2-016L PE2 Connecting Arc K056/C057 & C057/C058 Landside upper arcs splicing 2nrs (HF)	6	5 27-Nov-13 A 16-Feb-14 A				1				<u> </u>			
CAE2-016S PE2 Connecting Arc K056/C057 & C057/C058 Seaside upper arcs splicing 2nrs (HF)	50	6 14-Dec-13 A 22-Feb-14 A									-		
CAE2-022L PE2 Connecting Arc C062/C063 & C066/C067 Landside lower arcs 2nrs	11	1 07-Jan-14 A 19-Jan-14 A									_	-	
CAE2-022S PE2 Connecting Arc C062/C063 & C066/C067 Seaside lower arcs 2nrs	14	4 11-Dec-13 A 28-Dec-13 A				i 1 1							
Portion C2a between C103/104 to C111/C112 9arcs	200	2 17-Aug-13 A 06-Mar-14 A											
CAC2a-012L PC2a Connecting Arc C107/C108 - C111/C112 Landside lower arcs 5nrs	-	7 17-Aug-13 A 23-Aug-13 A					_						
CAC2a-012S PC2a Connecting Arc C107/C108 - C111/C112 Seaside lower arcs 5nrs	1!	5 01-Oct-13 A 20-Oct-13 A				1 1 1					1		
CAC2a-014L PC2a Connecting Arc C107/C108 - C111/C112 Landside upper arcs splicing 5nrs (205)	4	1 07-Nov-13 A 26-Dec-13 A											
CAC2a-014S PC2a Connecting Arc C107/C108 - C111/C112 Seaside upper arcs splicing 5nrs (205)	5	3 05-Nov-13 A 08-Jan-14 A											
CAC2a-018 PC2a Final backfill cellular cells & Arcs C107/108 - C111/112 5arcs Type_C 32,309m3		9 10-Jan-14 A 20-Jan-14 A							<u> </u>				
CAC2a-032L PC2a Connecting Arc C103/C104 - C106/C107 Landside lower arcs 4nrs		3 23-Aug-13 A 26-Aug-13 A											
CAC2a-032S PC2a Connecting Arc C103/C104 - C106/C107 Seaside lower arcs 4nrs		6 01-Jan-14 A 14-Feb-14 A	-				_					!	
CAC2a-034L PC2a Connecting Arc C105/C106 & C106/C107 Landside upper arcs splicing 2nrs (205)		0 17-Jan-14 A 28-Jan-14 A			į	i ! !							_
CAC2a-034S PC2a Connecting Arc C105/C106 & C106/C107 Seaside upper arcs splicing 2nrs (401)		2 21-Feb-14 A 06-Mar-14 A	$-\parallel$			1						_	
								.					
Portion C2c between C091/C092 to C102/C103 12arcs CAC2c 042L PC2c Connecting Arc C007/C008 C102/C103 Landeida lower arcs force		0 30-Sep-13 A 14-Apr-14 A		1	! ! !		1	1					
CAC2c-012L PC2c Connecting Arc C097/C098 - C102/C103 Landside lower arcs 6nrs		2 30-Sep-13 A 15-Oct-13 A		1			1 1 1 1						
CAC2c-012S PC2c Connecting Arc C097/C098 - C102/C103 Seaside lower arcs 6nrs		2 30-Sep-13 A 15-Oct-13 A					1				<u> </u>		_
CAC2c-014L PC2c Connecting Arc C100/C101 - C104/C105 Landside upper arcs splicing 5nrs (205)		3 31-Dec-13 A 10-Feb-14 A					! ! !						
CAC2c-014S PC2c Connecting Arc C101/C102 - C104/C105 Seaside upper arcs splicing 4nrs (401)		1 13-Jan-14 A 26-Mar-14 A							- <u></u>				
CAC2c-022L PC2c Connecting Arc C091/C092 - C096/C097 Landside lower arcs 6nrs		6 05-Oct-13 A 24-Oct-13 A		1			! ! !				1		
CAC2c-022S PC2c Connecting Arc C091/C092 - C096/C097 Seaside lower arcs 6nrs	41	0 14-Oct-13 A 29-Nov-13 A		1	! ! !		1 1 1					1	
■ Remaining Level of Effort ◆	34th Monthly Progres	ss Report Status as on 21Oct20	14 Ver.5h5			rogress Rep							
Actual Level of Effort Summary		Page 6 of 16		Resour	ce Profile	Filter:Aggre	gate.Ston	ne Aggrega	ate (cum))			
Actual WorkRemaining Work													
Remaining work Critical Remaining Work												mavera Sy	

contract No. HY/2010/02 Hong Kong - Zhuhai - Macao Bridge	Н	ong Kong B	oundary Cros	sing Faci	lities - F	Reclamat	tion Wo	rks							
Activity ID Activity Name	Origina Duratior	Start	Finish	Mar	I Apr	May	Jun	013 Jul	L Aug	Sep	Oct	Nov	Dec	Jan	014 Feb IM
CACCO 2004 PCCO Connecting Are CO04/CO05 C000/C400 and bide upper are orbiting Core (404)			00 lan 44 A	16	17	18	19	20	21	22	23	24	25	26	27 2
CAC2c-024L PC2c Connecting Arc C094/C095 - C099/C100 Landside upper arcs splicing 6nrs (401)		25-Dec-13 A			 								-		
CAC2c-024S PC2c Connecting Arc C094/C095 - C100/C101 Seaside upper arcs splicing 7nrs (WC1)			19-Mar-14 A				1	1	1		1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
CAC2c-034L PC2c Connecting Arc C088/C089 - C093/C094 Landside upper arcs splicing 6nrs (WC1)		07-Jan-14 A	·			 - 	i 	i 			ļ	i 			
Portion E1 between C073/C074 to C090/C091 18arcs	90	22-Oct-13 A	10-Feb-14 A				1				_	1	1		-
CAE1-012L PE1 Connecting Arc C080/C081 - C090/C091 Landside lower arcs 11nrs	91	22-Oct-13 A	10-Feb-14 A			1						!	!		
CAE1-012S PE1 Connecting Arc C080/C081 - C090/C091 Seaside lower arcs 11nrs	4	09-Dec-13 A	28-Jan-14 A		1										
CAE1-032L PE1 Connecting Arc C067/C068 - C076/C077 Landside lower arcs 10nrs	32	18-Dec-13 A	27-Jan-14 A										_		
CAE1-032S PE1 Connecting Arc C067/C068 - C076/C077 Seaside lower arcs 10nrs	30	12-Dec-13 A	18-Jan-14 A		1 1	1	1		1						; ; ;
Optimizing Rubble Mound Seawalls	300	24-May-13 A	19-Mar-14 A			_					1	1			
Optimizing Portion A at C118 - C134	287	7 24-May-13 A	06-Mar-14 A			_	1	!	!	1	1	1	!		
Seawall Portion A at C118 - C121, Ch5+100 to 4+880	174	1 21-Aug-13 A	28-Feb-14 A				1		_	1	<u> </u>				
RFA1-0010 PA at C121 - C118 Geotextile Type 1 above stone blanket 14,400m2	2	2 21-Aug-13 A	22-Aug-13 A		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				1		1				1
RFA1-0020 PA at C121 - C118 sound survey	2	23-Aug-13 A	24-Aug-13 A		1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1		1			1			! ! !
RFA1-0030 PA at C121 - C118 settlement markers install	2	2 26-Aug-13 A	27-Aug-13 A	1					1	 	<u>;</u>		 		
RFA1-0040 PA at C121 - C118 Filter Layer (Cat0 Fill 1m) under the Rubble Mound 10,200m3		5 28-Aug-13 A	02-Sep-13 A							<u>.</u>					1
RFA1-0050 PA at C121 - C118 Rockfill (Cat1) upto -3.0mPD 22,610m3	11	1 21-Oct-13 A	01-Nov-13 A				1		: !						1
RFA1-0060 PA at C121 - C118 Sand Blanket behind upto -4.0mPD	3	3 02-Nov-13 A	09-Nov-13 A			1	1				1				1
RFA1-0070 PA at C121 - C118 Rockfill (Cat1) , filter layer & geotextile +2.5mPD 18,870m3	67	7 11-Nov-13 A	21-Jan-14 A		1		1								
RFA1-0080 PA at C121 - C118 Rockfill (Cat1) for platform upto +2.5mPD 15,810m3	32	2 22-Jan-14 A	28-Feb-14 A		- - - -	 	 	 	; ;		<u> </u>	 	 		
RFA1-0090 PA at C121 - C118 Rockfill (Cat1) upto +6.0mPD & geotextile laying 6,460m3		3 21-Feb-14 A	23-Feb-14 A			1	1		1		1	1			
RFA1-0100 PA at C121 - C118 UnderLayer (Cat0) 0mPD 10,200m3			28-Feb-14 A								1				
Seawall Portion A at C122 - C124, Ch5+220 to 5+100		3 01-Jul-13 A	08-Oct-13 A				,				<u> </u>				
RFA2-0010 PA at C122 - C124 Geotextile Type 1 above stone blanket 11,000m2		2 01-Jul-13 A	02-Jul-13 A												!
RFA2-0020 PA at C122 - C124 sound survey		2 03-Jul-13 A	04-Jul-13 A			 - 	 	! !	<u></u>		<u> </u>				
RFA2-0030 PA at C122 - C124 settlement markers install		2 05-Jul-13 A	06-Jul-13 A			1	1		1		1				
								"			1				!
RFA2-0040 PA at C122 - C124 Filter Layer (Cat0 Fill 1m) under the Rubble Mound 7,800m3		1 07-Jul-13 A	10-Jul-13 A		 				_						1
RFA2-0050 PA at C122 - C124 Rockfill (Cat1) upto -3.0mPD 17,290m3			10-Aug-13 A				1		_						1
RFA2-0060 PA at C122 - C124 Sand Blanket behind upto -4.0mPD			13-Aug-13 A	4		 - 	 		I						
RFA2-0070 PA at C122 - C124 Rockfill (Cat1), filter layer & geotextile +2.5mPD 14,430m3			07-Sep-13 A		 						_	1			1
RFA2-0080 PA at C122 - C124 Rockfill (Cat1) for platform upto +2.5mPD 12,090m3		6 03-Oct-13 A					1								
Seawall Portion A at C125 - C128, Ch5+400 to 5+220		Ť	06-Mar-14 A			\	1	1	1		1	1			
RFA3-0010 PA at C125 - C128 Geotextile Type 1 above stone blanket 14,400m2	2	2 30-May-13 A	31-May-13 A				I				1				
RFA3-0020 PA at C125 - C128 sound survey	2	01-Jun-13 A	03-Jun-13 A		1										1
RFA3-0030 PA at C125 - C128 settlement markers install	2	04-Jun-13 A	05-Jun-13 A			 	1							 	
RFA3-0040 PA at C125 - C128 Filter Layer (Cat0 Fill 1m) under the Rubble Mound 10,200m3		24-Jun-13 A	28-Jun-13 A		1 1 1	1 1 1 1	•	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1		1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
RFA3-0050 PA at C125 - C128 Rockfill (Cat1) upto -3.0mPD 22,610m3	10	24-Jul-13 A	03-Aug-13 A			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		_	<u> </u>		!				1
RFA3-0060 PA at C125 - C128 Sand Blanket behind upto -4.0mPD	2	04-Aug-13 A	05-Aug-13 A				1		1						
RFA3-0070 PA at C125 - C128 Rockfill (Cat1) , filter layer & geotextile +2.5mPD 18,870m3	38	06-Aug-13 A	12-Sep-13 A			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1	1		-	1				
Remaining Level of Effort Milestone Actual Level of Effort Summary	34th Monthly Progres	s Report Status Page 7 of 1		Ver.5h5		SK filter: I source Pr	_	•				n)			
Actual Work		i aye i ui i	•												
Remaining Work															
Critical Remaining Work														Primavera	Systems, II


ID	RFA3-0808 PA at C125 - C128 Rockfill (Cat1) for platform upto +2.5mPD 15,810m3 RFA3-0909 PA at C125 - C128 Rockfill (Cat1) upto +5.0mPD & geotextile laying 6.460m3 RFA3-0100 PA at C125 - C128 UnderLayer 0mPD 10,200m3 Seawall Portion A at C129 - C131 Cround Investigation RFA4-0000 PA at C129 - C131 Ground Investigation RFA4-0010 PA at C129 - C131 Geotextile Type 1 above stone blanket 11,000m2 RFA4-0020 PA at C129 - C131 settlement markers install RFA4-0030 PA at C129 - C131 Settlement markers install RFA4-0040 PA at C129 - C131 Rockfill (Cat1) upto -3.0mPD 17,290m3 RFA4-0050 PA at C129 - C131 Rockfill (Cat1) upto -3.0mPD 17,290m3 RFA4-0060 PA at C129 - C131 Rockfill (Cat1) upto -3.0mPD 17,290m3 RFA4-0080 PA at C129 - C131 Rockfill (Cat1) filter layer & geotextille +2.5mPD 14,430m3 RFA4-0080 PA at C129 - C131 Rockfill (Cat1) upto +6.0mPD & geotextille laying 4,940m3 RFA4-0090 PA at C129 - C131 Rockfill (Cat1) upto +6.0mPD & geotextille laying 4,940m3 RFA4-0000 PA at C129 - C131 UnderLayer 0mPD 7,800m3 Seawall Portion A at C132 - C134 Rockfill (Cat1) upto +6.0mPD & geotextille laying 4,940m3 RFA5-0010 PA at C132 - C134 Rockfill (Cat1) upto -8.0mPD 8, geotextille laying 4,940m3 RFA5-0020 PA at C132 - C134 Rockfill (Cat1) upto -8.0mPD 8, geotextille laying 4,940m3 RFA5-0030 PA at C132 - C134 Rockfill (Cat1) upto -8.0mPD 15,295m3 RFA5-0040 PA at C132 - C134 Rockfill (Cat1) upto -8.0mPD 15,295m3 RFA5-0050 PA at C132 - C134 Rockfill (Cat1) upto -8.0mPD 15,295m3 RFA5-0060 PA at C132 - C134 Rockfill (Cat1) upto -8.0mPD 15,295m3 RFA5-0070 PA at C132 - C134 Rockfill (Cat1) upto -8.0mPD 15,295m3 RFA5-0080 PA at C132 - C134 Rockfill (Cat1) upto -8.0mPD 15,295m3 RFA5-0080 PA at C132 - C134 Rockfill (Cat1) upto -8.0mPD 15,295m3 RFA5-0080 PA at C132 - C134 Rockfill (Cat1) upto -8.0mPD 15,295m3 RFA5-0080 PA at C132 - C134 Rockfill (Cat1) upto -8.0mPD 15,295m3 RFA5-0080 PA at C132 - C134 Rockfill (Cat1) upto -8.0mPD 15,295m3 RFA5-0080 PA at C132 - C134 Rockfill (Cat1) upto -8.0mPD 15,295m3 RFA5-0080 P	Original Sta	art	Finish	Mar	Apr	May	Jun)13 Jul	Aug	Sep	Oct	Nov	Dec	Jan	2014 Fε	
						16	17	18	19	20	21	22	23	24	25	26	2
RFA3-	B-0080 PA at C125 - C128 Rockfill (Cat1) for pla	tform upto +2.5mPD 15,810m3	5 27	-Sep-13 A	02-Oct-13 A		1					=]				
RFA3-	8-0090 PA at C125 - C128 Rockfill (Cat1) upto +	6.0mPD & geotextile laying 6,460m3	3 24	-Feb-14 A	26-Feb-14 A		1		1			1					
RFA3-	8-0100 PA at C125 - C128 UnderLayer 0mPD 1	0,200m3	6 28	-Feb-14 A	06-Mar-14 A		1		1 1 1			1					
Seawa	all Portion A at C129 - C131, Ch5+550 to 5+400		280 24	-May-13 A	27-Feb-14 A		1	_	1	! !		1		1			
RFA4-	PA at C129 - C131 Ground Investigation		4 24	-May-13 A	27-May-13 A		1		1			1					
RFA4-	PA at C129 - C131 Geotextile Type 1 abo	ove stone blanket 11,000m2	2 28	-May-13 A	29-May-13 A		 	ı		; ;		-					
RFA4-	I-0020 PA at C129 - C131 sound survey		2 30	-May-13 A	31-May-13 A		1	į				1					
RFA4-	I-0030 PA at C129 - C131 settlement markers in	nstall	2 01	-Jun-13 A	03-Jun-13 A		1										
RFA4-	I-0040 PA at C129 - C131 Filter Layer (Cat0 Fill	1m) under the Rubble Mound 7,800m3	12 11	-Jun-13 A	23-Jun-13 A		1					1					
RFA4-	I-0050 PA at C129 - C131 Rockfill (Cat1) upto -	3.0mPD 17,290m3	17 06	-Jul-13 A	23-Jul-13 A		1		1			1					
RFA4-	I-0060 PA at C129 - C131 Sand Blanket behind	upto -4.0mPD	2 24	-Jul-13 A	25-Jul-13 A				; 	1							
RFA4-	I-0070 PA at C129 - C131 Rockfill (Cat1) , filter	layer & geotextile +2.5mPD 14,430m3	7 26	-Jul-13 A	02-Aug-13 A		1		1		i	1					
RFA4-	I-0080 PA at C129 - C131 Rockfill (Cat1) for pla	tform upto +2.5mPD 12,090m3	6 21	-Sep-13 A	26-Sep-13 A		1		1			_					
RFA4-	I-0090 PA at C129 - C131 Rockfill (Cat1) upto +	6.0mPD & geotextile laying 4,940m3	3 21	-Feb-14 A	23-Feb-14 A		1		1 1 1			1		1			
RFA4-	I-0100 PA at C129 - C131 UnderLayer 0mPD 7	,800m3	4 24	-Feb-14 A	27-Feb-14 A		1					1					
Seawa	all Portion A at C132 - C134, Ch5+700 to 5+550		129 01	-Oct-13 A	20-Feb-14 A												<u>}</u>
RFA5-	5-0010 PA at C132 - C134 Geotextile Type 1 abo	ove stone blanket 9,730m2	5 01	-Oct-13 A	05-Oct-13 A		 		1 1 1			i		1			
			2 06	-Oct-13 A	07-Oct-13 A		1		1			1	1				
RFA5-		nstall	2 08	-Oct-13 A	09-Oct-13 A		1		1			1	1				
					14-Oct-13 A				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1								
		<u>'</u>			24-Oct-13 A							<u>i</u>					ļ
					31-Oct-13 A		1		1								
					21-Jan-14 A		1		1 1 1 1			1		1			
					20-Feb-14 A		1		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			1					!
	<u> </u>	12.5m 2 10,000m			19-Mar-14 A		1) 1 1 1			1		1		_	1
		ova stona blankat 17.800m2			22-Jan-14 A				 	 						 	ļ
	,,	ove stone blanket 17,000m2			25-Jan-14 A				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1								
	•	otoll			27-Jan-14 A		1		i ! !			1				•	
					10-Feb-14 A		1		1			1				'	
	, , , , , , , , , , , , , , , , , , ,	<u> </u>					1		1 1 1			1		1		_	
					15-Feb-14 A												}
		<u> </u>			20-Feb-14 A				! ! !					1			
		ayer & geotextile +2.5mPD 5,040m3			19-Mar-14 A		1		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			1		1			
					10-Mar-14 A		1		1			1				_	
		ove stone blanket 17,800m2			25-Jan-14 A		1					1					
	•				27-Jan-14 A				¦ 	ļ 						 	ļ
RFB2-0					28-Jan-14 A		1		1 1 1	 		! ! !		1		1	
RFB2-0	-0040 PB at K018 - K022 Filter Layer (Cat0 Fill	1m) under the Rubble Mound 8835m3	6 10	-Feb-14 A	15-Feb-14 A		1		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			1		1			
RFB2-0	-0050 PB at K018 - K022 Rockfill (Cat1) upto -3	3.0mPD 6660m3	24 13	-Feb-14 A	10-Mar-14 A		1		1								
- Rema	aining Level of Effort ♦ Milestone		34th Monthly Progress Re	port Status	as on 21Oct2014 \	/er.5h5					ort Mar 201			,			
	al Level of Effort Summary		F	Page 8 of 16			Res	ource Pr	rofile Filte	r:Aggreg	ate.Stone	Aggreg	ate (cum)			
	al Work																
	aining Work al Remaining Work															Primavera	



ontract No. HY/2010/02 Hong Kong - Zhuhai - Macao Bridge	Hong Kong B	oundary Cros	sing Faci	lities - R	Reclamat	tion Wor	rks							
vity ID Activity Name	Original Start Duration	Finish	Mar	Apr	May)13 Jul	Aug	Sep	Oct	Nov	Dec		2014 Feb N
SABRC2a-01 Sand Blankets at PC2a 37,000m3 2,000m3/day East	27 01-Jun-13 A	30lun-13 A	16	17	18	19	20	21	22	23	24	25	26	27
SABRC2a-02 Sand Blankets at PC2a 36,000m3 1,000m3/day West	7 23-Sep-13 A			 						ĭ			 	
Land Portion C2c	27 01-Jun-13 A	·		1 1 1 1	,		7					 	1 1 1 1	
SABRC2c-01 Sand Blankets at PC2c 9,000m3 5,000m3/day	27 01-Jun-13 A			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	! !				1 1 1			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	 	! ! ! !
Land Portion C2b	19 01-Oct-13 A									<u> </u>			 	
SABRC2b-01 Sand Blankets at PC2b 9,000m3 2,000m3/day	19 01-Oct-13 A													
Land Portion E2 Northern Part	57 01-Nov-13 A			1	1				1		<u> </u>		,	! !
SABRE2-010 Sand Blankets at PE2 71,000m3 5,000m3/day North-West	57 01-Nov-13 A			1		1			 				 	! ! !
Land Portion E1	15 08-Jul-13 A			 			—					1	 	! !
SABRE1-010 Sand Blankets at PE1 15,000m3 5,000m3/day	15 08-Jul-13 A			 	 - -				1			1	! ! 	! -
Existing Seabed Above -5mPD	399 18-Feb-13 A			1	1	1			1			1	1	! !
Land Portion A	256 18-Feb-13 A													
SABRA0-010 Sand Blankets 557,500m3 PA Main Area stg1 6,000m3/day	110 18-Feb-13 A			<u> </u>		1			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			1		
SABRA0-020 Sand Blankets 114,779m3 PA Edge Area C118 to C121 4,000m3/day	25 24-Aug-13 A						. I	_	<u> </u>				 	1 1 1 1
SABRA0-030 Sand Blankets 163,971m3 PA Edge Area C122 to C126 2,000m3/day		20-Aug-13 A		 			¦		ļ	<u> </u>			 	
SABRA0-040 Sand Blankets 180,367m3 PA Edge Area C127 to C131 2,000m3/day	11 04-Jul-13 A	15-Jul-13 A		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				1 1 1	!		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1	! ! !
SABRA0-050 Sand Blankets 98383m3 PA Edge Area C132 to C134 4,000m3/day	12 08-Nov-13 A	20-Nov-13 A		1										
Land Portion B	162 01-Nov-13 A										-			
SABRB0-010 Sand Blankets at PB Edge K013 - K027 171,900m3 10,000m3/day	29 01-Dec-13 A	31-Dec-13 A		1 1 1	1				1				 	: : :
SABRB0-020 Sand Blankets at PB Main K028 - K051 200,550m3 5,000m3/day	28 01-Nov-13 A	30-Nov-13 A		·						¦		; 		:
SABRB0-030 Sand Blankets at PB Edge K028 - K056 200,550m3 5,000m3/day	72 10-Feb-14 A	28-Apr-14 A		 	1		1 1 1 1 1 1						 	
Land Portion C1a	113 01-Aug-13 A	30-Nov-13 A		1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		•		1		-	÷	1 1 1 1	1 1 1 1
SABRC1a-01 Sand Blankets at PC1a 191,000m3 5,000m3/day North	47 01-Aug-13 A	20-Sep-13 A		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	! !	1						1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	 	! ! !
SABRC1a-02 Sand Blankets at PC1a 191,000m3 5,000m3/day South	28 01-Nov-13 A	30-Nov-13 A		1								l	 	
Land Portion C1b	103 01-Jun-13 A	20-Sep-13 A		- - !	ļ		; 			ļ !				!
SABRC1b-01 Sand Blankets at PC1b 142000m3 2,000m3/day West	27 01-Jun-13 A	30-Jun-13 A		1	1				1 1 1			1		: : :
SABRC1b-02 Sand Blankets at PC1b 142000m3 5,000m3/day East	47 01-Aug-13 A	20-Sep-13 A		 									1 1 1 1	! ! !
Vertical Band Drains by Marine Plant	426 24-Apr-13 A	31-Jul-14 A		-										
Land Portion C2a 1,760nrs	416 04-May-13 A	31-Jul-14 A		1 1 1 1	-		: :		1		1	1	! !	
VBDC2a-010 PC2a Vertical Band Drains 52,300nrs completed by marine plant	416 04-May-13 A	31-Jul-14 A							1	‡	1	1	 	! !
Land Portion C2c 62,400nrs	277 24-Apr-13 A	20-Feb-14 A		-	!				1	:	1	1	 	-
VBDC2c-010 Vertical Band Drains 40,192nrs by marine plant at PC2c	164 24-Apr-13 A	17-Oct-13 A								-		1	 	! !
VBDC2c-020 Vertical Band Drains 22,208nrs by marine plant at PC2c (750nrs/ady)	63 11-Dec-13 A	20-Feb-14 A		1					1				:	
Land Portion C2b 62,400nrs	174 23-Aug-13 A	03-Mar-14 A		1 1 1 1			, I	_	1	<u> </u>	1	1		1
VBDC2b-010 Vertical Band Drains 12,896nrs by marine plant at PC2b upto 10Dec2013	101 23-Aug-13 A	10-Dec-13 A		 	.	1			1			1	 	
VBDC2b-020 Vertical Band Drains 49,504nrs by marine plant at PC2b (750nrs/day)	73 11-Dec-13 A	03-Mar-14 A		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1	1			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					
Land Portion E2 Northern Part 84,746nrs	61 02-Oct-13 A	05-Dec-13 A		1			. !		,	-		-	: ! !	! ! !
VBDE2-010 Vertical Band Drains 23,032nrs by marine plant at PE2 upto 5Dec2013	61 02-Oct-13 A	05-Dec-13 A		1								-		1 1 1 1
Remaining Level of Effort Milestone	34th Monthly Progress Report Status	as on 21Oct2014	Ver.5h5	TAS	SK filter:	ET Progre	ess Repo	ort Mar 2	: 013 to Fe	eb 2014.	<u>:</u>			
Actual Level of Effort Summary	Page 10 of 1	6				_	er:Aggrega							
Actual Work	. ago 10 0 1 1	-												
Remaining Work Critical Remaining Work													Deies - · ·	Ourste
- Oraca Romaning Work													Primavera	Systems


	/2010/02 Hong Kong - Zhuhai - Macao Bridge			Soundary Cross	sing Facili	ities - R	leclamat									
ID	Activity Name	Origina Duratio	al Start n	Finish	Mar		May		Jul					Dec	Jan	2014 Feb
Land Portion	E1 23,744nrs	6	7 13-Jun-13 A	23-Aug-13 A	16	17	18	19	20	21	22	23	24	25	26	27
VBDE1-010	Vertical Band Drains 23,744nrs by marine plant at PE1 (750nrs/day) upto 23Aug2013			23-Aug-13 A		 						† 		 	 	
Marine Fill		31	0 16-May-13 A	20-Apr-14 A			-									
Temporary Bu	nd	17	5 16-May-13 A	20-Nov-13 A			—				1	1	-		! !	
TB0010	Construction of Enclosed Temp Seawall East-North Corner ((3+19)*4/2)=44m2x720m 31,680m3 (2	,000m3/day) 2	1 16-May-13 A	07-Jun-13 A											! !	
TB0020	Construction of Enclosed Temp Seawall West-South Corner ((3+19)*4/2)=44m2x720m 31,680m3 (2	2,000m3/day) 2	1 08-Jun-13 A	30-Jun-13 A	+		1 1				1	1	 	!	! ! !	1
TB0030	Construction of Northern side Temp Seawall to C118 13,200m3 (2,000m3/day)	1	9 01-Nov-13 A	20-Nov-13 A							ļ		ļ		! ! ! !	
TB0040	Construction of Northern side Temp Seawall to C122 13,200m3 (2,000m3/day)	5	6 21-Aug-13 A	20-Oct-13 A	+					_	!				1 1 1 1	1
Land Portion	A	28	1 06-Jun-13 A	09-Apr-14 A				•			! !	! !		1	1 1 1	-
MFA0-010	Marine Fill Type A Sand 100% at PA Edge Area at C118 - C121 268,813m3 20,000m3/day	1	1 29-Dec-13 A	09-Jan-14 A	1									ı		
MFA0-020	Marine Fill Type A Sand 100% at PA Main Area (Enclosed Area PCB) 311,884m3 upto 29Jul2013	5	0 06-Jun-13 A	29-Jul-13 A	+		; ; ;								! !	
MFA0-030	Marine Fill Type A Sand 100% at PA Main Area (Enclosed Area PCB) 367,000m3 15,000m3/day	4	5 30-Jul-13 A	16-Sep-13 A											! !	
MFA0-040	Marine Fill Type A Sand 100% at PA Main Area 90,000m3 15,000m3/day PCB West	1	2 17-Sep-13 A	28-Sep-13 A	+										1 1 1 1	
MFA0-050	Marine Fill Type A Sand 100% at PA Main Area 330,000m3 20,000m3/day PCB West	4	7 30-Sep-13 A	18-Nov-13 A	+						1 1 1	1	1		1 1 1 1	
MFA0-060	Marine Fill Type A Sand 100% at PA Edge Area at C122 - C126 359,854m3 30,000m3/day	2	0 19-Nov-13 A	10-Dec-13 A	+								_	<u> </u>		
MFA0-070	Marine Fill Type A Sand 100% at PA Edge Area at C127 - C134 339,206m3 30,000m3/day CLP Sul	bstation 9	9 11-Dec-13 A	31-Mar-14 A	+											
MFA0-080	Marine Fill Type A Sand 100% at PA 356,482m3 20,000m3/day other areas	9	6 22-Dec-13 A	09-Apr-14 A												
Land Portion (C1b	10	6 23-Dec-13 A	20-Apr-14 A										_	1	-
MFC1b-010	PC1b West Sand Fill upto +2.5mPD 680,000m3 20,000m3/day	10	6 23-Dec-13 A	20-Apr-14 A	1						1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1		_	1	1
Vertical Band D	rains by Land Plant	41	7 17-Jan-13 A	09-Mar-14 A			1 1				1	1	1	1	1	1
Land Portion	A 233,590nrs	41	7 17-Jan-13 A	09-Mar-14 A			i i				!	!	!	<u> </u>		
VBDA0-010	Vertical Band Drains 21,696nrs by marine plant at PA PCB 17Jan13' to 7Jun13	12	9 17-Jan-13 A	07-Jun-13 A				_				<u> </u>		ļ ļ		
VBDA0-020	Vertical Band Drains 407nrs by land plant at PA PCB upto 20Oct2013	3	5 13-Sep-13 A	20-Oct-13 A	+										1 1 1 1	
VBDA0-030	Vertical Band Drains 21,000nrs by Land plant at PA PCB from 21Oct2013 to 19Nov2013	2	6 21-Oct-13 A	19-Nov-13 A	1							_	-		1 1 1 1	
VBDA0-040	Vertical Band Drains 54,757nrs by Land plant at PA PCB East 3,000nrs/day	1	3 19-Nov-13 A	02-Dec-13 A	1						1 1 1 1	1 1 1	_	<u> </u>	1 1 1 1	
VBDA0-050	Vertical Band Drains 32,115nrs by Land plant at PA PCB West 3,000nrs/day	3	5 03-Dec-13 A	09-Jan-14 A	1						1	1				
VBDA0-070	Vertical Band Drains 64,615nrs by Land plant at PA C122 - C126 Edge Side 1,400nrs/day (2VP)	5	1 10-Jan-14 A	09-Mar-14 A							ļ	ļ		ļ !		
Land Portion I	B 304,328nrs	13	0 19-Jul-13 A	05-Dec-13 A			 		-					 	! ! !	
Main Area 20	1,530nrs by Land	13	0 19-Jul-13 A	05-Dec-13 A			1 1		_		1			; ;	! ! !	
VBDB0-020	Vertical Band Drains by Marine plant at PB Main K028 - K054 47,530nrs from 19Jul13 to 5Dec2013	13	0 19-Jul-13 A	05-Dec-13 A	1						1	1	1	_	1 1 1 1	
Land Portion (C1b 98,260nrs by Land	9	8 02-Dec-13 A	09-Mar-14 A							1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			1	:
VBDC1b-005	Vertical Band Drains 67,850nrs by Marine plant at PC1b	9	8 02-Dec-13 A	09-Mar-14 A			<u></u>					† !				
Earthwork Fill		5	7 18-Dec-13 A	22-Feb-14 A										-		
Land Portion	A	5	7 18-Dec-13 A	22-Feb-14 A							1	1		-	1	
EFA0-010	Earthwork Fill Type D Sand 100% at PA (PCB East) 283,185m3 30,000m3/day	2	7 18-Dec-13 A	15-Jan-14 A			, , , , , , , , , , , , , , , , , , ,							_	1	
EFA0-030	Earthwork Fill Type D Sand 100% at PA (PCB West) 283,185m3 30,000m3/day	4	4 01-Jan-14 A	22-Feb-14 A	1 :						1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
Surcharge		20	7 16-Jan-14 A	10-Aug-14 A	 							 		{	▼	
Temporary Jett	ys	1	8 22-Feb-14 A	14-Mar-14 A			. !									,
Remaining Le	evel of Effort Milestone	34th Monthly Progres	ss Report Statu	s as on 21Oct2014	Ver.5h5	TAS	SK filter: E	T Progre	ess Repo	ort Mar 2	013 to F	eb 2014.	i	:		
Actual Level			Page 11 of	16		Res	source Pr	ofile Filte	r:Aggreg	ate.Ston	e Aggre	gate (cun	n)			
Actual Work			g 31													
Remaining W	ork uining Work														Primavera	

tract No. H	Y/2010/02 Hong Kong - Zhuhai - Macao Bridge	Hong Kong B	oundary Cross	ing Faci	ilities - l	Reclamat	tion Wo	rks							
ty ID	Activity Name	Original Start Duration	Finish	Mar	Apr	May	Jun	013 Jul	Aug	Sep	Oct	Nov	Dec		2014 Feb
1st Temporar	ry Jetty at C118	18 22-Feb-14 A	14-Mar-14 A	16	17	18	19	20	21	22	23	24	25	26	27
TP10020	Marine Piling 10nrs	18 22-Feb-14 A				1		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1		1		! ! ! !		
Portion A Sur		207 16-Jan-14 A			1		1 1 1	1							-
Main Reclama		207 16-Jan-14 A			 			!	!	ļ 		<u> </u> 			
A1 PCB East		207 16-Jan-14 A					1 1 1								
	Sand Surcharge Laying upto +11.5mPD at PA PCB East 446,001m3 30,000m3/day	14 16-Jan-14 A		1	1	1	1	1	1		1	1	! ! ! !	_	
	PA PCB East Surcharge Period +11.5mPD 6mths (8-2=6mths)	187 05-Feb-14 A		+	1	1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1								Ī
A1 PCB Wes			•		1) 1 1 1		1						
		207 16-Jan-14 A			 		 	 	 		 	 	 		
	Sand Surcharge Laying upto +11.5mPD at PA PCB West 446,002m3 30,000m3/day	32 16-Jan-14 A			1	1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1								:
	PA PCB WEST Surcharge Period +11.5mPD 6mths (8-2=6mths)	168 24-Feb-14 A					 								
	Instrumentation Works	193 01-Jun-13 A			1	1	!	1 1 1	1 1 1	1		1 1 1	I I		
	Instrumentation Works for Seawalls	76 21-Oct-13 A					1		1			1	1 1	_	
Portion A Ins	strumentation - SD	24 02-Dec-13 A	31-Dec-13 A				 			 - -		· •			
SD-24 C123		24 02-Dec-13 A	31-Dec-13 A			1	1	1	1		1	•			
CTSD-240	Installation of SD-24 (C123) PA	24 02-Dec-13 A	31-Dec-13 A				 	1	1						
SD-25 C128		24 02-Dec-13 A	31-Dec-13 A		1	1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1			1	•	•		}
CTSD-250	Installation of SD-25 (C128) PA	24 02-Dec-13 A	31-Dec-13 A		1) 1 1 1		1						
SD-26 C133		24 02-Dec-13 A	31-Dec-13 A				 	1				,	•		
CTSD-260	Installation of SD-26 (C133) PA	24 02-Dec-13 A	31-Dec-13 A	1				. ;			<u> </u>	; ;			
Cluster Type	SC 3nrs Strain Guage and Inclinometer Cluster inside cells	9 10-Jan-14 A	20-Jan-14 A		1		1	1	1		1	1			
SC-3 C108 P	Portion C2a	9 10-Jan-14 A	20-Jan-14 A		1	1	1	1			1			—	-
CTSC3-010	Installation of SC-3 C108 PC2a	9 10-Jan-14 A	20-Jan-14 A	†			! ! !	1							
Cluster Type	SE 26nrs Surface movement marker cluster at top of cell and sloping seawall	7 21-Oct-13 A	28-Oct-13 A		1	1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1	1		-	 			
CTSE-240	Installation of SE-24 (C121) PA	7 21-Oct-13 A	28-Oct-13 A	1		 					-	<u> </u>			
CTSE-250	Installation of SE-25 (C126) PA	7 21-Oct-13 A	28-Oct-13 A) 	1							
CTSE-260	Installation of SE-26 (C131) PA	7 21-Oct-13 A	28-Oct-13 A	_	1	1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1								
	Instrumentation Works for Reclamation RA & RB	41 01-Jun-13 A			1	,		-	1						
RB		41 01-Jun-13 A				,			1		1	! !			
SMT1-010	Installation of RB at PA	41 01-Jun-13 A		1				<u> </u>		<u> </u>		! !			
Settlement M		41 01-Jun-13 A			1			1	i 1 1						
SMT2-010	M2 - Installation of Settlement Marker Type2 at PA	41 01-Jun-13 A				1			1		1		! ! ! !		
	1912 - Installation of Settlement Marker Typez at LA	500 11-Dec-12 A			1	1	1	i !	1	! !	1	! !			
Portion D		500 11-Dec-12 A	· ·		1	1	1	1	i 1 1		1	i ! !			
Submission	*						 								
Design Submi		41 10-Mar-13 A					1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1							
	ssessment for Reclamation Areas at Portion D	41 10-Mar-13 A) 1 1		1						
	80 Settlement Assessment for Reclamation Area at PD 4th comments	41 10-Mar-13 A			1	1	1 1 1	1 1 1	1 1 1	1	1 1 1	1			
_	ment Submission	500 11-Dec-12 A				1		1	1		1				
Seawall —		500 11-Dec-12 A	24-Apr-14 A		1		1	1	1		1	1			
Remaining L	Level of Effort ◆	34th Monthly Progress Report Status	as on 21Oct2014	Ver.5h5		SK filter:						. \			
Actual Level	·	Page 12 of	16		Re	source Pr	ronie Filte	er:Aggreg	jate.Ston	e Aggre	yate (cun	1)			
Actual Work Remaining V															
_	naining Work												ı	Primavera	a Sveta



ontract No. HY/2010/02 Hong Kong - Zhuhai - Macao Bridge	Но	ong Kong B	oundary Cross	sing Facil	lities - R	Reclamati	ion Woı	rks							
vity ID Activity Name	Origina Duration	Start	Finish	Mar	I Apr	May	Jun)13 Jul	Aug	Sen	Oct	Nov	Dec	Jan	2014 Feb
PDAS-00030 Airport Existing Seawall 70m Seawall blocks installation 200nrs			20-Feb-14 A	16	17	18	19	20	21	22	23	24	25	26	27
					; ! !				1	1	: ! !	: ! !		: ! !	
Temporary Seawall CH6+136 - CH6+000 (136m)		3 12-Jul-13 A	20-Feb-14 A						i i i	 	i i i	 		 	
PDTS-10010 Stone Blanket (10,000m3)		2 27-Jul-13 A	29-Jul-13 A		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1										
PDTS-10020 Geotextile Laying 12shts		30-Jul-13 A	30-Jul-13 A		1 1 1			 	_	1	1			1	
PDTS-10025 S1 Temporary Seawall Rockfill type2 2,400m3			20-Aug-13 A		1 1 1			1 1 1 1		1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		!	
PDTS-10030 S1 Temporary Seawall Rockfill Type 1		12-Jul-13 A	24-Sep-13 A		1					1					
PDTS-10040 S1 West1 Temporary Seawall Stone Aggregate 43,526m3 2,500m3/day			25-Dec-13 A		 			 				1			
PDTS-10050 V2 West1 Temporary Seawall Stone Aggregate 45,198m3 2,500m3/day	20	21-Oct-13 A	11-Nov-13 A		 			 	 	1 1 1				!	
PDTS-10060 V2 West1 Temporary Seawall Seawall blocks installation 350nrs	10	10-Feb-14 A	20-Feb-14 A		1			 						1	_
Temporary Seawall CH6+000 - CH5+900 (100m)	193	05-Aug-13 A	05-Mar-14 A		1			! ! !	•	1	1	1		!	
PDTS-20010 Stone Blanket (6,100m3)	2	05-Aug-13 A	06-Aug-13 A		1			 	1	1					
PDTS-20020 Geotextile Laying 12shts	1	07-Aug-13 A	07-Aug-13 A					! ! !	1						
PDTS-20025 S1 Temporary Seawall Rockfill type2 2,400m3	2	26-Aug-13 A	27-Aug-13 A	1	 			L	I	1					
PDTS-20030 S1 Temporary Seawall Rockfill type1 9,500m3	5	25-Sep-13 A	30-Sep-13 A	1	: 1 1 1							1		1	
PDTS-20040 S1 West2 Temporary Seawall Stone Aggregate 43,526m3 2,500m3/day	23	3 26-Dec-13 A	18-Jan-14 A		 			 		1			•		
PDTS-20050 V2 West2 Temporary Seawall Stone Aggregate 45,198m3 2,500m3/day	47	7 12-Nov-13 A	31-Dec-13 A					1 1 1							
PDTS-20060 V2 West2 Temporary Seawall Seawall blocks installation 350nrs	12	2 21-Feb-14 A	05-Mar-14 A		 			 							ı
Temporary Seawall CH5+900 - CH5+800 (100m)	156	6 02-Sep-13 A	20-Feb-14 A		 			 		<u>}</u>				 	
PDTS-30010 Stone Blanket (7,900m3)	2	02-Sep-13 A	03-Sep-13 A					 		1					
PDTS-30020 Geotextile Laying 12shts		04-Sep-13 A	04-Sep-13 A					1 1 1 1		i.				1	
PDTS-30025 S1 Temporary Seawall Rockfill type2 2,400m3			06-Sep-13 A	+	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			1 1 1 1		1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		!	
PDTS-30030 S1 Temporary Seawall Rockfill type1 9,500m3			05-Oct-13 A	-	1			 - 	1	1	<u> </u>				
PDTS-30040 S1 East1 Temporary Seawall Stone Aggregate 43,526m3 2,500m3/day			20-Feb-14 A					; ; L						: :	
PDTS-30050 V2 East1 Temporary Seawall Stone Aggregate 45,198m3 2,500m3/day			13-Jan-14 A	-				 							
Temporary Seawall CH5+800 - CH5+650 (150m)			20-Mar-14 A		 			! !					1		
PDTS-40010 Stone Blanket (7,900m3)			12-Sep-13 A		 			1 1 1 1	1		1	1		1	
			13-Sep-13 A	-				 							
PDTS-40020 Geotextile Laying 11shts								! ! L			ļ			ļ	
PDTS-40025 S1 Temporary Seawall Rockfill type2 2,400m3		· .	16-Sep-13 A		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			1 1 1 1						_	
PDTS-40030 S1 East2 Temporary Seawall Rockfill type1 14,600m3			25-Jan-14 A		1			 	1	1					_
PDTS-40040 S1 East2 Temporary Seawall Stone Aggregate 43,527m3 2,500m3/day			20-Mar-14 A		! ! !			! ! ! !							·
PDTS-40050 V2 East2 Temporary Seawall Stone Aggregate 45,198m3 2,500m3/day			31-Jan-14 A		1 1 1			1 1 1 1		1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1			
Reclamation below +2.5mPD			13-Jan-14 A					 - 	<u> </u>	ļ !	ļ			<u>-</u>	
West1 (South CH 0 - 100 & North CH 6136 - 6000)			20-Dec-13 A					; ; ; ;			1				
A1630a PD - Aggregate bedding & sand blanket at C1			04-Nov-13 A		1 1 1 1			 	1	1	1				
A1630b PD - Marine Fill Type A Sand 100% upto +0mPD at West1 30,540m3 5,000m3/day	S	27-Nov-13 A	05-Dec-13 A		1 1 1			1 1 1	!	1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		!	1	
A1630c PD - Marine Fill Type A Sand 100% upto +2.5mPD at West1 30,540m3 5,000m3/day	5	16-Dec-13 A	20-Dec-13 A					 					-		
West2 (South CH 100 - 225 & North CH 6000 - 5900)	69	01-Nov-13 A	13-Jan-14 A								1				
A1630a10 PD - Aggregate bedding & sand blanket at C2	4	01-Nov-13 A	04-Nov-13 A		! !			 		!	1				
Remaining Level of Effort Milestone Actual Level of Effort Summary Actual Work	34th Monthly Progres	s Report Statu		Ver.5h5		TASK filter: ET Progress Report Mar 2013 to Feb 2014. Resource Profile Filter:Aggregate.Stone Aggregate (cum)									
Remaining Work															
Critical Remaining Work														Primavera	Systen

Contract No. HY/2010/02 Hong Kong - Zhuhai - Macao Bridge	Но	ong Kong B	oundary Crossi	ng Facil	Facilities - Reclamation Works										
Activity ID Activity Name	Origina Duration	Start	Finish	Mar	Apr	May	Jun	013 Jul	Aug	Sep	Oct	Nov	Dec		2014 Feb M
A1630b10 PD - Marine Fill Type A Sand 100% upto +0mPD at West2 30,540m3 5,000m3/day			15-Dec-13 A	16	17	18	19	20	21	22	23	24	25	26	27 2
													_		
A1630c10 PD - Marine Fill Type A Sand 100% upto +2.5mPD at West2 30,540m3 5,000m3/day			13-Jan-14 A		1 1 1				1	1		_			
East1 (South CH 225 - 325 & North CH 5900 - 5800)			08-Nov-13 A		i 1 1 1				1	1 1 1		W			1 1 1
A1635a PD - Aggregate bedding & sand blanket at C3			08-Nov-13 A												
East2 (South CH 325 - 450 & North CH 5800 - 5650)	4	4 09-Nov-13 A	13-Nov-13 A		1					1		₩			1 1 1
A1635a10 PD - Aggregate bedding & sand blanket at C4	4	1 09-Nov-13 A	13-Nov-13 A		! !										
Vertical Band Drain by Land Base	126	26-Nov-13 A	31-Mar-14 A		1 1 1				1	1		_			
Zone C & alternative 10,498nrs upto 23Feb2014	72	26-Nov-13 A	24-Feb-14 A		i 1 1				1	1		•			
A1631 PD - Install vertical band drain at existing seawall 70m by land Plant 1,418nrs upto 12Dec2013	15	26-Nov-13 A	12-Dec-13 A		 					1		_			
A1632 PD - Install vertical band drain 9,080nrs at West1 by Land Plant upto 24Feb2014 (4VP +2HP(NS))	58	3 13-Dec-13 A	24-Feb-14 A		!					!				!	
Zone C & B1 outstanding 8,521nrs from 24Feb2014	35	25-Feb-14 A	31-Mar-14 A		! !										-
A1635 PD - Install vertical band drain 8,520nrs by Land Plants 250nrs/day (4VP + 2HP(NS))	35	25-Feb-14 A	31-Mar-14 A		1 1 1				1	1					÷
Instrumentation & Monitoring Requirements	198	07-Aug-13 A	20-Feb-14 A		; ! ! !				-						
West Portion	82	2 01-Dec-13 A	20-Feb-14 A		 					1		•			
Vertical Seawalls - Cluster Type DV-1 & DV-2	82	2 01-Dec-13 A	20-Feb-14 A								†	.			
DV-1010 PD - Surface Movements Marker (Type 3B) 4nrs west	6	6 01-Jan-14 A	06-Jan-14 A		! ! !			 	 	1					
DV-1020 PD - Combine Inclinometer and Extensometer 2nrs west	10	0 01-Jan-14 A	10-Jan-14 A		1 1 1				1	1					1
DV-1030 PD - Sub-surface Settlement Marker 2nrs west	44	1 01-Dec-13 A	13-Jan-14 A		1					1					1
DV-1040 PD - Settlement Marker (Type 2) 2nrs west	11	1 10-Feb-14 A	20-Feb-14 A		! ! !										
Sloping Seawalls - Cluster Type DS-1 & DS-2			20-Feb-14 A								ļ		,		
DS-1010 PD - Surface Movement Marker (Type 3B) 4nrs east			20-Feb-14 A		i 					1					
DS-1020 PD - Combine Inclinometer and Extensiometer 2nrs east			20-Feb-14 A		! ! !										
DS-1030 PD - Sub-surface Settlement Marker 2nrs east			20-Feb-14 A		1										
DS-1040 PD - Settlement Marker (Type 2) 2nrs east			20-Feb-14 A		! !			1 1 1	1	1					
Reclamation - Cluster Type RA 3sets			20-Feb-14 A		 			¦ 		1	 				
					i 					1					
RA-1010 PD - Extensometer 3nrs			20-Feb-14 A		! ! !										
RA-1020 PD - Standpiipe / Casagrande Piezometer 3nrs			20-Feb-14 A		 					1					
RA-1030 PD - Double Tip Virbrating Wire Piezometer 9nrs			20-Feb-14 A		; ! ! !				1	1					
RA-1040 PD - Sub-surface Settlement Marker 3nrs			20-Feb-14 A							 	ļ 				
RA-1050 PD - Settlement Marker (Type 2) 6nrs			20-Feb-14 A		1										
Reclamation - Cluster Type RB 4sets			20-Feb-14 A		: ! !			1 1 1 1	! !	1	1 1 1 1		•	1	
RB-1010 PD - Sub-Surface Settlement Marker 4nrs west	51	1 01-Jan-14 A	20-Feb-14 A		 			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1	1					
RB-1020 PD - Settlement Marker (Type 2) 4nrs west	51	1 01-Jan-14 A	20-Feb-14 A		!										
East Portion	172	2 07-Aug-13 A	25-Jan-14 A		! ! !				—	1 1	1				
Reclamation - Cluster Type RA 1set	54	4 03-Dec-13 A	25-Jan-14 A							1				₹	
RA-1090 PD - Sub-surface Settlement Marker 1nr	1	1 03-Dec-13 A	03-Dec-13 A		1 1 1			1 1 1 1		1	i i i i		l		
RA-1100 PD - Settlement Marker (Type 2) 2nrs	1	1 25-Jan-14 A	25-Jan-14 A		! ! !			 	 	1	 			1	
Reclamation - Cluster Type RB 4sets	79	9 07-Aug-13 A	24-Oct-13 A		!			!	-						! ! !
Remaining Level of Effort Milestone	34th Monthly Progres	s Report Status	s as on 21Oct2014 V	er.5h5	TA:	SK filter: E	ET Progr	ess Repo	ort Mar 2	013 to Fe	eb 2014.				1
Actual Level of Effort Summary		Monthly Progress Report Status as on 21Oct2014 Ver.5h5 TASK filter: ET Progress Report Mar 2013 to Feb 2014. Resource Profile Filter: Aggregate. Stone Aggregate (cum))									
Actual Work		. 490 10 01													
Remaining Work															
Critical Remaining Work														Primavera	Systems, Ir



Appendix C - Implementation Schedule of Environmental Mitigation Measures

EIA Ref.	EM&A Log	Environmental Mitigation Measures	Location	Implementation
	Ref			Status
Air Quality				
S5.5.6.1 of	A1	The contractor shall follow the procedures and requirements given in the Air Pollution	All construction sites	V
HKBCFEIA		Control (Construction Dust) Regulation		
S5.5.6.2 of	A2	Proper watering of exposed spoil should be undertaken throughout the construction	All construction sites	V
HKBCFEIA		phase:		
and S4.8.1 of		Any excavated or stockpile of dusty material should be covered entirely by		
TKCLKLEIA		impervious sheeting or sprayed with water to maintain the entire surface wet and		
		then removed or backfilled or reinstated where practicable within 24 hours of the		
		excavation or unloading;		
		Any dusty materials remaining after a stockpile is removed should be wetted with		
		water and cleared from the surface of roads;		
		A stockpile of dusty material should not be extend beyond the pedestrian barriers,		
		fencing or traffic cones.		
		Where practicable, vehicle washing facilities with high pressure water jet should be		
		provided at every discernible or designated vehicle exit point. The area where		
		vehicle washing takes place and the road section between the washing facilities		
		and the exit point should be paved with concrete, bituminous materials or		
		hardcores;		
		When there are open excavation and reinstatement works, hoarding of not less than		

EIA Ref.	EM&A Log	Environmental Mitigation Measures	Location	Implementation
	Ref			Status
		2.4m high should be provided as far as practicable along the site boundary with		
		provision for public crossing. Good site practice shall also be adopted by the		
		Contractor to ensure the conditions of the hoardings are properly maintained		
		throughout the construction period;		
		The portion of any road leading only to construction site that is within 30m of a		
		vehicle entrance or exit should be kept clear of dusty materials;		
		Surfaces where any pneumatic or power-driven drilling, cutting, polishing or other		
		mechanical breaking operation takes place should be sprayed with water or a dust		
		suppression chemical continuously;		
		Any area that involves demolition activities should be sprayed with water or a dust		
		suppression chemical immediately prior to, during and immediately after the		
		activities so as to maintain the entire surface wet;		
		Where a scaffolding is erected around the perimeter of a building under		
		construction, effective dust screens, sheeting or netting should be provided to		
		enclose the scaffolding from the ground floor level of the building, or a canopy		
		should be provided from the first floor level up to the highest level of the scaffolding;		
		Any skip hoist for material transport should be totally enclosed by impervious		
		sheeting;		
		Every stock of more than 20 bags of cement or dry pulverised fuel ash (PFA) should		
		be covered entirely by impervious sheeting or placed in an area sheltered on the top		

EIA Ref.	EM&A Log	Environmental Mitigation Measures	Location	Implementation
	Ref			Status
		and the 3 sides;		
		Cement or dry PFA delivered in bulk should be stored in a closed silo fitted with an		
		audible high level alarm which is interlocked with the material filling line and no		
		overfilling is allowed;		
		All unpaved roads/exposed area shall be watered which results in dust suppression		
		by forming moist cohesive films among the discrete grains of road surface material.		
		No burning of debris or other materials on the works areas is allowed;		
		Water spray shall be used during the handling of fill material at the site and at active		
		cuts, excavation and fill sites where dust is likely to be created;		
		Open dropping heights for excavated materials shall be controlled to a maximum		
		height of 2m to minimise the fugitive dust arising from unloading;		
		During transportation by truck, materials shall not be loaded to a level higher than		
		the side and tail boards, and shall be dampened or covered before transport.		
		Materials having the potential to create dust shall not be loaded to a level higher		
		than the side and tail boards, and shall be covered by a clean tarpaulin. The		
		tarpaulin shall be properly secured and shall extend at least 300mm over the edges		
		of the side and tail boards;		
		Loading, unloading, transfer, handling or storage of bulk cement or dry PFA should		
		be carried out in a totally enclosed system or facility, and any vent or exhaust should		
		be fitted with an effective fabric filter or equivalent air pollution control system; and		

EIA Ref.	EM&A Log	Environmental Mitigation Measures	Location	Implementation
	Ref			Status
		Exposed earth should be properly treated by compaction, turfing, hydroseeding,		
		vegetation planting or sealing with latex, vinyl, bitumen, shotcrete or other suitable		
		surface stabiliser within six months after the last construction activity on the		
		construction site or part of the construction site where the exposed earth lies.		
S5.5.6.3 of	A3	The Contractor should undertake proper watering on all exposed spoil and associated	All construction sites	V
HKBCFEIA		work areas (with at least 8 times per day) throughout the construction phase.		
and S4.8.1 of				
TKCLKLEIA				
S5.5.6.4 of	A4	Implement regular dust monitoring under EM&A programme during the construction	Selected	V
HKBCFEIA		stage.	representative dust	
and S4.11 of			monitoring station	
TKCLKLEIA				
S5.5.7.1 of	A5	The following mitigation measures should be adopted to prevent fugitive dust emissions	All construction sites	N/A
HKBCFEIA		for concrete batching plant:		
		Loading, unloading, handling, transfer or storage of any dusty materials should be		
		carried out in totally enclosed system;		
		All dust-laden air or waste gas generated by the process operations should be		
		properly extracted and vented to fabric filtering system to meet the emission limits		
		for TSP;		
		Vents for all silos and cement/ pulverised fuel ash (PFA) weighing scale should be		

Appendix C EMIS 4 May 2014

EIA Ref.	EM&A Log	Environmental Mitigation Measures	Location	Implementation
	Ref			Status
		fitted with fabric filtering system;		
		The materials which may generate airborne dusty emissions should be wetted by water spray system;		
		All receiving hoppers should be enclosed on three sides up to 3m above unloading point;		
		All conveyor transfer points should be totally enclosed;		
		All access and route roads within the premises should be paved and wetted; and		
		Vehicle cleaning facilities should be provided and used by all concrete trucks		
		before leaving the premises to wash off any dust on the wheels and/or body.		
S5.5.2.7 of	A6	The following mitigation measures should be adopted to prevent	All construction sites	N/A
HKBCFEIA		fugitive dust emissions at barging point:		(Construction in
		All road surface within the barging facilities will be paved;		process)
		Dust enclosures will be provided for the loading ramp;		
		Vehicles will be required to pass through designated wheels wash facilities; and		
		Continuous water spray at the loading points.		
Construction	Noise (Air borr	ne)	1	
S6.4.10 of	N1	Use of good site practices to limit noise emissions by considering the following:	All construction sites	V
HKBCFEIA		only well-maintained plant should be operated on-site and plant should be serviced		
		regularly during the construction programme;		

EIA Ref.	EM&A Log	Environmental Mitigation Measures	Location	Implementation
	Ref			Status
		machines and plant (such as trucks, cranes) that may be in intermittent use should		
		be shut down between work periods or should be throttled down to a minimum;		
		plant known to emit noise strongly in one direction, where possible, be orientated		
		so that the noise is directed away from nearby NSRs;		
		silencers or mufflers on construction equipment should be properly fitted and		
		maintained during the construction works;		
		mobile plant should be sited as far away from NSRs as possible and practicable;		
		material stockpiles, mobile container site officer and other structures should be		
		effectively utilised, where practicable, to screen noise from on-site construction		
		activities.		
S6.4.11 of	N2	Install temporary hoarding located on the site boundaries between noisy construction	All construction sites	V
HKBCFEIA		activities and NSRs. The conditions of the hoardings shall be properly maintained		
		throughout the construction period.		
S6.4.12 of	N3	Install movable noise barriers (typically density @14kg/m²), acoustic mat or full enclosure	For plant items listed	N/A
HKBCFEIA		close to noisy plants including air compressor, generators, saw.	in Appendix 6D of the	
			EIA report at all	
			construction sites	
S6.4.13 of	N4	Select "Quiet plants" which comply with the BS 5228 Part 1 or TM standards.	For plant items listed	V
HKBCFEIA			in Appendix 6D of the	
			EIA report at all	

Appendix C EMIS 6 May 2014

EIA Ref.	EM&A Log	Environmental Mitigation Measures	Location	Implementation
	Ref			Status
			construction sites	
S6.4.14 of	N5	Sequencing operation of construction plants where practicable.	All construction sites	V
HKBCFEIA			where practicable	
S5.1 of	N6	Implement a noise monitoring under EM&A programme.	Selected	V
TMCLKLEIA			representative noise	
			monitoring station	
Waste Manag	jement (Consti	ruction Waste)		
S12.6 of	WM1	The Contractor shall identify a coordinator for the management of waste.	All construction sites	V
TMCLKLEIA			All construction sites	
S12.6 of	WM2	The Contractor shall apply for and obtain the appropriate licenses for the disposal of	All construction sites	V
TMCLKLEIA		public fill, chemical waste and effluent discharges.	All construction sites	
S12.6 of	WM3	EM&A of waste handling, storage, transportation, disposal procedures and		V
TMCLKLEIA		documentation through the site audit programme shall be undertaken.	All construction sites	
S8.3.8 of	WM4	Construction and Demolition Material		V
HKBCFEIA		The following mitigation measures should be implemented in handling the waste:		
and S12.6 of		Maintain temporary stockpiles and reuse excavated fill material for backfilling and		
TMCLKLEIA		reinstatement;	All construction sites	
		Carry out on-site sorting;		
		Make provisions in the Contract documents to allow and promote the use of		

EIA Ref.	EM&A Log	Environmental Mitigation Measures	Location	Implementation
	Ref			Status
		recycled aggregates where appropriate;		
		Adopt 'Selective Demolition' technique to demolish the existing structures and		
		facilities with a view to recovering broken concrete effectively for recycling purpose,		
		where possible;		
		Implement a trip-ticket system for each works contract to ensure that the disposal of		
		C&D materials are properly documented and verified;		
		Implement an enhanced Waste Management Plan similar to ETWBTC (Works) No.		
		19/2005 – "Environmental Management on Construction Sites" to encourage on-site		
		sorting of C&D materials and to minimize their generation during the course of		
		construction;		
		In addition, disposal of the C&D materials onto any sensitive locations such as		
		agricultural lands, etc. should be avoided. The Contractor shall propose the final		
		disposal sites to the Project Proponent and get its approval before implementation;		
		and		
		The surplus surcharge should be transferred to a fill bank.		
S8.3.9-	WM5	C&D Waste	All construction sites	V
S8.3.11 of		Standard formwork or pre-fabrication should be used as far as practicable in order to		
HKBCFEIA		minimise the arising of C&D materials. The use of more durable formwork or plastic		
and S12.6 of		facing for the construction works should be considered. Use of wooden hoardings		
TMCLKLEIA		should not be used, as in other projects. Metal hoarding and falsework should		

EIA Ref.	EM&A Log	Environmental Mitigation Measures	Location	Implementation
	Ref			Status
		be used to enhance the possibility of recycling. The purchasing of construction		
		materials will be carefully planned in order to avoid over ordering and wastage.		
		The Contractor should recycle as much of the C&D materials as possible on-site.		
		Public fill and C&D waste should be segregated and stored in different containers or		
		skips to enhance reuse or recycling of materials and their proper disposal. Where		
		practicable, concrete and masonry can be crushed and used as fill. Steel		
		reinforcement bar can be used by scrap steel mills. Different areas of the sites		
		should be considered for such segregation and storage.		
S8.2.12- S8.3.15 of	WM6	Chemical Waste Chemical waste that is produced, as defined by Schedule 1 of the Waste Disposal	All construction sites	V
HKBCFEIA		(Chemical Waste) (General) Regulation, should be handled in accordance with the		
and S12.6 of		Code of Practice on the Packaging, Labelling and Storage of Chemical Wastes.		
TMCLKLEIA		Containers used for the storage of chemical wastes should be suitable for the		
		substance they are holding, resistant to corrosion, maintained in a good condition,		
		and securely closed; have a capacity of less than 450 liters unless the specification		
		has been approved by the EPD; and display a label in English and Chinese in		
		accordance with instructions prescribed in Schedule 2 of the regulation.		
		The storage area for chemical wastes should be clearly labelled and used solely for		
		the storage of chemical waste; enclosed on at least 3 sides; have an impermeable		
		floor and bunding of sufficient capacity to accommodate 110% of the volume of the		

Appendix C EMIS 9 May 2014

EIA Ref.	EM&A Log	Environmental Mitigation Measures	Location	Implementation
	Ref			Status
	NCI	 largest container or 20 % of the total volume of waste stored in that area, whichever is the greatest; have adequate ventilation; covered to prevent rainfall entering; and arranged so that incompatible materials are adequately separated. Disposal of chemical waste should be via a licensed waste collector; be to a facility licensed to receive chemical waste, such as the Chemical Waste Treatment Centre which also offers a chemical waste collection service and can supply the necessary storage containers; or be to a reuser of the waste, under approval from the EPD. 		Otatus
S8.3.16 of HKBCFEIA and S12.6 of TMCLKLEIA	WM7	 Sewage Adequate numbers of portable toilets should be provided for the workers. The portable toilets should be maintained in a state, which will not deter the workers from utilizing these portable toilets. Night soil should be collected by licensed collectors regularly. 	All construction sites	V
S8.3.17 of HKBCFEIA and S12.6 of TMCLKLEIA	WM8	 General Refuse The site and surroundings shall be kept tidy and litter free. General refuse generated on-site should be stored in enclosed bins or compaction units separately from construction and chemical wastes. A reputable waste collector should be employed by the Contractor to remove general refuse from the site, separately from construction and chemical wastes, on a daily basis to minimize odour, pest and litter impacts. Burning of refuse on construction sites is prohibited by law. 	All construction sites	V

Ref • Aluminium cans are often recovered from the waste stream by individual collectors if	Status
Aluminium cans are often recovered from the waste stream by individual collectors if	
they are segregated and made easily accessible. Separate labelled bins for their deposit should be provided if feasible. Office wastes can be reduced through the recycling of paper if volumes are large enough to warrant collection. Participation in a local collection scheme should be considered by the Contractor. In addition, waste separation facilities for paper, aluminum cans, plastic bottles etc., should be provided. Training should be provided to workers about the concepts of site cleanliness and appropriate waste management procedure, including reduction, reuse and recycling of wastes. Sufficient dustbins shall be provided for storage of waste as required under the Public Cleansing and Prevention of Nuisances By-laws. In addition, general refuse shall be cleared daily and shall be disposed of to the nearest licensed landfill or refuse transfer station. All waste containers shall be in a secure area on hardstanding.	

EIA Ref.	EM&A Log	Environmental Mitigation Measures	Location	Implementation
	Ref			Status
Water Quality	(Construction	Phase)		
Water Quality		Phase) Mitigation during the marine works to reduce impacts to within acceptable levels have been recommended and will comprise a series of measures that restrict the method and sequencing of backfilling, as well as protection measures. Details of the measures are provided below: • Reclamation filling for the Project shall not proceed until at least 200m of leading seawall at the reclamation area formed above +2.2mPD, unless otherwise agreement was obtained from EPD, except for the 300m gaps for marine access. All underwater filling works shall be carried out behind seawalls to avoid dispersion of suspended solids outside the Project limit; • Except for the filling of the cellular structures, not more than 15% public fill shall be used for reclamation filling below +2.5mPD during construction of the seawall; • After the seawall is completed except for the 300m marine access as indicated in the EPs, not more than 30% public fill shall be used for reclamation filling below +2.5mPD, unless otherwise agreement from EPD was obtained;	During filling	V Y
		 Upon completion of 200m leading seawall, no more than a total of 60 filling barge trips per day shall be made with a cumulative maximum daily filling rate of 60,000 m3 for HKBCF and TMCLKL southern landfall reclamation during the filling operation; and 		

EIA Ref.	EM&A Log	Environmental Mitigation Measures	Location	Implementation
	Ref			Status
		Upon completion of the whole section of seawall except for the 300m marine access		
		as indicated in the EPs, no more than a total of 190 filling barge trips per day shall be		
		made with a cumulative maximum daily filling rate of 190,000 m3 for the remaining		
		filling operations for HKBCF and TMCLKL southern landfall reclamation.		
		Floating type perimeter silt curtains shall be around the HKBCF site before the		
		commencement of marine works. Staggered layers of silt curtain shall be provided to		
		prevent sediment loss at navigation accesses. The length of each staggered layers		
		shall be at least 200m;		
		Single layer silt curtain to be applied around the North-east airport water intake;		
		The silt-curtains should be maintained in good condition to ensure the sediment		
		plume generated from filling be confined effectively within the site boundary;		
		The filling works shall be scheduled to spread the works evenly over a working day;		
		Cellular structure shall be used for seawall construction;		
		A layer of geotextile shall be placed on top of the seabed before any filling activities		
		take place inside the cellular structures to form the seawall;		
		The conveyor belts shall be fitted with windboards and conveyor release points shall		
		be covered with curtain to prevent any spillage of filling materials onto the		
		surrounding waters; and		
		An additional layer of silt curtain shall be installed near the active stone column		

EIA Ref.	EM&A Log	Environmental Mitigation Measures	Location	Implementation
	Ref			Status
		installation points. A layer of geotextile with stone blanket on top shall be placed on		
		the seabed prior to stone column installation works.		
		All vessels shall be sized such that adequate clearance is maintained between		
		vessels and the sea bed at all states of the tide to ensure that undue turbidity is not		
		generated by turbulence from vessel movement or propeller wash		
S9.11.1.3 of	W2	Land Works	All land-based	V
HKBCFEIA		General construction activities on land should also be governed by standard good	construction sites	
and S6.10		working practice. Specific measures to be written into the works contracts should		
of TMCLKLEIA		include:		
TWOERLEIA		wastewater from temporary site facilities should be controlled to prevent direct		
		discharge to surface or marine waters;		
		sewage effluent and discharges from on-site kitchen facilities shall be		
		directed to Government sewer in accordance with the requirements of the WPCO		
		or collected for disposal offsite. The use of soakaways shall be avoided;		
		storm drainage shall be directed to storm drains via adequately designed sand/silt		
		removal facilities such as sand traps, silt traps and sediment basins. Channels,		
		earth bunds or sand bag barriers should be provided on site to properly direct		
		stormwater to such silt removal facilities. Catchpits and perimeter channels should		
		be constructed in advance of site formation works and earthworks;		

EIA Ref.	EM&A Log	Environmental Mitigation Measures	Location	Implementation
	Ref			Status
		silt removal facilities, channels and manholes shall be maintained and any deposited silt and grit shall be removed regularly, including specifically at the onset of and after each rainstorm;		
		 temporary access roads should be surfaced with crushed stone or gravel; rainwater pumped out from trenches or foundation excavations should be discharged into storm drains via silt removal facilities; 		
		measures should be taken to prevent the washout of construction materials, soil, silt or debris into any drainage system;		
		open stockpiles of construction materials (e.g. aggregates and sand) on site should be covered with tarpaulin or similar fabric during rainstorms;		
		 manholes (including any newly constructed ones) should always be adequately covered and temporarily sealed so as to prevent silt, construction materials or debris from getting into the drainage system, and to prevent storm run-off from getting into foul sewers; 		
		discharges of surface run-off into foul sewers must always be prevented in order not to unduly overload the foul sewerage system;		
		all vehicles and plant should be cleaned before they leave the construction site to ensure that no earth, mud or debris is deposited by them on roads. A wheel washing bay should be provided at every site exit;		

EIA Ref.	EM&A Log	Environmental Mitigation Measures	Location	Implementation
	Ref			Status
		 wheel wash overflow shall be directed to silt removal facilities before being discharged to the storm drain; 		
		the section of construction road between the wheel washing bay and the public road should be surfaced with crushed stone or coarse gravel;		
		wastewater generated from concreting, plastering, internal decoration, cleaning work and other similar activities, shall be screened to remove large objects;		
		 vehicle and plant servicing areas, vehicle wash bays and lubrication facilities shall be located under roofed areas. The drainage in these covered areas shall be connected to foul sewers via a petrol interceptor in accordance with the requirements of the WPCO or collected for offsite disposal; 		
		the contractors shall prepare an oil / chemical cleanup plan and ensure that leakages or spillages are contained and cleaned up immediately;		
		waste oil should be collected and stored for recycling or disposal, in accordance with the Waste Disposal Ordinance;		
		 all fuel tanks and chemical storage areas should be provided with locks and be sited on sealed areas. The storage areas should be surrounded by bunds with a capacity equal to 110% of the storage capacity of the largest tank; and surface run-off from bunded areas should pass through oil/grease traps prior to 		
		discharge to the storm water system		
S9.14 of	W3	Implement a water quality monitoring programme	At identified	V

EIA Ref.	EM&A Log Ref	Environmental Mitigation Measures	Location	Implementation Status
HKBCFEIA and S6.10 of TMCLKLEIA			monitoring location	
S6.10 of TMCLKLEIA	W4	All construction works shall be subject to routine audit to ensure implementation of all EIA recommendations and good working practice.	All construction site areas	V
S10.7 of HKBCFEIA and S8.14 of TMCLKLEIA	E1	 Install silt curtain during the construction Limit works fronts Construct seawall prior to reclamation filling where practicable Good site practices Strict enforcement of no marine dumping Site runoff control Spill response plan 	Seawall, reclamation area	V
S10.7 of HKBCFEIA	E2	Watering to reduce dust generation; prevention of siltation of freshwater habitats; Site runoff should be desilted, to reduce the potential for suspended sediments, organics and other contaminants to enter streams and standing freshwater.	Land-based works areas	V
S10.7 of HKBCFEIA and S8.14 of	E3	Good site practices, including strictly following the permitted works hours, using quieter machines where practicable, and avoiding excessive lightings during night time.	Land-based works areas	V

EIA Ref.	EM&A Log	Environmental Mitigation Measures	Location	Implementation
	Ref			Status
TMCLKLEIA				
S10.7 of	E4	Dolphin Exclusion Zone	Marine works	V
HKBCFEIA		Dolphin watching plan		
and S8.14 of				
TMCLKLEIA				
S10.7 of	E5	Decouple compressors and other equipment on working vessels	Marine works	V
HKBCFEIA		Proposal on design and implementation of acoustic decoupling measures applied		
and S8.14 of		during reclamation works		
TMCLKLEIA		Avoidance of percussive piling		
0407.6	5 0		N. 1	.,
S10.7 of	E6	Control vessel speed	Marine traffic	V
HKBCFEIA		Skipper training		
and S8.14 of		 Predefined and regular routes for working vessels; avoid Brothers Islands 		
TMCLKLEIA				
S10.10 of	E7	Vessel based dolphin monitoring	Northeast and	V
HKBCFEIA			Northwest	
and S8.14 of			Lantau	
TMCLKLEIA				
Fisheries				
S11.7 of	F1	Reduce re-suspension of sediments	Seawall, reclamation	٧
HKBCFEIA		Limit works fronts	area	

Appendix C EMIS 18 May 2014

EIA Ref.	EM&A Log	Environmental Mitigation Measures	Location	Implementation
	Ref			Status
		Good site practices		
		Strict enforcement of no marine dumping		
		Spill response plan		
S11.7 of	F2	Install silt-grease trap in the drainage system collecting surface runoff	Reclamation area	V
HKBCFEIA				
Landscape &	Visual (Constr	uction Phase)		
S14.3.3. 3 of	LV1	Mitigate Landscape Impacts	All construction site	N/A
HKBCFEIA			areas	
and S10.9 of		G1/CM4 Grass-hydroseed or sheeting bare soil surface and stock pile areas.		
TMCLKLEIA		G9 Reserve of loose natural granite rocks for re-use. Provide new coastline to		
		adopt "natural-look" by means of using armour rocks in the form of natural		
		rock materials and planting strip area accommodating screen buffer to		
		enhance "natural-look" of new coastline.		
S10.9 of	LV2	Mitigate Landscape Impacts	All construction site	V
TMCLKLEIA		CM7 Ensure no run-off into water body adjacent to the Project Area.	areas	
S14.3.3. 3 of	LV4	Mitigate Visual Impacts	All construction site	V
HKBCFEIA		V1 Minimize time for construction activities during construction period.	areas	
S10.9 of	LV5	Mitigate Visual Impacts	All construction site	V
TMCLKLEIA		CM6 Control night-time lighting and glare by hooding all lights.	areas	

EIA Ref.	EM&A Log	Environmental Mitigation Measures	Location	Implementation
	Ref			Status
EM&A				
S15.2.2 of	EM1	An Independent Environmental Checker needs to be employed as per the EM&A	All construction site	V
HKBCFEIA		Manual.	areas	
S15.5 - S15.6	EM2	An Environmental Team needs to be employed as per the EM&A Manual.	All construction site	V
of HKBCFEIA		Prepare a systematic Environmental Management Plan to ensure effective implementation of the mitigation measures.	areas	
		An environmental impact monitoring needs to be implementing by the Environmental Team to ensure all the requirements given in the EM&A Manual are fully complied with.		

Legend: V = implemented;

x = not implemented;

N/A = not applicable

Appendix D - Summary of Action and Limit Levels

Table 1 – Action and Limit Levels for 1-hour TSP

Location	Action Level	Limit Level
AMS2	374 μg/m³	500 μg/m³
AMS3A*	368 μg/m³	500 μg/m³
AMS6	360 μg/m³	500 μg/m³
AMS7	370 μg/m³	500 μg/m ³

Remarks: * Action Level set out at AMS3 Ho Yu College is adopted.

Table 2 - Action and Limit Levels for 24-hour TSP

Location	Action Level	Limit Level
AMS2	176 μg/m³	260 μg/m ³
AMS3A*	167 μg/m³	260 μg/m³
AMS6	173 μg/m³	260 μg/m ³
AMS7	183 μg/m³	260 μg/m³

Remarks: * Action Level set out at AMS3 Ho Yu College is adopted.

Table 3 – Action and Limit Levels for Construction Noise (0700-1900 hrs of normal weekdays)

Location	Action Level	Limit Level
NMS2	When one documented	75 dB(A)
	complaint, related to 0700 -	
NMS3A	1900 hours on normal	
	weekdays, is received	*65 / 70 dB(A)
	from any one of the sensitive	
	receivers	

^{*}Daytime noise Limit Level of 70 dB(A) applies to education institutions, while 65dB(A) applies during school examination period.

Table 4 – Action and Limit Levels for Water Quality	Table 4 – Action	and Limit Levels 1	for Water Quality
---	------------------	--------------------	-------------------

Parameters	Action	Limit
DO in mg L ⁻¹	Surface and Middle	Surface and Middle
(Surface, Middle & Bottom)	5.0	4 .2 (except 5 mg/L for FCZ)
	<u>Bottom</u>	<u>Bottom</u>
	4.7	3.6
SS in mg L ⁻¹	23.5 and 120% of upstream	34.4 and 130% of upstream
(depth-averaged)	control station's SS at the	control station's SS at the same
	same tide of the same day	tide of the same day and
		10mg/L for WSD Seawater
		intakes
Turbidity in NTU	27.5 and 120% of upstream	47.0 and 130% of upstream
(depth-averaged)	control station's turbidity at	control station's turbidity at the
	the same tide of the same	same tide of the same day
	day	

Notes:

- "depth-averaged" is calculated by taking the arithmetic means of reading of all three depths.
- 2. For DO, non-compliance of the water quality limits occurs when monitoring result is lower than the limits.
- 3. For turbidity, SS, non-compliance of the water quality limits occurs when monitoring result is higher than the limits.


Table 5(a) Action and Limit Levels for Chinese White Dolphin Monitoring - Approach to Define Action Level (AL) and Limit Level (LL):

	North Lantau Social Cluster	
	NEL	NWL
Action Level	(STG < 70% of baseline) &	(STG < 70% of baseline) &
	(ANI < 70% of baseline)	(ANI < 70% of baseline)
Limit Level	[(STG < 40% of baseline) & (ANI < 40% of baseline)] AND	
	[(STG < 40% of baseline) & (ANI < 40% of baseline)]	

For North Lantau Social Cluster, action level will be trigger if either NEL **or** NWL fall below the criteria; limit level will be triggered if both NEL **and** NWL fall below the criteria.


Table 5(b) Derived Value of Action Level (AL) and Limit Level (LL) for Chinese White Dolphin Monitoring

	North Lantau Social Cluster	
	NEL	NWL
Action Level	(STG < 4.2) &	(STG < 6.9) &
	(ANI < 15.5)	(ANI < 31.3)
Limit Level	[(STG < 2.4) & (ANI <8.9)] AND	
	[(STG < 3.9)& (ANI < 17.9)]	



AECOM

Graphical Presentation of Impact 1-hour TSP
Monitoring Results




HONG KONG - ZHUHAI - MACAO BRIDGE HONG KONG BOUNDARY CROSSING FACILITIES

- RECLAMATION WORKS Graphical Presentation of Impact 24-hour TSP

Monitoring Results

Project No.: 60249820 Date: April 2014 Appendix G

A=COM



*The monitoring station NMS3A were renamed to monitoring station NMS3B after relocation on 29 January

Remarks: Effective from July 2012, the Limit Level at NMS3A was revised to 70dB(A). Daytime noise Limit Level of 70 dB(A) applies to education institutions, while 65dB(A) applies during school examination period.


This Drawing has been prepared for the use of AECOM's client. It may not be used, modified, reproduced or relied upon by third parties, except as agreed by AECOM or as required by law. AECOM accepts no responsibility, and denies any liability whatsover, to any party that uses or relies on this drawing without AECOM's express written co

HONG KONG - ZHUHAI - MACAO BRIDGE HONG KONG BOUNDARY CROSSING FACILITIES

- RECLAMATION WORKS


Graphical Presentation of Impact Daytime Construction Noise Monitoring Results

AECOM




HONG KONG - ZHUHAI - MACAO BRIDGE HONG KONG BOUNDARY CROSSING FACILITIES

AECOM




AECOM

Graphical Presentation of Impact Water Quality
Monitoring Results




AECOM




AECOM

Graphical Presentation of Impact Water Quality
Monitoring Results




AECOM




AECOM


Graphical Presentation of Impact Water Quality
Monitoring Results



AECOM




AECOM




AECOM

Graphical Presentation of Impact Water Quality
Monitoring Results




AECOM




AECOM

- RECLAMATION WORKS Graphical Presentation of Impact Water Quality


Monitoring Results




AECOM




AECOM



AECOM



AECOM




AECOM

- RECLAMATION WORKS

Graphical Presentation of Impact Water Quality


Monitoring Results



- RECLAMATION WORKS


Graphical Presentation of Impact Water Quality Monitoring Results

Appendix G Project No.: 60249820 Date: May 2014




AECOM

Graphical Presentation of Impact Water Quality
Monitoring Results



AECOM




AECOM


- RECLAMATION WORKS

Graphical Presentation of Impact Water Quality


Monitoring Results




AECOM




AECOM




AECOM




Appendix G Project No.: 60249820 Date: May 2014



AECOM




AECOM




AECOM


Graphical Presentation of Impact Water Quality
Monitoring Results









AECOM




AECOM




AECOM




AECOM




AECOM




AECOM



AECOM








AECOM


Graphical Presentation of Impact Water Quality
Monitoring Results




AECOM

- RECLAMATION WORKS


Graphical Presentation of Impact Water Quality
Monitoring Results




AECOM




AECOM



AECOM




AECOM




HONG KONG - ZHUHAI - MACAO BRIDGE HONG KONG BOUNDARY CROSSING FACILITIES

- RECLAMATION WORKS

Graphical Presentation of Impact Water Quality Monitoring Results




AECOM



HONG KONG - ZHUHAI - MACAO BRIDGE HONG KONG BOUNDARY CROSSING FACILITIES


- RECLAMATION WORKS

Graphical Presentation of Impact Water Quality Monitoring Results




AECOM

Graphical Presentation of Impact Water Quality
Monitoring Results



AECOM




HONG KONG - ZHUHAI - MACAO BRIDGE HONG KONG BOUNDARY CROSSING FACILITIES **AECOM**


- RECLAMATION WORKS

Graphical Presentation of Impact Water Quality

Monitoring Results




AECOM




Date: May 2014

Project No.: 60249820


AECOM




AECOM




AECOM




AECOM



AECOM



AECOM



AECOM



China Harbour Engineering Company Limited

Summary of Waste Flow Table (Mar 2013 - Feb 2014)

Project: Hong Kong – Zhuhai – Macao Bridge, Hong Kong Boundary Crossing Facilities – Reclamation Works

Contract No.: HY/2010/02

	Actual Quantities of Inert C&D Materials Generated Monthly					ı		es of C&D Wa	stes Generated Mo		
Month	Total Quantity Generated	Hard Rock and Large Broken Concrete (see Note 1)	Reused in the Contract	Reused in other Projects	Disposed as Public Fill	Imported Fill	Metals	Paper/ cardboard packaging	Plastics (see Note 2)	Chemical Waste (see Note 4)	Others, e.g. general refuse (see Note 3)
	(in '000m ³)	(in '000m ³)	(in '000m ³)	(in '000m ³)	(in '000m ³)	(in '000m ³)	(in '000 kg)	(in '000kg)	(in '000kg)	(in '000kg)	(in '000 m ³)
Mar-13	0.0000	0.0000	0.0000	0.0000	0.0000	121.1545	0.0000	0.0000	0.0000	2.0000	0.0130
Apr-13	0.0000	0.0000	0.0000	0.0000	0.0000	197.7428	0.0000	0.0000	0.0000	0.0000	0.0260
May-13	0.0000	0.0000	0.0000	0.0000	0.0000	360.3733	0.0000	0.0000	0.0000	1.2000	0.0130
Jun-13	0.0000	0.0000	0.0000	0.0000	0.0000	415.9366	0.0000	0.0000	0.0000	0.0000	0.0130
Jul-13	0.0000	0.0000	0.0000	0.0000	0.0000	397.7040	0.0000	0.0000	0.5501	4.0000	0.0260
Aug-13	0.0000	0.0000	0.0000	0.0000	0.0000	447.7517	0.0000	0.0040	0.0000	1.6000	0.0325
Sep-13	0.0000	0.0000	0.0000	0.0000	0.0000	565.0243	0.0140	0.1400	0.0000	1.2000	0.0260
Oct-13	0.0000	0.0000	0.0000	0.0000	0.0000	800.3190	0.0000	0.1960	0.0000	0.0000	0.0325
Nov-13	0.0000	0.0000	0.0000	0.0000	0.0000	797.2930	0.0000	0.1960	0.0000	0.0000	0.0195
Dec-13	0.0000	0.0000	0.0000	0.0000	0.0000	1213.8441	0.0103	0.0000	0.0000	2.0000	0.0260
Jan-14	0.0000	0.0000	0.0000	0.0000	0.0000	1158.9828	0.0000	0.1680	0.0000	2.0000	0.0325
Feb-14	0.0000	0.0000	0.0000	0.0000	0.0000	1064.5957	0.0000	0.2520	0.0000	0.0000	0.0520
Total	0.0000	0.0000	0.0000	0.0000	0.0000	7540.7219	0.0243	0.9560	0.5501	14.0000	0.3120

Notes:

- (1) Broken concrete for recycling into aggregates.
- (2) Plastics refer to plastic bottles/ containers, plastic sheets/ foam from packaging materials.
- (3) Use the conversion factor: 1 full load of dumping truck being equivalent to 6.5 m³ by volume.
- (4) Chemical waste refer to spent "battery" and "oil with water".

Appendix J

Cumulative Statistics on Exceedances, Complaints, Notifications of Summons and Successful Prosecutions

Cumulative statistics on Exceedances

		Total no. recorded in this	Total no. recorded since
		reporting period	project commencement
1-Hour TSP	Action	-	-
	Limit	-	-
24-Hour TSP	Action	-	-
	Limit	•	-
Noise	Action	-	-
	Limit	-	-
Water Quality	Action	1	1
	Limit	1	1

Remarks: Exceedances which are not project-related are not presented in this table.

Cumulative statistics on Exceedances, Complaints, Notifications of Summons and Successful Prosecutions

	Date Received	Subject	Status	Total no. received in this	Total no. received since project
				reporting period	commencement
Environmental complaints	04 March13	One (1) complaint was referred by EPD to ET regarding the construction noise impact from cranes operating from the barges for the Hong Kong –Zhuhai-Macao Bridge Hong Kong Project generating squeak noise in the evening of 1 Mar 2013 causing annoyance to him/her. The investigation results show that the complaint was non-project related.	Closed	1	5

Trong Ho	ng Boundary Cross	ing racinties – Rectamation		arcii 2013 – 1 co	radif 2011
	08 April 13	One (1) complaint was referred by EPD regarding oil dumping observed from various vessels operating for HZMB HK projects near Tung Chung Development Pier over the past few months. The investigation results showed that the complaint was non-project related.	Closed	2	6
	10 May 2013	A complaint referred to the Contractor by EPD on 10 May 2013 regarding the scattered debris of silt curtain noted at Sha Lou Wan and Tung Chung Bay. Immediate inspection and clean up action was taken by the Contractor.	Closed	3	7
	23 May 2013	A follow-up complaint referred by EPD was received on 23 May 2013 regarding the oil stain noted near Tung Chung Development Pier for past few months.	Closed	4	8
	26 Sept 13	One (1) complaint was logged by the Contractor regarding the leakage from work barges causing water pollution near Tuen Mun Richland Garden received on 26 Sept 13. With refer to the available information such as photo record of the incident cannot indicate that the leakage from work barges was caused by the vessel of this Contract and the complaint could not be concluded as project related.	Closed	5	9
	1 Nov 13	As informed by the Contractor on 5 Nov 13, a noise complaint received on 14 Sept 13 was referred to the Contractor of HKBCF on 1 Nov 13. The captioned complaint involves	Closed	6	10

Hong Rong	Boundary Crossi	ing racinties – Reciamation	171	arch 2013 – 1 ct	Juary 2014
		noise generated by a tug boat			
		operating near a pier at Tung Chung			
		around 05:55am-06:45am on 14			
		Sept 13. After investigation, the			
		complaint is considered not likely			
		to be related to the construction			
		works.			
		As informed by the Contractor,			
		complaint received from			
		Penta-Ocean – Gitanes Joint			
		Venture (CV/2012/03)			
		mentioned that the formation			
		works of the Contaminated Mud			
		Pit CMP1 to the South of the			
		Brothers (CMP1 of SB) which			
		has been completed in			
		mid-August 2013 and the pit has			
		been commissioned for			
		receiving contaminated marine			
		mud from other projects starting			
		from 16 August 2013. However,			
		it was recently observed that			
	11 Nov 13	some of the project vessels of	Closed	7	11
		HY/2010/02 had berthed within			
		the said pit and those			
		anchorages would likely cause			
		disruption to the underlying			
		contaminated mud and thus			
		induce unfavourable			
		contamination impact to the			
		surrounding marine			
		environment. In this regard, they			
		reminded the contractor to avoid			
		berthing of their vessels within			
		the boundary of CMP1 of SB			
		thereafter for the sake of			
		environmental concern. After			
		investigation, the complaint is			
		<u> </u>	l	l	I

considered not likely to be related to the construction works. As informed by the Contractor on 5 Dec 13, one complaint was noted on 12 Nov regarding a barge moving through the southern channel. After investigation, the noise complaint was considered as non-project related. As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen Mun Pierhead Garden which	110115 110	Domining C1033	Ing Facilities – Reclamation	141	arch 2013 – 1 co	
As informed by the Contractor on 5 Dec 13, one complaint was noted on 12 Nov regarding a barge moving through the southern channel. After investigation, the noise complaint was considered as non-project related. As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and in quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen			_			
As informed by the Contractor on 5 Dec 13, one complaint was noted on 12 Nov regarding a barge moving through the southern channel. After investigation, the noise complaint was considered as non-project related. As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen						
on 5 Dec 13, one complaint was noted on 12 Nov regarding a barge moving through the southern channel. After investigation, the noise complaint was considered as non-project related. As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen						
noted on 12 Nov regarding a barge moving through the southern channel. After investigation, the noise complaint was considered as non-project related. As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without property covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen						
barge moving through the southern channel. After investigation, the noise complaint was considered as non-project related. As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen						
southern channel. After investigation, the noise complaint was considered as non-project related. As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen			noted on 12 Nov regarding a			
investigation, the noise complaint was considered as non-project related. As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen		5 Dec13		Closed	8	12
complaint was considered as non-project related. As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen			southern channel. After			
non-project related. As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen						
As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen			complaint was considered as			
on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen			non-project related.			
involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen			As informed by the Contractor			
from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen			on 12 Dec 13. A complaint			
discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen			involves the leakage of sand			
Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen			from barges causing water			
material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen Closed 9 13 Closed 10 4 Is a support of the inside of the residential area of Tuen			discoloration at sea near Tuen			
covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen			Mun Pierhead Garden and sand			
of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen			material without properly			
caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen			covered was blown to the inside			
residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen			of the residential area which			
residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly closed 10 14 covered was blown to the inside of the residential area of Tuen		12 Dec13	caused disturbance to	Closed	g	13
monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly closed 10 14 6 Jan 14 material without properly closed 10 14		12 20010	residence. With refer to available	010300		
Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly closed 10 14 covered was blown to the inside of the residential area of Tuen			information provided and			
the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen			monitoring data recorded on 09			
quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen			Dec 13, it cannot indicate that			
the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly Closed 10 14 covered was blown to the inside of the residential area of Tuen			the water quality impact and air			
therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly Closed 10 14 covered was blown to the inside of the residential area of Tuen			quality impact were caused by			
be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen			the vessel of this Contract and			
Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly Closed 10 14 covered was blown to the inside of the residential area of Tuen			therefore the complaint could not			
As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly Closed 10 14 covered was blown to the inside of the residential area of Tuen			be concluded as related to this			
on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen			Contract			
barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen			As informed by the Contractor			
6 Jan 14 material without properly Closed 10 14 covered was blown to the inside of the residential area of Tuen			on 6 Jan, A complaint involves			
covered was blown to the inside of the residential area of Tuen			barges loaded with sand			
of the residential area of Tuen		6 Jan 14	material without properly	Closed	10	14
			covered was blown to the inside			
Mun Pierhead Garden which			of the residential area of Tuen			
			Mun Pierhead Garden which			

caused disturbance to residence was received on 27 Dec 13. With refer to available information provided, it cannot indicate that the weter quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract. EPD referred a complaint from complaint who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons 29 April 13 regarding the suspected on 29 April 13 regarding the suspected invication case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.	Hong Ro	ing Doundary Cross	ring racintles – Reclamation	171	arcii 2013 – 1 co	Tuary 2014
refer to available information provided, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract. EPD referred a complaint from complainant who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons 29 April 13 29 April 13 29 April 13 regarding the suspected - 1 1 1 1 1 1 1			caused disturbance to residence			
provided, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract. EPD referred a complaint from complainant who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons was received on 29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			was received on 27 Dec 13. With			
the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract. EPD referred a complaint from complainant who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons 29 April 13 regarding the suspected - 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			refer to available information			
quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract. EPD referred a complaint from complainant who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons 29 April 13 regarding the suspected - 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			provided, it cannot indicate that			
the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract. EPD referred a complaint from complainant who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons 29 April 13 regarding the suspected - 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			the water quality impact and air			
therefore the complaint could not be concluded as related to this Contract. EPD referred a complaint from complainant who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons 29 April 13 regarding the suspected - 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			quality impact were caused by			
be concluded as related to this Contract. EPD referred a complaint from complainant who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons 29 April 13 regarding the suspected violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			the vessel of this Contract and			
Contract. EPD referred a complaint from complainant who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons 29 April 13 regarding the suspected - 1 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			therefore the complaint could not			
EPD referred a complaint from complainant who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons 29 April 13 regarding the suspected - 1 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			be concluded as related to this			
complainant who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons 29 April 13 regarding the suspected - 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			Contract.			
blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons 29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			EPD referred a complaint from			
the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons 29 April 13 regarding the suspected violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			complainant who advised that			
of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 regarding the suspected violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			blackish mud was found along			
Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 regarding the suspected - 1 1 1 2 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			the edge of the construction site			
the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons 29 April 13 regarding the suspected on 29 April 13 regarding the suspected violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			of Hong Kong-Zhuhai-Macao			
January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons 29 April 13 29 April 13 29 April 13 regarding the suspected - 1 1 1 15 Closed 11 15 As informed by the contract with the investigation results, the complaint is considered as not related to contract HY/2010/02 As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 regarding the suspected - 1 1 1 Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			Bridge Hong Kong Project near			
the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 Notification of summons was received on 29 April 13 As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 As informed by the Contractor on 9 May 13, one summons was received on 29 April 13			the airport in the morning of 18			
21 Jan 14 reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 29 April 13 regarding the Suspected - 1 1 1 15 Closed 11 15 Closed 11 15			January 2014. After receipt of			
21 Jan 14 investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 29 April 13 regarding the suspected - 1 1 0 1 Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			the complaint, site daily was			
investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			reviewed and follow-up	01 1		
dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 29 April 13 regarding the Suspected Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.		21 Jan 14	investigation has been	Closed	11	15
observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			conducted and excavation and			
boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			dredging activities were not			
joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			observed within the site			
Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			boundary of HKBCF during the			
investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of as informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			joint site inspection audit.			
Complaint is considered as not related to contract HY/2010/02 Notification of Summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			Therefore in accordance with the			
Notification of As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			investigation results, the			
Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			complaint is considered as not			
on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			related to contract HY/2010/02			
received on 29 April 13 regarding the suspected - 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.	Notification of		As informed by the Contractor			
29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.	summons		on 9 May 13, one summons was			
violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			received on 29 April 13			
Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.		29 April 13	regarding the suspected	-	1	1
Area WA4 on 31 Oct 2012.			violation case of Noise Control			
			Ordinance (Cap.400) at Works			
Successful 21 May 2013 As informed by the Contractor in - 1 1			Area WA4 on 31 Oct 2012.			
<u> </u>	Successful	21 May 2013	As informed by the Contractor in	-	1	1

Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing Facilities – Reclamation

Annual EM&A Review Report March 2013 – February 2014

Prosecutions	August 13, the Contractor was		
	subsequently prosecuted on 21		
	May 2013 for breaching Cap.400		
	Noise Control Ordinance.		

Appendix K – Event Action Plan

Event / Action Plan for Air Quality

Event		Action	1	
	ET Leader	IEC	ER	Contractor
Action Level				
Exceedance for one sample	Identify source, investigate the causes of exceedance and propose remedial measures; Inform IEC and ER; Repeat measurement to confirm finding; Increase monitoring frequency to daily.	Check monitoring data submitted by ET; Check Contractor's working method.	Notify Contractor.	Rectify any unacceptable practice; Amend working methods if appropriate.
Exceedance for two or more consecutive samples	 Identify source; Inform IEC and ER; Advise the ER on the effectiveness of the proposed remedial measures; Repeat measurements to confirm findings; Increase monitoring frequency to daily; Discuss with IEC and Contractor on remedial actions required; If exceedance continues, arrange meeting with IEC and ER; If exceedance stops, cease additional monitoring. 	 Check monitoring data submitted by ET; Check Contractor's working method; Discuss with ET and Contractor on possible remedial measures; Advise the ER on the effectiveness of the proposed remedial measures; Supervise Implementation of remedial measures. 	Confirm receipt of notification of failure in writing; Notify Contractor; Ensure remedial measures properly implemented.	1. Submit proposals for remedial to ER within 3 working days of notification; 2. Implement the agreed proposals; 3. Amend proposal if appropriate.

Event		Action				
	ET Leader	IEC	ER	Contractor		
Limit Level						
Exceedance for one sample	 Identify source, investigate the causes of exceedance and propose remedial measures; Inform ER, Contractor and EPD; Repeat measurement to confirm finding; Increase monitoring frequency to daily; Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and ER informed of the results. 	Contractor on possible	Confirm receipt of notification of failure in writing; Notify Contractor; Ensure remedial measures properly implemented.	 Take immediate action to avoid further exceedance; Submit proposals for remedial actions to IEC within 3 working days of notification; Implement the agreed proposals; Amend proposal if appropriate. 		

Event				
	ET Leader	IEC	ER	Contractor
Exceedance for two or more consecutive samples	 Notify IEC, ER, Contractor and EPD; Identify source; Repeat measurement to confirm findings; Increase monitoring frequency to daily; Carry out analysis of Contractor's working procedures to determine possible mitigation to be implemented; Arrange meeting with IEC and ER to discuss the remedial actions to be taken; Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and ER informed of the results; If exceedance stops, cease additional monitoring. 	 Discuss amongst ER, ET, and Contractor on the potential remedial actions; Review Contractor's remedial actions whenever necessary to assure their effectiveness and advise the ER accordingly; Supervise the implementation of remedial measures. 	 Confirm receipt of notification of failure in writing; Notify Contractor; In consultation with the IEC, agree with the Contractor on the remedial measures to be implemented; Ensure remedial measures properly implemented; If exceedance continues, consider what portion of the work is responsible and instruct the Contractor to stop that portion of work until the exceedance is abated. 	 Take immediate action to avoid further exceedance; Submit proposals for remedial actions to IEC within 3 working days of notification; Implement the agreed proposals; Resubmit proposals if problem still not under control; Stop the relevant portion of works as determined by the ER until the exceedance is abated.

Event / Action Plan for Construction Noise

Event	Action				
	ET Leader	IEC	ER	Contractor	
Action Level	 Notify IEC and Contractor; Identify source, investigate the causes of exceedance and propose remedial measures; Report the results of investigation to the IEC, ER and Contractor; Discuss with the Contractor and formulate remedial measures; Increase monitoring frequency to check mitigation effectiveness. 	 Review the analysed results submitted by the ET; Review the proposed remedial measures by the Contractor and advise the ER accordingly; Supervise the implementation of remedial measures. 	 Confirm receipt of notification of failure in writing; Notify Contractor; Require Contractor to propose remedial measures for the analysed noise problem; Ensure remedial measures are properly implemented. 	Submit noise mitigation proposals to IEC; Implement noise mitigation proposals.	
Limit Level	 Inform IEC, ER, EPD and Contractor; Identify source; Repeat measurements to confirm findings; Increase monitoring frequency; Carry out analysis of Contractor's working procedures to determine possible mitigation to be implemented; Inform IEC, ER and EPD the causes and actions taken for the exceedances; Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and ER informed of the results; If exceedance stops, cease additional monitoring. 	 Discuss amongst ER, ET, and Contractor on the potential remedial actions; Review Contractors remedial actions whenever necessary to assure their effectiveness and advise the ER accordingly; Supervise the implementation of remedial measures. 	notification of failure in writing; 2. Notify Contractor; 3. Require Contractor to propose remedial measures for the analysed noise problem;	 Take immediate action to avoid further exceedance; Submit proposals for remedial actions to IEC within 3 working days of notification; Implement the agreed proposals; Resubmit proposals if problem still not under control; Stop the relevant portion of works as determined by the ER until the exceedance is abated. 	

Event / Action Plan for Water Quality

Event	Action			
	ET Leader	IEC	ER	Contractor
Action level being exceeded by one sampling day	 Repeat in situ measurement to confirm findings; Identify source(s) of impact; Inform IEC, contractor and ER; Check monitoring data, all plant, equipment and Contractor's working methods; Discuss mitigation measures with IEC, ER and Contractor; Ensure mitigation measures are implemented; Repeat measurement on next day of exceedance to confirm findings. 	 Check monitoring data submitted by ET and Contractor's working methods; Discuss with ET and Contractor on possible remedial actions; Review the proposed mitigation measures submitted by Contractor and advise the ER accordingly; Assess the effectiveness of the implemented mitigation measures. 	Confirm receipt of notification of non-compliance in writing; Discuss with IEC on the proposed mitigation measures; Make agreement on mitigation measures to be implemented; Ensure mitigation measures are properly implemented.	 Inform the ER and confirm notification of the non-compliance in writing; Rectify unacceptable practice; Check all plant and equipment and consider changes of working methods; Discuss with ET and IEC on possible remedial actions and propose mitigation measures to IEC and ER; Implement the agreed mitigation measures. Amend working methods if appropriate.

Event	Action			
	ET Leader	IEC	ER	Contractor
Action level being exceeded by two or more consecutive sampling days	 Repeat in situ measurement to confirm findings; Identify source(s) of impact; Inform IEC, Contractor and ER; Check monitoring data, all plant, equipment and Contractor's working methods; Discuss mitigation measures with IEC, ER and Contractor; Ensure mitigation measures are implemented; Increase the monitoring frequency to daily until no exceedance of Action level; Repeat measurement on next day of exceedance to confirm findings. 	 Check monitoring data submitted by ET and Contractor's working method; Discuss with ET and Contractor on possible remedial actions; Review the proposed mitigation measures submitted by Contractor and advise the ER accordingly; Assess the effectiveness of the implemented mitigation measures. 	 Confirm receipt of notification of non-compliance in writing; Discuss with IEC on the proposed mitigation measures; Make agreement on mitigation measures to be implemented; Ensure mitigation measures are properly implemented; Assess the effectiveness of the implemented mitigation measures. 	 Inform the Engineer and confirm notification of the non-compliance in writing; Rectify unacceptable practice; Check all plant and equipment and consider changes of working methods; Discuss with ET and IEC on possible remedial actions and propose mitigation measures to IEC and ER within 3 working days of notification; Implement the agreed mitigation measures; Amend working methods if appropriate.

Event	Action			
	ET Leader	IEC	ER	Contractor
Limit level being exceeded by one sampling day	 Repeat in-situ measurement to confirm findings; Identify source(s) of impact; Inform IEC, Contractor, ER and EPD; Check monitoring data, all plant, equipment and Contractor's working methods; Discuss mitigation measures with IEC, ER and Contractor; Ensure mitigation measures are implemented; Increase the monitoring frequency to daily until no exceedance of Limit level. 	Check monitoring data submitted by ET and Contractor's working method; Discuss with ET and Contractor on possible remedial actions; Review the proposed mitigation measures submitted by Contractor and advise the ER accordingly; Assess the effectiveness of the implemented mitigation measures.	Confirm receipt of notification of failure in writing; Discuss with IEC, ET and Contractor on the proposed mitigation measures; Request Contractor to critically review the working methods; Ensure mitigation measures are properly implemented; Assess the effectiveness of the implemented mitigation measures.	 Inform the ER and confirm notification of the non-compliance in writing; Rectify unacceptable practice; Check all plant and equipment and consider changes of working methods; Submit proposal of mitigation measures to ER within 3 working days of notification and discuss with ET, IEC and ER; Implement the agreed mitigation measures; Amend working methods if appropriate.

Event	Action			
	ET Leader	IEC	ER	Contractor
or more consecutive sampling days	 Repeat in-situ measurement to confirm findings; Identify source(s) of impact; Inform IEC, contractor, ER and EPD; Check monitoring data, all plant, equipment and Contractor's working methods; Discuss mitigation measures with IEC, ER and Contractor; Ensure mitigation measures are implemented; Increase the monitoring frequency to daily until no exceedance of Limit level for two consecutive days. 	 Check monitoring data submitted by ET and Contractor's working method; Discuss with ET and Contractor on possible remedial actions; Review the Contractor's mitigation measures whenever necessary to assure their effectiveness and advise the ER accordingly. 	 Confirm receipt of notification of failure in writing; Discuss with IEC, ET and Contractor on the proposed mitigation measures; Request Contractor to critically review the working methods; Make agreement on the mitigation measures to be implemented; Ensure mitigation measures are properly implemented; Assess the effectiveness of the implemented mitigation measures; Consider and instruct, if necessary, the Contractor to slow down or to stop all or part of the construction activities until no exceedance of Limit level. 	 Inform the ER and confirm notification of the non-compliance in writing; Take immediate action to avoid further exceedance; Rectify unacceptable practice; Check all plant and equipment and consider changes of working methods; Submit proposal of mitigation measures to ER within 3 working days of notification and discuss with ET, IEC and ER; Implement the agreed mitigation measures; Resubmit proposals of mitigation measures if problem still not under control; As directed by the Engineer, to slow down or to stop all or part of the construction activities until no exceedance of Limit level.

Event / Action Plan for Dolphin Monitoring

Event	Action			
	ET Leader	IEC	ER	Contractor
Dolphin numbers	Repeat statistical data analysis to confirm findings; Review historical data to ensure	Discuss monitoring with the ET and the Contractor; Review proposals for	Discuss with the IEC additional monitoring requirements and any other	Inform the ER and confirm notification of the non-compliance in writing;
and behaviour	differences are as a result of	additional monitoring and any	measures proposed by the	2. Discuss with the ET and the
patterns recorded	natural variation or previously observed seasonal differences;	other measures submitted by the Contractor and advise the	ET; 2. Make agreement on the	IEC and propose measures to the IEC and the ER;
in the impact and	3. Identify source(s) of impact;4. Inform the IEC, ER and	ER accordingly.	measures to be implemented.	Implement the agreed measures.
post-construction	Contractor; 5. Check monitoring data;			
monitoring are	6. Discuss additional dolphin			
significantly lower	monitoring and any other			
than or different	measures, with the IEC and Contractor.			
from those				
recorded in the				
baseline				
monitoring				

Appendix H Impact Dolphin Monitoring Survey Findings and Analysis




Figure 1 Dolphin Sightings Recorded During Monitoring Surveys, March 2013-February 2014




Figure 2 Dolphin Sightings Recorded per Quarter During Monitoring Surveys, March 2013-February 2014




Figure 3 Encounter Rates of "On-Effort" Sightings (i.e., groups) for NEL, NWL and Combined per Quarter for the Period March 2013-February 2014

Appendix H Impact Dolphin Monitoring Survey Findings and Analysis




Figure 4 Dolphin Groups Sizes of More than Five Individuals per Quarter recorded between March 2013 and February 2014




Figure 5 Dolphin density DPSE (number of dolphins per 100 units of survey effort) for March 2013- February 2014

Appendix H Impact Dolphin Monitoring Survey Findings and Analysis




Figure 6 Sighting density SPSE (number of sightings per 100 units of survey effort) for March 2013- February 2014




Figure 7. Yearly Dolphin Density Maps (number of dolphins/dolphin groups per 100 units of survey effort). Derived from Baseline and Advanced Chinese White Dolphin Monitoring for the period between February 2011 - January 2012




Figure 8 Mother and Calf Pairs Sighted per Quarter During Monitoring Surveys, March 2013-February 2014

Appendix H Impact Dolphin Monitoring Survey Findings and Analysis



Appendix H Impact Dolphin Monitoring Survey Findings and Analysis



Appendix H Impact Dolphin Monitoring Survey Findings and Analysis



Figure 9. Calves of females identified in the HZMB Catalogue seen during the year March 2012 and February 2014. Images of first and last sighting to indicate current longevity.




Figure 10. Dolphin Behavioural Activities per Quarter recorded between March 2013 and February 2014

Appendix H Impact Dolphin Monitoring Survey Findings and Analysis




Figure 11 Dolphin Behavioural Activity per Quarter recorded between March 2013 and February 2014;




Figure 12 Dolphin Behavioural Activity per Quarter recorded between March 2012 and February 2013



Figure 13. Chinese white dolphins (Sousa chinensis) are often reported feeding in association with purse seine fishing boats




Figure 14. A Comparison of the location of behaviours in 2011-12 to 2013-14. The island in the northern part of NWL is highlighted as an important feeding area

Table 1 Impact Monitoring Survey Schedule and Details (March 2013 - February 2014)

Date	Location of Survey	No. Sightings ON	No. Sightings Opp	Total km ON EFFORT (favourable conditions)
3/18/2013	NE and NW Lantau	0	1	77.8
3/19/2013	NE Lantau	0	0	33.5
3/27/2013	NW Lantau	0	0	35.2
3/28/2013	NE and NW Lantau	2	0	64.3
4/1/2013	NW Lantau	5	1	63.9
4/2/2013	NE and NW Lantau	0	0	48.1
4/22/2013	NW Lantau	0	0	52.8
4/23/2013	NE and NW Lantau	0	0	40.5
5/9/2013	NW Lantau	3	4	64.6
5/10/2013	NE and NW Lantau	0	0	47.2
5/24/2013	NW Lantau	3	3	63.4
5/27/2013	NE and NW Lantau	0	0	47.6
6/13/2013	NW Lantau	2	2	67
6/14/2013	NE and NW Lantau	0	0	10.1
6/19/2013	NE Lantau	0	0	33.2
6/25/2013	NE and NW Lantau	3	0	59.9
6/26/2013	NW Lantau	1	0	49.3
7/8/2013	NW Lantau	5	6	63.5
7/9/2013	NE and NW Lantau	0	0	47.7
7/23/2013	NW Lantau	6	0	58.4
7/31/2013	NE and NW Lantau	3	1	52.4
8/5/2013	NW Lantau	3	2	70.9
8/6/2013	NE and NW Lantau	2	2	40.2
8/21/2013	NW Lantau	4	2	63.4
8/28/2013	NE and NW Lantau	0	0	26.1
8/30/2013	NE Lantau	0	1	21.7
9/17/2013	NE Lantau	0	0	32.5
9/19/2013	NE and NW Lantau	1	3	77.5
9/24/2013	NW Lantau	6	0	63.4
9/25/2013	NE and NW Lantau	0	0	47.6
10/15/2013	NW Lantau	6	3	59.7
10/17/2013	NE and NW Lantau	0	0	52.1
10/24/2013	NW Lantau	5	2	58.6
10/28/2013	NE and NW Lantau	0	0	51.8
11/1/2013	NE and NW Lantau	2	3	59.5
11/2/2013	NW Lantau	1	3	51

Date	Location of Survey	No. Sightings ON	No. Sightings Opp	Total km ON EFFORT (favourable conditions)
11/7/2013	NW Lantau	6	0	64.7
11/9/2013	NE and NW Lantau	1	0	47.5
12/19/2013	NW Lantau	4	1	62.1
12/21/2013	NE and NW Lantau	0	0	46.8
12/26/2013	NW Lantau	5	1	52.7
12/28/2013	NE and NW Lantau	1	2	59.6
1/6/2014	NW Lantau	5	1	51.5
1/7/2014	NE and NW Lantau	0	0	59.6
1/9/2014	NE and NW Lantau	2	0	59.2
1/10/2014	NW Lantau	2	0	50
2/10/2014	NW Lantau	0	0	43
2/11/2014	NE and NW Lantau	0	0	32
2/17/2014	NW Lantau	2	0	58
2/20/2014	NE and NW Lantau	0	0	52.3

Annual EM&A Review Report for March 2013 - February 2014

Table 2 Impact Monitoring Survey Effort Summary (March 2013 – February 2014)

Table 2 IIIIpa	ict Monitoring	Survey Ellon	Summary (W	arch 2013 =	February 2014)	<u>'</u>
Date	Area	Beaufort	Effort (km)	Season	Vessel	Туре
18/03/2013	NWL	1	74	SPRING	HKDW	IMPACT
18/03/2013	NEL	1	3.8	SPRING	HKDW	IMPACT
19/03/2013	NEL	1	29.9	SPRING	HKDW	IMPACT
19/03/2013	NEL	2	3.6	SPRING	HKDW	IMPACT
27/03/2013	NWL	1	6.8	SPRING	HKDW	IMPACT
27/03/2013	NWL	2	28.4	SPRING	HKDW	IMPACT
28/03/2013	NWL	1	6.8	SPRING	HKDW	IMPACT
28/03/2013	NWL	2	11.5	SPRING	HKDW	IMPACT
28/03/2013	NWL	3	9.2	SPRING	HKDW	IMPACT
28/03/2013	NWL	4	11.8	SPRING	HKDW	IMPACT
28/03/2013	NEL	1	30.2	SPRING	HKDW	IMPACT
28/03/2013	NEL	2	6.6	SPRING	HKDW	IMPACT
01/04/2013	NWL	1	31.7	SPRING	HKDW	IMPACT
01/04/2013	NWL	2	25.8	SPRING	HKDW	IMPACT
01/04/2013	NWL	3	6.4	SPRING	HKDW	IMPACT
02/04/2013	NWL	1	10.6	SPRING	HKDW	IMPACT
02/04/2013	NEL	0	4	SPRING	HKDW	IMPACT
02/04/2013	NEL	1	30.2	SPRING	HKDW	IMPACT
02/04/2013	NEL	2	3.3	SPRING	HKDW	IMPACT
22/04/2013	NWL	1	0.8	SPRING	HKDW	IMPACT
22/04/2013	NWL	2	19.9	SPRING	HKDW	IMPACT
22/04/2013	NWL	3	32.1	SPRING	HKDW	IMPACT
22/04/2013	NWL	4	17.6	SPRING	HKDW	IMPACT
23/04/2013	NWL	1	3.5	SPRING	HKDW	IMPACT
23/04/2013	NEL	1	36.6	SPRING	HKDW	IMPACT
23/04/2013	NEL	2	0.4	SPRING	HKDW	IMPACT
09/05/2013	NWL	1	59.5	SPRING	HKDW	IMPACT
09/05/2013	NWL	2	5.1	SPRING	HKDW	IMPACT
10/05/2013	NWL	1	10.2	SPRING	HKDW	IMPACT
10/05/2013	NEL	0	4.1	SPRING	HKDW	IMPACT
10/05/2013	NEL	1	31.1	SPRING	HKDW	IMPACT
10/05/2013	NEL	2	1.8	SPRING	HKDW	IMPACT
24/05/2013	NWL	0	15.8	SPRING	HKDW	IMPACT
24/05/2013	NWL	1	42.7	SPRING	HKDW	IMPACT
24/05/2013	NWL	2	0.6	SPRING	HKDW	IMPACT
24/05/2013	NWL	3	4.3	SPRING	HKDW	IMPACT
27/05/2013	NWL	2	3.2	SPRING	HKDW	IMPACT
27/05/2013	NWL	3	6.8	SPRING	HKDW	IMPACT
27/05/2013	NWL	4	0.3	SPRING	HKDW	IMPACT
27/05/2013	NEL	1	32.1	SPRING	HKDW	IMPACT
27/05/2013	NEL	2	3.7	SPRING	HKDW	IMPACT

Date 07/05/0040	Area	Beaufort	Effort (km)	Season	Vessel	Туре
27/05/2013	NEL	3	1.8	SPRING	HKDW	IMPACT
13/06/2013	NWL	1	28.1	SUMMER	HKDW	IMPACT
13/06/2013	NWL	2	31.7	SUMMER	HKDW	IMPACT
13/06/2013	NWL	3	7.2	SUMMER	HKDW	IMPACT
14/06/2013	NWL	1	6.6	SUMMER	HKDW	IMPACT
14/06/2013	NEL	1	3.5	SUMMER	HKDW	IMPACT
19/06/2013	NEL	1	33.2	SUMMER	HKDW	IMPACT
25/06/2013	NEL	1	16.2	SUMMER	HKDW	IMPACT
25/06/2013	NEL	2	18.6	SUMMER	HKDW	IMPACT
25/06/2013	NEL	3	2	SUMMER	HKDW	IMPACT
25/06/2013	NWL	2	8.2	SUMMER	HKDW	IMPACT
25/06/2013	NWL	3	14.9	SUMMER	HKDW	IMPACT
25/06/2013	NWL	4	1.6	SUMMER	HKDW	IMPACT
26/06/2013	NWL	2	14	SUMMER	HKDW	IMPACT
26/06/2013	NWL	3	35.3	SUMMER	HKDW	IMPACT
08/07/2013	NWL	1	29.9	SUMMER	HKDW	IMPACT
08/07/2013	NWL	2	22.1	SUMMER	HKDW	IMPACT
08/07/2013	NWL	3	11.5	SUMMER	HKDW	IMPACT
09/07/2013	NWL	1	10	SUMMER	HKDW	IMPACT
09/07/2013	NEL	1	27.2	SUMMER	HKDW	IMPACT
09/07/2013	NEL	2	9.2	SUMMER	HKDW	IMPACT
09/07/2013	NEL	3	1.3	SUMMER	HKDW	IMPACT
23/07/2013	NWL	0	3.8	SUMMER	HKDW	IMPACT
23/07/2013	NWL	1	32.6	SUMMER	HKDW	IMPACT
23/07/2013	NWL	2	22	SUMMER	HKDW	IMPACT
31/07/2013	NWL	2	12.3	SUMMER	HKDW	IMPACT
31/07/2013	NWL	3	3.2	SUMMER	HKDW	IMPACT
31/07/2013	NEL	1	2	SUMMER	HKDW	IMPACT
31/07/2013	NEL	2	25.9	SUMMER	HKDW	IMPACT
31/07/2013	NEL	3	9	SUMMER	HKDW	IMPACT
05/08/2013	NWL	1	63	SUMMER	HKDW	IMPACT
05/08/2013	NWL	2	7.9	SUMMER	HKDW	IMPACT
06/08/2013	NWL	1	3.1	SUMMER	HKDW	IMPACT
06/08/2013	NEL	1	22.4	SUMMER	HKDW	IMPACT
06/08/2013	NEL	2	9.3	SUMMER	HKDW	IMPACT
06/08/2013	NEL	3	5.4	SUMMER	HKDW	IMPACT
21/08/2013	NWL	1	46.2	SUMMER	HKDW	IMPACT
21/08/2013	NWL	2	17.2	SUMMER	HKDW	IMPACT
28/08/2013	NWL	1	10.7	SUMMER	HKDW	IMPACT
28/08/2013	NEL	1	15.4	SUMMER	HKDW	IMPACT
30/08/2013	NEL	1	14.6	SUMMER	HKDW	IMPACT
30/08/2013	NEL	2	7.1	SUMMER	HKDW	IMPACT

						013 - February 20
Date	Area	Beaufort	Effort (km)	Season	Vessel	Туре
17/09/2013	NEL	1	9.2	AUTUMN	HKDW	IMPACT
17/09/2013	NEL	2	15.6	AUTUMN	HKDW	IMPACT
17/09/2013	NEL	3	7.7	AUTUMN	HKDW	IMPACT
17/09/2013	NEL	4	1	AUTUMN	HKDW	IMPACT
19/09/2013	NEL	2	3.5	AUTUMN	HKDW	IMPACT
19/09/2013	NWL	1	10.6	AUTUMN	HKDW	IMPACT
19/09/2013	NWL	2	44.7	AUTUMN	HKDW	IMPACT
19/09/2013	NWL	3	18.7	AUTUMN	HKDW	IMPACT
24/09/2013	NWL	1	23.6	AUTUMN	HKDW	IMPACT
24/09/2013	NWL	2	19.4	AUTUMN	HKDW	IMPACT
24/09/2013	NWL	3	20.4	AUTUMN	HKDW	IMPACT
25/09/2013	NWL	1	7.6	AUTUMN	HKDW	IMPACT
25/09/2013	NWL	2	2.7	AUTUMN	HKDW	IMPACT
25/09/2013	NEL	1	20.3	AUTUMN	HKDW	IMPACT
25/09/2013	NEL	2	17	AUTUMN	HKDW	IMPACT
15/10/2013	NWL	1	35.8	AUTUMN	HKDW	IMPACT
15/10/2013	NWL	2	23.9	AUTUMN	HKDW	IMPACT
17/10/2013	NWL	1	1.1	AUTUMN	HKDW	IMPACT
17/10/2013	NWL	2	7.4	AUTUMN	HKDW	IMPACT
17/10/2013	NWL	3	6	AUTUMN	HKDW	IMPACT
17/10/2013	NEL	1	9.2	AUTUMN	HKDW	IMPACT
17/10/2013	NEL	2	20.5	AUTUMN	HKDW	IMPACT
17/10/2013	NEL	3	7.9	AUTUMN	HKDW	IMPACT
24/10/2013	NWL	1	12.2	AUTUMN	HKDW	IMPACT
24/10/2013	NWL	2	32.7	AUTUMN	HKDW	IMPACT
24/10/2013	NWL	3	13.7	AUTUMN	HKDW	IMPACT
24/10/2013	NWL	4	0.1	AUTUMN	HKDW	IMPACT
28/10/2013	NWL	1	4.9	AUTUMN	HKDW	IMPACT
28/10/2013	NWL	2	10.2	AUTUMN	HKDW	IMPACT
28/10/2013	NEL	1	14.6	AUTUMN	HKDW	IMPACT
28/10/2013	NEL	2	10.7	AUTUMN	HKDW	IMPACT
28/10/2013	NEL	3	11.4	AUTUMN	HKDW	IMPACT
01/11/2013	NEL	1	35.4	AUTUMN	HKDW	IMPACT
01/11/2013	NWL	1	14.6	AUTUMN	HKDW	IMPACT
01/11/2013	NWL	2	9.5	AUTUMN	HKDW	IMPACT
02/11/2013	NWL	2	26.7	AUTUMN	HKDW	IMPACT
02/11/2013	NWL	3	24.3	AUTUMN	HKDW	IMPACT
02/11/2013	NWL	4	1.2	AUTUMN	HKDW	IMPACT
07/11/2013	NWL	1	43.4	AUTUMN	HKDW	IMPACT
07/11/2013	NWL	2	21.3	AUTUMN	HKDW	IMPACT
09/11/2013	NEL	1	10	AUTUMN	HKDW	IMPACT
09/11/2013	NEL	2	21.2	AUTUMN	HKDW	IMPACT

Date	Area	Beaufort	Effort (km)	Season	Vessel	Туре
09/11/2013	NEL	3	6.5	AUTUMN	HKDW	IMPACT
09/11/2013	NWL	1	3.7	AUTUMN	HKDW	IMPACT
09/11/2013	NWL	2	6.1	AUTUMN	HKDW	IMPACT
19/12/2013	NWL	2	40.5	WINTER	HKDW	IMPACT
19/12/2013	NWL	3	21.6	WINTER	HKDW	IMPACT
21/12/2013	NWL	2	7.9	WINTER	HKDW	IMPACT
21/12/2013	NWL	3	2.1	WINTER	HKDW	IMPACT
21/12/2013	NEL	1	8.3	WINTER	HKDW	IMPACT
21/12/2013	NEL	2	20.9	WINTER	HKDW	IMPACT
21/12/2013	NEL	3	7.6	WINTER	HKDW	IMPACT
26/12/2013	NWL	2	35.8	WINTER	HKDW	IMPACT
26/12/2013	NWL	3	16.9	WINTER	HKDW	IMPACT
28/12/2013	NWL	1	4.8	WINTER	HKDW	IMPACT
28/12/2013	NWL	2	11.7	WINTER	HKDW	IMPACT
28/12/2013	NWL	3	6.9	WINTER	HKDW	IMPACT
28/12/2013	NEL	1	25	WINTER	HKDW	IMPACT
28/12/2013	NEL	2	11.2	WINTER	HKDW	IMPACT
06/01/2014	NWL	2	27.6	WINTER	HKDW	IMPACT
06/01/2014	NWL	3	23.9	WINTER	HKDW	IMPACT
07/01/2014	NWL	2	10.6	WINTER	HKDW	IMPACT
07/01/2014	NWL	3	12.5	WINTER	HKDW	IMPACT
07/01/2014	NEL	1	1.7	WINTER	HKDW	IMPACT
07/01/2014	NEL	2	33.1	WINTER	HKDW	IMPACT
07/01/2014	NEL	3	1.7	WINTER	HKDW	IMPACT
09/01/2014	NEL	1	20	WINTER	HKDW	IMPACT
09/01/2014	NEL	2	15.5	WINTER	HKDW	IMPACT
09/01/2014	NWL	2	23.7	WINTER	HKDW	IMPACT
10/01/2014	NWL	2	40.6	WINTER	HKDW	IMPACT
10/01/2014	NWL	3	9.4	WINTER	HKDW	IMPACT
10/02/2014	NWL	1	0.3	WINTER	HKDW	IMPACT
10/02/2014	NWL	2	4.9	WINTER	HKDW	IMPACT
10/02/2014	NWL	3	37.8	WINTER	HKDW	IMPACT
10/02/2014	NWL	4	25	WINTER	HKDW	IMPACT
11/02/2014	NWL	3	3.7	WINTER	HKDW	IMPACT
11/02/2014	NWL	4	2.4	WINTER	HKDW	IMPACT
11/02/2014	NEL	1	1.4	WINTER	HKDW	IMPACT
11/02/2014	NEL	3	26.9	WINTER	HKDW	IMPACT
11/02/2014	NEL	4	9.3	WINTER	HKDW	IMPACT
17/02/2014	NWL	2	15.7	WINTER	HKDW	IMPACT
17/02/2014	NWL	3	42.3	WINTER	HKDW	IMPACT
17/02/2014	NWL	4	1.4	WINTER	HKDW	IMPACT
20/02/2014	NWL	1	0.1	WINTER	HKDW	IMPACT

Date	Area	Beaufort	Effort (km)	Season	Vessel	Туре
20/02/2014	NWL	3	14.7	WINTER	HKDW	IMPACT
20/02/2014	NEL	1	0.1	WINTER	HKDW	IMPACT
20/02/2014	NEL	2	11	WINTER	HKDW	IMPACT
20/02/2014	NEL	3	26.4	WINTER	HKDW	IMPACT

Table 3. Comparison of low, moderate and high habitat utilisation in NEL and NWL between years 2011-12 and 2013-14 (in %)

	Advanced*	2013-14	Advanced*	2013-14	
Frequency of	NW	L	NEL		
Use		DF	SE		
<20	68	76	76	100	
20-60	16	14	20	0	
> 60	17	10	4	0	
		SP	SE		
<5	51	72	60	91	
5-15	27	20	31	9	
>15	22	8	9	0	

^{*}Advance = advance baseline monitoring conducted between 2011 and 2012.

Annual EM&A Review Report for March 2013 - February 2014

Table 4 Sightings of Individually Identified Chinese White Dolphin (Sousa chinensis) between March 2012 – February 2014 and baseline sightings

Identification Number	Baseline Identification Number	Date (YYYY-MM-DD)	Sighting Number	Area Sighted
HZMB 118		2014-01-06	890	NWL
HZMB 117		2014-01-06	888	NWL
HZMB 116		2013-12-26	879	NWL
HZMB 115		2013-12-26	879	NWL
HZMB 114		2013-10-24	827	NWL
HZMB 113		2013-10-24	827	NWL
HZMB 112		2013-10-15	815	NWL
HZMB111		2013-10-15	815	NWL
HZMB 110		2013-10-15	812	NWL
HZMB 108		2013-08-30	780	NEL
HZMB 107		2013-08-21	770	NWL
HZMB 106		2013-08-21	769	NWL
HZMB 105		2013-07-08	711	NWL
HZMB 104		2013-07-08	711	NWL
HZMB 103		2013-07-08	711	NWL
HZMB 102		2013-07-08	706	NWL
HZMB 101		2013-07-08	706	NWL
HZMB 100		2013-07-08	706	NWL
HZMB 099		2013-06-13	681	NWL
1121110 099		2013-06-13	680	NWL
		2014-01-06	888	NWL
		2013-11-02	849	NWL
UZMD 000	NII 404	2013-11-02	845	NWL
HZMB 098	NL104	2013-10-24	831	NWL
		2013-07-08	711	NWL
		2013-05-24	659	NWL
HZMB 097		2013-05-09	647	NWL
HZMB 096		2013-04-01	621	NWL
		2013-08-30	780	NEL
LIZMD OOF		2013-06-25	697	NWL
HZMB 095		2013-06-13	682	NWL
		2013-04-01	621	NWL

Identification Number	Baseline Identification Number	Date (YYYY-MM-DD)	Sighting Number	Area Sighted
Number	Number	2014-02-17	910	NWL NWL
HZMP 004		2013-06-26	703	NWL
HZMB 094		2013-06-25	698	NWL
		2013-03-18	601	NWL
11714D 000		2013-05-24	657	NWL
HZMB 093		2013-02-21	587	NWL
117NAD 000		2013-02-21	589	NWL
HZMB 092		2013-02-15	581	NWL
HZMB 091		2013-02-15	579	NWL
		2013-06-25	697	NWL
HZMB 090		2013-06-13	682	NWL
		2013-02-15	579	NWL
HZMB 089		2013-02-15	579	NWL
HZMB 088		2013-02-15	579	NWL
HZMB 087		2013-02-15	579	NWL
		2013-05-09	642	NWL
HZMB 086	NL242	2013-02-15	579	NWL
		2011-10-10	Baseline	NWL
		2013-06-26	703	NWL
HZMB 085		2013-02-15	579	NWL
HZMB 084		2013-02-14	575	NWL
HZMB 083	NL136	2013-12-19	863	NWL
		2013-03-28	607	NWL
		2013-02-15	579	NWL
		2013-01-28	568	NWL
		2012-01-28	564	NWL

Identification	Baseline	Date	Sighting Number	Area Sighted
Number	Identification Number	(YYYY-MM-DD)		
HZMB 082		2013-02-21	587	NWL
		2013-02-15	579	NWL
		2013-01-28	563	NWL
HZMB 081		2013-01-28	559	NWL
		2013-01-28	557	NWL
HZMB 080		2013-01-28	556	NWL
HZMB 079		2013-01-28	556	NWL
HZMB 078		2013-02-15	579	NWL
		2013-01-08	552	NWL
HZMB 077		2013-12-26	878	NWL
		2013-07-08	706	NWL
		2012-12-11	541	NWL
HZMB 076		2013-07-08	706	NWL
		2012-12-11	541	NWL
HZMB 075		2012-12-06	525	NEL
HZMB 074		2013-05-09	647	NWL
		2013-04-01	623	NWL
		2013-04-01	621	NWL
		2013-02-21	594	NEL
		2012-12-10	529	NEL
		2012-12-06	525	NEL
HZMB 073		2013-05-09	647	NWL
		2013-04-01	623	NWL
		2013-04-01	621	NWL
		2013-02-21	594	NEL
		2012-12-10	529	NEL
		2012-12-06	525	NEL
HZMB 072		2012-10-24	476	NWL

Identification	Baseline	Date	Sighting Number	Area Sighted
Number	Identification Number	(YYYY-MM-DD)		
HZMB 071		2012-10-24	475	NWL
		2012-10-12	466	NWL
HZMB 070		2012-10-24	476	NWL
HZMB 069		2013-08-21	774	NWL
		2013-07-08	711	NWL
		2012-10-24	476	NWL
HZMB 068		2013-11-01	839	NWL
		2012-10-24	476	NWL
HZMB 067		2012-10-24	475	NWL
HZMB 066	NL93	2013-01-28	559	NWL
		2012-12-11	537	NWL
		2012-10-24	475	NWL
		2012-10-12	466	NWL
HZMB 064		2013-05-09	647	NWL
		2013-01-28	561	NWL
		2012-10-24	475	NWL
		2012-10-12	466	NWL
HZMB 063		2013-05-09	647	NWL
		2012-10-12	466	NWL
HZMB 062		2012-12-06	525	NEL
		2012-10-11	457	NWL
HZMB 060		2012-09-18	447	NWL
HZMB 059		2013-02-21	591	NWL
		2012-09-18	445	NWL
HZMB 057		2012-09-18	440	NWL
HZMB 056		2012-09-18	442	NWL
		2012-09-05	433	NEL

Identification	Baseline Identification	Date		-
Number	Number	(YYYY-MM-DD)	Sighting Number	Area Sighted
HZMB 055		2012-09-04	425	NWL
HZMB 054	CH34	2014-01-06	888	NWL
		2013-11-07	854	NWL
		2013-11-02	845	NWL
		2013-10-24	831	NWL
		2013-08-30	780	NEL
		2013-07-08	711	NWL
		2013-09-18	448	NWL
		2012-09-05	432	NEL
		2011-11-07	Baseline	NWL
		2011-11-05	Baseline	NWL
		2011-11-02	Baseline	NWL
		2011-11-01	Baseline	NEL
		2011-11-01	Baseline	NEL
		2011-10-28	Baseline	NWL
		2011-10-06	Baseline	NWL
HZMB 053		2012-09-04	425	NWL
HZMB 052		2012-09-04	423	NWL
HZMB 051	NL213	2013-05-09	644	NWL
		2013-04-01	622	NWL
		2013-02-15	582	NWL
		2013-02-15	581	NWL
		2013-01-28	559	NWL
		2013-01-28	556	NWL
		2012-09-04	422	NWL
HZMB 050		2014-01-10	900	NWL
		2014-01-06	888	NWL
		2013-02-15	579	NWL
		2012-09-04	421	NWL

Identification Number	Baseline Identification	Date	Sighting Number	Area Sighted
	Number	(YYYY-MM-DD)		
HZMB 049		2012-09-03	419	NWL
HZMB 048		2012-09-03	419	NWL
HZMB 047		2012-09-03	412	NWL
HZMB 046		2012-09-03	412	NWL
HZMB 045		2014-02-17	910	NWL
		2013-06-13	682	NWL
		2013-02-15	579	NWL
		2012-11-01	495	NWL
HZMB 044	NL98	2014-02-17	910	NWL
		2013-12-19	864	NWL
		2013-11-02	845	NWL
		2013-11-01	842	NWL
		2013-10-15	819	NWL
		2013-05-09	648	NWL
		2013-05-09	647	NWL
		2013-04-01	623	NWL
		2013-04-01	621	NWL
		2013-02-15	579	NWL
		2012-11-01	495	NWL
		2012-09-18	448	NWL
HZMB 043		2012-09-03	407	NWL
HZMB 042	NL260	2013-12-19	863	NWL
		2012-11-01	495	NWL
		2011-11-07	Baseline	NWL

Identification	ification Baseline Date Sightin		Sighting Number	Area Sighted
Number	Identification Number	(YYYY-MM-DD)		
HZMB 041	NL24	2014-02-17	910	NWL
		2013-11-02	845	NWL
		2013-05-09	648	NWL
		2013-05-09	647	NWL
		2013-04-01	623	NWL
		2013-04-01	621	NWL
		2013-02-15	579	NWL
		2012-11-01	495	NWL
		2011-11-06	Baseline	NEL
		2011-11-05	Baseline	NWL
		2011-11-05	Baseline	NWL
		2011-10-10	Baseline	NWL
HZMB 040		2014-02-17	910	NWL
		2014-01-06	893	NWL
		2013-10-15	821	NWL
		2013-07-08	714	NWL
		2013-07-08	711	NWL
		2013-02-21	589	NWL
		2012-11-01	493	NWL
HZMB 038		2012-11-01	490	NWL
HZMB 037		2012-11-01	490	NWL
HZMB 036		2012-09-03	407	NWL
		2012-11-01	490	NWL
HZMB 035		2013-02-15	579	NWL
		2012-11-01	490	NWL
HZMB 034		2012-11-01	493	NWL
HZMB 028		2013-04-01	625	NWL
		2012-08-06	373	NWL
HZMB 027		2013-12-19	863	NWL
		2013-02-15	579	NWL
		2013-01-28	568	NWL
		2013-01-28	564	NWL
		2012-06-14	299	NWL

Identification	Baseline	Date	Sighting Number	Area Sighted
Number	Identification Number	(YYYY-MM-DD)		
HZMB 026		2013-06-25	697	NWL
		2013-05-09	642	NWL
		2013-01-28	561	NWL
		2012-06-13	295	NEL
HZMB 025		2013-02-22	596	NEL
		2013-02-21	591	NWL
		2012-12-06	525	NEL
		2012-10-11	457	NWL
		2012-06-13	295	NEL
HZMB 024		2013-03-18	601	NWL
		2012-06-13	295	NEL
HZMB 023		2014-01-06	888	NWL
		2013-07-08	715	NWL
		2013-07-08	711	NWL
		2013-04-01	619	NWL
		2013-02-21	589	NWL
		2013-02-15	579	NWL
		2012-07-10	330	NWL
HZMB 022		2014-01-06	888	NWL
		2013-10-24	827	NWL
		2013-07-08	715	NWL
		2013-07-08	711	NWL
		2013-04-01	619	NWL
		2013-02-21	589	NWL
		2013-02-15	579	NWL
		2012-07-10	330	NWL
HZMB 021	NL37	2012-07-10	330	NWL
		2011-09-16	Baseline	NWL
HZMB 020		2012-07-10	330	NWL
HZMB 019		2012-07-10	330	NWL

Identification	Baseline	Date	Sighting Number	h 2013 - February 2014 Area Sighted
Number	Identification Number	(YYYY-MM-DD)		
HZMB 018		2014-02-17	910	NWL
		2013-05-09	647	NWL
		2013-02-21	594	NEL
		2012-12-10	529	NEL
		2012-07-10	330	NWL
HZMB 017		2012-07-10	330	NWL
HZMB 016		2013-07-08	706	NWL
		2012-12-11	539	NWL
		2012-09-18	446	NWL
		2012-09-04	421	NWL
		2012-07-10	330	NWL
HZMB 015		2012-07-10	330	NEL
HZMB 014	NL176	2013-12-26	880	NWL
		2012-08-06	373	NWL
		2012-06-13	295	NEL
		2011-11-06	Baseline	NEL
		2011-11-01	Baseline	NEL
		2011-11-01	Baseline	NEL
HZMB 013		2012-05-28	281	NWL
HZMB 012		2012-05-28	281	NWL
HZMB 011	EL01	2013-02-22	597	NEL
		2013-02-21	592	NEL
		2013-02-14	572	NEL
		2012-11-06	517	NEL
		2012-09-19	452	NWL
		2012-03-31	261	NEL
		2011-11-02	Baseline	NWL
		2011-11-01	Baseline	NEL
HZMB 009		2012-05-28	281	NWL

Identification	Baseline	Date	Sighting Number	Area Sighted
Number	Identification Number	(YYYY-MM-DD)		
HZMB 008		2012-05-28	281	NWL
HZMB 007	NL246	2012-12-10	529	NEL
HZMB 006		2013-02-21	594	NEL
		2012-12-11	539	NWL
		2012-11-01	495	NWL
		2012-03-29	250	NWL
HZMB 005		2013-11-09	860	NWL
		2013-11-07	858	NWL
		2013-10-15	813	NWL
		2012-12-10	532	NWL
		2012-08-06	374	NWL
		2012-05-28	287	NWL
HZMB 004		2012-09-04	421	NWL
		2012-03-31	262	NWL
HZMB 003	NL179	2014-10-15	812	NWL
		2013-06-25	697	NWL
		2012-12-10	529	NEL
		2012-03-31	261	NWL
		2011-11-06	Baseline	NEL
		2011-09-16	Baseline	NWL

Identification	Baseline	Date	Sighting Number	Area Sighted
Number	Identification Number	(YYYY-MM-DD)		
HZMB 002	WL111	2013-12-26	878	NWL
		2013-12-19	863	NWL
		2013-11-01	839	NWL
		2013-10-15	819	NWL
		2013-09-24	798	NWL
		2013-02-14	573	NWL
		2012-12-11	536	NWL
		2012-12-11	535	NWL
		2012-10-12	466	NWL
		2012-10-24	475	NWL
		2012-05-28	281	NWL
		2012-03-29	250	NWL
HZMB 001	WL46	2013-08-21	771	NWL
		2013-06-13	681	NWL
		2013-04-01	617	NWL
		2013-02-14	573	NWL
		2012-03-29	250	NWL
	CH98	2011-11-02	Baseline	NWL
	NL11	2011-11-02	Baseline	NWL
		2011-11-07	Baseline	NWL
	NL12	2011-11-02	Baseline	NWL
	NL33	2011-09-23	Baseline	NWL
		2011-11-01	Baseline	NEL
		2011-11-05	Baseline	NWL
		2011-11-07	Baseline	NWL
	NL37	2011-09-16	Baseline	NWL
	NL46	2011-10-28	Baseline	NWL
	1	1	1	



China Harbour Engineering Company Limited

Summary of Waste Flow Table (Mar 2013 - Feb 2014)

Project: Hong Kong – Zhuhai – Macao Bridge, Hong Kong Boundary Crossing Facilities – Reclamation Works

Contract No.: HY/2010/02

	Actual Quantities of Inert C&D Materials Generated Monthly						ı		es of C&D Wa	stes Generated Mo	
Month	Total Quantity Generated	Hard Rock and Large Broken Concrete (see Note 1)	Reused in the Contract	Reused in other Projects	Disposed as Public Fill	Imported Fill	Metals	Paper/ cardboard packaging	Plastics (see Note 2)	Chemical Waste (see Note 4)	Others, e.g. general refuse (see Note 3)
	(in '000m ³)	(in '000m ³)	(in '000m ³)	(in '000m ³)	(in '000m ³)	(in '000m ³)	(in '000 kg)	(in '000kg)	(in '000kg)	(in '000kg)	(in '000 m ³)
Mar-13	0.0000	0.0000	0.0000	0.0000	0.0000	121.1545	0.0000	0.0000	0.0000	2.0000	0.0130
Apr-13	0.0000	0.0000	0.0000	0.0000	0.0000	197.7428	0.0000	0.0000	0.0000	0.0000	0.0260
May-13	0.0000	0.0000	0.0000	0.0000	0.0000	360.3733	0.0000	0.0000	0.0000	1.2000	0.0130
Jun-13	0.0000	0.0000	0.0000	0.0000	0.0000	415.9366	0.0000	0.0000	0.0000	0.0000	0.0130
Jul-13	0.0000	0.0000	0.0000	0.0000	0.0000	397.7040	0.0000	0.0000	0.5501	4.0000	0.0260
Aug-13	0.0000	0.0000	0.0000	0.0000	0.0000	447.7517	0.0000	0.0040	0.0000	1.6000	0.0325
Sep-13	0.0000	0.0000	0.0000	0.0000	0.0000	565.0243	0.0140	0.1400	0.0000	1.2000	0.0260
Oct-13	0.0000	0.0000	0.0000	0.0000	0.0000	800.3190	0.0000	0.1960	0.0000	0.0000	0.0325
Nov-13	0.0000	0.0000	0.0000	0.0000	0.0000	797.2930	0.0000	0.1960	0.0000	0.0000	0.0195
Dec-13	0.0000	0.0000	0.0000	0.0000	0.0000	1213.8441	0.0103	0.0000	0.0000	2.0000	0.0260
Jan-14	0.0000	0.0000	0.0000	0.0000	0.0000	1158.9828	0.0000	0.1680	0.0000	2.0000	0.0325
Feb-14	0.0000	0.0000	0.0000	0.0000	0.0000	1064.5957	0.0000	0.2520	0.0000	0.0000	0.0520
Total	0.0000	0.0000	0.0000	0.0000	0.0000	7540.7219	0.0243	0.9560	0.5501	14.0000	0.3120

Notes:

- (1) Broken concrete for recycling into aggregates.
- (2) Plastics refer to plastic bottles/ containers, plastic sheets/ foam from packaging materials.
- (3) Use the conversion factor: 1 full load of dumping truck being equivalent to 6.5 m³ by volume.
- (4) Chemical waste refer to spent "battery" and "oil with water".

Appendix J

Cumulative Statistics on Exceedances, Complaints, Notifications of Summons and Successful Prosecutions

Cumulative statistics on Exceedances

		Total no. recorded in this	Total no. recorded since
		reporting period	project commencement
1-Hour TSP	Action	-	-
	Limit	-	-
24-Hour TSP	Action	-	-
	Limit	•	-
Noise	Action	-	-
	Limit	-	-
Water Quality	Action	1	1
	Limit	1	1

Remarks: Exceedances which are not project-related are not presented in this table.

Cumulative statistics on Exceedances, Complaints, Notifications of Summons and Successful Prosecutions

	Date Received	Subject	Status	Total no. received in this	Total no. received since project
				reporting period	commencement
Environmental complaints	04 March13	One (1) complaint was referred by EPD to ET regarding the construction noise impact from cranes operating from the barges for the Hong Kong –Zhuhai-Macao Bridge Hong Kong Project generating squeak noise in the evening of 1 Mar 2013 causing annoyance to him/her. The investigation results show that the complaint was non-project related.	Closed	1	5

Trong Ho	ng Boundary Cross	ing racinties – Rectamation		arcii 2013 – 1 co	radif 2011
	08 April 13	One (1) complaint was referred by EPD regarding oil dumping observed from various vessels operating for HZMB HK projects near Tung Chung Development Pier over the past few months. The investigation results showed that the complaint was non-project related.	Closed	2	6
	10 May 2013	A complaint referred to the Contractor by EPD on 10 May 2013 regarding the scattered debris of silt curtain noted at Sha Lou Wan and Tung Chung Bay. Immediate inspection and clean up action was taken by the Contractor.	Closed	3	7
	23 May 2013	A follow-up complaint referred by EPD was received on 23 May 2013 regarding the oil stain noted near Tung Chung Development Pier for past few months.	Closed	4	8
	26 Sept 13	One (1) complaint was logged by the Contractor regarding the leakage from work barges causing water pollution near Tuen Mun Richland Garden received on 26 Sept 13. With refer to the available information such as photo record of the incident cannot indicate that the leakage from work barges was caused by the vessel of this Contract and the complaint could not be concluded as project related.	Closed	5	9
	1 Nov 13	As informed by the Contractor on 5 Nov 13, a noise complaint received on 14 Sept 13 was referred to the Contractor of HKBCF on 1 Nov 13. The captioned complaint involves	Closed	6	10

Hong Rong	Boundary Crossi	ing racinties – Reciamation	171	arch 2013 – 1 ct	Juary 2014
		noise generated by a tug boat			
		operating near a pier at Tung Chung			
		around 05:55am-06:45am on 14			
		Sept 13. After investigation, the			
		complaint is considered not likely			
		to be related to the construction			
		works.			
		As informed by the Contractor,			
		complaint received from			
		Penta-Ocean – Gitanes Joint			
		Venture (CV/2012/03)			
		mentioned that the formation			
		works of the Contaminated Mud			
		Pit CMP1 to the South of the			
		Brothers (CMP1 of SB) which			
		has been completed in			
		mid-August 2013 and the pit has			
		been commissioned for			
		receiving contaminated marine			
		mud from other projects starting			
		from 16 August 2013. However,			
		it was recently observed that			
	11 Nov 13	some of the project vessels of	Closed	7	11
		HY/2010/02 had berthed within			
		the said pit and those			
		anchorages would likely cause			
		disruption to the underlying			
		contaminated mud and thus			
		induce unfavourable			
		contamination impact to the			
		surrounding marine			
		environment. In this regard, they			
		reminded the contractor to avoid			
		berthing of their vessels within			
		the boundary of CMP1 of SB			
		thereafter for the sake of			
		environmental concern. After			
		investigation, the complaint is			
		<u> </u>	l	<u> </u>	<u>I</u>

considered not likely to be related to the construction works. As informed by the Contractor on 5 Dec 13, one complaint was noted on 12 Nov regarding a barge moving through the southern channel. After investigation, the noise complaint was considered as non-project related. As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen Mun Pierhead Garden which	110115 110	l Doundary C1033	Ing Facilities – Reclamation	141	arch 2013 – 1 co	
As informed by the Contractor on 5 Dec 13, one complaint was noted on 12 Nov regarding a barge moving through the southern channel. After investigation, the noise complaint was considered as non-project related. As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and in quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen			_			
As informed by the Contractor on 5 Dec 13, one complaint was noted on 12 Nov regarding a barge moving through the southern channel. After investigation, the noise complaint was considered as non-project related. As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen						
on 5 Dec 13, one complaint was noted on 12 Nov regarding a barge moving through the southern channel. After investigation, the noise complaint was considered as non-project related. As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen						
noted on 12 Nov regarding a barge moving through the southern channel. After investigation, the noise complaint was considered as non-project related. As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without property covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen						
barge moving through the southern channel. After investigation, the noise complaint was considered as non-project related. As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen						
southern channel. After investigation, the noise complaint was considered as non-project related. As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen			noted on 12 Nov regarding a			
investigation, the noise complaint was considered as non-project related. As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen		5 Dec13		Closed	8	12
complaint was considered as non-project related. As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen			southern channel. After			
non-project related. As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen						
As informed by the Contractor on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen			complaint was considered as			
on 12 Dec 13. A complaint involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen			non-project related.			
involves the leakage of sand from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen			As informed by the Contractor			
from barges causing water discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen			on 12 Dec 13. A complaint			
discoloration at sea near Tuen Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen			involves the leakage of sand			
Mun Pierhead Garden and sand material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen			from barges causing water			
material without properly covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen Closed 9 13 Closed 10 4 Is a support of the inside of the residential area of Tuen			discoloration at sea near Tuen			
covered was blown to the inside of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen			Mun Pierhead Garden and sand			
of the residential area which caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen			material without properly			
caused disturbance to residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly covered was blown to the inside of the residential area of Tuen			covered was blown to the inside			
residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen			of the residential area which			
residence. With refer to available information provided and monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly closed 10 14 covered was blown to the inside of the residential area of Tuen		12 Dec13	caused disturbance to	Closed	g	13
monitoring data recorded on 09 Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly closed 10 14 6 Jan 14 material without properly closed 10 14		12 20010	residence. With refer to available	Olooca		
Dec 13, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand material without properly closed 10 14 covered was blown to the inside of the residential area of Tuen			information provided and			
the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen			monitoring data recorded on 09			
quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen			Dec 13, it cannot indicate that			
the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly Closed 10 14 covered was blown to the inside of the residential area of Tuen			the water quality impact and air			
therefore the complaint could not be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly Closed 10 14 covered was blown to the inside of the residential area of Tuen			quality impact were caused by			
be concluded as related to this Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen			the vessel of this Contract and			
Contract As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly Closed 10 14 covered was blown to the inside of the residential area of Tuen			therefore the complaint could not			
As informed by the Contractor on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly Closed 10 14 covered was blown to the inside of the residential area of Tuen			be concluded as related to this			
on 6 Jan, A complaint involves barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen			Contract			
barges loaded with sand 6 Jan 14 material without properly covered was blown to the inside of the residential area of Tuen			As informed by the Contractor			
6 Jan 14 material without properly Closed 10 14 covered was blown to the inside of the residential area of Tuen			on 6 Jan, A complaint involves			
covered was blown to the inside of the residential area of Tuen			barges loaded with sand			
of the residential area of Tuen		6 Jan 14	material without properly	Closed	10	14
			covered was blown to the inside			
Mun Pierhead Garden which			of the residential area of Tuen			
			Mun Pierhead Garden which			

caused disturbance to residence was received on 27 Dec 13. With refer to available information provided, it cannot indicate that the weter quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract. EPD referred a complaint from complaint who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons 29 April 13 regarding the suspected on 29 April 13 regarding the suspected invication case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.	Hong Ro	ing Doundary Cross	ring racintles – Reclamation	171	arcii 2013 – 1 co	Tuary 2014
refer to available information provided, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract. EPD referred a complaint from complainant who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons 29 April 13 29 April 13 29 April 13 regarding the suspected - 1 1 1 1 1 1 1			caused disturbance to residence			
provided, it cannot indicate that the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract. EPD referred a complaint from complainant who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons was received on 29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			was received on 27 Dec 13. With			
the water quality impact and air quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract. EPD referred a complaint from complainant who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons 29 April 13 regarding the suspected - 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			refer to available information			
quality impact were caused by the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract. EPD referred a complaint from complainant who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons 29 April 13 regarding the suspected - 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			provided, it cannot indicate that			
the vessel of this Contract and therefore the complaint could not be concluded as related to this Contract. EPD referred a complaint from complainant who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons 29 April 13 regarding the suspected - 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			the water quality impact and air			
therefore the complaint could not be concluded as related to this Contract. EPD referred a complaint from complainant who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons 29 April 13 regarding the suspected - 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			quality impact were caused by			
be concluded as related to this Contract. EPD referred a complaint from complainant who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons 29 April 13 regarding the suspected violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			the vessel of this Contract and			
Contract. EPD referred a complaint from complainant who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons 29 April 13 regarding the suspected - 1 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			therefore the complaint could not			
EPD referred a complaint from complainant who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons 29 April 13 regarding the suspected - 1 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			be concluded as related to this			
complainant who advised that blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons 29 April 13 regarding the suspected - 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			Contract.			
blackish mud was found along the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons 29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			EPD referred a complaint from			
the edge of the construction site of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons 29 April 13 regarding the suspected violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			complainant who advised that			
of Hong Kong-Zhuhai-Macao Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 regarding the suspected violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			blackish mud was found along			
Bridge Hong Kong Project near the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 regarding the suspected - 1 1 1 2 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			the edge of the construction site			
the airport in the morning of 18 January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons 29 April 13 regarding the suspected on 29 April 13 regarding the suspected violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			of Hong Kong-Zhuhai-Macao			
January 2014. After receipt of the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons Notification of summons 29 April 13 29 April 13 29 April 13 regarding the suspected - 1 1 1 15 Closed 11 15 As informed by the contract with the investigation results, the complaint is considered as not related to contract HY/2010/02 As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 regarding the suspected - 1 1 1 Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			Bridge Hong Kong Project near			
the complaint, site daily was reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 Notification of summons was received on 29 April 13 As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 As informed by the Contractor on 9 May 13, one summons was received on 29 April 13			the airport in the morning of 18			
21 Jan 14 reviewed and follow-up investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 29 April 13 regarding the Suspected - 1 1 1 15 Closed 11 15 Closed 11 15			January 2014. After receipt of			
21 Jan 14 investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 29 April 13 regarding the suspected - 1 1 0 1 Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			the complaint, site daily was			
investigation has been conducted and excavation and dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			reviewed and follow-up	01 1		
dredging activities were not observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 29 April 13 regarding the Suspected Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.		21 Jan 14	investigation has been	Closed	11	15
observed within the site boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			conducted and excavation and			
boundary of HKBCF during the joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			dredging activities were not			
joint site inspection audit. Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			observed within the site			
Therefore in accordance with the investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			boundary of HKBCF during the			
investigation results, the complaint is considered as not related to contract HY/2010/02 Notification of as informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			joint site inspection audit.			
Complaint is considered as not related to contract HY/2010/02 Notification of Summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			Therefore in accordance with the			
Notification of As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			investigation results, the			
Notification of summons As informed by the Contractor on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			complaint is considered as not			
on 9 May 13, one summons was received on 29 April 13 29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			related to contract HY/2010/02			
received on 29 April 13 regarding the suspected - 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.	Notification of		As informed by the Contractor			
29 April 13 regarding the suspected - 1 1 1 violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.	summons		on 9 May 13, one summons was			
violation case of Noise Control Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.			received on 29 April 13			
Ordinance (Cap.400) at Works Area WA4 on 31 Oct 2012.		29 April 13	regarding the suspected	-	1	1
Area WA4 on 31 Oct 2012.			violation case of Noise Control			
			Ordinance (Cap.400) at Works			
Successful 21 May 2013 As informed by the Contractor in - 1 1			Area WA4 on 31 Oct 2012.			
<u> </u>	Successful	21 May 2013	As informed by the Contractor in	-	1	1

Prosecutions	August 13, the Contractor was		
	subsequently prosecuted on 21		
	May 2013 for breaching Cap.400		
	Noise Control Ordinance.		

Appendix K – Event Action Plan

Event / Action Plan for Air Quality

Event	Action					
	ET Leader	IEC	ER	Contractor		
Action Level						
Exceedance for one sample	Identify source, investigate the causes of exceedance and propose remedial measures; Inform IEC and ER; Repeat measurement to confirm finding; Increase monitoring frequency to daily.	Check monitoring data submitted by ET; Check Contractor's working method.	Notify Contractor.	Rectify any unacceptable practice; Amend working methods if appropriate.		
Exceedance for two or more consecutive samples	 Identify source; Inform IEC and ER; Advise the ER on the effectiveness of the proposed remedial measures; Repeat measurements to confirm findings; Increase monitoring frequency to daily; Discuss with IEC and Contractor on remedial actions required; If exceedance continues, arrange meeting with IEC and ER; If exceedance stops, cease additional monitoring. 	 Check monitoring data submitted by ET; Check Contractor's working method; Discuss with ET and Contractor on possible remedial measures; Advise the ER on the effectiveness of the proposed remedial measures; Supervise Implementation of remedial measures. 	Confirm receipt of notification of failure in writing; Notify Contractor; Ensure remedial measures properly implemented.	1. Submit proposals for remedial to ER within 3 working days of notification; 2. Implement the agreed proposals; 3. Amend proposal if appropriate.		

Event		Action				
	ET Leader	IEC	ER	Contractor		
Limit Level						
Exceedance for one sample	 Identify source, investigate the causes of exceedance and propose remedial measures; Inform ER, Contractor and EPD; Repeat measurement to confirm finding; Increase monitoring frequency to daily; Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and ER informed of the results. 	Contractor on possible	Confirm receipt of notification of failure in writing; Notify Contractor; Ensure remedial measures properly implemented.	 Take immediate action to avoid further exceedance; Submit proposals for remedial actions to IEC within 3 working days of notification; Implement the agreed proposals; Amend proposal if appropriate. 		

Event	Action				
	ET Leader	IEC	ER	Contractor	
Exceedance for two or more consecutive samples	 Notify IEC, ER, Contractor and EPD; Identify source; Repeat measurement to confirm findings; Increase monitoring frequency to daily; Carry out analysis of Contractor's working procedures to determine possible mitigation to be implemented; Arrange meeting with IEC and ER to discuss the remedial actions to be taken; Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and ER informed of the results; If exceedance stops, cease additional monitoring. 	 Discuss amongst ER, ET, and Contractor on the potential remedial actions; Review Contractor's remedial actions whenever necessary to assure their effectiveness and advise the ER accordingly; Supervise the implementation of remedial measures. 	 Confirm receipt of notification of failure in writing; Notify Contractor; In consultation with the IEC, agree with the Contractor on the remedial measures to be implemented; Ensure remedial measures properly implemented; If exceedance continues, consider what portion of the work is responsible and instruct the Contractor to stop that portion of work until the exceedance is abated. 	 Take immediate action to avoid further exceedance; Submit proposals for remedial actions to IEC within 3 working days of notification; Implement the agreed proposals; Resubmit proposals if problem still not under control; Stop the relevant portion of works as determined by the ER until the exceedance is abated. 	

Event / Action Plan for Construction Noise

Event	Action					
	ET Leader	IEC	ER	Contractor		
Action Level	 Notify IEC and Contractor; Identify source, investigate the causes of exceedance and propose remedial measures; Report the results of investigation to the IEC, ER and Contractor; Discuss with the Contractor and formulate remedial measures; Increase monitoring frequency to check mitigation effectiveness. 	 Review the analysed results submitted by the ET; Review the proposed remedial measures by the Contractor and advise the ER accordingly; Supervise the implementation of remedial measures. 	 Confirm receipt of notification of failure in writing; Notify Contractor; Require Contractor to propose remedial measures for the analysed noise problem; Ensure remedial measures are properly implemented. 	Submit noise mitigation proposals to IEC; Implement noise mitigation proposals.		
Limit Level	 Inform IEC, ER, EPD and Contractor; Identify source; Repeat measurements to confirm findings; Increase monitoring frequency; Carry out analysis of Contractor's working procedures to determine possible mitigation to be implemented; Inform IEC, ER and EPD the causes and actions taken for the exceedances; Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and ER informed of the results; If exceedance stops, cease additional monitoring. 	 Discuss amongst ER, ET, and Contractor on the potential remedial actions; Review Contractors remedial actions whenever necessary to assure their effectiveness and advise the ER accordingly; Supervise the implementation of remedial measures. 	notification of failure in writing; 2. Notify Contractor; 3. Require Contractor to propose remedial measures for the analysed noise problem;	 Take immediate action to avoid further exceedance; Submit proposals for remedial actions to IEC within 3 working days of notification; Implement the agreed proposals; Resubmit proposals if problem still not under control; Stop the relevant portion of works as determined by the ER until the exceedance is abated. 		

Event / Action Plan for Water Quality

Event	Action					
	ET Leader	IEC	ER	Contractor		
Action level being exceeded by one sampling day	 Repeat in situ measurement to confirm findings; Identify source(s) of impact; Inform IEC, contractor and ER; Check monitoring data, all plant, equipment and Contractor's working methods; Discuss mitigation measures with IEC, ER and Contractor; Ensure mitigation measures are implemented; Repeat measurement on next day of exceedance to confirm findings. 	 Check monitoring data submitted by ET and Contractor's working methods; Discuss with ET and Contractor on possible remedial actions; Review the proposed mitigation measures submitted by Contractor and advise the ER accordingly; Assess the effectiveness of the implemented mitigation measures. 	Confirm receipt of notification of non-compliance in writing; Discuss with IEC on the proposed mitigation measures; Make agreement on mitigation measures to be implemented; Ensure mitigation measures are properly implemented.	 Inform the ER and confirm notification of the non-compliance in writing; Rectify unacceptable practice; Check all plant and equipment and consider changes of working methods; Discuss with ET and IEC on possible remedial actions and propose mitigation measures to IEC and ER; Implement the agreed mitigation measures. Amend working methods if appropriate. 		

Event	Action				
	ET Leader	IEC	ER	Contractor	
Action level being exceeded by two or more consecutive sampling days	 Repeat in situ measurement to confirm findings; Identify source(s) of impact; Inform IEC, Contractor and ER; Check monitoring data, all plant, equipment and Contractor's working methods; Discuss mitigation measures with IEC, ER and Contractor; Ensure mitigation measures are implemented; Increase the monitoring frequency to daily until no exceedance of Action level; Repeat measurement on next day of exceedance to confirm findings. 	 Check monitoring data submitted by ET and Contractor's working method; Discuss with ET and Contractor on possible remedial actions; Review the proposed mitigation measures submitted by Contractor and advise the ER accordingly; Assess the effectiveness of the implemented mitigation measures. 	 Confirm receipt of notification of non-compliance in writing; Discuss with IEC on the proposed mitigation measures; Make agreement on mitigation measures to be implemented; Ensure mitigation measures are properly implemented; Assess the effectiveness of the implemented mitigation measures. 	 Inform the Engineer and confirm notification of the non-compliance in writing; Rectify unacceptable practice; Check all plant and equipment and consider changes of working methods; Discuss with ET and IEC on possible remedial actions and propose mitigation measures to IEC and ER within 3 working days of notification; Implement the agreed mitigation measures; Amend working methods if appropriate. 	

Event	Action				
	ET Leader	IEC	ER	Contractor	
Limit level being exceeded by one sampling day	 Repeat in-situ measurement to confirm findings; Identify source(s) of impact; Inform IEC, Contractor, ER and EPD; Check monitoring data, all plant, equipment and Contractor's working methods; Discuss mitigation measures with IEC, ER and Contractor; Ensure mitigation measures are implemented; Increase the monitoring frequency to daily until no exceedance of Limit level. 	Check monitoring data submitted by ET and Contractor's working method; Discuss with ET and Contractor on possible remedial actions; Review the proposed mitigation measures submitted by Contractor and advise the ER accordingly; Assess the effectiveness of the implemented mitigation measures.	Confirm receipt of notification of failure in writing; Discuss with IEC, ET and Contractor on the proposed mitigation measures; Request Contractor to critically review the working methods; Ensure mitigation measures are properly implemented; Assess the effectiveness of the implemented mitigation measures.	 Inform the ER and confirm notification of the non-compliance in writing; Rectify unacceptable practice; Check all plant and equipment and consider changes of working methods; Submit proposal of mitigation measures to ER within 3 working days of notification and discuss with ET, IEC and ER; Implement the agreed mitigation measures; Amend working methods if appropriate. 	

Event	Action				
	ET Leader	IEC	ER	Contractor	
or more consecutive sampling days	 Repeat <i>in-situ</i> measurement to confirm findings; Identify source(s) of impact; Inform IEC, contractor, ER and EPD; Check monitoring data, all plant, equipment and Contractor's working methods; Discuss mitigation measures with IEC, ER and Contractor; Ensure mitigation measures are implemented; Increase the monitoring frequency to daily until no exceedance of Limit level for two consecutive days. 	 Check monitoring data submitted by ET and Contractor's working method; Discuss with ET and Contractor on possible remedial actions; Review the Contractor's mitigation measures whenever necessary to assure their effectiveness and advise the ER accordingly. 	 Confirm receipt of notification of failure in writing; Discuss with IEC, ET and Contractor on the proposed mitigation measures; Request Contractor to critically review the working methods; Make agreement on the mitigation measures to be implemented; Ensure mitigation measures are properly implemented; Assess the effectiveness of the implemented mitigation measures; Consider and instruct, if necessary, the Contractor to slow down or to stop all or part of the construction activities until no exceedance of Limit level. 	 Inform the ER and confirm notification of the non-compliance in writing; Take immediate action to avoid further exceedance; Rectify unacceptable practice; Check all plant and equipment and consider changes of working methods; Submit proposal of mitigation measures to ER within 3 working days of notification and discuss with ET, IEC and ER; Implement the agreed mitigation measures; Resubmit proposals of mitigation measures if problem still not under control; As directed by the Engineer, to slow down or to stop all or part of the construction activities until no exceedance of Limit level. 	

Event / Action Plan for Dolphin Monitoring

Event		Action				
	ET Leader	IEC	ER	Contractor		
Dolphin numbers	 Repeat statistical data analysis to confirm findings; Review historical data to ensure 	Discuss monitoring with the ET and the Contractor; Review proposals for	Discuss with the IEC additional monitoring requirements and any other	Inform the ER and confirm notification of the non-compliance in writing;		
and behaviour patterns recorded	differences are as a result of natural variation or previously observed seasonal differences;	additional monitoring and any other measures submitted by the Contractor and advise the		2. Discuss with the ET and the IEC and propose measures to the IEC and the ER;		
in the impact and	3. Identify source(s) of impact;4. Inform the IEC, ER and	ER accordingly.	measures to be implemented.	Implement the agreed measures.		
post-construction monitoring are	Contractor; 5. Check monitoring data; 6. Discuss additional dolphin					
significantly lower	monitoring and any other measures, with the IEC and					
than or different	Contractor.					
from those						
recorded in the						
baseline						
monitoring						