Issue No.

1

Issue Date :

December 2010

Project No. :

912

PROVISION OF CREMATORS AT WO HOP SHEK CREMATORIUM

QUARTERLY ENVIRONMENTAL MONITORING & AUDIT REPORT (FEBRUARY 2010 – APRIL 2010)

Prepared By:


ALLIED ENVIRONMENTAL CONSULTANTS LTD.

COMMERCIAL-IN-CONFIDENCE

Allied Environmental Consultants Limited

Acousticians & Environmental Engineers







30 Visualisation Environment & Energy Information Technology



Architectural Services Department Architectural Branch 41/F, Queensway Government Offices 66 Queensway Hong Kong

Your reference:

Our reference:

HKASD101/50/100601

Date:

3 December 2010

Attn.: Mr Andrew NAM / Ms Salina LEE

BY FAX ONLY (Fax no.: 2524 7981)

Dear Sirs

Quotation Contract No. 9/2009/AB1
Provision of Cremators at Wo Hop Shek Crematorium - Independent Environmental Checker Service
Quarterly EM&A Report (February 2010 – April 2010)

We refer to your e-mail from your Environmental Team attaching a copy of the quarterly EM&A report (February 2010 – April 2010) on 2 December 2010. We have no comment and, hereby, endorse the report.

Should you have any queries, please do not hesitate to contact our Mr James Choi on 2869 6018.

Yours faithfully EDMS CONSULTING LTD

Andy W L Chung

Independent Environmental Checker

AC/lyl

CC

AEC - Ms Grace Kwok (Fax: 2815 5399)

Tel: (852) 2869 6018 Fax: (852) 3007 8556

Issue No. : 1
Issue Date : December 2010
Project No. : 912

PROVISION OF CREMATORS AT WO HOP SHEK CREMATORIUM

QUARTERLY ENVIRONMENTAL MONITORING & AUDIT REPORT (FEBRUARY 2010 - APRIL 2010)

Prepared By:

ALLIED ENVIRONMENTAL CONSULTANTS LTD.

COMMERCIAL-IN-CONFIDENCE

Certified by:

Grace M. H. Kwok Environmental Team Jeader

Issue No.

Ť Ž

Issue Date

December 2010

Project No.

912

PROVISION OF CREMATORS AT WO HOP SHEK CREMATORIUM

QUARTERLY ENVIRONMENTAL MONITORING & AUDIT REPORT (FEBRUARY 2010 – APRIL 2010)

Prepared By:

ALLIED ENVIRONMENTAL CONSULTANTS LTD.

COMMERCIAL-IN-CONFIDENCE

Author:

Nic H. H. Lam BSc (Hons) AMHKIOA

Checked:

Winnie M. W. Ma BEnvMgmt(Hons) MSc AMHKIOA Approved:

Grace Kwok Beng(Hork) MHKIEL MHKIOA MISWA MIAIA MIKAPA LEED AP

This report has been prepared by Allied Environmental Consultants Limited with all reasonable skill, care and diligence within the terms of the Agreement with the client, incorporating our General Terms and Conditions of Business and taking account of the resources devoted to it by agreement with the client.

We disclaim any responsibility to the client and others in respect of any matters outside the scope of the above.

This report is confidential to the client and we accept no responsibility of whatsoever nature to third parties to whom this report, or any part thereof, is made known. Any such party relies upon the report at their own risk.

Table of Contents

Table of Contents	i		
List of Tables	ii		
List of Figures	ii		
List of Appendices	ii		
EXECUTIVE SUMMARY	1		
1. PROJECT BACKGROUND	2		
1.1 Project Organization and Contact Personnel	3		
2. CONSTRUCTION WORKS & PROGRAMME	3		
3. SUMMARY OF EM&A REQUIREMENT	5		
4. AIR QUALITY MONITORING	7		
4.1 Air Quality Monitoring Methodology	7		
4.2 Monitoring Equipment	7		
4.3 Air Quality Monitoring Location	8		
5. RESULTS	8		
5.1. Air Quality	8		
5.2. Weather Conditions	8		
6. SITE INSPECTION & AUDIT	9		
7. LANDSCAPE AND VISUAL IMPACTS	10		
8. NON-COMPLIANCE, COMPLAINTS, NOTIFICATIONS OF SUMMON PROSECUTIONS	S AND SUCCESSFUI 10		
9. WASTE MANAGEMENT	11		
10. RECOMMENDATIONS AND CONCLUSIONS	11		
10.1. Recommendations	11		
10.2. Conclusions			

Issue 1_____ **AEC**

List of Tables

Table 1	Contact Details of Key Personnel
Table 2	Interrelationship between Construction Activities and Mitigation Measures
Table 3	Action and Limit Level for Air Quality Impact Monitoring
Table 4	Event Action Plan
Table 5	Descriptions of Air Quality Monitoring Locations
Table 6	Summary of Weather Conditions during the Monitoring Period
Table 7	Summary of Site Inspections

List of Figures

Figure 1	Site Location Plan
Figure 2	Location of Air Quality Monitoring Station
Figure 3	Photos of Air Quality Monitoring Station

List of Appendices

Calibration Record of High-Volume TSP Sampler
Summary and Graphical Plot of 1-Hour TSP Monitoring Record
Summary and Graphical Plot of 24-Hour TSP Monitoring Record
Wind Record

Issue 1_____AEC

EXECUTIVE SUMMARY

Allied Environmental Consultants Limited (AEC) has been appointed to conduct an environmental monitoring and audit (EM&A) program for the Provision of Cremators at Wo Hop Shek Crematorium (the "Project"). The construction works of the Project commenced on 1st November 2009. This report is the second quarterly EM&A report, which summarizes the environmental monitoring and audit results recorded during the period from 1st February 2010 to 30th April 2010.

Based on the monitoring results, the air quality and construction noise levels during the reporting period complied with the environmental requirements in EM&A Manual. There were no environmental complaints received in this reporting quarter. No notification of summons or prosecution was received.

Construction activities to be undertaken in May 2010 include construction of retaining wall; site backfilling at the stockpile area; delivery of excavated rock material to the recycled aggregates factory; site drainage works; excavation for the underground drainage system; erection of tower crane and excavation for the cremator plant room. Potential environmental impacts include dust generation from drilling, material transfer, vehicular movement, stockpile of excavated materials; noise from erection of tower crane and demolition of RC structure; wastewater generated from spraying water; and generation of various wastes including C&D and chemical wastes. The Contractor should properly implement environmental mitigation measures as per the implementation schedule in the EM&A manual to ensure no adverse environmental impacts to be arisen from the construction works. The Contractor is also reminded to maintain good housekeeping at the site.

Issue 1 ______AEC

1. PROJECT BACKGROUND

The existing Wo Hop Shek Crematorium is a coffin crematorium with two twin cremators. A skeletal cremator building with a single cremator operates nearby for the cremation of skeletal remains from burial. The skeletal cremator and the coffin cremators were commissioned in the 1960's and 1991 respectively.

As the five existing cremators had approached the end of their serviceable life, the Food and Environmental Hygiene Department (FEHD) proposed to demolish the existing coffin crematorium and the skeletal cremator building and to construct in-situ a new crematorium in the same site.

An Environmental Impact Assessment (EIA) was carried out for the Provision of Cremators at Wo Hop Shek Crematorium (hereafter referred to as the "Project") and the EIA Report was approved by Environmental Protection Department (EPD) in June 2008. The Environmental Permit (EP-329/2009) for the Project was issued by EPD in February 2009.

The locations of project site and air sensitive receivers are shown in *Figure 1*. The construction phase is divided in the three phases as outlined below:

Phase I (Year 2009 to Year 2011)

Construction works include the demolition of the existing coffin crematorium building, transformer room and pump room and provision of five new coffin cremators, one dual-purpose cremator, one new skeletal cremator, one cremation plant room with sufficient space for housing nine single cremators and other ancillary facilities such as service halls. The new crematorium will provide seven cremators upon completion of Phase I.

Phase II (Year 2012)

The existing skeletal cremator building will be demolished upon completion of Phase I (i.e. there will be no overlapping between Phases I and II).

Phase III: Future Expansion Phase (for completion by around 2014)

Two additional cremators and one additional service hall will be provided upon completion of Phase II to allow future expansion.

In July 2009, Architectural Services Department (ArchSD) as the works agent has awarded the construction contract of the Project to Wan Chung Construction Co. Ltd. ("the Contractor"). The Contractor has appointed Allied Environmental Consultants Limited (AEC) as the Environmental Team (ET) to undertake Environmental Monitoring and Audit (EM&A) programme in accordance with the EM&A Manual under the approved EIA report, which details the EM&A requirements for the construction and operation of the Project, and the EP-329/2009.

The Construction Programme of the Project is shown in Appendix A. The construction works commenced on 1st November 2009. This report is the second quarterly EM&A report, which details the EM&A results recorded during the period from 1st February 2010 to 30th April 2010.

Issue 1 AEC

1.1 Project Organization and Contact Personnel

Key personnel and contact particulars are summarized in *Table 1*.

Role	Department /	Names	Contact	Fax
	Company		Number	Number
Environmental	Food and Environmental	Ms. Karen Sin	3141 1226	3101 0450
Permit Holder	Hygiene Department			
Architect	Architecture Services	Mr. Andrew Nam	2867 3662	2290 2170
	Department			
Main Contractor	Wan Chung	Mr. Sunny Ngan	9491 9058	2676 7966
	Construction Co.,	Mr. Frank So	9863 6587	
	Limited			
Environmental	Allied Environmental	Mr. Adi Lee	2815 7028	2815 5399
Team Leader	Consultants Limited			
Independent	EDMS Consulting	Mr. Andy Chung	2869 6018	3007 8556
Environmental	Limited			
Checker				

Table 1 Contact Details of Key Personnel

2. CONSTRUCTION WORKS & PROGRAMME

The major works undertaken and/or completed during the reporting period are listed below:

- Construction of retaining wall;
- Site backfilling at the stockpile area;
- Removal of trees debris materials;
- Site drainage works;
- Excavation for the underground drainage system;
- Abatement of heavy metal in ash inside chimney and flue;
- Erection of tower crane; and
- Demolition of RC structure.

Figure 2 shows the works undertaken during the reporting period and *Table 2* shows the interrelationship between construction activities and environmental mitigation measures in the reporting period.

Issue 1 AEC

Provision of Cremators at Wo Hop Shek Crematorium

Environmental Monitoring & Audit Report (February 2010 – April 2010)

Construction Works	Major Environmental Impact	Mitigation Measures
Construction of Retaining wall.	Construction dust, construction noise and Water Quality Impact.	 Watering and imperious sheeting should be provide to dusty materials from drilling, inclusive of materials transfer; Water spraying should be provide to haul road and demolition works; Dust emission from stockpile of excavated materials should be covered by imperious sheeting; and Wastewater generated from spraying water should be well treated and recycled.
Site backfilling at the stockpile area.	Construction dust, construction noise and waste management.	Provide water spraying and imperious sheet to handling of debris material. Well-maintained and quiet plants were used. Trip record should maintain properly.
Delivery of excavated rock material to the recycled aggregates factory.	Construction dust and waste management.	Trip record should maintain properly. Water spraying to load and unloading process.
Site Drainage Works.	Construction dust and construction noise.	Water spraying to loading /unloading process and stockpile. Well-maintained and quiet plants were used.
Erection of tower crane.	Construction noise.	Well-maintained and quiet plants were used.
Demolition of RC structure.	Construction dust, construction noise and waste management.	Provide water spraying and imperious sheet to handling of debris material. Well-maintained and quiet plants were used. Trip record should maintain properly.
Excavation for the RC structure.	Construction dust, construction noise and waste management.	Provide water spraying and imperious sheet to handling of debris material. Well-maintained and quiet plants were used. Trip record should maintain properly.

Table 2 Interrelationship between Construction Activities and Mitigation Measures

Issue 1_____AEC

3. SUMMARY OF EM&A REQUIREMENT

For regular impact monitoring, the sampling frequency of at least once in every six-days, was strictly observed at the monitoring station for 24-hr TSP monitoring. For 1-hr TSP monitoring, the sampling frequency of at least three times in every six-days was undertaken when the highest dust impact occurs.

From baseline monitoring results, the Action and Limit Levels for air quality are summarized in *Table 3*.

Parameters	Monitoring Location	Baseline Level (μg/m³)	Action Level (μg/m³)	Limit Level (μg/m³)
24-Hour TSP Level	A22a	42.0	157.3	260
24-Hour 1SP Level	A22b	41.6	157.0	260
1-Hour TSP Level	A22a	48.8	281.7	500
	A22b	46.8	280.4	500

Table 3 Action and Limit Level for Air Quality Impact Monitoring

Should non-compliance of the above Action and Limit levels occurs, actions in accordance with the Event and Action Plan in *Table 4*.

Event	Action			
Event	ET	IEC	AR	Contractor
Action Level				
Exceedance for one sample	1. Identify source, investigate the causes of complaint and propose remedial measures; 2. Inform IEC and AR; 3. Repeat measurement to confirm finding; 4. Increase monitoring frequency to daily.	Check monitoring data submitted by ET; Check Contractor's working method.	1. Notify Contractor.	Rectify any unacceptable practice; Amend working methods if appropriate.
Exceedance for two or more consecutive samples	· · · · · · · · · · · · · · · · · · ·	 Check monitoring data submitted by ET; Check Contractor's working method; Discuss with ET and Contractor on possible remedial measures; Advise the ET on the effectiveness of the proposed remedial measures; Supervise 	Confirm receipt of notification of exceedance in writing; Notify Contractor; Ensure remedial measures properly implemented.	 Submit proposals for remedial to AR within three working days of notification; Implement the agreed proposals; Amend proposal if appropriate.

Issue 1_____AEC

Provision of Cremators at Wo Hop Shek Crematorium

Environmental Monitoring & Audit Report (February 2010 – April 2010)

Event	Action			
Event	ET	IEC	AR	Contractor
	required; 7. If exceedance continues, arrange meeting with IEC and AR; 8. If exceedance stops, cease additional monitoring.	Implementation of remedial measures.		
Limit Level	I	l	l	
Exceedance for one sample	1. Identify source, investigate the causes of exceedance and propose remedial measures; 2. Inform IEC, AR, Contractor and EPD; 3. Repeat measurement to confirm finding; 4. Increase monitoring frequency to daily; 5. Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and AR informed of the results.	1. Check monitoring data submitted by ET; 2. Check Contractor's working method; 3. Discuss with ET and Contractor on possible remedial measures; 4. Advise the AR on the effectiveness of the proposed remedial measures; 5. Supervise implementation of remedial measures.	Confirm receipt of notification of exceedance in writing; Notify Contractor; Ensure remedial measures properly implemented.	Take immediate action to avoid further exceedance; Submit proposals for remedial actions to IEC within three working days of notification; Implement the agreed proposals; Amend proposal if appropriate.
Exceedance for two or more consecutive samples		1. Discuss amongst AR, ET, and Contractor on the potential remedial actions; 2. Review Contractor's remedial actions whenever necessary to assure their effectiveness and advise the AR accordingly; 3. Supervise the implementation of remedial measures.	1. Confirm receipt of notification of exceedance in writing; 2. Notify Contractor; 3. In consultation with the IEC, agree with the Contractor on the remedial measures to be implemented; 4. Ensure remedial measures properly implemented; 5. If exceedance continues, consider what portion of the work is responsible and instruct the Contractor to stop that portion of work until the exceedance is abated.	1. Take immediate action to avoid further exceedance; 2. Submit proposals for remedial actions to IEC within three working days of notification; 3. Implement the agreed proposals; 4. Resubmit proposals if problem still not under control; 5. Stop the relevant portion of works as determined by the AR until the exceedance is abated

Table 4 Event and Action Plan

Issue 1______AEC

4. AIR QUALITY MONITORING

4.1 Air Quality Monitoring Methodology

TSP levels in 1-hour and 24-hour were measured to indicate the impacts of construction dust on air quality. TSP levels were measured by following the standard high volume sampling (HVS) method as set out in the Title 40 of the Code of Federal Regulations, Chapter 1 (Part 50). 1-hour TSP samples were taken three times a day between 0700-1900 hours. 24-hour TSP samples were taken every six days.

4.2 Monitoring Equipment

High Volume Sampler (HVS) in compliance with the specifications of section 2.2.1 of the EM&A Manual was used for carrying out the 1-hour and 24-hour TSP monitoring at the designated location. The model number of the HVSs is Anderson GMWS-2310 ACCU-VOL.

The HVSs are equipped with an electronic mass flow controller and be calibrated against a traceable standard at regular intervals. The flow rate of each HVS with mass flow controller is calibrated using an orifice calibrator. Initial calibration of dust monitoring equipment is conducted upon installation and prior to commissioning. Five point calibration is carried out every six months. The Calibration Certificates of the High-Volume TSP Sampler are given in *Appendix A*. The weighing of the filter paper was undertaken by SGS Hong Kong Limited.

Wind data monitoring equipment was set up on 30 November 2009 and set up at conspicuous locations for logging wind speed and wind direction near to the dust monitoring locations. Installation and operation of wind data monitoring equipment followed the followings:

- Wind sensors were installed on masts at an elevated level 10m above ground so that they are clear of obstructions of turbulence caused by the buildings;
- The wind data were captured by a data logger and to be downloaded for processing at least once a month;
- The wind data monitoring equipment shall be re-calibrated at least once every six months; and
- Wind direction is divided into 16 sectors of 22.5 degrees each.

Weather data were obtained from the on-site wind stations in the reporting period.

Issue 1 ______AEC

4.3

Air Quality Monitoring Location

1-hour and 24-hour TSP monitoring were conducted to monitor the air quality. Air quality monitoring were conducted at two designated air quality monitoring locations during construction phase: (i) 83 Wo Ka Lau Road (A22a) and (ii) 51D Wo Hop Shek San Tsuen (A22b) as shown in *Figure 2*. Details of the two air quality monitoring stations are shown in *Table 5*.

ID	Monitoring Location	Description of Monitoring Location	
A22a	83 Wo Ka Lau Road	G/F at the front gate of 83 Wo Ka Lau Road	
A22b	51D Wo Hop Shek San	G/F boundary wall of house 51D of Wo Hop Shek San	
AZZU	Tsuen	Tsuen	

Table 5 Descriptions of Air Quality Monitoring Locations

5. RESULTS

5.1. Air Quality

No exceedance was recorded in this quarter. Summary and graphical plots of air quality monitoring record of 1-hour TSP levels and 24-hour TSP levels are given in Appendix B and Appendix C.

5.2. Weather Conditions

Weather data were obtained from the on-site wind stations in the reporting period. Table 6 summarizes the wind data during the monitoring dates. Wind data records from the on-site wind stations are shown in Appendix D.

Date	Weather	Prevailing Wind Direction	Daily Average Wind Speed (m/s)
3 February 2010	Cloudy	SE	0.23
9 February 2010	Cloudy	WNW	0.03
17 February 2010	Cloudy	WNW	0.20
23 February 2010	Cloudy	NW	0.09
1 March 2010	Cloudy	SE	0.03
6 March 2010	Cloudy	NW	0.22
12 March 2010	Cloudy	NE	0.06
18 March 2010	Fine	NE	0.15
24 March 2010	Cloudy	NE	0.22
30 March 2010	Cloudy	SE	1.50
7 April 2010	Cloudy	NE	0.39
13 April 2010	Fine	Е	0.41
19 April 2010	Fine	Е	0.15
24 April 2010	Fine	SE	0.26
30 April 2010	Cloudy	S	0.19

Table 6 Summary of Weather Conditions during the Monitoring Period

AEC Issue 1_

6. SITE INSPECTION & AUDIT

Weekly site inspections were carried out by representatives of the ET. A total of thirteen site inspections were conducted by the ET in this reporting period. Observations by the ET, actions by the Contractor and outcome are summarized in the *Table 7*.

Date	Observations	Action taken by Contractor	Outcome
3 February 2010	No observations during inspection.	Nil	Nil
10 February 2010	No observations during inspection.	Nil	Nil
19 February 2010	Dust observed at the temporary access.	Contractor removed the accumulated dust at the temporary access.	The situation was rectified as observed on 26 February 2010 (Closed).
	No drip tray provided for lubricating oil for drilling machine.	Contractor provided the drip tray for lubricating oil.	The situation was rectified on 20 February 2010 (Closed).
26 February 2010	Non-inert waste was accumulated on site.	Contractor removed non-inert waste.	The situation was rectified as observed on 5 March 2010 (Closed).
5 March 2010	Unpaved hual road was observed dry.	Water spraying had been provided to unpaved hual road.	The situation was rectified as observed on 10 March 2010 (Closed).
10 March 2010	No observations during inspection.	Nil	Nil
17 March 2010	Unpaved hual road was observed dry.	Water spraying had been provided to unpaved hual road.	The situation was rectified as observed on 24 March 2010 (Closed).
	Dry stockpile of loaded materials was observed dry.	Water spraying had been provided to unpaved hual road.	The situation was rectified as observed on 24 March 2010 (Closed).
24 March 2010	Accumulation of debris was observed at the U-channel.	Removal of debris more frequently.	The situation was rectified as observed on 1 April 2010 (Closed).
1 April 2010	Mud and silt was observed outside the entrance of off-site storage area.	Clean up the entrance area and provide sufficient wheel washing.	The situation was rectified as observed on 7 April 2010 (Closed).

Issue 1_____AEC

7 April 2010	Waste storage area was not properly bunded.	Provide properly bunding for waste storage area.	The situation was rectified as observed on 16 April 2010 (Closed).
16 April 2010	No major environmental deficiency was observed.	Nil.	Nil.
22 April 2010	Water in the sump pit was full.	Divert the water to sedimentation tank in order to prevent overflowing.	The situation was rectified as observed on 6 May 2010 (Closed).
	Waste wood and re- useable wood were not separate clearly.	Those woods were properly sorted.	The situation was rectified as observed on 29 April 2010 (Closed).
29 April 2010	Surplus water was observed at the piling area.	Remove the surplus water.	The situation was rectified as observed on 6 May 2010 (Closed).

Table 7 Summary of Site Inspections

During site inspections in the reporting quarter, no non-conformance of implementation of environmental mitigation measures was identified. All environmental mitigation measures for construction stages as stated in approved EIA Report, EM&A Manual and EP-329/2009 were carried out properly in the reporting quarter.

7. LANDSCAPE AND VISUAL IMPACTS

A total of six landscape and visual impact inspections were carried out on 10th, 26th February 2010, 10th, 24th March 2010 and 7th, 22nd April 2010. In February and March 2010, the Aquilaria sinensis and Cibotium barometz were recorded in fair condition at transplanting receptor "T1" site. In April 2010, the transplanted trees *Aquilaria sinensis* showed deterioration in health condition at transplanting receptor site "T1". Daily watering and closely monitoring is recommended. Besides, four individuals of *Juniperus chinensis var.kaizuca* seems infected with virus/fungi. Fungicides are recommended spraying on the affected trees to control or cure their illness.

8. NON-COMPLIANCE, COMPLAINTS, NOTIFICATIONS OF SUMMONS AND SUCCESSFUL PROSECUTIONS

In this reporting quarter, no complaints, inspection notices, and notifications of summons or prosecution were received.

Issue 1 AEC

9. WASTE MANAGEMENT

A total of 2.977 m³ of inert C&D material was disposed to Tuen Mun Area 38 Fill Bank. 142.1 tonnes of metal wastes, 0.057 tonnes of paper / cardboard packaging and 0.2535 m³ of general refuse were disposed of to NENT Landfill. 0.4016 tonnes of chemical waste was transported off site to Chemical Waste Treatment Centre at Tsing Yi in this reporting quarter.

10. RECOMMENDATIONS AND CONCLUSIONS

10.1. Recommendations

In accordance with the environmental site audits undertaken during the reporting quarter, the following recommendations are made:

- Access haul roads and unpaved areas should be kept clear of dusty materials;
- Drip trays should be given for chemicals in site area;
- Excess waste should be removed regularly to prevent from accumulation;
- Muddy water and surface runoff should be cleaned up;
- Regular watering should be given to unpaved haul road and stockpile of dusty materials; and
- Perimeter u-channel should be clean regularly to prevent debris accumulation.


The ET will strictly follow the EM&A programme to ensure compliance of environmental requirements and the proper implementation of all necessary mitigation measures.

10.2. Conclusions

Environmental monitoring was carried out for the Provision of Cremators at Wo Hop Shek Crematorium in the reporting period. 1-hour and 24-hour TSP air quality monitoring were conducted at (i) 83 Wo Ka Lau Road (A22a) and (ii) 51D Wo Hop Shek San Tsuen (A22b) during the period from 1st February 2010 to 30th April 2010.

All monitoring results complied with the relevant action and limit levels. No environmental complaints and notification of summons or prosecution were received during the reporting period.


Issue 1_____AEC



PROVISION OF CREMATORS AT WO HOP SHEK CREMATORIUM AT KIU TAU ROAD
SITE LOCATION PLAN

Figure No.	Rev.:
1	0
Scale	Date
NTS	2/10





PROVISION OF CREMATORS AT WO HOP SHEK CREMATORIUM AT KIU TAU ROAD LOCATION OF AIR QUALITY MONITORING STATION

Figure No.	Rev.:
2	0
Scale	Date
NTS	2/10





Ground floor within the front gate of 83 Wo Ka Lau Road



Ground floor boundary wall of house 51D of Wo Hop Shek San Tsuen

PROVISION OF CREMATORS AT WO HOP SHEK CREMATORIUM AT KIU TAU ROAD

PHOTOS OF AIR QUALITY MONITORING STATION

Figure No.	Rev.:
3	0
Scale	Date
NTS	2/10





High-Volume TSP Sampler 5-Point Calibration Record

Location

Al (Fanling)

Calibrated by

P.F. Yeung

Date

7/1/2010

Sampler

Model

GMWS-2310 ACCU-VOL

Serial Number

S/N 0143

Calibration Orfice and Standard Calibration Relationship :

Serial Number

9833620

Service Date Slope (m)

18 May 2009

Intercept (b)

1.97702

Correlation Coefficient(r):

-0.00070 0.99992

Standard Condition

Pstd (hpa)

1013

Tstd (K)

298.18

Calibration Condition

Pa (hpa)

1016

Ta(K)

293

Zero Erro of Sampler Flow Rate Indication

Resistance Plate		dH [green liquid] (inch water)	Z	X=Qstd (cubic meter/min)	IC	Y
1	18 holes	12.0	3.520	1.781	66	67.1
2	13 holes	9.5	3.132	1.585	58	58.9
3	10 holes	7.6	2.801	1.417	52	52.8
4	7 holes	4.7	2.203	1,115	40	40.6
5	5 holes	2,9	1.731	0.876	30	30.5

Sampler Calibration Relationship

Slope(m):40.152 Intercept(b): -4.395

Correlation Coefficient(r): 0.9998

Checked by: Magnum Fan

Date: 8/01/2010

<u>High-Volume TSP Sampler</u> <u>5-Point Calibration Record</u>

Location : A1 (Fanling)
Calibrated by : P.F.Yeung
Date : 7/3/2010

Sampler

Model : GMWS-2310 ACCU-VOL

Serial Number : S/N 0143

Calibration Orfice and Standard Calibration Relationship

 Serial Number
 :
 9833620

 Service Date
 :
 18 May 2009

 Slope (m)
 :
 1.97702

 Intercept (b)
 :
 -0.00070

 Correlation Coefficient(r)
 :
 0.99992

Standard Condition

Pstd (hpa) : 1013 Tstd (K) : 298.18

Calibration Condition

Pa (hpa) : 1015 Ta(K) : 295

Zero Erro of Sampler Flow Rate Indication

IO : 0.0

Resi	stance Plate	dH [green liquid]	Z	X=Qstd	IC	Y
		(inch water)		(cubic meter/min)		
1	18 holes	12.7	3.548	1.795	60	59.7
2	13 holes	10.0	3.148	1.593	52	51.8
3	10 holes	8.1	2.833	1.434	46	45.8
4	7 holes	5.0	2.226	1.126	34	33.8
5	5 holes	3.1	1.753	0.887	23	22.9

Sampler Calibration Relationship

Slope(m):40.198 Intercept(b): -12.138 Correlation Coefficient(r): 0.9994

Checked by: Magnum Fan Date: 8/03/2010

High-Volume TSP Sampler 5-Point Calibration Record

Location Calibrated by A2, Fanling

P.F.Yeung 7/01/2010

Date

Sampler

Model

GMWS-2310 ACCU-VOL

Serial Number

S/N 1068

Calibration Orfice and Standard Calibration Relationship

Scrial Number

9833620

Service Date

18 May 2009

Slope (m) Intercept (b)

1.97702

-0.00070

Correlation Coefficient(r):

0.99992

Standard Condition

Pstd (hpa)

1013

Tstd (K)

298.18

Calibration Condition

Pa (hpa)

1016

Ta(K)

293

Zero Erro of Sampler Flow Rate Indication

IQ

0.0

Resistance Plate	dH [green liquid] (inch water)	Z	X=Qstd (cubic meter/min)	IC I	Y
1 18 holes	13,2	3.692		(indicated flow)	
2 13 holes	10.2	3.245	1.868	58	58,9
10 holes	8.1	2.892	1.642	50	50.8
7 holes	4 +		1.463	43	43.7
5 holes	7.0	2.226	1,126	30	30.5
	3.0	1.760	0.891	22	22.4

Sampler Calibration Relationship

Slope(m):37,865 Intercept(b):-11.678

Correlation Coefficient(r): 0.9997

Checked by: Magnum Fan

Date: 8/01/2010

<u>High-Volume TSP Sampler</u> <u>5-Point Calibration Record</u>

Location : A2, Fanling
Calibrated by : P.F.Yeung
Date : 7/03/2010

Sampler

Model : GMWS-2310 ACCU-VOL

Serial Number : S/N 1068

Calibration Orfice and Standard Calibration Relationship

 Serial Number
 :
 9833620

 Service Date
 :
 18 May 2009

 Slope (m)
 :
 1.97702

 Intercept (b)
 :
 -0.00070

 Correlation Coefficient(r)
 :
 0.99992

Standard Condition

Pstd (hpa) : 1013 Tstd (K) : 298.18

Calibration Condition

Pa (hpa) : 1015 Ta(K) : 295

Zero Erro of Sampler Flow Rate Indication

IO : 0.0

Resistance Plate		dH [green liquid]	Z	X=Qstd	IC	Y
		(inch water)		(cubic meter/min)	(indicated flow)	
1	18 holes	12.2	3.477	1.758	68	67.9
2	13 holes	9.6	3.085	1.562	60	59.7
3	10 holes	7.8	2.780	1.410	52	51.8
4	7 holes	4.9	2.204	1.122	40	39.8
5	5 holes	2.9	1.695	0.868	28	27.9

Sampler Calibration Relationship

Slope(m):44.784 Intercept(b): -10.794 Correlation Coefficient(r): 0.9996

Checked by: Magnum Fan Date: 8/03/2010



Summary and Graphical Plot of 1-Hour TSP Monitoring Record


Impact Monitoring for reprovisioning of cremators in Wo Hop Shek Crematorium

Air Quality Monitoring: 1-hour TSP

Month: February - April 2010

Date	1-hr TSP of A22a(µg/m ³)	Action Level for A22a (μg/m ³)	1-hr TSP of A22b(μg/m ³)	Action Level for A22b(μg/m ³)	Limit Level(μg/m ³)
03/02/10	133.3	281.7	116.7	280.4	500.0
09/02/10	116.0	281.7	107.0	280.4	500.0
17/02/10	95.0	281.7	97.7	280.4	500.0
23/02/10	113.7	281.7	109.0	280.4	500.0
01/03/10	124.0	281.7	121.3	280.4	500.0
06/03/10	116.0	281.7	110.0	280.4	500.0
12/03/10	110.3	281.7	101.3	280.4	500.0
18/03/10	127.0	281.7	107.0	280.4	500.0
24/03/10	109.3	281.7	100.7	280.4	500.0
30/03/10	97.7	281.7	105.7	280.4	500.0
07/04/10	125.7	281.7	106.3	280.4	500.0
13/04/10	111.7	281.7	105.3	280.4	500.0
19/04/10	112.3	281.7	104.3	280.4	500.0
24/04/10	95.7	281.7	75.3	280.4	500.0
30/04/10	104.7	281.7	99.7	280.4	500.0

1-Hour TSP air quality monitoring data plot recorded at the designated monitoring points





Summary and Graphical Plot of 24-Hour TSP Monitoring Record


Impact Monitoring for reprovisioning of cremators in Wo Hop Shek Crematorium

Air Quality Monitoring: 24-hour TSP

Month: February - April 2010

Date	24-hr TSP of A22a (μg/m3)	Action Level for A22a (µg/m3)	24-hr TSP of A22b (μg/m3)	Action Level for A22b (µg/m3)	Limit Level (μg/m3)
03/02/10	87.0	157.3	67.0	157.0	260.0
09/02/10	55.0	157.3	68.0	157.0	260.0
17/02/10	65.0	157.3	57.0	157.0	260.0
23/02/10	42.0	157.3	73.0	157.0	260.0
01/03/10	65.0	157.3	64.0	157.0	260.0
06/03/10	66.0	157.3	81.0	157.0	260.0
12/03/10	75.0	157.3	75.0	157.0	260.0
18/03/10	78.0	157.3	65.0	157.0	260.0
24/03/10	71.0	157.3	62.0	157.0	260.0
30/03/10	63.0	157.3	57.0	157.0	260.0
07/04/10	77.0	157.3	71.0	157.0	260.0
13/04/10	69.0	157.3	67.0	157.0	260.0
19/04/10	65.0	157.3	54.0	157.0	260.0
24/04/10	88.0	157.3	106.0	157.0	260.0
30/04/10	66.0	157.3	79.0	157.0	260.0


24-Hour TSP air quality monitoring data plot recorded at the designated monitoring points





Appendix D Wind Record


Wind Direction at On-site Wind Station

3/2/2010













Wind Speed at On-site Wind Station

3/2/2010













Wind Direction at On-site Wind Station


1/3/2010


















Wind Speed at On-site Wind Station


1/3/2010


















Wind Direction at On-site Wind Station


7/4/2010













Wind Speed at On-site Wind Station





19/4//2010

