

Maeda Corporation

---

**Castle Peak Road  
Improvement Between  
Sham Tseng and Ka  
Loon Tsuen,  
Tsuen Wan  
West Contract No.  
HY/99/18**

---

Quarterly Environmental  
Monitoring and Audit  
Summary Report  
August 2004 to October  
2004

**Second Issue**

Maeda Corporation

**West Contract No. HY/99/18  
Castle Peak Road Improvement Between  
Sham Tseng and Ka Loon Tsuen, Tsuen Wan**

Environmental Monitoring and Audit

Quarterly Environmental Monitoring and Audit Summary Report

August 2004 to October 2004

November 2004

**Ove Arup & Partners Hong Kong Ltd**

Level 5, Festival Walk, 80 Tat Chee Avenue, Kowloon Tong, Kowloon, Hong Kong

Tel +852 2528 3031 Fax +852 2268 3950

[www.arup.com](http://www.arup.com)

Job number            23437

Job title	West Contract No. HY/99/18		Job number
	Castle Peak Road Improvement Between		23437
	Sham Tseng and Ka Loon Tsuen, Tsuen Wan.		
Document title	Environmental Monitoring and Audit Quarterly LM&A Summary Report August 2004 to October 2004		File reference
Document ref	23437-48		
Revision	Date	Filename	
First Issue	05/11/04	Description	
		Filename	G:\env\project\23437\reports\Quarterly\2004-03\48-Aug04-Oct04.doc
		Description	Issue to IFC for comments
		Prepared by	Checked by
		Frederick Leong	Sam Tsui
		Approved by	
		Sam Tsui	
		Signature	
Second Issue	11/11/04	Filename	G:\env\project\23437\reports\Quarterly\2004-03\48-Aug04-Oct04_Rev A.doc
		Description	Submit to Client with IFC verification letter
		Prepared by	Checked by
		Frederick Leong	Sam Tsui
		Approved by	
		Sam Tsui	
		Signature	
		Filename	
		Description	
		Prepared by	Checked by
		Approved by	
		Signature	
		Filename	
		Description	
		Prepared by	Checked by
		Approved by	
		Signature	

Issue Document Verification with Document ☒

©Osteo Asset Partners LLC and its Affiliates  
All Rights Reserved | October 2020





安誠工程顧問有限公司

总店地址  
 型方大港路183号  
 合和中心4楼

५ नं (४५२) २०११ २२३३

圖書編號: 18521 2635 5520

કચ્છ સંદેશ: <http://www.kutchsanskrit.com>

✉ [www.hydroelectricaling.com](mailto:www.hydroelectricaling.com)

Hyder Consulting Limited

47/F Hopwood Centre  
183 Queen's Road East  
Wan Chai, Hong Kong

TEL (852) 2911 2253

—04. (652) 2505 5028

Email: hydar@hydar.com.tr

Website: [www.hydracooling.com](http://www.hydracooling.com)

Hydr Consulting Limited is incorporated in Hong Kong with limited liability  
 OCH Number 126012

11 November 2004

**BY POST & FAX (2268-3950)**

Ove Anup & Partners Hong Kong Ltd  
Level 5 Festival Walk  
80 Tat Chee Avenue  
Kowloon Tong  
Kowloon

**Your  
Ref:**

Our 910-06/E04-91729  
Ref:

For attention of: Mr. Sam Tsoi

Dear Mr. Tsoi

Contract HY/99/18 West Contract  
Castle Peak Road Improvement between Sham Tseng and Ka Loon Tsuen, Tsuen Wan  
Quarterly EM&A Summary Report (August to October 2004)

We refer to the electronic version of the captioned report submitted by your Mr Angus Choi via e-mail on 9 November 2004 and subsequent revised pages on 11 November 2004. We do not have comment and endorsed the report.

Please do not hesitate to contact the undersigned on 2911-2719 if you wish to discuss any further issues.

Yours sincerely



**Coleman Ng**  
Independent Checker (Environmental)  
**HYDER CONSULTING LIMITED**

cc MHJV Attention: Mr. Jeff Yu (Fax: 2417-0134)  
Maeda Attention: Mr. Derek Elliott (Fax: 2491-9678)

CNWLBY:ms





## CONTENTS

	Page
<b>EXECUTIVE SUMMARY</b>	<b>1</b>
<b>1. INTRODUCTION</b>	<b>5</b>
1.1 Project Background	5
1.2 Designated Project	6
1.3 Impact EM&A Requirements	6
1.4 Purpose of the Report	6
<b>2. ENVIRONMENTAL STATUS</b>	<b>7</b>
2.1 Construction Programme	7
2.2 Construction Activities of the Quarter	7
<b>3. SUMMARY OF EM&amp;A REQUIREMENTS</b>	<b>8</b>
3.1 Air Quality Monitoring	8
3.2 Construction Noise Monitoring	9
3.3 Water Quality (Designated Project)	10
3.4 Landscape and Visual Monitoring and Audit	14
3.5 Performance Limits and Event-Action Plans	14
<b>4. AIR QUALITY</b>	<b>24</b>
4.1 1-hour TSP Monitoring Results	24
4.2 24-hour TSP Monitoring Results	25
<b>5. NOISE</b>	<b>26</b>
5.1 Noise Monitoring Results	26
<b>6. WATER QUALITY (DESIGNATED PROJECT)</b>	<b>27</b>
6.1 Suspension and resumption of Marine Monitoring	27
<b>7. LANDSCAPE AND VISUAL MONITORING AND AUDIT</b>	<b>32</b>
<b>8. QUARTERLY SUMMARY, ENVIRONMENTAL COMPLAINT AND NON-COMPLIANCE RECORDS</b>	<b>33</b>
8.1 Summary of Waste Disposal	33
8.2 Complaint Record	33
8.3 Non-compliance	33
8.4 Notification of Summons and Successful Prosecution	33
8.5 Environmental Licenses	34
<b>9. COMMENTS, RECOMMENDATION AND CONCLUSION</b>	<b>35</b>
9.1 Comments and Recommendations	35
9.2 Conclusion	35
<b>10. REFERENCES</b>	<b>36</b>

## **APPENDICES**

### **APPENDIX A**

Construction programme

### **APPENDIX B**

Log record on environmental complaints



**TABLES**

Table 3-1	TSP monitoring parameters and frequency
Table 3-2	Air quality monitoring locations
Table 3-3	Construction noise monitoring parameters and frequency
Table 3-4	Construction noise monitoring locations
Table 3-5	Water quality monitoring locations
Table 3-6	Action and Limit Level for air quality
Table 3-7	Event/Action plan for air quality
Table 3-8	Action and Limit Levels for construction noise
Table 3-9	Event/Action plan for construction noise
Table 3-10	Action and Limit Levels of water quality
Table 3-11	Event/Action plan for water quality
Table 3-12	Event/Action plan for landscape and visual impact
Table 8-1	Waste disposal quantity in the period from August 2004 to October 2004
Table 8-2	Summary of exceedance of marine water quality monitoring from 2 Aug 04 to 27 Aug 04

**FIGURES**

Figure 1-1	Site location plan
Figure 3-1a	Monitoring locations
Figure 3-1b	Monitoring locations
Figure 3-1c	Monitoring locations
Figure 3-1d	Monitoring locations
Figure 3-1e	Monitoring locations
Figure 4-1	Trend of 1-hour TSP levels from July 2004 to October 2004
Figure 4-2	Trend of 24-hour TSP level from July 2004 to October 2004
Figure 5-1	Trend of noise level from July 2004 to October 2004
Figure 6-1	Turbidity levels during mid-ebb in August 2004
Figure 6-2	Turbidity levels during mid-flood in August 2004
Figure 6-2	Turbidity levels during mid-flood in August 2004
Figure 6-3	SS during mid-ebb in August 2004
Figure 6-4	SS during mid-flood in August 2004
Figure 6-4	SS during mid-flood in August 2004
Figure 6-5	DO at surface and middle level during mid-ebb in August 2004
Figure 6-6	DO at surface and middle level during mid-flood in August 2004
Figure 6-7	DO at bottom level during mid-ebb in August 2004
Figure 6-8	DO at bottom level during mid-flood in August 2004

---

**ABBREVIATIONS AND ACTONYMS**

A/L	Action or Limit Levels
AQO	Air Quality Objectives
Arup	Ove Arup & Partners Hong Kong Limited
ASR	Area Sensitive Rating
B&K	Brüel & Kjær
CFM	Cubic Feet per Minute
CNP	Construction Noise Permit
CT	Contractor
DO	Dissolved Oxygen
DGPS	Differential Global Positioning System
EA	Environmental Auditor
EIA	Environmental Impact Assessment
EM&A	Environmental Monitoring and Audit
EP	Environmental Permit
EPD	Environmental Protection Department
ER	Engineer / Engineer's Representative
ET	Environmental Team
HKPSG	Hong Kong Planning Standards and Guidelines
HKSAR	Hong Kong Special Administrative Region
HOKLAS	The Hong Kong Laboratory accreditation Scheme
HVS	High Volume Sampler
IEC	International Electrotechnical Commission Publications
K	Degrees Kelvin
MC	Maeda Corporation
MHJV	Mouchel Halcrow Joint Venture
NAMAS	National Measurement accreditation Service
NTU	Nephelometric Turbidity Unit
NSR	Noise Sensitive Receiver
SCFM	Standard Cubic Feet per Minute
SS	Suspended Solids
TSP	Total Suspended Particulates
Tby	Turbidity

## EXECUTIVE SUMMARY

This is the eleventh quarterly environmental monitoring and audit (EM&A) summary report summarising the site inspection findings, air quality, noise impact and landscape and visual monitoring and audit works for the period from August 2004 to October 2004.

Monitoring works included air quality monitoring at 9 locations and noise monitoring at 13 locations. Air quality was recorded in terms of 1-hour Total Suspended Particulates (TSP) and 24-hour TSP. Noise was measured in terms of  $L_{eq(30min)}$  with  $L_{10}$  and  $L_{90}$  measurements as references.

### Air Quality

The highest 1-hour TSP level was  $360.1\mu g/m^3$  recorded at G/F of Tsing Lung Tau Temple (WA6) on 30 September 2004 while the lowest 1-hour TSP level was  $100.8\mu g/m^3$  recorded at Podium of Sea Crest Villa Phase 4 Block 12 (WA7) on 18 August 2004. There was no exceedance of Action and Limit Levels in the reporting period.

The highest 24-hour TSP level was  $194.6\mu g/m^3$  recorded at G/F, Carpark, Lido Garden (WA11) on 23 October 2004 while the lowest 24-hour TSP level was  $30.4\mu g/m^3$  recorded at Car Park of Sea Crest Villa Phase 2 Block 6 (WA9) on 18 September 2004. There was no exceedance of Action and Limit Levels in the reporting period.

### Noise

The highest noise level was 74dB(A) recorded at Villa Alfavista (WN11) on 18 August 2004 while the lowest noise level was 63dB(A) recorded at Podium of Sea Crest Villa Phase 3 Block 8 (WN13) on 30 September 2004. There was no exceedance of the A/L Levels during the monitoring period.

### Marine Water Quality

As reported by the Contractor, major marine works at level below +2.5mPD had been completed in July 2003. The proposal on suspension of marine monitoring was submitted to IC(E), HyD, EPD and AFCD for comments on 25 September 2003. It was confirmed with IC(E) and AFCD that suspension of marine monitoring was acceptable if there is no “active” marine work being carried out. In future, if there is any marine work on or below +2.5mPD, the Contractor shall notify the relevant parties one month in advance and resume the marine monitoring. Subsequently, as instructed by the Contractor/ HyD, the marine monitoring was suspended during period from 10 October 2003 to 31 July 2004.

However, as informed by the Contractor, the planned sand placement activities were conducted at Seawall B. Marine impact monitoring near Seawall B were therefore resumed on 2 August 2004. Marine water quality monitoring was undertaken at monitoring locations, 4 for impact (i.e. WW1, WW2, WW3 and WW4) and 3 for control (i.e. WR-E-1234, WR-F-1234 and FCZ1) during the mid-ebb and mid-flood tidal cycles.

- **Summary of Mid-Ebb Tide**

The lowest Dissolved Oxygen DO levels of impact stations at surface & middle and bottom positions were 2.7mg/L at WW4 on 6 August 2004, and 2.70mg/L at WW3 on 13 August 2004 respectively.

The highest depth-averaged Tby result of impact stations was 7.5 Nephelometric Turbidity Unit (NTU) at WW3 on 13 August 2004.

The highest depth-averaged Suspended Solids SS result of impact stations was 56.3mg/L at WW3 on 13 August 2004.

- **Summary of Mid-Flood Tide**

The lowest DO levels of impact stations at surface & middle and bottom positions were 2.60mg/L at WW2 on 20 August 2004, and 2.4mg/L at WW2 on 20 August 2004.

The highest depth-averaged Tby result of impact stations was 8.4NTU at WW4 on 4 August 2004.

The highest depth-averaged SS result of impact stations was 17.3mg/L at WW2 on 25 August 2004.

There were exceedances on A/L Levels of DO and SS of marine water quality monitoring in August 2004. A thorough investigation had been triggered to reveal the causes of exceedances, including the review of Contractor's recent works, identification of other potential pollution sources, complaints, etc.

There was no exceedance of the Action and Limit Levels for Tby of marine water quality monitoring in the reporting period.

Since water quality monitoring had only been conducted in August 2004, there was no quarterly mean of SS level recorded from August 2004 to October 2004.

## **Landscape and Visual**

A total of 7 times of the landscape and visual monitoring and audits had been carried out in the reporting period by a Registered Landscape Architect. Frequently watering and tidying up of the construction site had been suggested after the landscape and visual monitoring and audits. The CT was informed of the recommendations for action.

## **Waste Disposal**

A total of 56 loads of Construction & Demolition (C&D) waste had been disposed of at WENT Landfill in the reporting period. A total of 3,707 loads of C&D fill materials (Public Fill) had been disposed of at Public Filling Area in Tuen Mun by dump trucks in the reporting period. There was no chemical waste disposed of in the reporting period.

## **Complaint Records**

A total of 3 environmental complaint, regarding sandy wake of a marine vessel carrying sand to the beach reinstatement areas of Seawall B, littering problem on the slope close to Sea Crest Villa Phase 2, and excessive garbage trapped along the adjacent shore of Seawall B west end, were received in the reporting period. The complaints had been resolved after investigation.

## **Non-compliance**

There was no non-compliance for air quality and noise monitoring during the reporting period.

There were occasional exceedances on A/L Levels of DO and SS of marine water quality at different impact monitoring stations on different monitoring days in August 2004. The no of exceedances of DO and SS in the periods from 2 August 2004 to 27 August 2004 are summarized in Table 8-2. No exceedance of Turbidity was recorded in August 2004.

Monitoring Stations	Exceedance Level	DO (mg/L)		Turbidity (NTU)		SS (mg/L)		Total	
		Mid-Ebb	Mid-Flood	Mid-Ebb	Mid-Flood	Mid-Ebb	Mid-Flood	Mid-Ebb	Mid-Flood
WW1	Action	0	3	0	0	0	0	0	3
	Limit	22	15	0	0	0	0	22	15
WW2	Action	0	4	0	0	0	0	0	4
	Limit	24	17	0	0	0	0	24	17
WW3	Action	0	0	0	0	1	0	1	0
	Limit	32	26	0	0	1	0	33	26
WW4	Action	0	1	0	0	0	1	0	2
	Limit	20	15	0	0	1	0	20	16
FCZ1	Action	0	1	0	0	0	0	0	1
	Limit	14	16	0	0	0	0	14	16
Total	Action	0	9	0	0	1	1	11	
	Limit	112	89	0	0	2	0	203	

210 exceedances of DO (9 times of Actions Levels and 201 time of Limit Levels) were recorded in the monitoring programme from 2 August 2004 to 27 August 2004 (i.e. 12 monitoring days). It was believed that the majority of exceedances of DO were possibly not justified to the sand placing works, taking into account the very short period and intermittent nature of works (3 consecutive days on 5-7 August 2004 and 13 August 2004). In addition, there was no identifiable source of discharge from the sites, either point or non-point source, which may affect the DO levels within the monitoring areas. In fact, such exceedances would likely be caused by elevated water temperature (recorded as about 27-32°C), which reduced the solubility of DO in water throughout the monitoring period in summer.

5 exceedances of SS (3 times of Action Levels and 1 time of Limit Levels) were recorded in the same monitoring programme. It was concluded that the exceedances of SS on 13 August 2004 was justified to the sand placing works, based on the information from complaint no 149. However, the implementation of proper mitigation measures promptly rectified the problem as illustrated by the resumption to compliance SS levels for the subsequent monitoring. As no sand placing work or other marine works have been carried out, other exceedances of SS on 20 and 25 August 2004 were not considered as caused by construction work.

**Comments**

The environmental performance of the Contractor during the reporting period was acceptable. Upon advised by the ET, remedial measures had been taken to mitigate the environmental impacts caused by the construction activities. EM&A programme had been conducted as planned in the reporting period.


## 1. INTRODUCTION

Ove Arup & Partners Hong Kong Limited (Arup) was appointed by the Contractor - Maeda Corporation (MC) as the Environmental Team (ET) for *Contract No. HY/99/18 Castle Peak Road Improvements between Sham Tseng and Ka Loon Tsuen, Tsuen Wan* (hereafter called the “Project”). Environmental parameters including air quality, construction noise, water quality and landscape & visual issues were selected for impact monitoring for the Project. The contract period of the Project are anticipated as 43 months from December 2001 to June 2005.

### 1.1 Project Background

The Castle Peak Road improvements works consists of upgrading the existing Castle Peak Road to provide a dual two-lane carriageway of “Rural Road A” classification between Area 2, Tsuen Wan and Ka Loon Tsuen, and all associated utility, junction and pedestrian facilities. The Castle Peak Improvement project is divided into three contracts. This Environmental Monitoring and Audit (EM&A) exercise only concerns the West Contract No. HY/99/18 between Sham Tseng and Ka Loon Tsuen, Tsuen Wan. Figure 1-1 shows the site location plan.

Figure 1-1 Site location plan



The scope of the construction work includes:

- Improvement to Castle Peak Road between Area 2 and Ka Loon Tsuen, Tsuen Wan to a dual two-lane carriageway;
- Provision of pedestrian facilities in the form of footpaths, subways, footbridges and Crossings;
- Road junction and signal design and the re-provision of access roads and connections to existing road networks;
- Construction of associated drainage and landscaping works;
- Environmental mitigation measures;
- Design and construction of watermains;
- Construction of entrusted sewerage works; and
- Dredging and reclamation (designated project – see also Section 1.2)

## **1.2 Designated Project**

The marine reclamation and the construction of the associated seawall at Tsing Lung Tau and Sham Tseng West within Contract No. HY/99/18 are classified as designated projects under the Environmental Permits No. EP-093/2001 and EP-094/2001 respectively.

## **1.3 Impact EM&A Requirements**

The impact environmental monitoring and audit included air quality monitoring (both 1-hour and 24-hour TSP), noise, water quality, landscape and visual monitoring, and environmental audit.

## **1.4 Purpose of the Report**

The purpose of the quarterly EM&A summary report is to summarise and provide the information on monitoring methodology, monitoring results, environmental permit status, site audit findings, recommendations and conclusions for the period from August 2004 to October 2004.



## **2. ENVIRONMENTAL STATUS**

### **2.1 Construction Programme**

The construction work was commenced in February 2002. The updated construction programme is given in Appendix A.

### **2.2 Construction Activities of the Quarter**

The major construction activities carried out by the Contractor (CT) in the reporting period included excavation, rock breaking, rock drilling and chemical blasting; bored piling, construction of outfalls; sand placing in seawall B bench reinstatement work and installation of retaining walls.

### 3. SUMMARY OF EM&A REQUIREMENTS

Air quality, construction noise, marine water quality and landscape issues are significant environmental impacts identified for the construction period of the project. In accordance with the Project specific EM&A Manual<sup>[1]</sup>, air quality, noise, water quality, landscape impact monitoring, and audit shall be performed by an ET at all specified monitoring locations during the construction and operational stages.

#### 3.1 Air Quality Monitoring

##### 3.1.1 Monitoring Parameters

Air monitoring was measured in terms of the TSP levels for both 24-hour and 1-hour periods.

##### 3.1.2 Monitoring Frequency

24-hour TSP and 1-hour TSP levels were monitored during the course of construction according to the EM&A Manual. The monitoring parameters and frequencies are specified in Table 3-1.

**Table 3-1 TSP monitoring parameters and frequency**

Parameters	Monitoring Frequency	Time Period	No. of measurement for each monitoring
24-hour TSP	Once every six days	0000 – 2400	1
1-hour TSP	Three times per every six days	0700 – 1900	1

##### 3.1.3 Monitoring Locations

A total of eleven locations were specified for the air quality monitoring and they are given in Table 3-2 and presented in Figures 3-1a to 3-1d.

**Table 3-2 Air quality monitoring locations**

Air Monitoring Station No.	Location	Location description
WA1	Bayside Villas	G/F, Bayside Villas (Temporary Suspended)
WA2	Grand Bay Villas	G/F, Grand Bay Villas (Temporary Suspended)
WA3	Hong Kong Garden	G/F, Hong Kong Garden (Regent Heights)
WA4	Hong Kong Garden	G/F, Hong Kong Garden (Between Blk 1 & 2)
WA5	Hong Kong Garden	G/F, Hong Kong Garden (Block 4)
WA6	Tsing Lung Tau Tin Hau Temple	G/F, Tsing Lung Tau Tin Hau Temple
WA7	Sea Crest Villa	Podium, Sea Crest Villa (Phase 4 Block 12)
WA8	Sea Crest Villa	Podium, Sea Crest Villa (Phase 3 Block 8)
WA9	Sea Crest Villa	Car Park (L3), Sea Crest Villa (Phase 2 Block 6)

Air Monitoring Station No.	Location	Location description
WA10	Sea Crest Villa	Podium, Sea Crest Villa (Phase 1 Block 1)
WA11	Lido Garden	G/F, Carpark, Lido Garden Tower 1

**Note:** Bayside Villas (WA1) and Grand Bay Villas (WA2) are no longer the air sensitive receivers as all residents of Bayside Villas and Grand Bay Villas had been evacuated since September 2002. Therefore, the air quality monitoring at Bayside Villas and Grand Bay Villas were temporary suspended since October 2002 after approval from IC(E) and EPD.

## 3.2 Construction Noise Monitoring

### 3.2.1 Monitoring Parameters

Construction noise monitoring was measured in terms of the A-weighted equivalent continuous sound pressure level ( $L_{eq}$ ).  $L_{10}$  and  $L_{90}$  will also be recorded as supplementary reference information for data auditing.

### 3.2.2 Monitoring Frequency

Construction noise measurements were required to be taken on a weekly basis according to the EM&A Manual. The monitoring time periods, monitoring parameters and frequency are specified in Table 3-3.

**Table 3-3 Construction noise monitoring parameters and frequency**

Time Period (when construction activity is found)	Parameters	Monitoring Frequency	No. of Measurements for Each Monitoring
Between 0700-1900 hours on normal weekdays	Leq(30 min)	Once per week	1
Between 1900-2300 hours on normal weekdays	Leq(5 min)*		3 (consecutive)
Between 2300-0700 hours of next day			
Between 0700-1900 hours on holidays			

**Remarks:** \* The  $L_{eq}(5 \text{ min})$  will only be measured if construction activities are conducted in holidays and between the period of 1900 and 0700 hours during normal weekdays.

### 3.2.3 Monitoring Locations

A total of sixteen noise monitoring locations were specified. They are given in Table 3-4 and presented in Figures 3-1a to 3-1d. The measurements shall be taken at a position 1m from the exterior of building façade and at a position of 1.2m above ground.

**Table 3-4 Construction noise monitoring locations**

Noise Monitoring Station No.	Location	Monitoring Point
WN1	Ka Loon Tsuen	House No.3, Ka Loon Tsuen
WN2	Ka Loon Tsuen	House No.15, Ka Loon Tsuen
<del>WN3</del>	<del>Bayside Villas</del>	<del>Upper G/F, Bayside Villas</del> (Temporary Suspended)
<del>WN4</del>	<del>Bayside Villas</del>	<del>Lower G/F, Bayside Villas</del> (Temporary Suspended)
<del>WN5</del>	<del>Grand Bay Villas</del>	<del>G/F, Grand Bay Villas</del> (Temporary Suspended)

Noise Monitoring Station No.	Location	Monitoring Point
WN6	Hong Kong Garden	G/F, Hong Kong Garden (Regent Heights)
WN7	Hong Kong Garden	G/F, Hong Kong Garden (Between Blk 1 & 2)
WN8	Hong Kong Garden	G/F, Hong Kong Garden (Block 4)
WN9	Tsing Lung Tau Village	House 1, Tsing Lung Tau Village
WN10	Tsing Lung Tau Village	House 60-64, Tsing Lung Tau Village
WN11	Villa Alfavista	G/F, Villa Alfavista
WN12	Sea Crest Villa	Podium, Sea Crest Villa (Phase 4 Block 12)
WN13	Sea Crest Villa	Podium, Sea Crest Villa (Phase 3 Block 8)
WN14	Sea Crest Villa	Car Park (L3), Sea Crest Villa (Phase 2 Block 6)
WN15	Sea Crest Villa	Podium, Sea Crest Villa (Phase 1 Block 1)
WN16	Lido Garden	G/F, Carpark, Lido Garden Tower 1

**Note:** Bayside Villas (WN3 and WN4) and Grand Bay Villas (WN5) are no longer the noise sensitive receivers as all residents of Bayside Villas and Grand Bay Villas had been evacuated since September 2002. Therefore, the noise monitoring at Bayside Villas and Grand Bay Villas were temporary suspended since October 2002 after approval from IC(E) and EPD.

### 3.3 Water Quality (Designated Project)

#### 3.3.1 Monitoring Parameters

Water quality monitoring includes Turbidity (Tby) in the unit of NTU, Dissolved Oxygen (DO) in the unit of mg/L and Suspended Solids (SS) in the unit of mg/L. In addition to the water quality parameters, other relevant data, such as monitoring location/position, time, water depth, water temperature, salinity, DO saturation, weather conditions, sea conditions, tidal stage will be recorded including any special phenomena, work underway at the construction site, etc.

#### 3.3.2 Monitoring Frequency


Water quality monitoring during the impact stage will be conducted thrice per week, during mid-flood and mid-ebb tides and at sixteen designated sampling locations. The interval between two sets of monitoring will not be less than 36 hours except where exceedances above the Action Level or Limit Level were detected (see also section 3.4). In these cases, the monitoring frequency will be increased.


#### 3.3.3 Monitoring Locations



A total of sixteen locations, 9 for impact and 7 for control had been selected for marine water quality monitoring and the locations are given in Table 3-5 and presented in Figure 3-1b to 3-1e.


**Table 3-5 Water quality monitoring locations**

Water Monitoring Station No.		Location	
		Eastings	Northings
Tsing Lung Tau	WW1 (Impact Station)	822306	824405
	WW2 (Impact Station)	822377	824462
	WW3 (Impact Station)	822529	824500
	WW4 (Impact Station)	822775	824560
	WR-E-1234 (Control Station for Mid-Ebb Tide)	822204	824312
	WR-F-1234 (Control Station for Mid-Flood Tide)	822850	824519
Angler's Beach: Sham Tseung West	WW5 (Impact Station)	823700	824905
	WW6/7 (Impact Station)	823797	824964
	WW8 (Impact Station)	823900	825023
	WR-E-5678 (Control Station for Mid-Ebb Tide)	823590	824830
	WR-F-5678 (Control Station for Mid-Flood Tide)	823994	825034
Ma Wan Fish Culture Zone	FCZ1 (Impact Station)	823500	823870

**Figure 3-1a Monitoring locations**

**Figure 3-1b Monitoring locations**

**Figure 3-1c Monitoring locations****Figure 3-1d Monitoring locations**

**Figure 3-1e Monitoring locations**

### 3.4 Landscape and Visual Monitoring and Audit

#### 3.4.1 Audit Parameters

All landscape and visual mitigation measures undertaken by both the CT and the Landscape Contractor during the construction phase and during the first year of the operational phase were audited by a Registered Landscape Architect, to ensure compliance with the intended aims of the mitigation measures.

#### 3.4.2 Audit Frequency

The landscape and visual monitoring and audit was undertaken at least once every two weeks throughout the construction period and once every two months during the operational phase.

#### 3.4.3 Audit Location

The landscape and visual monitoring and audit was conducted throughout the entire site area.

### 3.5 Performance Limits and Event-Action Plans

The monitoring results were checked against appropriate standards and requirements. A two-tier system performance limits had been established in the Project specific EM&A Manual. The “Action Level” and the “Limit Level” (A/L) are established according to the EPD requirements. ET, ER, IC(E), and CT will take corresponding



actions in accordance with the Event-Action Plans if the monitoring results exceed the performance limits.

### 3.5.1 Air Quality

The action and limit levels for air quality have been established during the baseline monitoring and are provided in Table 3-6.

**Table 3-6 Action and Limit Level for air quality**

Air Monitoring Station No.	1-hour TSP Level in $\mu\text{g}/\text{m}^3$		24-hour TSP Level in $\mu\text{g}/\text{m}^3$	
	Action Level	Limit Level	Action Level	Limit Level
WA1	350	500	187	260
WA2	362		192	
WA3	353		190	
WA4	362		187	
WA5	346		185	
WA6	362		204	
WA7	351		187	
WA8	347		188	
WA9	345		182	
WA10	352		183	
WA11	357		195	

Table 3-7 details the actions required to be carried out by different parties in case of an exceedance of performance limits being detected.

**Table 3-7 Event/Action plan for air quality**

Event	Action				Contractor
	ET Leader	IC(E)	ER		
<b>Action Level</b>					
1. Exceedance for one sample	1. Identify the source. 2. Inform the IC(E) and the ER. 3. Repeat measurement to confirm finding. 4. Increase monitoring frequency to daily.	1. Check monitoring data submitted by the ET Leader. 2. Check Contractor's working method.	1. Notify Contractor.	1. Rectify any unacceptable practice. 2. Amend working methods if appropriate.	
2. Exceedance for two or more consecutive samples	1. Identify the source. 2. Inform the IC(E) and the ER. 3. Repeat measurements to confirm findings. 4. Increase monitoring frequency to daily. 5. Discuss with the IC(E) and the Contractor on remedial actions required. 6. If exceedance continues, arrange meeting with the IC(E) and the ER. 7. If exceedance stops, cease additional monitoring.	1. Check monitoring data submitted by the ET Leader. 2. Check the Contractor's working method. 3. Discuss with the ET Leader and the Contractor on possible remedial measures. 4. Advise the ER on the effectiveness of the proposed remedial measures. 5. Supervisor implementation of remedial measures.	1. Confirm receipt of notification of failure in writing. 2. Notify the Contractor. 3. Ensure remedial measures properly implemented.	1. Submit proposals for remedial actions to IC(E) within 3 working days of notification. 2. Implement the agreed proposals. 3. Amend proposal if appropriate.	
<b>Limit Level</b>					
1. Exceedance for one sample	1. Identify the source. 2. Inform the ER and the EPD. 3. Repeat measurement to confirm finding. 4. Increase monitoring frequency to daily. 5. Assess effectiveness of Contractor's remedial actions and keep the IC(E), the EPD and the ER informed of the results.	1. Check monitoring data submitted by the ET Leader. 2. Check the Contractor's working method. 3. Discuss with the ET Leader and the Contractor on possible remedial measures. 4. Advise the ER on the effectiveness of the proposed remedial measures. 5. Supervisor implementation of remedial measures.	1. Confirm receipt of notification of failure in writing. 2. Notify the Contractor. 3. Ensure remedial measures properly implemented.	1. Take immediate action to avoid further exceedance. 2. Submit proposals for remedial actions to IC(E) within 3 working days of notification. 3. Implement the agreed proposals. 4. Amend proposal if appropriate.	
2. Exceedance for two or more consecutive samples	1. Notify the IC(E), the ER, the EPD and the Contractor. 2. Identify the source 3. Repeat measurements to confirm findings. 4. Increase monitoring frequency to daily. 5. Carry out analysis of the Contractor's working procedures to determine possible mitigation to be implemented. 6. Arrange meeting the IC(E) and the ER to discuss the remedial actions to be taken. 7. Assess effectiveness of the Contractor's remedial actions and keep the IC(E), the EPD and the ER informed of the results. 8. If exceedance stops, cease additional monitoring.	1. Discuss amongst the ER, the ET Leader and the Contractor on the potential remedial actions. 2. Review the Contractor's remedial actions whenever necessary and advise the ER accordingly. 3. Supervise the implementation of remedial measures.	1. Confirm receipt of notification of failure in writing. 2. Notify the Contractor. 3. In consultation with the IC(E), agree with the remedial measures to be implemented. 4. Ensure remedial measures are properly implemented. 5. If exceedance continues, consider what activity of the work is responsible and instruct the Contractor to stop that activity of work until the exceedance is abated.	1. Take immediate action to avoid further exceedance. 2. Submit proposals for remedial actions to IC(E) within 3 working days of notification. 3. Implement the agreed proposals. 4. Resubmit proposals if problem still not under control. 5. Stop the relevant activity of works as determined by the ER until the exceedance is abated.	

### 3.5.2 Construction Noise Impact

The action and limit levels for the construction noise have been established in accordance with the Baseline Monitoring Report<sup>[2]</sup> and are tabulated in Table 3-8.

**Table 3-8 Action and Limit Levels for construction noise**

Time Period	Action	Limit
0700 – 1900 hours on any day not being a Sunday or public holiday	When one documented complaint is received	75dB(A) <sup>(1)</sup>
19:00 – 23:00 hours on all days and 07:00 – 23:00 on general holidays (including Sundays)		55 <sup>(2)</sup> / 70 <sup>(3)</sup>
23:00 – 07:00 hours on all days		40 <sup>(2)</sup> / 55 <sup>(3)</sup>

**Remarks:**

- (1) For educational establishments the limit level shall be 70dB(A) and reduced to 65dB(A) during examination periods.
- (2) Refers to the types of Plant regulated under the Technical Memorandum on Noise from Construction Work in Designated Areas (DA-TM).
- (3) Refers to the types of Plant regulated under the Technical Memorandum on Noise Other than Percussive Piling (GW-TM).
- (4) Owing to the high background noise level recorded at WN5, WN9, and WN10, the noise impact monitoring results at these 3 locations will be corrected by its background using the following background correction equation:  $L_{eq(30min)} = 10 \log (10^{m/10} - 10^{b/10})$  as  $m = \text{Measured } L_{eq(30min)}$ ,  $b = \text{Average Baseline } L_{eq(30min)}$ . Only up to the maximum of 3dB(A) is allowed to be deducted after the background correction.

Table 3-9 details the actions required to be carried out by different parties in the case of an exceedance of performance limits being detected.

**Table 3-9 Event/Action plan for construction noise**

Event	Action			
	ET Leader	IC(E)	ER	Contractor
<b>Action Level</b>	<ol style="list-style-type: none"> <li>1. Notify the IC(E) and the Contractor.</li> <li>2. Carry out investigation.</li> <li>3. Report the results of investigation to the IC(E) and the Contractor.</li> <li>4. Discuss with the Contractor and formulate remedial measures.</li> <li>5. Increase monitoring frequency to check mitigation measures.</li> </ol>	<ol style="list-style-type: none"> <li>1. Review with analysed results submitted by the ET.</li> <li>2. Review the proposed remedial measures by the Contractor and advise the ER accordingly.</li> <li>3. Supervise the implement of remedial measures.</li> </ol>	<ol style="list-style-type: none"> <li>1. Confirm receipt of notification of failure in writing.</li> <li>2. Notify the Contractor.</li> <li>3. Require the Contractor to propose remedial measures for the analysed noise problem.</li> <li>4. Ensure remedial measures are properly implemented.</li> </ol>	<ol style="list-style-type: none"> <li>1. Submit noise mitigation proposals to IC(E).</li> <li>2. Implement noise mitigation proposals.</li> </ol>
<b>Limit Level</b>	<ol style="list-style-type: none"> <li>1. Notify the IC(E), the ER, the EPD and the Contractor.</li> <li>2. Identify the source.</li> <li>3. Repeat measurement to confirm findings.</li> <li>4. Increase monitoring frequency.</li> <li>5. Carry out analysis of Contractor's working procedures to determine possible mitigation to be implemented.</li> <li>6. Inform the IC(E), the ER, and the EPD the causes &amp; actions taken for the exceedances.</li> <li>7. Assess effectiveness of the contractor's remedial actions and keep the IC(E), the EPD and the ER informed of the results.</li> <li>8. If exceedance stops, cease additional monitoring</li> </ol>	<ol style="list-style-type: none"> <li>1. Discuss amongst the ER, the ET Leader and the Contractor on the potential remedial actions.</li> <li>2. Review the Contractor's remedial actions whenever necessary to assure their effectiveness and advise the ER accordingly.</li> <li>3. Supervise the implementation of remedial measures.</li> </ol>	<ol style="list-style-type: none"> <li>1. Confirm receipt of notification of failure in writing.</li> <li>2. Notify the Contractor.</li> <li>3. Require the Contractor to propose remedial measures for the analysed noise problem.</li> <li>4. Ensure remedial measures are properly implemented.</li> <li>5. If exceedance continues, consider what activity of the work is responsible and instruct the Contractor to stop that activity of work until the exceedance is abated.</li> </ol>	<ol style="list-style-type: none"> <li>1. Take immediate action to avoid further exceedance.</li> <li>2. Submit proposals for remedial actions to IC(E) within 3 working days of notification.</li> <li>3. Implement the agreed proposals.</li> <li>4. Resubmit proposals if problem still not under control.</li> <li>5. Stop the relevant activity of works as determined by the ER until the exceedance is abated.</li> </ol>

### 3.5.3 Water Quality

The action and limit levels for the water quality have been established in accordance with the EM&A Manual and approved by EPD on 15 October 2002. EPD and IC(E) had agreed on 10 April 2003 to apply the “Direct Comparison” method for evaluation of the marine water quality exceedance. The A/L levels had been revised in April 2003 and are presented in Table 3-10.

**Table 3-10 Action and Limit Levels of water quality**

Parameters		Monitoring Location			
		WW1 to WW8		FCZ1	
		Action Level	Limit Level	Action Level	Limit Level
<b>Mid-Ebb</b>					
DO (mg/L)	Surface & Middle	4.9	4.8	4.7	4.6
	Bottom	4.8	4.8	4.0	4.0
SS (mg/L) (Depth-averaged)		17.0	23.4	For EPD: 12.9 For AFCD: 12.9 and 120% of upstream control station's SS at the same tide of the same day	For EPD: 14.0 For AFCD: 14.0 and 130% of upstream control station's SS at the same tide of the same day
Tby (NTU) (Depth-averaged)		12.0	13.6	For EPD: 9.1 For AFCD: 9.1 and 120% of upstream control station's Tby at the same tide of the same day	For EPD: 10.3 For AFCD: 10.3 and 130% of upstream control station's Tby at the same tide of the same day.
<b>Mid-Flood</b>					
DO (mg/L)	Surface & Middle	4.3	4.2	4.5	4.4
	Bottom	4.3	4.1	4.1	4.1
SS (mg/L) (Depth-averaged)		25.3	28.7	For EPD: 23.3 For AFCD: 23.3 and 120% of upstream control station's SS at the same tide of the same day	For EPD: 25.9 For AFCD: 25.9 and 130% of upstream control station's SS at the same tide of the same day
Tby (NTU) (Depth-averaged)		25.2	31.5	For EPD: 18.7 For AFCD: 18.7 and 120% of upstream control station's Tby at the same tide of the same day	For EPD: 22.3 For AFCD: 22.3 and 130% of upstream control station's Tby at the same tide of the same day.

**Notes:** “Depth-averaged” is calculated by taking the arithmetic means of reading of all three depths.  
For DO, non-compliance of the water quality limits occurs when monitoring result is lower than the limits.

In order to better differentiate between exceedance caused by the contract works and elevated readings arising from causes unrelated to contract works, all parties had agreed to introduce a term “Reaching of Trigger Value” to represent the scenario where the A/L levels were exceeded by the “Direct Comparison” evaluation method. Upon the detection of “Reaching of Trigger Value”, an initial analysis would be

carried out to determine whether it was caused by contract works. Exceedance and non-compliance should only be recorded in case where the “Reaching of Trigger Value” was caused by the contract works.

Table 3-11 details the actions required to be carried out by different parties in the case of water quality exceedance of performance limits being detected. The revised Event/Action Plan for water quality has been endorsed by IC(E) in May 2003, and will be finalised subject to agreement with EPD.

**Table 3-11 Event/Action plan for water quality**

Event	Action			
	ET Leader	IC(E)	ER	Contractor
<b>Trigger Value</b>				
1. Trigger Value being surpassed for one sampling day	<ol style="list-style-type: none"> <li>Repeat in-situ measurement to confirm findings.</li> <li>Conduct investigation to identify the source(s) of impact.</li> <li>Check monitoring data, all plant, equipment, mitigation measures and the Contractor's working methods.</li> <li>Inform the IC(E), ER, EPD, HyD, Contractor and AFCD (if required) the investigation results.</li> <li>If exceedance is confirmed as caused by the construction works, take relevant actions as detailed in "Action Level" and "Limit Level"</li> </ol>	<ol style="list-style-type: none"> <li>If exceedance is confirmed as caused by the construction works, take relevant actions as detailed in "Action Level" and "Limit Level"</li> </ol>	<ol style="list-style-type: none"> <li>If exceedance is confirmed as caused by the construction works, take relevant actions as detailed in "Action Level" and "Limit Level"</li> </ol>	
<b>Action Level</b>				
1. Action level being exceeded by one sampling day and is caused by the construction works	<ol style="list-style-type: none"> <li>Discuss the current mitigation measures with the IC(E) and the Contractor.</li> <li>Pay attention on the monitoring results collected on the subsequent scheduled monitoring date to see if an exceedance, caused by the same or related construction works, is recurring.</li> </ol>	<ol style="list-style-type: none"> <li>Discuss with the ET Leader and the Contractor on the current mitigation measures.</li> <li>Assess the effectiveness of the current mitigation measures and advised the ER accordingly.</li> </ol>	<ol style="list-style-type: none"> <li>Discuss with the IC(E) on the current mitigation measures.</li> </ol>	<ol style="list-style-type: none"> <li>Inform the ER and confirm notification of the exceedance in writing.</li> <li>Rectify unacceptable practice.</li> <li>Check all plants and equipment.</li> <li>Consider changes of working methods.</li> <li>Discuss with the ET Leader and the IC(E) on the current mitigation measures.</li> </ol>
2. Action level being exceeded by more than one consecutive days and is caused by the construction works	<ol style="list-style-type: none"> <li>Discuss mitigation measures with the IC(E) and the Contractor.</li> <li>Ensure the proposed mitigation measures are implemented.</li> <li>Further evaluation of the monitoring results on the next scheduled monitoring day and report to all concerned parties, if the affected monitoring stations are still being affected (or are no longer affected) by the construction works.</li> <li>Prepare to increase the monitoring frequency to daily, if the Limit Level is exceeded as below.</li> </ol>	<ol style="list-style-type: none"> <li>Discuss with the ET Leader and the Contractor on the proposed mitigation measures.</li> <li>Review proposals on mitigation measures submitted by the Contractor and advised the ER accordingly.</li> <li>Assess the effectiveness of the implemented mitigation measures.</li> </ol>	<ol style="list-style-type: none"> <li>Discuss with IC(E), the ET Leader and the Contractor on the proposed mitigation measures.</li> <li>Make agreement on the proposed mitigation measures to be implemented.</li> <li>Assess the effectiveness of the implemented mitigation measures.</li> </ol>	<ol style="list-style-type: none"> <li>Inform the ER and confirm notification of the consecutive exceedance in writing.</li> <li>Rectify unacceptable practice.</li> <li>Check all plants and equipment.</li> <li>Consider changes of working methods.</li> <li>Discuss with the ET Leader and the IC(E) and propose mitigation measures to the IC(E) and the ER within 3 working day.</li> <li>Implement the agreed mitigation measures.</li> </ol>
<b>Limit Level</b>				
1. Limit level being exceeded by one sampling day and is caused by the construction works	<ol style="list-style-type: none"> <li>Discuss mitigation measures with the IC(E), the ER and the Contractor.</li> <li>Ensure the proposed mitigation measures are implemented.</li> <li>Prepare to increase the monitoring frequency to daily if further exceedances of the Limit Level are detected on the next sampling day</li> </ol>	<ol style="list-style-type: none"> <li>Discuss with the ET Leader and the Contractor on the proposed mitigation measures.</li> <li>Review proposals on mitigation measures submitted by the Contractor and advised the ER accordingly.</li> <li>Assess the effectiveness of the implemented mitigation measures.</li> </ol>	<ol style="list-style-type: none"> <li>Discuss with IC(E), the ET Leader and the Contractor on the proposed mitigation measures.</li> <li>Request the Contractor to Critically review the working methods.</li> <li>Make agreement on the proposed mitigation measures to be implemented.</li> <li>Assess the effectiveness of the implemented mitigation measures.</li> </ol>	<ol style="list-style-type: none"> <li>Inform the ER and confirm notification of the exceedance in writing.</li> <li>Rectify unacceptable practice.</li> <li>Check all plants and equipment.</li> <li>Consider changes of working methods.</li> <li>Discuss with the ET Leader, the IC(E) and the ER, and propose mitigation measures to the IC(E) and the ER within 3 working days.</li> <li>Implement the agreed mitigation measures.</li> </ol>

Action				
Event	ET Leader	IC(E)	ER	Contractor
2. Limit level being exceeded by more than one consecutive days and is cause by the construction works	<ol style="list-style-type: none"> <li>1. Discuss further mitigation measures with the IC(E), the ER and the Contractor.</li> <li>2. Ensure the proposed further mitigation measures are implemented.</li> <li>3. Increase the monitoring frequency to daily until no exceedance of the Limit Level.</li> </ol>	<ol style="list-style-type: none"> <li>1. Discuss with the ET Leader and the Contractor on the proposed further mitigation measures.</li> <li>2. Review proposals on further mitigation measures submitted by the Contractor and advise the ER accordingly.</li> <li>3. Assess the effectiveness of the implemented further mitigation measures.</li> </ol>	<ol style="list-style-type: none"> <li>1. Discuss with IC(E), the ET Leader and the Contractor on the proposed further mitigation measures.</li> <li>2. Request the Contractor to Critically review the working methods.</li> <li>3. Make agreement on the further mitigation measures to be implemented.</li> <li>4. Assess the effectiveness of the implemented further mitigation measures.</li> <li>5. Consider and instruct, if necessary, the Contractor to slow down or to stop all or part of the marine work until no exceedance of Limit Level.</li> </ol>	<ol style="list-style-type: none"> <li>1. Inform the ER and confirm notification of the consecutive exceedance in writing.</li> <li>2. Rectify unacceptable practice.</li> <li>3. Check all plants and equipment.</li> <li>4. Consider changes of working methods.</li> <li>5. Discuss with the ET Leader, the IC(E) and the ER, and propose further mitigation measures to the IC(E) and the ER within 3 working days.</li> <li>6. Implement the agreed further mitigation measures.</li> <li>7. As directed by the ER, slow down or stop all or part of the construction activities.</li> </ol>



### 3.5.4 Landscape and Visual

The Final Tree Survey Report<sup>[3]</sup> approved in April 2001 was adopted as the framework of the baseline landscape condition of this road section. In addition, a supplementary tree survey has been carried out in December 2001. The Supplementary Tree Survey Report (Revision A)<sup>[4]</sup> completed in March 2002 is also adopted to provide supplementary information of the baseline landscape condition of this road section.

If any non-conformity on landscape and visual issue is observed, the actions in accordance with Event/Action Plan shown in Table 3-12 shall be carried out.

**Table 3-12 Event/Action plan for landscape and visual impact**

Event	Action			
	ET Leader	IC(E)	ER	Contractor
Non-conformity on one occasion	<ol style="list-style-type: none"> <li>1. Identify Source(s).</li> <li>2. Inform the IC(E) and the ER.</li> <li>3. Discuss mitigation actions with the IC(E), the ER and the Contractor.</li> <li>4. Monitor remedial actions until rectification has been completed.</li> </ol>	<ol style="list-style-type: none"> <li>1. Check report.</li> <li>2. Check the Contractor's working method.</li> <li>3. Discuss with the ET Leader and the Contractor on possible remedial measures.</li> <li>4. Advise the ER on effectiveness of proposed remedial measures.</li> <li>5. Check implementation of remedial measures.</li> </ol>	<ol style="list-style-type: none"> <li>1. Notify Contractor.</li> <li>2. Ensure remedial measures are properly implemented.</li> </ol>	<ol style="list-style-type: none"> <li>1. Amend working method.</li> <li>2. Rectify damage and undertaken any necessary replacement.</li> </ol>
Repeated Non-conformity	<ol style="list-style-type: none"> <li>1. Identify Source(s).</li> <li>2. Inform the IC(E) and the ER.</li> <li>3. Increase monitoring frequency</li> <li>4. Discuss mitigation actions with the IC(E), the ER and the Contractor.</li> <li>5. Monitor remedial actions until rectification has been completed.</li> <li>6. If exceedance stops, cease additional monitoring</li> </ol>	<ol style="list-style-type: none"> <li>1. Check monitoring report</li> <li>2. Check the Contractor's working method</li> <li>3. Discuss with the ET Leader and the Contractor on possible remedial measures.</li> <li>4. Advise the ER on effectiveness of proposed remedial measures.</li> <li>5. Supervise implementation of remedial measures.</li> </ol>	<ol style="list-style-type: none"> <li>1. Notify the Contractor.</li> <li>2. Ensure remedial measures are properly implemented.</li> </ol>	<ol style="list-style-type: none"> <li>1. Amend working method.</li> <li>2. Rectify damage and undertaken any necessary replacement.</li> </ol>

## 4. AIR QUALITY


### 4.1 1-hour TSP Monitoring Results

The highest 1-hour TSP level was  $360.1\mu\text{g}/\text{m}^3$  recorded at G/F of Tsing Lung Tau Temple (WA6) on 30 September 2004 while the lowest 1-hour TSP level was  $100.8\mu\text{g}/\text{m}^3$  recorded at Podium of Sea Crest Villa Phase 4 Block 12 (WA7) on 18 August 2004.

There was no exceedance of Action and Limit Levels in the reporting period.

The trend of 1-hour TSP levels at each monitoring location are plotted and presented in Figure 4-1.

**Figure 4-1 Trend of 1-hour TSP levels from July 2004 to October 2004**




## 4.2 24-hour TSP Monitoring Results

The highest 24-hour TSP level was  $194.6\mu\text{g}/\text{m}^3$  recorded at G/F, Carpark, Lido Garden (WA11) on 23 October 2004 while the lowest 24-hour TSP level was  $30.4\mu\text{g}/\text{m}^3$  recorded at Car Park of Sea Crest Villa Phase 2 Block 6 (WA9) on 18 September 2004.

There was no exceedance of Action and Limit Levels in the reporting period.

The trend of 24-hour TSP levels at each monitoring location are plotted and presented in Figure 4-2.

**Figure 4-2 Trend of 24-hour TSP level from July 2004 to October 2004**



## 5. NOISE


### 5.1 Noise Monitoring Results

All the noise measurements were taken between 0700-1900 hours on normal weekdays during which the construction site was under normal operation.

The highest noise level was 74dB(A) recorded at Villa Alfavista (WN11) on 18 August 2004 while the lowest noise level was 63dB(A) recorded at Podium of Sea Crest Villa Phase 3 Block 8 (WN13) on 30 September 2004.

The trend of the noise levels at each monitoring location are plotted and presented in Figure 5-1.

Figure 5-1 Trend of noise level from July 2004 to October 2004



## 6. WATER QUALITY (DESIGNATED PROJECT)


### 6.1 Suspension and resumption of Marine Monitoring



As reported by the Contractor, major marine works at level below +2.5mPD had been completed in July 2003. The proposal on suspension of marine monitoring was submitted to IC(E), HyD, EPD and AFCD for comments on 25 September 2003. It was confirmed with IC(E) and AFCD that suspension of marine monitoring was acceptable if there is no “active” marine work being carried out. In future, if there is any marine work on or below +2.5mPD, the Contractor shall notify the relevant parties one month in advance and resume the marine monitoring. Subsequently, as instructed by the Contractor/ HyD, the marine monitoring was suspended during period from 10 October 2003 to 31 July 2004.



However, as informed by the Contractor, the planned sand placement activities were conducted at Seawall B. Marine impact monitoring near Seawall B were therefore resumed on 2 August 2004. Marine water quality monitoring was undertaken at monitoring locations, 4 for impact (i.e. WW1, WW2, WW3 and WW4) and 3 for control (i.e. WR-E-1234, WR-F-1234 and FCZ1) during the mid-ebb and mid-flood tidal cycles.

The monitoring results from August 2004 to October 2004 are plotted and presented in Figure 6-1 to Figure 6-8.


**Figure 6-1 Turbidity levels during mid-ebb in August 2004**




**Figure 6-2 Turbidity levels during mid-flood in August 2004****Figure 6-3 SS during mid-ebb in August 2004**

**Figure 6-4 SS during mid-flood in August 2004****Figure 6-5 DO at surface and middle level during mid-ebb in August 2004**

**Figure 6-6 DO at surface and middle level during mid-flood in August 2004**




**Figure 6-7 DO at bottom level during mid-ebb in August 2004**





**Figure 6-8 DO at bottom level during mid-flood in August 2004**



There were exceedances on A/L Levels of DO and SS of marine water quality monitoring in August 2004. A thorough investigation had been triggered to reveal the causes of exceedances, including the review of Contractor's recent works, identification of other potential pollution sources, complaints, etc.

There was no exceedance of the Action and Limit Levels for Tby of marine water quality monitoring in the reporting period.

## **7. LANDSCAPE AND VISUAL MONITORING AND AUDIT**

A total of 7 times of the landscape and visual monitoring and audits had been carried out in the reporting period by a Registered Landscape Architect. Frequently watering and tidy up the construction site have been suggested after the landscape and visual monitoring and audits. The CT was informed of the recommendations for action.

## 8. QUARTERLY SUMMARY, ENVIRONMENTAL COMPLAINT AND NON-COMPLIANCE RECORDS

### 8.1 Summary of Waste Disposal

Table 8-1 summarises the waste disposal quantity in the reporting period.

**Table 8-1 Waste disposal quantity in the period from August 2004 to October 2004**

Type of waste or material	Disposal at	No. of loads or quantities			
		Aug-04	Sep-04	Oct-04	Total
C&D waste	WENT Landfill	23 loads	15 loads	18 loads	<b>56 loads</b>
C&D material	Public Filling Area in Tuen Mun	1,909 loads	692 loads	1,106 loads	<b>3,707 loads</b>
Grease trap waste	Interim Grease Trap Waste Treatment Facility at WENT Landfill	0	0	0	<b>0</b>
Chemical waste	Collected by licenced collector	0	0	0	<b>0</b>

### 8.2 Complaint Record

A total of 3 environmental complaints, regarding sandy wake of a marine vessel carrying sand to the beach reinstatement areas of Seawall B, littering problem on the slope close to Sea Crest Villa Phase 2, and excessive garbage trapped along the adjacent shore of Seawall B west end, were received in the reporting period. The complaints had been resolved after investigation. A log record on the environmental complaints is given in Appendix B.

### 8.3 Non-compliance

There was no non-compliance for air quality monitoring during the reporting period.

### 8.4 Notification of Summons and Successful Prosecution

There was no notification of summons or prosecution received during the reporting period.

There were occasional exceedances on A/L Levels of DO and SS of marine water quality at different impact monitoring stations on different monitoring days in August 2004. The no of exceedances of DO and SS in the periods from 2 August 2004 to 27 August 2004 are summarized in Table 8-2. The daily exceedance records are detailed in Appendix N. No exceedance of Turbidity was recorded in August 2004.

**Table 8-2 Summary of exceedance of marine water quality monitoring from 2 August 2004 to 27 August 2004**

Monitoring Stations	Exceedance Level	DO (mg/L)		Turbidity (NTU)		SS (mg/L)		Total	
		Mid-Ebb	Mid-Flood	Mid-Ebb	Mid-Flood	Mid-Ebb	Mid-Flood	Mid-Ebb	Mid-Flood
WW1	Action	0	3	0	0	0	0	0	3
	Limit	22	15	0	0	0	0	22	15
WW2	Action	0	4	0	0	0	0	0	4
	Limit	24	17	0	0	0	0	24	17
WW3	Action	0	0	0	0	1	0	1	0
	Limit	32	26	0	0	1	0	33	26
WW4	Action	0	1	0	0	0	1	0	2
	Limit	20	15	0	0	1	0	20	16
FCZ1	Action	0	1	0	0	0	0	0	1
	Limit	14	16	0	0	0	0	14	16
<b>Total</b>	<b>Action</b>	<b>0</b>	<b>9</b>	<b>0</b>	<b>0</b>	<b>1</b>	<b>1</b>	<b>11</b>	
	<b>Limit</b>	<b>112</b>	<b>89</b>	<b>0</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>203</b>	

210 exceedances of DO (9 times of Actions Levels and 201 time of Limit Levels) were recorded in the monitoring programme from 2 August 2004 to 27 August 2004 (i.e. 12 monitoring days). It was believed that the majority of exceedances of DO were possibly not justified to the sand placing works, taking into account the very short period and intermittent nature of works (3 consecutive days on 5-7 August 2004 and 13 August 2004). In addition, there was no identifiable source of discharge from the sites, either point or non-point source, which may affect the DO levels within the monitoring areas. In fact, such exceedances would likely be caused by elevated water temperature (recorded as about 27-32°C), which reduced the solubility of DO in water throughout the monitoring period in summer.

5 exceedances of SS (3 times of Action Levels and 1 time of Limit Levels) were recorded in the same monitoring programme. It was concluded that the exceedances of SS on 13 August 2004 was justified to the sand placing works, based on the information from complaint no 149. However, the implementation of proper mitigation measures promptly rectified the problem as illustrated by the resumption to compliance SS levels for the subsequent monitoring. As no sand placing work or other marine works have been carried out, As no sand placing work or other marine works have been carried out, other exceedances of SS on 20 and 25 August 2004 were not considered as caused by construction work. Investigation report of exceedances of water quality monitoring data are attached in Appendix R.

## 8.5 Environmental Licenses

There was no new environmental license granted during the reporting period.

## **9. COMMENTS, RECOMMENDATION AND CONCLUSION**

### **9.1 Comments and Recommendations**

Regarding the water quality issue, there had been occasionally accumulation of silt, construction debris or sands inside the existing and temporary drainage systems and desilting facilities. In addition, stagnant water had always been found within the construction site, but was cleared up immediately by the Contractor. Pest control had been conducted during site audits. Provision of facilities and implementation of wheel washing were in progress. Some entrances had been closed but mud trails were often found outside site entrance.

Regarding the air quality issue, dust had been occasionally spotted from the activities such as rock breaking, excavation and vehicle movement on dry and dusty haul roads and mud trails on public roads. The Contractor had therefore implemented mitigation measures for dust suppression upon requested by the ET. These included spraying water onto rock breaking and excavation activities, watering of dry and dusty haul road; provision of wheel washing facilities, and cleaning the public road when necessary. Exposed slopes and stockpiles was occasionally spotted but were covered after requested.

Construction noise impact was insignificant in the reporting period. It was occasionally spotted that noise label had not been provided for some PMEs but was provided after verbal warning.

Accumulation of general refuse, C&D waste and chemical or oil containers had been occasionally spotted by the ET. Upon advised, the Contractor had disposed of the waste, removed the containers, cleaned up the area and provided drip tray for the chemical or oil containers accordingly. Oil stain was often spotted and the Contractor was advised to remove the contaminated soil. General housekeeping was gradually improving.

No significant landscape and visual impacts had been recorded in the reporting period.

The EM&A programme including landscape and visual monitoring and audit for the period from August 2004 to October 2004 had been conducted as planned to avoid significant environmental and visual impacts to the sensitive receivers.

### **9.2 Conclusion**

The environmental performance of the Contractor during the reporting period was acceptable. Upon advised by the ET, remedial measures had been taken to mitigate the environmental impacts caused by the construction activities. As a whole, EM&A programme had been well conducted in the reporting period.

---

**10. REFERENCES**

- [1] Mouchel Halcrow Joint Venture. 2001. Castle Peak Road Improvement between Area 2 and Ka Loon Tsuen, Tsuen Wan West Contract No. HY/99/18, Environmental Monitoring & Audit Manual.
- [2] Ove Arup & Partners Hong Kong Limited. July 2002. Contract No. HY/99/18 Castle Peak Road Improvement between Shem Tseng and Ka Lung Tsuen, Tsuen Wan, Environmental Baseline Monitoring Report (Second Issue).
- [3] Mouchel Halcrow Joint Venture. 2001. D&C Consultancy Agreement No. CE 1/96 Castle Peak Road Improvement between Area 2 and Ka Loon Tsuen, Tsuen Wan, Tree Survey Report & Tree Felling Application Revision D.
- [4] Mouchel Halcrow Joint Venture. Contract No. HY/99/18 March 2002. D&C Consultancy Agreement No. CE 1/96 Castle Peak Road Improvement between Area 2 and Ka Loon Tsuen, Tsuen Wan, Supplementary Tree Survey Report & Tree Felling Application Revision A.

APPENDIX A

---

**Construction  
programme**

Activity ID

Activity Description

Orig. Dur

Early Start

Early Finish

% Comp

Total Float

01-120152

Proposed CL 4 of 4 B.C. way CH-1800-1820

4

12/12/24

12/30/24

50

11

01-120153

Proposed CL 3 of 4 B.C. way CH-1770-1870

12

24/01/25

24/01/25

50

100

01-120154

Proposed CL 2 of 4 B.C. way CH-1720-1870

7

10/02/24

10/02/24

0

54

01-120155

Proposed CL 1 of 4 B.C. way CH-1670-1870

5

24/02/24

24/02/24

0

107

01-120156

Proposed CL 0 of 4 B.C. way CH-1620-1870

4

17/03/24

21/03/24

0

112

01-120157

Proposed CL 4 of 4 B.C. way CH-1570-1870

4

24/03/24

24/03/24

0

106

01-120158

Proposed CL 3 of 4 B.C. way CH-1520-1870

13

24/03/24

10/04/24

0

91

01-120159

Proposed CL 2 of 4 B.C. way CH-1470-1870

13

10/04/24

10/04/24

0

115

01-120160

Proposed CL 1 of 4 B.C. way CH-1420-1870

6

10/04/24

10/04/24

0

115

01-120161

Proposed CL 0 of 4 B.C. way CH-1370-1870

4

08/05/24

12/05/24

0

182

01-120162

Proposed CL 4 of 4 B.C. way CH-1320-1870

4

08/05/24

12/05/24

0

182

01-120163

Proposed CL 3 of 4 B.C. way CH-1270-1870

4

08/05/24

12/05/24

0

111

01-120164

Proposed CL 2 of 4 B.C. way CH-1220-1870

13

08/05/24

17/06/24

0

182

01-120165

Proposed CL 1 of 4 B.C. way CH-1170-1870

6

17/06/24

17/06/24

0

112

01-120166

Proposed CL 0 of 4 B.C. way CH-1120-1870

4

17/06/24

17/06/24

0

182

01-120167

Proposed CL 4 of 4 B.C. way CH-1070-1870

6

17/06/24

17/06/24

0

182

01-120168

Proposed CL 3 of 4 B.C. way CH-1020-1870

6

17/06/24

17/06/24

0

182

01-120169

Proposed CL 2 of 4 B.C. way CH-0970-1870

6

17/06/24

17/06/24

0

182

01-120170

Proposed CL 1 of 4 B.C. way CH-0920-1870

6

17/06/24

17/06/24

0

182

01-120171

Proposed CL 0 of 4 B.C. way CH-0870-1870

6

17/06/24

17/06/24

0

182

01-120172

Proposed CL 4 of 4 B.C. way CH-0820-1870

6

17/06/24

17/06/24

0

182

01-120173

Proposed CL 3 of 4 B.C. way CH-0770-1870

6

17/06/24

17/06/24

0

182

01-120174

Proposed CL 2 of 4 B.C. way CH-0720-1870

6

17/06/24

17/06/24

0

182

01-120175

Proposed CL 1 of 4 B.C. way CH-0670-1870

6

17/06/24

17/06/24

0

182

01-120176

Proposed CL 0 of 4 B.C. way CH-0620-1870

6

17/06/24

17/06/24

0

182

01-120177

Proposed CL 4 of 4 B.C. way CH-0570-1870

6

17/06/24

17/06/24

0

182

01-120178

Proposed CL 3 of 4 B.C. way CH-0520-1870

6

17/06/24

17/06/24

0

182

01-120179

Proposed CL 2 of 4 B.C. way CH-0470-1870

6

17/06/24

17/06/24

0

182

01-120180

Proposed CL 1 of 4 B.C. way CH-0420-1870

6

17/06/24

17/06/24

0

182

01-120181

Proposed CL 0 of 4 B.C. way CH-0370-1870

6

17/06/24

17/06/24

0

182

01-120182

Proposed CL 4 of 4 B.C. way CH-0320-1870

6

17/06/24

17/06/24

0

182

01-120183

Proposed CL 3 of 4 B.C. way CH-0270-1870

6

17/06/24

17/06/24

0

182

01-120184

Proposed CL 2 of 4 B.C. way CH-0220-1870

6

17/06/24

17/06/24

0

182

01-120185

Proposed CL 1 of 4 B.C. way CH-0170-1870

6

17/06/24

17/06/24

0

182

01-120186

Proposed CL 0 of 4 B.C. way CH-0120-1870

6

17/06/24

17/06/24

0

182

01-120187

Proposed CL 4 of 4 B.C. way CH-0070-1870

6

17/06/24

17/06/24

0

182

01-120188

Proposed CL 3 of 4 B.C. way CH-0020-1870

6

17/06/24

17/06/24

0

182

01-120189

Proposed CL 2 of 4 B.C. way CH-0000-1870

6

17/06/24

17/06/24

0

182

01-120190

Proposed CL 1 of 4 B.C. way CH-0000-1870

6

17/06/24

17/06/24

0

182

02-120191

Proposed CL 4 of 4 B.C. way CH-1800-1820

4

12/12/24

12/30/24

50

11

02-120192

Proposed CL 3 of 4 B.C. way CH-1770-1870

12

24/01/25

24/01/25

50

100

02-120193

Proposed CL 2 of 4 B.C. way CH-1720-1870

7

10/02/24

10/02/24

0

54

02-120194

Proposed CL 1 of 4 B.C. way CH-1670-1870

5

24/02/24

24/02/24

0

107

02-120195

Proposed CL 0 of 4 B.C. way CH-1620-1870

4

17/03/24

21/03/24

0

112

02-120196

Proposed CL 4 of 4 B.C. way CH-1570-1870

4

24/03/24

24/03/24

0

106

02-120197

Proposed CL 3 of 4 B.C. way CH-1520-1870

13

24/03/24

10/04/24

0

91

02-120198

Proposed CL 2 of 4 B.C. way CH-1470-1870

13

10/04/24

10/04/24

0

115

02-120199

Proposed CL 1 of 4 B.C. way CH-1420-1870

6

10/04/24

10/04/24

0

115

02-120200

Proposed CL 0 of 4 B.C. way CH-1370-1870

4

08/05/24

12/05/24

0

182

02-120201

Proposed CL 4 of 4 B.C. way CH-1320-1870

4

08/05/24

12/05/24

0

182

02-120202

Proposed CL 3 of 4 B.C. way CH-1270-1870

4

08/05/24

12/05/24

0

111

02-120203

Proposed CL 2 of 4 B.C. way CH-1220-1870

13

08/05/24

17/06/24

0

182

02-120204

Proposed CL 1 of 4 B.C. way CH-1170-1870

6

17/06/24

17/06/24

0

112

02-120205

Proposed CL 0 of 4 B.C. way CH-1120-1870

4

17/06/24

17/06/24

0

182

02-120206

Proposed CL 4 of 4 B.C. way CH-1070-1870

6

17/06/24

17/06/24

0

182

02-120207

Proposed CL 3 of 4 B.C. way CH-1020-1870

6

17/06/24

17/06/24

0

182

02-120208

Proposed CL 2 of 4 B.C. way CH-0970-1870

6

17/06/24

17/06/24

0

182

02-120209

Proposed CL 1 of 4 B.C. way CH-0920-1870

6

17/06/24

17/06/24

0

182

02-120210

Proposed CL 0 of 4 B.C. way CH-0870-1870

6

17/06/24

17/06/24

0

182

02-120211

Proposed CL 4 of 4 B.C. way CH-0820-1870

6

17/06/24

17/06/24

0

182

02-120212

Proposed CL 3 of 4 B.C. way CH-0770-1870

6

17/06/24

17/06/24

0

182

02-120213

Proposed CL 2 of 4 B.C. way CH-0720-1870

6

17/06/24

17/06/24

0

182

02-120214

Proposed CL 1 of 4 B.C. way CH-0670-1870

6

17/06/24

17/06/24

0

182

02-120215

Proposed CL 0 of 4 B.C. way CH-0620-1870

6

17/06/24

17/06/24

0

182

02-120216

Proposed CL 4 of 4 B.C. way CH-0570-1870

6

17/06/24

17/06/24

0

182

02-120217

Proposed CL 3 of 4 B.C. way CH-0520-1870

6

17/06/24

17/06/24

0

182

02-120218

Proposed CL 2 of 4 B.C. way CH-0470-1870

6

17/06/24

17/06/24

0

182

02-120219

Proposed CL 1 of 4 B.C. way CH-0420-1870

6

17/06/24

17/06/24

0

182

02-120220

Proposed CL 0 of 4 B.C. way CH-0370-1870

6

17/06/24

17/06/24

0

182

02-120221

Proposed CL 4 of 4 B.C. way CH-0320-1870

6

17/06/24

17/06/24

0

182

02-120222

Proposed CL 3 of 4 B.C. way CH-0270-1870

6

17/06/24

17/06/24

0

182

02-120223

Proposed CL 2 of 4 B.C. way CH-0220-1870

6

17/06/24

17/06/24

0

182

02-120224

Proposed CL 1 of 4 B.C. way CH-0170-1870

6

17/06/24

17/06/24

0

182

02-120225

Proposed CL 0 of 4 B.C. way CH-0120-1870

6

17/06/24

17/06/24

0

182

02-120226

Proposed CL 4 of 4 B.C. way CH-0070-1870

6

17/06/24

17/06/24

0

182

02-120227

Proposed CL 3 of 4 B.C. way CH-0020-1870

6

17/06/24

17/06/24

0

182

02-120228

Proposed CL 2 of 4 B.C. way CH-0000-1870

6

17/06/24

17/06/24

0

182

02-120229

Proposed CL 1 of 4 B.C. way CH-0000-1870

6

17/06/24

17/06/24

0

182

03-120230

Proposed CL 4 of 4 B.C. way CH-1800-1820

4

12/12/24

12/30/24

50

11

03-120231

Proposed CL 3 of 4 B.C. way CH-1770-1870

12

24/01/25

24/01/25

50

100

03-120232

Proposed CL 2 of 4 B.C. way CH-1720-1870

7

10/02/24

10/02/24

0

54

03-120233

Proposed CL 1 of 4 B.C. way CH-1670-1870

5

24/02/24

24/02/24

0

107

03-120234

Proposed CL 0 of 4 B.C. way CH-1620-1870

4

17/03/24

21/03/24

0

112

03-120235

Proposed CL 4 of 4 B.C. way CH-1570-1870

4

24/03/24

24/03/24

0

106

03-120236

Proposed CL 3 of 4 B.C. way CH-1520-1870

13

24/03/24

10/04/24

0

91

03-120237

Proposed CL 2 of 4 B.C. way CH-1470-1870

13

10/04/24

10/04/24

0

115

03-120238

Proposed CL 1 of 4 B.C. way CH-1420-1870

6

10/04/24

10/04/24

0

115

03-120239

Proposed CL 0 of 4 B.C. way CH-1370-1870

4

08/05/24

12/05/24

0

182

03-120240

Proposed CL 4 of 4 B.C. way CH-1320-1870

4

08/05/24

12/05/24

0

182

03-120241

Proposed CL 3 of 4 B.C. way CH-1270-1870

4

08/05/24

12/05/24

0

111

03-120242

Proposed CL 2 of 4 B.C. way CH-1220-1870

13

08/05/24

17/06/24

0

182

03-120243

Proposed CL 1 of 4 B.C. way CH-1170-1870

6

17/06/24

17/06/24

0

112

03-120244

Proposed CL 0 of 4 B.C. way CH-1120-1870

4

17/06/24

17/06/24

0

182

03-120245

Proposed CL 4 of 4 B.C. way CH-1070-1870

6

17/06/24

17/06/24

0

182

03-120246

Proposed CL 3 of 4 B.C. way CH-1020-1870

6

17/06/24

17/06/24

0

182

03-120247

Proposed CL 2 of 4 B.C. way CH-0970-1870

6

17/06/24

17/06/24

0

182

03-120248

Proposed CL 1 of 4 B.C. way CH-0920-1870

6

17/06/24

17/06/24

0

182

03-120249

Proposed CL 0 of 4 B.C. way CH-0870-1870

6

17/06/24

17/06/24

0

182

03-120250

Proposed CL 4 of 4 B.C. way CH-0820-1870

6

17/06/24

17/06/24

0

182

03-120251

Proposed CL 3 of 4 B.C. way CH-0770-1870

6

17/06/24

17/06/24

0

182

03-120252

Proposed CL 2 of 4 B.C. way CH-0720-1870

6

17/06/24

17/06/24

0

182

03-120253

Proposed CL 1 of 4 B.C. way CH-0670-1870

6

17/06/24

17/06/24

0

182

03-120254

Proposed CL 0 of 4 B.C. way CH-0620-1870

6

17/06/24

17/06/24

0

182

03-120255

Proposed CL 4 of 4 B.C. way CH-0570-1870

6

17/06/24

17/06/24

0

182

03-120256

Proposed CL 3 of 4 B.C. way CH-0520-1870

6

17/06/24

17/06/24

0

182

03-120257

Proposed CL 2 of 4 B.C. way CH-0470-1870

6

17/06/24

17/06/24

0

182

03-120258

Proposed CL 1 of 4 B.C. way CH-0420-1870

6

17/06/24

17/06/24

0

182

03-120259

Proposed CL 0 of 4 B.C. way CH-0370-1870

6

17/06/24

17/06/24

0

182

03-120260

Proposed CL 4 of 4 B.C. way CH-0320-1870

6

17/06/24

17/06/24

0

182

03-120261

Proposed CL 3 of 4 B.C. way CH-0270-1870

6

17/06/24

17/06/24

0

182

03-120262

Proposed CL 2 of 4 B.C. way CH-0220-1870

6

17/06/24

17/06/24

0

182

03-120263

Proposed CL 1 of 4 B.C. way CH-0170-1870

6

17/06/24

17/06/24

0

182

03-120264

Proposed CL 0 of 4 B.C. way CH-0120-1870

6

17/06/24

17/06/24

0

182

03-120265

Proposed CL 4 of 4 B.C. way CH-0070-1870

6

17/06/24

17/06/24

0

182

03-120266

Proposed CL 3 of 4 B.C. way CH-0020-1870

6

17/06/24

17/06/24

0

182

03-120267

Proposed CL 2 of 4 B.C. way CH-0000-1870

6

17/06/24

17/06/24

0

182

03-120268

Proposed CL 1 of 4 B.C. way CH-0000-1870

6

17/06/24

17/06/24

0

182

04-120269

Proposed CL 4 of 4 B.C. way CH-1800-1820

4

12/12/24

12/30/24

50

11

04-120270

Proposed CL 3 of 4 B.C. way CH-1770-1870

12

24/01/25

24/01/25

50

100

04-120271

Proposed CL 2 of 4 B.C. way CH-1720-1870

7

10/02/24

10/02/24

0

54

04-120272

Proposed CL 1 of 4 B.C. way CH-1670-1870

5

24/02/24

24/02/24

0

107

04-120273

Proposed CL 0 of 4 B.C. way CH-1620-1870

4

17/03/24

21/03/24

0

112

04-120274

Proposed CL 4 of 4 B.C. way CH-1570-1870

4

24/03/24

24/03/24

0

106

04-120275

Proposed CL 3 of 4 B.C. way CH-1520-1870

13

24/03/24

10/04/24

0

91

04-120276

Proposed CL 2 of 4 B.C. way CH-1470-1870

13

10/04/24

10/04/24

0

115

04-120277

Proposed CL 1 of 4 B.C. way CH-1420-1870

6

10/04/24

10/04/24

0

115

04-120278

Proposed CL 0 of 4 B.C. way CH-1370-1870

4

08/05/24

12/05/24

0

182

04-120279

Proposed CL 4 of 4 B.C. way CH-1320-1870

4

08/05/24

12/05/24

0

182

04-120280

Proposed CL 3 of 4 B.C. way CH-1270-1870

4

08/05/24

12/05/24

0

111

04-120281

Proposed CL 2 of 4 B.C. way CH-1220-1870

13

08/05/24

17/06/24

0

182

04-120282

Proposed CL 1 of 4 B.C. way CH-1170-1870

6

17/06/24

17/06/24

0

112

04-120283

Proposed CL 0 of 4 B.C. way CH-1120-1870

4

17/06/24

17/06/24

0

182

04-120284

Proposed CL 4 of 4 B.C. way CH-1070-1870

6

17/06/24

17/06/24

0

182

04-120285

Proposed CL 3 of 4 B.C. way CH-1020-1870

6





Activity	Activity Description	On & Off	Early Start	Barry Finish	% Comp	Total Floor
L-Shape Walls						
05-0101	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0102	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0103	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0104	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0105	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0106	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0107	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0108	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0109	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0110	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0111	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0112	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0113	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0114	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0115	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0116	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0117	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0118	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0119	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0120	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0121	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0122	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0123	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0124	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0125	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0126	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0127	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0128	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0129	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0130	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0131	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0132	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0133	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0134	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0135	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0136	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0137	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0138	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0139	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0140	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0141	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0142	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0143	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0144	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0145	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0146	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0147	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0148	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0149	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0150	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0151	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0152	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0153	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0154	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0155	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0156	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0157	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0158	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0159	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0160	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0161	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0162	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0163	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0164	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0165	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0166	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0167	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0168	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0169	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0170	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0171	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0172	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0173	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0174	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0175	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0176	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0177	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0178	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0179	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0180	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0181	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0182	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0183	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0184	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0185	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0186	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0187	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0188	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0189	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0190	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0191	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0192	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0193	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0194	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0195	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0196	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0197	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0198	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0199	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0200	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0201	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0202	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0203	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0204	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0205	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0206	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0207	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0208	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0209	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0210	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0211	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0212	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0213	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0214	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0215	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0216	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0217	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0218	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0219	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0220	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0221	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0222	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0223	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0224	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0225	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0226	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0227	Formwork RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0228	Cast-in-place concrete RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0229	Concrete 5' and Retaining Wall RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0230	Reinforcing Steel RW-24; 10' 2" High Wall	10/10/00	10/10/00	10/10/00	100	100
05-0231	Formwork RW-24;					



[illegible]

Activity	Activity Description	Q-q Dur	Early Start	Early Finish	% Comp	Total Float	2004 NOV	2005 JAN
<b>5. Footbridges</b>								
<b>Footbridge FB01</b>								
05-5111	Prep Work at Main Support for FB01 (2 NW)		20050104	20050104	0	15		
05-5112	Final Scaffolding & Material for FB01 (50,000)	20	20050104	20050104	0	160		
05-5113	Decorative Paneling & Painting for FB01 (10)		20050104	20050104	0	20		
05-5114	Final Finishes for FB01 (5 NW)	20	20050104	20050104	0	20		
<b>Footbridge FB02</b>								
05-5215	Steel Structure & Bracing for FB02 (North)	30	20050104	20050104	0	120		
05-5216	Final Scaffolding & Material for FB02 (South)	20	20050104	20050104	0	140		
05-5217	Final Scaffolding & Material for FB02 (North)	20	20050104	20050104	0	120		
05-5218	Final Finishes for FB02 (5 NW)	20	20050104	20050104	0	120		
<b>7. Noise Structures</b>								
<b>Noise Mitigation No. 02</b>								
07-7221	Steel Structure & Bracing for NM02	30	20050104	20050104	0	120		
07-7222	Final Scaffolding & Material for NM02 (South)	20	20050104	20050104	0	120		
07-7223	Final Scaffolding & Material for NM02 (North)	20	20050104	20050104	0	120		
07-7224	Final Finishes for NM02 (North)	20	20050104	20050104	0	120		
<b>Noise Mitigation No. 03</b>								
07-7311	Steel Structure & Bracing for NM03 (South)	30	20050104	20050104	0	120		
07-7312	Final Scaffolding & Material for NM03 (South)	20	20050104	20050104	0	120		
07-7313	Final Scaffolding & Material for NM03 (North)	20	20050104	20050104	0	120		
07-7314	Final Finishes for NM03 (North)	20	20050104	20050104	0	120		
<b>Noise Mitigation No. 04</b>								
07-7401	Foundation of Noise Barrier	30	20050104	20050104	0	120		
07-7402	Foundation of Noise Barrier	20	20050104	20050104	0	120		
07-7403	Foundation of Noise Barrier	20	20050104	20050104	0	120		
07-7404	Foundation of Noise Barrier	20	20050104	20050104	0	120		
<b>8. Culverts and Outfalls</b>								
<b>Culvert-Outfall F</b>								
08-8101	Concrete Structure & 1.5m 20% Cor Trade 1	30	20050104	20050104	0	120		
08-8102	Concrete Structure & 1.5m 20% Cor Trade 1	20	20050104	20050104	0	120		
08-8103	Concrete Structure & 1.5m 20% Cor Trade 1	20	20050104	20050104	0	120		
08-8104	Concrete Structure & 1.5m 20% Cor Trade 1	20	20050104	20050104	0	120		
<b>Culvert-Outfall GB</b>								
08-8201	Concrete Structure & 1.5m 20% Cor Trade 1	30	20050104	20050104	0	120		
08-8202	Concrete Structure & 1.5m 20% Cor Trade 1	20	20050104	20050104	0	120		
08-8203	Concrete Structure & 1.5m 20% Cor Trade 1	20	20050104	20050104	0	120		
08-8204	Concrete Structure & 1.5m 20% Cor Trade 1	20	20050104	20050104	0	120		
<b>9. Seawalls and Marina Works</b>								
<b>Sea Wall B (710 m Length)</b>								
09-9101	Concrete Structure & 1.5m 20% Cor Trade 1	30	20050104	20050104	0	120		





Activity ID	Activity Description	Only Dur	Early Start	Early Finish	% Comp	Total Comp	2004											
							JAN FEB MAR APR MAY JUN JUL AUG SEP OCT NOV DEC											
<b>L-Shaped Walls</b>																		
06-0000	Construction of L-shaped wall RW15		10/05/2004	10/05/2004	100	100												
06-0001	Excavation for RW15 base		10/05/2004	10/05/2004	100	100												
06-0002	Backfill for RW15 base		10/05/2004	10/05/2004	100	100												
06-0003	Construction of L-shaped wall RW16		10/05/2004	10/05/2004	100	100												
06-0004	Excavation for RW16 base		10/05/2004	10/05/2004	100	100												
06-0005	Backfill for RW16 base		10/05/2004	10/05/2004	100	100												
06-0006	Construction of L-shaped wall RW17		10/05/2004	10/05/2004	100	100												
06-0007	Excavation for RW17 base		10/05/2004	10/05/2004	100	100												
06-0008	Backfill for RW17 base		10/05/2004	10/05/2004	100	100												
06-0009	Construction of L-shaped wall RW18		10/05/2004	10/05/2004	100	100												
06-0010	Excavation for RW18 base		10/05/2004	10/05/2004	100	100												
06-0011	Backfill for RW18 base		10/05/2004	10/05/2004	100	100												
<b>B. Culverts and Outfalls</b>																		
<b>Culvert Outfall 1A</b>																		
08-0110	Excavation for Culvert Outfall 1A		10/05/2004	10/05/2004	100	100												
08-0111	Construction of Culvert Outfall 1A		10/05/2004	10/05/2004	100	100												
<b>10. Geotechnical &amp; Slope Works</b>																		
<b>Existing Slope Works</b>																		
12-1001	Stabilization of Slope 1A		10/05/2004	10/05/2004	100	100												
12-1002	Stabilization of Slope 1B		10/05/2004	10/05/2004	100	100												
<b>12. Enriched Watermain</b>																		
12-1201	Construction of Enriched Watermain		10/05/2004	10/05/2004	100	100												
<b>13. Reprovisioning of LCSD &amp; FEHD Facilities</b>																		
<b>Stairways</b>																		
13-1301	Construction of Stairway 1A		10/05/2004	10/05/2004	100	100												
13-1302	Construction of Stairway 1B		10/05/2004	10/05/2004	100	100												
13-1303	Construction of Stairway 1C		10/05/2004	10/05/2004	100	100												
13-1304	Construction of Stairway 1D		10/05/2004	10/05/2004	100	100												
13-1305	Construction of Stairway 1E		10/05/2004	10/05/2004	100	100												
<b>18. Variation Works</b>																		
<b>New Slope No. 1</b>																		
18-1801	Construction of New Slope No. 1		10/05/2004	10/05/2004	100	100												
<b>Culvert Outfall 1A</b>																		
18-1802	Construction of Culvert Outfall 1A		10/05/2004	10/05/2004	100	100												
18-1803	Construction of Culvert Outfall 1B		10/05/2004	10/05/2004	100	100												
18-1804	Construction of Culvert Outfall 1C		10/05/2004	10/05/2004	100	100												
<b>New L-Shaped Wall Between RW13 &amp; RW15</b>																		
18-1805	Construction of New L-Shaped Wall		10/05/2004	10/05/2004	100	100												
18-1806	Construction of New L-Shaped Wall		10/05/2004	10/05/2004	100	100												
18-1807	Construction of New L-Shaped Wall		10/05/2004	10/05/2004	100	100												
18-1808	Construction of New L-Shaped Wall		10/05/2004	10/05/2004	100	100												





Activity ID	Activity Description	Only Dur	Early Start	Early Finish	% Comp	Total Float	2004																											
							DEC							NOV							OCT							JAN						
							4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24							
Road Works																																		
05-045001	Direct Road to Port C (400m long)	3		2004/12/14	0	00																												
05-045002	Low sub-grade for 100m long	3	2004/12/14	2004/12/16	0	00																												
05-045003	Low sub-grade for 100m long	3	2004/12/16	2004/12/18	0	00																												
05-045004	Low sub-grade for 100m long	3	2004/12/18	2004/12/20	0	00																												
05-045005	Low sub-grade for 100m long	3	2004/12/20	2004/12/22	0	00																												
5. Footbridges																																		
Footbridge #B03																																		
05-045006	Concrete slab for 100m long	3	2004/12/14	2004/12/16	0	00																												
05-045007	Concrete slab for 100m long	3	2004/12/16	2004/12/18	0	00																												
05-045008	Concrete slab for 100m long	3	2004/12/18	2004/12/20	0	00																												
05-045009	Concrete slab for 100m long	3	2004/12/20	2004/12/22	0	00																												
05-045010	Concrete slab for 100m long	3	2004/12/22	2004/12/24	0	00																												
05-045011	Concrete slab for 100m long	3	2004/12/24	2004/12/26	0	00																												
05-045012	Concrete slab for 100m long	3	2004/12/26	2004/12/28	0	00																												
05-045013	Concrete slab for 100m long	3	2004/12/28	2004/12/30	0	00																												
05-045014	Concrete slab for 100m long	3	2004/12/30	2005/01/01	0	00																												
05-045015	Concrete slab for 100m long	3	2005/01/01	2005/01/03	0	00																												
05-045016	Concrete slab for 100m long	3	2005/01/03	2005/01/05	0	00																												
05-045017	Concrete slab for 100m long	3	2005/01/05	2005/01/07	0	00																												
05-045018	Concrete slab for 100m long	3	2005/01/07	2005/01/09	0	00																												
05-045019	Concrete slab for 100m long	3	2005/01/09	2005/01/11	0	00																												
05-045020	Concrete slab for 100m long	3	2005/01/11	2005/01/13	0	00																												
05-045021	Concrete slab for 100m long	3	2005/01/13	2005/01/15	0	00																												
8. Culverts and Outfalls																																		
Culvert-Outfall #B																																		
05-045022	Concrete slab for 100m long	3	2004/12/14	2004/12/16	0	00																												
05-045023	Concrete slab for 100m long	3	2004/12/16	2004/12/18	0	00																												
05-045024	Concrete slab for 100m long	3	2004/12/18	2004/12/20	0	00																												
Culvert-Outfall #C																																		
05-045025	Concrete slab for 100m long	3	2004/12/14	2004/12/16	0	00																												
05-045026	Concrete slab for 100m long	3	2004/12/16	2004/12/18	0	00																												
05-045027	Concrete slab for 100m long	3	2004/12/18	2004/12/20	0	00																												
05-045028	Concrete slab for 100m long	3	2004/12/20	2004/12/22	0	00																												
05-045029	Concrete slab for 100m long	3	2004/12/22	2004/12/24	0	00																												
05-045030	Concrete slab for 100m long	3	2004/12/24	2004/12/26	0	00																												
05-045031	Concrete slab for 100m long	3	2004/12/26	2004/12/28	0	00																												
05-045032	Concrete slab for 100m long	3	2004/12/28	2004/12/30	0	00																												
9. Seawalls and Marine Works																																		
Seawall C (400m long)																																		
05-045033	Concrete slab for 100m long	3	2004/12/14	2004/12/16	0	00																												
05-045034	Concrete slab for 100m long	3	2004/12/16	2004/12/18	0	00																												
05-045035	Concrete slab for 100m long	3	2004/12/18	2004/12/20	0	00																												
05-045036	Concrete slab for 100m long	3	2004/12/20	2004/12/22	0	00																												
05-045037	Concrete slab for 100m long	3	2004/12/22	2004/12/24	0	00																												
05-045038	Concrete slab for 100m long	3	2004/12/24	2004/12/26	0	00																												
05-045039	Concrete slab for 100m long	3	2004/12/26	2004/12/28	0	00																												
05-045040	Concrete slab for 100m long	3	2004/12/28	2004/12/30	0	00																												
05-045041	Concrete slab for 100m long	3	2004/12/30	2005/01/01	0	00																												
05-045042	Concrete slab for 100m long	3	2005/01/01	2005/01/03	0	00																												
05-045043	Concrete slab for 100m long	3	2005/01/03	2005/01/05	0	00																												
05-045044	Concrete slab for 100m long	3	2005/01/05	2005/01/07	0	00																												
05-045045	Concrete slab for 100m long	3	2005/01/07	2005/01/09	0	00																												
05-045046	Concrete slab for 100m long	3	2005/01/09	2005/01/11	0	00																												
05-045047	Concrete slab for 100m long	3	2005/01/11	2005/01/13	0	00																												
05-045048	Concrete slab for 100m long	3	2005/01/13	2005/01/15	0	00																												
05-045049	Concrete slab for 100m long	3	2005/01/15	2005/01/17	0	00																												
05-045050	Concrete slab for 100m long	3	2005/01/17	2005/01/19	0	00																												
05-045051	Concrete slab for 100m long	3	2005/01/19	2005/01/21	0	00																												
05-045052	Concrete slab for 100m long	3	2005/01/21	2005/01/23	0	00																												
05-045053	Concrete slab for 100m long	3	2005/01/23	2005/01/25	0	00																												
05-045054	Concrete slab for 100m long	3	2005/01/25	2005/01/27	0	00																												
05-045055	Concrete slab for 100m long	3	2005/01/27	2005/01/29	0	00																												
05-045056	Concrete slab for 100m long	3	2005/01/29	2005/01/31	0	00																												





## APPENDIX B

---

### **Log record on environmental complaints**

## Log Record on Environmental Complaints

No.	Date of Complaint Received	Description	Proposed Actions	Completion Date	Remarks
029	12-Aug-02	Complaint from Mr. Au regarding muddy water washing out from Kowloon Bound Lane from the construction site	Enlarge concrete paving at site entrance; further improvement to the existing temporary drainage system to minimise wash-off of waste water to the adjacent road; and make sure temporary water supply points are properly turned off during lunch break or other times when they are not in use.	16-Aug-02	
036	31-Aug-02	Complaint from Mrs. Chung regarding the generation of fugitive dust from the construction site in front of Tsing Lung Tau Village	Frequent watering of the related works area with the aid of water browser	31-Aug-02	
054	07-Dec-02	Complaint from Mr. Lo regarding the stagnant water ponding in front of the construction site at Sham Tseng	Explained to the complainant that the water ponding was a wheel washing bay	07-Dec-02	
067	03-Mar-03	Complaint from Hong Kong Garden Management Office regarding the noise from vehicular movement over the temporary road cover at Castle Peak Road provided by the Contractor	The Contractor has added extra welding to improve the rigidity of the temporary steel deck. The work was completed during the off-peak hours in the period between 12-Mar-03 to 17-Mar-03.	17-Mar-03	The Contractor has taken noise readings and found that the noise level was within the baseline levels.
068	11-Mar-03	Complaint from Mr. Leung at Hong Kong Garden regarding the noise from evening road traffic, travelling over the steel decking plate on the adjacent temporary road diversion.	The Contractor has added extra welding to improve the rigidity of the temporary steel deck. The work was completed during the off-peak hours in the period between 12-Mar-03 to 17-Mar-03.	17-Mar-03	The Contractor has taken noise readings and found that the noise level was within the baseline levels.
070	06-Mar-03	Complaint from EPD regarding the reclamation works at Seawall B opposite to Hong Kong Garden on Sunday	The Contractor has previously informed the subcontractor of the statutory requirements as noise, dust emission, water discharge, and waste management. The Contractor agreed to keep vigilant in monitoring and surveillance of the site and continue to remind the subcontractors of the statutory requirements.	10-Mar-03	The Contractor has formally closed all site area for the Chinese New Year. Entrances of all site area were barricaded before the Contractor's staff vacated the sites on 30 January 2003.
070	06-Mar-03	Complaint from EPD regarding dust emission from the reclamation works at Seawall B opposite to Hong Kong Garden.	The Contractor has previously informed the subcontractor of the statutory requirements as noise, dust emission, water discharge, and waste management. The Contractor agreed to keep vigilant in monitoring and surveillance of the site and continue to remind the subcontractors of the statutory requirements.	10-Mar-03	The Contractor has investigated and confirmed that the marine works towards the eastern end of Seawall B was wet and the concreting works at the west end of the Seawall B were not dusty and no dust was emitted. Ground surface was also covered with crushed rock. The Contractor was also further reminded to spray water before and during unloading and moving of rock boulders and onto the haul road.
070	24-Mar-03	Complaint from EPD regarding daytime construction noise at Seawall B opposite to Hong Kong Garden.	The Contractor agreed to continuously monitor and review the operation in the vicinity opposite to Lung tang Court, in order to minimize the noise impact caused to the public. In addition the Contractor will respond to the complaints received on the 24- hours Contract Complaint Hotline 2496 2555 in the first instant.	31-Mar-03	No exceedance was recorded at the noise monitoring station WN6, WN7 and WN8 from January 2003 to March 2003. It was suspected that the noise was due to traffic noise together with operational noise of plant equipment at Seawall B. The Contractor was also reminded if reorganization of working arrangement is necessary, mitigation proposal should be submitted to IC(E) for review. Additional noise monitoring shall also be conducted at the noise monitoring station WN8 once the mitigation proposal is implemented.

### Log Record on Environmental Complaints

No.	Date of Complaint Received	Description	Proposed Actions	Completion Date	Remarks
076	15-Apr-03	Complaint from Mr. Wong of TL 60 Management Limited regarding the noise nuisance generated from the vehicle movement over the temporary steel decking in front of Hong Kong Garden at Castle Peak Road provided by the Contractor.	The Contractor has replaced the isolated decking plate by 17 April 2003 and agreed to frequently inspect the condition of the steel decking. Further improvement works were completed on 25 April 2003.	25-Apr-03	
078	15-Apr-03	Complaint from Mr. Chau of Hong Kong Garden regarding the noise nuisance generated from vehicle movement over the temporary steel plate in front of the premises.	The Contractor has explained to Mr. Chau that the improvement works were completed on 25 April 2003 and agreed to carry out daily inspection to check the condition of the steel plate.	29-Apr-03	The complainant agreed that the noise nuisance has abated.
080	05-May-03	Complaint from Mr. Tsao / Mr. Chan of Mui Yuen, opposite to Bayside Villas regarding water leakage from the rocky slope behind his house and the damage of water pipes by cleaning works.	The water pipe was repaired on 9 May 2003. The Contractor has explained that the rocky slope was outside the site boundary.	09-May-03	
082	07-May-03	Complaint from Ms. Chan regarding water ponding on existing footpath along Castle Peak Road near the Contractor's site office.	The Contractor has formed holes at existing upstand wall to drain off water trapped in the adjacent footpath and to patch up local depression at the affected footway with plain concrete.	19-May-03	
084	21-May-03	Complaint from Ms. Lam of Sea Crest Villa Phase I regarding construction noise from the slope works outside Sea Crest Villa Phase I.	<p>The Contractor has observed low-noise emission construction equipment were being used at the time of inspection and proposed to speed up the works to limit the duration of daytime construction noise impact.</p> <p>The Contractor has provided additional information in their letter ref. HY/99/18/M45/300/40/10229 dated 25 June 2003. Additional noise monitoring had been taken by the Contractor on 22 May 2003 at WN15 obtaining the result of 66.6dB(A), which was below the limit level of 75dB(A). After reviewing the findings and investigation details, the Contractor confirmed that no further remedial actions was required.</p>	25-Jun-03	<p>The Contractor was requested to submit mitigation proposal to IC(E) for review and to implement the mitigation proposal. Additional noise monitoring is required to be conducted at the noise monitoring station WN15 once the mitigation proposal is implemented.</p> <p>The IC(E) had no comment on the Contractor's findings. Since no mitigation measures were implemented, additional noise monitoring was not conducted.</p>
086	23-May-03	Complaint from Mr. So regarding stagnant water in the drainage and wheel washing bay near the entrance of Sea Crest Villa Phase IV and the damage of road surface near L1 main gate and CLP electricity supply room.	Explained to the complainant that the stagnant water inside the wheel washing bay was for cleaning of vehicle. The leakage found the temporary water pipe was repaired. The water and silt trapped in the U-channel near the main entrance of the estate was removed and the kerb on west side of the run-in to Gate L1 was reinstated.	29-May-03	The Contractor will properly maintain the wheel washing facility, regularly inspect and clean the drainage channel and the gully pots near the main entrance of the estate. The damaged paving slab and cable pit near the power supply room will be restored to original condition after completion of the adjacent substructure works around mid August 2003.
088	03-Jun-03	Complaint from EPD regarding construction dust from Seawall B.	The Contractor proposed to place the concerned area under higher priority and endeavor to water the concerned haul road more frequently during dry days.	06-Jun-03	No rock breaking activity has been observed in site audits since 5 June 2003. The haul road at Seawall B was observed wetted in the site audits. The Contractor was reminded to provide water spraying if there is rock breaking activity in this vicinity.

## Log Record on Environmental Complaints

No.	Date of Complaint Received	Description	Proposed Actions	Completion Date	Remarks
088	03-Jun-03	Complaint from EPD regarding construction noise from Seawall B.	The Contractor reported that there may be occasional crashing noise for the piling works when rock level is reached. The Contractor has been providing mitigation measures, such as barrier and restriction of the rate of concerned works. The Contractor will also endeavor to expedite the works to reduce the duration of perceived daytime impact. The Contractor proposed to perform additional ad hoc inspections on Mondays, Wednesday and Fridays at the concerned area to confirm continual implementation of measures and to conduct additional noise monitoring where appropriate.	06-Jun-03	No rock breaking activity has been observed in site audits since 5 June 2003. Contractor has been reminded to submit mitigation proposal to IC(E) for review and to implement the mitigation proposal if provision of additional mitigation measures is required. The Contractor was also advised to provide portable noise barrier if there is rock breaking activity. Additional noise monitoring is also required to be conducted at the noise monitoring station WN8 once the mitigation proposal is implemented. The IC(E) had no comment on the Contractor's findings. Since no mitigation measures were implemented, additional noise monitoring was not conducted.
091	16-Jun-03	Complaint from Ms. Chan of Sea Crest Villa Phase 1 regarding noise from drilling works carried out at BPRW70 outside Sea Crest Villa Phase 1 before 07:00.	Upon investigation, the Contractor confirmed that there has been no construction work being conducted before 07:00. Nevertheless, the Contractor has scheduled the concerned work to be commenced at 08:00 as on 17 July 2003.	17-Jun-03	
092	16-Jun-03	Complaint from Mrs. Chung of Lido Garden regarding noise from drilling works carried out at BPRW70 opposite to Lido Garden before 07:00.	Upon investigation, the Contractor confirmed that there has been no construction work being conducted before 07:00. Nevertheless, the Contractor has scheduled the concerned work to be commenced at 08:00 as on 17 July 2003.	17-Jun-03	
097	27-Jun-03	Complaint from Mr Fok of Kai Shing Management Services regarding noise nuisance and the ponding of stagnant water arising from the construction activities outside Sea Crest Villa Phase III.	Upon investigation, the condition of water pumps installed separately at east end of the slope close to SCV Phase III and Pai Min Kok Stream Course has been checked. Noise generated from the ongoing construction works in these areas has been monitored. The rock breaking with jackhammer at PMK had been completed on 26 June 2003.	04-Jul-03	After further enquiry into the nature of the complaint, it appears that the complaint refers to the extended duration of construction works in the concerned area (i.e. inconvenience caused due to lengthy works program). The Contractor's Mr Peter Ip has explained the nature of the works to the Management Office. There have been no further complaints from SCV Phase III since the briefing.
103	31-Jul-03	Complaint from Hong Kong Management Office regarding the noise generated by vehicles running over the steel decking plate on the Castle Peak Road close to Hong Kong Garden.	The existing steel decking plate had been repaired during off peak hours and regular inspection on the condition of steel plate and adjacent road surface was agreed to be conducted.	05-Aug-03	There had been no further complaints after the repair.
105	13-Aug-03	Complaint from Mr Chow of Sham Tseng regarding fell of all old trees along section of Castle Peak Road near Ma Wan Pier.	After investigation on the matter, it had been confirmed that the felling and the transplanting of group of trees along the Castle Peak Road near Ma Wan Pier had been carried out in compliance with approved plans and schedules. No follow up is required.	16-Aug-03	
108	11-Sep-03	Complaint from Mr Edith Lee of Sea Crest Villa Phase I complained that it was very dusty at her house and she found that there was no water spraying at the construction site of the slope near Ma Wan Pier.	After investigation on the matter, water browser was arranged for spraying through the haul road. Rock breaking location would be sprayed directly connected from water supply point. To follow up the case, water browser would be arranged every 2 to 3 hours depends on drying up condition. A worker would be arranged for spraying water through out the rock breaking process.	11-Sep-03	



## Log Record on Environmental Complaints

No.	Date of Complaint Received	Description	Proposed Actions	Completion Date	Remarks
112	10-Oct-03	Complaint from Mr Cheung of FEHD that regarding the general refuse being accumulating on the pedestrian walkway between Sea Crest Villa Phase III and Phase II and the drainage channel at Pai Min Kok Village.	Investigation was conducted immediately on 11 October 2003. It was observed that the pedestrian walkway and Outfall I had been tidied up except at the corner of Sea Crest Villa Phase III where a broken umbrella and some broken traffic light was lying on the ground. Immediate action was taken to remove the broken umbrella and signal lights. The site area would be maintained regularly. It was noted that wooden formwork and construction materials might possibly been mistaken to be rubbish.	13-Oct-03	
114	25-Nov-03	Complaint log no. 114 was received on 25 November 2003 regarding the muddy water found on the beach opposite to Sea Crest Villa Phase III.	An inspection for the concerned site area at the interface between the beach and the construction site revealed that there was no evidence of active construction works adjacent to the beach or the presence of muddy water. There was also no evidence of muddy water discharge from Outfall I. The work programme for the following days leading up to the complaint was inspection and found that the bored piling activity had been completed and removed since 15 November 2003. The contractor would regularly monitor the area for muddy water. If potential discharge sources were identified, the Contractor would take action to rectify the situation.	26-Nov-03	
115	30-Nov-03	Complaint from Miss Chan of Sham Tseng Latrine was received on 30 November 2003 regarding the pond of foul water at the footway in front of Sham Tseng Latrine.	An inspection for the concerned site area was carried out. The water ponding was confirmed to be overflow from the terminal manhole, which was a part of public latrine system. The maintenance of the public latrine and the associated systems were the responsibility of FEHD. The Contractor had contacted FEHD to follow up the issue.	01-Dec-03	
116	06-Dec-03	Complaint from Mr Paul Wong of Hong Kong Garden Management Office was received on 6 December 2003 regarding construction noise during early hours of 8:00am.	Inspection of concern area and no abnormal construction activities was found. The Contractor had explained to the Complainer that no statutory permit was required for construction work other than percussive piling at 8:00am and the nature of works conducted at the area was well within permitted limits. ET was reminded the Contractor to implement noise mitigation proposal in accordance with EM&A Manual.	08-Dec-03	Noise generated from the ongoing construction works in these areas was monitored and no exceedance was found. As the Contractor had responded to the complainant and no further complaint was recorded, the Contractor proposed that no further remedial/preventative measures were necessary.
123	20-Feb-04	Complaint from Mr Ho of TL60 Management Ltd was received on 20 February 2004 regarding noise arising from the temporary steel plates on road pavement near Blocks 1 & 2 of Hong Kong Garden	Condition of the decking plat was checked on 23 February 2004 and was repaired on 24 February 2004 during off peak hours.	24-Feb-04	Regular inspection will be conducted and adjacent works was be expedited to allow early road diversion for permanent removal of the steel plates.
139	09-Jul-04	Complaint from EPD was received on 9 July 2004 regarding noise arising from prescribed construction works or works using power mechanical equipment at night near Seawall-B area opposite to Hong Kong Garden	After investigation on the matter, there was no evidence of carrying out the prescribed construction works or using power mechanical equipment between 1900 and 2300 on 3 July 2004.	23-Jul-04	
140	10-Jul-04	Complaint from Highway Department was received on 10 July 2004 regarding noise arising from rock breaking near Sea Crest Villa Phase 3	After investigation on the matter, there was no evidence of rock breaking activities undertaken in the vicinity of Sea Crest Villa Phase 3.	23-Jul-04	

### Log Record on Environmental Complaints

No.	Date of Complaint Received	Description	Proposed Actions	Completion Date	Remarks
149	11-Aug-04	Complaint from EPD regarding the sandy wake of a marine vessel carrying sand to the beach reinstatement area of Seawall B	After investigation on the matter, the following action was proposed. The vessel and water depth should be thoroughly checked prior to sand placing. If shallow water need to be approached, another shallower vessel should be used. The land co-ordinator should cease the sand placing operation if muddy plumes were noticeable.		
154	25-Aug-04	Complaint from Ms Tang regarding littering on the slope close to the Sea Crest Villa Phase 2.	After investigation on the matter, there was no evidence that the problem was caused by any construction activities.	27-Aug-04	
156	18-Sep-04	Complaint from Mr Chu regarding excessive garbage trapped along the adjacent shore of Seawall B west end.	It was out of control over the accumulation of floating rubbish drifting toward the shore. However, the contractor would remove them as soon as possible.	20-Sep-04	