Contract No. GE/2013/06

Landslip Prevention and Mitigation Programme, 2008, Package J

Landslip Prevention and Mitigation Works in New Territories

Above Leung Fai Tin along Clear Water Bay Road, Sai Kung

Study Area: 12/NW-C/SA1 (Study Area H)

Independent Environmental Checker (IEC)
Monthly Audit Report No. 10

1 November to 30 November 2014

182663/B&V/010/Issue 1

Kwan On Construction Co Ltd 3E, Yiko Industrial Building 10, Ka Yip Street Chai Wan, Hong Kong Black & Veatch Hong Kong Limited 25/F, Millennium City 6 392 Kwun Tong Road Kowloon Hong Kong

December 2014

均安建築有限公司 KWAN ON CONSTRUCTION CO. LTD.

15 Dec 2014

Senior Environmental Protection Officer (Regional Assessment)3
Environmental Protection Department
Environmental Assessment Division - Regional Assessment Group
27/F, Southorn Centre,
130 Hennessy Road, Wan Chai, Hong Kong

By Post

Attn: Mr. WONG Wai-yan, Richard

Dear Sirs,

CEDD Contract No. GE/2013/06
Landslip Prevention and Mitigation Programme, 2008, Package J
Landslip Prevention and Mitigation Works in New Territories
Environmental Permit No. EP-448/2013
Independent Environmental Checker (IEC) Monthly Audit Report No. 10

Pursuant to Clause 2.5 of the Environmental Permit No. EP-448/2013, we would like to submit captioned the Independent Environmental Checker Monthly Audit Report No. 10 for your perusal.

Yours faithfully, Kwan On Construction Co., Ltd.

Joey WONG

Ref: GE/2013/06-S579

Encl.

c.c. - GEO/LPM2 – Mr. Harris LAM w/e
- CH2M HILL Halcrow China Limited – Mr. Joe Nam w/e



BLACK & VEATCH HONG KONG LIMITED

25/F, Millennium City 6, 392 Kwun Tong Road, Hong Kong 博威工程顧問有限公司

香港九龍觀塘道 392 號創紀之城第六期 25 樓 Tel 電話 +852 2601 1000 • Fax 傳真 +852 2601 3988 Email 電郵 bvhk@bv.com

By POST

OUR REF 182663-019

YOUR REF

5 December 2014 DATE

Kwan On Construction Co Ltd 3E, Yiko Industrial Building 10, Ka Yip Street Chai Wan, Hong Kong

For the attention of Mr Aman WONG / Mr. Roy LEUNG

Dear Sir.

CEDD Contract No. GE/2013/06

Landslip Prevention and Mitigation Programme, 2008, Package J, Landslip Prevention and Mitigation Works in New Territories - Above Leung Fai Tin along Clear Water Bay Road, Sai Kung - Study Area No.: 12NW-C/SA1 (Study Area H) Independent Environmental Checker (IEC) Monthly Report No. 10

According to Environmental Permit (EP-448/2013) Specific Condition Clause 2.5, we are pleased to submit an IEC Monthly Report No. 10 (1 November to 30 November 2014) for your record. IEC Monthly Reports are enclosed for your internal record (1 copy) and onward submission to Environmental Protection Department (2 copies and 1 electronic copy).

Should you have any queries, please feel free to contact Ms Esther Tong at 2608-7379.

Yours faithfully, for and on behalf of

BLACK & VEATCH HONG KONG LIMITED

KELVIN N.F. LAU DIRECTOR

ET

Encl.

Certificate No.: HKG6017620

CC. CH2M HILL Halcrow China Limited

Attn: Mr. Joe Nam GE/CM43, LPM Division 2, GEO Attn: Mr. Harris Lam [without encl.] [without encl.]





ET/MC/AK/KL/182663/14.2100

Document Control		ol	CEDD Contract No. GE/2013/06 Landslip Prevention and Mitigation Works in New Territories	No : 182663/B&V/010
		_	Above Leung Fai Tin along Clear Water Bay Road, Sai Kung	/Issue 1
Amend	ment Reco	ord	Study Area: 12/NW-C/SA1 (Study Area H)	Prepared by : B&V
IFC Mor	nthly Audit	Renort	Client:	Initials: ET
No.10 (1	Nov 2014)	пероп	Kwan On Construction Co. Ltd	Date:
			Itwan on construction co. Etc	5 th Dec 2014
Pages	Date	Issue	Description	Initials:
		No.		
All	Dec 14	1	IEC Monthly Audit Report No. 10	ET

^{*} The Registered Recipient is responsible for destroying or marking as *superseded* all superseded documents.

CONTENTS

	P	age
1.	INTRODUCTION	1
1.1	Background and Project Description	
1.2	Types of Designated Project	
1.3	Location and Scale of Project	
1.4	Organisation and Reporting Schedule	
2.	PROGRESS OF THE CONTRACT	2
2.1	Status of the Environmental Licence and Permits	3
2.2	Progress of the Construction Works	ک د
2.3	Summary of Site Inspection and Audit	د د
2.4	Summary of Complaints and Prosecutions	3
3.		
3.	CONCLUSIONS	4
4.	RECOMMENDATIONS	5
FIGUR Figure	ES Location Plan of the Designated Project	0
Figure Figure	 IEC Site Audit Route and Random Tree Check on 19 November 2014 Three Numbers of Aquilaria sinensis Felled by Others 	

APPENDICES

Appendix A Environmental Inspection Checklist

	Name	Signature	Date
Prepared	Esther TONG	Gusher	1 lec 2014
Checked	Manuel CHUA	len	1 Dec 2014
Reviewed / Authorised	Norman SONG	Them	1 Per 2014

1. INTRODUCTION

1.1 Background and Project Description

- 1.1.1 Geotechnical Engineering Office (GEO) of the Civil Engineering and Development Department has identified about 2700 natural hillside catchments with a known history of landslides close to existing buildings and important transport corridors based on interpretation of large-scale historical aerial photographs. Natural hillside catchments affecting individual units of existing development are further grouped into different Study Areas designated for natural terrain hazard studies by GEO.
- 1.1.2 The natural hillside, Study Area No. 12NW-C/SA1, at Leung Fai Tin above Clear Water Bay Road in Clear Water Bay Peninsula, includes a number of hillside catchments which warrant high priority for natural terrain hazard study and mitigation actions. The location and the extent of the Study Area are shown in **Figure 1**.
- 1.1.3 The natural hillside within the Study Area has been disturbed since 1940s, and there were 3 landslides identified to have occurred on the natural hillside in 1970s. A detailed natural terrain hazard study concluded that the natural hillside within the Study Area is highly susceptible to landslide failures and the landslide debris would travel downslope and be channelised along the stream course reaching Clear Water Bay Road and the village houses at Leung Fai Tin.
- 1.1.4 Hence, natural terrain hazard mitigation works (HMW) are required at the lower portion of the Study Area (hereinafter referred to as the "Works Area") to mitigate the potential hazards arising from natural terrain open hillslope landslides, boulder falls and channelised debris flows at the Study Area affecting Clear Water Bay Road and village houses at Leung Fai Tin downhill. The proposed natural terrain HMW includes erection of tensioned steel mesh fences (also known as flexible barrier), construction of masonry maintenance staircases and associated landscape treatments at the Works Area. The extent of the Works Area has been carefully considered to limit the extent of proposed works, necessary working space and the site access.

1.2 Types of Designated Project

- 1.2.1 The Natural Terrain Hazard Mitigating Works at Study Area No. 12NW-C/SA 1 above Leung Fai Tin along Clear Water Bay Road, Sai Kung is referred as "Designated Project" (DP) which includes the works area of the Project falls within a Conservation Area under the approved Clear Water Bay Peninsula South Outline Zoning Plan No. S/SK-CWBS/2 and Item Q.1 Part 1 of Schedule 2 under the Environmental Impact Assessment Ordinance (EIAO). The Project Profile (Register No. PP-480/2013) was submitted for directly application of Environmental Permit (EP) on 18 March 2013. Environmental Protection Department (EPD) granted the EP (EP No.: EP-448/2013) to the GEO/Civil Engineering and Development Department (hereinafter referred to as the "Client") in 10 April 2013 to construct the Designated Project (DP) under the Environmental Impact Assessment Ordinance (EIAO).
- 1.2.2 According to the EP Specific Condition Clause 2.5, the Permit Holder shall employ an

Independent Environmental Checker (IEC) to audit the implementation of all mitigation measures recommended in the Project Profile and the approved Landscape and Compensatory Planting Plan, and to certify in writing in the monthly audit report full implementation of the mitigation measures during and upon completion of the construction works. The IEC shall not be in any way an associated body of the Contractor of the Project.

1.3 Location and Scale of Project

- 1.3.1 The proposed HMW will be constructed within the Works Area at the lower portion of the Study Area No. 12NW-C/SA1 above Clear Water Bay Road, Leung Fai Tin in Clear Water Bay Peninsula. The Works Area is located within a Conservation Area. Extent of the Works Area is approximately 6,000m² and the project comprises as follows:
 - a. Erect about 250m long, 5m-6m high flexible barrier supported by vertical and raking steel bar anchors (about 120 nos.) to be drilled and installed in ground.
 - b. Construct of 300m long, 600mm wide masonry maintenance access with handrails
 - c. Provision of soft landscape works includes pit-planting of native/shrub seedlings, plant of climbers and hydroseeding.

1.4 Organisation and Reporting Schedule

1.4.1 CEDD commissioned CH2M HILL Halcrow China Limited (CHMHC) as the Engineer. The Contractor of the Project is Kwan On Construction Co. Ltd (KOCCL). Black & Veatch Hong Kong Limited (B&V) was appointed as Independent Environmental Checker (IEC) on 10 February 2014. This Report covers the period from 1 November 2014 to 30 November 2014.

2. PROGRESS OF THE CONTRACT

2.1 Status of the Environmental Licence and Permits

2.1.1 Table 2-1 presents a summary of the status of environmental licenses and permits for this Contract.

Table 2-1 Status of Environmental Permit

Type of Licence	Permit/License	Issue Date	Covered Area	Validity	Status
	No.				
Environmental	EP-448/2013	10 April 2013	Study Area No.	Whole Project	Valid
Permit			12NW-C/SA1	·	
			above Leung Fai		
			Tin along Clear		
			Water Bay		
			Road, Sai Kung		

2.2 Progress of the Construction Works

2.2.1 The Project has been commenced on 15 January 2014. During the reporting period, erection of scaffolding and foundation works of the flexible barriers were being carried out during the site inspection. Site audit was carried out along the works areas as shown in **Figure 2**.

2.3 Summary of Site Inspection and Audit

- 2.3.1 Temporary access outside the permitted boundary, recorded in September 2014, was fenced off properly (Photo 1). No work was carried out outside the permitted boundary (Photo 2).
- 2.3.2 Join site audit was carried out with CHMHC and KOCCL on 19th November 2014. Erection of chain link fencing and scaffolding and drilling of upslope anchor for flexible barrier were observed within the works area (Photos 3 and 4). All construction works were within the works boundary.

Random Trees Check

2.3.3 Trees along the temporary works area were inspected. No tree damage was observed. Temporary tree protective cover to tree trunk were provided. 10 trees were randomly selected for inspection and all of them were retained in-situ with tree tags (Table 2-2).

Table 2-2 Randomly Selected Trees for Site Inspection

Tree I.D.	Species	Condition
TA104	Machilus chekiangensis	Fair with tree tag
T431	Cinnamomum parthenoxylon	Fair with tree tag
TA079	Machilus chekiangensis	Fair with tree tag
T827	Machilus chekiangensis	Fair with tree tag
T415	Machilus chekiangensis	Fair with tree tag
T338	Machilus chekiangensis	Fair with tree tag
T251	Aporusa dioica	Fair with tree tag
T65	Diospyros morrisiana	Fair with tree tag

Tree I.D.	Species	Condition
T63	Machilus chekiangensis	Fair with tree tag
T171	Litsea rotundifolia	Fair with tree tag

- 2.3.4 Bright colour tree protection signage was provided at protective trees (Photo 5). Information sheet with colour photos of *Aquilaria sinensis* and *Pavetta hongkongensis* were displayed conspicuously within the construction site.
- 2.3.5 Three individuals of *Aquliaria sinensis* (T606, T627 & T607) were observed felled by others on 7 and 17 November 2014 respectively (Photos 6, 7 & 8). Similar case was happened in February 2014, these two incidents were reported to HKPF and EPD by the Contractor and the Engineer accordingly. It was suspected that such tree felling activities were happened in night time, thus, the Permittee would provide a night time watchman to reinforce site security and prevent similar recurrence.
- 2.3.6 No observation was recorded during the site inspection and audit in the reporting month. No tree felling was recorded.

Reminder

- 2.3.7 It is reminded that the Contractor shall ensure construction activities shall fully comply with the environmental permit conditions.
- 2.3.8 It is noted that a dense group of *Aquilaria sinensis* were located along the FB1 Section 11 to 13. The Contractor was reminded to align the foundation, flexible barrier, maintenance staircases away from protective trees as far as practical. Tree protective measures such as fencing, tree tag, and bright colour tree protection signage shall be provided during the construction phase.
- 2.3.9 It is reminded that the Contractor shall provide sufficient induction training to all site personnel (both supervision staff and workers) in order to brief them on tree preservation including the locations of the *Aquilaria sinensis* and *Pavetta hongkongensis* individuals and their importance. The resident site supervisory staff shall closely monitor the conditions of the *Aquilaria sinensis* and *Pavetta hongkongensis* individuals during the construction phase.
- 2.3.10 We suggested to put warning signs at various locations, e.g. near the felled *Aquilaria sinensis*, to warn the trespasser not to damage the trees.

2.4 Summary of Complaints and Prosecutions

- 2.4.1 No environmental complaint was recorded in the reporting period.
- 2.4.2 No prosecution was recorded in the reporting month.
- 2.4.3 The update statistical summary of complaint is presented in Table 2-3.

Table 2-3 Status of Complaints and Prosecution

Donorting Doried	Complaint S	Statistics	Anna of Congonn	Validity	Ctatua
Reporting Period	Number	Cumulative	Area of Concern	Validity	Status
1 st Nov 2014 – 30 th Nov 2014	0	0	-	-	-

3. CONCLUSIONS

- 3.1.1 During the reporting period, erection of chain link fencing and scaffolding and drilling of upslope anchor for flexible barrier were carried out. The Contractor was reminded to provide protective measures to all *Aquilaria sinensis* and *Pavetta hongkongensis* (香港大沙葉) and retained in-situ. No Follow up action is required.
- 3.1.2 No environmental complaint was received in the reporting month. No summon or prosecution related to the environmental issues was made against the Project in the reporting month.

4. RECOMMENDATIONS

4.1.1 The Contractor was reminded to implement the relevant mitigation measures as stated in the Environmental Permit and the Contract to prevent any non-compliance throughout the construction period.

Photos

December 2014 Black & Veatch

Photo 1 Temporary access was fenced off properly.



Temporary works area within the project boundary (Section FB1 11-12).



Photo 2

Temporary works area within the project boundary (Section FB1 1-2).

No work was observed at the temporary access.



Photo 5 Bright colour tree protection signage was provided at protective tree.





December 2014 Black &Veatch

Photo 6 T606 *Aquilaria sinensis* was felled by others.



Photo 7 T607 *Aquilaria sinensis* was felled by others.




Photo 8 T627 *Aquilaria sinensis* was felled by others.



December 2014 Black &Veatch

Figure

December 2014 Black & Veatch





Project Title : Natural Terrain Hazard Mitigation Works at Study Area No. 12NW-C/SA1 above Leung Fai Tin along Clear Water Bay Road, Sai Kung

工程項目名稱: 西 貢 清 水 灣 道 兩 塊 田 天 然 山 坡 研 究 地 區 編 號 12NW/C/SA1

天然山坡災害緩減工程

Environmental Permit No.: EP-448/2013 環境許可證編號: EP-448/2013 Figure 1: Location of the Project

圖 1: 工程項目位置

(This figure was prepared based on Figure 1 of the Project Profile (Register No.: PP-480/2013)) (本圖是根據工程項目簡介(登記冊編號: PP-480/2013) 圖 1 編製)




Figure 2 IEC Audit Route along the Temporary Access and Random Tree Check on 19 Nov 2014




Figure 3 Three numbers of Aquilaria sinensis (T606, T607 & T627) Felled by Others

Appendix A Environmental Inspection Checklist

December 2014 Black & Veatch



Environmental Inspection Checklist

		Ch	ecklist Nu	mber:		GE/2013,	/16_No. 10
Project	:	Contract No. GE/2013/16	spected by	:			
			C's Repres	entative:		Ms. Esthe	er Tong
		Study Area: 12NW-C/SA1 (Study Area H)	's Represe	ntative:		Mr. Felix	Siu
	ion Date:		's Represe			-	
Time:		Co	ntractor's	Represen	tative:	Mr. Roy l	_eung
PART A	:	GENERAL INFORMATION				0-0-0-0	
Weathe	er:	Sunny Haze Cloudy R	ainy 🔽	Fine			
Temper	rature:	70 °C					
Humidi	ty:	High √ Moderate Low					
Wind:		Strong Breeze 🗸 Light Ca	alm				
Maia	. Camatuu at	an Wanta Ohaamad					
		on Works Observed link fencing and scaffolding and drilling of upslope anchor fo	r flexible b	arrier wei	e observe	ed during t	he site audit.
PROCESS					***************************************		
PART B	:	SITE AUDIT					
Note:		pplicable; Yes : Compliance; N/C : Non-Compliance; Observations requiring follow-Up actions	N/A	Yes	Follow Up	N/C	Photo/ Remarks
Section	1: Construc	tion Noise					
1.01		equipment and activities positioned as far as practicable ensitive receivers?		X			
1.02	Is silenced	equipment adopted?	X				
1.03	Is idle equ	ipment turned off or throttled down?		X			
1.04	Are plant	and equipment kept to a minimum?		X			
1.05	Is parallel	use of noisy equipment / machinery avoided?	X				
1.06	Are all pla	nt and equipment well maintained and in good condition?		X			
1.07		barriers or enclosures provided at areas where on activities cause noise impact on sensitive receivers?	X				
1.08	Are hand operation	neld breakers fitted with valid noise emission labels during?	X				
1.09	Are air co operation	mpressors fitted with valid noise emission labels during ?	X				
1.10	Are flaps a operation	and panels of mechanical equipment closed during ?	X				
1.11		ruction Noise Permit(s) applied for general construction ing restricted hours?	X				
1.12	Are valid (site?	Construction Noise Permit(s) displayed on the construction	X				



Environmental Inspection Checklist

Checklist Number:

GE/2013/16_No. 10

Note:	N/A: Not Applicable; Yes: Compliance; N/C: Non-Compliance; Follow Up: Observations requiring follow-Up actions	N/A	Yes	Follow Up	N/C	Photo/ Remarks
Sectio	n 2: Air Quality			•		
2.01	Are the excavated materials sprayed with water during handling?	X				
2.02	Are stockpiles of dusty materials sprayed with water, covered or placed in sheltered areas?	X				
2.03	Is the exposed earth properly treated within six months after the last construction activities?	×				
2.04	Is the surface where any drilling, cutting, polishing or breaking operation continuously sprayed with water?	X				
2.05	Are de-bagging, batching and mixing processes carried out in sheltered areas during the use of bagged cement?	×				
2.06	Are there any fencing provided along the site boundary, which adjoins areas accessible to the public?		X			
Note:	N/A: Not Applicable; Yes: Compliance; N/C: Non-Compliance; Follow Up: Observations requiring follow-Up actions	N/A	Yes	Follow Up	N/C	Photo/ Remarks
Sectio	n 3: Water Quality					
3.01	Is the discharge of turbid water avoided?	\times				
3.02	Are there proper desilting facilities in the drainage systems to reduce SS levels in effluent?	×				
3.03	Are there channels, sandbags or bunds to direct surface run-off to sedimentation tanks?	\times				
3.04	Are there any perimeter channels provided at site boundaries to intercept storm runoff from crossing the site?	\times				
3.05	Are the maintenance access and/or anchor built within the stream?	X				
3.06	Are temporary exposed slopes properly covered?	X				
3.08	Are earthworks final surfaces well compacted or protected?					
3.09	Are there any procedures and equipment for rainstorm protection?	X				
3.10	Are the vehicle and plant servicing areas paved and located within roofed areas?	X				
3.11	Is the oil leakage or spillage avoided?	X				
3.12	Are there any measures to collect spilt cement and concrete washings during concreting works?	×				
3.13	Are the oil interceptors/grease traps maintained properly?	X				
3.14	Concreting wastes water should be neutralized below the pH Action Levels before discharge.	X				
3.15	Mobile toilets should provide on-site and located away the stream course.	X				
3.16	License collector should be employed for handling the sewage of mobile toilet.	X				



Environmental Inspection Checklist

Checklist Number:

GE/2013/16_No. 10

Note:	N/A: Not Applicable; Yes: Compliance; N/C: Non-Compliance; Follow Up: Observations requiring follow-Up actions	N/A	Yes	Follow Up	N/C	Photo/ Remarks
Sectio	n 4: Ecology					
4.01	Are the maintenance access and/or anchor built within the stream?	X				
4.02	Is there any opening (at least 0.5m allowed) between the stream bed and the bottom of the flexible barrier provide?	×				
4.03	Are protected plants species are retained in-situ?		\times			
4.04	Is there any tree pruning to damage the preserved trees?	\times				
4.05	Are all <i>Aquilaria sinensis</i> (85 nos.) and <i>Pavetta hongkongensis</i> (10 nos.) retained in-situ and fenced off?		\times			
4.06	Are there any tagged provided at retained in-situ trees?		X			
4.07	Are all retained trees closed to the construction works providing protective wrapping properly to minimize the damage?		\times			
4.08	Are only 25 nos. of non-protected trees are felled?	\times				
4.09	Are any native light standard trees provided as compensatory planting (ratio 1:3)?	X				
4.10	Are the proposed compensatory trees planting native and shade-tolerant trees species according to the recommendation of Project Profile?	X				
4.11	Is the positioning the alignment has minimum 1.5m in radius away from the alignment?	X				
4.12	Any induction training course to all site personnel (both supervision staff and workers) to brief the persevered trees location and importance?		X			
4.13	Any adjustment of the foundation of flexible barriers and staircases to avoid the damage of root systems of existing trees?	X				
4.14	Is there any re-vegetation area to compensate the temporary loss of 200m² (due to temporary access) understorey area?	X				
4.15	Is there any re-vegetation area to compensate the permanent loss of 200m² (due to maintenance access and anchor) understorey area?	×				
Note:	N/A: Not Applicable; Yes: Compliance; N/C: Non-Compliance; Follow Up: Observations requiring follow-Up actions	N/A	Yes	Follow Up	N/C	Photo/ Remarks
Sectio	n 5: Landscape and Visual					
5.01	Is the landscape design including the compensatory planting follow GEO Publication No. 1/2011?	\times				
5.02	Is there any erecting of hoarding to minimize the unsightly construction activities?		X			
5.03	Is the hoarding with decorative panels with patterns of vegetation mature trees below the hoardings for nature screening) to minimize the visual impact?		\boxtimes			
5.04	Any utilization of existing trees located in fornt of hte flexible barrier as natural screening?	X				
5.05	Any provision Pit-planting of native light standard trees and planting of climbers in front of the fence to provided screening effect?	X				-
5.06	Is the dark colour of the flexible barrier used?	X				



Environmental Inspection Checklist

		Checklist I	Number:		GE/2013/	/16_No. 10
5.07	Are the concrete footing of the anchor and the handrails along the maintenance access painted with sub-due colour as far as practical?					
5.08	Are the maintenance accesses apply masonry finished to blend with surroundings?	X				
Note:	N/A: Not Applicable; Yes: Compliance; N/C: Non-Compliance; Follow Up: Observations requiring follow-Up actions	N/A	Yes	Follow Up	N/C	Photo/ Remarks
Sectio	n 6: Waste Management					
6.01	Has the Waste Management Plan prepared according to ETWB TC(W) No. 19/2005 and submit to Engineer?	X				
6.02	Are receptacles available for general refuse collection?	X				
6.03	Is general refuse sorting or recycling implemented?	X				
6.04	Is general refuse disposed of properly and regularly?	X				
6.05	Is the Contractor registered as a chemical waste producer?	X				
6.06	Are the chemical waste containers properly labelled?	X				
6.07	Are the chemical wastes stored in proper storage areas?	X				
6.08	Is the chemical waste storage area properly labelled?	X				
6.09	Is the chemical waste storage area used for storage of chemical waste only?	X				
6.10	Are incompatible chemical wastes stored in different areas?	\times				
6.11	Are the chemical wastes disposed of by licensed collectors?	\boxtimes				
6.12	Are trip tickets for chemical wastes disposal available for inspection?	Y				
6.13	Are chemical/fuel storage areas bunded?	X				
6.14	Are designated areas identified for storage and sorting of construction wastes?	X				
6.15	Are construction wastes sorted (inert and non-inert) on site?	X				
6.16	Are construction wastes reused?	X				
6.17	Are construction wastes disposed of properly?	Ý				9
6.18	Are site hoardings and signboards made of durable materials instead of timber?	X				
6.19	Is trip ticket system implemented for the disposal of construction wastes and records available for inspection?	X				
6.20	Are appropriate procedures followed if contaminated material exists?	X				
6.21	Is relevant license/ permit for disposal of construction waste or excavated materials available for inspection?	X				
6.22	Site cleanliness and appropriate waste management training had provided for the site workers.	X				



Environmental Inspection Checklist

		Checklist	Number:		GE/2013/	/16_No. 10
Note:	N/A: Not Applicable; Yes: Compliance; N/C: Non-Compliance; Follow Up: Observations requiring follow-Up actions	N/A	Yes	Follow Up	N/C	Photo/ Remarks
Sectio	n 7: Licence					
7.01	Is relevant Environmental Permit posted at all vehicle site entrances/exits?					
7.02	Any N/C of EP condition?	X				
Section	n 8: Follow-up of the previous monthly environmental audit on date		Chacklist	No GE/20	13/16 No	Y.
0000	in or ronour up or the previous monthly environmental addition date	-	_ (CITECKIISE	140. GE/ 20	13/10_140	· _ /
Note:	N/A: Not Applicable; Yes: Compliance; N/C: Non-Compliance; Follow Up: Observations requiring follow-Up actions	N/A	Yes	Follow Up	N/C	Photo/ Remarks
	N/A: Not Applicable; Yes: Compliance; N/C: Non-Compliance;			Follow		Photo/
Note:	N/A: Not Applicable; Yes: Compliance; N/C: Non-Compliance; Follow Up: Observations requiring follow-Up actions			Follow		Photo/
Note: 8.01	N/A: Not Applicable; Yes: Compliance; N/C: Non-Compliance; Follow Up: Observations requiring follow-Up actions Is the situation in item improved / rectified?			Follow		Photo/
Note: 8.01 8.02	N/A: Not Applicable; Yes: Compliance; N/C: Non-Compliance; Follow Up: Observations requiring follow-Up actions Is the situation in item improved / rectified? Is the situation in item improved / rectified?			Follow		Photo/
8.01 8.02 8.03	N/A: Not Applicable; Yes: Compliance; N/C: Non-Compliance; Follow Up: Observations requiring follow-Up actions Is the situation in item improved / rectified? Is the situation in item improved / rectified? Is the situation in item improved / rectified?			Follow		Photo/



Contract No. GE/2013/16

Landslip Prevention and Mitigation Programme, 2008, Package J, Landslip Prevention and Mitigation Works in New Territories

Above Leung Fai Tin along Clear Water Bay Road, Sai Kung

Study Area No.: 12NW-C/SA1 (Study Area H)
Environmental Inspection Checklist

		Checklist Number:	GE/2013/16_No. 10
Remarks / Observations:			
Nil			
	Committee and the second of th		
			TO A TAXABLE CONTROL OF THE PROPERTY OF THE PR
enterte for Laurer White the Mandallier of American personal and American Manager (Manager American Am		MATERIAL PARTICIPATION OF COURSE CONTROL OF COURSE COURS	
The state of the s	The second secon		Andreas analysis and reserve and a constraint as the constraint and an analysis and an analysi
	,		
THE RESERVE AS A SECOND CONTRACT OF THE PROPERTY OF THE PROPER			
	The state of the second control of the secon		
Signature: IEC's Representative	RE's representative	ET's representative	Contractor's representative
Guther	TEN .	•	3
Name: Ms. Esther Tong	Name. Mr. Felix Siu	Name: NIL	Name: Mr. Roy Leung
Date: 17 Nov 2014	Date: Nov 2014	Date: -	Date: Nov 2014