



**Contract No. SS M333**


**Reprovisioning of Diamond Hill  
Crematorium**

**Supplementary Contamination  
Assessment Report  
(For the Existing CLP Secondary  
Substation at Phase I Area)**

[April 2005]


Reviewed by (PM): (Florence Yuen)


Checked by: (Lawrence Tsui)


Approved by: (ET Leader – Y T Tang)

Report Version: <u>Version 0</u>	Date of Submission: <u>14 April 2005</u>
----------------------------------	--

The information contained in this report is, to the best of our knowledge, correct at the time of printing. The interpretation and recommendations in the report are based on our experience, using reasonable professional skill and judgment, and based upon the information that was available to us. These interpretations and recommendations are not necessarily relevant to any aspect outside the restricted requirements of our brief. This report has been prepared for the sole and specific use of our client and MEMCL accepts no responsibility for its use by others.

This report is copyright and may not be reproduced in whole or in part without prior written permission.

**MAUNSELL ENVIRONMENTAL MANAGEMENT CONSULTANTS LTD**

11/F, Grand Central Plaza, Tower 2, 138 Shatin Rural Committee Road, Shatin, NT, Hong Kong

Tel: (852) 2893 1551 Fax: (852) 2891 0305 Email: [mem@maunsell.aecom.com](mailto:mem@maunsell.aecom.com)



安誠工程顧問有限公司

香港灣仔  
皇后大道東183號  
合和中心47樓

**Hyder Consulting**

47/F Hopewell Centre,  
183 Queen's Road East  
Wan Chai, Hong Kong

電話: (852) 2911 2233

圖文傳真: (852) 2805 5028

電子郵件: hyder@hyder.com.hk

網址: www.hyderconsulting.com

Tel : (852) 2911 2233

Fax : (852) 2805 5028

Email: hyder@hyder.co

Website: www.hydercor

Hyder Consulting Limited is incorporated in Hong Kong with limited  
COI Number 126012

15 April 2004

Architectural Services Department  
Queensway Government Offices  
66 Queensway  
Hong Kong

**BY POST & FAX (2524 81)**

Your  
Ref:

Our  
Ref: 1148-04/E05-27061

For attention of: Mr Michael Mak

Dear Michael

**Reprovisioning of Diamond Hill Crematorium  
Supplementary Contamination Assessment (SCA) Report for the Existing CLP  
Secondary Substation at Phase 1 Area**

We refer to the fax, ref.: S07904(001)/C/cglw50411 dated 14 April 2005, from MEMCL copied to us enclosing the Supplementary Contamination Assessment Report for the Existing CLP Secondary Substation at Phase I Area.

We have no comment and hereby verified the SCA Report.

Should you have any queries, please do not hesitate to contact the undersigned on 2911 2719 or Adi Lee on 2911 2729.

Yours sincerely

A handwritten signature in black ink, appearing to read "Coleman Ng", written over a white background.

**Coleman Ng  
Independent Environmental Checker  
HYDER CONSULTING LIMITED**

Handwritten initials "RR" in black ink, located to the left of the name Coleman Ng.

cc MEMCL – Mr. Y. T. Tang/Ms Florence Yuen  
CRCL – Mr. Eric To

(Fax: 2891 0305)  
(Fax: 2827 2921)

CN/AL



## TABLE OF CONTENTS

1	INTRODUCTION .....	1
2	OBJECTIVES OF THE SUPPLEMENTARY CONTAMINATION ASSESSMENT (SCA) REPORT .....	1
3	CONTAMINATION ASSESSMENT METHODOLOGY .....	1
4	ASSESSMENT CRITERIA .....	2
5	ANALYTICAL RESULTS AND INTERPRETATION.....	2
6	CONCLUSIONS AND RECOMMENDATIONS.....	3

### List of Table

Table 4.1	Dutch ABC Values for Relevant Soil Testing Parameters .....	2
-----------	---	---

### List of Figure

Figure 1	As-built Sampling Location for the Existing CLP Secondary Substation at Phase I Area
----------	--

### Appendices

Appendix A	Sampling and Testing Schedule Proposed in the Sampling and Analysis Plan
Appendix B	Soil Boring Log
Appendix C	Photographic Records of TR1
Appendix D	Laboratory Results

## 1 INTRODUCTION

- 1.1 According to the *Environmental Permit (EP) (No. EP-179/2004) of the 'Reprovisioning of Diamond Hill Crematorium EIA (Register No. AEIAR-076/2004)'* ('The Project'), a supplementary contamination assessment (SCA) shall be carried out for the existing CLP secondary substation ('Subject Site') during the construction and demolition of certain parts of the Project (Phase I works).
- 1.2 Maunsell Environmental Management Consultants Limited ('The Consultant') was commissioned by the China Resources Construction Company Limited (The Contractor') to undertake the supplementary contamination assessment for the Subject Site.
- 1.3 A site visit was conducted on 7 October 2004. It was observed that a switch board with wire facilities as well as a transformer were found inside the substation. In order to investigate any potential contamination caused by the leakage of transformer oil, a sampling point, TR1, was proposed underneath the existing transformer. The location of TR1 is shown in **Figure 1**.
- 1.4 A sampling and analysis plan ('The Plan') incorporating the site investigation and testing schedule for the assessment of polychlorinated biphenyls (PCBs) and Total Petroleum Hydrocarbons (TPH) at TR1 was prepared following the *Environmental Permit Clauses 3.6 and 3.7* and the *Particular Specification PS.G11 4.5.4* of the Project. The Plan was approved by Environmental Protection Department (EPD) on 25 January 2005. The sampling and testing schedule detailed in the Plan is presented in **Appendix A**.
- 1.5 The site investigation was subsequently carried out on 14 and 15 March 2005 in accordance with the sampling and testing schedule stated in the Plan. The soil boring was undertaken by the Contractor and supervised by the Consultant. The analytical testing was carried out by a laboratory accredited by the Hong Kong Laboratory Accreditation Scheme (HOKLAS).

## 2 OBJECTIVES OF THE SUPPLEMENTARY CONTAMINATION ASSESSMENT (SCA) REPORT

- 2.1 The objectives of this Supplementary Contamination Assessment Report are to report the sampling and analysis results, identify the nature and extent of contamination, as well as quantify the contaminated soil according to the *Environmental Permit Clauses 3.6 and 3.7* and the *Particular Specification PS.G11 4.5.4* of the Project.

## 3 CONTAMINATION ASSESSMENT METHODOLOGY

### Soil Boring and Sampling

- 3.1 Excavation of the trial pit, TR1, was carried out by hand tools. A total of three soil samples were collected at 0m (i.e. immediately below concrete), 1m and 2m in depth at TR1 in order to delineate the vertical profile of contamination. The soil samples were collected by hand sampling using stainless steel tools.
- 3.2 Before excavation and between sampling at the trial pit, the sampling equipment and all equipment in contact with the ground were thoroughly decontaminated prior to use by laboratory-grade detergent followed by distilled water rinsing.
- 3.3 Sufficient soil sample were taken to fill up the sample container upon sample collection. The sample container was wide mouth amber glass jar with Teflon lid liner provided by the laboratory.
- 3.4 The soil samples were properly labelled and stored in cool boxes chilled at a temperature of around 4°C until delivered to the analytical laboratory.

### Strata Logging

3.5 Strata logging for the trial pit was undertaken during the course of digging and sampling by qualified geologist. The soil boring log is given in **Appendix B**. The log included the general stratigraphic descriptions, depth of soil sampling and sample notation. The presence of rocks/boulders/cobbles and foreign materials such as metals, wood and plastics would also be recorded. Photographic records for the trial pit were taken and are given in **Appendix C**.

### Free Product and Groundwater Level Measurement

3.6 As no free product and groundwater were observed at the site, no such sampling was conducted during the site investigation.

## 4 ASSESSMENT CRITERIA

4.1 The assessment methodology of this Study was developed in accordance with the Practice Note ProPECC PN3/94 “*Contaminated Land Assessment and Remediation*” and “*Guidance Notes for Investigation and Remediation of Contaminated Sites of Petrol Filling Stations, Boatyards, and Car Repair / Dismantling Workshops*” issued by EPD.

4.2 The ProPECC Note PN 3/94 was used in setting the soil contamination criteria. The Practice Note makes reference to criteria developed in the Netherlands (Dutch ‘ABC’ Levels), which are most comprehensive and widely used for contaminated site assessment. The preliminary screening approach adopted in this study was based on the Dutch criteria which consist of 3 levels of guidelines, namely A, B, and C. The simplified explanation of the ABC levels is as follows:

- ‘A’ level implies unpolluted;
- ‘B’ level implies potential pollution present that requires further investigation or remediation; and
- ‘C’ level implies pollution which requires remediation.

4.3 The Dutch criteria are very stringent as they are developed based on a “good for all uses” philosophy. The EPD generally requires remediation for soil contamination above the Dutch B level. In other words, the Dutch B level is the cleanup target for remediation of soil. Relevant soil Dutch ‘ABC’ levels for this Study are presented in **Table 4.1**.

**Table 4.1 Dutch ABC Values for Relevant Soil Testing Parameters**

Parameter	Soil (mg/kg)		
	Dutch A	Dutch B	Dutch C
Total Petroleum Hydrocarbons (TPH) (as mineral oil)	100	1000	5000
Total PCBs	0.05	1	10

Note: Total PCBs = Sum of PCB 28, 52, 101, 118, 138, 153 and 180 (according to the New Dutch List).


## 5 ANALYTICAL RESULTS AND INTERPRETATION

5.1 A total of three soil samples were collected from the TR1 for laboratory analysis. Among these collected soil samples, no exceedance of TPH and/or PCBs for Dutch B levels was found at all samples. The laboratory results are given in **Appendix D**.

## 6 CONCLUSIONS AND RECOMMENDATIONS

- 6.1 According to the results of site investigation, no exceedance of Dutch B levels for TPH and PCBs was found in the three soil samples collected from the trial pit TR1. Potential land contamination due to the transformer is therefore not expected. Remediation for soil and groundwater would not be required and there are also no special requirements for handling of soil and groundwater at the subject site. Any construction works that would disturb the ground can be proceeded at the concerned area of the existing CLP secondary substation.

**FIGURE**



**LEGEND:**

	TR1 SAMPLING LOCATION
--	-----------------------

**MAUNSELL | AECOM**

Maunsell Environmental Management Consultants Ltd

CONTRACT NO. SS M333 REPROVISIONING OF DIAMOND HILL CREMATORIUM

**AS-BUILT SAMPLING LOCATION FOR THE EXISTING CLP SECONDARY SUBSTATION AT PHASE 1 AREA**

SCALE	A4 1:500	DATE	APR 2005
CHECK	CGLW	DRAWN	TCYL
JOB No.	S07904	DRAWING No.	1
		REV	-



---

---

**APPENDIX A**

**SAMPLING AND TESTING SCHEDULE  
PROPOSED IN THE SAMPLING AND  
ANALYSIS PLAN**

---

---

**Appendix A      Sampling and Testing Plan For the Existing CLP Secondary Substation**

Sampling Location	Sampling Method	Sample Matrix		Testing Parameter	Detection Limit or otherwise stated	Reference Method
TR1	Trial pit excavated down to 2m below concrete layer by means of hand tools	Soil	Immediately below the concrete layer	Total PCBs TPH	Total PCBs: 0.05 mg/kg	USEPA 8270
		Soil	1m below the concrete layer	Total PCBs TPH	TPH: C6-C9: 2 mg/kg C10-C14: 50 mg/kg C15-C28: 100 mg/kg C29-C36: 100 mg/kg	USEPA 8015
		Soil	2m below the concrete layer or the greatest depth achieved by trial pit	Total PCBs TPH		
		GW	If present	Total PCBs TPH	Total PCBs: 0.2 µg/L  TPH: C6-C9: 20 µg/L C10-C14: 25 µg/L C15-C28: 25 µg/L C29-C36: 25 µg/L	USEPA 8270  USEPA 8015

Remarks:

Total PCBs = Sum of PCB 28, 52, 101, 118, 138, 153 and 180 (according to the New Dutch List).

GW = Groundwater

---

---

**APPENDIX B**



**SOIL BORING LOG**

---

---

Excavation Dates: 15-03-2005 to 15-03-2005		Checked by: F. Lui	Date checked: 16-03-2005	Logged by: B. Liu	Date logged: 15-03-2005
Backfill Date: 21-03-2005					
Project: Ground Investigation Works for Contract No. SSIM333 Re-provisioning of Diamond Hill Crematorium at Po Kong Village Road, Kowloon.					
Co-ordinates: E 839429.75 N 822875.60 Ground Level: +76.28 mPD					
Sketch					
Sample & Tests	Depth (m)	Face A 1.10 m	Face B 1.00 m	Face C 1.10 m	Face D 1.00 m
	0.15	▽ 0.32	▽ 0.32	▽ 0.77	▽ 0.15
	1.00				
	2.00				
Description					
Grey, CONCRETE, with 5mm dia. steel reinforcement. (GROUND SLAB)					
Grey, CONCRETE.					
Soft, yellowish brown and reddish brown, sandy SILT, with some subangular to subrounded, medium to coarse gravel and cobbles of rock fragments, and occasional roots and nylon strings. (FILL)					
End of the trial pit at 2.00m in FILL.					

REMARKS
1. Shoring was used to stabilize the trial pit. 2. No groundwater was encountered. 3. 3 nos. of small disturbed samples were taken at depths 0.15m, 1.00m and 2.00m.



SYMBOL	
• Small disturbed sample ▭ Large disturbed sample ▭ Undisturbed vertical sample ▭ Undisturbed horizontal sample	□ Block sample ▭ In-situ density test ▭ Water sample ▭ Water seepage ▭ N - Schmidt Hammer Test

---



---

**APPENDIX C**


**PHOTOGRAPHIC RECORDS OF TR1**

---


---















---

---

**APPENDIX D**

**LABORATORY RESULTS**

---

---

**Result Summary of Soil Sampling for the Existing CLP Secondary Substation at Phase 1 Area**

Sampling ID	Depth of Sampling (m below ground)	Date of Sampling Date	Concentration of Testing Parameters (mg/kg)					
			C6-C9 Fraction	C10-C14 Fraction	C15-C28 Fraction	C29-C36 Fraction	Total TPH (Mineral Oil in Dutch List)	Total PCBs
	Dutch A		-	-	-	-	100	0.05
	<b>Dutch B</b>		-	-	-	-	<b>1000</b>	<b>1</b>
	<u>Dutch C</u>		-	-	-	-	<u>5000</u>	<u>10</u>
<b>TR1 (0m)</b>	0m	15-Mar-05	<2	<50	<100	<100	<252	<0.1
<b>TR1 (1m)</b>	1m	15-Mar-05	<2	<50	<100	<100	<252	<0.1
<b>TR1 (2m)</b>	2m	15-Mar-05	<2	<50	<100	<100	<252	<0.1

Notes:  
 Total PCBs = Sum of PCB 28, 52, 101, 118, 138, 153 and 180 (according to the New Dutch List).  
 No exceedance of Dutch B levels for total PCBs and TPH in all soil samples  
 Full analytical results should be referred to laboratory report



MAUNSELL ENV MGT CNLT LTD

Attention: MS CARY WAN  
 YourOrder: S07904-001  
 SampleType:SOIL  
 Project:

Page-no: 1  
 HONG KONG  
 Batch-no: 34625  
 Sub-batch:0  
 No-samples:3  
 Received: 15/03/05  
 Checked:

Method	Analysis description	Units	LOR	TR1/0.0M	TR1/1.0M	TR1/2.0M
				15/03/05	15/03/05	15/03/05
EA-055	Moisture Content (dried @ 103' %	%	0.1	13.8	13.3	14.8
EP-066-SS	TOTAL POLYCHLORINATED BIPHENYL	mg/kg	0.1	<0.1	<0.1	<0.1
EP-066S-SS	POLYCHLORINATED BIPHENYLS SURR					
EP-066S-SS	Tetrachloro-m-xylene	%	20	100	103	91
EP-066S-SS	Dibutylchloroendate	%	20	95	101	129

Samples analysed on an as received basis. Results reported on a dry weight basis. Sample preparation techniques: Semivolatile - Separatory Funnel and Tumbler, Volatile - Purge & Trap. Sample analysis techniques: Semivolatile components - GC/MS; TPH - GC/FID; Volatile components - GC/MS; Pesticides - GC/ECD, GC/MS. Refer to the attached

### ALS TECHNICHEM HK P/L

HONG KONG  
 Phone: (852) 2610 1044  
 Fax: (852) 2610 2021

BRISBANE  
 Phone: (61) 7-3243 7222  
 Fax: (61) 7-3243 7218

SYDNEY  
 Phone: (61) 2-8784 8335  
 Fax: (61) 2-8784 8300

MELBOURNE  
 Phone: (61) 3-9538 4444  
 Fax: (61) 3-9538 4400

NEWCASTLE  
 Phone: (61) 2-4968 9433  
 Fax: (61) 2-4968 0349



MAUNSELL ENV MGT CNLT LTD

Attention: MS CARY WAN  
 YourOrder: S07904-001  
 SampleType:QUALITY CONTROL  
 Project:

Page-no: 1  
 HONG KONG  
 Batch-no: 34625  
 Sub-batch:0  
 No-samples:3  
 Received: 15/03/05  
 Checked:

Method	Analysis description	Units	LOR	BLANK
EA-055	Moisture Content (dried @ 103' %		0.1	----
EP-066-SS	TOTAL POLYCHLORINATED BIPHENYL	mg/kg	0.1	<0.1
EP-066S-SS	POLYCHLORINATED BIPHENYLS SURR			
EP-066S-SS	Tetrachloro-m-xylene	%	20	98
EP-066S-SS	Dibutylchloredate	%	20	87

Results which appear on this report are routine laboratory checks for QUALITY CONTROL purposes.

### ALS TECHNICHEM HK P/L

HONG KONG  
 Phone: (852) 2610 1044  
 Fax: (852) 2610 2021

BRISBANE  
 Phone: (61) 7-3243 7222  
 Fax: (61) 7-3243 7218

SYDNEY  
 Phone: (61) 2-8784 8555  
 Fax: (61) 2-8784 8500

MELBOURNE  
 Phone: (61) 3-9538 4444  
 Fax: (61) 3-9538 4400

NEWCASTLE  
 Phone: (61) 2-4968 9433  
 Fax: (61) 2-4968 0349



MAUNSELL ENV MGT CNLT LTD

Attention: MS CARY WAN  
 YourOrder: S07904-001  
 SampleType:SOIL  
 Project:

Page-no: 1  
 HONG KONG  
 Batch-no: 34625  
 Sub-batch:1  
 No-samples:3  
 Received: 15/03/05  
 Checked:

Method	Analysis description	Units	LOR	TR1/0.0M	TR1/1.0M	TR1/2.0M
				15/03/05	15/03/05	15/03/05
EA-055	Moisture Content (dried @ 103' %		0.1	13.8	13.3	14.8
EP-071-SS	TOTAL PETROLEUM HYDROCARBONS					
EP-071-SS	C6 - C9 Fraction	mg/kg	2	<2	<2	<2
EP-071-SS	C10 - C14 Fraction	mg/kg	50	<50	<50	<50
EP-071-SS	C15 - C28 Fraction	mg/kg	100	<100	<100	<100
EP-071-SS	C29 - C36 Fraction	mg/kg	100	<100	<100	<100
EP-080-SS	BTEX					
EP-080S-SS	Dibromofluoromethane	%	2	106	98	114
EP-080S-SS	Toluene-d8	%	2	101	103	104
EP-080S-SS	4-BFB	%	2	103	104	105

Samples analysed on an as received basis. Results reported on a dry weight basis. Sample preparation techniques: Semivolatile - Separatory Funnel and Tumbler, Volatile - Purge & Trap. Sample analysis techniques: Semivolatile components - GC/MS; TPH - GC/FID; Volatile components - GC/MS; Pesticides - GC/ECD, GC/MS. Refer to the attached

### ALS TECHNICHEM HK P/L

HONG KONG  
 Phone: (852) 2610 1044  
 Fax: (852) 2610 2021

BRISBANE  
 Phone: (61) 7-3243 7222  
 Fax: (61) 7-3243 7218

SYDNEY  
 Phone: (61) 2-8784 8335  
 Fax: (61) 2-8784 8300

MELBOURNE  
 Phone: (61) 3-9538 4444  
 Fax: (61) 3-9538 4400

NEWCASTLE  
 Phone: (61) 2-4968 9433  
 Fax: (61) 2-4968 0349



MAUNSELL ENV MGT CNLT LTD

Attention: MS CARY WAN  
 YourOrder: S07904-001  
 SampleType:QUALITY CONTROL  
 Project:

Page-no: 1  
 HONG KONG  
 Batch-no: 34625  
 Sub-batch:1  
 No-samples:3  
 Received: 15/03/05  
 Checked:

Method	Analysis description	Units	LOR	BLANK
EA-055	Moisture Content (dried @ 103' %		0.1	----
EP-071-SS	TOTAL PETROLEUM HYDROCARBONS			
EP-071-SS	C6 - C9 Fraction	mg/kg	2	<2
EP-071-SS	C10 - C14 Fraction	mg/kg	50	<50
EP-071-SS	C15 - C28 Fraction	mg/kg	100	<100
EP-071-SS	C29 - C36 Fraction	mg/kg	100	<100
EP-080-SS	BTEX			
EP-080S-SS	Dibromofluoromethane	%	2	94
EP-080S-SS	Toluene-d8	%	2	102
EP-080S-SS	4-BFB	%	2	108

Results which appear on this report are routine laboratory checks for QUALITY CONTROL purposes.

### ALS TECHNICHEM HK P/L

HONG KONG  
 Phone: (852) 2610 1044  
 Fax: (852) 2610 2021

BRISBANE  
 Phone: (61) 7-3243 7222  
 Fax: (61) 7-3243 7218

SYDNEY  
 Phone: (61) 2-8784 8335  
 Fax: (61) 2-8784 8300

MELBOURNE  
 Phone: (61) 3-9538 4444  
 Fax: (61) 3-9538 4400

NEWCASTLE  
 Phone: (61) 2-4968 9433  
 Fax: (61) 2-4968 0349