



Ref.: HYDZHMBEEM00\_0\_7419L.19.doc

30 May 2019

By Fax (3468 2076) and By Post

AECOM Asia Co. Ltd.  
The PRE's Office  
550 Cheung Tung Road, Lantau  
Hong Kong

Attention: Mr. Simon Cheung

Dear Sir,

**Re: Agreement No. CE 48/2011 (EP)  
Environmental Project Office for the  
HZMB Hong Kong Link Road, HZMB Hong Kong Boundary Crossing  
Facilities, and Tuen Mun-Chek Lap Kok Link – Investigation**

**Contract No. HY/2013/01  
HZMB HKBCF – Passenger Clearance Building  
Quarterly EM&A Report No. 13 for September 2017 to November 2017**

Reference is made to the Environmental Team's submission of Quarterly EM&A Report No. 13 for September 2017 to November 2017 (Revision 4) certified by the ET Leader (ET's ref.: "5126871/19.10/OC122/KC/RL" dated 30 May 2019) and provided to us via e-mail on 30 May 2019.

We are pleased to inform you that we have no adverse comments on the captioned Quarterly EM&A Report for September 2017 to November 2017.

Thank you very much for your attention and please feel free to contact the undersigned should you require further information.

Yours faithfully,  
For and on behalf of  
Ramboll Hong Kong Limited

Ray Yan  
Independent Environmental Checker

c.c.	HyD	Mr. Cheng Pan	(By Fax: 3188 6614)
	HyD	Ms. Iris Ng	(By Fax: 3188 6614)
	Atkins	Mr. Keith Chau	(By Fax: 2890 6343)
	LCWJV	Mr. Owen Leung	(By Fax: 3621 0180)

Internal: DY, YH, DF, HW, ENPO Site

Your ref.  
Our ref. 5126871/19.10/OC122/KC/RL  
Date: 30 May 2019

**By Post and e-mail (Stephen.Tsang@lcwjb.com)**

Leighton – Chun Wo Joint Venture  
39/F Sun Hung Kai Centre  
30 Harbour Road  
Hong Kong

**Attn: Mr. Stephen Tsang**

Dear Mr. Tsang,

**Contract No. HY/2013/01  
Hong Kong – Zhuhai – Macao Bridge  
Hong Kong Boundary Crossing Facilities – Passenger Clearance Building  
Certification of Quarterly EM&A Report No. 13**

Atkins China Limited certifies, in the capacity of Environmental Team Leader, that Quarterly EM&A Report No. 13 (Revision 4) conforms the requirements provided in Condition 16.4 of the Environmental Monitoring and Audit Manual for HKBCF (Version 1.0).

**Yours faithfully,  
for and on behalf of  
Atkins China Limited**



**Keith Chau  
Environmental Team Leader**

**cc.**

1. AECOM – Mr. Malcolm Sage (By Fax.: 3468 2076)
2. IEC / ENPO – Mr. Ray Yan & Mr. Y.H. Hui (By Fax.: 3465 2899)

13F Wharf T&T Centre  
Harbour City  
Tsim Sha Tsui  
Kowloon Hong Kong  
 +852 2972 1000  
 +852 2890 6343  
 [info.hk@atkinsglobal.com](mailto:info.hk@atkinsglobal.com)

[atkinsglobal.com](http://atkinsglobal.com)  
[snclavalin.com](http://snclavalin.com)

**Contract No. HY/2013/01**

**Hong Kong-Zhuhai-Macao Bridge  
Hong Kong Boundary Crossing Facilities – Passenger Clearance  
Building**

**Quarterly EM&A Report No. 13  
(Covering the Period from 1 September 2017 to 30 November 2017)**

20 May 2019

Revision 4

**Main Contractor**



**Leighton - Chun Wo  
Joint Venture**

**Environmental Team**





## Contents

### Executive Summary

<b>1</b>	<b>Introduction .....</b>	<b>4</b>
1.1	Basic Project Information .....	4
1.2	Project Organisation .....	4
1.3	Construction Programme .....	4
1.4	Construction Works Undertaken During the Reporting Period .....	5
<b>2</b>	<b>EM&amp;A Requirement .....</b>	<b>6</b>
2.1	Summary of EM&A Requirements .....	6
2.2	Monitoring Requirements .....	10
2.3	Action and Limit Levels .....	10
2.4	Event Action Plans .....	12
2.5	Mitigation Measures .....	12
<b>3</b>	<b>Environmental Monitoring and Audit .....</b>	<b>13</b>
3.1	Air Quality Monitoring Results .....	13
3.2	Noise Monitoring Results .....	14
3.3	Water Quality Monitoring Results .....	15
3.4	Dolphins Monitoring Results .....	19
3.5	Implementation of Environmental Measures .....	26
3.6	Advice on the Solid and Liquid Waste Management Status .....	26
3.7	Environmental Licenses and Permits .....	26
<b>4</b>	<b>Summary of Exceedance, Complaint, Notification of Summons and Successful Prosecution .....</b>	<b>27</b>
4.1	Summary of Exceedance of the Environmental Quality Performance Limit .....	27
4.2	Summary of Complaints, Notification of Summons and Successful Prosecution .....	27
<b>5</b>	<b>Comments, Recommendations and Conclusion .....</b>	<b>29</b>
5.1	Comments .....	29
5.2	Recommendations .....	29
5.3	Conclusions .....	30



---

### **Figures**

- Figure 2.1 Location of Air Quality Monitoring Stations
- Figure 2.2 Location of Noise Monitoring Stations
- Figure 2.3 Location of Water Quality Monitoring Stations
- Figure 2.4 Impact Dolphins Monitoring Line Transect Layout Map

### **Appendices**

- Appendix A Location of Works Areas
- Appendix B Project Organization for Environmental Works
- Appendix C Construction Programme
- Appendix D Event and Action Plan
- Appendix E Implementation Schedule for Environmental Mitigation Measures (EMIS)
- Appendix F Graphical Plot (Air Quality, Noise and Water Quality)
- Appendix G Site Audit Findings and Corrective Actions
- Appendix H Waste Flow Table
- Appendix I Environmental Licenses and Permits
- Appendix J Statistics on Environmental Complaints, Notification of Summons and Successful Prosecutions
- Appendix K Investigation Report
- Appendix L Dolphin Monitoring Results

## Executive Summary

This Quarterly Environmental Monitoring and Audit (EM&A) Report is prepared for Contract HY/2013/01 Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing Facilities (HKBCF) – Passenger Clearance Building (hereafter referred to as “the Contract”) for the Highways Department of Hong Kong Special Administrative Region (HKSAR). The Contract was awarded to Leighton – Chun Wo Joint Venture (hereafter referred to as “the Contractor”) and Atkins China Limited was appointed as the Environmental Team (ET) by the Contractor.

The Contract is part of Hong Kong – Zhuhai – Macao Bridge HKBCF which is a “Designated Project”, under Schedule 2 of the Environmental Impact Assessment Ordinance (EIAO) (Cap 499) and Environmental Impact Assessment (EIA) Report (Register No. AEIAR-145/2009) was prepared for the Project. The current Environmental Permit (EP) No. EP-353/2009/K for HKBCF was issued on 11 April 2016. These documents are available through the EIA Ordinance Register. Site preparation works of the Contract started on 26 September 2014 and the construction works of the Contract commenced on 6 October 2014.

Atkins China Limited has been appointed by the Contractor to implement the Environmental Monitoring & Audit (EM&A) programme for the Contract in accordance with the Updated EM&A Manual for HKBCF (Version 1.0) and will be providing environmental team services to the Contract.

This is the thirteenth Quarterly EM&A Report for the Contract which summaries findings of the EM&A works during the reporting period from 1 September 2017 to 30 November 2017.

## Environmental Monitoring and Audit Progress

The EM&A programme was undertaken in accordance with the Updated EM&A Manual for HKBCF (Version 1.0). The air quality, noise, water quality and dolphin monitoring works under Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works were suspended from 1 September 2017. The ET of Contract No. HY/2013/01 is required and continues the same implementation of environmental monitoring commencing on 1 September 2017. It should be noted that the air quality monitoring station (AMS6) is covered by Contract No. HY/2011/03 Hong Kong-Zhuhai Macao Bridge Hong Kong Link Road – Section between Scenic Hill and HKBCF.

A summary of the monitoring activities during the reporting period are listed below:

Monitoring Items	Date		
	September 2017	October 2017	November 2017
1-hour TSP Monitoring	1, 4, 5, 8, 11, 14, 15, 20, 21, 26, 27 and 29	3, 4, 6, 10, 12, 16, 18, 20, 24, 26 and 30	1, 3, 7, 9, 13, 15, 17, 21, 23, 27 and 29
24-hour TSP Monitoring	1, 4, 7, 8, 13, 14, 19, 20, 25, 26, 28 and 30	3, 6, 9, 11, 13, 17, 19, 23, 25, 27 and 31	2, 6, 8, 10, 14, 16, 20, 22, 24, 28 and 30
Noise Monitoring	4, 6, 12, 14, 18, 20, 26 and 28	3, 4, 9, 10, 16, 18, 24, 26 and 30	1, 7, 9, 13, 15, 21, 23, 27 and 29
Water Quality Monitoring	1, 6, 8, 11, 13, 15, 18, 20, 22, 25, 27 and 29	2, 4, 6, 9, 11, 13, 16, 18, 20, 23, 25, 27 and 30	1, 3, 6, 8, 10, 13, 15, 17, 20, 22, 24, 27 and 29
Chinese White Dolphin Monitoring	5, 14, 21 and 25	6, 12, 17 and 19	6, 14, 23 and 28
Environmental Site Inspection	6, 13, 20 and 27	4, 11, 18 and 25	1, 8, 15, 22 and 29

## Breaches of Action and Limit Levels

A summary of environmental exceedances for the reporting period are listed below:

Environmental Monitoring	Parameters	Action Level (AL)			Limit Level (LL)		
		Sep 2017	Oct 2017	Nov 2017	Sep 2017	Oct 2017	Nov 2017
Air Quality	1-hr TSP	-	-	-	-	-	-
	24-hr TSP	-	-	1	-	-	-
Noise	Leq (30 min)	-	-	-	-	-	-
Water Quality	Suspended solids level (SS)	8	5	15	1	-	4
	Turbidity level	5	-	-	1	-	-
	Dissolved oxygen level (DO)	137	7	-	26	8	-
Dolphin Monitoring	Quarterly Analysis	-			1		
Total		178			41		

Based on the investigation results, all exceedances are found that not related to Contract No. HY/2013/01.

## Implementation of Environmental Measures

Site inspections were carried out on a weekly basis to monitor the implementation of proper environmental pollution control and mitigation measures for the Project. Potential environmental impacts due to the construction activities were monitored and reviewed.

## Complaint Log

There were two complaints received in relation to the environmental impact during the reporting period.

A summary of environmental complaints for the previous reporting period is as follows:

Environmental Complaint No.	Date of Complaint Received	Description of Environmental Complaints
009	27 October 2017	Water Quality
010	23 November 2017	Dust

### Complaint No.009

A complaint was received by EPD which regarding to the water quality at C3 area, the complaint was informed to the Environmental Team, Engineer's Representative and Contractor by ENPO's email on 27 October 2017.

Based on the investigation results, it is found that the complaint is not related to Contract No. HY/2013/01. No immediate mitigation measures are required as the complaint is not related to Contact No. HY/2013/01.

### Complaint No.010

A complaint was received by EPD regarding dust emission from HZMB construction site. Environmental Team was informed by ENPO on 23 November 2017.

The Water Spraying Plan, which include the information of watering schedule, routing of trucks of watering and the location of water filling, was prepared and submitted to RE and ENPO.

---

## Notifications of Summons and Successful Prosecutions

There was no notification of summon or prosecution received during this reporting period.

### Reporting Change

The ET of Contract No. HY/2013/01 implemented the environmental monitoring (air quality, noise, water quality and dolphin monitoring works for the entire HKBCF) since 1 September 2017. It should be noted that the air quality monitoring station (AMS6) is covered by Contract No. HY/2011/03 Hong Kong-Zhuhai-Macao Bridge Hong Kong Link Road – Section between Scenic Hill and HKBCF.

Air quality monitoring station-AMS3B, noise monitoring station-NMS3B and the meteorological station have been slightly re-located to AECOM PRE's Office since 1 September 2017.



## 1 Introduction

### 1.1 Basic Project Information

- 1.1.1 This Quarterly Environmental Monitoring and Audit (EM&A) Report is prepared for Contract HY/2013/01 Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing Facilities – Passenger Clearance Building (hereafter referred to as “the Contract”) for the Highways Department of Hong Kong Special Administrative Region. The Contract was awarded to Leighton – Chun Wo Joint Venture (hereafter referred to as “the Contractor”) and Atkins China Limited was appointed as the Environmental Team (ET) by the Contractor.
- 1.1.2 The Contract is part of Hong Kong – Zhuhai – Macao Bridge Hong Kong Boundary Crossing Facilities (HKBCF) which is a “Designated Project”, under Schedule 2 of the Environmental Impact Assessment Ordinance (EIAO) (Cap 499). An Environmental Impact Assessment (EIA) Report (Register No. AEIAR-145/2009) was prepared for the Project. The current Environmental Permit (EP) No. EP-353/2009/K for HKBCF was issued on 11 April 2016. These documents are available through the EIA Ordinance Register. Site preparation work of the Contract started on 26 September 2014 and the construction works of the Contract commenced on 6 October 2014. The works areas of the Contract are shown in **Appendix A**.
- 1.1.3 This is the thirteenth Quarterly EM&A Report for the Contract which summarizes the audit findings of the EM&A programme during the reporting period from 1 September 2017 to 30 November 2017.

### 1.2 Project Organisation

- 1.2.1 The project organization structure and lines of communication with respect to the on-site environmental management structure is shown in **Appendix B**. The key personnel contact names and numbers are summarized in **Table 1.1**.

**Table 1.1 Contact Information of Key Personnel**

Party	Position	Name	Telephone	Fax
Engineer or Engineer's Representative (AECOM Asia Co. Ltd.)	Chief Resident Engineer	Michael Tovey	3958 7339	3468 2076
Environmental Project Office / Independent Environmental Checker (Ramboll Environ Hong Kong Limited)	Environmental Project Office Leader	Y. H. Hui	3465 2888	3465 2899
	Independent Environmental Checker	Raymond Dai	3465 2888	3465 2899
Contractor (Leighton – Chun Wo Joint Venture)	Project Manager	Owen Leung	9232 5750	3621 0180
	Environmental Officer	Michael Lee	6461 8635	3621 0180
Environmental Team (Atkins China Limited)	Environmental Team Leader	Keith Chau	2972 1721	2890 6343
24 hours complaint hotline	---	---	3958 7300	---

### 1.3 Construction Programme

- 1.3.1 A copy of the Contractor’s construction programme is provided in **Appendix C**.

## 1.4 Construction Works Undertaken During the Reporting Period

1.4.1 A summary of the construction activities undertaken during this reporting period is shown below:

### *Land-Based Work*

- Waterproofing
- Backfilling
- Formwork and falsework stripping
- Western vertical column
- Blockwork walls
- Pipework and ductwork installation
- Hanger rods for cable container
- Wet trade works
- Dry trade works
- Facade Bracket for Cabins
- Mechanical, Electrical and Plumbing (MEP) High Level Containment
- Removal of Temporary Works
- Window wall glazing
- Heat exchanger installation
- Heavy MEP plant set up in basement
- Double Bow Truss installation
- Mullion Frame installation
- Curtain wall glazing
- Hanging scaffolding
- Hanging scaffolding removal
- Footbridge construction
- Roof cladding
- Refuse collection point
- Southern toilet
- Miscellaneous steelwork
- Lift installation
- Escalator installation
- Glazed lift installation
- Road and Kerbing
- Testing and commissioning works
- Water features and planters

### *Marine Based work*

- Seawater intake seawall reinstatement
- Seawater outfall pipe laying
- Localized silt curtain deployment at jetty
- Localized silt curtain removal at seawater intake and box culvert
- Temporary jetty dismantling

## 2 EM&A Requirement

### 2.1 Summary of EM&A Requirements

- 2.1.1 The EM&A programme was undertaken in accordance with the Updated EM&A Manual for HKBCF (Version 1). The air quality, noise, water quality and dolphin monitoring works under Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works were suspended from 1 September 2017. The ET of Contract No. HY/2013/01 is required and continues the same implementation of environmental monitoring commencing on 1 September 2017. It should be noted that the air quality monitoring station (AMS 6) is covered by Contract No. HY/2011/03 Hong Kong-Zhuhai Macao Bridge Hong Kong Link Road – Section between Scenic Hill and HKBCF.
- 2.1.2 The permission to carry out impact air quality monitoring work at AMS7 (Hong Kong SkyCity Marriott Hotel) was not granted after 31 January 2015. The impact air quality monitoring location (AMS7) was relocated to a nearby air sensitive receiver, Chu Kong Air-Sea Union Transportation Co. Ltd. (AMS7A), from 5 February 2015 to 30 December 2015. The alternative location at Chu Kong Air-Sea Union Transportation Co. Ltd. was approved by EPD on 5 February 2015. However, AMS7A was relocated back to its original location (AMS7-Hong Kong SkyCity Marriott Hotel) on 30 December 2015. The relocation of air quality monitoring location, AMS7A, back to AMS7 was approved by EPD on 21 December 2015. The baseline and action/limit level for air quality as derived from the baseline monitoring data recorded at Hong Kong SkyCity Marriott Hotel (AMS7) was adopted for the air quality monitoring location.
- 2.1.3 A summary of air and noise monitoring locations are presented in **Table 2.1**. The location of air quality and noise monitoring stations are shown as in **Figure 2.1** and **Figure 2.2**, respectively.

**Table 2.1 Summary of Impact EM&A Requirements**

Environmental Monitoring	ID	Location Description
Air Quality	AMS2 <sup>(1)</sup>	Tung Chung Development Pier
	AMS3B <sup>(1)</sup>	Site Boundary of Site Office Area at Work Area WA2
	AMS6 <sup>(1)</sup>	Dragonair/CNAC (Group) Building
	AMS7 <sup>(1)(2)</sup>	Hong Kong SkyCity Marriott Hotel
Noise	NMS2 <sup>(3)</sup>	Seaview Crescent
	NMS3B <sup>(3)(4)</sup>	Site Boundary of Site Office Area at Works Area WA2

Remarks:

- (1) The ET of this Contract should conduct impact air quality monitoring at the Air Monitoring Station listed in the table as part of EM&A programme according to the latest notification from ENPO when the monitoring station(s) is/are no longer covered by another ET of the HZMB project.
- (2) The original monitoring location was at Hong Kong SkyCity Marriott Hotel (AMS7). As the permission to carry out air quality monitoring at Hong Kong SkyCity Marriott Hotel was not granted after 31 January 2015, the monitoring location was relocated to Chu Kong Air-Sea Union Transportation Co. Ltd. (AMS7A) from 5 February 2015 to 30 December 2015. The alternative monitoring location at Chu Kong Air-Sea Union Transportation Co. Ltd. was approved by EPD on 5 February 2015. However, AMS7A was relocated back to its original location (AMS7-Hong Kong SkyCity Marriott Hotel) on 30 December 2015. The relocation of air quality monitoring location, AMS7A, back to AMS7 was approved by EPD on 21 December 2015.
- (3) The ET of this Contract should conduct impact noise monitoring at the NMS listed in the table as part of EM&A programme according to the latest notification from ENPO when the monitoring station(s) is/are no longer covered by another ET of the HZMB project.
- (4) The Action and Limit Levels for schools will be applied for this alternative monitoring location.

- 2.1.4 The water quality works under Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works were suspended from 1 September 2017. The ET of Contract No. HY/2013/01 is required and continues the same implementation of environmental monitoring commencing on 1 September 2017. A total of twenty-one stations (nine Impact Stations (IS),

seven Sensitive Receiver Stations (SR) and five Control/Far Field Stations (CS)) are covered by the current EM&A programme.

2.1.5 The water quality monitoring stations at CS(Mf)3 (Coordinate: 809989E, 821117N), IS10 (Coordinate: 812577E, 820670N) and SR5 (811489E, 820455N) have been occupied by the marine work of a designated project - Expansion of Hong Kong International Airport into a Three-Runway System (3RS Project). The alternative water quality monitoring station at CS(Mf)3(N) (Coordinate: 808814E, 822355N), IS10(N) (Coordinate: 812942E, 820881N) and SR5(N) (812569E, 8201475N) were justified and verified by the ET Leader for Contract No. HY/2010/02 and the IEC respectively on 24 March 2017 and it was approved by EPD on 12 May 2017.

2.1.6 **Table 2.2** and **Figure 2.3** show the locations of water quality monitoring stations.

**Table 2.2 Impact Water Quality Monitoring Stations**

Station	Description	East	North
IS5	Impact Station (Close to HKBCF construction site)	811579	817106
IS(Mf)6	Impact Station (Close to HKBCF construction site)	812101	817873
IS7	Impact Station (Close to HKBCF construction site)	812244	818777
IS8	Impact Station (Close to HKBCF construction site)	814251	818412
IS(Mf)9	Impact Station (Close to HKBCF construction site)	813273	818850
IS10	Impact Station (Close to HKBCF construction site)	812577	820670
IS10(N)*	Impact Station (Close to HKBCF construction site)	812942	820881
IS(Mf)11	Impact Station (Close to HKBCF construction site)	813562	820716
IS(Mf)16	Impact Station (Close to HKBCF construction site)	814328	819497
IS17	Impact Station (Close to HKBCF construction site)	814539	820391
SR3^	Sensitive receivers (San Tau SSSI)	810525	816456
SR4(N)	Sensitive receivers (Tai Ho)	814705	817859
SR5	Sensitive receivers (Artificial Reef in NE Airport)	811489	820455
SR5(N)*	Sensitive receiver (Artificial Reef in NE Airport)	812569	821475
SR6	Sensitive receivers (Sha Chau and Lung Kwu Chau Marine Park)	805837	821818
SR7	Sensitive receivers (Tai Mo Do)	814293	821431
SR10A^	Sensitive receivers (Ma Wan FCZ) 1	823741	823495
SR10B(N)^	Sensitive receivers (Ma Wan FCZ) 2	823683	823187
CS(Mf)3	Control Station	809989	821117
CS(Mf)3(N)*	Control Station	808814	822355
CS(Mf)5	Control Station	817990	821129
CS4	Control Station	810025	824004
CS6	Control Station	817028	823992

CSA	Control Station	818103	823064
-----	-----------------	--------	--------

Remarks:

\* Alternative water quality monitoring stations at CS(Mf)3(N), SR5(N) and IS10(N) were justified and verified by the ET Leader for Contract No. HY/2010/02 and the IEC respectively on 24 March 2017 and it was approved by EPD on 12 May 2017.

^ Water sampling team reported that the monitoring stations at SR3, SR10A and SR10B(N) were not available for water sampling due to safety reason, thus, monitoring stations were changed to tentative coordination (i.e. SR3(N): E810689 N816591; SR10A(N): E823644 N823484 and SR10B(N2): E823689 N823159).

- 2.1.7 The dolphin monitoring works under Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works were suspended from 1 September 2017. The ET of Contract No. HY/2013/01 is required to conduct dolphin monitoring at the twenty-four transects.
- 2.1.8 The dolphin monitoring should adopt line-transect vessel survey method. The survey follows pre-set and fixed transect lines in the two areas defined by AFCD as: Northeast Lantau survey area; and Northwest Lantau survey area. The change of transect lines 2, 3, 4, 5, 6 and 7 and new vessel-based transect line 24 for dolphin monitoring have been proposed due to the marine work of a designated project - Expansion of Hong Kong International Airport into a Three-Runway System (3RS Project). It was justified and verified by the ET Leader for Contract No. HY/2010/02 and the IEC respectively on 24 March 2017 and it was approved by EPD on 12 May 2017.
- 2.1.9 The co-ordinates for the transect lines showing the transect lines have been obtained from AFCD and are shown in **Table 2.3** and **Figure 2.4** shows the layout map.

**Table 2.3 Impact Dolphin Monitoring Line Transect Co-ordinates**

Transect ID	HK Grid System	
	East	North
1*	804671	815456
	804671	831404
2	805476	820800
	805476	826654
3	806464	821150
	806464	822911
4	807518	821500
	807518	829230
5	808504	821850
	808504	828602
6	809490	822150
	809490	825352
7	810499	822000
	810499	824613
8*	811508	821123
	811508	824254
9*	812516	821303
	812516	824254
10*	813525	820827
	813525	824657
11#	814556	818853
	814556	820992
12	815542	818807
	815542	824882
13	816506	819480
	816506	824859
14	817537	820220
	817537	824613
15	818568	820735
	818568	824433
16	819532	821420
	819532	824209
17	820451	822125
	820451	823671



18	821504	822371
	821504	823761
19	822513	823268
	822513	824321
20	823477	823402
	823477	824613
21	805476	827081
	805476	830562
22	806464	824033
	806464	829598
23	814559	821739
	814559	824768
24	805476	815900
	805476	819100

Remarks:

- (a) \* Due to the presence of deployed silt curtain systems at the site boundaries of the Contract, some of the transect lines shown in Figure 5.1 could not be fully surveyed during the regular survey. Transect 10 is reduced from 6.4km to approximately 3.6km in length due to the HKBCF construction site. Therefore the total transect length for both NEL and NWL combined is reduced to approximately 108km
- (b) # Coordinates for transect lines 1, 8, 9 and 11 have been updated in respect to the Proposal for Alteration of Transect Line for Dolphin Monitoring approved by EPD on 19 August 2015.
- (c) The change of transect lines 2, 3, 4, 5, 6 and 7 and new vessel-based transect line 24 for dolphin monitoring have been proposed due to the marine work of a designated project-Expansion of Hong Kong International Airport into a Three-Runway System (3RS Project). It was justified and verified by the ET Leader for Contract No. HY/2010/02 and the IEC respectively on 24 March 2017 and it was approved by EPD on 12 May 2017.
- (d) Due to marine work of the Expansion of Hong Kong International Airport into a Three-Runway System (3RS Project), original transect lines of dolphin monitoring 2, 3, 4, 5, 6 and 7 are enclosed by works boundary of 3RS Project. Alternative dolphin monitoring transect lines 2, 3, 4, 5, 6, 7 and 24 are adopted starting from 17 May 2017 to replace the original transect lines.

## 2.2 Monitoring Requirements

- 2.2.1 The monitoring requirements, monitoring equipment, monitoring parameters, frequency and duration, monitoring methodology, monitoring schedule, meteorological information is detailed in the monthly EM&A Reports for Contract No. HY/2013/01.

## 2.3 Action and Limit Levels

- 2.3.1 The Action and Limit Level for 1-hr TSP and 24-hr TSP are provided in **Table 2.4** and **Table 2.5**, respectively.

**Table 2.4 Action and Limit Levels for 1-hour TSP**

Monitoring Station	Action Level, $\mu\text{g}/\text{m}^3$	Limit Level, $\mu\text{g}/\text{m}^3$
AMS2 – Tung Chung Development Pier	374	500
AMS3B - Site Boundary of Site Office at Work Area WA2	368	
AMS6 – Dragonair/CNAC (Group) Building (HKIA)	360	
AMS7 – Hong Kong SkyCity Marriott Hotel	370	

**Table 2.5 Action and Limit Levels for 24-hour TSP**

Monitoring Station	Action Level, $\mu\text{g}/\text{m}^3$	Limit Level, $\mu\text{g}/\text{m}^3$
AMS2 – Tung Chung Development Pier	176	260
AMS3B - Site Boundary of Site Office at Work Area WA2	167	
AMS6 – Dragonair/CNAC (Group) Building (HKIA)	173	
AMS7 – Hong Kong SkyCity Marriott Hotel	183	

- 2.3.2 The Action and Limit Levels for construction noise are defined in **Table 2.6**.

**Table 2.6 Action and Limit Level for Construction Noise**

Parameter	Action Level	Limit Level
07:00 – 19:00 hours on normal weekdays	When one documented complaint is received	75/70/65 dB(A)*

Notes :

If works are to be carried out during restricted hours, the conditions stipulated in the construction noise permit issued by the Noise Control Authority have to be followed.

\* Reduce to 70 dB(A) for schools and 65 dB(A) during school examination period. The Action and limit Levels for schools will be applied for NMS3B. Daytime noise Limit Level of 70 dB(A) applies to education institutions, while 65 dB(A) applies during the school examination period.

- 2.3.3 The Action and Limit Levels for water quality are provided in **Table 2.7**.

**Table 2.7 Action and Limit Levels for Water Quality**

Parameters	Action	Limit
DO in mg L <sup>-1</sup> (Surface, Middle & Bottom)	Surface and Middle 5.0 Bottom 4.7	Surface and Middle 4.2 (except 5 mg/L for FCZ) Bottom 3.6
SS in mg L <sup>-1</sup> (depth-averaged) at all monitoring stations and control stations	23.5 and 120% of upstream control station's SS at the same tide of the same day*	34.4 and 130% of upstream control station's SS at the same tide of the same day and 10mg/L for WSD Seawater intakes*
Turbidity in NTU (depth-averaged)	27.5 and 120% of upstream control station's turbidity at the same tide of the same day*	47.0 and 130% of upstream control station's turbidity at the same tide of the same day*

\* Remarks: Reference is made to EPD approval of adjustment of water quality assessment criteria issued and became effective on 18 February 2013.

- Notes:
1. "depth-averaged" is calculated by taking the arithmetic means of reading of all three depths.
  2. For DO, non-compliance of the water quality limits occurs when monitoring result is lower than the limits.
  3. For turbidity, SS, non-compliance of the water quality limits occurs when monitoring result is higher than the limits.
  4. All the figures given in the table are used for reference only and the EPD may amend the figures whenever it is considered as necessary.
  5. The 1%-ile of baseline data for dissolved oxygen (surface and middle) and dissolved oxygen (bottom) are 4.2 mg/L and 3.6 mg/L respectively.

2.3.4 The Action and Limit Levels for Chinese White Dolphin Monitoring are provided in **Table 2.8** and **Table 2.9**, respectively.

**Table 2.8 Action and Limit Levels for Chinese White Dolphin Monitoring - Approach to Define Action Level (AL) and Limit Level (LL)**

	North Lantau Social Cluster	
	NEL	NWL
Action Level	(STG < 70% of baseline) & (ANI < 70% of baseline)	(STG < 70% of baseline) & (ANI < 70% of baseline)
Limit Level	[(STG < 40% of baseline) & (ANI < 40% of baseline)] AND [ (STG < 40% of baseline) & (ANI < 40% of baseline)]	



**Table 2.9 Derived Value of Action Level (AL) and Limit Level (LL) for Chinese White Dolphin Monitoring**

	North Lantau Social Cluster	
	NEL	NWL
Action Level	(STG < 4.2) & (ANI < 15.5)	(STG < 6.9) & (ANI < 31.3)
Limit Level	[(STG < 2.4) & (ANI < 8.9)] AND [(STG < 3.9) & (ANI < 17.9)]	

## 2.4 Event Action Plans

- 2.4.1 The Event Actions Plans for air quality, noise, water quality and dolphin monitoring are provided in **Appendix D**.

## 2.5 Mitigation Measures

- 2.5.1 Environmental mitigation measures for the Contract were recommended in the approved EIA Report. **Appendix E** lists the recommended mitigation measures and the implementation status.

### 3 Environmental Monitoring and Audit

#### 3.1 Air Quality Monitoring Results

- 3.1.1 In accordance with the Contract Specific EM&A Manual, impact 1-hour Total Suspended Particulates (TSP) monitoring was conducted for at least three times every 6 days, while impact 24-hour TSP monitoring was carried out for at least once every 6 days at the 4 monitoring stations (AMS2, AMS3B, AMS6 and AMS7).
- 3.1.2 The weather was sunny and hot, with occasional cloudy in the reporting period. Construction works during the quarterly period are shown in Section 1.4.1. The major dust source in the reporting period included construction activities from the Project, as well as traffic emission. No specific trend of the monitoring results or existence of persistent pollution source was noted.
- 3.1.3 Summary of Action and Limit Level exceedance of 1-hr TSP level and 24-hr TSP level at AMS6 shall be referred to the monthly EM&A Reports (for September to November 2017) prepared by Contract No. HY/2011/03.
- 3.1.4 The graphical plots of the monitoring results are presented in **Appendix F**.
- 3.1.5 The number of exceedances recorded during the reporting period are presented in the **Table 3.1**. The monitoring results for 1-hour and 24-hour are summarized in **Table 3.2** and **Table 3.3** respectively.

**Table 3.1 Summary of number of exceedances for 1-hr and 24-hr TSP Monitoring**

Monitoring Station	September 2017		October 2017		November 2017	
	Action Level	Limit Level	Action Level	Limit Level	Action Level	Limit Level
AMS2	-	-	-	-	-	-
AMS3B	-	-	-	-	-	1 (24-hr TSP)
AMS7	-	-	-	-	-	-

**Table 3.2 Summary of 1-hour TSP Monitoring Results Obtained During the Reporting Period**

Reporting month	Monitoring Station	Average ( $\mu\text{g}/\text{m}^3$ )	Range ( $\mu\text{g}/\text{m}^3$ )	Action Level ( $\mu\text{g}/\text{m}^3$ )	Limit Level ( $\mu\text{g}/\text{m}^3$ )
September 2017	AMS2	28	15 - 52	374	500
	AMS3B	15	3 - 31	368	
	AMS7	55	8 - 160	370	
October 2017	AMS2	45	26 - 92	374	500
	AMS3B	35	16 - 58	368	
	AMS7	46	29 - 102	370	
November 2017	AMS2	122	14 - 312	374	500
	AMS3B	34	12 - 87	368	
	AMS7	47	21 - 106	370	

**Table 3.3 Summary of 24-hour TSP Monitoring Results Obtained During the Reporting Period**

Reporting month	Monitoring Station	Average ( $\mu\text{g}/\text{m}^3$ )	Range ( $\mu\text{g}/\text{m}^3$ )	Action Level ( $\mu\text{g}/\text{m}^3$ )	Limit Level ( $\mu\text{g}/\text{m}^3$ )
September 2017	AMS2	40	20 - 65	176	260
	AMS3B	47	27 - 68	167	
	AMS7	50	26 - 90	183	
October 2017	AMS2	75	27 - 107	176	260
	AMS3B	79	36 - 119	167	
	AMS7	91	42 - 120	183	
November 2017	AMS2	109	52 - 150	176	260
	AMS3B	108	57 - 168	167	
	AMS7	83	54 - 118	183	

- 3.1.6 No Action and Limit Level exceedances of 1-hour TSP were recorded at AMS2, AMS3B and AMS7 during the reporting period.
- 3.1.7 No Action and Limit Level exceedances of 24-hour TSP were recorded at AMS2 and AMS7 during the reporting period.
- 3.1.8 One Action Level and no Limit Level exceedance of 24-hour TSP was recorded at AMS3B during the reporting period. For detail of investigation, please refer to **Appendix K**.

## 3.2 Noise Monitoring Results

- 3.2.1 In accordance with the Contract Specific EM&A Manual, impact noise monitoring was conducted for at least once per week during the construction phase of the Contract. The graphical plots of the monitoring results are presented in **Appendix F**. No specific trend of the monitoring results or existence of persistent pollution source was noted.
- 3.2.2 The number of exceedances recorded during the reporting period are presented in the **Table 3.4**. The monitoring results for noise are summarized in **Table 3.5**.

**Table 3.4 Summary of number of exceedances for Impact Noise Monitoring**

Monitoring Station	September 2017		October 2017		November 2017	
	Action Level	Limit Level	Action Level	Limit Level	Action Level	Limit Level
NMS2	-	-	-	-	-	-
NMS3B(*)	-	-	-	-	-	-

Remark (\*): Daytime noise Limit Level of 70 dB(A) applies to education institutions, while 65 dB(A) applies during the school examination period. The examination period of Ho Yu College was 2 – 15 November 2017, the Limit Level of 65 dB(A) was applied.

**Table 3.5 Summary of Noise Monitoring Result Obtained During Reporting Period**

Reporting month	Monitoring Station	Average, dB(A) L <sub>eq</sub> (30 mins)	Range, dB(A) L <sub>eq</sub> (30 mins)	Limit Level, dB(A) L <sub>eq</sub> (30 mins)
September 2017	NMS2	66	63 - 67	75
	NMS3B(*)	65	63 - 66	70/65
October 2017	NMS2	65	64 - 66	75
	NMS3B(*)	66	65 - 67	70/65
November 2017	NMS2	65	65 - 66	75
	NMS3B(*)	66	65 - 68	70/65

- 3.2.3 No Action and Limit Level exceedances of Noise monitoring were recorded at NMS2 and NMS3B during the reporting period.
- 3.2.4 The measured noise level was 67.5 dB(A) on 7 November 2017 at Station NMS3B, which exceeded the noise level of 65dB(A) during examination period and it was higher than the baseline level of 66.3 dB(A). Therefore, baseline correction was carried out and the corrected noise level which solely represent the noise level of Construction works are 61.3 dB(A) and no exceedance after correction. As such the Event and Action Plan was not triggered.
- 3.2.5 The measured noise level was 66.4 dB(A) on 13 November 2017 at Station NMS3B, which exceeded the noise level of 65dB(A) during examination period and it was higher than the baseline level of 66.3 dB(A). Therefore, baseline correction was carried out and the corrected noise level which solely represent the noise level of Construction works are 50.0 dB(A) and no exceedance after correction. As such the Event and Action Plan was not triggered.

### 3.3 Water Quality Monitoring Results

- 3.3.1 Impact water quality monitoring was carried out to ensure that any deterioration of water quality was detected, and that timely action was taken to rectify the situation. For impact water quality monitoring, measurement was taken in accordance with the Contract Specific EM&A Manual.
- 3.3.2 The graphical plots of the monitoring results are presented in **Appendix F**.
- 3.3.3 For impact water quality monitoring, number of exceedances recorded for reporting period at each impact station are summarised in **Table 3.6**.

**Table 3.6 Summary of Water Quality Exceedances**

Station	Exceedance Level	DO (S&M)		DO (Bottom)		Turbidity		SS	
		Ebb	Flood	Ebb	Flood	Ebb	Flood	Ebb	Flood
IS5	Action Level		2017-09-08	2017-09-01; 2017-09-13; 2017-09-18	2017-09-01; 2017-09-13; 2017-09-29	2017-09-08		2017-09-08	
	Limit Level								
IS(Mf)6	Action Level								2017-11-06; 2017-11-15
	Limit								



Station	Exceedance Level	DO (S&M)		DO (Bottom)		Turbidity		SS	
		Ebb	Flood	Ebb	Flood	Ebb	Flood	Ebb	Flood
	Level								
IS7	Action Level	2017-09-08		2017-09-08; 2017-09-29					
	Limit Level								
IS8	Action Level		2017-09-08; 2017-09-11; 2017-09-22	2017-09-29	2017-09-11				2017-09-06; 2017-09-18; 2017-09-25; 2017-11-13; 2017-11-24
	Limit Level						2017-09-15		
IS(Mf)9	Action Level		2017-09-08; 2017-09-11; 2017-09-22		2017-09-13				
	Limit Level								
IS10(N)	Action Level	2017-09-08; 2017-09-11; 2017-09-13; 2017-09-22; 2017-09-29	2017-09-08; 2017-09-11; 2017-09-22	2017-09-01; 2017-09-15; 2017-09-18; 2017-09-22; 2017-09-27; 2017-09-29	2017-09-01; 2017-09-11; 2017-09-15; 2017-09-29			2017-09-08	
	Limit Level								2017-09-08
IS(Mf)11	Action Level	2017-09-11; 2017-09-15; 2017-09-22	2017-09-08; 2017-09-11; 2017-09-13; 2017-09-15; 2017-09-22	2017-09-01; 2017-09-11; 2017-09-18; 2017-09-29	2017-09-01; 2017-09-08; 2017-09-11; 2017-09-29		2017-09-06; 2017-09-08		2017-09-08; 2017-10-20; 2017-11-03; 2017-11-08
	Limit Level								
IS(Mf)16	Action Level	2017-09-08	2017-09-08; 2017-09-11; 2017-09-22	2017-09-08; 2017-09-11; 2017-09-13; 2017-09-29	2017-09-11; 2017-09-13				2017-11-06
	Limit Level								
IS17	Action Level	2017-09-08; 2017-09-11; 2017-09-15	2017-09-08; 2017-09-11; 2017-09-13; 2017-09-22	2017-09-01; 2017-09-06; 2017-09-08; 2017-09-11; 2017-09-13; 2017-09-15; 2017-09-27	2017-09-08; 2017-09-11; 2017-09-13; 2017-09-29				
	Limit Level								



Station	Exceedance Level	DO (S&M)		DO (Bottom)		Turbidity		SS	
		Ebb	Flood	Ebb	Flood	Ebb	Flood	Ebb	Flood
SR3 <sup>A</sup>	Action Level	2017-09-08; 2017-09-22	2017-09-08						
	Limit Level								
SR4(N)	Action Level		2017-09-08; 2017-09-11; 2017-09-22						2017-09-06
	Limit Level								2017-11-08
SR5(N)	Action Level	2017-09-11; 2017-09-13; 2017-09-22	2017-09-08; 2017-09-11; 2017-09-22	2017-09-01; 2017-09-11; 2017-09-27; 2017-09-29	2017-09-11; 2017-09-29				2017-10-18; 2017-10-20; 2017-10-23
	Limit Level								2017-11-03; 2017-11-08
SR6	Action Level	2017-09-08; 2017-09-11; 2017-09-18; 2017-09-22	2017-09-06; 2017-09-08; 2017-09-11; 2017-09-15; 2017-09-18; 2017-09-20; 2017-09-22	2017-09-18	2017-09-11; 2017-09-15; 2017-09-18; 2017-09-20		2017-09-08	2017-11-03; 2017-11-08; 2017-11-22	2017-09-06; 2017-09-20
	Limit Level								2017-11-22
SR7	Action Level	2017-09-11	2017-09-08; 2017-09-11; 2017-09-22						2017-10-20; 2017-11-03; 2017-11-06; 2017-11-20
	Limit Level								
SR10A <sup>A</sup>	Action Level			2017-10-02; 2017-10-04	2017-09-06; 2017-09-08; 2017-09-11; 2017-09-13; 2017-09-15; 2017-09-20; 2017-09-27; 2017-10-02; 2017-10-04				2017-11-06
	Limit Level	2017-09-06; 2017-09-08; 2017-09-13; 2017-09-22; 2017-10-04	2017-09-06; 2017-09-08; 2017-09-11; 2017-09-13; 2017-09-15; 2017-09-18; 2017-09-20; 2017-09-22; 2017-10-04						
SR10B (N) <sup>A</sup>	Action Level			2017-09-11; 2017-09-27; 2017-09-29	2017-09-06; 2017-09-11; 2017-09-13; 2017-09-15; 2017-09-22; 2017-09-25;				2017-11-06

Station	Exceedance Level	DO (S&M)		DO (Bottom)		Turbidity		SS	
		Ebb	Flood	Ebb	Flood	Ebb	Flood	Ebb	Flood
					2017-09-27; 2017-10-02; 2017-10-04; 2017-10-06				
	Limit Level	2017-09-06; 2017-09-08; 2017-09-11; 2017-09-22; 2017-10-04; 2017-10-06	2017-09-06; 2017-09-08; 2017-09-11; 2017-09-13; 2017-09-15; 2017-09-18; 2017-09-20; 2017-09-22; 2017-09-25; 2017-09-27; 2017-10-02; 2017-10-04; 2017-10-06; 2017-10-09						
Total	Action Level	23	39	38	44	1	4	4	24
		177							
	Limit Level	11	23	0	0	0	1	0	5
		40							

Remark:

^ Water sampling team reported that the monitoring stations at SR3, SR10A and SR10B(N) were not available for water sampling due to safety reason, thus, monitoring stations were changed to tentative coordination (i.e. SR3(N): E810689 N816591; SR10A(N): E823644 N823484 and SR10B(N2): E823689 N823159).

- 3.3.4 There were 61 Action Level exceedances of dissolved oxygen were recorded at mid-ebb tide while 83 Action Level exceedances of dissolved oxygen were recorded at mid-flood tide. 11 Limit Level exceedances of dissolved oxygen were recorded at mid-ebb tide while 23 Limit Level exceedances of dissolved oxygen were recorded at mid-flood tide.
- 3.3.5 An Action Level exceedance of turbidity was recorded at mid-ebb tide while 4 Action Level exceedances of turbidity were recorded at mid-flood tide. No Limit Level exceedance of turbidity was recorded at ebb tide while 1 Limit Level exceedance of turbidity was recorded at flood tide.
- 3.3.6 4 Action Level exceedances of suspended solid were recorded at mid-ebb tide while 24 Action Level exceedances of suspended solid were recorded at mid-flood tide. No Limit Level exceedances of suspended solid were recorded at mid-ebb tide while 5 Limit Level exceedances of suspended solid were recorded mid-flood tide.
- 3.3.7 As confirmed by the Contractor, no marine transportation and marine-based work was conducted when water quality monitoring was conducted in September, October and November 2017. Therefore, it is concluded that the exceedances were not related the Contract. The detailed investigation results of these exceedances recorded are shown in **Appendix K**.
- 3.3.8 The weather was mostly fine and hot, with occasional showers, with abundant sunshine, temperatures stays high degrees during September 2017.
- 3.3.9 Temperature was one of essential factor to dissolved oxygen, based on past weather summary report from Hong Kong Observatory, there were more 22 days of daily mean temperature recorded for September 2017 as above normal and 10 of these days were defined as extremely high temperature, while the weather remained mostly fine and hot till mid-October when cooler temperatures to Hong Kong for the rest of the month. the weather in November in Hong Kong was generally fine and dry, while windy and rainy weather was recorded the rest of the month. In a conclusion, number of exceedances in dissolved oxygen of September 2017 was higher than October and November 2017. After detailed analysis and comparison between the impaction

stations and control stations, such overall variations in all sampling stations are considered to have been driven by natural fluctuations.

### 3.4 Dolphins Monitoring Results

#### Data Analysis

- 3.4.1 Distribution Analysis – The line-transect survey data was integrated with the Geographic Information System (GIS) in order to visualize and interpret different spatial and temporal patterns of dolphin distribution using sighting positions. Location data of dolphin groups were plotted on map layers of Hong Kong using a desktop GIS (ArcView® 3.1) to examine their distribution patterns in details. The dataset was also stratified into different subsets to examine distribution patterns of dolphin groups with different categories of group sizes, young calves and activities.
- 3.4.2 Encounter rate analysis – Encounter rates of Chinese white dolphins (number of on-effort sightings per 100 km of survey effort, and total number of dolphins sighted on-effort per 100 km of survey effort) were calculated in NEL and NWL survey areas in relation to the amount of survey effort conducted during each month of monitoring survey. Dolphin encounter rates were calculated in two ways for comparisons with the HZMB baseline monitoring results as well as to AFCD long-term marine mammal monitoring results.
- 3.4.3 Firstly, for the comparison with the HZMB baseline monitoring results, the encounter rates were calculated using primary survey effort alone, and only data collected under Beaufort 3 or below condition would be used for encounter rate analysis. The average encounter rate of sightings (STG) and average encounter rate of dolphins (ANI) were deduced based on the encounter rates from six events during the present quarter (i.e. six sets of line-transect surveys in North Lantau), which was also compared with the one deduced from the six events during the baseline period (i.e. six sets of line-transect surveys in North Lantau).
- 3.4.4 Secondly, the encounter rates were calculated using both primary and secondary survey effort collected under Beaufort 3 or below condition as in AFCD long-term monitoring study. The encounter rate of sightings and dolphins were deduced by dividing the total number of on-effort sightings (STG) and total number of dolphins (ANI) by the amount of survey effort for the present quarterly period.
- 3.4.5 Quantitative grid analysis on habitat use – To conduct quantitative grid analysis of habitat use, positions of on-effort sightings of Chinese White Dolphins collected during the quarterly impact phase monitoring period were plotted onto 1-km<sup>2</sup> grids among NWL and NEL survey areas on GIS. Sighting densities (number of on-effort sightings per km<sup>2</sup>) and dolphin densities (total number of dolphins from on-effort sightings per km<sup>2</sup>) were then calculated for each 1 km by 1 km grid with the aid of GIS. Sighting density grids and dolphin density grids were then further normalized with the amount of survey effort conducted within each grid. The total amount of survey effort spent on each grid was calculated by examining the survey coverage on each line-transect survey to determine how many times the grid was surveyed during the study period. For example, when the survey boat traversed through a specific grid 50 times, 50 units of survey effort were counted for that grid. With the amount of survey effort calculated for each grid, the sighting density and dolphin density of each grid were then normalized (i.e. divided by the unit of survey effort).
- 3.4.6 The newly-derived unit for sighting density was termed SPSE, representing the number of on-effort sightings per 100 units of survey effort. In addition, the derived unit for actual dolphin density was termed DPSE, representing the number of dolphins per 100 units of survey effort. Among the 1-km<sup>2</sup> grids that were partially covered by land, the percentage of sea area was calculated using GIS tools, and their SPSE and DPSE values were adjusted accordingly. The following formulae were used to estimate SPSE and DPSE in each 1-km<sup>2</sup> grid within the study area:

$$SPSE = ((S / E) \times 100) / SA\%$$

$$DPSE = ((D / E) \times 100) / SA\%$$

where S = total number of on-effort sightings



D = total number of dolphins from on-effort sightings

E = total number of units of survey effort

SA% = percentage of sea area

- 3.4.7 Behavioural analysis – When dolphins were sighted during vessel surveys, their behaviour was observed. Different activities were categorized (i.e. feeding, milling/resting, traveling, socializing) and recorded on sighting datasheets. This data was then input into a separate database with sighting information, which can be used to determine the distribution of behavioural data with a desktop GIS. Distribution of sightings of dolphins engaged in different activities and behaviours would then be plotted on GIS and carefully examined to identify important areas for different activities of the dolphins.
- 3.4.8 Ranging pattern analysis – Location data of individual dolphins that occurred during the 3-month impact phase monitoring period were obtained from the dolphin sighting database and photo-identification catalogue. To deduce home ranges for individual dolphins using the fixed kernel methods, the program Animal Movement Analyst Extension, was loaded as an extension with ArcView© 3.1 along with another extension Spatial Analyst 2.0. Using the fixed kernel method, the program calculated kernel density estimates based on all sighting positions, and provided an active interface to display kernel density plots. The kernel estimator then calculated and displayed the overall ranging area at 95% UD level.

#### Summary of Survey Effort and Dolphin Sightings

- 3.4.9 During the period of September to November 2017, six sets of systematic line-transect vessel surveys were conducted for the HKBCF project to cover all transect lines in NWL and NEL survey areas twice per month.
- 3.4.10 From these surveys, a total of 790.3 km of survey effort was collected, with 97.9% of the total survey effort being conducted under favourable weather conditions (i.e. Beaufort Sea State 3 or below with good visibility). Among the two areas, 289.9 km and 500.4 km of survey effort were conducted in NEL and NWL survey areas respectively.
- 3.4.11 The total survey effort conducted on primary lines was 574.2 km, while the effort on secondary lines was 216.1 km. Survey effort conducted on both primary and secondary lines were considered as on-effort survey data. A summary table of the survey effort is shown in **Annex I of Appendix L**.
- 3.4.12 During the six sets of monitoring surveys in September to November 2017, six groups of 25 Chinese White Dolphins were sighted, with the summary table of the dolphin sightings shown in **Annex II of Appendix L**. All dolphin sightings were made during on-effort search, while five of the six on-effort dolphin sightings were made on primary lines. In addition, all dolphin groups were sighted in NWL, and no dolphin was sighted at all in NEL.

#### Distribution

- 3.4.13 Distribution of dolphin sightings made during monitoring surveys in September to November 2017 is shown in **Figure 1 of Appendix L**. Five of the four sightings were made at the northwest portion of the North Lantau region, mainly within the Sha Chau and Lung Kwu Chau Marine Park (**Figure 1 of Appendix L**). One dolphin group was also sighted at the southwestern end of NWL survey area, or near the HKLR09 alignment. On the contrary, the dolphins were completely absent from the central and eastern portions of North Lantau waters, similar to the consistent findings of HKLR03 surveys in recent years (**Figure 1 of Appendix L**).
- 3.4.14 All dolphin sightings were located far away from the HKBCF and HKLR03 reclamation sites as well as along the alignment and Tuen Mun-Chek Lap Kok Link (TMCLKL) (**Figure 1 of Appendix L**). However, one sighting was made near the alignment of HKLR09 as mentioned above.
- 3.4.15 Sighting distribution of dolphins during the present impact phase monitoring period (September to November 2017) was drastically different from the one during the baseline monitoring period (**Figure 1 of Appendix L**). In the present quarter, dolphins have disappeared from the NEL region, which was in stark contrast to their frequent occurrence around the Brothers Islands, near Shum Shui Kok and in the vicinity of HKBCF reclamation site during the baseline period (**Figure 1 of Appendix L**).

3.4.16 On the other hand, dolphin occurrence in NWL waters was also noticeably different between the baseline and impact phase periods. During the present impact monitoring period, dolphins were seldom sighted here, and mainly at the northwestern end of the area, which was in stark contrast with their frequent occurrences throughout the entire survey area during the baseline period (**Figure 1 of Appendix L**). Seasonal distributions of dolphins during baseline and impact periods can be referred to those presented in the corresponding quarterly EM&A summary report prepared under Contract No. HY/2011/03.

#### Encounter Rate

3.4.17 During the present three-month study period, the encounter rates of Chinese White Dolphins deduced from the survey effort and on-effort sighting data from the primary transect lines under favourable conditions (Beaufort 3 or below) for each set of the surveys in NEL and NWL are shown in **Table 3.7**. The average encounter rates deduced from the six sets of surveys were also compared with the ones deduced from the baseline monitoring period (September – November 2011) (**Table 3.8**).

3.4.18 To facilitate the comparison with the AFCD long-term monitoring results, the encounter rates were also calculated for the present quarter using both primary and secondary survey effort. The encounter rates of sightings (STG) and dolphins (ANI) in NWL were 1.2 sightings and 5.2 dolphins per 100 km of survey effort respectively, while the encounter rates of sightings (STG) and dolphins (ANI) in NEL were both nil for this quarter.

**Table 3.7 Dolphin Encounter Rates (Sightings Per 100 km of Survey Effort) During Reporting Period (September to November 2017)**

Survey Area	Dolphin Monitoring	Encounter rate (STG) (no. of on-effort dolphin sightings per 100 km of survey effort)	Encounter rate (ANI) (no. of dolphins from all on-effort sightings per 100 km of survey effort)
		Primary Lines Only	Primary Lines Only
Northeast Lantau	Set 1 (5 & 14 Sep 2017)	0.0	0.0
	Set 2 (21 & 25 Sep 2017)	0.0	0.0
	Set 3 (6 & 12 Oct 2017)	0.0	0.0
	Set 4 (17 & 19 Oct 2017)	0.0	0.0
	Set 5 (6 & 14 Nov 2017)	0.0	0.0
	Set 6 (23 & 28 Nov 2017)	0.0	0.0
Northwest Lantau	Set 1 (5 & 14 Sep 2017)	3.4	11.9
	Set 2 (21 & 25 Sep 2017)	3.3	8.3
	Set 3 (6 & 12 Oct 2017)	0.0	0.0
	Set 4 (17 & 19 Oct 2017)	0.0	0.0
	Set 5 (6 & 14 Nov 2017)	1.7	1.7
	Set 6 (23 & 28 Nov 2017)	0.0	0.0

**Table 3.8 Comparison of Average Dolphin Encounter Rates From Impact Monitoring Period (September to November 2017) and Baseline Monitoring Period (September to November 2011)**

Survey Area	Encounter rate (STG) (no. of on-effort dolphin sightings per 100 km of survey effort)		Encounter rate (ANI) (no. of dolphins from all on-effort sightings per 100 km of survey effort)	
	Reporting Period	Baseline Monitoring Period	Reporting Period	Baseline Monitoring Period
Northeast Lantau	0.0	6.0 ± 5.1	0.0	22.2 ± 26.8
Northwest Lantau	1.4 ± 1.7	9.9 ± 5.9	3.7 ± 5.2	44.7 ± 29.9

Notes:

- 1) The encounter rates deduced from the baseline monitoring period have been recalculated based only on the survey effort and on-effort sighting data made along the primary transect lines under favourable conditions.
- 2) ± denotes the standard deviation of the average encounter rates.

- 3.4.19 In NEL, the average dolphin encounter rates (both STG and ANI) in the present three-month impact monitoring period were both zero with no on-effort sighting being made, and such extremely low occurrence of dolphins in NEL have also been consistently recorded in recent years of HZMB monitoring (**Table 3.8**).
- 3.4.20 Comparison of average dolphin encounter rates (**Table 3.9**) in Northeast Lantau survey area from the same autumn quarters of HKLR03 and HKBCF impact monitoring period and baseline monitoring period (September-November 2011) (Note: encounter rates deduced from the baseline monitoring period have been recalculated based only on survey effort and on-effort sighting data made along the primary transect lines under favourable conditions; ± denotes the standard deviation of the average encounter rates)

**Table 3.9 Comparison of Average Dolphin Encounter Rates in Northeast Lantau Survey Area from All Quarters of Impact Monitoring Period and Baseline Monitoring Period (September to November 2011)**

	Encounter rate (STG) (no. of on-effort dolphin sightings per 100 km of survey effort)	Encounter rate (ANI) (no. of dolphins from all on-effort sightings per 100 km of survey effort)
<b>September-November 2011 (Baseline)</b>	<b>6.0 ± 5.1</b>	<b>22.2 ± 26.8</b>
September-November 2013 (HKLR03 Impact <sup>(*)</sup> )	1.0 ± 1.6	3.8 ± 6.5
September-November 2014 (HKLR03 Impact <sup>(*)</sup> )	0.0	0.0
September-November 2015 (HKLR03 Impact <sup>(*)</sup> )	0.0	0.0
September-November 2016 (HKLR03 Impact <sup>(*)</sup> )	0.0	0.0
<b>September-November 2017 (HKBCF Impact)</b>	<b>0.0</b>	<b>0.0</b>

Notes:

- 1) The encounter rates deduced from the baseline monitoring period have been recalculated based only on survey effort and on-effort sighting data made along the primary transect lines under favourable conditions.

2)  $\pm$  denotes the standard deviation of the average encounter rates.

(\*) As explained in Section 1.5 of Appendix L, the previous monitoring data from Contract No. HY/2011/03 (i.e. HKLR03) were adopted for comparison with the baseline and present HKBCF impact monitoring period.

- 3.4.21 On the other hand, the average dolphin encounter rates (STG and ANI) in NWL during the present impact phase monitoring period (reductions of 85.7% and 91.8% respectively) were only very small fractions of the ones recorded during the three-month baseline period, indicating a dramatic decline in dolphin usage of this survey area as well during the present impact phase period (**Table 3.10**).
- 3.4.22 During the same autumn quarters, dolphin encounter rates in NWL during autumn 2017 was similar to the previous autumn period in and 2016 but was much lower than the ones in the summer periods of 2013, 2014 and 2015 (**Table 3.10**). Such temporal trend should be closely monitored in the upcoming monitoring quarters whether the dolphin occurrence would continue to increase as the construction activities of HZMB works have been mostly completed in coming months.

**Table 3.10 Comparison of Average Dolphin Encounter Rates in Northwest Lantau Survey Area from All Quarters of Impact Monitoring Period and Baseline Monitoring Period (September to November 2011)**

Monitoring Period	Encounter rate (STG) (no. of on-effort dolphin sightings per 100 km of survey effort)	Encounter rate (ANI) (no. of dolphins from all on-effort sightings per 100 km of survey effort)
<b>September-November 2011 (Baseline)</b>	<b>9.9 <math>\pm</math> 5.9</b>	<b>44.7 <math>\pm</math> 29.9</b>
September-November 2013 (HKLR03 Impact <sup>(*)</sup> )	8.0 $\pm$ 1.1	32.5 $\pm$ 26.5
September-November 2014 (HKLR03 Impact <sup>(*)</sup> )	5.1 $\pm$ 4.4	20.5 $\pm$ 15.1
September-November 2015 (HKLR03 Impact <sup>(*)</sup> )	3.9 $\pm$ 1.6	21.1 $\pm$ 17.2
September-November 2016 (HKLR03 Impact <sup>(*)</sup> )	2.9 $\pm$ 2.0	10.9 $\pm$ 11.0
<b>September-November 2017 (HKBCF Impact)</b>	<b>3.1 <math>\pm</math> 1.9</b>	<b>10.4 <math>\pm</math> 9.7</b>

Notes:

1) The encounter rates deduced from the baseline monitoring period have been recalculated based only on survey effort and on-effort sighting data made along the primary transect lines under favourable conditions.

2)  $\pm$  denotes the standard deviation of the average encounter rates.

(\*) As explained in Section 1.5 of Appendix L, the previous monitoring data from Contract No. HY/2011/03 (i.e. HKLR03) were adopted for comparison with the baseline and present HKBCF impact monitoring period.

- 3.4.23 A two-way ANOVA with repeated measures and unequal sample size was conducted to examine whether there were any significant differences in the average encounter rates between the baseline and impact monitoring periods. The two variables that were examined included the two periods (baseline and impact phases) and two locations (NEL and NWL).
- 3.4.24 For the comparison between the baseline period and the present quarter, the p-values for the differences in average dolphin encounter rates of STG and ANI were 0.0025 and 0.0156 respectively. If the alpha value is set at 0.05, significant differences were detected between the baseline and present quarters in both the average dolphin encounter rates of STG and ANI.
- 3.4.25 As indicated in both dolphin distribution patterns and encounter rates, dolphin usage has been significantly reduced in both NEL and NWL survey areas during the present quarterly period, and such low occurrence of dolphins has also been consistently documented in past HZMB dolphin monitoring studies.
- 3.4.26 The dramatic decline in dolphin usage of North Lantau region raises serious concern, as the timing of the decline in dolphin usage in North Lantau waters coincided well with the construction schedule of the HZMB-related projects (Hung 2017). Apparently, there was no sign of recovery

of dolphin usage even though most of the marine works associated with the HZMB construction have been completed.

### Group Size

- 3.4.27 Group size of Chinese White Dolphins ranged from one to 12 individuals per group in North Lantau region during September to November 2017. The average dolphin group sizes from these three months were compared with the ones deduced from the baseline period in September to November 2011, as shown in **Table 3.11**.

**Table 3.11 Comparison of Average Dolphin Group Sizes between Reporting Period (September to November 2017) and Baseline Monitoring Period (September to November 2011)**

Survey Area	Average Dolphin Group Size	
	Reporting Period	Baseline Monitoring Period
Overall	4.2 ± 4.2 (n = 6)	3.7 ± 3.1 (n = 66)
Northeast Lantau	---	3.2 ± 2.2 (n = 17)
Northwest Lantau	4.2 ± 4.2 (n = 6)	3.9 ± 3.4 (n = 49)

Note:

- 1) ± denotes the standard deviation of the average group size.
- 3.4.28 The average dolphin group size in NWL waters during September to November 2017 was lower than the one recorded during the three-month baseline period, but this could be partly related to the small sample size of 6 dolphin groups when compared to the 66 groups sighted during the baseline period (**Table 3.11**).
- 3.4.29 Notably, four of the 6 dolphin groups were composed of 1-4 individuals only, while there was one medium-sized group with five dolphins, and another large group with 12 dolphins (**Annex II of Appendix L**).
- 3.4.30 Distribution of the larger dolphin groups (i.e. five individuals or more per group) during the present quarter is shown in **Figures 3a and 3b of Appendix L**, with comparison to the one in baseline period. The medium-sized group with 5 dolphins was located to the west of the airport near the HKLR09 alignment, while the large group of 12 dolphins was sighted adjacent to the west of Lung Kwu Chau (**Figure 2 of Appendix L**). Such distribution pattern was very different from the baseline period, when the larger dolphin groups were frequently sighted and evenly distributed in NWL waters, with a few also sighted in NEL waters (**Figure 2 of Appendix L**).

### Habitat Use

- 3.4.31 From September to November 2017, the three of the six grids with high dolphin densities were located to the west of Lung Kwu Chau, north of Sha Chau and near the HKLR09 alignment (**Figures 3a and 3b of Appendix L**). All grids near HKLR03/HKBCF reclamation sites as well as TMCLKL alignment did not record any presence of dolphins at all during on-effort search in the present quarterly period (**Figures 3a and 3b of Appendix L**).
- 3.4.32 However, it should be emphasized that the amount of survey effort collected in each grid during the three-month period was fairly low (6-12 units of survey effort for most grids), and therefore the habitat use pattern derived from the three-month dataset should be treated with caution. A more complete picture of dolphin habitat use pattern should be examined when more survey effort for each grid will be collected throughout the impact phase monitoring programme.
- 3.4.33 When compared with the habitat use patterns during the baseline period, dolphin usage in NEL and NWL has drastically diminished in both areas during the present impact monitoring period (**Figure 4 of Appendix L**). During the baseline period, many grids between Siu Mo To and Shum Shui Kok in NEL recorded moderately high to high dolphin densities, which was in stark contrast to the complete absence of dolphins there during the present impact phase period (**Figure 4 of Appendix L**).

3.4.34 The density patterns were also very different in NWL between the baseline and impact phase monitoring periods, with high dolphin usage throughout the area during the baseline period. In contrast, only several grids with high dolphin densities were located near Lung Kwu Chau and Sha Chau during the present impact phase period (**Figure 4 of Appendix L**).

#### **Mother-calf Pairs**

3.4.35 During the present quarterly period, no young calf was sighted at all among the six groups of dolphins.

#### **Activities and Associations with Fishing Boats**

3.4.36 During the three-month study period, one of the 6 dolphin groups (i.e. the large group located just to the west of Lung Kwu Chau; (**Figure 5 of Appendix L**) were engaged in socializing activity, while the rest of the groups were not engaged in feeding, traveling or milling/resting activity during the three-month study period.

3.4.37 When compared to the baseline period, distribution of various dolphin activities during the present impact phase monitoring period was drastically different with very rare occurrence of such activities in the present quarter (**Figure 5 of Appendix L**).

3.4.38 Moreover, none of the dolphin groups was found to be associated with any operating fishing boat during the present impact phase period.

#### **Summary Photo-identification works**

3.4.39 From September to November 2017, over 1,000 digital photographs of Chinese White Dolphins were taken during the impact phase monitoring surveys for the photo-identification work.

3.4.40 In total, 18 individuals sighted 19 times altogether were identified (see summary table in **Annex III of Appendix L** and photographs of identified individuals in **Annex IV of Appendix L**). All of these re-sightings were made in NWL. Among the 18 individuals, only one individual (i.e. CH34) was re-sighted twice, while the rest were only re-sighted once during the three-month period (**Annex III of Appendix L**).

3.4.41 Notably, ten of these 18 individuals (i.e. CH34, NL12, NL49, NL104, NL136, NL182, NL202, NL320, NL321 and WL05) were also sighted in Northwest Lantau during the HKLR03 monitoring surveys conducted concurrently in the same three-month period. Moreover, six individuals (i.e. CH34, NL12, NL49, NL182, NL317, and WL05) were also sighted in West Lantau waters during the HKLR09 monitoring surveys from September to November 2017, showing their extensive individual movements across different survey areas.

#### **Individual range use**

3.4.42 Ranging patterns of the 18 individuals identified during the three-month study period were determined by fixed kernel method, and are shown in **Annex V of Appendix L**.

3.4.43 All identified dolphins sighted in the present quarter were utilizing NWL waters only but have completely avoided NEL waters where many of them have utilized as their core areas in the past (**Annex V of Appendix L**). This is in stark contrary to the extensive movements between NEL and NWL survey areas observed in the earlier impact monitoring quarters as well as the baseline period.

3.4.44 On the other hand, three individuals (NL12, NL182 and WL05) consistently utilized North Lantau waters in the past have extended their range use to WL during the present quarter.

3.4.45 In the upcoming quarters, individual range use and movements should be continuously monitored to examine whether there has been any consistent shifts of individual home ranges from North Lantau to West or Southwest Lantau, as such shift could possibly be related to the HZMB-related construction works (see Hung 2017).

#### **Action Level / Limit Level Exceedance**

3.4.46 There was one Limit Level exceedance of dolphin monitoring for the quarterly monitoring data (between September 2017 – November 2017). For detail of investigation, please refer to **Appendix K**.

- 3.4.47 During the present quarter of dolphin monitoring, no adverse impact from the activities of this construction project on Chinese White Dolphins was noticeable from general observations.
- 3.4.48 Although dolphins seldom occurred in the area of HKBCF construction in the past and during the baseline monitoring period, it is apparent that dolphin usage has been dramatically reduced in North Lantau waters in recent years, and many individuals have shifted away from this once-important habitat for the dolphins.
- 3.4.49 It is critical to continuously monitor the dolphin usage in North Lantau region in the upcoming quarters, to determine whether the dolphins are continuously affected by the various construction activities in relation to the HZMB-related works, and whether there is any sign of recovery when the construction works have been completed.

### 3.5 Implementation of Environmental Measures

- 3.5.1 In response to the site audit findings, the Contractor carried out corrective actions. Details of site audit findings and the corrective actions during the reporting period are presented in **Appendix G**.
- 3.5.2 The Contractor waters 8 times per day on all exposed soil within the Contract site and associated works areas when construction activities are being undertaken.
- 3.5.3 The marine traffic records and geographical plots of all the vessels tracks for the reporting month will be submitted by the Contractor to Engineer's Representative (ER), Environmental Team Leader (ETL) and Independent Environmental Checker / Environmental Project Office (IEC/ENPO) within 3 weeks after the reporting month. As informed by Contractor, there was no marine traffic since 2 June 2017.
- 3.5.4 Regular marine travel route for marine vessels were implemented properly and training was provided for barge operators in accordance with the Regular Marine Travel Routes Plan and relevant records were kept properly.
- 3.5.5 A summary of the Implementation Schedule of Environmental Mitigation Measures (EMIS) is presented in **Appendix E**. Most of the necessary mitigation measures were implemented properly.

### 3.6 Advice on the Solid and Liquid Waste Management Status

- 3.6.1 The Contractor registered as a chemical waste producer for the Contract. Sufficient numbers of receptacles were available for general refuse collection and sorting.
- 3.6.2 No marine sediment was generated/treated and no treated marine sediment was reused in the reporting period. As informed by the Contractor in March 2016, the transfer of treated marine sediment to Contract no. HY/2010/02 has been discontinued since July 2015.
- 3.6.3 The summary of waste flow table is detailed in **Appendix H**.
- 3.6.4 The Contractor was reminded that chemical waste containers should be properly treated and stored temporarily in designated chemical waste storage area on site in accordance with the *Code of Practice on the Packaging, Labelling and Storage of Chemical Wastes*.

### 3.7 Environmental Licenses and Permits

- 3.7.1 The valid environmental licenses and permits during the reporting period are summarized in **Appendix I**.

## 4 Summary of Exceedance, Complaint, Notification of Summons and Successful Prosecution

### 4.1 Summary of Exceedance of the Environmental Quality Performance Limit

- 4.1.1 For air quality monitoring, No Action and Limit Level exceedances of 1-hour TSP were recorded at AMS2, AMS3B and AMS7 during the reporting period. No Action and Limit Level exceedances of 24-hour TSP were recorded at AMS2 and AMS7 during the reporting period. No Limit Level exceedance of 24-hour TSP was recorded at AMS3B during the reporting period while on 28 November 2017, one AL exceedance of 24-hour TSP at ASM3B was recorded.
- 4.1.2 Summary of Action and Limit Level exceedance of 1-hr TSP level and 24-hr TSP level at AMS6 shall be referred to the monthly EM&A Reports (for September to November 2017) prepared by Contract No. HY/2011/03.
- 4.1.3 There were no Action and Limit Level exceedance for noise recorded at NMS2 and NMS3B during the reporting period.
- 4.1.4 For water quality monitoring during the reporting period, there were 61 Action Level exceedances of dissolved oxygen were recorded at mid-ebb tide while 83 Action Level exceedances of dissolved oxygen were recorded at mid-flood tide. 11 Limit Level exceedances of dissolved oxygen were recorded at mid-ebb tide while 23 Limit Level exceedances of dissolved oxygen were recorded at mid-flood tide.
- 4.1.5 An Action Level exceedance of turbidity was recorded at mid-ebb tide while 4 Action Level exceedances of turbidity were recorded at mid-flood tide. No Limit Level exceedance of turbidity was recorded at ebb tide while 1 Limit Level exceedance of turbidity was recorded at flood tide.
- 4.1.6 4 Action Level exceedances of suspended solid were recorded at mid-ebb tide while 24 Action Level exceedances of suspended solid were recorded at mid-flood tide. No Limit Level exceedances of suspended solid were recorded at mid-ebb tide while 5 Limit Level exceedances of suspended solid were recorded mid-flood tide.
- 4.1.7 After investigation, the exceedance was considered not likely to be caused by this Contract's activities. No follow-up action is required.
- 4.1.8 Impact dolphin monitoring results at all transects are reported in the EM&A Reports prepared for Contract No. HY/2013/01. One Limit Level exceedance of dolphin monitoring was recorded in the reporting quarter.

### 4.2 Summary of Complaints, Notification of Summons and Successful Prosecution

- 4.2.1 There was two complaints were received in relation to the environmental impact during the reporting period. A summary of environmental complaint is presented in **Table 4.1**. The details of cumulative statistics of Environmental Complaints are provided in **Appendix J**.

**Table 4.1 A Summary of Environmental Complaints for the Previous Reporting Month**

Environmental Complaint No.	Date of Complaint Received	Description of Environmental Complaints
009	27 October 2017	Water Quality
010	23 November 2017	Dust

Environmental Compliant No. 009 – Water Quality





- 4.2.1 According to ENPO's email to the Environmental Team, Engineer's Representative and Contractor on 27 October 2017, it was noted that EPD received a complaint regarding the water quality at C3 area.
- 4.2.2 Based to the observation of weekly site inspections (4, 11, 18 and 25 October 2017 and 1 November 2017) and confirmed by the Contractor, the wastewater generated on site is treated by the wastewater treatment facilities (sedimentation tank and AquaSed) before discharge. No site runoff within the Contract site was observed.
- 4.2.3 Based on water quality monitoring results in October 2017, total 5 Action Level exceedances of Suspended Solid were recorded at SR5(N), IS(Mf)11 and SR7 on 18, 20 and 23 October 2017. After the investigation which concluded the exceedances were not related to the Contract.
- 4.2.4 Based on the investigation results, it is found that the complaint is not related to Contract No. HY/2013/01.
- Environmental Compliant No. 010 – Dust
- 4.2.5 The complaint focuses on the dust generation from the haul road. Based on the information from the Contractor, the construction works undertaken on 23 November 2017 is shown as below:
- Waterproofing
  - Formwork and falsework stripping
  - Pipework and ductwork installation
  - Hanger rods for cable container
  - Wet trade works
  - Dry trade works
  - Mechanical, electrical, and plumbing (MEP) High Level Containment
  - Removal of temporary works
  - Window wall glazing
  - Curtain wall glazing
  - Hanging scaffolding removal
  - Refuse collection point
  - Southern toilet
  - Minimal instruction set computer (MISC) steelwork
  - Lift installation
  - Testing and commissioning works
- 4.2.6 The Contractor has implemented measures to avoid dust emission according to Water Spraying Plan in November. The Contractor has provided the guideline to remind the site vehicles should travel within speed limit of 8 km/hr. According to site inspection which conducted on 1, 8, 15 and 22 November 2017, no dusty activities and dry condition in haul road were observed.
- 4.2.7 The Contractor have arranged a staff to supervise the haul road condition near PCB building. In case of adverse dust emission, the Contractor should arrange the water truck or front-line staff to enhance the watering. The watering plan, which include the information of watering schedule, routing of trucks for watering and the location of water filling, was prepared and submitted to RE and ENPO. The Contractor was also reminded to implement all necessary mitigation as specified in EIA (Section 5.5.6.3), EM&A Manual (EM&A Log Ref: A3), EMP, Method Statements, General and Particular Specifications of this Project to minimize the potential dust impact during construction activities.



4.2.8 Statistics on notifications of summons and successful prosecutions are summarized in **Appendix J**.

## 5 Comments, Recommendations and Conclusion

### 5.1 Comments

5.1.1 According to the environmental site inspections undertaken during the reporting period, the following recommendations were provided:

- The Contractor was reminded to provide watering for the road to avoid dust generation.
- The Contractor was reminded to provide drip trays for chemical containers.
- The Contractor was reminded to clear the general refuse.
- The Contractor was reminded to cover the dusty material to prevent fugitive dust emission.
- The Contractor was reminded to provide water spraying during concrete breaking in process.
- The Contractor was reminded to carry out cement mixing work in an area sheltered on the top and 3 sides to avoid dust emission.
- The Contractor was reminded to cover the bags of cement entirely by impervious sheeting or place them in an area sheltered on the top and 3 sides.
- The Contractor was reminded to display environmental permit and a construction noise permit major site exits.

5.1.2 A summary of the Implementation Schedule of Environmental Mitigation Measures (EMIS) is presented in **Appendix E**. Most of the necessary mitigation measures were implemented properly.

### 5.2 Recommendations

5.2.1 With implementation of the recommended environmental mitigation measures, the contract's environmental impacts were considered environmentally acceptable. The weekly environmental site inspections ensured that all the environmental mitigation measures recommended were effectively implemented.

5.2.2 The recommended environmental mitigation measures, as included in the EM&A programme, effectively minimize the potential environmental impacts from the contract. Also, the EM&A programme effectively monitored the environmental impacts from the construction activities and ensure the proper implementation of mitigation measures. No particular recommendation was advised for the improvement of the programme.

## 5.3 Conclusions

- 5.3.1 The site preparation work of the Contract started on 26 September 2014 and the construction works of the Contract commenced on 6 October 2014. This is the thirteen Quarterly EM&A Report summaries findings of the EM&A works during the reporting period from 1 September to 30 November 2017.
- 5.3.2 For air quality monitoring, no Action and Limit Level exceedances of 1-hour TSP were recorded at AMS2, AMS3B and AMS7 during the reporting period. No Action and Limit Level exceedances of 24-hour TSP were recorded at AMS2 and AMS7 during the reporting period. No Limit Level exceedance of 24-hour TSP was recorded at AMS3B during the reporting period while one AL exceedance of 24-hour TSP at ASM3B was recorded on 28 November 2017.
- 5.3.3 Summary of Action and Limit Level exceedance of 1-hr TSP level and 24-hr TSP level at AMS6 shall be referred to the monthly EM&A Reports (for September to November 2017) prepared by Contract No. HY/2011/03.
- 5.3.4 There were no Action and Limit Level exceedance for noise recorded at NMS2 and NMS3B during the reporting period.
- 5.3.5 For water quality monitoring during the reporting period, there were 61 Action Level exceedances of dissolved oxygen were recorded at mid-ebb tide while 83 Action Level exceedances of dissolved oxygen were recorded at mid-flood tide. 11 Limit Level exceedances of dissolved oxygen were recorded at mid-ebb tide while 23 Limit Level exceedances of dissolved oxygen were recorded at mid-flood tide.
- 5.3.6 An Action Level exceedance of turbidity was recorded at mid-ebb tide while 4 Action Level exceedances of turbidity were recorded at mid-flood tide. No Limit Level exceedance of turbidity was recorded at ebb tide while 1 Limit Level exceedance of turbidity was recorded at flood tide.
- 5.3.7 4 Action Level exceedances of suspended solid were recorded at mid-ebb tide while 24 Action Level exceedances of suspended solid were recorded at mid-flood tide. No Limit Level exceedances of suspended solid were recorded at mid-ebb tide while 5 Limit Level exceedances of suspended solid were recorded mid-flood tide.
- 5.3.8 After investigation, the exceedance was considered not likely to be caused by this Contract's activities. No follow-up action is required.
- 5.3.9 Impact dolphin monitoring results at all transects are reported in the EM&A Reports prepared for Contract No. HY/2013/01. One Limit Level exceedance of dolphin monitoring was recorded during the monitoring period (between September 2017 – November 2017).
- 5.3.10 Environmental site inspections were carried out on 6, 13, 20 and 27 September 2017, 4, 11, 18 and 25 October 2017 and 1, 8, 15, 22 and 29 November 2017. Recommendations on remedial actions were given to the Contractors for the deficiencies identified during the site inspections.
- 5.3.11 There were two complaints received in relation to the environmental impact during the reporting period. The complaint investigations were closed and details were in Investigation No. 009 ver2 and 010 ver1 in **Appendix K**.
- 5.3.12 No notification of summons and successful prosecution was received during the reporting period.



# FIGURES

---






Figure 2.1  
Location of Air Quality Monitoring Stations and Wind Station



**Figure 2.2 Location of Noise Monitoring Stations**

**LEGEND**

NMS2 and NMS3B ● NOISE MONITORING STATIONS



Station	East	North
IS5	811579	817106
IS(Mf)6	812101	817873
IS7	812244	818777
IS8	814251	818412
IS(Mf)9	813273	818850
IS10(N)	812942	820881
IS(Mf)11	813562	820716
IS(Mf)16	814328	819497
IS17	814539	820391
SR3(N)	810689	816591
SR4(N)	814705	817859
SR5(N)	812569	821475
SR6	805837	821818
SR7	814293	821431
SR10A(N)	823644	823484
SR10B(N2)	823689	823159
CS(Mf)3(N)	808814	822355
CS(Mf)5	817990	821129
CS4	810025	824004
CS6	817028	823992
CSA	818103	823064

FIGURE 2.3 – LOCATION OF WATER QUALITY MONITORING STATIONS




Figure 2.4  
Impact Dolphins Monitoring Line  
Transect Layout Map







# APPENDIX A

---

## Location of Works Areas



- NOTES:**
- COORDINATES ARE RELATED TO HONG KONG METRIC GRID (1980).
  - DIMENSIONS ARE IN MILLIMETER AND CHAINAGE ARE IN METRES UNLESS OTHERWISE SHOWN.
  - THIS DRAWING SHALL BE READ IN CONJUNCTION WITH DRAWING NOS. 60191048/C1/000/C00/1041 TO 1043.



**WORKS AREA 'WA1'**  
THE SITE SEE DRAWING NO. 60191048/C1/000/C00/1003

TUEN MUN-CHEK LAP KOK LINK (TM-CLKL) (BY OTHERS)

**WORKS AREA 'WA3'**  
SEE DRAWING NO. 60191048/C1/000/C00/1042

RECLAMATION FOR THE TM-CLKL SOUTHERN LANDFALL (BY OTHERS)  
OTHER INFRASTRUCTURE AND BUILDING WORKS OUTSIDE SITH BOUNDARY (BY OTHERS)

**WORKS AREA 'WA2'**  
SEE DRAWING NO. 60191048/C1/000/C00/1041

HONG KONG LINK ROAD (HKLR) (SEPARATE PROJECT) (BY OTHERS)

**WORKS AREA 'WA4'**  
SEE DRAWING NO. 60191048/C1/000/C00/1043

B	WORKING DRAWING	BWCW SCI JUN.14
A	TENDER ADDENDUM NO. 1	BWCW SCI OCT.13
-	TENDER DRAWING	BWCW SCI SEP.13
REV. 修改	DESCRIPTION 內容摘要	DATE 日期

**路政署 HIGHWAYS DEPARTMENT**  
香港機場管理局  
Hong Kong - Zhuhai - Macao Bridge Hong Kong Project Management Office

HONG KONG-ZHUHAI-MACAO BRIDGE  
HONG KONG BOUNDARY CROSSING FACILITIES  
- PASSENGER CLEARANCE BUILDING


**SITE LOCATION PLAN**

**AECOM** + +  
Rogers Stirk Harbour + Partners  
BURO HAPPOLD ATKINS ADI + +  
**Aedas**

DRG.NO. 60191048/C1/000/C00/1000B  
圖紙編號

DESIGNED BY 設計	BWCW	CONTRACT NO. 合約編號	HY/2013/01	P. DIR. APPROVED 批准人	TKH
DRAWN BY 繪圖	WSY	STATUS 階段	<b>WORKING DRAWING</b>		
SCALE 比例	A1 1 : 25000	DIMENSIONS ARE IN 尺寸單位 METRES			
© COPYRIGHT RESERVED 版權所 有					

Plot File by : 7/10/2013 WONGKKK




GATE 2 TO BE CONSTRUCTED WHEN HY/2013/02 CONTRACTOR TAKE OVER PORTION 1

HAUL ROAD TO BE CONSTRUCTED DIVERTED, MANAGED AND MAINTAINED BY HY/2013/01 CONTRACT

GATE TO BE CONSTRUCTED BY CLP

MARINE LOADING AND UNLOADING POINTS, EXACT LOCATION AND EXTENT TO BE LIAISED AND CONFIRMED WITH HY/2013/02 CONTRACTOR

GATE 1 TO BE CONSTRUCTED AT THE COMMENCEMENT OF THE CONTRACT



LOCATION PLAN  
SCALE 1 : 20000

NOTES:

- COORDINATES ARE BASED ON HONG KONG METRIC GRID (1980) UNLESS OTHERWISE NOTED.
- LEVELS ARE IN METRES RELATIVE TO HONG KONG PRINCIPAL DATUM (mPD) UNLESS OTHERWISE NOTED.
- DIMENSIONS ARE IN METRES UNLESS OTHERWISE STATED.
- SETTING OUT, DIMENSIONS, LEVELS, COORDINATES ARE TO BE CALCULATED BY THE CONTRACTOR. NO INFORMATION SHOULD BE SCALED PHYSICALLY OR ELECTRONICALLY FROM THE DRAWINGS OR FILES.
- SITE ACCESS SHALL BE HARD PAVED WITH PROPER DRAINAGE PROVIDED. IT SHALL BE KEPT UNOBSTRUCTED AND UNDISRUPTED AT ALL TIMES.

LEGEND:

- SITE BOUNDARY
- 7.3m CLEAR WIDTH CONSTRUCTION HAUL ROAD
- INDICATIVE 20m WIDE VEHICULAR ACCESS BY RECLAMATION CONTRACT HY/2010/02

REV.	DESCRIPTION	CHK'D	DATE
01	TENDER DRAWING	BWCW SCI	SEP.13

路政署 HIGHWAYS DEPARTMENT  
港珠澳大橋香港工程管理局  
Hong Kong - Zhuhai - Macao Bridge Hong Kong Project Management Office

HONG KONG-ZHUHAI-MACAO BRIDGE  
HONG KONG BOUNDARY CROSSING FACILITIES  
- PASSENGER CLEARANCE BUILDING

WORKS AREA WA1

**AECOM** +  
Rogers Stirk Harbour + Partners  
BURO HAPPOLD ATKINS ADI +



DRG.NO. 60191048/C1/000/C00/1044  
圖紙編號

DESIGNED BY BWCW CONTRACT NO. HY/2013/01 P. Dir. APPROVED EMSC

DRAWN BY WSY STATUS SCALE A1 1 : 2500

DIMENSIONS ARE IN METRES © COPYRIGHT RESERVED

Plot File by : 2013/9/10 WANGSY



**LOCATION PLAN**  
SCALE 1 : 25000

- NOTES:**
- COORDINATES ARE RELATED TO HONG KONG METRIC GRID (1980).
  - DIMENSIONS ARE IN MILLIMETER AND CHAINAGE ARE IN METRES UNLESS OTHERWISE SHOWN.

- LEGEND:**
- WORKS AREA BOUNDARY
  - PORTION 2.1
  - PORTION 2.2
  - PORTION 2.3

WORKS AREA OCCUPIED BY CONTRACT NO. HY/2010/02

COMMON ACCESS TO BE PROVIDED AND MAINTAINED BY CONTRACT NO. HY/2010/02

**SETTING OUT POINT**

POINT	EASTING	NORTHING
201	813071.417	817531.755
202	813046.124	817528.520
203	813041.528	817559.119
204	812918.331	817540.618
205	812754.843	817398.454
206	812767.133	817302.381
207	812780.486	817294.062
208	812745.200	817289.613
209	812752.963	817300.569
210	812748.782	817300.034
211	812734.825	817409.146
212	812788.988	817454.350
213	812777.075	817578.404
214	813058.837	817612.753
215	812925.889	817596.485
216	812931.852	817542.648
217	812930.654	817552.515
218	812909.983	817549.657
219	812802.930	817457.358
220	812798.921	817461.656
221	812788.702	817458.876

B	WORKING DRAWING	BWCW SCI	JUN.14
A	TENDER ADDENDUM NO. 1	BWCW SCI	OCT.13
-	TENDER DRAWING	BWCW SCI	SEP.13
REV.	DESCRIPTION	CHECKED	DATE
01	內務圖	WONG	14/06/14

路政署 HIGHWAYS DEPARTMENT  
 港珠澳大橋香港工程管理局  
 Hong Kong - Zhuhai - Macao Bridge Hong Kong Project Management Office

HONG KONG-ZHUHAI-MACAO BRIDGE  
 HONG KONG BOUNDARY CROSSING FACILITIES  
 - PASSENGER CLEARANCE BUILDING

**WORKS AREA WA2**


**AECOM** +  
**Rogers Stirk Harbour + Partners** +  
**BURO HAPPOLD ATKINS ADI** +  
**Aedas**

DRG.NO: 60191048/C1/000/C00/1041B

DESIGNED BY BWCW	CONTRACT NO. HY/2013/01	P. DIR. APPROVED TKH
DRAWN BY WSY	STATUS WSD	<b>WORKING DRAWING</b>
SCALE A1 1 : 1000	DIMENSIONS ARE IN METRES	

SETTING OUT POINT


POINT	EASTING	NORTHING
301	817467.265	819162.683
302	817314.741	819069.828
303	817327.338	819049.295
304	817440.865	819117.811
305	817340.825	819027.314
306	817387.350	819023.403
307	817387.861	819043.396
308	817466.133	819091.047
309	817469.783	819087.181
310	817513.449	819113.764
311	817347.717	819016.082
312	817526.774	819020.578
313	817531.659	819021.641
314	817531.154	819001.065
315	817533.345	818991.306
316	817620.269	819000.620



LOCATION PLAN  
SCALE 1 : 25000

- NOTES:
- COORDINATES ARE RELATED TO HONG KONG METRIC GRID (1980).
  - DIMENSIONS ARE IN MILLIMETER AND CHAINAGE ARE IN METRES UNLESS OTHERWISE SHOWN.

- LEGEND:
- WORKS AREA BOUNDARY
  - PORTION 3.1
  - PORTION 3.2
  - PORTION 3.3
  - PORTION 3.4
  - PORTION 3.5
  - PORTION 3.6
  - PORTION 3.7
  - PORTION 3.8
  - PORTION 3.9



10m WIDE COMMON ACCESS TO BE MAINTAINED BY CONTRACT NO. HY/2010/02

WORKS AREA OCCUPIED BY CONTRACT NO. HY/2010/02

10m WIDE COMMON ACCESS TO BE CONSTRUCTED AND INITIALLY MAINTAINED BY CONTRACT NO. HY/2013/01. UPON COMMENCEMENT OF CONTRACT NO. HY/2013/03, THE MAINTENANCE RESPONSIBILITY SHALL BE TRANSFERRED FROM CONTRACT NO. HY/2013/01 TO CONTRACT NO. HY/2013/03.

WORKS AREA OCCUPIED BY CONTRACT NO. HY/2011/03

WORKS AREA OCCUPIED BY CONTRACT NO. HY/2011/09

REV. 01	WORKING DRAWING	BWCW SCI JUN. 14
REV. 02	TENDER DRAWING	BWCW SCI SEP. 13

路政署 HIGHWAYS DEPARTMENT  
港珠澳大橋香港工程管理局  
Hong Kong - Zhuhai - Macao Bridge Hong Kong Project Management Office

HONG KONG-ZHUHAI-MACAO BRIDGE  
HONG KONG BOUNDARY CROSSING FACILITIES  
- PASSENGER CLEARANCE BUILDING

WORKS AREA WA3

**AECOM** Aedas  
Rogers Stirk Harbour + Partners  
BURO HAPPOLD ATKINS ADI

DRG.NO. 60191048/C1/000/C00/1042A  
圖紙編號

DESIGNED BY BWCW CONTRACT NO. HY/2013/01 P. DIR. APPROVED TKH

SCALE A1 1 : 1000 WORKING DRAWING

DIMENSIONS ARE IN METRES © COPYRIGHT RESERVED

SETTING OUT POINT

POINT	EASTING	NORTHING
401	822488.151	822632.315
402	822640.593	822689.415
403	822515.608	822559.848
404	822610.940	822599.642
405	822629.428	822607.359
406	822526.988	822529.813
407	822618.348	822567.950
408	822542.232	822489.581
409	822584.983	822507.426
410	822606.866	822516.561
411	822560.278	822441.956
412	822602.949	822460.010
413	822621.914	822467.959
414	822624.130	822470.998
415	822651.725	822508.856



822400 E

822600 E

822600 N

822400 N

Plot File by : 2013/9/10 WANGSY



LOCATION PLAN  
SCALE 1 : 25000

NOTES:

- COORDINATES ARE RELATED TO HONG KONG METRIC GRID (1980).
- DIMENSIONS ARE IN MILLIMETER AND CHAINAGE ARE IN METRES UNLESS OTHERWISE SHOWN.

LEGEND:

- WORKS AREA BOUNDARY
- [Hatched Pattern 1] PORTION 4.1
- [Hatched Pattern 2] PORTION 4.2
- [Hatched Pattern 3] PORTION 4.3
- [Hatched Pattern 4] PORTION 4.4
- [Hatched Pattern 5] PORTION 4.5
- [Hatched Pattern 6] PORTION 4.6
- [Hatched Pattern 7] PORTION 4.7
- [Hatched Pattern 8] PORTION 4.8

REV.	DESCRIPTION	DATE
1	TENDER DRAWING	SEP.13

路政署 HIGHWAYS DEPARTMENT  
港珠澳大橋香港工程管理局  
Hong Kong - Zhuhai - Macao Bridge Hong Kong Project Management Office

HONG KONG-ZHUHAI-MACAO BRIDGE  
HONG KONG BOUNDARY CROSSING FACILITIES  
- PASSENGER CLEARANCE BUILDING

WORKS AREA WA4

**AECOM** Aedas  
Rogers Stirk Harbour + Partners  
BURO HAPPOLD ATKINS ADI

DRG.NO. 60191048/C1/000/C00/1043  
圖紙編號

DESIGNED BY W.S.Y.	CONTRACT NO. HY/2013/01	P. Dir. APPROVED EMSC
-----------------------	----------------------------	--------------------------

DRAWN BY WSY	STATUS CHECKED
-----------------	-------------------

SCALE 1:1000  
DIMENSIONS ARE IN METRES  
© COPYRIGHT RESERVED




# APPENDIX B

---

## Project Organization for Environmental Works

## Project Organisation for Environmental Works








# APPENDIX C

---


## Construction Programme



- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 1 of 36

Date	Revision	Checked	Approved




- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

## Three Month Rolling Programme

### HKMZB HKBCF - Passenger Clearance Building


Page 2 of 36

Date	Revision	Checked	Approved



**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 3 of 36

Date	Revision	Checked	Approved




- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

## Three Month Rolling Programme

HKMZB HKBCF - Passenger Clearance Building

Page 4 of 36


Date	Revision	Checked	Approved



- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 5 of 36


Date	Revision	Checked	Approved



- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 6 of 36

Date	Revision	Checked	Approved




- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 7 of 36

Date	Revision	Checked	Approved






- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

## Three Month Rolling Programme

### HKMZB HKBCF - Passenger Clearance Building

Page 8 of 36

Date	Revision	Checked	Approved




- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

## Three Month Rolling Programme

### HKMZB HKBCF - Passenger Clearance Building

Page 9 of 36


Date	Revision	Checked	Approved



- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 10 of 36


Date	Revision	Checked	Approved



- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 11 of 36

Date	Revision	Checked	Approved




- Actual Work
- Remaining Work
- Critical Remaining Work
- ◆ Milestone

## Three Month Rolling Programme

HKMZB HKBCF - Passenger Clearance Building  
Page 12 of 36

Date	Revision	Checked	Approved




- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

## Three Month Rolling Programme

### HKMZB HKBCF - Passenger Clearance Building

Page 13 of 36

Date	Revision	Checked	Approved




- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

## Three Month Rolling Programme

HKMZB HKBCF - Passenger Clearance Building  
Page 14 of 36

Date	Revision	Checked	Approved




- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 15 of 36

Date	Revision	Checked	Approved






- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

## Three Month Rolling Programme

### HKMZB HKBCF - Passenger Clearance Building

Page 16 of 36

Date	Revision	Checked	Approved




- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

## Three Month Rolling Programme

### HKMZB HKBCF - Passenger Clearance Building

Page 17 of 36


Date	Revision	Checked	Approved



- Actual Work
- Remaining Work
- Critical Remaining Work
- ◆ Milestone


**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 18 of 36

Date	Revision	Checked	Approved



**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 19 of 36


Date	Revision	Checked	Approved



- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 20 of 36


Date	Revision	Checked	Approved



- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 21 of 36


Date	Revision	Checked	Approved



- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 22 of 36

Date	Revision	Checked	Approved




- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

**Three Month Rolling Programme**  
 HKMZH HKBCF - Passenger Clearance Building  
 Page 23 of 36

Date	Revision	Checked	Approved






- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 24 of 36


Date	Revision	Checked	Approved



- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 25 of 36


Date	Revision	Checked	Approved



- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 26 of 36


Date	Revision	Checked	Approved



- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 27 of 36


Date	Revision	Checked	Approved



- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 28 of 36


Date	Revision	Checked	Approved



- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 29 of 36

Date	Revision	Checked	Approved




- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

### Three Month Rolling Programme

HKMZB HKBCF - Passenger Clearance Building

Page 30 of 36

Date	Revision	Checked	Approved




- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 31 of 36

Date	Revision	Checked	Approved






- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 32 of 36

Date	Revision	Checked	Approved




- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

## Three Month Rolling Programme

HKMZB HKBCF - Passenger Clearance Building

Page 33 of 36


Date	Revision	Checked	Approved



- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 34 of 36


Date	Revision	Checked	Approved



- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 35 of 36

Date	Revision	Checked	Approved



- Actual Work
- Remaining Work
- Critical Remaining Work
- Milestone

**Three Month Rolling Programme**  
 HKMZB HKBCF - Passenger Clearance Building  
 Page 36 of 36

Date	Revision	Checked	Approved



# APPENDIX D

---

## Event and Action Plan

## Event/Action Plan for Air Quality Monitoring

EVENT	ACTION			
	ET	IEC	ER	CONTRACTOR
<b>ACTION LEVEL</b>				
1. Exceedance for one sample	<ol style="list-style-type: none"> <li>1. Identify source, investigate the causes of exceedance and propose remedial measures;</li> <li>2. Inform IEC and ER;</li> <li>3. Repeat measurement to confirm finding;</li> <li>4. Increase monitoring frequency to daily.</li> </ol>	<ol style="list-style-type: none"> <li>1. Check monitoring data submitted by ET;</li> <li>2. Check Contractor's working method.</li> </ol>	<ol style="list-style-type: none"> <li>1. Notify Contractor.</li> </ol>	<ol style="list-style-type: none"> <li>1. Rectify any unacceptable practice;</li> <li>2. Amend working methods if appropriate.</li> </ol>
2. Exceedance for two or more consecutive samples	<ol style="list-style-type: none"> <li>1. Identify source;</li> <li>2. Inform IEC and ER;</li> <li>3. Advise the ER on the effectiveness of the proposed remedial measures;</li> <li>4. Repeat measurements to confirm findings;</li> <li>5. Increase monitoring frequency to daily;</li> <li>6. Discuss with IEC and Contractor on remedial actions required;</li> <li>7. If exceedance continues, arrange meeting with IEC and ER;</li> <li>8. If exceedance stops, cease additional monitoring.</li> </ol>	<ol style="list-style-type: none"> <li>1. Check monitoring data submitted by ET;</li> <li>2. Check Contractor's working method;</li> <li>3. Discuss with ET and Contractor on possible remedial measures;</li> <li>4. Advise the ER on the effectiveness of the proposed remedial measures;</li> <li>5. Supervise Implementation of remedial measures.</li> </ol>	<ol style="list-style-type: none"> <li>1. Confirm receipt of notification of failure in writing;</li> <li>2. Notify Contractor;</li> <li>3. Ensure remedial measures properly implemented.</li> </ol>	<ol style="list-style-type: none"> <li>1. Submit proposals for remedial to ER within 3 working days of notification;</li> <li>2. Implement the agreed proposals;</li> <li>3. Amend proposal if appropriate.</li> </ol>

EVENT	ACTION			
	ET	IEC	ER	CONTRACTOR
<b>LIMIT LEVEL</b>				
1. Exceedance for one sample	<ol style="list-style-type: none"> <li>1. Identify source, investigate the causes of exceedance and propose remedial measures;</li> <li>2. Inform ER, Contractor and EPD;</li> <li>3. Repeat measurement to confirm finding;</li> <li>4. Increase monitoring frequency to daily;</li> <li>5. Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and ER informed of the results.</li> </ol>	<ol style="list-style-type: none"> <li>1. Check monitoring data submitted by ET;</li> <li>2. Check Contractor's working method;</li> <li>3. Discuss with ET and Contractor on possible remedial measures;</li> <li>4. Advise the ER on the effectiveness of the proposed remedial measures;</li> <li>5. Supervise implementation of remedial measures.</li> </ol>	<ol style="list-style-type: none"> <li>1. Confirm receipt of notification of failure in writing;</li> <li>2. Notify Contractor;</li> <li>3. Ensure remedial measures properly implemented.</li> </ol>	<ol style="list-style-type: none"> <li>1. Take immediate action to avoid further exceedance;</li> <li>2. Submit proposals for remedial actions to IEC within 3 working days of notification;</li> <li>3. Implement the agreed proposals;</li> <li>4. Amend proposal if appropriate.</li> </ol>
2. Exceedance for two or more consecutive samples	<ol style="list-style-type: none"> <li>1. Notify IEC, ER, Contractor and EPD;</li> <li>2. Identify source;</li> <li>3. Repeat measurement to confirm findings;</li> <li>4. Increase monitoring frequency to daily;</li> <li>5. Carry out analysis of Contractor's working procedures to determine possible mitigation to be implemented;</li> <li>6. Arrange meeting with IEC and ER to discuss the remedial actions to be taken;</li> <li>7. Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and ER informed of the results;</li> <li>8. If exceedance stops, cease additional monitoring.</li> </ol>	<ol style="list-style-type: none"> <li>1. Discuss amongst ER, ET, and Contractor on the potential remedial actions;</li> <li>2. Review Contractor's remedial actions whenever necessary to assure their effectiveness and advise the ER accordingly;</li> <li>3. Supervise the implementation of remedial measures.</li> </ol>	<ol style="list-style-type: none"> <li>1. Confirm receipt of notification of failure in writing;</li> <li>2. Notify Contractor;</li> <li>3. In consultation with the IEC, agree with the Contractor on the remedial measures to be implemented;</li> <li>4. Ensure remedial measures properly implemented;</li> <li>5. If exceedance continues, consider what portion of the work is responsible and instruct the Contractor to stop that portion of work until the exceedance is abated.</li> </ol>	<ol style="list-style-type: none"> <li>1. Take immediate action to avoid further exceedance;</li> <li>2. Submit proposals for remedial actions to IEC within 3 working days of notification;</li> <li>3. Implement the agreed proposals;</li> <li>4. Resubmit proposals if problem still not under control;</li> <li>5. Stop the relevant portion of works as determined by the ER until the exceedance is abated.</li> </ol>



## Event / Action Plan for Construction Noise Monitoring

EVENT	ACTION			
	ET	IEC	ER	CONTRACTOR
Action Level	<ol style="list-style-type: none"> <li>1. Notify IEC and Contractor;</li> <li>2. Identify source, investigate the causes of exceedance and propose remedial measures;</li> <li>3. Report the results of investigation to the IEC, ER and Contractor;</li> <li>4. Discuss with the Contractor and formulate remedial measures;</li> <li>5. Increase monitoring frequency to check mitigation effectiveness.</li> </ol>	<ol style="list-style-type: none"> <li>1. Review the analysed results submitted by the ET;</li> <li>2. Review the proposed remedial measures by the Contractor and advise the ER accordingly;</li> <li>3. Supervise the implementation of remedial measures.</li> </ol>	<ol style="list-style-type: none"> <li>1. Confirm receipt of notification of failure in writing;</li> <li>2. Notify Contractor;</li> <li>3. Require Contractor to propose remedial measures for the analysed noise problem;</li> <li>4. Ensure remedial measures are properly implemented.</li> </ol>	<ol style="list-style-type: none"> <li>1. Submit noise mitigation proposals to IEC;</li> <li>2. Implement noise mitigation proposals.</li> </ol>
Limit Level	<ol style="list-style-type: none"> <li>1. Inform IEC, ER, EPD and Contractor;</li> <li>2. Identify source;</li> <li>3. Repeat measurements to confirm findings;</li> <li>4. Increase monitoring frequency;</li> <li>5. Carry out analysis of Contractor's working procedures to determine possible mitigation to be implemented;</li> <li>6. Inform IEC, ER and EPD the causes and actions taken for the exceedances;</li> <li>7. Assess effectiveness of Contractor's remedial actions and keep IEC, EPD and ER informed of the results;</li> <li>8. If exceedance stops, cease additional monitoring.</li> </ol>	<ol style="list-style-type: none"> <li>1. Discuss amongst ER, ET, and Contractor on the potential remedial actions;</li> <li>2. Review Contractor's remedial actions whenever necessary to assure their effectiveness and advise the ER accordingly;</li> <li>3. Supervise the implementation of remedial measures.</li> </ol>	<ol style="list-style-type: none"> <li>1. Confirm receipt of notification of failure in writing;</li> <li>2. Notify Contractor;</li> <li>3. Require Contractor to propose remedial measures for the analysed noise problem;</li> <li>4. Ensure remedial measures properly implemented;</li> <li>5. If exceedance continues, consider what portion of the work is responsible and instruct the Contractor to stop that portion of work until the exceedance is abated.</li> </ol>	<ol style="list-style-type: none"> <li>1. Take immediate action to avoid further exceedance;</li> <li>2. Submit proposals for remedial actions to IEC within 3 working days of notification;</li> <li>3. Implement the agreed proposals;</li> <li>4. Resubmit proposals if problem still not under control;</li> <li>5. Stop the relevant portion of works as determined by the ER until the exceedance is abated.</li> </ol>

## Event / Action Plan for Water Quality Monitoring

EVENT	ACTION			
	ET	IEC	ER	CONTRACTOR
Action level being exceeded by one sampling day	<ol style="list-style-type: none"> <li>1. Repeat in situ measurement to confirm findings;</li> <li>2. Identify source(s) of impact;</li> <li>3. Inform IEC, contractor and ER;</li> <li>4. Check monitoring data, all plant, equipment and Contractor's working methods;</li> <li>5. Discuss mitigation measures with IEC, ER and Contractor;</li> <li>6. Ensure mitigation measures are implemented;</li> <li>7. Repeat measurement on next day of exceedance to confirm findings.</li> </ol>	<ol style="list-style-type: none"> <li>1. Check monitoring data submitted by ET and Contractor's working methods;</li> <li>2. Discuss with ET and Contractor on possible remedial actions;</li> <li>3. Review the proposed mitigation measures submitted by Contractor and advise the ER accordingly;</li> <li>4. Assess the effectiveness of the implemented mitigation measures.</li> </ol>	<ol style="list-style-type: none"> <li>1. Confirm receipt of notification of non-compliance in writing;</li> <li>2. Discuss with IEC on the proposed mitigation measures;</li> <li>3. Make agreement on mitigation measures to be implemented;</li> <li>4. Ensure mitigation measures are properly implemented.</li> </ol>	<ol style="list-style-type: none"> <li>1. Inform the ER and confirm notification of the non-compliance in writing;</li> <li>2. Rectify unacceptable practice;</li> <li>3. Check all plant and equipment and consider changes of working methods;</li> <li>4. Discuss with ET and IEC on possible remedial actions and propose mitigation measures to IEC and ER;</li> <li>5. Implement the agreed mitigation measures.</li> <li>6. Amend working methods if appropriate.</li> </ol>
Action level being exceeded by two or more consecutive sampling days	<ol style="list-style-type: none"> <li>1. Repeat in situ measurement to confirm findings;</li> <li>2. Identify source(s) of impact;</li> <li>3. Inform IEC, Contractor and ER;</li> <li>4. Check monitoring data, all plant, equipment and Contractor's working methods;</li> <li>5. Discuss mitigation measures with IEC, ER and Contractor;</li> <li>6. Ensure mitigation measures are implemented;</li> <li>7. Increase the monitoring frequency to daily until no exceedance of Action level;</li> <li>8. Repeat measurement on next day of exceedance to confirm findings.</li> </ol>	<ol style="list-style-type: none"> <li>1. Check monitoring data submitted by ET and Contractor's working method;</li> <li>2. Discuss with ET and Contractor on possible remedial actions;</li> <li>3. Review the proposed mitigation measures submitted by Contractor and advise the ER accordingly;</li> <li>4. Assess the effectiveness of the implemented mitigation measures.</li> </ol>	<ol style="list-style-type: none"> <li>1. Confirm receipt of notification of non-compliance in writing;</li> <li>2. Discuss with IEC on the proposed mitigation measures;</li> <li>3. Make agreement on mitigation measures to be implemented;</li> <li>4. Ensure mitigation measures are properly implemented;</li> <li>5. Assess the effectiveness of the implemented mitigation measures.</li> </ol>	<ol style="list-style-type: none"> <li>1. Inform the Engineer and confirm notification of the non-compliance in writing;</li> <li>2. Rectify unacceptable practice;</li> <li>3. Check all plant and equipment and consider changes of working methods;</li> <li>4. Discuss with ET and IEC on possible remedial actions and propose mitigation measures to IEC and ER within 3 working days of notification;</li> <li>5. Implement the agreed mitigation measures;</li> <li>6. Amend working methods if appropriate.</li> </ol>

EVENT	ACTION			
	ET	IEC	ER	CONTRACTOR
Limit level being exceeded by one sampling day	<ol style="list-style-type: none"> <li>1. Repeat <i>in-situ</i> measurement to confirm findings;</li> <li>2. Identify source(s) of impact;</li> <li>3. Inform IEC, Contractor, ER and EPD;</li> <li>4. Check monitoring data, all plant, equipment and Contractor's working methods;</li> <li>5. Discuss mitigation measures with IEC, ER and Contractor;</li> <li>6. Ensure mitigation measures are implemented;</li> <li>7. Increase the monitoring frequency to daily until no exceedance of Limit level.</li> </ol>	<ol style="list-style-type: none"> <li>1. Check monitoring data submitted by ET and Contractor's working method;</li> <li>2. Discuss with ET and Contractor on possible remedial actions;</li> <li>3. Review the proposed mitigation measures submitted by Contractor and advise the ER accordingly;</li> <li>4. Assess the effectiveness of the implemented mitigation measures.</li> </ol>	<ol style="list-style-type: none"> <li>1. Confirm receipt of notification of failure in writing;</li> <li>2. Discuss with IEC, ET and Contractor on the proposed mitigation measures;</li> <li>3. Request Contractor to critically review the working methods;</li> <li>4. Ensure mitigation measures are properly implemented;</li> <li>5. Assess the effectiveness of the implemented mitigation measures.</li> </ol>	<ol style="list-style-type: none"> <li>1. Inform the ER and confirm notification of the non-compliance in writing;</li> <li>2. Rectify unacceptable practice;</li> <li>3. Check all plant and equipment and consider changes of working methods;</li> <li>4. Submit proposal of mitigation measures to ER within 3 working days of notification and discuss with ET, IEC and ER;</li> <li>5. Implement the agreed mitigation measures;</li> <li>6. Amend working methods if appropriate.</li> </ol>
Limit level being exceeded by two or more consecutive sampling days	<ol style="list-style-type: none"> <li>1. Repeat <i>in-situ</i> measurement to confirm findings;</li> <li>2. Identify source(s) of impact;</li> <li>3. Inform IEC, contractor, ER and EPD;</li> <li>4. Check monitoring data, all plant, equipment and Contractor's working methods;</li> <li>5. Discuss mitigation measures with IEC, ER and Contractor;</li> <li>6. Ensure mitigation measures are implemented;</li> <li>7. Increase the monitoring frequency to daily until no exceedance of Limit level for two consecutive days.</li> </ol>	<ol style="list-style-type: none"> <li>1. Check monitoring data submitted by ET and Contractor's working method;</li> <li>2. Discuss with ET and Contractor on possible remedial actions;</li> <li>3. Review the Contractor's mitigation measures whenever necessary to assure their effectiveness and advise the ER accordingly.</li> </ol>	<ol style="list-style-type: none"> <li>1. Confirm receipt of notification of failure in writing;</li> <li>2. Discuss with IEC, ET and Contractor on the proposed mitigation measures;</li> <li>3. Request Contractor to critically review the working methods;</li> <li>4. Make agreement on the mitigation measures to be implemented;</li> <li>5. Ensure mitigation measures are properly implemented;</li> <li>6. Assess the effectiveness of the implemented mitigation measures;</li> <li>7. Consider and instruct, if necessary, the Contractor to slow down or to stop all or part of the construction activities until no exceedance of Limit level.</li> </ol>	<ol style="list-style-type: none"> <li>1. Inform the ER and confirm notification of the non-compliance in writing;</li> <li>2. Take immediate action to avoid further exceedance;</li> <li>3. Rectify unacceptable practice;</li> <li>4. Check all plant and equipment and consider changes of working methods;</li> <li>5. Submit proposal of mitigation measures to ER within 3 working days of notification and discuss with ET, IEC and ER;</li> <li>6. Implement the agreed mitigation measures;</li> <li>7. Resubmit proposals of mitigation measures if problem still not under control;</li> <li>8. As directed by the Engineer, to slow down or to stop all or part of the construction activities until no exceedance of Limit level.</li> </ol>

## Event / Action Plan for Dolphin Monitoring

EVENT	ACTION			
	ET	IEC	ER	CONTRACTOR
Action Level	<ol style="list-style-type: none"> <li>1. Repeat statistical data analysis to confirm findings;</li> <li>2. Review all available and relevant data, including raw data and statistical analysis results of other parameters covered in the EM&amp;A, to ascertain if differences are as a result of natural variation or previously observed seasonal differences;</li> <li>3. Identify source(s) of impact;</li> <li>4. Inform the IEC, ER/SOR and Contractor;</li> <li>5. Check monitoring data.</li> <li>6. Review to ensure all the dolphin protective measures are fully and properly implemented and advise on additional measures if necessary.</li> </ol>	<ol style="list-style-type: none"> <li>1. Check monitoring data submitted by ET and Contractor;</li> <li>2. Discuss monitoring results and finding with the ET and the Contractor.</li> </ol>	<ol style="list-style-type: none"> <li>1. Discuss monitoring with the IEC and any other measures proposed by the ET;</li> <li>2. If ER/SOR is satisfied with the proposal of any other measures, ER/SOR to signify the agreement in writing on the measures to be implemented.</li> </ol>	<ol style="list-style-type: none"> <li>1. Inform the ER/SOR and confirm notification of the non-compliance in writing;</li> <li>2. Discuss with the ET and the IEC and propose measures to the IEC and the ER/SOR;</li> <li>3. Implement the agreed measures.</li> </ol>

EVENT	ACTION			
	ET	IEC	ER	CONTRACTOR
Limit Level	<ol style="list-style-type: none"> <li>1. Repeat statistical data analysis to confirm findings;</li> <li>2. Review all available and relevant data, including raw data and statistical analysis results of other parameters covered in the EM&amp;A, to ascertain if differences are as a result of natural variation or previously observed seasonal differences;</li> <li>3. Identify source(s) of impact;</li> <li>4. Inform the IEC, ER/SOR and Contractor of findings;</li> <li>5. Check monitoring data;</li> <li>6. Repeat review to ensure all the dolphin protective measures are fully and properly implemented and advise on additional measures if necessary.</li> <li>7. If ET proves that the source of impact is caused by any of the construction activity by the works contract, ET to arrange a meeting to discuss with IEC, ER/SOR and Contractor the necessity of additional dolphin monitoring and/or any other potential mitigation measures (e.g., consider to modify the perimeter silt curtain or consider to control/temporarily stop relevant construction activity etc.) and submit to IEC a proposal of additional dolphin monitoring and/or mitigation measures where necessary.</li> </ol>	<ol style="list-style-type: none"> <li>1. Check monitoring data submitted by ET and Contractor;</li> <li>2. Discuss monitoring results and findings with the ET and the Contractor;</li> <li>3. Attend the meeting to discuss with ET, ER/SOR and Contractor the necessity of additional dolphin monitoring and any other potential mitigation measures.</li> <li>4. Review proposals for additional monitoring and any other mitigation measures submitted by ET and Contractor and advise ER/SOR of the results and findings accordingly.</li> <li>5. Supervise / Audit the implementation of additional monitoring and/or any other mitigation measures and advise ER/SOR the results and findings accordingly.</li> </ol>	<ol style="list-style-type: none"> <li>1. Attend the meeting to discuss with ET, IEC and Contractor the necessity of additional dolphin monitoring and any other potential mitigation measures.</li> <li>2. If ER/SOR is satisfied with the proposals for additional dolphin monitoring and/or any other mitigation measures submitted by ET and Contractor and verified by IEC, ER/SOR to signify the agreement in writing on such proposals and any other mitigation measures.</li> <li>3. Supervise the implementation of additional monitoring and/or any other mitigation measures.</li> </ol>	<ol style="list-style-type: none"> <li>1. Inform the ER/SOR and confirm notification of the non-compliance in writing;</li> <li>2. Attend the meeting to discuss with ET, IEC and ER/SOR the necessity of additional dolphin monitoring and any other potential mitigation measures.</li> <li>3. Jointly submit with ET to IEC a proposal of additional dolphin monitoring and/or any other mitigation measures when necessary.</li> <li>4. Implement the agreed additional dolphin monitoring and/or any other mitigation measures.</li> </ol>



## **APPENDIX E**

---

### **Implementation Schedule for Environmental Mitigation Measures (EMIS)**

Contract No. HY/2013/01 – Hong Kong Zhuhai and Macao Bridge Hong Kong Boundary Crossing Facilities – Passenger Clearance Building

Implementation Schedule for Environmental Mitigation Measures

EIA Ref.	EM&A Log Ref	Recommended Mitigation Measures	Objectives of the Recommended Measures & Main Concerns to address	Who to implement the measures?	Location of the measures	When to implement the measures?	What requirements or standards for the measures to achieve?	Implementation Status
<b>Air Quality</b>								
S5.5.6.1	A1	1) The contractor shall follow the procedures and requirements given in the Air Pollution Control (Construction Dust) Regulation	Good construction site practices to control the dust impact at the nearby sensitive receivers to within the relevant criteria.	Contractor	All construction sites	Construction stage	To control the dust impact to within the HKAQO and TM-EIA criteria (Ref. 1- hr and 24hr TSP levels are 500 $\mu\text{g}\text{m}^{-3}$ and 260 $\mu\text{g}\text{m}^{-3}$ , respectively)	√
S5.5.6.2	A2	2) Proper watering of exposed spoil should be undertaken throughout the construction phase: <ul style="list-style-type: none"> <li>• Any excavated or stockpile of dusty material should be covered entirely by impervious sheeting or sprayed with water to maintain the entire surface wet and then removed or backfilled or reinstated where practicable within 24 hours of the excavation or unloading;</li> <li>• Any dusty materials remaining after a stockpile is removed should be wetted with water and cleared from the surface of roads;</li> <li>• A stockpile of dusty material should not be extend beyond the pedestrian barriers, fencing or traffic cones.</li> <li>• The load of dusty materials on a vehicle leaving a construction site should be covered entirely by impervious sheeting to ensure that the dusty materials do not leak from the vehicle;</li> <li>• Where practicable, vehicle washing facilities with high pressure water jet should be provided at every discernible or designated vehicle exit point. The area where vehicle washing takes place and the road section between the washing facilities and the exit point should be paved with concrete, bituminous materials or hardcores;</li> <li>• The portion of any road leading only to construction site that is within 30m of a vehicle entrance or exit should be kept clear of dusty materials;</li> <li>• Surfaces where any pneumatic or power-driven drilling, cutting, polishing or other mechanical breaking operation takes place should be sprayed with water or a dust suppression chemical continuously;</li> <li>• Any area that involves demolition activities should be sprayed with water or a dust suppression chemical immediately prior to, during and immediately after the activities so as to maintain the entire surface wet;</li> </ul>	Good construction site practices to control the dust impact at the nearby sensitive receivers to within the relevant criteria.	Contractor	All construction sites	Construction stage	To control the dust impact to within the HKAQO and TM-EIA criteria (Ref. 1- hr and 24hr TSP levels are 500 $\mu\text{g}\text{m}^{-3}$ and 260 $\mu\text{g}\text{m}^{-3}$ , respectively)	√ √ √ √ √ √ √

EIA Ref.	EM&A Log Ref	Recommended Mitigation Measures	Objectives of the Recommended Measures & Main Concerns to address	Who to implement the measures?	Location of the measures	When to implement the measures?	What requirements or standards for the measures to achieve?	Implementation Status
S5.5.6.2	A2	<ul style="list-style-type: none"> <li>Where a scaffolding is erected around the perimeter of a building under construction, effective dust screens, sheeting or netting should be provided to enclose the scaffolding from the ground floor level of the building, or a canopy should be provided from the first floor level up to the highest level of the scaffolding;</li> <li>Any skip hoist for material transport should be totally enclosed by impervious sheeting;</li> <li>Every stock of more than 20 bags of cement or dry pulverised fuel ash (PFA) should be covered entirely by impervious sheeting or placed in an area sheltered on the top and the 3 sides;</li> <li>Cement or dry PFA delivered in bulk should be stored in a closed silo fitted with an audible high level alarm which is interlocked with the material filling line and no overfilling is allowed;</li> <li>Loading, unloading, transfer, handling or storage of bulk cement or dry PFA should be carried out in a totally enclosed system or facility, and any vent or exhaust should be fitted with an effective fabric filter or equivalent air pollution control system; and</li> <li>Exposed earth should be properly treated by compaction, turfing, hydroseeding, vegetation planting or sealing with latex, vinyl, bitumen, shotcrete or other suitable surface stabiliser within six months after the last construction activity on the construction site or part of the construction site where the exposed earth lies.</li> </ul>	Good construction site practices to control the dust impact at the nearby sensitive receivers to within the relevant criteria.	Contractor	All construction sites	Construction stage	To control the dust impact to within the HKAQO and TM-EIA criteria (Ref. 1- hr and 24hr TSP levels are 500 $\mu\text{g}\text{m}^{-3}$ and 260 $\mu\text{g}\text{m}^{-3}$ , respectively)	<p>√</p> <p>√</p> <p>√</p> <p>√</p> <p>√</p>
S5.5.6.4	A3	The Contractor should undertake proper watering on all exposed spoil (with at least 8 times per day) throughout the construction phase.	Control construction dust	Contractor	All construction sites	Construction stage	To control the dust impact	√
S5.5.6.5	A4	Engineer to incorporate the controlled measures into the Particular Specification (PS) for the civil work. The PS should also draw the contractor's attention to the relevant latest Practice Notes issued by EPD.	Control construction dust	Engineer	All construction sites	Design Stage	Air Pollution Control (Construction Dust) Regulation	√



EIA Ref.	EM&A Log Ref	Recommended Mitigation Measures	Objectives of the Recommended Measures & Main Concerns to address	Who to implement the measures?	Location of the measures	When to implement the measures?	What requirements or standards for the measures to achieve?	Implementation Status
S5.5.6.5	A5	Implement regular dust monitoring under EM&A programme during the construction stage.	Monitor the 24 hr and 1hr TSP levels at the representative dust monitoring stations to ensure compliance with relevant criteria throughout the construction period.	Contractor	Selected representative dust monitoring station	Construction stage	<ul style="list-style-type: none"> <li>Air Pollution Control (Construction Dust) Regulation</li> <li>To control the dust impact to within the HKAQO and TM-EIA criteria (Ref. 1- hr and 24hr TSP levels are 500 <math>\mu\text{g}\text{m}^{-3}</math> and 260 <math>\mu\text{g}\text{m}^{-3}</math>, respectively)</li> </ul>	<p style="text-align: center;">√</p> (The dust monitoring works (Station AMS6) under EM&A programme for the Contract is covered by Contract No. HY/2011/03. Monitoring stations AMS2, AMS3B and AMS7 for the Contract are covered by Contract No. HY/2013/01)
S5.5.7.1	A6	The following mitigation measures should be adopted to prevent fugitive dust emissions for concrete batching plant: <ul style="list-style-type: none"> <li>Loading, unloading, handling, transfer or storage of any dusty materials should be carried out in totally enclosed system;</li> <li>All dust-laden air or waste gas generated by the process operations should be properly extracted and vented to fabric filtering system to meet the emission limits for TSP;</li> <li>Vents for all silos and cement/pulverised fuel ash (PFA) weighing scale should be fitted with fabric filtering system;</li> <li>The materials which may generate airborne dusty emissions should be wetted by water spray system;</li> <li>All receiving hoppers should be enclosed on three sides up to 3m above unloading point;</li> <li>All conveyor transfer points should be totally enclosed;</li> <li>All access and route roads within the premises should be paved and wetted; and</li> <li>Vehicle cleaning facilities should be provided and used by all concrete trucks before leaving the premises to wash off any dust on the wheels and/or body.</li> </ul>	Monitor the 24 hr and 1hr TSP levels at the representative dust monitoring stations to ensure compliance with relevant criteria throughout the construction period.	Contractor	Selected representative dust monitoring station	Construction stage	<ul style="list-style-type: none"> <li>Air Pollution Control (Construction Dust) Regulation</li> <li>To control the dust impact to within the HKAQO and TM-EIA criteria (Ref. 1- hr and 24hr TSP levels are 500 <math>\mu\text{g}\text{m}^{-3}</math> and 260 <math>\mu\text{g}\text{m}^{-3}</math>, respectively)</li> </ul>	N/A
S5.5.2.7	A7	The following mitigation measures should be adopted to prevent fugitive dust emissions at barging point: <ul style="list-style-type: none"> <li>All road surface within the barging facilities will be paved;</li> <li>Dust enclosures will be provided for the loading ramp;</li> <li>Vehicles will be required to pass through designated wheels wash facilities; and</li> <li>Continuous water spray at the loading points.</li> </ul>	Control construction dust	Contractor	All construction sites	Construction stage	Air Pollution Control (Construction Dust) Regulation	N/A

EIA Ref.	EM&A Log Ref	Recommended Mitigation Measures	Objectives of the Recommended Measures & Main Concerns to address	Who to implement the measures?	Location of the measures	When to implement the measures?	What requirements or standards for the measures to achieve?	Implementation Status
<b>Construction Noise (Air borne)</b>								
S6.4.10	N1	1) Use of good site practices to limit noise emissions by considering the following: <ul style="list-style-type: none"> <li>only well-maintained plant should be operated on-site and plant should be serviced regularly during the construction programme;</li> <li>machines and plant (such as trucks, cranes) that may be in intermittent use should be shut down between work periods or should be throttled down to a minimum;</li> <li>plant known to emit noise strongly in one direction, where possible, be orientated so that the noise is directed away from nearby NSRs;</li> <li>silencers or mufflers on construction equipment should be properly fitted and maintained during the construction works;</li> <li>mobile plant should be sited as far away from NSRs as possible and practicable;</li> <li>material stockpiles, mobile container site office and other structures should be effectively utilised, where practicable, to screen noise from on-site construction activities.</li> </ul>	Control construction airborne noise by means of good site practices	Contractor	All construction sites	Construction stage	Noise Control Ordinance	 √  √  √  √  √  √
S6.4.11	N2	2) Install temporary hoarding located on the site boundaries between noisy construction activities and NSRs. The conditions of the hoardings shall be properly maintained throughout the construction period.	Reduce the construction noise levels at low-level zone of NSRs through partial screening.	Contractor	All construction sites	Construction stage	<ul style="list-style-type: none"> <li>Noise Control Ordinance</li> <li>Annex 5, TM-EIA</li> </ul>	N/A
S6.4.12	N3	3) Install movable noise barriers (typically density @14kg/m <sup>2</sup> ), acoustic mat or full enclosure close to noisy plants including air compressor, generators, saw.	Screen the noisy plant items to be used at all construction sites	Contractor	For plant items listed in Appendix 6D of the EIA report at all construction sites	Construction stage	<ul style="list-style-type: none"> <li>Noise Control Ordinance</li> <li>Annex 5, TM-EIA</li> <li>75dB(A) for residential premises</li> <li>The movable barrier should achieve at least 5dB(A) and the full enclosure should be designed to achieve 10dB(A)</li> </ul>	N/A

EIA Ref.	EM&A Log Ref	Recommended Mitigation Measures	Objectives of the Recommended Measures & Main Concerns to address	Who to implement the measures?	Location of the measures	When to implement the measures?	What requirements or standards for the measures to achieve?	Implementation Status
S6.4.13	N4	4) Select "Quiet plants" which comply with the BS 5228 Part 1 or TM standards.	Reduce the noise levels of plant items	Contractor	For plant items listed in Appendix 6D of the EIA report at all construction sites	Construction stage	<ul style="list-style-type: none"> <li>Noise Control Ordinance &amp; its TM</li> <li>Annex 5, TM-EIA</li> </ul>	√
S6.4.14	N5	5) Sequencing operation of construction plants where practicable.	Operate sequentially within the same work site to reduce the construction airborne noise	Contractor	All construction sites where practicable	Construction stage	<ul style="list-style-type: none"> <li>Noise Control Ordinance</li> <li>Annex 5, TM-EIA</li> </ul>	√
S6.4.14	N6	6) Implement a noise monitoring under EM&A programme.	Monitor the construction noise levels at the selected representative locations	Contractor	Selected representative noise monitoring station	Construction stage	<ul style="list-style-type: none"> <li>Noise Control Ordinance</li> <li>Annex 5, TM-EIA</li> <li>75dB(A) for residential premises</li> </ul>	(ET of Contract No. HY/2013/01 is responsible conducting monitoring for entire HKBCF) √
<b>Sediment</b>								
S7.3	S1	1) The requirements as recommended in ETWB TC 34/2002 Management of Dredged/Excavated Sediment shall be included in the Particular Specification as appropriate.	Develop sediment disposal arrangement	Engineer	All construction sites	Design stage	<ul style="list-style-type: none"> <li>Waste Disposal Ordinance</li> <li>ETW B TC 34/2002</li> </ul>	N/A
<b>Waste Management (Construction Waste)</b>								
S8.3.8	WM1	<u>Construction and Demolition Material</u>  The following mitigation measures should be implemented in handling the waste: <ul style="list-style-type: none"> <li>Maintain temporary stockpiles and reuse excavated fill material for backfilling and reinstatement;</li> <li>Carry out on-site sorting;</li> <li>Make provisions in the Contract documents to allow and promote the use of recycled aggregates where appropriate;</li> <li>Adopt 'Selective Demolition' technique to demolish the existing structures and facilities with a view to recovering broken concrete effectively for recycling purpose, where possible;</li> <li>Implement a trip-ticket system for each works contract to ensure that the disposal of C&amp;D materials are properly documented and verified; and</li> </ul>	Good site practice to minimize the waste generation and recycle the C&D materials as far as practicable so as to reduce the amount for final disposal	Contractor	All construction sites	Construction stage	<ul style="list-style-type: none"> <li>Land (Miscellaneous Provisions) Ordinance</li> <li>Waste Disposal Ordinance</li> <li>ETW BTC 19/2005</li> </ul>	√ √ √ √

EIA Ref.	EM&A Log Ref	Recommended Mitigation Measures	Objectives of the Recommended Measures & Main Concerns to address	Who to implement the measures?	Location of the measures	When to implement the measures?	What requirements or standards for the measures to achieve?	Implementation Status
S8.3.8	WM1	<ul style="list-style-type: none"> <li>Implement an enhanced Waste Management Plan similar to ETW BTC (Works) No. 19/2005 – “Environmental Management on Construction Sites” to encourage on-site sorting of C&amp;D materials and to minimize their generation during the course of construction.</li> <li>In addition, disposal of the C&amp;D materials onto any sensitive locations such as agricultural lands, etc. should be avoided. The Contractor shall propose the final disposal sites to the Project Proponent and get its approval before implementation.</li> </ul>	Good site practice to minimize the waste generation and recycle the C&D materials as far as practicable so as to reduce the amount for final disposal	Contractor	All construction sites	Construction stage	<ul style="list-style-type: none"> <li></li> </ul>	<p>√</p> <p>√</p>
S8.3.9- S8.3.11	WM2	<p><u>C&amp;D Waste</u></p> <ul style="list-style-type: none"> <li>Standard formwork or pre-fabrication should be used as far as practicable in order to minimise the arising of C&amp;D materials. The use of more durable formwork or plastic facing for the construction works should be considered. Use of wooden hoardings should not be used, as in other projects. Metal hoarding should be used to enhance the possibility of recycling. The purchasing of construction materials will be carefully planned in order to avoid over ordering and wastage.</li> <li>The Contractor should recycle as much of the C&amp;D materials as possible on-site. Public fill and C&amp;D waste should be segregated and stored in different containers or skips to enhance reuse or recycling of materials and their proper disposal. Where practicable, concrete and masonry can be crushed and used as fill. Steel reinforcement bar can be used by scrap steel mills. Different areas of the sites should be considered for such segregation and storage.</li> </ul>	Good site practice to minimize the waste generation and recycle the C&D materials as far as practicable so as to reduce the amount for final disposal	Contractor	All construction sites	Construction stage	<ul style="list-style-type: none"> <li>Land (Miscellaneous Provisions) Ordinance</li> <li>Waste Disposal Ordinance</li> <li>ETWB TC 19/2005</li> </ul>	<p>√</p> <p>√</p>
S8.2.12- S8.3.15	WM3	<p><u>Chemical Waste</u></p> <ul style="list-style-type: none"> <li>Chemical waste that is produced, as defined by Schedule 1 of the Waste Disposal (Chemical Waste) (General) Regulation, should be handled in accordance with the Code of Practice on the Packaging, Labelling and Storage of Chemical Wastes.</li> <li>Containers used for the storage of chemical wastes should be suitable for the substance they are holding, resistant to corrosion, maintained in a good condition, and securely closed; have a capacity of less than 450 liters unless the specification has been approved by the EPD; and display a label in English and Chinese in accordance with instructions prescribed in Schedule 2 of the regulation.</li> <li>The storage area for chemical wastes should be clearly labelled and used solely for the storage of chemical waste; enclosed on at least 3 sides; have an impermeable floor and bunding of sufficient capacity to accommodate 110% of the volume of the largest container or 20 % of the total volume of waste stored in that area, whichever is the greatest; have adequate ventilation; covered to prevent rainfall entering; and arranged so that incompatible materials are adequately separated.</li> </ul>	Control the chemical waste and ensure proper storage, handling and disposal.	Contractor	All construction sites	Construction stage	<ul style="list-style-type: none"> <li>Waste Disposal (Chemical Waste) (General) Regulation</li> <li>Code of Practice on the Packaging, Labelling and Storage of Chemical Waste</li> </ul>	<p>√</p> <p>√</p> <p>√</p>

EIA Ref.	EM&A Log Ref	Recommended Mitigation Measures	Objectives of the Recommended Measures & Main Concerns to address	Who to implement the measures?	Location of the measures	When to implement the measures?	What requirements or standards for the measures to achieve?	Implementation Status
S8.2.12- S8.3.15	WM3	<ul style="list-style-type: none"> <li>Disposal of chemical waste should be via a licensed waste collector; be to a facility licensed to receive chemical waste, such as the Chemical Waste Treatment Centre which also offers a chemical waste collection service and can supply the necessary storage containers; or be to a reuser of the waste, under approval from the EPD.</li> </ul>	Control the chemical waste and ensure proper storage, handling and disposal.	Contractor	All construction sites	Construction stage		√
S8.3.16	WM4	<p><u>Sewage</u></p> <ul style="list-style-type: none"> <li>Adequate numbers of portable toilets should be provided for the workers. The portable toilets should be maintained in a state, which will not deter the workers from utilizing these portable toilets. Night soil should be collected by licensed collectors regularly.</li> </ul>	Proper handling of sewage from worker to avoid odour, pest and litter impacts	Contractor	All construction sites	Construction stage	<ul style="list-style-type: none"> <li>Waste Disposal Ordinance</li> </ul>	√
S8.3.17	WM5	<p><u>General Refuse</u></p> <ul style="list-style-type: none"> <li>General refuse generated on-site should be stored in enclosed bins or compaction units separately from construction and chemical wastes.</li> <li>A reputable waste collector should be employed by the Contractor to remove general refuse from the site, separately from construction and chemical wastes, on a daily basis to minimize odour, pest and litter impacts. Burning of refuse on construction sites is prohibited by law.</li> <li>Aluminium cans are often recovered from the waste stream by individual collectors if they are segregated and made easily accessible. Separate labelled bins for their deposit should be provided if feasible.</li> <li>Office wastes can be reduced through the recycling of paper if volumes are large enough to warrant collection. Participation in a local collection scheme should be considered by the Contractor. In addition, waste separation facilities for paper, aluminum cans, plastic bottles etc., should be provided.</li> <li>Training should be provided to workers about the concepts of site cleanliness and appropriate waste management procedure, including reduction, reuse and recycling of wastes.</li> </ul>	Minimize production of the general refuse and avoid odour, pest and litter impacts	Contractor	All construction sites	Construction stage	<ul style="list-style-type: none"> <li>Waste Disposal Ordinance</li> </ul>	√ √ √ √ √

EIA Ref.	EM&A Log Ref	Recommended Mitigation Measures	Objectives of the Recommended Measures & Main Concerns to address	Who to implement the measures?	Location of the measures	When to implement the measures?	What requirements or standards for the measures to achieve?	Implementation Status
<b>Water Quality (Construction Phase)</b>								
S.9.11.1.7	W1	<p>Mitigation during the marine works to reduce impacts to within acceptable levels have been recommended and will comprise a series of measures that restrict the method and sequencing of backfilling, as well as protection measures. Details of the measures are provided below:</p> <ul style="list-style-type: none"> <li>• Reclamation filling for the Project shall not proceed until at least 200m of leading seawall at the reclamation area formed above +2.2mPD, unless otherwise agreement was obtained from EPD, except for the 300m gaps for marine access. All underwater filling works shall be carried out behind seawalls to avoid dispersion of suspended solids outside the Project limit;</li> </ul>	To control construction water quality	Contractor	During filling	Construction stage	TM-EIAO	√
S.9.11.1.7	W1	<ul style="list-style-type: none"> <li>• Except for the filling of the cellular structures, not more than 15% public fill shall be used for reclamation filling below +2.5mPD during construction of the seawall;</li> <li>• After the seawall is completed except for the 300m marine access as indicated in the EPs, not more than 30% public fill shall be used for reclamation filling below +2.5mPD, unless otherwise agreement from EPD was obtained;</li> <li>• Upon completion of 200m leading seawall, no more than a total of 60 filling barge trips per day shall be made with a cumulative maximum daily filling rate of 60,000 m3 for HKBCF and TMCLKL southern landfall reclamation during the filling operation; and</li> <li>• Upon completion of the whole section of seawall except for the 300m marine access as indicated in the EPs, no more than a total of 190 filling barge trips per day shall be made with a cumulative maximum daily filling rate of 190,000 m3 for the remaining filling operations for HKBCF and TMCLKL southern landfall reclamation.</li> <li>• Floating type perimeter silt curtains shall be around the HKBCF site before the commencement of marine works. Staggered layers of silt curtain shall be provided to prevent sediment loss at navigation accesses. The length of each staggered layers shall be at least 200m;</li> <li>• Single layer silt curtain to be applied around the North-east airport water intake;</li> <li>• The silt-curtains should be maintained in good condition to ensure the sediment plume generated from filling be confined effectively within the site boundary;</li> <li>• The filling works shall be scheduled to spread the works evenly over a working day;</li> <li>• Cellular structure shall be used for seawall construction;</li> <li>• A layer of geotextile shall be placed on top of the seabed before any filling activities take place inside the cellular structures to form the seawall;</li> </ul>	To control construction water quality	Contractor	During filling	Construction stage	TM-EIAO	√ √ √ √ √ √ √ √ √ √ √ √ √

EIA Ref.	EM&A Log Ref	Recommended Mitigation Measures	Objectives of the Recommended Measures & Main Concerns to address	Who to implement the measures?	Location of the measures	When to implement the measures?	What requirements or standards for the measures to achieve?	Implementation Status
S.9.11.1.7	W1	<ul style="list-style-type: none"> <li>The conveyor belts shall be fitted with windboards and conveyor release points shall be covered with curtain to prevent any spillage of filling materials onto the surrounding waters; and</li> <li>An additional layer of silt curtain shall be installed near the active stone column installation points. A layer of geotextile with stone blanket on top shall be placed on the seabed prior to stone column installation works.</li> </ul>	To control construction water quality	Contractor	During filling	Construction stage	TM-EIAO	<p>√</p> <p>√</p>
S.9.11.1.7	W2	<p><u>Land Works</u></p> <p>General construction activities on land should also be governed by standard good working practice. Specific measures to be written into the works contracts should include:</p> <ul style="list-style-type: none"> <li>wastewater from temporary site facilities should be controlled to prevent direct discharge to surface or marine waters;</li> </ul>	To control construction water quality	Contractor	Land-based works areas	Construction stage	TM-EIAO	<p>√</p>
S.9.11.1.7	W2	<ul style="list-style-type: none"> <li>sewage effluent and discharges from on-site kitchen facilities shall be directed to Government sewer in accordance with the requirements of the WPCO or collected for disposal offsite. The use of soakaways shall be avoided;</li> <li>storm drainage shall be directed to storm drains via adequately designed sand/silt removal facilities such as sand traps, silt traps and sediment basins. Channels, earth bunds or sand bag barriers should be provided on site to properly direct stormwater to such silt removal facilities. Catchpits and perimeter channels should be constructed in advance of site formation works and earthworks;</li> <li>silt removal facilities, channels and manholes shall be maintained and any deposited silt and grit shall be removed regularly, including specifically at the onset of and after each rainstorm;</li> <li>temporary access roads should be surfaced with crushed stone or gravel;</li> <li>rainwater pumped out from trenches or foundation excavations should be discharged into storm drains via silt removal facilities;</li> <li>measures should be taken to prevent the washout of construction materials, soil, silt or debris into any drainage system;</li> <li>open stockpiles of construction materials (e.g. aggregates and sand) on site should be covered with tarpaulin or similar fabric during rainstorms;</li> <li>manholes (including any newly constructed ones) should always be adequately covered and temporarily sealed so as to prevent silt, construction materials or debris from getting into the drainage system, and to prevent storm run-off from getting into foul sewers;</li> <li>discharges of surface run-off into foul sewers must always be prevented in order not to unduly overload the foul sewerage system;</li> </ul>	To control construction water quality	Contractor	Land-based works areas	Construction stage	TM-EIAO	<p>√</p> <p>√</p> <p>√</p> <p>√</p> <p>√</p> <p>√</p> <p>√</p> <p>√</p> <p>√</p>

EIA Ref.	EM&A Log Ref	Recommended Mitigation Measures	Objectives of the Recommended Measures & Main Concerns to address	Who to implement the measures?	Location of the measures	When to implement the measures?	What requirements or standards for the measures to achieve?	Implementation Status
S9.11.1.7	W2	<ul style="list-style-type: none"> <li>all vehicles and plant should be cleaned before they leave the construction site to ensure that no earth, mud or debris is deposited by them on roads. A wheel washing bay should be provided at every site exit;</li> <li>wheel wash overflow shall be directed to silt removal facilities before being discharged to the storm drain;</li> <li>the section of construction road between the wheel washing bay and the public road should be surfaced with crushed stone or coarse gravel;</li> <li>wastewater generated from concreting, plastering, internal decoration, cleaning work and other similar activities, shall be screened to remove large objects;</li> <li>vehicle and plant servicing areas, vehicle wash bays and lubrication facilities shall be located under roofed areas. The drainage in these covered areas shall be connected to foul sewers via a petrol interceptor in accordance with the requirements of the WPCO or collected for off site disposal;</li> <li>the contractors shall prepare an oil / chemical cleanup plan and ensure that leakages or spillages are contained and cleaned up immediately;</li> <li>waste oil should be collected and stored for recycling or disposal, in accordance with the Waste Disposal Ordinance;</li> <li>all fuel tanks and chemical storage areas should be provided with locks and be sited on sealed areas. The storage areas should be surrounded by bunds with a capacity equal to 110% of the storage capacity of the largest tank; and</li> <li>surface run-off from bunded areas should pass through oil/grease traps prior to discharge to the stormwater system.</li> </ul>	To control construction water quality	Contractor	Land-based works areas	Construction stage	TM-EIAO	<ul style="list-style-type: none"> <li>√</li> <li>√</li> <li>√</li> <li>√</li> <li>√</li> <li>√</li> <li>√</li> <li>√</li> </ul>
S.9.14	W3	<ul style="list-style-type: none"> <li>Implement a water quality monitoring programme.</li> </ul>	To control water quality	Contractor	Selected representative water quality monitoring station	Construction stage	<ul style="list-style-type: none"> <li>TM-EIAO</li> <li>Water Pollution Control Ordinance</li> </ul>	<ul style="list-style-type: none"> <li>√</li> </ul> <p>(ET of ContractNo. HY/2013/01 is responsible conducting monitoring for entire HKBCF)</p>



EIA Ref.	EM&A Log Ref	Recommended Mitigation Measures	Objectives of the Recommended Measures & Main Concerns to address	Who to implement the measures?	Location of the measures	When to implement the measures?	What requirements or standards for the measures to achieve?	Implementation Status
<b>Ecology (Construction Phase)</b>								
S10.7	E1	<ul style="list-style-type: none"> <li>Install silt curtain during the construction</li> <li>Limit works fronts</li> <li>Construct seawall prior to reclamation filling where practicable</li> <li>Good site practices</li> <li>Strict enforcement of no marine dumping</li> <li>Site runoff control</li> <li>Spill response plan</li> </ul>	Prevent Sedimentation from Land-based works areas	Contractor	Seawall, reclamation area	During construction	TM-Water	<ul style="list-style-type: none"> <li>√</li> <li>√</li> <li>√</li> <li>√</li> <li>√</li> <li>√</li> </ul>
S10.7	E2	<ul style="list-style-type: none"> <li>Watering to reduce dust generation; prevention of siltation of freshwater habitats; Site runoff should be desilted, to reduce the potential for suspended sediments, organics and other contaminants to enter streams and standing freshwater.</li> </ul>	Prevent Sedimentation from Land-based works areas	Contractor	Land-based works areas	During construction	TM-Water	<ul style="list-style-type: none"> <li>√</li> </ul>
S10.7	E3	<ul style="list-style-type: none"> <li>Good site practices, including strictly following the permitted works hours, using quieter machines where practicable, and avoiding excessive lightings during night time</li> </ul>	Prevent disturbance to terrestrial fauna and habitats	Contractor	Land-based works areas	During construction	TM-Water	<ul style="list-style-type: none"> <li>√</li> </ul>
S10.7	E4	<ul style="list-style-type: none"> <li>Dolphin Exclusion Zone</li> <li>Dolphin Watching plan</li> </ul>	Minimise marine traffic disturbance on dolphins	Contractor	Marine Works	During construction	TM-Water	<ul style="list-style-type: none"> <li>√</li> <li>√</li> </ul>
S10.7	E5	<ul style="list-style-type: none"> <li>Decouple compressors and other equipment on working vessels</li> <li>Proposal on design and implementation of acoustic decoupling measures applied during reclamation works</li> <li>Avoidance of percussive piling</li> </ul>	Minimise marine traffic disturbance on dolphins	Contractor	Marine Works	During construction	TM-Water	<ul style="list-style-type: none"> <li>√</li> <li>√</li> <li>√</li> </ul>
S10.7	E6	<ul style="list-style-type: none"> <li>Control vessel speed</li> <li>Skipper training</li> <li>Predefined and regular routes for working vessels; avoid Brother Islands.</li> </ul>	Minimise marine traffic disturbance on dolphins	Contractor	Marine Traffic	During construction	TM-Water	<ul style="list-style-type: none"> <li>√</li> <li>√</li> <li>√</li> </ul>
S10.7	E7	<ul style="list-style-type: none"> <li>Vessel based dolphin monitoring</li> </ul>	Minimise marine traffic disturbance on dolphins	Contractor	Northeast and Northwest Lantau	During construction	TM-Water	<ul style="list-style-type: none"> <li>√</li> </ul> <p>(ET of Contract No. HY/2013/01 is responsible conducting monitoring for entire HKBCF.)</p>
<b>Fisheries</b>								
S11.7	F1	<ul style="list-style-type: none"> <li>Reduce re-suspension of sediments</li> <li>Limit works fronts</li> <li>Good site practices</li> <li>Strict enforcement of no marine dumping</li> <li>Spill response plan</li> </ul>	Minimise impacts on marine water quality impacts	Marine Department	Seawall, reclamation area	During operation		<ul style="list-style-type: none"> <li>√</li> <li>√</li> <li>√</li> <li>√</li> <li>√</li> </ul>
S11.7	F2	<ul style="list-style-type: none"> <li>Install silt-grease trap in the drainage system collecting surface runoff</li> </ul>	Minimise impacts on marine water quality impacts	Marine Department	Reclamation area	During operation		<ul style="list-style-type: none"> <li>√</li> </ul>

EIA Ref.	EM&A Log Ref	Recommended Mitigation Measures	Objectives of the Recommended Measures & Main Concerns to address	Who to implement the measures?	Location of the measures	When to implement the measures?	What requirements or standards for the measures to achieve?	Implementation Status
S11.7	F4	<ul style="list-style-type: none"> <li>Maritime Oil Spill Response Plan (MOSRP);</li> <li>Contingency plan.</li> </ul>	Minimise impacts on marine water quality impacts	Marine Department	HKBCF	During operation		N/A
<b>Landscape &amp; Visual (Detailed Design Phase)</b>								
S14.3.3.1	LV1	<p>General design measures include:</p> <ul style="list-style-type: none"> <li>Roadside planting and planting along the edge of the HKBCF Island is proposed;</li> <li>Transplanting of mature trees in good health and amenity value where appropriate and reinstatement of areas disturbed during construction by compensatory hydro-seeding and planting;</li> <li>Protection measures for the trees to be retained during construction activities;</li> <li>Optimizing the sizes and spacing of the bridge columns; Fine-tuning the location of the bridge columns to avoid visually-sensitive locations;</li> <li>Maximizing new tree, shrub and other vegetation planting to compensate tree felled and vegetation removed;</li> <li>Providing planting area around peripheral of HKBCF for tree planting screening effect;</li> <li>Providing salt-tolerant native trees along the planter strip at affected seawall and newly reclaimed coastline;</li> </ul>	Minimise visual & landscape impact	Detailed designer	HKBCF	Design Stage		N/A
S14.3.3.1	LV1	<ul style="list-style-type: none"> <li>For HKBCF, providing aesthetic architectural design on the related buildings (e.g. similar materials for PCB building facade to Airport buildings, roof planting and subtle materials for other facilities buildings and so on), and the related infrastructure (e.g. parapet planting and transparent cover for elevated footbridges) to provide harmonious atmosphere of the HKBCF; and</li> <li>Fine-tuning the sizes of the structural members to minimize the bulkiness of buildings and adjustment of building arrangement to minimise disturbance to surrounding vegetation in the HKBCF.</li> </ul>	Minimise visual & landscape impact	Detailed designer	HKBCF	Design Stage		N/A

EIA Ref.	EM&A Log Ref	Recommended Mitigation Measures	Objectives of the Recommended Measures & Main Concerns to address	Who to implement the measures?	Location of the measures	When to implement the measures?	What requirements or standards for the measures to achieve?	Implementation Status
<b>Landscape &amp; Visual (Construction Phase)</b>								
S14.3.3.3	LV2	<p>Mitigate both Landscape and Visual Impacts</p> <ul style="list-style-type: none"> <li>Grass-hydroseed bare soil surface and stock pile areas.</li> <li>Add planting strip and automatic irrigation system if appropriate at some portions of bridge footbridge to screen bridge and traffic.</li> <li>Not applicable as this is for HKLR.</li> <li>For HKBCF, providing aesthetic architectural design on the related buildings (e.g. similar materials for PCB building facade to Airport buildings, roof planting and subtle materials for other facilities buildings and so on), and the related infrastructure (e.g. parapet planting and transparent cover for elevated footbridges) to provide harmonious atmosphere of the HKBCF.</li> <li>Vegetation reinstatement and upgrading to disturbed areas</li> <li>Maximizing new tree shrub and other vegetation planting to compensate tree felled and vegetation removed</li> <li>Providing planting area around peripheral of HKBCF for tree planting screening effect;</li> <li>Plant salt-tolerant native and shrubs etc along the planter strip at affected seawall.</li> <li>Reserve of loose natural granite rocks for re-use. Provide new coastline to adopt "natural-look" by means of using armour rocks in the form of natural rock materials and planting strip area accommodating screen buffer to enhance "natural-look" of the new coastline.</li> </ul>	Minimise visual & landscape impact	Contractor	HKBCF	Construction stage		N/A
S14.3.3.3	LV3	<p><u>Mitigate Visual Impacts</u></p> <ul style="list-style-type: none"> <li>V1.Minimize time for construction activities during construction period.</li> <li>V2.Provide screen hoarding at the portion of the project site / works areas / storage areas near VSRs who have close low-level views to the Project during HKBCF construction.</li> </ul>						√ N/A
<b>EM&amp;A</b>								
S15.2.2	EM1	An Independent Environmental Checker needs to be employed as per the EM&A Manual.	Control EM&A Performance	Project Proponent	All construction sites		<ul style="list-style-type: none"> <li>EIAO Guidance Note No.4/2002</li> <li>TM-EIAO</li> </ul>	√

EIA Ref.	EM&A Log Ref	Recommended Mitigation Measures	Objectives of the Recommended Measures & Main Concerns to address	Who to implement the measures?	Location of the measures	When to implement the measures?	What requirements or standards for the measures to achieve?	Implementation Status
S15.5 - S15.6	EM2	<ul style="list-style-type: none"> <li>An Environmental Team needs to be employed as per the EM&amp;A Manual.</li> <li>Prepare a systematic Environmental Management Plan to ensure effective implementation of the mitigation measures.</li> <li>An environmental impact monitoring needs to be implementing by the Environmental Team to ensure all the requirements given in the EM&amp;A Manual are fully complied with.</li> </ul>	Perform environmental monitoring & auditing	Contractor	All construction sites		<ul style="list-style-type: none"> <li>EIAO Guidance Note No.4/2002</li> <li>TM-EIAO</li> </ul>	<ul style="list-style-type: none"> <li>√</li> <li>√</li> <li>√</li> </ul>


Legends: √ = Implemented; X = Not implemented; N/A = Not applicable




# APPENDIX F

---


## Graphical Plot (Air Quality, Noise and Water Quality)




Remark: The air quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.




Remark: The air quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.



Remark: The air quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.




Remark: The air quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results from for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.




Remark: The air quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.






Remark: The air quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.




Remark: The noise monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.




Remark: The noise monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.

The measured noise level was 67.5 dB(A) on 7 Nov 2017 at Station NMS3B, which exceeded the noise level of 65dB(A) during examination period and it was higher than the baseline level of 66.3 dB(A). Therefore, baseline correction was carried out and the corrected noise level which solely represent the noise level of Construction works are 61.3 dB(A). As such the EAP was not triggered.


The measured noise level was 66.4 dB(A) on 7 Nov 2017 at Station NMS3B, which exceeded the noise level of 65dB(A) during examination period and it was higher than the baseline level of 66.3 dB(A). Therefore, baseline correction was carried out and the corrected noise level which solely represent the noise level of Construction works are 50.0 dB(A). As such the EAP was not triggered.




Remark: The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.




Remark: The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.




Remark: The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.




Remark: The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.




Remark: The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.




Remark: The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.




Remark: The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.



Remark: The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.




Remark: The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.




Remark: The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.







Remark: The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.




Remark: The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.




Remark: The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.




Remark: The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.




Remark: The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.




Remark: The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.




Remark: The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.




Remark: The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3



Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3







Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3



Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3







Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3



Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3







Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3



Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3







Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3



Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3







Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3



Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3







Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3



Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3




Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3







Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3



Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3



Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3



Remark: -The water quality monitoring before 1 September 2017 are conducted by Contract No. HY/2010/02 Hong Kong-Zhuhai-Macao Bridge HKBCF – Reclamation Works. Please refer the monitoring results for August 2017 in the published Monthly EM&A Report for Contract No. HY/2010/02.  
 - The water quality monitoring on 04 Sep 2017 was cancelled due to Typhoon Signal No.3



# APPENDIX G

---

## Site Audit Findings and Corrective Actions

## Appendix F – Site Audit Findings and Corrective Actions

1.1.1 Site Inspections were carried out on a weekly basis to monitor the implementation of proper environmental pollution control and mitigation measures for the Project. During the reporting period, thirteen site inspections were carried out 6, 13, 20 and 27 September, 4, 11 18 and 25 October 2017 and 1, 8, 15, 22 and 29 November 2017.

1.1.2 Particular observations during the site inspections are described in the table below.

Date of Audit	Observations	Actions Taken by Contractor / Recommendation	Date of Observations Closed
30 August 2017	1. Chemical containers were observed without proper labels. A chemical container was observed without drip tray.	1. Proper labels were affixed to the chemical containers. The chemical containers were placed within the drip trays to prevent potential leakage.	6 September 2017
6 September 2017	No particular environmental issue was recorded during the site inspection.	Nil.	Nil.
13 September 2017	1. Dusty materials were placed without cover on 1/F at Row 4 PCB Building. 2. More than 20 bags of cement were placed without cover on 1/F at Row 4 PCB Building. 3. General refuse was scattered on 1/F at Row 3 PCB Building.	1. Dusty materials were removed on 1/F at Row 4 PCB Building. 2. The cement bags were provided cover on 1/F at Row 4 PCB Building. 3. General refuse has been removed on 1/F at Row 3 PCB Building.	20 September 2017
20 September 2017	1. A chemical drum was found without drip tray on G/F at Row 4 PCB Building.	1. The chemical containers was placed within a drip tray to prevent potential leakage on G/F at Row 4 PCB Building.	27 September 2017
27 September 2017	1. Chemical drums were found without proper chemical labels on 1/F at Row 4 PCB Building.	1. Proper chemical labels were provided to the chemical drums at Row 4 PCB Building.	4 October 2017
4 October 2017	No particular environmental issue was recorded during the site inspection.	Nil.	Nil.
11 October 2017	1. Unpaved road was observed dry near Row 5 PCB Building. 2. Bags of dusty materials were observed without proper cover on 1/F of Row	1. Unpaved road was observed wet near Row 5 PCB Building. 2. Bags of dusty materials were removed on 1/F of Row 4 PCB Building.	18 October 2017

Date of Audit	Observations	Actions Taken by Contractor / Recommendation	Date of Observations Closed
	4 PCB Building.		
18 October 2017	1. Concrete breaking was observed without water spraying on 1/F of Row 4 PCB Building.	1. Water spraying was provided to dusty operation on 1/F of Row 4 PCB Building.	25 October 2017
25 October 2017	1. A chemical drum was found on Row 5 of PCB Building.	1. A drip tray was provided to the chemical drum on G/F of Row 5 PCB Building.	1 November 2017
1 November 2017	1. Cement de-bagging and mixing processes were carried out without proper cover/ enclosure on 1/F of Row 3 PCB Building.	1. De-bagging, batching and mixing processes of cement were not observed on 1/F of Row 3 PCB Building.	8 November 2017
8 November 2017	No particular environmental issue was recorded during the site inspection.	Nil.	Nil.
15 November 2017	1. An environmental permit and a construction noise permit were not displayed at vehicular site entrances/ exits of construction site. 2. Non-road mobile machinery (a forklift) bears an inappropriate NRMM label on ground floor of Row 2 PCB Building.	1. Environmental permit and construction noise permit are displayed at site entrance. 2. The forklift is off site. A green NRMM label will be displayed on it if the forklift has to work on site again.	22 November 2017
22 November 2017	1. The chemical containers were found without drip tray at G/F of Row 3.	1. The chemical containers were removed at G/F of Row 3.	29 November 2017
29 November 2017	1. Chemical drums were found without chemical labels near the main gate.	1. The Contractor was reminded to provide proper labels for the chemical drums near the main gate.	Follow-up action undertaken by the Contractor will be inspected during the site inspection to be undertaken in December 2017.



# APPENDIX H

---

## Waste Flow Table

## Monthly Summary Waste Flow Table for 2017



Month	Actual Quantities of Inert C&D Materials Generated Monthly						Actual Quantities of C&D Wastes Generated Monthly				
	a.Total Quantity Generated (see Note 8)	b. Hard Rock and Large Broken Concrete (see Note 9)	c. Reused in the Contract	d. Reused in Other Projects	e. Disposed as Public Fill (see Note 10)	f. Imported Fill	g. Metals (see Note 5)	h. Paper / Cardboard Packaging (see Note 5)	i. Plastics (see Note 3) (see Note 5)	j. Chemical Waste	k. Others, e.g. general refuse
	(in '000m <sup>3</sup> )	(in '000m <sup>3</sup> )	(in '000m <sup>3</sup> )	(in '000m <sup>3</sup> )	(in '000m <sup>3</sup> )	(in '000m <sup>3</sup> )	(in '000kg)	(in '000kg)	(in '000kg)	(in '000kg)	(in '000m <sup>3</sup> )
January	0.046	0.046	0.000	0.000	0.046	0.000	55.920	1.564	0.000	0.000	0.707
February	0.364	0.364	0.000	0.000	0.364	0.000	56.790	1.785	0.000	0.000	0.625
March	0.957	0.957	0.000	0.000	0.957	3.152	85.350	1.477	0.000	0.000	0.813
April	0.487	0.487	0.000	0.000	0.487	30.030	144.450	1.412	0.000	0.090	0.709
May	1.807	1.807	0.000	0.000	1.807	0.000	46.300	0.000	0.000	0.000	0.737
June	3.140	3.140	0.000	0.000	3.140	0.000	117.810	0.000	0.000	0.000	0.595
Sub-total	6.801	6.801	0.000	0.000	6.801	33.182	506.620	6.238	0.000	0.090	4.186
July	1.780	1.780	0.000	0.000	1.780	0.000	177.660	2.856	0.000	0.800	0.664
August	1.190	1.190	0.000	0.000	1.190	0.000	21.140	1.168	0.000	0.000	0.740
September	0.679	0.679	0.000	0.000	0.679	0.000	36.090	1.516	0.000	0.000	1.015
October*	0.410	0.410	0.000	0.000	0.410	0.000	8.310	0.000	0.000	0.000	1.200
November	1.068	1.068	0.000	0.000	1.068	0.000	57.750	2.028	0.000	0.000	1.441
December											
Total	11.928	11.928	0.000	0.000	11.928	33.182	807.570	13.806	0.000	0.890	9.246

Total C&D waste generated = a+b+f+g+h+i+j+k

Total C&D waste generated (excluded excavated material) = g+h+i+j+k

Total C&D waste recycled = c+d+g+h+i

% of recycled C&D waste = (Total C&D waste generated - Total C&D waste recycled) / Total C&D waste generated

Notes: \* The items (a) and (e) had been updated for October 2017. The updates on quantities of items (a) and (e) have been confirmed with the Contractor and RSS.

- (1) The performance target are given in PS Clause 6(14)
- (2) The waste flow table shall also include C&D materials that are not specified in the Contract to be imported for use at the Site
- (3) Plastics refer to plastic bottles/containers, plastic sheets/foam from packaging material
- (4) The Contractor shall also submit the latest forecast of the amount of C&D materials expected to be generated from the Works, together with a break down of the nature where the total amount of C&D materials expected to be generated from the Works is equal to or exceeding 50,000m<sup>3</sup>.
- (5) All recyclable materials, including metals, paper / cardboard packaging, plastics, etc. will be collected by registered collector for recycling.
- (6) Conversion factors for reporting purpose:
  - in-situ: rock = 2.5 tonnes/m<sup>3</sup>; soil = 2.0 tonnes/m<sup>3</sup>
  - excavated: rock = 2.0 tonnes/m<sup>3</sup>; soil = 1.8 tonnes/m<sup>3</sup>; broken concrete and bitumen = 2.4 tonnes/m<sup>3</sup>
  - C&D Waste = 0.9 tonnes/m<sup>3</sup>; bentonite slurry = 2.8 tonnes/m<sup>3</sup>
  - Diesel density: 0.8kg/l
- (7) Numbers are rounded off to the nearest three decimal places
- (8) The "Total Quantity Generated" equals to the sum of "Reuse in the Contract", "Reuse in Other Projects" and "Disposed as Public Fill"
- (9) The "Hard Rock and Large Broken Concrete" were disposed as public fill
- (10) The amount in "Disposed as Public Fill" included the "Hard Rock and Large Broken Concrete" disposed as public fill





# APPENDIX I

---

## Environmental Licenses and Permits

Environmental License/ Permits /Notification Register

Contract No. HY/2013/01 – Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing Facilities – Passenger Clearance Building

Date : November 2017									
Item No.	Permit/License or Registration Application			Permit/License/ Notification/ Registration Description	Permit/License/ Registration Number	Issue/Start Date	Expiry Date	Issuing Office	Remark
	Work Area	Date	Reference						
1.	All Areas	29 Jul 2013	N/A	Environmental Permit for Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing Facilities	EP-353/2009/G	6 Aug 2013	N/A	EPD	Superseded by EP-353/2009/H
2.	All Areas	16 Jan 2015	N/A	Environmental Permit for Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing Facilities	EP-353/2009/H	19 Jan 2015	N/A	EPD	Superseded by EP-353/2009/I
3.	All Areas	30 Jun 2015	N/A	Environmental Permit for Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing Facilities	EP-353/2009/I	17 Jul 2015	N/A	EPD	Superseded by EP-353/2009/J
4.	All Areas	18 Feb 2016	N/A	Environmental Permit for Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing Facilities	EP-353/2009/J	25 Feb 2016	N/A	EPD	Superseded by EP-353/2009/K
5.	All Areas	24 Mar 2016	N/A	Environmental Permit for Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing Facilities	EP-353/2009/K	11 Apr 2016	N/A	EPD	-
6.	All Areas	29 Apr 2014	H2620-LTR-EPD-AU-000006	<b>Billing Account</b> for disposal of construction waste	Billing Account No.: 7019944	16 May 2014	N/A	EPD	-

Environmental License/ Permits /Notification Register

Contract No. HY/2013/01 – Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing Facilities – Passenger Clearance Building

Date : November 2017								Remark	
Item No.	Permit/License or Registration Application			Permit/License/ Notification/ Registration Description	Permit/License/ Registration Number	Issue/Start Date	Expiry Date		Issuing Office
	Work Area	Date	Reference						
7.	PCB	30 Apr 2014	H2620-LTR- EPD-000002	<b>Notification</b> that notifiable works are anticipated to commence (Form NA).	Acknowledge Receipt Ref. No. 373961	5 May 2014	N/A	EPD	-
8.	WA2	30 Apr 2014	H2620-LTR- EPD-000003	<b>Notification</b> that notifiable works are anticipated to commence (Form NA).	Acknowledge Receipt Ref. No. 373956	5 May 2014	N/A	EPD	-
9.	WA3	30 Apr 2014	H2620-LTR-EPD-AU-000001	<b>Notification</b> that notifiable works are anticipated to commence (Form NA).	Acknowledge Receipt Ref. No. 373962	5 May 2014	N/A	EPD	-
10.	PCB	30 May 2014	H2620-LTR-EPD-AU-000020	<b>Registration</b> as Chemical Waste Producer for disposal of spent batteries, used lubrication oil and surplus paint at PCB area	WPN: 5213-951-L2846-01	8 Jul 2014	N/A	EPD	-
11.	PCB	23 Jun 2014	In H2620-LTR-EPD-000017	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out pre-drill and bore piling works from 19:00 to 23:00 and 23:00 to 07:00. (Non-designated area)	GW-RS0683-14	3 Jul 2014	29 Dec 2014	EPD	Superseded by GW-RS0908-14

Environmental License/ Permits /Notification Register

Contract No. HY/2013/01 – Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing Facilities – Passenger Clearance Building

Date : November 2017									
Item No.	Permit/License or Registration Application			Permit/License/ Notification/ Registration Description	Permit/License/ Registration Number	Issue/Start Date	Expiry Date	Issuing Office	Remark
	Work Area	Date	Reference						
12.	WA2	2 Jul 2014	H2620-LTR-LCJ-AU-000280	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out ER Office construction works from 19:00 to 23:00. (Non-designated area)	GW-RS0715-14	17 Jul 2014	15 Jan 2015	EPD	Superseded by GW-RS1034-14
13.	WA3	2 Jul 2014	H2620-LTR-LCJ-AU-000324	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out construction of JV site office from 19:00 to 23:00. (Non-designated)	GW-RS0716-14	17 Jul 2014	15 Jan 2015	EPD	Expired
14.	PCB	23 Jun 2014	H2620-LTR- EPD-000527	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out pre-drill and bore piling works from 19:00 to 23:00 and 23:00 to 07:00. (Non-designated area)	GW-RS0908-14	3 Sep 2014	22 Dec 2014	EPD	Superseded by GW-RS1044-14
15.	PCB	29 Sep 2014	H2620-LTR-EPD-AU-000034	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out pre-drill and bore piling works from 19:00 to 23:00 and 23:00 to 07:00. (Non-designated area)	GW-RS1044-14	29 Sep 2014	24 Dec 2014	EPD	Superseded by GW-RS1300-14

Environmental License/ Permits /Notification Register

Contract No. HY/2013/01 – Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing Facilities – Passenger Clearance Building

Date : November 2017								Remark	
Item No.	Permit/License or Registration Application			Permit/License/ Notification/ Registration Description	Permit/License/ Registration Number	Issue/Start Date	Expiry Date		Issuing Office
	Work Area	Date	Reference						
16.	WA2	12 Sep 2014	H2620-LTR-EPD-AU-000032	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out ER Office construction works from 19:00 to 23:00. (Non-designated area)	GW-RS1034-14	29 Sep 2014	28 Mar 2015	EPD	Expired
17.	WA4	17 Oct 2014	H2620-LTR-EPD-AU-000036	<b>CNP</b> for the use of powered mechanical equipment from 19:00 to 23:00. (Non-designated area)	GW-RW0814-14	20 Oct 2014	19 Apr 2015	EPD	Expired and replaced by GW-RW0171-15
18.	PCB	3 Nov 2014	H2620-LTR-EPD-AU-000040	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out pre-drill and bore piling works from 19:00 to 23:00 and 23:00 to 07:00. (Non-designated area)	GW-RS1300-14	17 Nov 2014	16 Feb 2015	EPD	Superseded by GW-RS0087-15
19.	PCB	12 Jan 2015	H2620-LTR-EPD-AU-000046	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out pre-drill and bore piling works from 19:00 to 23:00 and 23:00 to 07:00. (Non-designated area)	GW-RS0087-15	26 Jan 2015	25 Apr 2015	EPD	Superseded by GW-RS0308-15

Environmental License/ Permits /Notification Register

Contract No. HY/2013/01 – Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing Facilities – Passenger Clearance Building

Date : November 2017								Remark	
Item No.	Permit/License or Registration Application			Permit/License/ Notification/ Registration Description	Permit/License/ Registration Number	Issue/Start Date	Expiry Date		Issuing Office
	Work Area	Date	Reference						
20.	PCB	12 Mar 2015	H2620-LTR-EPD-AU-000051	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out pre-drill and bore piling works from 19:00 to 23:00 and 23:00 to 07:00. (Non-designated area)	GW-RS0308-15	26 Mar 2015	25 Jun 2015	EPD	Superseded by GW-RS0476-15
21.	PCB	31 Jul 2014	H2620-LTR-EPD-AU-000038	<b>Water Discharge License</b> for construction works on PCB island	WT00020335-2014	13 Nov 2014	30 Nov 2019	EPD	-
22.	WA4	27 Mar 2015	H2620-LTR-EPD-AU-000054	<b>CNP</b> for the use of powered mechanical equipment from 19:00 to 23:00. (Non-designated area)	GW-RW0171-15	20 Apr 2015	19 Oct 2015	EPD	Superseded by GW-RW0351-15
23.	PCB	15 Apr 2015	H2620-LTR-EPD-AU-000057	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out pre-drill and bore piling works from 19:00 to 23:00 and 23:00 to 07:00. (Non-designated area)	GW-RS0476-15	1 May 2015	31 Jul 2015	EPD	Superseded by GW-RS0685-15

Environmental License/ Permits /Notification Register

Contract No. HY/2013/01 – Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing Facilities – Passenger Clearance Building

Date : November 2017								Remark	
Item No.	Permit/License or Registration Application			Permit/License/ Notification/ Registration Description	Permit/License/ Registration Number	Issue/Start Date	Expiry Date		Issuing Office
	Work Area	Date	Reference						
24.	PCB	9 Jun 2015	H2620-LTR-EPD-AU-000063	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out pre-drill and bore piling works from 19:00 to 23:00 and 23:00 to 07:00. (Non-designated area)	GW-RS0685-15	1 Jul 2015	30 Sep 2015	EPD	Superseded by GW-RS0877-15
25.	WA4	29 Jun 2015	H2620-LTR-EPD-AU-000066	<b>CNP</b> for the use of powered mechanical equipment from 19:00 to 23:00. (Non-designated area)	GW-RW0351-15	17 Jul 2015	12 Jan 2016	EPD	Expired. Replaced by GW-RW0003-16
26.	PCB	27 Jul 2015	H2620-LTR-EPD-AU-000069	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out pre-drill and bore piling works from 19:00 to 23:00 and 23:00 to 07:00. (Non-designated area)	GW-RS0877-15	10 Aug 2015	09 Nov 2015	EPD	Superseded by GW-RS1016-15
27.	PCB	2 Sep 2015	H2620-LTR-EPD-AU-000072	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out pre-drill and bore piling works from 19:00 to 23:00 and 23:00 to 07:00. (Non-designated area)	GW-RS1016-15	18 Sep 2015	17 Dec 2015	EPD	Superseded by GW-RS1195-15

Environmental License/ Permits /Notification Register

Contract No. HY/2013/01 – Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing Facilities – Passenger Clearance Building

Date : November 2017								Remark	
Item No.	Permit/License or Registration Application			Permit/License/ Notification/ Registration Description	Permit/License/ Registration Number	Issue/Start Date	Expiry Date		Issuing Office
	Work Area	Date	Reference						
28.	PCB	22 Oct 2015	H2620-LTR-EPD-AU-000075	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out works from 19:00 to 23:00 and 23:00 to 07:00. (Non-designated area)	GW-RS1195-15	9 Nov 2015	8 Feb 2016	EPD	Superseded by GW-RS1444-15
29.	PCB	17 Dec 2015	H2620-LTR-EPD-AU-000076	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out works from 19:00 to 23:00 and 23:00 to 07:00. (Non-designated area)	GW-RS1444-15	31 Dec 2015	30 Mar 2016	EPD	Superseded by GW-RS0191-16
30.	WA4	24 Dec 2015	H2620-LTR-EPD-AU-000080	<b>CNP</b> for the use of powered mechanical equipment from 19:00 to 23:00. (Non-designated area)	GW-RW0003-16	13 Jan 2016	6 Jul 2016	EPD	Superseded by GW-RW0394-16
31.	PCB	17 Feb 2016	H2620-LTR-EPD-AU-000083	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out works from 19:00 to 23:00 and 23:00 to 07:00. (Non-designated area)	GW-RS0191-16	3 Mar 2016	2 Jun 2016	EPD	Superseded by GW-RS0543-16



Environmental License/ Permits /Notification Register

Contract No. HY/2013/01 – Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing Facilities – Passenger Clearance Building

Date : November 2017									
Item No.	Permit/License or Registration Application			Permit/License/ Notification/ Registration Description	Permit/License/ Registration Number	Issue/Start Date	Expiry Date	Issuing Office	Remark
	Work Area	Date	Reference						
32.	PCB	18 May 2016	H2620-LTR-EPD-AU-000086	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out works from 19:00 to 23:00 and 23:00 to 07:00. (Non-designated area)	GW-RS0543-16	2 Jun 2016	1 Sep 2016	EPD	Superseded by GW-RS0879-16
33.	WA4	20 Jun 2016	H2620-LTR-EPD-AU-000089	<b>CNP</b> for the use of powered mechanical equipment from 19:00 to 23:00. (Non-designated area)	GW-RW0394-16	7 Jul 2016	6 Jan 2017	EPD	Superseded by GW-RW0742-16
34.	PCB	09 Aug 2016	H2620-LTR-EPD-AU-000092	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out works from 19:00 to 23:00 and 23:00 to 07:00. (Non-designated area)	GW-RS0879-16	23 Aug 2016	22 Dec 2016	EPD	Superseded by GW-RS1193-16
35.	PCB	16 Nov 2016	H2620-LTR-EPD-AU-000094	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out works from 19:00 to 23:00 and 23:00 to 07:00. (Non-designated area)	GW-RS1193-16	30 Nov 2016	29 May 2017	EPD	Superseded by GW-RS0005-17
36.	WA4	17 Dec 2016	H2620-LTR-EPD-AU-000100	<b>CNP</b> for the use of powered mechanical equipment from 19:00 to 23:00. (Non-designated area)	GW-RW0742-16	7 Jan 2017	6 Jul 2017	EPD	Superseded by GW-RW0341-17

Environmental License/ Permits /Notification Register

Contract No. HY/2013/01 – Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing Facilities – Passenger Clearance Building

Date : November 2017								Remark	
Item No.	Permit/License or Registration Application			Permit/License/ Notification/ Registration Description	Permit/License/ Registration Number	Issue/Start Date	Expiry Date		Issuing Office
	Work Area	Date	Reference						
37.	PCB	19 Dec 16	H2620-LTR-EPD-AU-000103	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out works from 19:00 to 23:00 and 23:00 to 07:00. (Non-designated area)	GW-RS0005-17	6 Jan 2017	5 Jul 2017	EPD	Superseded by GW-RS0461-17
38.	WA3	30 Dec 16	H2620-LTR-EPD-AU-000102	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out construction of JV site office from 19:00 to 23:00. (Non-designated area)	GW-RS0015-17	12 Jan 2017	11 Jul 2017	EPD	Superseded by GW-RS0587-17
39.	PCB	12 May 17	H2620-LTR-EPD-AU-000106	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out works from 19:00 to 23:00 and 23:00 to 07:00. (Non-designated area)	GW-RS0461-17	25 May 2017	24 Nov 2017	EPD	Superseded by GW-RS0998-17
40.	WA3	22 Jun 17	H2620-LTR-EPD-AU-000113	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out construction of JV site office from 19:00 to 23:00. (Non-designated)	GW-RS0587-17	12 Jul 2017	11 Jan 2018	EPD	-

Environmental License/ Permits /Notification Register

Contract No. HY/2013/01 – Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing Facilities – Passenger Clearance Building

Date : November 2017									
Item No.	Permit/License or Registration Application			Permit/License/ Notification/ Registration Description	Permit/License/ Registration Number	Issue/Start Date	Expiry Date	Issuing Office	Remark
	Work Area	Date	Reference						
41.	WA4	19 Jun 17	H2620-LTR-EPD-AU-000112	<b>CNP</b> for the use of powered mechanical equipment from 19:00 to 23:00. (Non-designated area)	GW-RW0341-17	10 Jul 2017	6 Jan 2018	EPD	-
42.	PCB	20 Oct 17	H2620-LTR-LCJ-EN-005050	<b>CNP</b> for the use of powered mechanical equipment for the purpose of carry out works from 19:00 to 23:00 and 23:00 to 07:00. (Non-designated area)	GW-RS0998-17	15 Nov 17	12 May 18	EPD	-



## **APPENDIX J**

---

### **Statistics on Environmental Complaints, Notification of Summons and Successful Prosecutions**

### Statistics on Environmental Complaints, Notifications of Summons and Successful Prosecutions

Reporting Period	Cumulative Statistics		
	Complaints	Notifications of summons	Successful prosecutions
This reporting period	0	0	0
From commencement date of contract to end of reporting period	10	0	0

# APPENDIX K

---

## Investigation Report

**Contract No. HY/2013/01 - Hong Kong- Zhuhai- Macao Bridge Hong Kong Boundary Crossing Facilities – Passenger Clearance Building**  
**Notifications of Environmental Quality Limits Exceedances** Notification No.: 20170901DO\_v1

**Date of Notification:** 5 September 2017 **Date of Investigation Report:** 6 October 2017

**Works Inspected:** Data collected from water sampling works on 1 September 2017 and the results were issued on 4 September 2017

**Monitoring Location:** Water Quality Monitoring Station

**Parameter:** Dissolved Oxygen (DO)/ ~~Suspended Solid (SS)~~/ Turbidity (TURB)


**Action & Limit Level (AL & LL) / Measured Level:**

PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)
DO	IS5	Bottom	Surface and Middle 5.0 Bottom 4.7	Surface and Middle 4.2 (except 5 mg/L for FCZ) Bottom 3.6	<b>4.4</b>	<b>4.4</b>
DO	IS10(N)	Bottom			<b>4.5</b>	<b>4.5</b>
DO	IS(Mf)11	Bottom			<b>4.6</b>	<b>4.5</b>
DO	IS17	Bottom			<b>4.5</b>	5.2
DO	SR5(N)	Bottom			<b>4.5</b>	4.7

Notes:  
 AL means Action Level.  
 LL means Limit Level.  
**Bold** means AL exceedances.  
**Bold with underline** means LL exceedances.

**Possible reason for Action and Limit Level Non-compliance:**

On 1 September 2017, five AL exceedances of DO recorded at IS5, IS10(N), IS(Mf)11, IS17 and SR5(N) were recorded during mid-ebb tide and three AL exceedances of DO recorded at IS5, IS10(N) and IS(Mf)11 were recorded during mid-flood tide.



As confirmed by the Contractor, there were no marine transportation and marine-based work on 1 September 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedance was not related the Contract.

**Actions taken/ to be taken:**  
 As the exceedance was not related to the Contract, no immediate action are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Reviewed by : Keith Chau Title : ET Leader  
 Date : 6 October 2017

Copied to: Contractor and Engineer Representative

**Contract No. HY/2013/01 - Hong Kong- Zhuhai- Macao Bridge**  
**Hong Kong Boundary Crossing Facilities – Passenger Clearance Building**  
**Notifications of Environmental Quality Limits Exceedances** Notification No.: 20170906DO\_TURB\_v3

**Date of Notification:** 11 September 2017 **Date of Investigation Report:** 9 October 2017

**Works Inspected:** Data collected from water sampling works on 6 September 2017 and the results were issued on 11 September 2017

**Monitoring Location:** Water Quality Monitoring Station

**Parameter:** Dissolved Oxygen (DO)/ ~~Suspended Solid (SS)~~/ Turbidity (TURB)

**Action & Limit Level (AL & LL) / Measured Level:**


PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)
DO	IS17	Bottom	Surface and Middle 5.0 Bottom 4.7	Surface and Middle 4.2 (except 5 mg/L for FCZ) Bottom 3.6	<b>4.6</b>	4.9
	SR6	Surface and Middle			5.7	<b>4.8</b>
	SR10A	Surface and Middle			<b>4.9</b>	<b>4.6</b>
		Bottom			4.8	<b>4.5</b>
	SR10B(N)	Surface and Middle			<b>4.8</b>	<b>4.6</b>
		Bottom			4.8	<b>4.5</b>
PARAM	STATION	DEPTH	AL (NTU)	LL (NTU)	MEASURED AT MID-EBB TIDE (NTU)	MEASURED AT MID-FLOOD TIDE (NTU)
TURB	IS(Mf)11	Depth Average	27.5 and 120% (i.e. 17.6 for mid-ebb/18.7 for mid-flood) of upstream control station's turbidity at the same tide of the same day	47.0 and 130% (i.e. 19.0 for mid-ebb/20.2 for mid-flood) of upstream control station's turbidity at the same tide of the same day	14.6	<b>27.9</b>

Notes:  
AL means Action Level.  
LL means Limit Level.  
**Bold** means AL exceedances.  
**Bold with underline** means LL exceedances.  
Upstream control stations of mid-ebb tide: CS(Mf)3(N) and CS4  
Upstream control stations of mid-flood tide: CS(Mf)5, CS6 and CSA



**Possible reason for Action and Limit Level Non-compliance:**


On 6 September 2017, one AL exceedance of DO recorded at IS17 was recorded during mid-ebb tide, three AL exceedances of DO recorded at SR6, SR10A, and SR10B(N) were recorded during mid-flood tide, two LL exceedances of DO recorded at SR10A and SR10B(N) were recorded during mid-ebb tide, two LL exceedances of DO recorded at SR10A and SR10B(N) were recorded during mid-flood tide and one AL exceedance of TURB recorded at IS(Mf)11 was recorded during mid-flood tide.



As confirmed by the Contractor, there were no marine transportation and marine-based work on 6 September 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedances were not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Reviewed by : Keith Chau  


Title : ET Leader

Date : 9 October 2017

Copied to : Contractor and Engineer Representative

**Contract No. HY/2013/01 - Hong Kong- Zhuhai- Macao Bridge  
 Hong Kong Boundary Crossing Facilities – Passenger Clearance Building  
 Notifications of Environmental Quality Limits Exceedances** Notification No.: 20170906SS\_v1

**Date of Notification:** 19 September 2017 **Date of Investigation Report:** 25 September 2017

**Works Inspected:** Data collected from water sampling works on 6 September 2017 and the results were issued on 15 September 2017

**Monitoring Location:** Water Quality Monitoring Station


**Parameter:** Dissolved Oxygen (DO)/ Suspended Solid (SS)/ Turbidity (TURB)

**Action & Limit Level (AL & LL) / Measured Level:**

PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)
SS	IS8	Depth Average	23.5 and 120% (i.e. 11.3 for mid-ebb/14.1 for mid-flood) of upstream control station's SS at the same tide of the same day	34.4 and 130% (i.e. 12.3 for mid-ebb/15.3 for mid-flood) of upstream control station's SS at the same tide of the same day and 10mg/L for WSD Seawater intakes	8.1	<b>26.4</b>
	SR4(N)				9.4	<b>25.3</b>
	SR6				6.2	<b>23.6</b>

Notes:  
 AL means Action Level.  
 LL means Limit Level.  
**Bold** means AL exceedances.  
**Bold with underline** means LL exceedances.  
 Upstream control stations of mid-ebb tide: CS(Mf)3(N) and CS4  
 Upstream control stations of mid-flood tide: CS(Mf)5, CS6 and CSA

**Possible reason for Action and Limit Level Non-compliance:**  
 On 6 September 2017, three AL exceedances of SS recorded at IS8,SR4(N) and SR6 were recorded during mid-flood tide.



As confirmed by the Contractor, there were no marine transportation and marine-based work on 6 September 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**  
 As the exceedances were not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Reviewed by : Keith Chau Title : ET Leader  
 Date : 25 September 2017

Copied to : Contractor and Engineer Representative

**Contract No. HY/2013/01 - Hong Kong- Zhuhai- Macao Bridge**  
**Hong Kong Boundary Crossing Facilities – Passenger Clearance Building**  
**Notifications of Environmental Quality Limits Exceedances** Notification No.: 20170908DO\_TURB\_v3

**Date of Notification:** 13 September 2017 **Date of Investigation Report:** 9 October 2017

**Works Inspected:** Data collected from water sampling works on 8 September 2017 and the results were issued on 12 September 2017

**Monitoring Location:** Water Quality Monitoring Station

**Parameter:** Dissolved Oxygen (DO)/ ~~Suspended Solid (SS)~~/ Turbidity (TURB)

**Action & Limit Level (AL & LL) / Measured Level:**

PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)
DO	IS5	Surface and Middle	Surface and Middle 5.0 Bottom 4.7	Surface and Middle 4.2 (except 5 mg/L for FCZ) Bottom 3.6	5.0	<b>4.9</b>
	IS7	Surface and Middle			<b>4.8</b>	5.1
		Bottom			<b>4.6</b>	5.2
	IS8	Surface and Middle			5.0	<b>4.9</b>
	IS(Mf)9	Surface and Middle			5.3	<b>4.8</b>
	IS10(N)	Surface and Middle			<b>4.9</b>	<b>4.7</b>
	IS(Mf)11	Surface and Middle			5.0	<b>4.7</b>
		Bottom			4.8	<b>4.6</b>
	IS(Mf)16	Surface and Middle			<b>4.6</b>	<b>4.9</b>
		Bottom			<b>4.3</b>	5.0
	IS17	Surface and Middle			<b>4.9</b>	<b>4.7</b>
		Bottom			<b>4.3</b>	<b>4.5</b>
	SR3	Surface and Middle			<b>4.7</b>	<b>4.9</b>
	SR4(N)	Surface and Middle			5.2	<b>4.9</b>
	SR5(N)	Surface and Middle			5.0	<b>4.8</b>
	SR6	Surface and Middle			<b>4.9</b>	<b>4.9</b>
SR7	Surface and Middle	5.1	<b>4.9</b>			
	Bottom	<b>4.9</b>	<b>4.3</b>			
SR10A	Surface and Middle	<b>4.9</b>	<b>4.3</b>			
	Bottom	4.8	<b>4.3</b>			
SR10B(N)	Surface and Middle	<b>4.8</b>	<b>4.7</b>			
PARAM	STATION	DEPTH	AL (NTU)	LL (NTU)	MEASURED AT MID-EBB TIDE (NTU)	MEASURED AT MID-FLOOD TIDE (NTU)
TURB	IS5	Depth Average	27.5 and 120% (i.e. 20.2 for mid-ebb/13.7 for mid-flood) of upstream control station's turbidity at the same tide of the same day	47.0 and 130% (i.e. 21.9 for mid-ebb/14.9 for mid-flood) of upstream control station's turbidity at the same tide of the same day	<b>34.4</b>	6.6
	IS10(N)				25.2	<b>31.6</b>
	IS(Mf)11				17.8	<b>29.0</b>
	SR6				12.2	<b>35.3</b>

**Notes:**

AL means Action Level.

LL means Limit Level.

**Bold** means AL exceedances.


**Bold with underline** means LL exceedances.

Upstream control stations of mid-ebb tide: CS(Mf)3(N) and CS4

Upstream control stations of mid-flood tide: CS(Mf)5, CS6 and CSA

**Possible reason for Action and Limit Level Non-compliance:**


On 8 September 2017, nine AL exceedances of DO recorded at IS7, IS10(N), IS(Mf)16, IS17, SR3 and SR6 were recorded during mid-ebb tide, fifteen AL exceedances of DO recorded at IS5, IS8, IS(Mf)9, IS10(N), IS(Mf)11, IS(Mf)16, IS17, SR3, SR4(N), SR5(N), SR6, SR7 and SR10A were recorded during mid-flood tide, two LL exceedances of DO recorded at SR10A and SR10B(N) were recorded during mid-ebb tide, two LL exceedances of DO recorded at SR10A and SR10B(N) were recorded during mid-flood tide, one AL exceedance of TURB recorded at IS5 was recorded during mid-ebb tide and three AL exceedances of TURB recorded at IS10(N), IS(Mf)11 and SR6 were recorded during mid-flood tide.



As confirmed by the Contractor, there were no marine transportation and marine-based work on 8 September 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedances were not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Reviewed by : Keith Chau  


Title : ET Leader

Date : 9 October 2017

Copied to : Contractor and Engineer Representative

Date of Notification: 19 September 2017

Date of Investigation Report: 25 September 2017

Works Inspected: Data collected from water sampling works on 8 September 2017 and the results were issued on 18 September 2017

Monitoring Location: Water Quality Monitoring Station

Parameter: Dissolved Oxygen (DO)/ Suspended Solid (SS)/ Turbidity (TURB)

Action & Limit Level (AL & LL) / Measured Level:

PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)
SS	IS5	Depth Average	23.5 and 120% (i.e. 20.4 for mid-ebb/10.5 for mid-flood) of upstream control station's SS at the same tide of the same day	34.4 and 130% (i.e. 22.1 for mid-ebb/11.4 for mid-flood) of upstream control station's SS at the same tide of the same day and 10mg/L for WSD Seawater intakes	28.4	8.7
	IS10(N)				19.5	<b><u>35.5</u></b>
	IS(Mf)11				15.4	<b>33.2</b>

Notes:

AL means Action Level.

LL means Limit Level.

**Bold** means AL exceedances.


**Bold with underline** means LL exceedances.

Upstream control stations of mid-ebb tide: CS(Mf)3(N) and CS4

Upstream control stations of mid-flood tide: CS(Mf)5, CS6 and CSA

Possible reason for Action and Limit Level Non-compliance:

On 8 September 2017, one AL exceedance of SS recorded at IS5 was recorded during mid-ebb tide. One AL exceedance of SS recorded at IS(Mf)11 and one LL exceedance of SS at IS10(N) were recorded during mid-flood tide.



As confirmed by the Contractor, there were no marine transportation and marine-based work on 8 September 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

Actions taken/ to be taken:

As the exceedances were not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Reviewed by : Keith Chau

Title : ET Leader



Date : 25 September 2017

Copied to : Contractor and Engineer Representative

**Contract No. HY/2013/01 -  
Hong Kong- Zhuhai- Macao Bridge  
Hong Kong Boundary Crossing Facilities – Passenger Clearance Building  
Notifications of Environmental Quality Limits Exceedances**

Notification No.: 20170911DO\_v1

**Date of Notification:** 15 September 2017

**Date of Investigation Report:** 6 October 2017

**Works Inspected:** Data collected from water sampling works on 11 September 2017 and the results were issued on 14 September 2017

**Monitoring Location:** Water Quality Monitoring Station

**Parameter:** Dissolved Oxygen (DO)/ ~~Suspended Solid (SS)~~/ Turbidity (TURB)

**Action & Limit Level (AL & LL) / Measured Level:**

PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)
DO	IS8	Surface and Middle	Surface and Middle 5.0 Bottom 4.7	Surface and Middle 4.2 (except 5 mg/L for FCZ) Bottom 3.6	5.2	<b>4.8</b>
		Bottom			5.0	<b>4.6</b>
	IS(Mf)9	Surface and Middle			5.3	<b>4.8</b>
		Bottom			<b>4.9</b>	<b>4.6</b>
	IS10(N)	Surface and Middle			4.8	<b>4.4</b>
		Bottom			<b>4.9</b>	<b>4.6</b>
	IS(Mf)11	Surface and Middle			<b>4.6</b>	<b>4.5</b>
		Bottom			5.2	<b>4.7</b>
	IS(Mf)16	Surface and Middle			<b>4.3</b>	<b>4.6</b>
		Bottom			<b>4.8</b>	<b>4.5</b>
	IS17	Surface and Middle			<b>4.2</b>	<b>4.2</b>
		Bottom			5.3	<b>4.8</b>
	SR4(N)	Surface and Middle			<b>4.7</b>	<b>4.6</b>
	SR5(N)	Surface and Middle			<b>4.6</b>	<b>4.6</b>
		Bottom			<b>4.7</b>	<b>4.7</b>
	SR6	Surface and Middle			4.7	<b>4.6</b>
		Bottom			<b>4.9</b>	<b>4.7</b>
	SR7	Surface and Middle			5.2	<b>4.5</b>
	SR10A	Surface and Middle			5.1	<b>4.1</b>
		Bottom			<b>4.8</b>	<b>4.2</b>
SR10B(N)	Surface and Middle	<b>4.6</b>	<b>4.0</b>			
	Bottom					

**Notes:**

AL means Action Level.

LL means Limit Level.

**Bold** means AL exceedances.


**Bold with underline** means LL exceedances.

Upstream control stations of mid-ebb tide: CS(Mf)3(N) and CS4

Upstream control stations of mid-flood tide: CS(Mf)5, CS6 and CSA

**Possible reason for Action and Limit Level Non-compliance:**

On 11 September 2017, eleven AL exceedances of DO recorded at IS10(N), IS(Mf)11, IS(Mf)16, IS17, SR5(N), SR6, SR7 and SR10B(N) were recorded during mid-ebb tide, nineteen AL exceedances of DO recorded at IS8, IS(Mf)9, IS10(N), IS(Mf)11, IS(Mf)16, IS17, SR4(N), SR5(N), SR6, SR10A and SR10B(N) were recorded during mid-flood tide. One LL exceedance of DO recorded at SR10B(N) was recorded during mid-ebb tide, two LL exceedances of DO recorded at SR10A and SR10B(N) were recorded during mid-flood tide.



As confirmed by the Contractor, there were no marine transportation and marine-based work on 11 September 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedances were not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Reviewed by : Keith Chau Title : ET Leader



Date : 6 October 2017

Copied to : Contractor, Engineer Representative and IEC/ENPO

**Contract No. HY/2013/01 - Hong Kong- Zhuhai- Macao Bridge**  
**Hong Kong Boundary Crossing Facilities – Passenger Clearance Building**  
**Notifications of Environmental Quality Limits Exceedances** Notification No.: 20170913DO\_v1

**Date of Notification:** 19 September 2017 **Date of Investigation Report:** 6 October 2017

**Works Inspected:** Data collected from water sampling works on 13 September 2017 and the results were issued on 18 September 2017

**Monitoring Location:** Water Quality Monitoring Station

**Parameter:** Dissolved Oxygen (DO)/ ~~Suspended Solid (SS)~~/ Turbidity (TURB)

**Action & Limit Level (AL & LL) / Measured Level:**


PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)
DO	IS5	Bottom	Surface and Middle 5.0 Bottom 4.7	Surface and Middle 4.2 (except 5 mg/L for FCZ) Bottom 3.6	<b>4.1</b>	<b>4.1</b>
	IS(Mf)9	Bottom			6.5	<b>4.2</b>
	IS10(N)	Surface and Middle			<b>4.7</b>	5.0
	IS(Mf)11	Surface and Middle			5.1	<b>4.9</b>
	IS(Mf)16	Bottom			<b>4.1</b>	<b>4.2</b>
	IS17	Surface and Middle			5.0	<b>4.9</b>
		Bottom			<b>3.8</b>	<b>4.1</b>
	SR5(N)	Surface and Middle			<b>4.8</b>	5.5
	SR10A	Surface and Middle			<b>4.9</b>	<b>4.4</b>
		Bottom			5.2	<b>3.9</b>
	SR10B(N)	Surface and Middle			5.2	<b>4.4</b>
		Bottom			5.4	<b>4.1</b>

Notes:  
AL means Action Level.  
LL means Limit Level.  
**Bold** means AL exceedances.  
**Bold with underline** means LL exceedances.  
Upstream control stations of mid-ebb tide: CS(Mf)3(N) and CS4  
Upstream control stations of mid-flood tide: CS(Mf)5, CS6 and CSA



**Possible reason for Action and Limit Level Non-compliance:**

On 13 September 2017, five AL exceedances of DO recorded at IS5, IS10(N), IS(Mf)16, IS17 and SR5(N) were recorded during mid-ebb tide, eight AL exceedances of DO recorded at IS5, IS(Mf)9, IS(Mf)11, IS(Mf)16, IS17, SR10A and SR10B(N) were recorded during mid-flood tide. One LL exceedance of DO recorded at SR10A was recorded during mid-ebb tide, two LL exceedances of DO recorded at SR10A and SR10B(N) were recorded during mid-flood tide.




As confirmed by the Contractor, there were no marine transportation and marine-based work on 13 September 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedances were not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Reviewed by : Keith Chau Title : ET Leader

 Date : 6 October 2017

Copied to : Contractor, Engineer Representative and IEC/ENPO

**Contract No. HY/2013/01 - Hong Kong- Zhuhai- Macao Bridge**  
**Hong Kong Boundary Crossing Facilities – Passenger Clearance Building**  
**Notifications of Environmental Quality Limits Exceedances** Notification No.: 20170915DO\_TURB\_v2

**Date of Notification:** 21 September 2017 **Date of Investigation Report:** 12 October 2017

**Works Inspected:** Data collected from water sampling works on 15 September 2017 and the results were issued on 19 September 2017

**Monitoring Location:** Water Quality Monitoring Station

**Parameter:** Dissolved Oxygen (DO)/ ~~Suspended Solid (SS)~~/ Turbidity (TURB)


**Action & Limit Level (AL & LL) / Measured Level:**

PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)
DO	IS10(N)	Bottom	Surface and Middle 5.0 Bottom 4.7	Surface and Middle 4.2 (except 5 mg/L for FCZ) Bottom 3.6	<b>4.2</b>	<b>4.5</b>
	IS(Mf)11	Surface and Middle			<b>4.1</b>	<b>4.7</b>
	IS17	Surface and Middle			<b>4.9</b>	5.7
		Bottom			<b>3.9</b>	4.7
	SR6	Surface and Middle			5.5	<b>4.8</b>
		Bottom			4.7	<b>4.5</b>
	SR10A	Surface and Middle			5.5	<b>4.7</b>
		Bottom			5.4	<b>3.9</b>
	SR10B(N)	Surface and Middle			5.4	<b>4.6</b>
		Bottom			5.0	<b>4.3</b>
TURB	IS8	Depth Average	27.5 and 120% (i.e. 19.6 for mid-ebb/15.4 for mid-flood) of upstream control station's turbidity at the same tide of the same day	47.0 and 130% (i.e. 21.2 for mid-ebb/16.7 for mid-flood) of upstream control station's turbidity at the same tide of the same day	10.6	<b><u>95.4*</u></b>

Notes:  
AL means Action Level.  
LL means Limit Level.  
**Bold** means AL exceedances.  
**Bold with underline** means LL exceedances.  
Upstream control stations of mid-ebb tide: CS(Mf)3(N) and CS4  
Upstream control stations of mid-flood tide: CS(Mf)5, CS6 and CSA  
\*The muddy water was observed due to 3 fast boats were moving around near the monitoring location during measurement period.

**Possible reason for Action and Limit Level Non-compliance:**

On 15 September 2017, four AL exceedances of DO recorded at IS10(N), IS(Mf)11 and IS17 were recorded during mid-ebb tide, six AL exceedances of DO recorded at IS10(N), IS(Mf)11, SR6, SR10A and SR10B(N) were recorded during mid-flood tide and two LL exceedances of DO recorded at SR10A and SR10B(N) were recorded during mid-flood tide. One AL exceedance of TURB recorded at IS8 was recorded during mid-flood tide.



As confirmed by the Contractor, there were no marine transportation and marine-based work on 15 September 2017. No site runoff within the Contract site has been observed. The muddy water was observed due to 3 fast boats were moving around near the monitoring station IS8 during measurement period. No observation photos were taken during measurement period.

Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedances were not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Reviewed by : Keith Chau Title : ET Leader


*Keith* Date : 12 October 2017

Copied to : Contractor, Engineer Representative and IEC/ENPO

<b>Contract No. HY/2013/01 -  Hong Kong- Zhuhai- Macao Bridge  Hong Kong Boundary Crossing Facilities – Passenger Clearance Building  Notifications of Environmental Quality Limits Exceedances</b>							Notification No.: 20170918DO_SS_v1
<b>Date of Notification:</b> 27 September 2017				<b>Date of Investigation Report:</b> 27 September 2017			
<b>Works Inspected:</b> Data collected from water sampling works on 18 September 2017 and the results were issued on 27 September 2017							
<b>Monitoring Location:</b> Water Quality Monitoring Station							
<b>Parameter:</b> Dissolved Oxygen (DO)/ Suspended Solid (SS)/ Turbidity (TURB)							
<b>Action &amp; Limit Level (AL &amp; LL) / Measured Level:</b>							
PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)	
DO	IS5	Bottom	Surface and Middle 5.0 Bottom 4.7	Surface and Middle 4.2 (except 5 mg/L for FCZ) Bottom 3.6	<b>4.5</b>	5.8	
	IS10(N)	Bottom			<b>4.6</b>	5.0	
	IS(Mf)11	Bottom			<b>4.6</b>	5.0	
	IS(Mf)16	Bottom			<b>4.4</b>	5.0	
	SR6	Surface and Middle			<b>4.7</b>	<b>4.4</b>	
		Bottom			<b>4.5</b>	<b>4.3</b>	
	SR10A	Surface and Middle			5.5	<b><u>4.7</u></b>	
SR10B(N)	Surface and Middle	5.4	<b><u>4.9</u></b>				
SS	IS8	Depth Average	23.5 and 120% (i.e. 9.9 for mid-ebb/13.4 for mid-flood) of upstream control station's SS at the same tide of the same day	34.4 and 130% (i.e. 10.8 for mid-ebb/14.5 for mid-flood) of upstream control station's SS at the same tide of the same day and 10mg/L for WSD Seawater intakes	6.3	<b>25.0</b>	
Notes: AL means Action Level. LL means Limit Level. <b>Bold</b> means AL exceedances. <b>Bold with underline</b> means LL exceedances. Upstream control stations of mid-ebb tide: CS(Mf)3(N) and CS4 Upstream control stations of mid-flood tide: CS(Mf)5, CS6 and CSA							

**Possible reason for Action and Limit Level Non-compliance:**


On 18 September 2017, six AL exceedances of DO recorded at IS5, IS10(N), IS(Mf)11, IS(Mf)16 and SR6 were recorded during mid-ebb tide, two AL exceedances of DO recorded at SR6 were recorded during mid-flood tide, two LL exceedances of DO recorded at SR10A and SR10B(N) were recorded during mid-flood tide and one AL exceedance of SS recorded at IS8 was recorded during mid-flood tide.



As confirmed by the Contractor, there were no marine transportation and marine-based work on 18 September 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedances were not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Reviewed by : Keith Chau Title : ET Leader  
  
Date : 27 September 2017

Copied to : Contractor, Engineer Representative and IEC/ENPO

**Contract No. HY/2013/01 - Hong Kong- Zhuhai- Macao Bridge**  
**Hong Kong Boundary Crossing Facilities – Passenger Clearance Building**  
**Notifications of Environmental Quality Limits Exceedances** Notification No.: 20170920DO\_SS\_v1

**Date of Notification:** 25 September 2017 **Date of Investigation Report:** 11 October 2017

**Works Inspected:** Data collected from water sampling works on 20 September 2017 and the results were issued on 29 September 2017

**Monitoring Location:** Water Quality Monitoring Station

**Parameter:** Dissolved Oxygen (DO)/ Suspended Solid (SS)/ ~~Turbidity (TURB)~~


**Action & Limit Level (AL & LL) / Measured Level:**

PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)
DO	SR6	Surface and Middle	Surface and Middle 5.0 Bottom 4.7	Surface and Middle 4.2 (except 5 mg/L for FCZ) Bottom 3.6	5.1	<b>4.5</b>
		Bottom			5.0	<b>4.6</b>
	SR10A	Surface and Middle			5.0	<b>4.5</b>
		Bottom			4.7	<b>4.5</b>
SR10B(N)	Surface and Middle	5.0	<b>4.5</b>			
SS	SR6	Depth Average	23.5 and 120% (i.e. 16.7 for mid-ebb/19.0 for mid-flood) of upstream control station's SS at the same tide of the same day	34.4 and 130% (i.e. 18.1 for mid-ebb/20.6 for mid-flood) of upstream control station's SS at the same tide of the same day and 10mg/L for WSD Seawater intakes	10.4	<b>25.4</b>

Notes:  
AL means Action Level.  
LL means Limit Level.  
**Bold** means AL exceedances.  
**Bold with underline** means LL exceedances.  
Upstream control stations of mid-ebb tide: CS(Mf)3(N) and CS4  
Upstream control stations of mid-flood tide: CS(Mf)5, CS6 and CSA

**Possible reason for Action and Limit Level Non-compliance:**

On 20 September 2017, three AL exceedances of DO at SR6 and SR10A were recorded during mid-flood tide, two LL exceedances of DO at SR10A and SR10B(N) were recorded during mid-flood tide and one AL exceedance of SS at SR6 was recorded during mid-flood tide.



As confirmed by the Contractor, there were no marine transportation and marine-based work on 20 September 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedances were not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Reviewed by : Keith Chau Title : ET Leader  
*Keith* Date : 11 October 2017

Copied to : Contractor, Engineer Representative and IEC/ENPO

Contract No. HY/2013/01 -

Hong Kong- Zhuhai- Macao Bridge

Hong Kong Boundary Crossing Facilities – Passenger Clearance Building

Notifications of Environmental Quality Limits Exceedances

Notification No.: 20170922DO\_v1

Date of Notification: 27 September 2017

Date of Investigation Report: 11 October 2017

Works Inspected: Data collected from water sampling works on 22 September 2017 and the results were issued on 26 September 2017

Monitoring Location: Water Quality Monitoring Station

Parameter: Dissolved Oxygen (DO)/ Suspended Solid (SS)/ Turbidity (TURB)

Action & Limit Level (AL & LL) / Measured Level:

PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)
DO	IS8	Surface and Middle	Surface and Middle 5.0 Bottom 4.7	Surface and Middle 4.2 (except 5 mg/L for FCZ) Bottom 3.6	5.2	<b>4.8</b>
	IS(Mf)9	Surface and Middle			5.3	<b>4.9</b>
	IS10(N)	Surface and Middle			<b>4.8</b>	<b>4.8</b>
		Bottom			<b>4.6</b>	4.8
	IS(Mf)11	Surface and Middle			<b>4.7</b>	<b>4.9</b>
	IS(Mf)16	Surface and Middle			5.1	<b>4.8</b>
	IS17	Surface and Middle			5.0	<b>4.8</b>
	SR3	Surface and Middle			<b>4.9</b>	5.0
	SR4(N)	Surface and Middle			5.2	<b>4.8</b>
	SR5(N)	Surface and Middle			<b>4.9</b>	<b>4.8</b>
	SR6	Surface and Middle			<b>4.8</b>	<b>4.8</b>
	SR7	Surface and Middle			5.0	<b>4.8</b>
	SR10A	Surface and Middle			<b>4.9</b>	<b>4.7</b>
	SR10B(N)	Surface and Middle			<b>4.8</b>	<b>4.6</b>
Bottom		4.9	<b>4.5</b>			

Notes:

AL means Action Level.

LL means Limit Level.


**Bold** means AL exceedances.

**Bold with underline** means LL exceedances.



**Possible reason for Action and Limit Level Non-compliance:**

On 22 September 2017, six AL exceedances of DO at IS10(N), IS(Mf)11, SR3, SR5(N) and SR6 were recorded during mid-ebb tide, two LL exceedances of DO at SR10A and SR10B(N) were recorded during mid-ebb tide. Eleven AL exceedances of DO at IS8, IS(Mf)9, IS10(N), IS(Mf)11, IS(Mf)16, IS17, SR4(N), SR5(N), SR6, SR7 and SR10B(N) were recorded during mid-flood tide, two LL exceedances of DO at SR10A and SR10B(N) were recorded during mid-flood tide.



As confirmed by the Contractor, there were no marine transportation and marine-based work on 22 September 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedances were not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Reviewed by : Keith Chau Title : ET Leader

*Keith* Date : 11 October 2017

Copied to : Contractor, Engineer Representative and IEC/ENPO

**Contract No. HY/2013/01 - Hong Kong- Zhuhai- Macao Bridge**  
**Hong Kong Boundary Crossing Facilities – Passenger Clearance Building**  
**Notifications of Environmental Quality Limits Exceedances** Notification No.: 20170925DO\_SS\_v1

**Date of Notification:** 3 October 2017 **Date of Investigation Report:** 11 October 2017

**Works Inspected:** Data collected from water sampling works on 25 September 2017 and the results were issued on 6 October 2017

**Monitoring Location:** Water Quality Monitoring Station

**Parameter:** Dissolved Oxygen (DO)/ Suspended Solid (SS)/ ~~Turbidity (TURB)~~


**Action & Limit Level (AL & LL) / Measured Level:**

PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)
DO	SR10B(N)	Surface and Middle	Surface and Middle 5.0	Surface and Middle 4.2 (except 5 mg/L for FCZ) Bottom 3.6	5.1	<b><u>4.7</u></b>
		Bottom	Bottom 4.7		5.0	<b>4.6</b>
SS	IS8	Depth Average	23.5 and 120% (i.e. 7.3 for mid-ebb/9.1 for mid-flood) of upstream control station's SS at the same tide of the same day	34.4 and 130% (i.e. 7.9 for mid-ebb/9.8 for mid-flood) of upstream control station's SS at the same tide of the same day and 10mg/L for WSD Seawater intakes	11.3	<b>30.4</b>

Notes:  
AL means Action Level.  
LL means Limit Level.  
**Bold** means AL exceedances.  
**Bold with underline** means LL exceedances.  
Upstream control stations of mid-ebb tide: CS(Mf)3(N) and CS4  
Upstream control stations of mid-flood tide: CS(Mf)5, CS6 and CSA

**Possible reason for Action and Limit Level Non-compliance:**


On 25 September 2017, one AL exceedance of DO at SR10B(N) was recorded during mid-flood tide, one LL exceedance of DO at SR10B(N) was recorded during mid-flood tide and one AL exceedance of SS at IS8 was recorded during mid-flood tide..



As confirmed by the Contractor, there were no marine transportation and marine-based work on 25 September 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedances were not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Reviewed by : Keith Chau  


Title : ET Leader

Date : 11 October 2017

Copied to : Contractor, Engineer Representative and IEC/ENPO

**Contract No. HY/2013/01 -  
 Hong Kong- Zhuhai- Macao Bridge  
 Hong Kong Boundary Crossing Facilities – Passenger Clearance Building**  
**Notifications of Environmental Quality Limits Exceedances** Notification No.: 20170927DO\_v1

**Date of Notification:** 4 October 2017 **Date of Investigation Report:** 10 October 2017

**Works Inspected:** Data collected from water sampling works on 27 September 2017 and the results were issued on 3 October 2017

**Monitoring Location:** Water Quality Monitoring Station


**Action & Limit Level (AL & LL) / Measured Level:**

PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)
DO	IS10(N)	Bottom	Surface and Middle 5.0 Bottom 4.7	Surface and Middle 4.2 (except 5 mg/L for FCZ) Bottom 3.6	<b>4.6</b>	5.0
DO	IS17	Bottom			<b>4.6</b>	4.8
DO	SR5(N)	Bottom			<b>4.6</b>	5.0
DO	SR10A	Bottom			5.3	<b>4.6</b>
DO	SR10B(N)	Surface and Middle			5.0	<b><u>4.7</u></b>
		Bottom			<b>4.4</b>	<b>4.4</b>

Notes:  
 AL means Action Level.  
 LL means Limit Level.  
**Bold** means AL exceedances.  
**Bold with underline** means LL exceedances.

**Possible reason for Action and Limit Level Non-compliance:**


On 27 September 2017, four AL exceedances of DO at IS10(N), IS17, SR5(N) and SR10B(N) were recorded during mid-ebb tide. Two AL exceedance of DO at SR10A and SR10B(N) were recorded during mid-flood tide, one LL exceedance of DO at SR10B(N) was recorded during mid-flood tide.



As confirmed by the Contractor, there were no marine transportation and marine-based work on 27 September 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedances were not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Reviewed by : Keith Chau Title : ET Leader  
 Date : 10 October 2017

Copied to : Contractor, Engineer Representative and IEC/ENPO

Contract No. HY/2013/01 -

Hong Kong- Zhuhai- Macao Bridge

Hong Kong Boundary Crossing Facilities – Passenger Clearance Building

Notifications of Environmental Quality Limits Exceedances

Notification No.: 20170929DO\_v3

Date of Notification: 9 October 2017

Date of Investigation Report: 17 October 2017

Works Inspected: Data collected from water sampling works on 29 September 2017 and the results were issued on 6 October 2017

Monitoring Location: Water Quality Monitoring Station

Parameter: Dissolved Oxygen (DO)/ ~~Suspended Solid (SS)~~/ Turbidity (TURB)

Action & Limit Level (AL & LL) / Measured Level:

PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)
DO	IS5	Bottom	Surface and Middle 5.0 Bottom 4.7	Surface and Middle 4.2 (except 5 mg/L for FCZ) Bottom 3.6	<b>4.8</b>	<b>4.4</b>
	IS7	Bottom			<b>4.3</b>	15.0*
	IS8	Bottom			<b>4.4</b>	5.7
	IS10(N)	Surface and Middle			<b>4.8</b>	6.2
		Bottom			<b>4.2</b>	<b>4.2</b>
	IS(Mf)11	Bottom			<b>4.6</b>	<b>4.1</b>
	IS(Mf)16	Bottom			<b>4.4</b>	5.5
	IS17	Bottom			4.7	<b>4.2</b>
	SR5(N)	Bottom			<b>4.3</b>	<b>4.2</b>
SR10B(N)	Bottom	<b>4.5</b>	5.0			

Notes:

AL means Action Level.

LL means Limit Level.


**Bold** means AL exceedances.

**Bold with underline** means LL exceedances.

\* Red tide was observed by water sampling team near WQM stations SR3, IS5, IS(Mf)6, IS7 and IS(Mf)6 during mid-flood tide on 29 September 2017.

**Possible reason for Action and Limit Level Non-compliance:**


On 29 September 2017, eight AL exceedances of DO at IS7, IS8, IS10(N), IS(Mf)11, IS(Mf)16, SR5(N) and SR10B(N) were recorded during mid-ebb tide. Five AL exceedance of DO at IS5, IS10(N), IS(Mf)11, IS17 and SR5(N) were recorded during mid-flood tide.



As confirmed by the Contractor, there were no marine transportation and marine-based work on 29 September 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedances were not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Reviewed by : Keith Chau Title : ET Leader  
 Date : 17 October 2017

Copied to : Contractor, Engineer Representative and IEC/ENPO

**Contract No. HY/2013/01 - Hong Kong- Zhuhai- Macao Bridge**  
**Hong Kong Boundary Crossing Facilities – Passenger Clearance Building**  
**Notifications of Environmental Quality Limits Exceedances** Notification No.: 20171002DO\_v1

**Date of Notification:** 10 October 2017 **Date of Investigation Report:** 20 October 2017

**Works Inspected:** Data collected from water sampling works on 2 October 2017 and the results were issued on 10 October 2017

**Monitoring Location:** Water Quality Monitoring Station

**Parameter:** Dissolved Oxygen (DO)/ ~~Suspended Solid (SS)~~/ Turbidity (TURB)

**Action & Limit Level (AL & LL) / Measured Level:**


PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)
DO	SR10A*	Bottom	Surface and Middle 5.0 Bottom 4.7	Surface and Middle 4.2 (except 5 mg/L for FCZ) Bottom 3.6	<b>4.6</b>	<b>4.5</b>
	SR10B(N)*	Surface and Middle			5.4	<b><u>4.7</u></b>
	SR10B(N)*	Bottom			5.1	<b>4.6</b>

Notes:  
AL means Action Level.  
LL means Limit Level.  
**Bold** means AL exceedances.  
**Bold with underline** means LL exceedances.  
\* Monitoring stations SR3, SR10A and SR10B(N) were not available for water sampling due to safety reason, the monitoring stations were changed to tentative coordination.  
(i.e. SR3(N): E810689 N816591, SR10A(N): E823644 N823484 and SR10B(N2): E823689 N823159)



**Possible reason for Action and Limit Level Non-compliance:**


On 2 October 2017, one AL exceedance of DO at SR10A was recorded during mid-ebb tide, two AL exceedances of DO at SR10A and SR10B(N) were recorded during mid-flood tide and one LL exceedance of DO at SR10B(N) was recorded during mid-flood tide.



As confirmed by the Contractor, there were no marine transportation and marine-based work on 2 October 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedances were not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Reviewed by : Keith Chau Title : ET Leader  
 Date : 20 October 2017

Copied to : Contractor, Engineer Representative and IEC/ENPO

**Contract No. HY/2013/01 - Hong Kong- Zhuhai- Macao Bridge**  
**Hong Kong Boundary Crossing Facilities – Passenger Clearance Building**  
**Notifications of Environmental Quality Limits Exceedances** Notification No.: 20171004DO\_v1

**Date of Notification:** 12 October 2017 **Date of Investigation Report:** 20 October 2017

**Works Inspected:** Data collected from water sampling works on 4 October 2017 and the results were issued on 9 October 2017

**Monitoring Location:** Water Quality Monitoring Station

**Parameter:** Dissolved Oxygen (DO)/ ~~Suspended Solid (SS)/ Turbidity (TURB)~~


**Action & Limit Level (AL & LL) / Measured Level:**

PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)
DO	SR10A**	Surface and Middle	Surface and Middle 5.0 Bottom 4.7	Surface and Middle 4.2 (except 5 mg/L for FCZ) Bottom 3.6	<b><u>4.7</u></b>	<b><u>4.5</u></b>
	SR10A**	Bottom			<b>4.6</b>	<b>4.3</b>
	SR10B(N)*	Surface and Middle			<b><u>4.8</u></b>	<b><u>4.5</u></b>
	SR10B(N)*	Bottom			4.9	<b>4.5</b>

Notes:  
AL means Action Level.  
LL means Limit Level.  
**Bold** means AL exceedances.  
**Bold with underline** means LL exceedances.  
\* Monitoring stations SR3, SR10A and SR10B(N) were not available for water sampling due to safety reason, the monitoring stations were changed to tentative coordination.  
(i.e. SR3(N): E810689 N816591, SR10A(N): E823644 N823484 and SR10B(N2): E823689 N823159)  
# Location was changed due to fishing net installed in the vicinity (22<sup>o</sup>21.1165'N; 114<sup>o</sup>03.1185'E)

**Possible reason for Action and Limit Level Non-compliance:**

On 4 October 2017, one AL exceedance of DO at SR10A was recorded during mid-ebb tide, two AL exceedances of DO at SR10A and SR10B(N) were recorded during mid-flood tide, two LL exceedances of DO at SR10A and SR10B(N) were recorded during mid-ebb tide and two LL exceedances of DO at SR10A and SR10B(N) were recorded during mid-flood tide.



As confirmed by the Contractor, there were no marine transportation and marine-based work on 4 October 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedances were not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Reviewed by : Keith Chau

Title : ET Leader

Date : 20 October 2017

Copied to : Contractor, Engineer Representative and IEC/ENPO

**Contract No. HY/2013/01 - Hong Kong- Zhuhai- Macao Bridge**  
**Hong Kong Boundary Crossing Facilities – Passenger Clearance Building**  
**Notifications of Environmental Quality Limits Exceedances** Notification No.: 20171006DO\_v2

**Date of Notification:** 11 October 2017 **Date of Investigation Report:** 26 October 2017

**Works Inspected:** Data collected from water sampling works on 6 October 2017 and the results were issued on 11 October 2017

**Monitoring Location:** Water Quality Monitoring Station

**Parameter:** Dissolved Oxygen (DO)/ ~~Suspended Solid (SS)~~/ Turbidity (TURB)


**Action & Limit Level (AL & LL) / Measured Level:**

PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)
DO	SR10B(N)*	Surface and Middle	Surface and Middle 5.0	Surface and Middle 4.2 (except 5 mg/L for FCZ) Bottom 3.6	<b><u>4.9</u></b>	<b><u>4.5</u></b>
	SR10B(N)*	Bottom	Bottom 4.7		5.0	<b><u>4.6</u></b>

Notes:  
AL means Action Level.  
LL means Limit Level.  
**Bold** means AL exceedances.  
**Bold with underline** means LL exceedances.  
\* Monitoring stations SR3, SR10A and SR10B(N) were not available for water sampling due to safety reason, the monitoring stations were changed to tentative coordination.  
(i.e. SR3(N): E810689 N816591, SR10A(N): E823644 N823484 and SR10B(N2): E823689 N823159)

**Possible reason for Action and Limit Level Non-compliance:**


On 6 October 2017, one AL exceedance of DO at SR10B(N) was recorded during mid-flood tide, one LL exceedance of DO at SR10B(N) was recorded during mid-ebb tide and one LL exceedance of DO at SR10B(N) was recorded during mid-flood tide.



As confirmed by the Contractor, there were no marine transportation and marine-based work on 6 October 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedances were not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.


Reviewed by : Keith Chau Title : ET Leader  
 Date : 26 October 2017

Copied to : Contractor, Engineer Representative and IEC/ENPO

<b>Contract No. HY/2013/01 - Hong Kong- Zhuhai- Macao Bridge</b> <b>Hong Kong Boundary Crossing Facilities – Passenger Clearance Building</b> <b>Notifications of Environmental Quality Limits Exceedances</b>							Notification No.: 20171009DO_v1
<b>Date of Notification:</b> 12 October 2017				<b>Date of Investigation Report:</b> 26 October 2017			
<b>Works Inspected:</b> Data collected from water sampling works on 9 October 2017 and the results were issued on 12 October 2017							
<b>Monitoring Location:</b> Water Quality Monitoring Station							
<b>Parameter:</b> Dissolved Oxygen (DO)/ <del>Suspended Solid (SS)</del> / Turbidity (TURB)							
<b>Action &amp; Limit Level (AL &amp; LL) / Measured Level:</b>							
PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)	
DO	SR10B(N)*	Surface and Middle	Surface and Middle 5.0 Bottom 4.7	Surface and Middle 4.2 (except 5 mg/L for FCZ) Bottom 3.6	5.2	<b><u>4.8</u></b>	
Notes: AL means Action Level. LL means Limit Level. <b>Bold</b> means AL exceedances. <b><u>Bold with underline</u></b> means LL exceedances. * Monitoring stations SR3, SR10A and SR10B(N) were not available for water sampling due to safety reason, the monitoring stations were changed to tentative coordination. (i.e. SR3(N): E810689 N816591, SR10A(N): E823644 N823484 and SR10B(N2): E823689 N823159)							

**Possible reason for Action and Limit Level Non-compliance:**

On 9 October 2017, one LL exceedance of DO at SR10B(N) was recorded during mid-flood tide.



As confirmed by the Contractor, there were no marine transportation and marine-based work on 9 October 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedance was not related to the Contract.

**Actions taken/ to be taken:**

As the exceedance was not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Prepared by: Evan Wong Title: Environmental Team Representative

Signature:  Date: 26 October 2017

Checked by: Keith Chau Title: Environmental Team Leader


Signature:  Date: 26 October 2017

<b>Contract No. HY/2013/01 -  Hong Kong- Zhuhai- Macao Bridge  Hong Kong Boundary Crossing Facilities – Passenger Clearance Building  Notifications of Environmental Quality Limits Exceedances</b>							Notification No.: 20171018SS
<b>Date of Notification:</b> 27 October 2017				<b>Date of Investigation Report:</b> 30 October 2017			
<b>Works Inspected:</b> Data collected from water sampling works on 18 October 2017 and the results were issued on 26 October 2017							
<b>Monitoring Location:</b> Water Quality Monitoring Station							
<b>Parameter:</b> <del>Dissolved Oxygen (DO)</del> / Suspended Solid (SS)/ <del>Turbidity (TURB)</del>							
<b>Action &amp; Limit Level (AL &amp; LL) / Measured Level:</b>							
PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)	
SS	SR5(N)	Depth Average	23.5 and 120% (i.e. 10.6 for mid-ebb/23.9 for mid-flood) of upstream control station's SS at the same tide of the same day	34.4 and 130% (i.e. 11.5 for mid-ebb/25.9 for mid-flood) of upstream control station's SS at the same tide of the same day and 10mg/L for WSD Seawater intakes	9.5	<b>30.1</b>	
Notes: AL means Action Level. LL means Limit Level. <b>Bold</b> means AL exceedances. <b><u>Bold with underline</u></b> means LL exceedances. Upstream control stations of mid-ebb tide: CS(Mf)3(N) and CS4 Upstream control stations of mid-flood tide: CS(Mf)5, CS6 and CSA							



**Possible reason for Action and Limit Level Non-compliance:**

On 18 October 2017, one AL exceedance of SS at SR5(N) was recorded during mid-flood tide.



As confirmed by the Contractor, there was no marine transportation and marine-based work on 18 October 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedance was not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Prepared by: Evan Wong Title: Environmental Team Representative

Signature:  Date: 30 October 2017

Checked by: Keith Chau Title: Environmental Team Leader


Signature:  Date: 30 October 2017

Copied to : Contractor, Engineer Representative and IEC/ENPO

<b>Contract No. HY/2013/01 - Hong Kong- Zhuhai- Macao Bridge</b> <b>Hong Kong Boundary Crossing Facilities – Passenger Clearance Building</b> <b>Notifications of Environmental Quality Limits Exceedances</b>							Notification No.: 20171020SS
<b>Date of Notification:</b> 31 October 2017				<b>Date of Investigation Report:</b> 3 November 2017			
<b>Works Inspected:</b> Data collected from water sampling works on 20 October 2017 and the results were issued on 30 October 2017							
<b>Monitoring Location:</b> Water Quality Monitoring Station							
<b>Parameter:</b> <del>Dissolved Oxygen (DO)</del> / <del>Suspended Solid (SS)</del> / <del>Turbidity (TURB)</del>							
<b>Action &amp; Limit Level (AL &amp; LL) / Measured Level:</b>							
PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)	
SS	IS(Mf)11	Depth Average	23.5 and 120% (i.e. 20.8 for mid-ebb/20.1 for mid-flood) of upstream control station's SS at the same tide of the same day	34.4 and 130% (i.e. 22.6 for mid-ebb/21.8 for mid-flood) of upstream control station's SS at the same tide of the same day and 10mg/L for WSD Seawater intakes	11.9	<b>26.1</b>	
	SR5(N)				8.0	<b>24.4</b>	
	SR7				14.9	<b>28.3</b>	
Notes: AL means Action Level. LL means Limit Level. <b>Bold</b> means AL exceedances. <b><u>Bold with underline</u></b> means LL exceedances. Upstream control stations of mid-ebb tide: CS(Mf)3(N) and CS4 Upstream control stations of mid-flood tide: CS(Mf)5, CS6 and CSA							

**Possible reason for Action / Limit Level Non-compliance:**



On 20 October 2017, three AL exceedances of SS at IS(Mf)11, SR5(N) and SR7 were recorded during mid-flood tide.



As confirmed by the Contractor, there was no marine transportation and marine-based work on 20 October 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**


As the exceedance was not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Prepared by:	<u>Evan Wong</u>	Title:	<u>Environmental Team Representative</u>
Signature:	<u></u>	Date:	<u>3 November 2017</u>
Checked by:	<u>Keith Chau</u>	Title:	<u>Environmental Team Leader</u>
Signature:	<u></u>	Date:	<u>3 November 2017</u>
Copied to	: Contractor, Engineer Representative and IEC/ENPO		

<b>Contract No. HY/2013/01 -  Hong Kong- Zhuhai- Macao Bridge  Hong Kong Boundary Crossing Facilities – Passenger Clearance Building  Notifications of Environmental Quality Limits Exceedances</b>							Notification No.: 20171023SS
<b>Date of Notification:</b> 1 November 2017				<b>Date of Investigation Report:</b> 6 November 2017			
<b>Works Inspected:</b> Data collected from water sampling works on 23 October 2017 and the results were issued on 1 November 2017							
<b>Monitoring Location:</b> Water Quality Monitoring Station							
<b>Parameter:</b> <del>Dissolved Oxygen (DO)</del> / Suspended Solid (SS)/ <del>Turbidity (TURB)</del>							
<b>Action &amp; Limit Level (AL &amp; LL) / Measured Level:</b>							
PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)	
SS	SR5(N)	Depth Average	23.5 and 120% (i.e. 14.8 for mid-ebb/16.9 for mid-flood) of upstream control station's SS at the same tide of the same day	34.4 and 130% (i.e. 16.0 for mid-ebb/18.3 for mid-flood) of upstream control station's SS at the same tide of the same day and 10mg/L for WSD Seawater intakes	10.4	<b>26.3</b>	
Notes: AL means Action Level. LL means Limit Level. <b>Bold</b> means AL exceedances. <b><u>Bold with underline</u></b> means LL exceedances. Upstream control stations of mid-ebb tide: CS(Mf)3(N) and CS4 Upstream control stations of mid-flood tide: CS(Mf)5, CS6 and CSA							

**Possible reason for Action / Limit Level Non-compliance:**

On 23 October 2017, one AL exceedance of SS at SR5(N) was recorded during mid-flood tide.



As confirmed by the Contractor, there was no marine transportation and marine-based work on 23 October 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedance was not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Prepared by: Evan Wong Title: Environmental Team Representative

Signature:  Date: 6 November 2017

Checked by: Keith Chau Title: Environmental Team Leader


Signature:  Date: 6 November 2017

Copied to : Contractor, Engineer Representative and IEC/ENPO

<b>Contract No. HY/2013/01 -  Hong Kong- Zhuhai- Macao Bridge  Hong Kong Boundary Crossing Facilities – Passenger Clearance Building  Notifications of Environmental Quality Limits Exceedances</b>							Notification No.: 20171103SS
<b>Date of Notification:</b> 10 November 2017				<b>Date of Investigation Report:</b> 14 November 2017			
<b>Works Inspected:</b> Data collected from water sampling works on 3 November 2017 and the results were issued on 10 November 2017							
<b>Monitoring Location:</b> Water Quality Monitoring Station							
<b>Parameter:</b> <del>Dissolved Oxygen (DO)</del> / <del>Suspended Solid (SS)</del> / <del>Turbidity (TURB)</del>							
<b>Action &amp; Limit Level (AL &amp; LL) / Measured Level:</b>							
PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)	
SS	IS(Mf)11	Depth Average	23.5 and 120% (i.e. 15.7 for mid-ebb/13.8 for mid-flood) of upstream control station's SS at the same tide of the same day	34.4 and 130% (i.e. 17.0 for mid-ebb/14.9 for mid-flood) of upstream control station's SS at the same tide of the same day and 10mg/L for WSD Seawater intakes	10.8	<b>26.6</b>	
	SR5(N)				14.8	<b><u>37.8</u></b>	
	SR6				<b>25.9</b>	14.1	
	SR7				13.6	<b>33.7</b>	
Notes: AL means Action Level. LL means Limit Level. <b>Bold</b> means AL exceedances. <b>Bold with underline</b> means LL exceedances. Upstream control stations of mid-ebb tide: CS(Mf)3(N) and CS4 Upstream control stations of mid-flood tide: CS(Mf)5, CS6 and CSA							

**Possible reason for Action / Limit Level Non-compliance:**

On 3 November 2017, one AL exceedance of SS at SR6 was recorded during mid-ebb tide. Two AL exceedances of SS at IS(Mf)11 and SR7 were recorded during mid-flood tide. One LL exceedance of SS at SR5(N) was recorded during mid-flood tide.



As confirmed by the Contractor, there was no marine transportation and marine-based work on 3 November 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedance was not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Prepared by: Evan Wong

Title: Environmental Team Representative

Signature: 

Date: 14 November 2017

Checked by: Keith Chau

Title: Environmental Team Leader

Signature: 

Date: 14 November 2017


Copied to : Contractor, Engineer Representative and IEC/ENPO

<b>Contract No. HY/2013/01 -  Hong Kong- Zhuhai- Macao Bridge  Hong Kong Boundary Crossing Facilities – Passenger Clearance Building</b>							Notification No.: 20171106SS
<b>Date of Notification:</b> 15 November 2017				<b>Date of Investigation Report:</b> 16 November 2017			
<b>Works Inspected:</b> Data collected from water sampling works on 6 November 2017 and the results were issued on 14 November 2017							
<b>Monitoring Location:</b> Water Quality Monitoring Station							
<b>Parameter:</b> <del>Dissolved Oxygen (DO)</del> / Suspended Solid (SS)/ <del>Turbidity (TURB)</del>							
<b>Action &amp; Limit Level (AL &amp; LL) / Measured Level:</b>							
PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)	
SS	IS(Mf)6	Depth Average	23.5 and 120% (i.e. 15.9 for mid-ebb/19.8 for mid-flood) of upstream control station's SS at the same tide of the same day	34.4 and 130% (i.e. 17.2 for mid-ebb/21.4 for mid-flood) of upstream control station's SS at the same tide of the same day and 10mg/L for WSD Seawater intakes	10.0	<b>27.2</b>	
	IS(Mf)16				11.5	<b>25.1</b>	
	SR7				10.3	<b>25.5</b>	
	SR10A				15.0	<b>26.0</b>	
	SR10B(N)				7.9	<b>25.2</b>	
Notes: AL means Action Level. LL means Limit Level. <b>Bold</b> means AL exceedances. <b><u>Bold with underline</u></b> means LL exceedances. Upstream control stations of mid-ebb tide: CS(Mf)3(N) and CS4 Upstream control stations of mid-flood tide: CS(Mf)5, CS6 and CSA							



**Possible reason for Action / Limit Level Non-compliance:**

On 6 November 2017, five AL exceedances of SS at IS(Mf)6, IS(Mf)16, SR7, SR10A and SR10B(N) were recorded during mid-flood tide.



As confirmed by the Contractor, there was no marine transportation and marine-based work on 6 November 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedance was not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Prepared by: Evan Wong Title: Environmental Team Representative

Signature:  Date: 16 November 2017

Checked by: Keith Chau Title: Environmental Team Leader


Signature:  Date: 16 November 2017

Copied to : Contractor, Engineer Representative and IEC/ENPO

<b>Contract No. HY/2013/01 -  Hong Kong- Zhuhai- Macao Bridge  Hong Kong Boundary Crossing Facilities – Passenger Clearance Building  Notifications of Environmental Quality Limits Exceedances</b>							Notification No.: 20171108SS
<b>Date of Notification:</b> 16 November 2017				<b>Date of Investigation Report:</b> 20 November 2017			
<b>Works Inspected:</b> Data collected from water sampling works on 8 November 2017 and the results were issued on 16 November 2017							
<b>Monitoring Location:</b> Water Quality Monitoring Station							
<b>Parameter:</b> <del>Dissolved Oxygen (DO)</del> / Suspended Solid (SS)/ <del>Turbidity (TURB)</del>							
<b>Action &amp; Limit Level (AL &amp; LL) / Measured Level:</b>							
PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)	
SS	IS(Mf)11	Depth Average	23.5 and 120% (i.e. 19.7 for mid-ebb/13.2 for mid-flood) of upstream control station's SS at the same tide of the same day	34.4 and 130% (i.e. 21.3 for mid-ebb/14.3 for mid-flood) of upstream control station's SS at the same tide of the same day and 10mg/L for WSD Seawater intakes	10.2	<b>24.3</b>	
	SR4(N)				18.5	<b><u>35.1</u></b>	
	SR5(N)				14.9	<b><u>38.2</u></b>	
	SR6				<b>27.9</b>	18.9	
Notes: AL means Action Level. LL means Limit Level. <b>Bold</b> means AL exceedances. <b>Bold with underline</b> means LL exceedances. Upstream control stations of mid-ebb tide: CS(Mf)3(N) and CS4 Upstream control stations of mid-flood tide: CS(Mf)5, CS6 and CSA							

**Possible reason for Action / Limit Level Non-compliance:**

On 8 November 2017, one AL exceedance of SS at IS(Mf)11 was recorded during mid-flood tide. One AL exceedance of SS at SR6 was recorded during mid-ebb tide. Two LL exceedances of SS at SR4(N) and SR5(N) were recorded during mid-flood tide.



As confirmed by the Contractor, there was no marine transportation and marine-based work on 8 November 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedance was not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Prepared by: Evan Wong Title: Environmental Team Representative

Signature:  Date: 20 November 2017

Checked by: Keith Chau Title: Environmental Team Leader


Signature:  Date: 20 November 2017

Copied to : Contractor, Engineer Representative and IEC/ENPO

<b>Contract No. HY/2013/01 -  Hong Kong- Zhuhai- Macao Bridge  Hong Kong Boundary Crossing Facilities – Passenger Clearance Building  Notifications of Environmental Quality Limits Exceedances</b>							Notification No.: 20171113SS
<b>Date of Notification:</b> 22 November 2017				<b>Date of Investigation Report:</b> 24 November 2017			
<b>Works Inspected:</b> Data collected from water sampling works on 13 November 2017 and the results were issued on 22 November 2017							
<b>Monitoring Location:</b> Water Quality Monitoring Station							
<b>Parameter:</b> <del>Dissolved Oxygen (DO)</del> / Suspended Solid (SS)/ <del>Turbidity (TURB)</del>							
<b>Action &amp; Limit Level (AL &amp; LL) / Measured Level:</b>							
PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)	
SS	IS8	Depth Average	23.5 and 120% (i.e. 7.6 for mid-ebb/9.1 for mid-flood) of upstream control station's SS at the same tide of the same day	34.4 and 130% (i.e. 8.2 for mid-ebb/9.9 for mid-flood) of upstream control station's SS at the same tide of the same day and 10mg/L for WSD Seawater intakes	16.6	<b>29.1</b>	
Notes: AL means Action Level. LL means Limit Level. <b>Bold</b> means AL exceedances. <b><u>Bold with underline</u></b> means LL exceedances. Upstream control stations of mid-ebb tide: CS(Mf)3(N) and CS4 Upstream control stations of mid-flood tide: CS(Mf)5, CS6 and CSA							

**Possible reason for Action / Limit Level Non-compliance:**

On 13 November 2017, one AL exceedance of SS at IS8 was recorded during mid-flood tide.



As confirmed by the Contractor, there was no marine transportation and marine-based work on 13 November 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedance was not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Prepared by: Evan Wong Title: Environmental Team Representative

Signature:  Date: 24 November 2017

Checked by: Keith Chau Title: Environmental Team Leader


Signature:  Date: 24 November 2017

Copied to : Contractor, Engineer Representative and IEC/ENPO

<b>Contract No. HY/2013/01 -  Hong Kong- Zhuhai- Macao Bridge  Hong Kong Boundary Crossing Facilities – Passenger Clearance Building  Notifications of Environmental Quality Limits Exceedances</b>							Notification No.: 20171115SS
<b>Date of Notification:</b> 22 November 2017				<b>Date of Investigation Report:</b> 24 November 2017			
<b>Works Inspected:</b> Data collected from water sampling works on 15 November 2017 and the results were issued on 22 November 2017							
<b>Monitoring Location:</b> Water Quality Monitoring Station							
<b>Parameter:</b> <del>Dissolved Oxygen (DO)</del> / Suspended Solid (SS)/ <del>Turbidity (TURB)</del>							
<b>Action &amp; Limit Level (AL &amp; LL) / Measured Level:</b>							
PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)	
SS	IS(Mf)6	Depth Average	23.5 and 120% (i.e. 8.4 for mid-ebb/5.5 for mid-flood) of upstream control station's SS at the same tide of the same day	34.4 and 130% (i.e. 9.1 for mid-ebb/6.0 for mid-flood) of upstream control station's SS at the same tide of the same day and 10mg/L for WSD Seawater intakes	8.9	<b>24.8</b>	
Notes: AL means Action Level. LL means Limit Level. <b>Bold</b> means AL exceedances. <b><u>Bold with underline</u></b> means LL exceedances. Upstream control stations of mid-ebb tide: CS(Mf)3(N) and CS4 Upstream control stations of mid-flood tide: CS(Mf)5, CS6 and CSA							

**Possible reason for Action / Limit Level Non-compliance:**

On 15 November 2017, one AL exceedance of SS at IS(Mf)6 was recorded during mid-flood tide.



As confirmed by the Contractor, there was no marine transportation and marine-based work on 15 November 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedance was not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Prepared by: Evan Wong Title: Environmental Team Representative

Signature:  Date: 24 November 2017

Checked by: Keith Chau Title: Environmental Team Leader

Signature:  Date: 24 November 2017

Copied to : Contractor, Engineer Representative and IEC/ENPO

<b>Contract No. HY/2013/01 -  Hong Kong- Zhuhai- Macao Bridge  Hong Kong Boundary Crossing Facilities – Passenger Clearance Building</b>						
<b>Notifications of Environmental Quality Limits Exceedances</b>						Notification No.: 20171120SS
<b>Date of Notification:</b> 28 November 2017				<b>Date of Investigation Report:</b> 30 November 2017		
<b>Works Inspected:</b> Data collected from water sampling works on 20 November 2017 and the results were issued on 28 November 2017						
<b>Monitoring Location:</b> Water Quality Monitoring Station						
<b>Parameter:</b> <del>Dissolved Oxygen (DO)</del> / Suspended Solid (SS)/ <del>Turbidity (TURB)</del>						
<b>Action &amp; Limit Level (AL &amp; LL) / Measured Level:</b>						
PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)
SS	SR7	Depth Average	23.5 and 120% (i.e. 19.7 for mid-ebb/14.0 for mid-flood) of upstream control station's SS at the same tide of the same day	34.4 and 130% (i.e. 21.4 for mid-ebb/15.2 for mid-flood) of upstream control station's SS at the same tide of the same day and 10mg/L for WSD Seawater intakes	11.7	<b>24.1</b>
Notes: AL means Action Level. LL means Limit Level. <b>Bold</b> means AL exceedances. <b><u>Bold with underline</u></b> means LL exceedances. Upstream control stations of mid-ebb tide: CS(Mf)3(N) and CS4 Upstream control stations of mid-flood tide: CS(Mf)5, CS6 and CSA						






<b>Contract No. HY/2013/01 -  Hong Kong- Zhuhai- Macao Bridge  Hong Kong Boundary Crossing Facilities – Passenger Clearance Building  Notifications of Environmental Quality Limits Exceedances</b>							Notification No.: 20171122SS
<b>Date of Notification:</b> 30 November 2017				<b>Date of Investigation Report:</b> 6 December 2017			
<b>Works Inspected:</b> Data collected from water sampling works on 22 November 2017 and the results were issued on 29 November 2017							
<b>Monitoring Location:</b> Water Quality Monitoring Station							
<b>Parameter:</b> <del>Dissolved Oxygen (DO)</del> / Suspended Solid (SS)/ <del>Turbidity (TURB)</del>							
<b>Action &amp; Limit Level (AL &amp; LL) / Measured Level:</b>							
PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)	
SS	SR6	Depth Average	23.5 and 120% (i.e. 12.5 for mid-ebb/7.5 for mid-flood) of upstream control station's SS at the same tide of the same day	34.4 and 130% (i.e. 13.5 for mid-ebb/8.2 for mid-flood) of upstream control station's SS at the same tide of the same day and 10mg/L for WSD Seawater intakes	<b>26.6</b>	<b><u>36.1</u></b>	
Notes: AL means Action Level. LL means Limit Level. <b>Bold</b> means AL exceedances. <b>Bold with underline</b> means LL exceedances. Upstream control stations of mid-ebb tide: CS(Mf)3(N) and CS4 Upstream control stations of mid-flood tide: CS(Mf)5, CS6 and CSA							

**Possible reason for Action / Limit Level Non-compliance:**

On 22 November 2017, one AL exceedance of SS at SR6 was recorded during mid-ebb tide and one LL exceedance of SS at SR6 was recorded during mid-flood tide.



As confirmed by the Contractor, there was no marine transportation and marine-based work on 22 November 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedance was not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Prepared by: Evan Wong

Title: Environmental Team Representative

Signature: 

Date: 6 December 2017

Checked by: Keith Chau

Title: Environmental Team Leader

Signature: 

Date: 6 December 2017

Copied to : Contractor, Engineer Representative and IEC/ENPO

**Contract No. HY/2013/01 -  
 Hong Kong- Zhuhai- Macao Bridge  
 Hong Kong Boundary Crossing Facilities – Passenger Clearance Building**  
**Notifications of Environmental Quality Limits Exceedances** Notification No.: 20171124SS\_v1

**Date of Notification:** 1 December 2017 **Date of Investigation Report:** 7 December 2017

**Works Inspected:** Data collected from water sampling works on 24 November 2017 and the results were issued on 1 December 2017

**Monitoring Location:** Water Quality Monitoring Station

**Parameter:** ~~Dissolved Oxygen (DO)~~/ Suspended Solid (SS)/~~Turbidity (TURB)~~


**Action & Limit Level (AL & LL) / Measured Level:**

PARAM	STATION	DEPTH	AL (mg/L)	LL (mg/L)	MEASURED AT MID-EBB TIDE (mg/L)	MEASURED AT MID-FLOOD TIDE (mg/L)
SS	IS8	Depth Average	23.5 and 120% (i.e. 16.8 for mid-ebb/12.8 for mid-flood) of upstream control station's SS at the same tide of the same day	34.4 and 130% (i.e. 18.2 for mid-ebb/13.9 for mid-flood) of upstream control station's SS at the same tide of the same day and 10mg/L for WSD Seawater intakes	10.6	<b>29.9</b>

Notes:  
 AL means Action Level.  
 LL means Limit Level.  
**Bold** means AL exceedances.  
**Bold with underline** means LL exceedances.  
 Upstream control stations of mid-ebb tide: CS(Mf)3(N) and CS4  
 Upstream control stations of mid-flood tide: CS(Mf)5, CS6 and CSA

**Possible reason for Action / Limit Level Non-compliance:**

On 24 November 2017, one AL exceedance of SS at IS8 was recorded during mid-flood tide.



As confirmed by the Contractor, there was no marine transportation and marine-based work on 24 November 2017. No site runoff within the Contract site has been observed. Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

As the exceedance was not related to the Contract, no immediate actions are required. However, the Contractor was also reminded to implement environmental mitigation measures in accordance with Environmental Mitigation Implementation Schedule.

Prepared by: Evan Wong Title: Environmental Team Representative

Signature:  Date: 7 December 2017

Checked by: Keith Chau Title: Environmental Team Leader

Signature:  Date: 7 December 2017

Copied to : Contractor, Engineer Representative and IEC/ENPO

<b>Contract No. HY/2013/01 -          Hong Kong- Zhuhai- Macao Bridge          Hong Kong Boundary Crossing Facilities – Passenger Clearance Building</b> <b>Notifications of Environmental Quality Limits Exceedances</b> <span style="float: right;">Notification No.: 20171128_Air_24hr_v2</span>				
<b>Date of Notification:</b> 6 December 2017		<b>Date of Investigation Report:</b> 13 December 2017		
<b>Date of Environmental Quality Limit Exceedance:</b> 28 November 2017 and the results were issued on 6 December 2017				
<b>Monitoring Location:</b> AMS3B – Site Boundary of Site Office Area at Work Area WA2				
<b>Monitoring Date:</b> 28 November 2017		<b>Start Time:</b> 08:00		
<b>Action &amp; Limit Level (AL &amp; LL) / Measured Level:</b>				
<u>PARAMETER</u>	<u>STATION</u>	<u>AL (µg/m<sup>3</sup>)</u>	<u>LL (µg/m<sup>3</sup>)</u>	<u>MEASURED LEVEL, µg/m<sup>3</sup></u>
24-hr TSP	AMS3B – Site Boundary of Site Office Area at Works Area WA2	167	260	<b>168</b>
Notes: <b><i>Bold Italic</i></b> means AL exceedance <b><i><u>Bold Italic with underline</u></i></b> means LL exceedance				

**Possible reason for Action / Limit Level Non-compliance:**

On 28 November 2017, one AL exceedance of 24-hr TSP at AMS3B was recorded.

Based on the information from the Contractor, the construction works undertaken on 28 and 29 November 2017 are shown as below:

- Waterproofing
- Backfilling
- Formwork and falsework stripping
- Pipework and ductwork installation
- Hanger rods for cable container
- Wet trade works
- Dry trade works
- MEP High Level Containment
- Removal of temporary works
- Window wall glazing
- Heat exchanger installation
- Curtain wall glazing
- Hanging scaffolding removal
- Footbridge construction
- Refuse collection point
- Southern toilet
- MISC steelwork
- Lift installation
- Escalator Installation
- Glazed lift installation
- Road & Kerbing
- Testing and commissioning works
- Water features and planters

The Contractor confirmed that the mitigation measures according to Water Spraying Plan in November 2017 (Appendix A) are implemented to avoid dust emission. Photos of haul road condition and dust suppression are included in Appendix A. The Contractor has provided the guideline to remind the site vehicles travel within speed limit of 8km/hr. According to the site inspection conducted on 29 November 2017, no dusty activities and dry condition in haul road were observed in the site area.


The Air Quality Health Index (AQHI) of Tung Chung station with the wind data from the on-site wind station are shown in Appendix B. The hourly AQHI of Tung Chung Station ranged 3 to 8 (Low to Very High) on 28 and 29 November 2017 during monitoring period. According to the wind data at on-site wind station, no prevailing wind direction was found in the monitoring period. The PCB site of HKBCF is far away from AMS3B (more than 1km). No potential dust source was observed near the monitoring station at AMS3B during the monitoring period.

Therefore, it is concluded that the exceedances were not related to the Contract.

**Actions taken/ to be taken:**

The Water Spraying Plan including the information of watering schedule, routing of trucks of for watering and the location of water filling, was prepared and submitted to RE and ENPO. The Contractor was also reminded to implement all necessary mitigation as specified in EIA (Section 5.5.6.3), EM&A Manual (EM&A Log Ref: A3), EMP, Method Statements, General and Particular Specifications of this Project to minimize the potential dust impact during construction activities.

Prepared by: Evan Wong Title: Environmental Team Representative

Signature:  Date: 13 December 2017

Checked by: Keith Chau Title: Environmental Team Leader

Signature:  Date: 13 December 2017

Copied to : Contractor, Engineer Representative and IEC/ENPO



Leighton - Chan Wo Joint Venture

**Contract No. HY/2013/01**  
**Hong Kong – Zhuhai – Macao – Bridge**  
**Boundary Crossing Facility – Passenger Clearance Building**

Water Truck License Plate Number: TH7681

Capacity of Water Truck: 18000L


Volume of water / distance travelled = 11.4L/m

Water Truck could spray 18000L in one 50 minutes trip.

**Planned Schedule of Watering Spraying by Water Truck**

Cycle	Time of water spraying
1	08:00 – 09:15
2	09:15 – 10:30
3	10:30 – 11:45
4	13:00 – 14:15
5	14:15 – 15:30
6	15:30 – 16:45
7	16:45 – 18:00
8	18:00 – 19:00





Water spraying record on 28 Nov 2017



Water truck spray water on haul road (Point A)



Haul road is wet (Point A)



Haul road is wet (Point B)

Water spraying record on 29 Nov 2017



Water truck spray water on haul road (Point C)



Haul road is wet (Point C)



Haul road is wet (Point D)

Appendix B

Date	Hour	AQHI at Tung Chung Station	Average Wind Speed (m/s) #	Average Wind Direction #
2017/11/28	8	3	0	---
2017/11/28	9	3	0	---
2017/11/28	10	3	0	---
2017/11/28	11	4	0	---
2017/11/28	12	4	0	E
2017/11/28	13	4	0	---
2017/11/28	14	5	0	---
2017/11/28	15	5	0	---
2017/11/28	16	7	0	WNW
2017/11/28	17	5 <sup>^</sup>	0	---
2017/11/28	18	6 <sup>^</sup>	0	---
2017/11/28	19	8	0	---
2017/11/28	20	7	0	E
2017/11/28	21	6	0	---
2017/11/28	22	6	0	---
2017/11/28	23	6	0	---
2017/11/29	0	5	0	---
2017/11/29	1	5	0	---
2017/11/29	2	4	0	---
2017/11/29	3	4	0	---
2017/11/29	4	4	0	---
2017/11/29	5	3 <sup>^</sup>	0	---
2017/11/29	6	3 <sup>^</sup>	0	SSE
2017/11/29	7	3	0	SSE
2017/11/29	8	3	0.4	ENE

Remark:

<sup>^</sup> The data collection for calculation of AQHI was affected due to station or equipment maintenance, the data of a most similar station was adopted.

#- The related wind data is obtained from the on-site wind station.

N.A. - Not available.

**Contract No. HY/2013/01 - Hong Kong- Zhuhai- Macao Bridge Hong Kong Boundary Crossing Facilities – Passenger Clearance Building Notification of Environmental Quality Limit Exceedance** Notification No.: 201709-201711D

**Date of Notification:** 4 March 2019

**Works Inspected:** Not Applicable

**Monitoring Location:** NEL & NWL

**Parameter:** Ecology (Chinese White Dolphin Monitoring)

Action & Limit Levels		Monitoring Results
	North Lantau Social Cluster	
	Action Level (AL)	Limit Level (LL)
		The quarter of September 2017 – November 2017
Northeast Lantau (NEL)	STG < 4.2 & ANI < 15.5	<b><i>STG = 0; ANI = 0</i></b>
Northwest Lantau (NWL)	STG < 6.9 & ANI < 31.3	<b><i>STG = 1.41; ANI = 3.65</i></b>

Notes:

1. STG means quarterly encounter rate of number of dolphin sightings.
2. ANI means quarterly encounter rate of total number of dolphins.
3. For North Lantau Social Cluster, AL will be triggered if either NEL or NWL falls below the criteria; LL will be triggered if both NEL and NWL fall below the criteria.
4. ***Bold Italic*** means AL exceedances.
5. ***Bold Italic with underline*** means LL exceedances

**Possible reason for Action / Limit Level Non-compliance:**

One Limit Level exceedance of dolphin monitoring was recorded during quarterly monitoring (September – November 2017). The ETL informed IEC, ENPO, ER and Contractor via email on 7 December 2017.

According to information provided by ER, the marine based works undertaken during the quarterly were shown as below:

Contract No.: HY/2013/01

- Seawater intake seawall reinstatement and
- Seawater outfall pipe laying.

There is no evidence showing the current LL non-compliance directly related to the construction works of Contract No. HY/2013/01 (the Contract). The working vessels under the Contract have been travelling from source to destination in accordance with the Marine Travel Route to minimize impacts on Chinese White Dolphin (CWD). In addition, the fundamental principle is that the routes will not go through the dolphin hotspots near Brothers Marine Park.

Contract No.: HY/2013/02

- No marine based works.

Contract No.: HY/2013/03

- Box Culvert B outfall construction with cofferdams.

Contract No.: HY/2013/04

- Construction of temp steel cofferdam for Outfall construction at Box C and D.

**Actions taken/ to be taken:**

1. Statistical data analysis has been repeated to confirm findings;
2. All available and relevant data, including raw data and statistical analysis results of other parameters covered in the EM&A have been reviewed;
3. Identification of source of impact was carried out;
4. The ETL informed IEC, ENPO, ER and Contractor have been informed of findings on 7 December 2017;
5. Monitoring data have been checked;
6. Repeated review to ensure all the dolphin protective measures are fully and properly implemented and advise on additional measures if necessary;
7. After investigation, there was no evidence that indicated that the reduced number of dolphins in NWL and NEL was related solely to Project works. It was also concluded the contributed of impacted due to the HZMB works as a whole (or individual nor separate).

**Recommendations/ mitigation measures/ actions if necessary:**

All dolphin protective measures are fully and properly implemented in accordance with the EM&A Manual.

Contract No.: HY/2013/01

According to information from ER, silt curtain was installed.

Contract No.: HY/2013/02

According to information from ER, silt curtain was removed on 5 September 2017.

Contract No.: HY/2013/03

According to information from ER, silt curtain was installed.

Contract No.: HY/2013/04

According to information from ER, silt curtain was installed.

Based on section 10.2.19 of the Updated EM&A Manual (for Hong Kong Boundary Crossing Facilities)(version 1.0) that verification by IEC on 4 January 2012, the travelling speed of vessels must not exceed 10 knots within the boundaries of the Sha Chau/Lung Kwu Chau Marine Park appears to be effective in protecting the dolphins from vessel collisions. The Contractor will continue to provide training for Captains of construction vessels working in the West Lantau waters and near the Brothers Marine Park should undergo training to learn about local dolphins and porpoises. They should be trained to be aware of the protocol for “dolphin friendly” vessel operation. All working vessels should be required to use regular travel routes, in order to minimize the chance of vessel collision. And the routes would not go through the dolphin hotspot near Brothers Marine Park.

A meeting was held on 7 March 2018 with attendance of representative of ENPO, Resident Site Staff (RSS), Environmental Team (ET) and dolphin specialist for Contract Nos. HY/2013/01, HY/2011/03, HY/2011/09, HY/2012/07, HY/2012/08, to discuss the issues regarding to dolphin exceedance for the quarter September- November 2017.

In the meeting, it was concluded that the Hong Kong-Zhuhai-Macao Bridge (HZMB) works is one of the contributing factors affecting the dolphins. It was also concluded the contribution of impacts due to the HZMB works as a whole (or individual marine contracts) cannot be quantified nor separate from the other stress factors.

It was reminded that the ETs shall keep reviewing the implementation status of the dolphin related mitigation measures and remind the contractor to ensure the relevant measures were fully implemented.

It was recommended that the marine works of HZMB projects should be completed as soon as possible so as to reduce the overall duration of impacts and allow the dolphins population to recover as early as possible.

It was also recommended that the marine works footprint (e.g., reduce the size of peripheral silt curtain) and vessels for the marine works should be reduced as much as possible, and vessels idling / mooring in other part of the North Lantau shall be avoided whenever possible.

The marine travel route will shift along the edge of Brothers Marine Park (BMP) as much as practical under the Regular Marine Travel Route Plan. It was noted that even though marine vessels may moor within the mooring site of BMP, commercial activities including loading / unloading / transshipment are not allowed except a permit is obtained. The HZMB works vessels were recommended to avoid the BMP.

Prepared by: Ruby Law Title: ET Representative (up to 31 October 2018)



Date: 4 March 2019

Reviewed by: Keith Chau Title: ET Leader (up to 31 October 2018)



Date : 4 March 2019

Copied to: IEC/ENPO, Contractor and Engineer Representative



# APPENDIX L

---

## Dolphin Monitoring Results

**CONTRACT NO. HY/2013/01**  
**Hong Kong-Zhuhai-Macao Bridge Hong Kong Boundary Crossing**  
**Facilities – Dolphin Monthly Monitoring**

*First Quarterly Progress Report (September-November 2017)*  
*submitted to Leighton – Chun Wo Joint Venture*

Submitted by  
Samuel K.Y. Hung, Ph.D., Hong Kong Cetacean Research Project

January 18, 2018

**1. Introduction**

- 1.1. For the Hong Kong-Zhuhai-Macao Bridge (HZMB) Hong Kong Boundary Crossing Facilities (HKBCF), the construction of the Passenger Clearance Building (PCB) requires the contractor (i.e. Leighton – Chun Wo Joint Venture) and the associated environmental team to conduct monthly line-transect vessel surveys for the Chinese White Dolphins to cover the Northwest (NWL) and Northeast Lantau (NEL) survey areas under the Environmental Monitoring and Audit (EM&A) programme.
- 1.2. In August 2017, Hong Kong Cetacean Research Project (HKCRP) has been commissioned by the contractor to conduct regular dolphin monitoring study in order to collect data on Chinese White Dolphins during the construction phase (i.e. impact period) of the HKBCF-PCB project, and to analyze the collected survey data to monitor distribution, encounter rate, activities and occurrence of dolphin calves. Photo-identification will also be collected from individual Chinese White Dolphins to examine their individual ranging patterns.
- 1.3. From the monitoring results, any changes in dolphin occurrence within the study area will be examined for possible causes, and appropriate actions and additional mitigation measures will be recommended as necessary.
- 1.4. This report is the first quarterly progress report under the HKBCF construction phase dolphin monitoring programme submitted to Leighton – Chun Wo Joint Venture, summarizing the results of the surveys findings during the period of September to November 2017.



1.5. Notably, throughout the present quarterly progress report, the previous monitoring data obtained under Contract No. HY/2011/03 (i.e. HKLR03) are referenced and compared to the present quarterly monitoring data collected for the HKBCF-PCB project, as both HKBCF-PCB and HKLR03 project data was collected by the same HKCRP survey team, to ensure 100% consistency in monitoring methodology including vessel survey method as well as various analyses. On the contrary, the previous monitoring data collected under HZMB HKBCF-Reclamation Works contract (Contract No. HY/2010/02) was from a different survey team that have adopted different survey methodology (e.g. two observers and one data recorder under HKBCF-Reclamation Works contract, as compared to one primary observer and one data recorder under HKLR03 and HKBCF-PCB contract). Therefore, we cannot ensure that such HKBCF monitoring data under that contract can be directly comparable to the HKBCF-PCB monitoring data, and would rather use the previous HKLR03 monitoring data instead for comparison with the present quarterly findings.

## 2. Monitoring Methodology

### 2.1. Vessel-based Line-transect Survey

2.1.1. According to the requirement of the updated EM&A manual, dolphin monitoring programme should cover all transect lines in NEL and NWL survey areas (see Figure 1) twice per month throughout the entire construction period. The co-ordinates of all transect lines are shown in Table 1.

Table 1 Co-ordinates of transect lines

Line No.		Easting	Northing		Line No.	Easting	Northing	
1	Start Point	804671	815456		13	Start Point	816506	819480
1	End Point	804671	831404		13	End Point	816506	824859
2	Start Point	805476	820800		14	Start Point	817537	820220
2	End Point	805476	826654		14	End Point	817537	824613
3	Start Point	806464	821150		15	Start Point	818568	820735
3	End Point	806464	822911		15	End Point	818568	824433
4	Start Point	807518	821500		16	Start Point	819532	821420
4	End Point	807518	829230		16	End Point	819532	824209

5	Start Point	808504	821850		17	Start Point	820451	822125
5	End Point	808504	828602		17	End Point	820451	823671
6	Start Point	809490	822150		18	Start Point	821504	822371
6	End Point	809490	825352		18	End Point	821504	823761
7	Start Point	810499	822000		19	Start Point	822513	823268
7	End Point	810499	824613		19	End Point	822513	824321
8	Start Point	811508	821123		20	Start Point	823477	823402
8	End Point	811508	824254		20	End Point	823477	824613
9	Start Point	812516	821303		21	Start Point	805476	827081
9	End Point	812516	824254		21	End Point	805476	830562
10	Start Point	813525	821176		22	Start Point	806464	824033
10	End Point	813525	824657		22	End Point	806464	829598
11	Start Point	814556	818853		23	Start Point	814559	821739
11	End Point	814556	820992		23	End Point	814559	824768
12	Start Point	815542	818807		24	Start Point	805476	815900
12	End Point	815542	824882		24	End Point	805476	819100

- 2.1.2. The survey team used standard line-transect methods (Buckland et al. 2001) to conduct the systematic vessel surveys, and followed the same technique of data collection that has been adopted over the last 19 years of marine mammal monitoring surveys in Hong Kong developed by HKCRP (see Hung 2017). For each monitoring vessel survey, a 15-m inboard vessel with an open upper deck (about 4.5 m above water surface) was used to make observations from the flying bridge area.
- 2.1.3. Two experienced observers (a data recorder and a primary observer) made up the on-effort survey team, and the survey vessel transited different transect lines at a constant speed of 13-15 km per hour. The data recorder searched with unaided eyes and filled out the datasheets, while the primary observer searched for dolphins and porpoises continuously through 7 x 50 *Fujinon* marine binoculars. Both observers searched the sea ahead of the vessel, between 270° and 90° (in relation to the bow, which is defined as 0°). One to two additional experienced observers were available on the boat to work in shift (i.e. rotate every 30 minutes) in order to minimize fatigue of the survey team members. All observers were experienced in small cetacean survey techniques and identifying local

cetacean species.

- 2.1.4. During on-effort survey periods, the survey team recorded effort data including time, position (latitude and longitude), weather conditions (Beaufort sea state and visibility), and distance traveled in each series (a continuous period of search effort) with the assistance of a handheld GPS (*Garmin eTrex Legend*).
- 2.1.5. Data including time, position and vessel speed were also automatically and continuously logged by handheld GPS throughout the entire survey for subsequent review.
- 2.1.6. When dolphins were sighted, the survey team would end the survey effort, and immediately record the initial sighting distance and angle of the dolphin group from the survey vessel, as well as the sighting time and position. Then the research vessel was diverted from its course to approach the animals for species identification, group size estimation, assessment of group composition, and behavioural observations. The perpendicular distance (PSD) of the dolphin group to the transect line was later calculated from the initial sighting distance and angle.
- 2.1.7. Survey effort being conducted along the parallel transect lines that were perpendicular to the coastlines (as indicated in Figure 1) was labeled as “primary” survey effort, while the survey effort conducted along the connecting lines between parallel lines was labeled as “secondary” survey effort. According to HKCRP long-term dolphin monitoring data, encounter rates of Chinese white dolphins deduced from effort and sighting data collected along primary and secondary lines were similar in NEL and NWL survey areas. Therefore, both primary and secondary survey effort were presented as on-effort survey effort in this report.

## 2.2. Photo-identification Work

- 2.2.1. When a group of Chinese White Dolphins were sighted during the line-transect survey, the survey team would end effort and approach the group slowly from the side and behind to take photographs of them. Every attempt was made to photograph every dolphin in the group, and even photograph both sides of the dolphins, since the colouration and markings on both sides may not be symmetrical.
- 2.2.2. One to two professional digital cameras (*Canon EOS 7D and/or 60D models*), each equipped with long telephoto lenses (100-400 mm zoom), were available on board for researchers to take sharp, close-up photographs of dolphins as they surfaced. The images were shot at the highest available resolution and stored on Compact Flash memory cards for downloading onto a computer.

- 2.2.3. All digital images taken in the field were first examined, and those containing potentially identifiable individuals were sorted out. These photographs would then be examined in greater detail, and were carefully compared to the existing Chinese White Dolphin photo-identification catalogue maintained by HKCRP since 1995.
- 2.2.4. Chinese White Dolphins can be identified by their natural markings, such as nicks, cuts, scars and deformities on their dorsal fin and body, and their unique spotting patterns were also used as secondary identifying features (Jefferson 2000).
- 2.2.5. All photographs of each individual were then compiled and arranged in chronological order, with data including the date and location first identified (initial sighting), re-sightings, associated dolphins, distinctive features, and age classes entered into a computer database.

### 2.3. *Data analysis*

- 2.3.1. Distribution Analysis – The line-transect survey data was integrated with the Geographic Information System (GIS) in order to visualize and interpret different spatial and temporal patterns of dolphin distribution using sighting positions. Location data of dolphin groups were plotted on map layers of Hong Kong using a desktop GIS (ArcView<sup>®</sup> 3.1) to examine their distribution patterns in details. The dataset was also stratified into different subsets to examine distribution patterns of dolphin groups with different categories of group sizes, young calves and activities.
- 2.3.2. Encounter rate analysis – Encounter rates of Chinese white dolphins (number of on-effort sightings per 100 km of survey effort, and total number of dolphins sighted on-effort per 100 km of survey effort) were calculated in NEL and NWL survey areas in relation to the amount of survey effort conducted during each month of monitoring survey. Dolphin encounter rates were calculated in two ways for comparisons with the HZMB baseline monitoring results as well as to AFCD long-term marine mammal monitoring results.

Firstly, for the comparison with the HZMB baseline monitoring results, the encounter rates were calculated using primary survey effort alone, and only data collected under Beaufort 3 or below condition would be used for encounter rate analysis. The average encounter rate of sightings (STG) and average encounter rate of dolphins (ANI) were deduced based on the encounter rates from six events during the present quarter (i.e. six sets of line-transect surveys in North Lantau), which was also compared with the one deduced from the six events during the baseline period (i.e. six sets of line-transect surveys in North Lantau).

Secondly, the encounter rates were calculated using both primary and secondary survey effort collected under Beaufort 3 or below condition as in AFCD long-term monitoring study. The encounter rate of sightings and dolphins were deduced by dividing the total number of on-effort sightings (STG) and total number of dolphins (ANI) by the amount of survey effort for the present quarterly period.

- 2.3.3. Quantitative grid analysis on habitat use – To conduct quantitative grid analysis of habitat use, positions of on-effort sightings of Chinese White Dolphins collected during the quarterly impact phase monitoring period were plotted onto 1-km<sup>2</sup> grids among NWL and NEL survey areas on GIS. Sighting densities (number of on-effort sightings per km<sup>2</sup>) and dolphin densities (total number of dolphins from on-effort sightings per km<sup>2</sup>) were then calculated for each 1 km by 1 km grid with the aid of GIS.

Sighting density grids and dolphin density grids were then further normalized with the amount of survey effort conducted within each grid. The total amount of survey effort spent on each grid was calculated by examining the survey coverage on each line-transect survey to determine how many times the grid was surveyed during the study period. For example, when the survey boat traversed through a specific grid 50 times, 50 units of survey effort were counted for that grid. With the amount of survey effort calculated for each grid, the sighting density and dolphin density of each grid were then normalized (i.e. divided by the unit of survey effort).

The newly-derived unit for sighting density was termed SPSE, representing the number of on-effort sightings per 100 units of survey effort. In addition, the derived unit for actual dolphin density was termed DPSE, representing the number of dolphins per 100 units of survey effort. Among the 1-km<sup>2</sup> grids that were partially covered by land, the percentage of sea area was calculated using GIS tools, and their SPSE and DPSE values were adjusted accordingly. The following formulae were used to estimate SPSE and DPSE in each 1-km<sup>2</sup> grid within the study area:

$$SPSE = ((S / E) \times 100) / SA\%$$

$$DPSE = ((D / E) \times 100) / SA\%$$

where S = total number of on-effort sightings  
D = total number of dolphins from on-effort sightings  
E = total number of units of survey effort  
SA% = percentage of sea area

- 2.3.4. Behavioural analysis – When dolphins were sighted during vessel surveys, their behaviour was observed. Different activities were categorized (i.e. feeding, milling/resting, traveling, socializing) and recorded on sighting datasheets. This data was then input into a separate database with sighting information, which can be used to determine the distribution of behavioural data with a desktop GIS. Distribution of sightings of dolphins engaged in different activities and behaviours would then be plotted on GIS and carefully examined to identify important areas for different activities of the dolphins.
- 2.3.5. Ranging pattern analysis – Location data of individual dolphins that occurred during the 3-month impact phase monitoring period were obtained from the dolphin sighting database and photo-identification catalogue. To deduce home ranges for individual dolphins using the fixed kernel methods, the program Animal Movement Analyst Extension, was loaded as an extension with ArcView<sup>®</sup> 3.1 along with another extension Spatial Analyst 2.0. Using the fixed kernel method, the program calculated kernel density estimates based on all sighting positions, and provided an active interface to display kernel density plots. The kernel estimator then calculated and displayed the overall ranging area at 95% UD level.

### 3. Monitoring Results

#### 3.1. *Summary of survey effort and dolphin sightings*

- 3.1.1. During the period of September to November 2017, six sets of systematic line-transect vessel surveys were conducted for the HKBCF project to cover all transect lines in NWL and NEL survey areas twice per month.
- 3.1.2. From these surveys, a total of 790.3 km of survey effort was collected, with 97.9% of the total survey effort being conducted under favourable weather conditions (i.e. Beaufort Sea State 3 or below with good visibility). Among the two areas, 289.9 km and 500.4 km of survey effort were conducted in NEL and NWL survey areas respectively.
- 3.1.3. The total survey effort conducted on primary lines was 574.2 km, while the effort on secondary lines was 216.1 km. Survey effort conducted on both primary and secondary lines were considered as on-effort survey data. A summary table of the survey effort is shown in Appendix I.
- 3.1.4. During the six sets of monitoring surveys in September to November 2017, six groups of 25 Chinese White Dolphins were sighted, with the summary table of the dolphin sightings

shown in Appendix II. All dolphin sightings were made during on-effort search, while five of the six on-effort dolphin sightings were made on primary lines. In addition, all dolphin groups were sighted in NWL, and no dolphin was sighted at all in NEL.

### 3.2. *Distribution*

- 3.2.1. Distribution of dolphin sightings made during monitoring surveys in September to November 2017 is shown in Figure 1. Five of the four sightings were made at the northwest portion of the North Lantau region, mainly within the Sha Chau and Lung Kwu Chau Marine Park (Figure 1). One dolphin group was also sighted at the southwestern end of NWL survey area, or near the HKLR09 alignment. On the contrary, the dolphins were completely absent from the central and eastern portions of North Lantau waters, similar to the consistent findings of HKLR03 surveys in recent years (Figure 1).
- 3.2.2. All dolphin sightings were located far away from the HKBCF and HKLR03 reclamation sites as well as along the alignment and Tuen Mun-Chek Lap Kok Link (TMCLKL) (Figure 1). However, one sighting was made near the alignment of HKLR09 as mentioned above.
- 3.2.3. Sighting distribution of dolphins during the present impact phase monitoring period (September to November 2017) was drastically different from the one during the baseline monitoring period (Figure 1). In the present quarter, dolphins have disappeared from the NEL region, which was in stark contrast to their frequent occurrence around the Brothers Islands, near Shum Shui Kok and in the vicinity of HKBCF reclamation site during the baseline period (Figure 1).
- 3.2.4. On the other hand, dolphin occurrence in NWL waters was also noticeably different between the baseline and impact phase periods. During the present impact monitoring period, dolphins were seldom sighted here, and mainly at the northwestern end of the area, which was in stark contrast with their frequent occurrences throughout the entire survey area during the baseline period (Figure 1).

### 3.3. *Encounter rate*

- 3.3.1. During the present three-month study period, the encounter rates of Chinese White Dolphins deduced from the survey effort and on-effort sighting data from the primary transect lines under favourable conditions (Beaufort 3 or below) for each set of the surveys in NEL and NWL are shown in Table 2. The average encounter rates deduced from the six sets of surveys were also compared with the ones deduced from the baseline monitoring period (September – November 2011) (Table 3).

3.3.2. To facilitate the comparison with the AFCD long-term monitoring results, the encounter rates were also calculated for the present quarter using both primary and secondary survey effort. The encounter rates of sightings (STG) and dolphins (ANI) in NWL were 1.2 sightings and 5.2 dolphins per 100 km of survey effort respectively, while the encounter rates of sightings (STG) and dolphins (ANI) in NEL were both nil for this quarter.

Table 2. Dolphin encounter rates (sightings per 100 km of survey effort) during September-November 2017

SURVEY AREA	DOLPHIN MONITORING DATES	Encounter rate (STG) (no. of on-effort dolphin sightings per 100 km of survey effort)	Encounter rate (ANI) (no. of dolphins from all on-effort sightings per 100 km of survey effort)
		Primary Lines Only	Primary Lines Only
Northeast Lantau	Set 1 (5 & 14 Sep 2017)	0.0	0.0
	Set 2 (21 & 25 Sep 2017)	0.0	0.0
	Set 3 (6 & 12 Oct 2017)	0.0	0.0
	Set 4 (17 & 19 Oct 2017)	0.0	0.0
	Set 5 (6 & 14 Nov 2017)	0.0	0.0
	Set 6 (23 & 28 Nov 2017)	0.0	0.0
Northwest Lantau	Set 1 (5 & 14 Sep 2017)	3.4	11.9
	Set 2 (21 & 25 Sep 2017)	3.3	8.3
	Set 3 (6 & 12 Oct 2017)	0.0	0.0
	Set 4 (17 & 19 Oct 2017)	0.0	0.0
	Set 5 (6 & 14 Nov 2017)	1.7	1.7
	Set 6 (23 & 28 Nov 2017)	0.0	0.0

3.3.3. In NEL, the average dolphin encounter rates (both STG and ANI) in the present three-month impact monitoring period were both zero with no on-effort sighting being made, and such extremely low occurrence of dolphins in NEL have also been consistently recorded in recent years of HZMB monitoring (Table 4).



Table 3. Comparison of average dolphin encounter rates from impact monitoring period (September – November 2017) and baseline monitoring period (September – November 2011) (Note: encounter rates deduced from the baseline monitoring period have been recalculated based only on survey effort and on-effort sighting data made along the primary transect lines under favourable conditions;  $\pm$  denotes the standard deviation of the average encounter rates)

	<b>Encounter rate (STG)</b> (no. of on-effort dolphin sightings per 100 km of survey effort)		<b>Encounter rate (ANI)</b> (no. of dolphins from all on-effort sightings per 100 km of survey effort)	
	<b>September – November 2017</b>	<b>September – November 2011</b>	<b>September – November 2017</b>	<b>September – November 2011</b>
<b>Northeast Lantau</b>	0.0	6.0 $\pm$ 5.05	0.0	22.2 $\pm$ 26.81
<b>Northwest Lantau</b>	1.4 $\pm$ 1.65	9.9 $\pm$ 5.85	3.7 $\pm$ 5.17	44.7 $\pm$ 29.85

Table 4. Comparison of average dolphin encounter rates in Northeast Lantau survey area from the same autumn quarters of HKLR03 and HKBCF impact monitoring period and baseline monitoring period (September-November 2011) (Note: encounter rates deduced from the baseline monitoring period have been recalculated based only on survey effort and on-effort sighting data made along the primary transect lines under favourable conditions;  $\pm$  denotes the standard deviation of the average encounter rates)

	<b>Encounter rate (STG)</b> (no. of on-effort dolphin sightings per 100 km of survey effort)	<b>Encounter rate (ANI)</b> (no. of dolphins from all on-effort sightings per 100 km of survey effort)
<b>September-November 2011 (Baseline)</b>	<b>6.0 <math>\pm</math> 5.05</b>	<b>22.2 <math>\pm</math> 26.81</b>
September-November 2013 (HKLR03 Impact*)	1.0 $\pm$ 1.59	3.8 $\pm$ 6.49
September-November 2014 (HKLR03 Impact*)	0.00	0.00
September-November 2015 (HKLR03 Impact*)	0.00	0.00
September-November 2016 (HKLR03 Impact*)	0.00	0.00
<b>September-November 2017 (HKBCF Impact)</b>	<b>0.00</b>	<b>0.00</b>

\* As explained in Section 1.5, the previous monitoring data from Contract No. HY/2011/03 (i.e. HKLR03) were adopted for comparison with the baseline and present HKBCF impact monitoring period

3.3.4. On the other hand, the average dolphin encounter rates (STG and ANI) in NWL during the present impact phase monitoring period (reductions of 85.7% and 91.8% respectively) were only very small fractions of the ones recorded during the three-month baseline period, indicating a dramatic decline in dolphin usage of this survey area as well during the present impact phase period (Table 5).

3.3.5. During the same autumn quarters (with comparison to past HKLR03 monitoring data), dolphin encounter rates in NWL during autumn 2017 was similar to the previous autumn period in and 2016, but was much lower than the ones in the summer periods of 2013, 2014 and 2015 (Table 5). Such temporal trend should be closely monitored in the upcoming monitoring quarters whether the dolphin occurrence would continue to increase as the construction activities of HZMB works have been mostly completed in coming months.

Table 5. Comparison of average dolphin encounter rates in Northwest Lantau survey area from all quarters of HKLR03 and HKBCF impact monitoring period and baseline monitoring period (September-November 2011) (Note: encounter rates deduced from the baseline monitoring period have been recalculated based only on survey effort and on-effort sighting data made along the primary transect lines under favourable conditions;  $\pm$  denotes the standard deviation of the average encounter rates)

	<b>Encounter rate (STG)</b> (no. of on-effort dolphin sightings per 100 km of survey effort)	<b>Encounter rate (ANI)</b> (no. of dolphins from all on-effort sightings per 100 km of survey effort)
<b>September-November 2011 (Baseline)</b>	<b>9.9 <math>\pm</math> 5.85</b>	<b>44.7 <math>\pm</math> 29.85</b>
September-November 2013 (HKLR03 Impact*)	8.0 $\pm$ 1.10	32.5 $\pm$ 26.51
September-November 2014 (HKLR03 Impact*)	5.1 $\pm$ 4.40	20.5 $\pm$ 15.10
September-November 2015 (HKLR03 Impact*)	3.9 $\pm$ 1.57	21.1 $\pm$ 17.19
September-November 2016 (HKLR03 Impact*)	2.9 $\pm$ 1.98	10.9 $\pm$ 10.98
<b>September-November 2017 (HKBCF Impact)</b>	<b>3.1 <math>\pm</math> 1.91</b>	<b>10.4 <math>\pm</math> 9.66</b>

\* As explained in Section 1.5, the previous monitoring data from Contract No. HY/2011/03 (i.e. HKLR03) were adopted for comparison with the baseline and present HKBCF impact monitoring period

3.3.6. A two-way ANOVA with repeated measures and unequal sample size was conducted to examine whether there were any significant differences in the average encounter rates between the baseline and impact monitoring periods. The two variables that were examined included the two periods (baseline and impact phases) and two locations (NEL and NWL).

3.3.7. For the comparison between the baseline period and the present quarter, the p-values for the differences in average dolphin encounter rates of STG and ANI were 0.0025 and 0.0156 respectively. If the alpha value is set at 0.05, significant differences were detected between the baseline and present quarter in both the average dolphin encounter rates of STG and ANI.

- 3.3.8. As indicated in both dolphin distribution patterns and encounter rates, dolphin usage has been significantly reduced in both NEL and NWL survey areas during the present quarterly period, and such low occurrence of dolphins has also been consistently documented in past HZMB dolphin monitoring studies.
- 3.3.9. The dramatic decline in dolphin usage of North Lantau region raises serious concern, as the timing of the decline in dolphin usage in North Lantau waters coincided well with the construction schedule of the HZMB-related projects (Hung 2017). Apparently there was no sign of recovery of dolphin usage even though most of the marine works associated with the HZMB construction have been completed.
- 3.4. *Group size*
- 3.4.1. Group size of Chinese White Dolphins ranged from one to 12 individuals per group in North Lantau region during September to November 2017. The average dolphin group sizes from these three months were compared with the ones deduced from the baseline period in September to November 2011, as shown in Table 6.

Table 6. Comparison of average dolphin group sizes from impact monitoring period (September-November 2017) and baseline monitoring period (September-November 2011) (Note:  $\pm$  denotes the standard deviation of average group size)

	Average Dolphin Group Size	
	September – November 2017	September – November 2011
<b>Overall</b>	4.2 $\pm$ 4.17 (n = 6)	3.7 $\pm$ 3.13 (n = 66)
<b>Northeast Lantau</b>	---	3.2 $\pm$ 2.16 (n = 17)
<b>Northwest Lantau</b>	4.2 $\pm$ 4.17 (n = 6)	3.9 $\pm$ 3.40 (n = 49)

- 3.4.2. The average dolphin group size in NWL waters during September to November 2017 was slightly higher than the one recorded during the three-month baseline period, but it should also be noted that the sample size of six dolphin groups in the present quarter was very small when compared to the 66 groups sighted during the baseline period (Table 6).
- 3.4.3. Notably, four of the six dolphin groups were composed of 1-4 individuals only, while there was one medium-sized group with five dolphins, and another large group with 12 dolphins (Appendix II).
- 3.4.4. Distribution of the larger dolphin groups with five individuals or more per group during the present quarter is shown in Figure 3, with comparison to the one in baseline period. The medium-sized group with 5 dolphins was located to the west of the airport near the HKLR09 alignment, while the large group of 12 dolphins was sighted adjacent to the west

of Lung Kwu Chau (Figure 2). Such distribution pattern was very different from the baseline period, when the larger dolphin groups were frequently sighted and evenly distributed in NWL waters, with a few also sighted in NEL waters (Figure 2).

### 3.5. *Habitat use*

- 3.5.1. From September to November 2017, the three of the six grids with high dolphin densities were located to the west of Lung Kwu Chau, north of Sha Chau and near the HKLR09 alignment (Figures 3a and 3b). Notably, all grids near HKBCF/HKLR03 reclamation sites as well as TMCLKL alignment did not record any presence of dolphins at all during on-effort search in the present quarterly period (Figures 3a and 3b).
- 3.5.2. However, it should be emphasized that the amount of survey effort collected in each grid during the three-month period was fairly low (6-12 units of survey effort for most grids), and therefore the habitat use pattern derived from the three-month dataset should be treated with caution. A more complete picture of dolphin habitat use pattern should be examined when more survey effort for each grid will be collected throughout the impact phase monitoring programme.
- 3.5.3. When compared with the habitat use patterns during the baseline period, dolphin usage in NEL and NWL has drastically diminished in both areas during the present impact monitoring period (Figure 4). During the baseline period, many grids between Siu Mo To and Shum Shui Kok in NEL recorded moderately high to high dolphin densities, which was in stark contrast to the complete absence of dolphins there during the present impact phase period (Figure 4).
- 3.5.4. The density patterns were also very different in NWL between the baseline and impact phase monitoring periods, with high dolphin usage throughout the area during the baseline period. In contrast, only several grids with high dolphin densities were located near Lung Kwu Chau and Sha Chau during the present impact phase period (Figure 4).
- ### 3.6. *Mother-calf pairs*
- 3.6.1. During the present quarterly period, no young calf was sighted at all among the six groups of dolphins.
- ### 3.7. *Activities and associations with fishing boats*
- 3.7.1. One of the six dolphin groups (i.e. the large group located just to the west of Lung Kwu Chau; Figure 5) were engaged in socializing activity, while the rest of the groups were not engaged in feeding, traveling or milling/resting activity during the three-month study period.

- 3.7.2. When compared to the baseline period, distribution of various dolphin activities during the present impact phase monitoring period was drastically different with very rare occurrence of such activities in the present quarter (Figure 5).
- 3.7.3. Notably, none of the six groups was associated with any operating fishing vessel during the present impact phase period.
- 3.8. *Summary of photo-identification works*
- 3.8.1. From September to November 2017, over 1,000 digital photographs of Chinese White Dolphins were taken during the impact phase monitoring surveys for the photo-identification work.
- 3.8.2. In total, 18 individuals sighted 19 times altogether were identified (see summary table in Appendix III and photographs of identified individuals in Appendix IV). All of these re-sightings were made in NWL.
- 3.8.3. Among the 18 individuals, only one individual (i.e. CH34) was re-sighted twice, while the rest were only re-sighted once during the three-month period (Appendix III).
- 3.8.4. Notably, ten of these 18 individuals (i.e. CH34, NL12, NL49, NL104, NL136, NL182, NL202, NL320, NL321 and WL05) were also sighted in Northwest Lantau during the HKLR03 monitoring surveys conducted concurrently in the same three-month period. Moreover, six individuals (i.e. CH34, NL12, NL49, NL182, NL317, and WL05) were also sighted in West Lantau waters during the HKLR09 monitoring surveys from September to November 2017, showing their extensive individual movements across different survey areas.
- 3.9. *Individual range use*
- 3.9.1. Ranging patterns of the 18 individuals identified during the three-month study period were determined by fixed kernel method, and are shown in Appendix V.
- 3.9.2. All identified dolphins sighted in the present quarter were utilizing NWL waters only, but have completely avoided NEL waters where many of them have utilized as their core areas in the past (Appendix V). This is in stark contrary to the extensive movements between NEL and NWL survey areas observed in the earlier impact monitoring quarters as well as the baseline period.
- 3.9.3. On the other hand, some individuals (NL12, NL182 and WL05) consistently utilized North Lantau waters in the past have extended their range use to WL during the present

quarter.

- 3.9.4. In the upcoming quarters, individual range use and movements should be continuously monitored to examine whether there has been any consistent shifts of individual home ranges from North Lantau to West or Southwest Lantau, as such shift could possibly be related to the HZMB-related construction works (see Hung 2017).

#### 4. Conclusion

- 4.1. During the present quarter of dolphin monitoring, no adverse impact from the activities of this construction project on Chinese White Dolphins was noticeable from general observations.
- 4.2. Although dolphins seldom occurred in the area of HKBCF construction in the past and during the baseline monitoring period, it is apparent that dolphin usage has been dramatically reduced in North Lantau waters in recent years, and many individuals have shifted away from this once-important habitat for the dolphins.
- 4.3. It is critical to continuously monitor the dolphin usage in North Lantau region in the upcoming quarters, to determine whether the dolphins are continuously affected by the various construction activities in relation to the HZMB-related works, and whether there is any sign of recovery when the construction works have been completed.

#### 5. References

- Buckland, S. T., Anderson, D. R., Burnham, K. P., Laake, J. L., Borchers, D. L., and Thomas, L. 2001. Introduction to distance sampling: estimating abundance of biological populations. Oxford University Press, London.
- Hung, S. K. 2008. Habitat use of Indo-Pacific humpback dolphins (*Sousa chinensis*) in Hong Kong. Ph.D. dissertation. University of Hong Kong, Hong Kong, 266 p.
- Hung, S. K. 2017. Monitoring of Marine Mammals in Hong Kong waters: final report (2016-17). An unpublished report submitted to the Agriculture, Fisheries and Conservation Department, 162 pp.
- Jefferson, T. A. 2000. Population biology of the Indo-Pacific hump-backed dolphin in Hong Kong waters. Wildlife Monographs 144:1-65.





Figure 1. Distribution of Chinese white dolphin sighting in Northwest and Northeast Lantau during HKBCF impact phase (top) and baseline monitoring surveys (bottom)





Figure 2. Distribution of Chinese white dolphins with larger group sizes during HKBCF impact phase (top) and baseline monitoring surveys (bottom) (green dots: group sizes of 5 or more; purple dots: group sizes of 10 or more)






Figure 3a. Sighting density of Chinese white dolphins with corrected survey effort per km<sup>2</sup> in Northeast and Northwest Lantau survey areas, using data collected during HKBCF impact monitoring period (Sep-Nov 17) (SPSE = no. of on-effort sightings per 100 units of survey effort)




Figure 3b. Density of Chinese white dolphins with corrected survey effort per km<sup>2</sup> in Northeast and Northwest Lantau survey areas, using data collected during HKBCF impact monitoring period (Sep-Nov 17) (DPSE = no. of dolphins per 100 units of survey effort)




Figure 4. Comparison of density of Chinese white dolphins with corrected survey effort per km<sup>2</sup> in Northwest and Northeast Lantau survey area between the HKBCF impact monitoring period (September-November 2017) and baseline monitoring period (September-November 2011) (DPSE = no. of dolphins per 100 units of survey effort)





Figure 5. Distribution of Chinese white dolphins engaged in feeding (purple dots), socializing (pink dots) and traveling (green dots) activities during HKBCF impact phase (top) and baseline monitoring surveys (bottom)

## Annex I. HKBCF Survey Effort Database (September-November 2017)

(Abbreviations: BEAU = Beaufort Sea State; P = Primary Line Effort; S = Secondary Line Effort)

DATE	AREA	BEAU	EFFORT	SEASON	VESSEL	TYPE	P/S
5-Sep-17	NW LANTAU	2	16.02	AUTUMN	STANDARD36826	HKBCF	P
5-Sep-17	NW LANTAU	3	8.63	AUTUMN	STANDARD36826	HKBCF	P
5-Sep-17	NW LANTAU	2	6.47	AUTUMN	STANDARD36826	HKBCF	S
5-Sep-17	NW LANTAU	3	4.47	AUTUMN	STANDARD36826	HKBCF	S
5-Sep-17	NE LANTAU	2	21.92	AUTUMN	STANDARD36826	HKBCF	P
5-Sep-17	NE LANTAU	3	13.97	AUTUMN	STANDARD36826	HKBCF	P
5-Sep-17	NE LANTAU	2	10.56	AUTUMN	STANDARD36826	HKBCF	S
5-Sep-17	NE LANTAU	3	1.85	AUTUMN	STANDARD36826	HKBCF	S
14-Sep-17	NW LANTAU	2	9.06	AUTUMN	STANDARD36826	HKBCF	P
14-Sep-17	NW LANTAU	3	25.07	AUTUMN	STANDARD36826	HKBCF	P
14-Sep-17	NW LANTAU	2	5.67	AUTUMN	STANDARD36826	HKBCF	S
14-Sep-17	NW LANTAU	3	6.90	AUTUMN	STANDARD36826	HKBCF	S
21-Sep-17	NW LANTAU	1	10.28	AUTUMN	STANDARD36826	HKBCF	P
21-Sep-17	NW LANTAU	2	24.36	AUTUMN	STANDARD36826	HKBCF	P
21-Sep-17	NW LANTAU	1	1.22	AUTUMN	STANDARD36826	HKBCF	S
21-Sep-17	NW LANTAU	2	12.10	AUTUMN	STANDARD36826	HKBCF	S
21-Sep-17	NE LANTAU	2	23.33	AUTUMN	STANDARD36826	HKBCF	P
21-Sep-17	NE LANTAU	3	4.20	AUTUMN	STANDARD36826	HKBCF	P
21-Sep-17	NE LANTAU	2	7.47	AUTUMN	STANDARD36826	HKBCF	S
21-Sep-17	NE LANTAU	3	0.90	AUTUMN	STANDARD36826	HKBCF	S
25-Sep-17	NE LANTAU	2	6.73	AUTUMN	STANDARD36826	HKBCF	P
25-Sep-17	NE LANTAU	3	2.11	AUTUMN	STANDARD36826	HKBCF	P
25-Sep-17	NE LANTAU	2	2.36	AUTUMN	STANDARD36826	HKBCF	S
25-Sep-17	NW LANTAU	2	8.74	AUTUMN	STANDARD36826	HKBCF	P
25-Sep-17	NW LANTAU	3	16.74	AUTUMN	STANDARD36826	HKBCF	P
25-Sep-17	NW LANTAU	2	3.18	AUTUMN	STANDARD36826	HKBCF	S
25-Sep-17	NW LANTAU	3	7.54	AUTUMN	STANDARD36826	HKBCF	S
6-Oct-17	NW LANTAU	2	15.46	AUTUMN	STANDARD36826	HKBCF	P
6-Oct-17	NW LANTAU	3	19.54	AUTUMN	STANDARD36826	HKBCF	P
6-Oct-17	NW LANTAU	2	7.20	AUTUMN	STANDARD36826	HKBCF	S
6-Oct-17	NW LANTAU	3	6.20	AUTUMN	STANDARD36826	HKBCF	S
6-Oct-17	NE LANTAU	2	16.90	AUTUMN	STANDARD36826	HKBCF	P
6-Oct-17	NE LANTAU	3	18.40	AUTUMN	STANDARD36826	HKBCF	P
6-Oct-17	NE LANTAU	2	7.60	AUTUMN	STANDARD36826	HKBCF	S
6-Oct-17	NE LANTAU	3	6.40	AUTUMN	STANDARD36826	HKBCF	S
12-Oct-17	NW LANTAU	2	19.17	AUTUMN	STANDARD36826	HKBCF	P
12-Oct-17	NW LANTAU	3	6.73	AUTUMN	STANDARD36826	HKBCF	P
12-Oct-17	NW LANTAU	2	5.59	AUTUMN	STANDARD36826	HKBCF	S
12-Oct-17	NW LANTAU	3	4.33	AUTUMN	STANDARD36826	HKBCF	S
17-Oct-17	NW LANTAU	2	11.40	AUTUMN	STANDARD36826	HKBCF	P
17-Oct-17	NW LANTAU	3	14.40	AUTUMN	STANDARD36826	HKBCF	P
17-Oct-17	NW LANTAU	2	3.90	AUTUMN	STANDARD36826	HKBCF	S
17-Oct-17	NW LANTAU	3	6.90	AUTUMN	STANDARD36826	HKBCF	S
17-Oct-17	NE LANTAU	2	36.66	AUTUMN	STANDARD36826	HKBCF	P
17-Oct-17	NE LANTAU	2	12.04	AUTUMN	STANDARD36826	HKBCF	S
19-Oct-17	NW LANTAU	2	13.37	AUTUMN	STANDARD36826	HKBCF	P
19-Oct-17	NW LANTAU	3	17.70	AUTUMN	STANDARD36826	HKBCF	P
19-Oct-17	NW LANTAU	4	1.20	AUTUMN	STANDARD36826	HKBCF	P
19-Oct-17	NW LANTAU	2	7.63	AUTUMN	STANDARD36826	HKBCF	S
19-Oct-17	NW LANTAU	3	10.20	AUTUMN	STANDARD36826	HKBCF	S

## Annex I. (cont'd)

(Abbreviations: BEAU = Beaufort Sea State; P = Primary Line Effort; S = Secondary Line Effort)

DATE	AREA	BEAU	EFFORT	SEASON	VESSEL	TYPE	P/S
6-Nov-17	NW LANTAU	2	10.92	AUTUMN	STANDARD36826	HKBCF	P
6-Nov-17	NW LANTAU	3	21.13	AUTUMN	STANDARD36826	HKBCF	P
6-Nov-17	NW LANTAU	2	7.10	AUTUMN	STANDARD36826	HKBCF	S
6-Nov-17	NW LANTAU	3	4.45	AUTUMN	STANDARD36826	HKBCF	S
6-Nov-17	NE LANTAU	1	4.96	AUTUMN	STANDARD36826	HKBCF	P
6-Nov-17	NE LANTAU	2	28.51	AUTUMN	STANDARD36826	HKBCF	P
6-Nov-17	NE LANTAU	3	2.80	AUTUMN	STANDARD36826	HKBCF	P
6-Nov-17	NE LANTAU	1	2.40	AUTUMN	STANDARD36826	HKBCF	S
6-Nov-17	NE LANTAU	2	7.23	AUTUMN	STANDARD36826	HKBCF	S
6-Nov-17	NE LANTAU	3	1.00	AUTUMN	STANDARD36826	HKBCF	S
14-Nov-17	NW LANTAU	2	12.06	AUTUMN	STANDARD36826	HKBCF	P
14-Nov-17	NW LANTAU	3	14.63	AUTUMN	STANDARD36826	HKBCF	P
14-Nov-17	NW LANTAU	2	4.60	AUTUMN	STANDARD36826	HKBCF	S
14-Nov-17	NW LANTAU	3	5.11	AUTUMN	STANDARD36826	HKBCF	S
23-Nov-17	NW LANTAU	3	16.80	AUTUMN	STANDARD36826	HKBCF	P
23-Nov-17	NW LANTAU	4	10.19	AUTUMN	STANDARD36826	HKBCF	P
23-Nov-17	NW LANTAU	2	1.00	AUTUMN	STANDARD36826	HKBCF	S
23-Nov-17	NW LANTAU	3	6.61	AUTUMN	STANDARD36826	HKBCF	S
23-Nov-17	NW LANTAU	4	4.40	AUTUMN	STANDARD36826	HKBCF	S
23-Nov-17	NE LANTAU	2	18.00	AUTUMN	STANDARD36826	HKBCF	P
23-Nov-17	NE LANTAU	3	17.50	AUTUMN	STANDARD36826	HKBCF	P
23-Nov-17	NE LANTAU	4	0.70	AUTUMN	STANDARD36826	HKBCF	P
23-Nov-17	NE LANTAU	2	6.00	AUTUMN	STANDARD36826	HKBCF	S
23-Nov-17	NE LANTAU	3	7.40	AUTUMN	STANDARD36826	HKBCF	S
28-Nov-17	NW LANTAU	2	21.36	AUTUMN	STANDARD36826	HKBCF	P
28-Nov-17	NW LANTAU	3	12.50	AUTUMN	STANDARD36826	HKBCF	P
28-Nov-17	NW LANTAU	2	10.14	AUTUMN	STANDARD36826	HKBCF	S

**Annex II. HKBCF Chinese White Dolphin Sighting Database (September-November 2017)**


(Abberviations: STG# = Sighting Number; HRD SZ = Dolphin Herd Size; BEAU = Beaufort Sea State; PSD = Perpendicular Distance; BOAT ASSOC. = Fishing Boat Association P/S: Sighting Made on Primary/Secondary Lines)

DATE	STG #	TIME	HRD SZ	AREA	BEAU	PSD	EFFORT	TYPE	NORTHING	EASTING	SEASON	BOAT ASSOC.	P/S
5-Sep-17	1	1014	5	NW LANTAU	2	101	ON	HKBCF	816642	805426	AUTUMN	NONE	P
5-Sep-17	2	1214	2	NW LANTAU	2	670	ON	HKBCF	826960	806796	AUTUMN	NONE	P
21-Sep-17	1	1054	1	NW LANTAU	1	796	ON	HKBCF	824041	804659	AUTUMN	NONE	P
21-Sep-17	2	1200	4	NW LANTAU	2	73	ON	HKBCF	824247	806431	AUTUMN	NONE	P
12-Oct-17	1	1158	12	NW LANTAU	2	460	ON	HKBCF	826486	805415	AUTUMN	NONE	S
6-Nov-17	1	1133	1	NW LANTAU	2	285	ON	HKBCF	829220	806451	AUTUMN	NONE	P

**Annex III. Individual dolphins identified during HKBCF monitoring surveys in September - November 2017**

<b>ID#</b>	<b>DATE</b>	<b>STG#</b>	<b>AREA</b>
CH34	05/09/17	1	NW LANTAU
	06/11/17	1	NW LANTAU
NL12	12/10/17	1	NW LANTAU
NL49	05/09/17	1	NW LANTAU
NL104	12/10/17	1	NW LANTAU
NL136	05/09/17	1	NW LANTAU
NL182	12/10/17	1	NW LANTAU
NL202	05/09/17	2	NW LANTAU
NL233	12/10/17	1	NW LANTAU
NL259	05/09/17	1	NW LANTAU
NL280	12/10/17	1	NW LANTAU
NL302	21/09/17	2	NW LANTAU
NL317	12/10/17	1	NW LANTAU
NL320	12/10/17	1	NW LANTAU
NL321	12/10/17	1	NW LANTAU
WL05	05/09/17	1	NW LANTAU
WL15	21/09/17	2	NW LANTAU
WL188	12/10/17	1	NW LANTAU
WL278	21/09/17	2	NW LANTAU

Annex IV. Eighteen individual dolphins that were identified during September to November 2017 under HKBCF impact phase monitoring surveys





Annex IV. (cont'd)

NL136



NL182



NL202



NL233



Annex IV. (cont'd)

NL259



NL280



NL302



NL317



Annex IV. (cont'd)

NL320



NL321



WL05









WL15









Annex IV. (cont'd)



Annex V. Ranging patterns (95 % kernel ranges) of 18 individual dolphins that were sighted during HKBCF impact phase monitoring period (note: yellow dots with red circles indicate sightings made in September – November 2017 during HKBCF monitoring surveys; other yellow dots indicate the ones made during HKLR03 & HKLR09 monitoring surveys)



Annex V. (cont'd)



Annex V. (cont'd)

