Contract No. HY 2004/09 Improvements to San Tin Interchange Weekly Report No.: 075 Water Quality Visual Inspection Report				
170/2017-17-17-17-17-17-17-17-17-17-17-17-17-1	(1)	(2)	(3)	
Date of Inspection:	5 th December 2006	7 th December 2006	9 th December 2006	
Time:	15:00	14:30	9:30	
Weather Condition:	Sunny	Sunny	Cloudy	

Drainage laying and

Division North 1, 2 & South

formwork erection

Drainage laying and

Division North 1, 2 & South

formwork erection

Are Works in Compliance with:	Y N
Water Pollution Control Ordinance and the Subsidiary Legislation	\square
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	\square
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	\checkmark
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	\square
6. Any relevant Effluent Discharge License received by the Contractor	\square
Description of Environmental Non-compliance or Deficiency (if any):	
Nil.	***************************************
Remedial Actions – Mitigation Measures Implemented or Proposed (if any):	
Nil.	-
	A PARTY LANGE

Remarks:

Works Inspected:

Location:

Drainage laying and

Division North 1, 2 & South

formwork erection

- No specific water quality issues were observed during the inspections conducted on 5th December and 9th December, respectively.
- During the inspection on 7th December 2006, stagnant water pools were observed to have been accumulated at several locations: beside Bridge K in N2 Division, on top of the constructional material in M6 Works area in South Division area and inside unused sedimentation tanks in N1 open lay-down area and South Abutment works area. The stagnant water pools were seen to have been cleared up during the inspection on 9th December 2006.

Prepared by	:	Howard Chan	Title :	Environmental Team
Signature	:	Howard	Date :	11 th December 2006
Reviewed and approved by	:	Susana Bezy	Title :	Environmental Team Leader
Signature	<u></u>		Date :	11 th December 2006

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

Contract No. HY 2004/09 Improvements to San Tin Interchange Weekly Report No.: 076 Water Quality Visual Inspection Report (2)(1) (3)Date of Inspection: 12th December 2006 14th December 2006 16th December 2006 Time: 15:00 14:30 14:30 Weather Condition: Fine Cloudy Fine Works Inspected: Drainage laying and Drainage laying and Drainage laying and formwork erection formwork erection formwork erection Location: Division North 1, 2 & South Division North 1, 2 & South Division North 1, 2 & South Are Works in Compliance with: Y N 1. Water Pollution Control Ordinance and the Subsidiary Legislation \square 2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit $\overline{\mathsf{V}}$ 3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP) \square 4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04 $\overline{\mathsf{V}}$ 5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage" \square 6. Any relevant Effluent Discharge License received by the Contractor $\overline{\mathsf{V}}$ Description of Environmental Non-compliance or Deficiency (if any):

NII.	
Remedial Actions – Mitigation Measures Implemented or Proposed (if any):	
Nil.	

Remarks:

- No specific water quality issues were observed during the inspections conducted on 12th December 2006 and 14th December 2006.
- During the inspection on 16th December 2006, stagnant water pool was observed to have been accumulated beside Bridge K in N2 Division. The Contractor was reminded to clear up the stagnant water pool to prevent mosquito breeding.

Prepared by	:	K. L. Cheung	Title :	ET – Environmental Consultant
Signature		Cheung Kam Lay	Date :	18 th December 2006
Reviewed and approved by		Susana Bezy	Title :	Environmental Team Leader
Signature	_		Date :	18 th December 2006
Sent to:		TEC (ERM), ER (Maunsell), Contractor (Chun W	0)	

Contract No. HY 2004/09 Improvements to San Tin Intercha	ange Weekly Report No.: 077
Water Quality Visual Inspection Report	_

	(1)	(2)	(3)
Date of Inspection:	19 th December 2006	21 st December 2006	23 rd December 2006
Time:	13:30	14:30	10:30
Weather Condition:	Sunny	Sunny	Sunny
Works Inspected:	Drainage laying and formwork erection	Drainage laying and formwork erection	Drainage laying and formwork erection
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

Are Works in Compliance with:	Y N
Water Pollution Control Ordinance and the Subsidiary Legislation	\square
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	\square
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	\square
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	
6. Any relevant Effluent Discharge License received by the Contractor	
Description of Environmental Non-compliance or Deficiency (if any):	
Nil.	
Remedial Actions – Mitigation Measures Implemented or Proposed (if any):	
Nil.	
140.	

Remarks:

- No specific water quality issues were observed during the inspections conducted on 19th December 2006 and 23rd December 2006.
- During the inspection on 21st December 2006, site runoff from South Abutment works area near Box Culvert BC2 in N1 Division was observed to be discharged into EMDC directly without treatment by sedimentation. During the inspection on 23rd December 2006, it was observed that the Contractor has diverted the site runoff to site drainage system.
- During the inspection on 21st December 2006, stagnant water pool was observed to have been accumulated in unused sedimentation basins at N1 open lay-down area in N1 Division. The stagnant water pool was seen to have been cleared up during inspection on 23rd December 2006.
- During the inspection on 21st December 2006, wastewater from wheel washing facility at the South Abutment works area was observed to be discharged to gully pit in front of site entrance without sedimentation. The Contractor was reminded to divert the wastewater to sump pit for treatment prior to discharge.

Prepared by	:	K. L. Cheung	Title :	ET – Environmental Consultant
Signature	<u>:</u>	Cherry Kam Lay	Date :	27 th December 2006
Reviewed and approved by		Susana Bezy	Title :	Environmental Team Leader
Signature	<u>_</u>		Date :	27/12/06

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

	2004/09 Improvements to ual Inspection Report	o San Tin Interchange	Weekly Report No.: 078
	(1)	(2)	(3)
Date of Inspection:	27 th December 2006	28 th December 2006	30 th December 2006
Time:	15:00	14:30	13:30
Weather Condition:	Sunny	Sunny	Sunny
Works Inspected:	Drainage laying and formwork erection	Drainage laying and formwork erection	Drainage laying and formwork erection
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South
 Recommendations a Recommendations a Contract No. HY/200 Recommendations a Any relevant Effluent Description of Environmental	rol Ordinance and the Subsidiary L nd requirements in the Project EIA nd requirements in the Contractor's 4/09, Particular Specification Secti	Report, EM&A Manual and Envirors Drainage Management Plan (DMF on 26, Environmental Protection, its Note PN 1/94 "Construction Site Drage Contractor Deficiency (if any):	ems under Clause 26.04
Remarks:			
 During the inspectionside gully in M1 the inspection on 3 During the inspection of the inspection of the inspection of the inspection of the inspection. 	tion on 28 th December 2006, s works area in South Division. 30 th December 2006. tion on 30 th December 2006, s	uring the inspection conducted obtains the inspection conducted obtains the stagnant water was seen to stagnant water pool was observed in N1 Division. The Contractors.	red to have been accumulated to have been cleared up during red to have been accumulated
Prepared by : K	L. Cheung	Title : ET – E	nvironmental Consultant
Signature :	heung Kam Lay	Date : 2 nd Jar	nuary 2007
Reviewed and approved by : S	usana Bezy	Title : Enviro	nmental Team Leader

Sent to:

IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

Date: 2nd January 2007