

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 079

	(1)	(2)	(3)
Date of Inspection:	2 nd January 2007	4 th January 2007	6 th January 2007
Time:	14:30	14:30	09:30
Weather Condition:	Cloudy	Sunny	Sunny
Works Inspected:	Drainage laying and formwork erection	Drainage laying and formwork erection	Drainage laying and formwork erection
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

Are Works in Compliance with:

	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):

Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):


Nil.

Remarks:

No specific water quality issues were observed during the inspections conducted on 2nd January 2007, 4th January 2007 and 6th January 2007, respectively.

Prepared by : Howard Chan

Title : Environmental Technician

Signature : 

Date : 8th January 2007

Reviewed and approved by : Susana Bezy

Title : Environmental Team Leader

Signature : 

Date : 8th January 2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 080

	(1)	(2)	(3)
Date of Inspection:	8 th January 2007	11 th January 2007	13 th January 2007
Time:	15:00	14:30	10:00
Weather Condition:	Sunny	Cloudy	Sunny
Works Inspected:	Drainage laying and formwork erection	Drainage laying and formwork erection	Drainage laying and formwork erection
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

Are Works in Compliance with:

	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):

Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):

Nil.

Remarks:

No specific water quality issues were observed during the inspections conducted on 8th January 2007, 11th January 2007 and 13th January 2007 respectively.

Prepared by : K. L. Cheung Title : ET – Environmental Consultant

Signature :  Date : 15th January 2007

Reviewed and approved by : Susana Bezy Title : Environmental Team Leader

Signature :  Date : 15th January 2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 081

	(1)	(2)	(3)
Date of Inspection:	16 th January 2007	18 th January 2007	20 th January 2007
Time:	14:00	14:30	10:00
Weather Condition:	Sunny	Cloudy	Cloudy
Works Inspected:	Drainage laying and formwork erection	Drainage laying and formwork erection	Drainage laying and formwork erection
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

Are Works in Compliance with:

	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):

Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):

Nil.


Remarks:

- No specific water quality issues were observed during the inspections conducted on 16th January 2007 and 20th January 2007, respectively.
- During the inspection on 18th January 2007, stagnant water was observed to have been accumulated inside unused gullies along Slip Road B works area in South Division. The stagnant water was seen to be cleared up during inspection on 20th January 2007.

Prepared by : Howard Chan Title : ET – Environmental Technician

Signature :  Date : 23rd January 2007

Reviewed and approved by : Susana Bezy Title : Environmental Team Leader

Signature :  Date : 24/01/2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 082

	(1)	(2)	(3)
Date of Inspection:	22 nd January 2007	25 th January 2007	27 th January 2007
Time:	10:00	14:30	10:30
Weather Condition:	Cloudy	Sunny	Sunny
Works Inspected:	Drainage laying and formwork erection	Drainage laying and formwork erection	Drainage laying and formwork erection
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

Are Works in Compliance with:

	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):

Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):

Nil.

Remarks:

- No specific water quality issues were observed during the inspection conducted on 22nd January 2007.
- During the inspections on 25th and 27th January 2007, stagnant water was observed to have been accumulated in several areas: inside unused gullies along Slip Road A and Slip Road B works areas in South Division; and inside an open void chamber at Slip Road B works area. The Contractor was reminded to clear up the stagnant water to prevent mosquito breeding. The Contractor was also reminded to cover the unused gullies and void chamber to prevent stagnant water accumulation.

Prepared by : K. L. Cheung


Title : ET – Environmental Consultant

Signature : 

Date : 29th January 2007

Reviewed and approved by : Susana Bezy

Title : Environmental Team Leader

Signature : 

Date : 29th January 2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)