

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 083

	(1)	(2)	(3)
Date of Inspection:	29 th January 2007	1 st February 2007	2 nd February 2007
Time:	14:00	14:30	13:30
Weather Condition:	Sunny	Sunny	Sunny
Works Inspected:	Drainage laying and formwork erection	Drainage laying and formwork erection	Drainage laying and formwork erection
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

Are Works in Compliance with:

	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):

Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):

Nil.

Remarks:

- During the inspections on 29th January 2007, stagnant water was observed to have been accumulated in unused gullies along Slip Road A and Slip Road B works areas in South Division. The unused gullies were seen to have been covered during the inspection on 1st February 2007.
- No specific water quality issue was observed during the inspections conducted on 1st and 2nd February 2007.

Prepared by : K. L. Cheung


Title : ET – Environmental Consultant

Signature : 

Date : 5th February 2007

Reviewed and approved by : Susana Bezy

Title : Environmental Team Leader

Signature : 

Date : 5th February 2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 084

	(1)	(2)	(3)
Date of Inspection:	6 th February 2007	8 th February 2007	10 th February 2007
Time:	10:00	14:30	10:00
Weather Condition:	Sunny	Sunny	Cloudy
Works Inspected:	Drainage laying and formwork erection	Drainage laying and formwork erection	Drainage laying and formwork erection
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

Are Works in Compliance with:

	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):

Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):

Nil.

Remarks:

No specific water quality issue was observed during the inspections conducted on 6th, 8th and 10th February 2007.

Prepared by : K. L. Cheung

Title : ET – Environmental Consultant

Signature : 

Date : 10th February 2007

Reviewed and approved by : Susana Bezy

Title : Environmental Team Leader

Signature : 

Date : 12th February 2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 085

	(1)	(2)	(3)
Date of Inspection:	12 th February 2007	14 th February 2007	16 th February 2007
Time:	14:30	14:00	10:00
Weather Condition:	Sunny	Sunny	Sunny
Works Inspected:	Drainage laying and formwork erection	Drainage laying and formwork erection	Drainage laying and formwork erection
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

Are Works in Compliance with:

	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):

Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):

Nil.

Remarks:

- During the inspections on 12th February 2007 and 14th February 2007, stagnant water was observed to have been accumulated inside unused gullies along Slip Road A and Slip Road B works areas in South Division. Stagnant water should be cleared promptly to prevent mosquito breeding. The unused gullies were seen to have been covered during the inspection on 16th February 2007.
- No specific water quality issue was observed during the inspection conducted on 16th February 2007.

Prepared by : K. L. Cheung Title : ET – Environmental Consultant

Signature :  Date : 21st February 2007

Reviewed and approved by : Susana Bezy Title : Environmental Team Leader

Signature :  Date : 22nd February 2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 086

	(1)	(2)	(3)
Date of Inspection:	21 st February 2007	22 nd February 2007	23 rd February 2007
Time:	14:30	14:00	10:00
Weather Condition:	Sunny	Cloudy with drizzle	Cloudy
Works Inspected:	Drainage laying and formwork erection	Drainage laying and formwork erection	Drainage laying and formwork erection
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

Are Works in Compliance with:

	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):

Nil.


Remedial Actions – Mitigation Measures Implemented or Proposed (if any):

Nil.

Remarks:

- During the inspections on 21st February 2007 and 22nd February 2007, stagnant water was observed to have been accumulated inside unused gullies and void chambers along Slip Road A and Slip Road B works areas in South Division. Stagnant water should be cleared promptly to prevent mosquito breeding. The stagnant water was seen to have been cleared and the unused gullies were seen to have been covered during the inspection on 23rd February 2007.
- During the inspection on 22nd February 2007, water outflow from the sedimentation basin beside Pier B8 in South Division appeared to be still muddy. Water outflow from the sedimentation basin was stopped immediately after the inspection. The Contractor was reminded to use sedimentation basin with sufficient capacity to increase the retention time of sedimentation process, especially when after rainstorm event.
- No specific water quality issue was observed during the inspection conducted on 23rd February 2007.

Prepared by : K. L. Cheung Title : ET – Environmental Consultant

Signature :  Date : 27th February 2007

Reviewed and approved by : Susana Bezy Title : Environmental Team Leader

Signature :  Date : 27th February 2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)