

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 114

	(1)	(2)	(3)
Date of Inspection:	3 rd September 2007	5 th September 2007	7 th September 2007
Time:	14:35	14:30	14:15
Weather Condition:	Fine	Sunny	Drizzle
Works Inspected:	Drainage laying and trench works	Drainage laying and trench works	Drainage laying and trench works
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

Are Works in Compliance with:	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):
Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):
Nil.

Remarks:

- No specific water quality issue was observed during the inspection conducted on 3rd September 2007.
- Stagnant water pool was seen near the RE site office at Division N1 during the inspection on 5th September 2007.
- The stagnant pool near the RE site office at Division N1 was removed and the hollow area was backfilled as seen on 7th September 2007.

Prepared by : Chau Tsz Wing Title : ET – Environmental Technician

Signature :  Date : 10th September 2007

Reviewed and approved by : Susana Bezy Title : Environmental Team Leader

Signature :  Date : 10th September 2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 115

	(1)	(2)	(3)
Date of Inspection:	10 th September 2007	12 th September 2007	14 th September 2007
Time:	14:50	14:30	15:30
Weather Condition:	Fine	Sunny	Haze
Works Inspected:	Drainage laying and trench works	Drainage laying and trench works	Drainage laying and trench works
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

Are Works in Compliance with:

	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):

Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):


Nil.

Remarks:

- No specific water quality issue was observed during the inspection conducted on 10th September 2007 and 14th September 2007, respectively.
- Piping connection to the sedimentation tank (near site office) was temporary detached from the pump due to temporary works on 12th September 2007. The contractor advised that they would reconnect the pipe to the sedimentation tank immediately after the temporary works during the inspection.
- Litters have accumulated in the U-channel near Fanling Highway at M2 area on 12th September 2007. The Contractor is reminded to clear the litter to proper maintain the drainage system.

Prepared by : Chau Tsz Wing

Title : ET – Environmental Technician

Signature : 

Date : 18th September 2007

Reviewed and approved by : Susana Bezy

Title : Environmental Team Leader

Signature : 

Date : 18th September 2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 116

	(1)	(2)	(3)
Date of Inspection:	18 th September 2007	19 th September 2007	20 th September 2007
Time:	14:50	14:30	16:30
Weather Condition:	Fine	Fine	Cloudy
Works Inspected:	Drainage laying and trench works	Drainage laying and trench works	Drainage laying and trench works
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

Are Works in Compliance with:	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):
Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):
Nil.

Remarks:

- No specific water quality issue was observed during the inspection conducted on 18th September 2007 and 20th September 2007.
- Litters and silts were accumulated in the U-channel near to the West Abutment and V-ditch adjacent to M3 works area (South Division) on 19th September 2007. The Contractor was reminded to clear the litters and silts and this was seen done on 20th September 2007.

Prepared by : Chau Tsz Wing

Title : ET – Environmental Technician

Signature : 

Date : 24th September 2007

Reviewed and approved by : Susana Bezy

Title : Environmental Team Leader

Signature : 

Date : 27th September 2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)

**Contract No. HY 2004/09 Improvements to San Tin Interchange
Water Quality Visual Inspection Report**

Weekly Report No.: 117

	(1)	(2)	(3)
Date of Inspection:	24 th September 2007	25 th September 2007	28 th September 2007
Time:	15:30	14:00	14:30
Weather Condition:	Rainy	Fine	Fine
Works Inspected:	Drainage laying and trench works	Drainage laying and trench works	Drainage laying and trench works
Location:	Division North 1, 2 & South	Division North 1, 2 & South	Division North 1, 2 & South

Are Works in Compliance with:

	Y	N
1. Water Pollution Control Ordinance and the Subsidiary Legislation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Recommendations and requirements in the Project EIA Report, EM&A Manual and Environmental Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Recommendations and requirements in the Contractor's Drainage Management Plan (DMP)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Contract No. HY/2004/09, Particular Specification Section 26, Environmental Protection, items under Clause 26.04	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Recommendations and requirements in the ProPECC Note PN 1/94 "Construction Site Drainage"	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Any relevant Effluent Discharge License received by the Contractor	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Description of Environmental Non-compliance or Deficiency (if any):

Nil.

Remedial Actions – Mitigation Measures Implemented or Proposed (if any):

Nil.

Remarks:

- No specific water quality issue was observed during the inspection conducted on 24th September 2007.
- Stagnant water was seen in the works area next to the West Abutment and South Abutment works area on 25th September 2007. The contractor was reminded to clear the stagnant water promptly to prevent mosquito breeding.
- Stagnant water pools were seen to have been cleared during the inspection conducted on and 28th September 2007.

Prepared by : Chau Tsz Wing Title : ET – Environmental Technician

Signature :  Date : 3rd October 2007

Reviewed and approved by : Susana Bezy Title : Environmental Team Leader

Signature :  Date : 3rd October 2007

Sent to: IEC (ERM), ER (Maunsell), Contractor (Chun Wo)