REPORT

CLP Power Hong Kong Ltd

Renewable Energy Supply on Town Island (Construction Phase): 7th Monthly Environmental Site Audit Report

October 2011

Environmental Resources Management

21/F Lincoln House 979 King's Road Taikoo Place Island East, Hong Kong Telephone: (852) 2271 3000 Facsimile: (852) 2723 5660 E-mail: post.hk@erm.com http://www.erm.com

CLP Power Hong Kong Ltd

Renewable Energy Supply on Town Island (Construction Phase): 7th Monthly Environmental Site Audit Report

October 2011

Reference 0129569

For and on behalf of ERM-Hong Kong, Limited		
Approved	by: Frank Wan	
Signed:	Harch-AT.	
Position:	Partner	
Certified b	y: Winnie Ko	
Signed :	Marie	
Position:	Independent Environmental Checker	
Date :	26 October 2011	

CONTENTS

1	ENVIRO	NMENTAL SITE AUDIT	1
1.1	BACKGRO	UND	1
1.2	SITE AUDI	T FINDINGS AND OBSERVATIONS	1
	Annex A	Environmental Site Audit Checklist	
	Annex B	Photo Records	

1 ENVIRONMENTAL SITE AUDIT

1.1 BACKGROUND

The construction works of *Renewable Energy Supply on Town Island* (the Project) has commenced in March 2011.

To fulfill Condition 2.2 of the Environmental Permit (EP-397/2010) and environmental audit requirements stated in Section 5.7.1 of the approved Project Profile (PP) submitted for direct application of an Environmental Permit under EIA Ordinance (EIAO) (PP-413/2010), monthly environmental site audits should be undertaken to ensure that the mitigation measures recommended in PP are properly implemented.

This is the seventh *Monthly Environmental Site Audit Report* presenting the key findings and observations of the site audit conducted on 18 October 2011.

1.2 SITE AUDIT FINDINGS AND OBSERVATIONS

The seventh monthly environmental site audit was conducted on 18 October 2011. No construction activities were observed during the site inspection. The temporary worksites for underground pipe and cabling works have been reinstated (*Photo 1*). No specific observation was identified from the site inspection.

The remedial actions for the environmental deficiency which were recorded during the previous reporting period has been taken and verified during the site inspection:

• The concrete stain on ground at Site 1 has been removed (*Photo 2*).

The environmental site audit checklist is appended in *Annex A*.

Photos of the site audit are given in *Annex B*.

Annex A

Environmental Site Audit Checklist



Renewable Energy Supply on Town Island Construction Phase - Environmental Site Audit



E	KM							
In	spection Date:	18-10-2011	Time:	10:00	to	_	11:00	
	Inspected By:	IEC Representative : CLP Representative : Contractor :	Andre Fung Raymond Ho Rebel Hui					
We	ather							112
	nperature	Sunny Fine 28 °C Calm V Light	Humidity H	rizzie Rain igh Mode trong		orm [Hazy	
A	General			Yes	Yes, but need Improvemen		N/A or not observed	Photo/Remarks
A1	Is the Environ	mental Permit displayed a	t the entrances / exits?				1	
В	Air Quality			Yes	Yes, but need Improvemen		N/A or not observed	Photo/Remarks
В1	Is open burnin	ng avoided?					7	
B2	Are exposed s	soil surfaces regularly water	ared to avoid generation of	dust?			7	
В3	Are plant and from powered		d? (ie without black smoke				4	
B4	Are stockpiles	of dusty material covered	or regularly watered?				1	
B5	Is watering im	plemented during excavat	ion?				√	
В6	Is generation	of dust avoided during loa	ding/unloading/excavation?				\Box	
С	Noise			Yes	Yes, but need Improveme		N/A or not observed	Photo/Remarks
C1	Is the Constru (if any)	ction Noise Permit display	yed at the entrances / exits	`			1	No Construction
C2	Are all plant a condition?	nd equipment well maintal	ined and in good operating				1	Work. Worksite has been reinstated.
C3	Is idle equipm	ent turned off or throttled	down?					
C4	Are powered r acoustic mate	nechanical equipment cov rials?	vered or shielded by				7	
C5		quipment used where pra						
C6		of contstruction plant being	C No.					-
C7		ssors have valid noise lab					\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
C8	Do compresso	ors operate with doors clos	sed?			Ш	1	
D	Water Quali	ty		Yes	Yes, but need Improvement		N/A or not observe	Photo/Remarks d
D1	Is wastewater	discharge license, if any,	available for inspection?				V	
D2		stem adequate?					V	
D3	Is drainage sy	stem well maintained?					V	All III
D4	Is debris and r	rubbish in the drainage sy	stem collected and				1)	

D5	Are there temporary ditches for runoff discharge into appropriate					
	Watercourse?				1	
	With silt retention pond?				4	
D6	Are there sedimentation tanks for settling runoff prior to disposal?				7	
D7	Is the capacity of sedimentation tank adequate?				✓	
D8	Is the sedimentation free from silt and sediment?					
D9	Are the temporary stockpiles located away from stream or coastline?				4	
D10	Are treaching carried out for the section of cable in the vicinity of and crossing the stream between Sites 1 and 2?				√	
D11	Is cable trenching works scheduled to be carried out during dry season?				4	
E	Waste/Chemical Management	Yes	Yes,	No	N/A or	Photo/Remarks
			but need Improvemen		ot observe	
E1	General refuse Accumulation avoided?					
E2	Receptacles (e.g. rubbish bins) available?	H	H	H		
E3	Disposed of regularly and properly?		H	H	1	
	Chemical waste, waste oil		ш			
E4	Is the Chemical Waste Producer Registration available for inspection?				V	No Construction
E5	Stored properly in designated area?				V	work. Worksire has
E6	Labelled properly?				1	been reinstated.
E7	Disposed of properly?				√	
E8	Trip tickets/ chits available for inspection?				7	
E9	Chemical/fuel storage area Are all spillage containment provided for all chemicals, oils and fuels stored on site, those equipment which potentially have oil leakage and for the area where maintenance works carrying out?				V	
E10	Is storage area bunded?				V	
E11	Adequate bund capacity? (>110% of the largest tank)				V	
E12	Are storage areas provided with locks and located on sealed areas?				1	
E13	Construction Waste Reused where practicable?				1	
	Is sorting conducted on site?					
E14	Transported offsite by boat for proper disposal?					
E15	Are surplus inert materials being reused where practical as an alternative to ordering imported fill material?				1	
E16	Excavated Material Appears uncontaminated? (colour, odour)					
E17	If suspected contaminated, appropriate procedures followed?	H	H	H		
E18	Relevant license/permit/trip tickets/chits for disposal of construction waste or excavated materials available for inspection?		H		7	
F	General / Housekeeping	Yes	Yes, but need Improveme		N/A or not observe	Photo/Remarks
	Are potential stagnant pools cleared and mosquito breeding prevented?				7	
G	Ecology	Yes	Yes, but need	No	N/A or	Photo/Remarks
			Improveme		iidi observ	
	Is damage and disturbance to the remaining and surrounding natural shrubby grassland and yound woodland habitats avoided? (particularly those caused by filling and illegal dumping)				V)	-

2	Is damage to surrounding areas avoided?
	Are temporary work sites/disturbed areas reinstated?
	Is disturbance to streams avoided during cable laying?
	Is any alternative method adopted for laying cable across stream between Sites 1 and 2?
	Items for Inspection
	- Site 1 (No construction work.)
	- Temporary worksite for underground pipe and cabling works (Worksite has been reinstated after excavation.)
	- Site 2 (No construction work.)
ľ	
	Notes / Issues Recorded On Site
	- No construction work. Temporary worksites for underground pipe and cabling works has been reinstated.
ı	
ı	
	Corrective Actions
	Nanafures ·
	Signatures: EC Representative: CLP Representative: Contractor: (3Tech Co. Ltd.)
	Signatures: EC Representative: CLP Representative: Contractor: (3Tech Co. Ltd.
1	Signatures: EC Representative: CLP Representative: Contractor: (37ech Co. Ltd. GRAF Name: (Name: Raymond Ho) Name: CHISOK KAM (LAN)

Annex B

Photo Records

Photo Records on 18 October 2011



Photo 1 - The worksite for underground pipe and cabling works have been reinstated.



Photo 2 – The concrete stain on ground at Site 1 has been removed.