

CLP Power Hong Kong Ltd

Renewable Energy Supply on
Town Island (Construction
Phase): *16th Monthly*
Environmental Site Audit Report

July 2012

Environmental Resources Management

21/F Lincoln House
979 King's Road
Taikoo Place
Island East, Hong Kong
Telephone: (852) 2271 3000
Facsimile: (852) 2723 5660
E-mail: post.hk@erm.com
<http://www.erm.com>

CLP Power Hong Kong Ltd

Renewable Energy Supply on
Town Island (Construction
Phase): 16th Monthly
Environmental Site Audit Report

July 2012

Reference 0129569

For and on behalf of ERM-Hong Kong, Limited

Approved by: Frank Wan

Signed: 

Position: Partner

Certified by : Winnie Ko

Signed : 

Position : Independent Environmental Checker

Date : 13 July 2012

CONTENTS

1	ENVIRONMENTAL SITE AUDIT	1
1.1	BACKGROUND	1
1.2	SITE AUDIT FINDINGS AND OBSERVATIONS	1

Annex A Environmental Site Audit Checklist
Annex B Photo Records

1 ENVIRONMENTAL SITE AUDIT

1.1 BACKGROUND

The construction works of *Renewable Energy Supply on Town Island* (the Project) has commenced in March 2011.

To fulfill Condition 2.2 of the Environmental Permit (EP-397/2010) and environmental audit requirements stated in Section 5.7.1 of the approved Project Profile (PP) submitted for direct application of an Environmental Permit under EIA Ordinance (EIAO) (PP-413/2010), monthly environmental site audits should be undertaken to ensure that the mitigation measures recommended in PP are properly implemented.

This is the sixteenth *Monthly Environmental Site Audit Report* presenting the key findings and observations of the site audit conducted on 10 July 2012.

1.2 SITE AUDIT FINDINGS AND OBSERVATIONS

The sixteenth monthly environmental site audit was conducted on 10 July 2012. The construction works undertaken during the site audit included superstructure works and installation of photovoltaic panel at Site 1 and foundation and superstructure works at Site 2. All the temporary worksites have been reinstated. Two observations have been recorded during the site audit and are described below:

- Dusty stockpile was observed not being properly covered at Site 1 (*Photo 1*). The Contractor was reminded to cover the dusty stockpile properly.
- Cement stain was observed outside the site boundary at Site 2 (*Photo 2*). The Contractor was reminded to remove the cement.

The remedial action for the environmental deficiency which was recorded during the previous reporting period has been taken and rectified during the site inspection:

- The construction materials observed storing outside the site boundary during the last site inspection has been kept within the site boundary.

The environmental site audit checklist is appended in *Annex A*.

Photos of the site audit are given in *Annex B*.

Annex A

Environmental Site Audit Checklist



Renewable Energy Supply on Town Island
Construction Phase - Environmental Site Audit



Inspection Date: 15-06-2012 Time: 10:00 to 12:00

Inspected By: IEC Representative : Fung Siu Chung Andrew
 CLP Representative : Raymond Ho / Lee Tin Yau
 Contractor : Rebel Hul (3Tech Corporate Ltd.)

Weather

Condition Sunny Fine Overcast Drizzle Rain Storm Hazy
 Temperature 29 °C Humidity High Moderate Low
 Wind Calm Light Breeze Strong

A General

	Yes	Yes, but need Improvement	No	N/A or not observed	Photo/Remarks
--	-----	---------------------------	----	---------------------	---------------

A1 Is the Environmental Permit displayed at the entrances / exits? _____

B Air Quality

	Yes	Yes, but need Improvement	No	N/A or not observed	Photo/Remarks
--	-----	---------------------------	----	---------------------	---------------

B1 Is open burning avoided? _____
 B2 Are exposed soil surfaces regularly watered to avoid generation of dust? _____
 B3 Are plant and equipment well maintained? (ie without black smoke from powered plant) _____
 B4 Are stockpiles of dusty material covered or regularly watered? Note 1
 B5 Is watering implemented during excavation? _____
 B6 Is generation of dust avoided during loading/unloading/excavation? _____

C Noise

	Yes	Yes, but need Improvement	No	N/A or not observed	Photo/Remarks
--	-----	---------------------------	----	---------------------	---------------

C1 Is the Construction Noise Permit displayed at the entrances / exits (if any)? _____
 C2 Are all plant and equipment well maintained and in good operating condition? _____
 C3 Is idle equipment turned off or throttled down? _____
 C4 Are powered mechanical equipment covered or shielded by acoustic materials? _____
 C5 Are silenced equipment used where practicable? _____
 C6 Is the number of construction plant being used minimized? _____
 C7 Do air compressors have valid noise labels? _____
 C8 Do compressors operate with doors closed? _____

D Water Quality

	Yes	Yes, but need Improvement	No	N/A or not observed	Photo/Remarks
--	-----	---------------------------	----	---------------------	---------------

D1 Is wastewater discharge license, if any, available for inspection? _____
 D2 Is drainage system adequate? _____
 D3 Is drainage system well maintained? _____
 D4 Is debris and rubbish in the drainage system collected and disposed of properly? _____

D5	Are there temporary ditches for runoff discharge into appropriate Watercourse? With silt retention pond?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
D6	Are there sedimentation tanks for settling runoff prior to disposal?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
D7	Is the capacity of sedimentation tank adequate?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
D8	Is the sedimentation free from silt and sediment?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
D9	Are the temporary stockpiles located away from stream or coastline?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
D10	Are treaching carried out for the section of cable in the vicinity of and crossing the stream between Sites 1 and 2?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
D11	Is cable trenching works scheduled to be carried out during dry season?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	

E Waste/Chemical Management

	Yes	Yes, but need improvement	No	N/A or not observed	Photo/Remarks	
General refuse						
E1	Accumulation avoided?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
E2	Receptacles (e.g. rubbish bins) available?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
E3	Disposed of regularly and properly?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Chemical waste, waste oil						
E4	Is the Chemical Waste Producer Registration available for inspection?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
E5	Stored properly in designated area?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
E6	Labelled properly?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
E7	Disposed of properly?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
E8	Trip tickets/ chits available for inspection?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Chemical/fuel storage area						
E9	Are all spillage containment provided for all chemicals, oils and fuels stored on site, those equipment which potentially have oil leakage and for the area where maintenance works carrying out?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
E10	Is storage area bunded?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
E11	Adequate bund capacity? (>110% of the largest tank)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
E12	Are storage areas provided with locks and located on sealed areas?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Construction Waste						
E13	Reused where practicable?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
	Is sorting conducted on site?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
E14	Transported offsite by boat for proper disposal?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
E15	Are surplus inert materials being reused where practical as an alternative to ordering imported fill material?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Excavated Material						
E16	Appears uncontaminated? (colour, odour)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
E17	If suspected contaminated, appropriate procedures followed?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
E18	Relevant license/permit/trip tickets/chits for disposal of construction waste or excavated materials available for inspection?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

F General / Housekeeping

	Yes	Yes, but need improvement	No	N/A or not observed	Photo/Remarks	
F1	Are potential stagnant pools cleared and mosquito breeding prevented?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

G Ecology

	Yes	Yes, but need improvement	No	N/A or not observed	Photo/Remarks	
G1	Is damage and disturbance to the remaining and surrounding natural shrubby grassland and young woodland habitats avoided? (particularly those caused by filling and illegal dumping)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Note 2

G2	Is damage to surrounding areas avoided?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
G3	Are temporary work sites/disturbed areas reinstated?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
G4	Is disturbance to streams avoided during works?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
G5	Is any alternative method adopted for laying cable across stream between Sites 1 and 2?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	_____

Items for Inspection

- Site 1 construction site.
- Site 2 construction site.

Notes / Issues Recorded On Site

- 1) Dusty stockpile was observed not being properly covered at Site 1.
- 2) Cement stain was observed outside the site boundary at Site 2.

Corrective Actions


- 1) The Contractor was reminded to cover the dusty stockpile properly.
- 2) The Contractor was reminded to remove the cement stain.

Signatures:

IEC Representative :


 (Name: Andrew Fung)

CLP Representative :


 (Name: T.Y. Lee)

Contractor : 3Tech Corporate Ltd


 (Name: Rebel Hui)

Annex B

Photo Records

Photo Records on 10 July 2012



Photo 1 – Dusty stockpile was observed not being properly covered at Site 1.



Photo 2 – Cement stain was observed outside the site boundary at Site 2.