CLP Power Hong Kong Ltd

Renewable Energy Supply on Town Island (Construction Phase): 20th Monthly Environmental Site Audit Report

November 2012

Environmental Resources Management

16/F DCH Commercial Centre 25 Westlands Road Quarry Bay, Hong Kong Telephone: (852) 2271 3000 Facsimile: (852) 2723 5660 E-mail: post.hk@erm.com http://www.erm.com CLP Power Hong Kong Ltd

Renewable Energy Supply on Town Island (Construction Phase): 20th Monthly Environmental Site Audit Report

November 2012

Reference 0129569

For and on behalf of ERM-Hong Kong, Limited				
Approved I	oy: Frank Wan			
Signed:	Narch-M.T.			
Position:	Partner			
Certified by	V: Winnie Ko			
Signed :	MAS			
Position :	Independent Environmental Checker			
Date :	5 th December 2012			

CONTENTS

1	ENVIRONMENTAL SITE AUDIT	1
1.1	BACKGROUND	1
1.2	SITE AUDIT FINDINGS AND OBSERVATIONS	1

Annex AEnvironmental Site Audit ChecklistAnnex BPhoto Records

1 ENVIRONMENTAL SITE AUDIT

1.1 BACKGROUND

The construction works of *Renewable Energy Supply on Town Island* (the Project) commenced in March 2011.

To fulfill Condition 2.2 of the Environmental Permit (EP-397/2010) and environmental audit requirements stated in Section 5.7.1 of the approved Project Profile (PP) submitted for direct application of an Environmental Permit under the EIA Ordinance (EIAO) (PP-413/2010), monthly environmental site audits should be undertaken to ensure that the mitigation measures recommended in PP are properly implemented.

This is the twentieth *Monthly Environmental Site Audit Report* presenting the key findings and observations of the site audit conducted on 27th November 2012.

1.2 SITE AUDIT FINDINGS AND OBSERVATIONS

The twentieth monthly environmental site audit was conducted on 27th November 2012. Major construction works at both Site 1 and Site 2 have been completed. One observation was made during the site audit and is described below:

• Chemical stain was found on the ground near the entrance of Site 1 (*Photo* 1). The Contractor removed the chemical stain and disposed of it as chemical waste immediately once notified (*Photo* 2).

The environmental site audit checklist is given in *Annex A*.

Photos of the site audit are given in *Annex B*.

1.3 COMPLETION OF THE CONSTRUCTION PHASE ENVIRONMENTAL SITE AUDIT

As confirmed by the CLP, major construction works of this Project has been completed. Following the requirement set out in Condition 2.3 of the Environmental Permit (EP-397/2010), all temporary work sites and disturbed areas have been reinstated. The construction phase of the Project has been completed and no further environmental site audit is required. Hence, this is the last monthly environmental site audit report for the construction phase.

1

Annex A

Environmental Site Audit Checklist

E	Renewable E Construction P				С		中電
Ins	spection Date: 27-11-2012 Time:	1	10:00	to		12:00	
	Inspected By: IEC Representative : Fung Siu Chung / CLP Representative : T.Y. Lee Contractor : Mic Kowk (3Tech		td.)				
Wea	ather				-	11.1	
		Drizzle √ High Strong	_√_Rain Moderat	Storn e Low	n 🗌	Hazy	
Α	General		Yes	Yes, but need mprovement	No r	N/A or not observed	Photo/Remarks
A1	Is the Environmental Permit displayed at the entrances / exits	?	\checkmark			□.	<u></u>
В	Air Quality		Yes	Yes, but need mprovement	No r	N/A or not observed	Photo/Remarks
B1	Is open burning avoided?		N				
B2	Are exposed soil surfaces regularly watered to avoid generati	on of dust?	\checkmark				
B3	Are plant and equipment well maintained? (ie without black sr from powered plant)	noke				√	
B4	Are stockpiles of dusty material covered or regularly watered?	?	N				
B5	Is watering implemented during excavation?					V	
B6	Is generation of dust avoided during loading/unloading/excave	ation?				_	
С	Noise		Yes	Yes, but need mprovement	No	N/A or not observed	Photo/Remarks
C1	Is the Construction Noise Permit displayed at the entrances / (if any)	exits?				V	
C2	Are all plant and equipment well maintained and in good oper condition?	ating				\checkmark	
C3	Is idle equipment turned off or throttled down?					\checkmark	
C4	Are powered mechanical equipment covered or shielded by acoustic materials?						
C5	Are silenced equipment used where practicable?						
C6	Is the number of contstruction plant being used minimized?					V	
C7	Do air compressors have valid noise labels?					V	
C8	Do compressors operate with doors closed?					V	
D	Water Quality		Yes	Yes, but need Improvement	No	N/A or not observed	Photo/Remarks
D1	Is wastewater discharge license, if any, available for inspection	on?	\checkmark				entra an
D2	Is drainage system adequate?		V				
D3	Is drainage system well maintained?		\checkmark				100 11 11 11 11 11 11 11 11 11 11 11 11
D4	Is debris and rubbish in the drainage system collected and disposed of properly?		V				nan is kenninga

D5	Are there temporary ditches for runoff discharge into appropriate					
	Watercourse?	V				
-	With silt retention pond?	V				
	Are there sedimentation tanks for settling runoff prior to disposal?	V				
D7	Is the capacity of sedimentation tank adequate?	\checkmark				<u>den skrepner (</u>
D8	Is the sedimentation free from silt and sediment?	\checkmark			-	
D9	Are the temporary stockpiles located away from stream or coastline?	\checkmark				<u>i curan</u>
D10	Are treaching carried out for the section of cable in the vicinity of and crossing the stream between Sites 1 and 2?				\checkmark	
D11	Is cable trenching works scheduled to be carried out during dry season?				V	<u></u>
E	Waste/Chemical Management	Yes	Yes,	No	N/A or	Photo/Remarks
			but need		not observed	
			Improvement	t		
E1	General refuse Accumulation avoided?					
				H		
E2	Receptacles (e.g. rubbish bins) available?	N				2000 - Contra - Contr
E3	Disposed of regularly and properly?	V				
E4	Chemical waste, waste oil Is the Chemical Waste Producer Registration available for inspection?	V				
E5	Stored properly in designated area?					
E6	Labelled properly?	\checkmark				
E7	Disposed of properly?					Note 1
E8	Trip tickets/ chits available for inspection?	\checkmark		H		
E9	Chemical/fuel storage area Are all spillage containment provided for all chemicals, oils and fuels stored on site, those equipment which potentially have oil					
	leakage and for the area where maintenance works carrying out?					
E10	Is storage area bunded?					
E11	Adequate bund capacity? (>110% of the largest tank)			F		
E12	Are storage areas provided with locks and located on				a de la constante de	and the second second
	sealed areas?				\checkmark	
	Construction Waste					
E13	Reused where practicable?	\checkmark				
	Is sorting conducted on site?	\checkmark				
E14	Transported offsite by boat for proper disposal?	\checkmark				
E15	Are surplus inert materials being reused where practical as an alternative to ordering imported fill material?	\checkmark				
	Excavated Material			-		
E16	Appears uncontaminated? (colour, odour)	V				
E17	If suspected contaminated, appropriate procedures followed?				\checkmark	
E18	Relevant license/permit/trip tickets/chits for disposal of construction waste or excavated materials available for inspection?				V	
F	General / Housekeeping	Yes	Yes, but need	No	N/A or not observed	Photo/Remarks
			Improvemen		nor observed	
F1	Are potential stagnant pools cleared and mosquito breeding prevented?	V				
G	Ecology	Yes	Yes,	No	N/A or	Photo/Remarks
-		165	but need Improvemen		not observed	
G1	Is damage and disturbance to the remaining and surrounding natural shrubby grassland and yound woodland habitats avoided? (particularly those caused by filling and illegal dumping)	N				

Items for Inspection

- Site 1 construction site.
- Site 2 construction site.

Notes / Issues Recorded On Site

1) Chemical stain was found on the ground near the entrance of Site 1.

Corrective Actions

1) The Contractor has removed the chemical stain immediately.

Signatures: IEC Representative :

w Fung Ì

CLP Representative :

(Name: T.Y. Le

Contractor :

(Name:

Page 3 of 3

Annex B

Photo Records

Photo Record on 27th November 2012



Photo 1 – Chemical stain was found on the ground near the entrance of Site 1.



Photo 2 – Chemical stain had been removed following notification.