Tseung Kwan O Development, Phase II

Contract No. TK57/02

Grade Separated Interchange T1/P1/P2

Weekly Site Inspection Record Sheet

Inspection Information

Checklist Reference Number	30328
Date	28 March 2003
Time	10:25 – 11:30

Non-Compliance	Remarks No.
None	

Water Quality	
• Following the last site audit, the situations in remark 6 and 7 were not rectified.	
Air Quality	
Following the last site audit, the situation in remark 3 was not rectified.	
• Following the last site audit, the excavator emitted black smoke at Po Shum Road (Central	3
Divider) has been moved to Area 40.	3
Noise	
No violation was observed during site inspection.	
Waste / Chemical Management	
Oil tanks were placed on the bared ground at Bridge D.	1
Rubbish was accumulated at Wan Po Road.	2
• Following the last site audit, the situations in remark 1, 2 and 8 were not rectified.	
Permit/Licenses	
No violation was observed during site inspection.	

	Name	Signature	Date
Recorded by	Lemon Lam		28 March 2003
Checked by	C M Cheung		28 March 2003

Tseung Kwan O Development, Phase II

Contract No. TK57/02

Grade Separated Interchange T1/P1/P2

Weekly Site Inspection Record Sheet

Inspection Information

Checklist Reference Number	30404
Date	04 April 2003
Time	10:15 – 12:15

Non-Compliance Remarks No.

None

Water Quality	
Damaged sand bags were found near the gully at Po Shun Road and King Lam Estate.	2
• Following the previous site audit (ref no. 30321), water overflow from wheel washing bay still observed at Area 40.	3
Air Quality	
No violation was observed during site inspection.	
Noise	
No violation was observed during site inspection.	
Waste / Chemical Management	
Following up the last site audit, rubbishes were accumulated at Wan Po Road.	1
Rubbishes were found at Po Shun Road near Chung Ming Court.	1
Following the previous site audit (ref no. 30321), oil tank was placed on the bared ground at Wan Po Road.	4
Permit/Licenses	
No violation was observed during site inspection.	

	Name	Signature	Date
Recorded by	Lemon Lam		04 April 2003
Checked by	C M Cheung		04 April 2003

Tseung Kwan O Development, Phase II Contract No. TK57/02

Grade Separated Interchange T1/P1/P2

Weekly Site Inspection Record Sheet

Inspection Information

Checklist Reference Number	31111
Date	11 April 2003
Time	10:15 – 12:25

Non-Compliance Remarks No.

None

Water Quality	
Water ponds were found at Po Shun Road near King Lam Estate and Area 40.	2
Air Quality	
Mud was found in the site entrance (public road) at Wan Po Road.	5
Noise	
No violation was observed during site inspection.	
Waste / Chemical Management	
Following up the last site audit, rubbishes were still accumulated at Wan Po Road.	1
Rubbishes were found at Bridge D, Po Shun Road near King Lam Estate and Area 40.	1,4
Oil drums were placed on the bared ground at Area 40.	3
Permit/ Licenses	
No violation was observed during site inspection.	

	Name	Signature	Date
Recorded by	Lemon Lam		11 April 2003
Checked by	C M Cheung		11 April 2003

Tseung Kwan O Development, Phase II

Contract No. TK57/02

Grade Separated Interchange T1/P1/P2

Weekly Site Inspection Record Sheet

Inspection Information

Checklist Reference Number	31717
Date	17 April 2003
Time	14:05 – 15:50

Non-Compliance Remarks No.

None

Ouservations	
Water Quality	
• Sand runoff into the gullies was found at Po Shun Road near King Lam Estate.	3
 Water runoff to the public road from drilling machine was found at Po Shun Road near King Lam Estate. 	5
• Water pond was found at Area 40.	6
• Stand water inside the trip tray were found at Wan Po Road.	9
Air Quality	
• Black smoke emitted from air compressor (AC008) was observed at Po Shun Road near King Lam Estate.	4
Noise	
No violation was observed during site inspection.	
Waste / Chemical Management	
• Rubbishes were found at Bridge D, Po Shun Road and Wan Po Road.	1
Oil dripping from crane was observed at Po Shun Road near Chung Ming Court.	2
• Oil dripped on the bared ground was found at Area 40 and Wan Po Road.	7
Oil drums were placed on the bared ground was observed at Wan Po Road.	8
Permit/Licenses	
No violation was observed during site inspection.	

	Name	Signature	Date
Recorded by	Lemon Lam		22 April 2003
Checked by	C M Cheung		22 April 2003

Tseung Kwan O Development, Phase II Contract No. TK57/02

Grade Separated Interchange T1/P1/P2

Weekly Site Inspection Record Sheet

Inspection Information

Checklist Reference Number	32525
Date	25 April 2003
Time	10:05 am

Non-Compliance Remarks No.

None

Observations		
Water Quality		
• Stand water was accumulated inside the tank at Po Shun Road near Chung Ming Court.	2	
• Stand water was accumulated inside the trip tray at Po Shun Road near King Lam Estate and Area 40.	4	
• Following up the last site audit, sand runoff into the gullies still found at Po Shun Road near King Lam Estate.	8	
Air Quality		
• The unpaved area was dry at Po Shun Road and Area 40.	3	
Large area of stockpile/excavated materials were not covered at Area 40.	5	
Noise		
No violation was observed during site inspection.		
Waste / Chemical Management		
• Oil drums were placed on the bared ground was observed at Po Shun Road near King Lam Estate and Chung Ming Court.	1	
• Oil leakages from crawler crane were found at Bridge C and Wan Po Road.	6	
• Following up the last site audit, rubbishes still found at Area 40 and Bridge D.	7	
• Following up the last site audit, oil dripping from crawler crane still observed at Po Shun Road near Chung Ming Court.	9	
Permit/Licenses		
No violation was observed during site inspection.		

	Name	Signature	Date
Recorded by	Lemon Lam		28 April 2003
Checked by	C M Cheung		28 April 2003