-CCECC & CRWJ Joint Venture

Contract No. HY/2003/19

Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha

Monthly EM&A Report (Version 2.0)

September 2009

Certified By

(Environmental Team Leader)

REMARKS:

The information supplied and contained within this report is, to the best of our knowledge, correct at the time of printing.

CINOTECH accepts no responsibility for changes made to this report by third parties.

CINOTECH CONSULTANTS LTD

Room 1710, Technology Park, 18 On Lai Street, Shatin, NT, Hong Kong Tel: (852) 2151 2083

Fax: (852) 3107 1388 Email: info@cinotech.com.hk

TABLE OF CONTENTS

EXI	ECUTIVE SUMMARY
1.	INTRODUCTION
Raci	kground
	ect Organizations
	struction Programme
	imary of EM&A Requirements
2.	ENVIRONMENTAL AUDIT
	Auditsus of Environmental Licensing and Permitting
	us of Waste Management
	lementation Status of Environmental Mitigation Measures
	-compliance Recorded during Site Inspections
	imary of Mitigation Measures Implemented
	imary of Complaint, Warning, Notification of any Summons and Successful Prosecution.
3.	FUTURE KEY ISSUES
•	Issues for the Coming Month
	struction Program for the Project (Construction Program for the Next Month)
Con	
4.	CONCLUSIONS AND RECOMMENDATIONS10
Con	clusions10
Reco	ommendations10
LIS	T OF TABLES
Tabl	le I Summary Table for Key Information in the Reporting Month
Tabl	le 2.1 Summary of Environmental Licensing and Permit Status
Tabl	le 2.2 Observations and Recommendations of Site Inspections
LIS	T OF FIGURES
Figu	
Figu	· · · · · · · · · · · · · · · · · · ·
6-	
T TO	T OF A DRENDICES
	T OF APPENDICES Site Audit Summery
A B	Site Audit Summary Environmental Mitigation Implementation Schedule (EMIS)
C	Complaint Logs
D	Summary of Warnings/Direction issued by the EPD and Prosecution
E	Site Audit Schedule
_	5100 I ludit belledule

ABBREVIATION AND ACRONYM

AL Levels Action and Limit Levels

E / ER Engineer/Engineer's Representative

EIA Environmental Impact Assessment

EM&A Environmental Monitoring and Audit

EMIS Environmental Mitigation Implementation Schedule

EP Environmental Permit

EPD Environmental Protection Department

ET Environmental Team

HVS High Volume Sampler

HyD Highways Department

IEC Independent Environmental Checker

NOE Notification of Exceedance

QA/QC Quality Assurance / Quality Control

RE Resident Engineer

RH Relative Humidity

SLM Sound Level Meter

TSP Total Suspended Particulates

WMP Waste Management Plan

EXECUTIVE SUMMARY

Introduction

- 1. This is the 59th monthly Environmental Monitoring and Audit (EM&A) Report prepared by Cinotech Consultants Limited for the project "Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha" (the Project). This report documents the findings of EM&A Works conducted in September 2009.
- 2. The construction activities undertaken in the reporting month included:
 - Landscaping works;
 - Street furniture installation; and
 - Reinstatement works of the footpath.

Environmental Monitoring Works

- 3. The construction phase environmental monitoring for air quality, construction noise and water quality of the Project was approved by EPD to cease since end of August 2009.
- 4. Site audits were conducted once per two weeks. The implementation of the environmental mitigation measures and environmental complaint handling procedures were also checked.

Environmental Licensing and Permitting

5. License/Permits granted to the Project include Environmental Permit (License No.: EP-170/2003/C), Registration of Chemical Waste Producer (License: WPN5214-950-C1213-01), Water Discharge License (License No.: EP890/W7/XP089, EP890/W7/XP090 and EP890/W2/XG013).

Key Information in the Reporting Month

6. Summary of key information in the reporting month is tabulated in Table I.

Table I Summary Table for Key Information in the Reporting Month

	Event Details		Action Taken	Status	Remark
Event	Number	Nature			
Complaint received	0		N.A.	N.A.	
Changes to the assumptions and key construction / operation activities recorded	0		N.A.	N.A.	
Notifications of any summons received	0		N.A.	N.A.	
Notifications of any successful prosecution received	0		N.A.	N.A.	

Complaints and Prosecutions

- 7. No environmental complaint was received in the reporting month.
- 8. No warning and summons or notification of successful prosecution was received in the reporting month.

Future Key Issues

9. All civil works for this project have been substantially completed by the Contractor. No key issue was identified for the coming month.

1. INTRODUCTION

Background

- 1.1 The Project "Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha" involves the widening and realignment of Tung Chung Road between Lung Tseng Tau in North Lantau and Cheung Sha in South Lantau. The layout plan of the Project is shown in **Figure 1**.
- 1.2 The scope of the Project includes:
 - a) widening and realignment of a 3.6 km section of Tung Chung Road (TCR) between Lung Tseng Tau and Pak Kung Au from a single-lane road for two-way traffic to a single two-lane road for two-way traffic with a footpath having a minimum width of 1.6 m, and construction of a 2.6 km long single two-lane road between Pak Kung Au and Cheung Sha, including elevated highway structures of a total length of 750 m, with a footpath of a minimum width of 1.6 m;
 - b) provision of 21 passing bays/bus-bays along the road and a roundabout at Cheung Sha; and
 - c) associated works including road rehabilitation, drainage, utility, environmental mitigation measures, landscaping, slope stabilization, traffic aids, road safety enhancement measures, lighting, traffic control and surveillance system, and electrical and mechanical (E&M) works.
- 1.3 The Environmental Impact Assessment (EIA) Report for the Project was approved on 4 July 2002 under the Environmental Impact Assessment Ordinance (EIAO). An Environmental Permit (EP- 170/2003) for the works was also granted on 27 June 2003. Two varied Environmental Permits (EP) (EP-170/2003/B and EP-170/2003/C) were issued in June 2006 and July 2007 respectively. Environmental Monitoring and Audit (EM&A) Manual for the Project was also included as part of the EIA reports in the register. An updated EM&A Manual (Revision C) has been issued on 28 April 2006.
- 1.4 Highways Department awarded the construction of the Project to CCECC & CRWJ Joint Venture (being a joint venture of China Civil Engineering Construction Corporation & China Railway Wuju Group Corporation) (hereinafter called "the Contractor") in June 2004. The construction works commenced on 4 November 2004 and are scheduled to be completed by September 2007.
- 1.5 Cinotech Consultants Limited (Cinotech) was commissioned by the Contractor to undertake the Environmental Team (ET) Services for the Project since 1 September 2006. All environmental and audit works were conducted by Cinotech and the laboratory testing works were conducted by a HOKLAS laboratory, Wellab Limited. This is the 59th monthly EM&A report summarizing the EM&A works for the Project in September 2009.

Project Organizations

- 1.6 Different parties with different levels of involvement in the project organization include:
 - Project Proponent Major Works Project Management Office (MWPMO) of Highways Department (HyD)
 - Engineer (E) / Engineer's Representative (ER) Mott Connell Limited
 - Contractor CCECC & CRWJ Joint Venture
 - Environmental Team (ET) Cinotech Consultants Limited
 - Independent Environmental Checker (IEC) ENSR Asia (HK) Limited
- 1.7 The responsibilities of respective parties are detailed in Section 1.5 of the Updated EM&A Manual (Revision C, issued on 28 April 2006) of the Project. The project organization chart is presented in **Figure 2**.

Construction Programme

1.8 The construction activities undertaken in the reporting month were:

Northern Section

- Street furniture installation at Zone A to Zone F;
- Reinstatement work of the footpath.

Southern Section

• Slope reinstatement works from STR010 to STR013.

Summary of EM&A Requirements

- 1.9 The EM&A programme requires construction phase monitoring for air quality and construction noise, water quality and environmental site audit. The EM&A requirements for each parameter are described in the following sections, including:
 - All monitoring parameters;
 - Action and Limit levels for all environmental parameters;
 - Event Action Plans;
 - Environmental mitigation measures, as recommended in the project EIA report; and
 - Environmental requirements in contract documents.
- 1.10 The advice on the implementation status of environmental protection and pollution control/mitigation measures is summarized in Section 2 of this report.
- 1.11 The construction phase environmental monitoring for air quality, construction noise and water quality of the Project was approved by EPD to cease since end of August 2009. However, bi-weekly site audit works were still carried out in order to check for any inappropriate practices by the Contractor and to follow-up the previous observation/recommendations.

1.12 This report presents the site audit works for the Project in the reporting month.

2. ENVIRONMENTAL AUDIT

Site Audits

- 2.1 Site audits were carried out on a bi-weekly basis to monitor the timely implementation of proper environmental management practices and mitigation measures in the Project site.
- 2.2 ET site audits were conducted on 10th and 24th September 2009 in the reporting month. IEC site inspection was conducted on 10th September 2009. The summaries of site audits are attached in **Appendix A**.

Status of Environmental Licensing and Permitting

2.3 All permits/licenses obtained for the Project are summarized in Table 2.1.

Table 2.1 Summary of Environmental Licensing and Permit Status

	Valid Period Day 19					
Permit No.	From	To	Details	Status		
Environmental Peri	mit (EP)					
EP-170/2003/C Registration of Che	31/7/07	N/A	Construction of (a) Widening and realignment of an approximate 3.6 kilometre long section of Tung Chung Road between Lung Tseng Tau and Pak Kung Au from a single-lane road for two-way traffic to a single two-lane road with footpath; (b) Construction of an approximate 2.6 kilometre long single two-lane road between Pak Kung Au and Cheung Sha with footpath and elevated highway structures; and © Provision of passing bays/bus lay-bys along Tung Chung Road.	Valid		
WPN5214 – 950-	lilicai vvasu	N/A	Chamical wasta types	Valid		
C1213-01		IN/A	Chemical waste types: spent Indication oil, surplus paint, spent diesel, spent thinner, mixing residue containing pesticides, spent mineral oil	v and		
Water Discharge Li	Water Discharge License					
EP890/W7/XP089		N/A	Discharge from Sewage Treatment System (Northern Section)	Valid		
EP890/W7/XP090		N/A	Industrial discharge (Northern Section)	Valid		
EP890/W2/XG013		N/A	Industrial discharge (Southern Section)	Valid		

Status of Waste Management

- 2.4 The waste management of the Project has to follow the requirements and procedures stated in the Waste Management Plan which was prepared by the Contractor.
- 2.5 The solid waste generated from the Project was mainly general refuse that was

collected by a licensed collector on an as need basis.

Implementation Status of Environmental Mitigation Measures

2.6 During site inspections in the reporting month, no non-conformance was identified. The observations and recommendations are summarized in Table 2.2.

Table 2.2 Observations and Recommendations of Site Inspections

Parameters	Date	Observations and Recommendations	Follow-up
Water Quality	10/09/09	The Contractor was reminded of the followings: - Provide sand bag at the culvert at Shan Shek Wan.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	10/09/09	 The Contractor was reminded of the followings: Clear the construction waste, silt and debris in the culvert at near Stream 20 and 21, SD7-13, SD6-12, SD5-11 and SD4-7. 	
	24/09/09	The Contractor was reminded of the followings: - Properly remove the construction materials at the U-Channel and culvert at near Stream 21 and 22.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	24/09/09	The Contractor was reminded of the followings: - Provide sand bag at the culvert at Shan Shek Wan.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	24/09/09	The Contractor was reminded of the followings: - Clear remaining C&D waste, silt and debris in the culvert at near Stream 20 and 21, SD7-13, SD6-12, SD5-11 and SD4-7.	
Waste / Chemical Management	10/09/09	The Contractor was reminded of the followings: - Clear the construction waste, silt and debris in the culvert at near Stream 20 and 21, SD7-13, SD6-12, SD5-11 and SD4-7.	
	10/09/09	The Contractor was reminded of the followings: - Clear remaining C&D waste and general refuse at Stream 22,34,37 and 38.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	24/09/09	The Contractor was reminded of the followings: - Clear the construction waste, silt and debris in the culvert at near Stream 20 and 21, SD7-13, SD6-12, SD5-11 and SD4-7.	
	24/09/09	The Contractor was reminded of the followings: - Clear remaining C&D waste and general refuse at Stream 22,34,37 and 38.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
Ecology	10/09/09	The Contractor was reminded of the followings: - Clear remaining C&D waste and general refuse at Stream 22,34,37 and 38.	This item was not rectified during the follow-up audit session. Follow-up action was needed for the outstanding item.
	24/09/09	The Contractor was reminded of the followings: - Clear remaining C&D waste and general refuse at Stream 22,34,37 and 38.	This item was not rectified during the follow-up audit session. Follow-up action was needed for

Parameters	Date	Observations and Recommendations	Follow-up
			the outstanding item.

Non-compliance Recorded during Site Inspections

2.7 No non-compliance was recorded in the reporting period.

Summary of Mitigation Measures Implemented

2.8 The Contractor has implemented the mitigation measures as recommended in the EIA and the Updated EM&A Manual. The mitigation measures implemented by the Contractor in the reporting month are summarized as follow:

Water Quality

(1) The construction waste, silt, debris and sediment in the culvert and U-channel at CH7000 were cleared.

Waste/Chemical Management

- (1) Proper disposal of empty oil containers and discarded hose at Shan Shek Wan.
- (2) C&D wastes were kept clear and sorted near Stream 27, 30 and 36.
- 2.9 According to the Updated EM&A Manual, mitigation measures are required to be implemented. An updated summary of the EMIS is provided in **Appendix B**.

Summary of Complaint, Warning, Notification of any Summons and Successful Prosecution

- 2.10 No environmental complaint was received in the reporting month.
- 2.11 No warning and summons or notification of successful prosecution was received in the reporting month.
- 2.12 There were a total of 55 environmental complaints, 13 warnings, 3 summons and 2 successful prosecutions received since the commencement of the Project.
- 2.13 The Complaint Log is attached in **Appendix C** and the summary of warnings issued by the EPD and prosecution is attached in **Appendix D**.

3. FUTURE KEY ISSUES

Key Issues for the Coming Month

3.1 All civil works for this project have been substantially completed by the Contractor. No key issue was identified for the coming month.

Monitoring Schedule for the Next Month

3.2 The tentative environmental site audit schedule for the next reporting month is shown in **Appendix E**

Construction Program for the Project (Construction Program for the Next Month)

- 3.3 Construction activities were will be undertaken in the coming month:
 - Landscaping works;
 - Street furniture installation; and
 - Reinstatement works of the footpath.

4. CONCLUSIONS AND RECOMMENDATIONS

Conclusions

- 4.1 No environmental complaint was received in the reporting month.
- 4.2 No warning and summons and notification of successful prosecution was received in the reporting month.
- 4.3 The construction phase environmental monitoring for air quality, construction noise and water quality of the Project was approved by EPD to cease since end of August 2009. However, bi-weekly site audit works were still carried out in order to check for any inappropriate practices by the Contractor and to follow-up the previous observation/recommendations.

Recommendations

4.4 According to the environmental audit performed in the reporting month, the following recommendations were made:

Dust Impact

- To ensure that all vehicles carrying dusty material are properly covered before leaving the site.
- To maintain the machinery and vehicles in a good working condition on site.

Noise Impact

• To space out noisy equipment and position as far away as possible from sensitive receivers.


Water Quality Impact


- To prevent any surface runoff discharge into any stream course.
- To avoid accumulation of stagnant and ponding water on site.
- To review the capacity of de-silting facilities for discharge.

Waste / Chemical Management

- To remove ponding water regularly in drip trays on site.
- To ensure proper collection and disposal of rubbish generated on site.
- To avoid storage of construction materials at any stream.
- To check for any accumulation of waste materials or rubbish on site.

FIGURES





CINOTECH Cinotech Consultants Limited Improvement to Tung Chung Road between Lung Tseng Tau and Cheung Sha

Organization Chart

SCALE	N.T.S.	DATE	200	7	
CHECK	KL	DRAWN	FL		
JOB NO.		DRAWING	No. Rev		
	MA6030		2	1	

APPENDIX A SITE AUDIT SUMMARY

Bi- Weekly Site Inspection Record Summary

Inspection Information

This pection into the time	
Checklist Reference Number	90910
Date	10 September 2009 (Thursday)
Time	9:00 – 11:30

		Related
Ref. No.	Non-Compliance	Item No.
-	None identified	
		Related
Ref. No.	Remarks/Observations	Item No.
	A. Water Quality	
	No environmental deficiency was identified during site inspection.	
	B. Air Quality	
	No environmental deficiency was identified during site inspection.	
	C. Noise	
	No environmental deficiency was identified during site inspection.	
	D. Waste / Chemical Management	
	No environmental deficiency was identified during site inspection.	
	E. Ecology	
	No environmental deficiency was identified during site inspection.	
	F. Others	
	 All environmental deficiencies identified in previous audit session were improved/rectified by the Contractor except items (90827-R02-R04). Follow-up action is needed for the outstanding items. 	

•	Reminders	Related Item No.
	The Contractor was reminded to implement the following preventive measures:	
	A. Water Quality	
90910-R01	Provide sand bag at the culvert at Shan Shek Wan.	B1
90910-R02	• Clear the construction waste, silt and debris in the culvert at near Stream 20 and 21, SD7-13, SD6-12, SD5-11 and SD4-7.	В8
	B. Waste / Chemical Management	
90910-R02	• Clear the construction waste, silt and debris in the culvert at near Stream 20 and 21, SD7-13, SD6-12, SD5-11 and SD4-7.	E4ii.
90910-R03	• Clear remaining C&D waste and general refuse at Stream 22, 34, 37 and 38.	Eliii. and E4ii.
	C. Ecology	
90910-R03	• Clear remaining C&D waste and general refuse at Stream 22, 34, 37 and 38.	F1

Bi- Weekly Site Inspection Record Summary

Ref. No.	Proposed Completion Date	Completion Date	Remarks
90827-O01			
90827-R05	10 September 2009	10 September 2009	Rectified
90910-R01			
90910-R02	24 September 2009		Follow Up Required
90910-R03			

	Name	Signature	Date
Recorded by	Ivy Tam	Zux	10 September 2009
Checked by	Dr. Priscilla Choy	WI	10 September 2009

Bi-Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	90924	
Date	24 September 2009 (Thursday)	
Time	13:00 – 15:30	

		Related
Ref. No.	Non-Compliance	Item No.
-	None identified	-
		Related
Ref. No.	Remarks/Observations	Item No.
	A. Water Quality	
	No environmental deficiency was identified during site inspection.	
	B. Air Quality	
	No environmental deficiency was identified during site inspection.	
	C. Noise	
	No environmental deficiency was identified during site inspection.	
	D. Waste / Chemical Management	
	No environmental deficiency was identified during site inspection.	
	E. Ecology	
	No environmental deficiency was identified during site inspection.	
	F. Others	
	 All environmental deficiencies identified in previous audit session were not improved/rectified by the Contractor. Follow-up action is needed for the outstanding items. 	

•	Reminders	Related Item No.
	The Contractor was reminded to implement the following preventive measures:	
	A. Water Quality	
90924-R01	Provide sand bag at the culvert at Shan Shek Wan.	B1
90924-R02	• Properly remove the construction materials at the U-Channel and culvert at near Stream 22 and 21.	В1
90924-R03	• Clear remaining C&D waste, silt and debris in the culvert at near Stream 20 and 21, SD7-13, SD6-12, SD5-11 and SD4-7.	В8
	B. Waste / Chemical Management	
90924-R03	• Clear remaining C&D waste, silt and debris in the culvert at near Stream 20 and 21, SD7-13, SD6-12, SD5-11 and SD4-7.	E4ii.
90924-R04	Clear remaining C&D waste at Stream 22, 34, 37 and 38.	E4ii.
	C. Ecology	
90924-R04	Clear remaining C&D waste at Stream 22, 34, 37 and 38.	F1

1

Bi-Weekly Site Inspection Record Summary

Ref. No.	Proposed Completion Date	Completion Date	Remarks
90924-R01			
90924-R02	9 Octobou 2000		Follow Up Required
90924-R03	8 October 2009		
90924-R04			

7v~	24 September 2009
//* X	
WiL	24 September 2009
-	WIL

APPENDIX B ENVIRONMENTAL MITIGATION IMPLEMENTATION SCHEDULE (EMIS)

Appendix B - Summary of Environmental Mitigation Implementation Schedule

Types of Impacts	Mitigation Measures	Status
	A stockpile of dusty materials should not extend beyond the pedestrian barriers, fencing or traffic cones.	٨
	Vehicle washing facilities should be provided at every exit point.	*
	• The area where vehicle washing takes place and the section of the road between the washing facilities and the exit point should be paved with concrete, bituminous materials or hardcores.	*
	• Where a site boundary adjoins a road, street, service lane or other area accessible to the public, hoarding of not less than 2.4m high from ground level should be provided along the entire length of that portion of the site boundary except for a site entrance or exit.	N/A
	 Every main haul road should be sprayed with water or a dust suppression chemical so as to maintain the entire road surface wet. 	^
	• The portion of any road leading only to a construction site that is within 30m of a discernible or designated vehicle entrance or exit should be kept clear of dusty materials.	*
Construction Dust	• Any stockpile of dusty materials should be either covered entirely be impervious sheeting, placed in an area sheltered on the top and the 3 sides or sprayed with water or a dust suppression chemical so as to maintain the entire surface wet.	۸
	During cement debagging or concrete batching operation in an area sheltered on top and 3 sides.	*
	 All dusty materials should be sprayed with water or a dust suppression chemical immediately prior to any loading, unloading or transfer operation so as to maintain the dusty materials wet. 	*
	 Every vehicle should be washed to remove any dusty materials from its body and wheels immediately before leaving a construction site. 	*
	• The working area of any excavation should be sprayed with water or a dust suppression chemical immediately before, during and immediately after the operation so as to maintain the entire surface wet.	*
	 Proper enclosures and water spraying should be implemented for the main dust-generating activities, such as soil nailing or piling works. 	*
	 Proper plant maintenance should be provided to avoid black smoke emission from plants/equipment. 	^

Types of Impacts	Mitigation Measures	Status
	 Only well-maintained plant should be operated on –site and plant should be serviced regularly during the construction works. Machines and plant that may be in intermittent use should be shut down between work periods or should be throttled down to a minimum. 	^ ^
	 Plant know to emit noise strongly in one direction, should where possible, be orientated to direct noise away from the NSRS. Mobile plant should be sited as far away from NSRs as possible. 	^ ^
Construction Noise	 Material stockpiles and other structures should be effectively utilised, where practicable, to screen noise from on-site construction activities. 	
	Use quite plant and Working Method	^
	 Reduce the number of plant operating in critical areas close NSRs. Construct temporary and movable noise barriers 	N/A
	Construction Runoff and Drainage	
	• Discharges to natural water courses shall only take place when the effluent can be shown to comply with the standards specified in the Technical Memorandum, Standards for Effluents Discharged in to Drainage and Sewerage Systems, Inland and Coastal Waters. Discharges in the water gathering grounds should meet Group A standard for inland waters.	*
	Use of sediment traps and the adequate maintenance of drainage systems to prevent flooding and overflow.	*
Water Quality	 Boundaries of critical areas of earthworks should be marked and surrounded by dykes or embankments for flood protection. Temporary ditches should be provided to facilities runoff discharge into the appropriate watercourses, via a silt retention pond. Permanent drainage channels should incorporate sediment basins or traps and baffles to enhance deposition rates. 	^
	 All temporary and permanent drainage pipes and culverts provided to facilitate runoff discharge should be adequately designed for the controlled release of storm flows. All sediment traps should be regularly cleaned and maintained. The temporarily diverted drainage should be reinstated to its original condition when the construction works has finished or the temporary diversion is no longer required 	*
	• Sand silt in the wash water from the wheel washing facilities, which ensure no earth, mud and debris is deposited on roads, should be settled out the removed before discharging into storm drains. A section of the road between the wheel washing bay and the public road should be paved with backfill to prevent wash water or other site runoff form entering public road drains.	٨
	• Oil interceptors should be provided in the drainage system and regularly emptied to prevent the release of oils and grease into the storm water drainage system after accidental spillage. The interceptor should have a bypass to prevent flushing during periods of heavy rain.	N/A
	 Catchpits and perimeter channels shall be constructed in advance of site formation works and earthworks. 	^
	• Silt removal facilities, channels and manholes shall be suitably maintained with the deposited silt and grit being removed at least once a week, and at the onset of and after each rainstorm to ensure that these facilities are functioning properly at all times.	*

Types of Impacts	Mitigation Measures	Status
	• Earthworks final surfaces shall be well compacted and the subsequent permanent work or surface protection shall be carried out immediately after the final surfaces are formed to prevent erosion caused by rainstorms. Appropriate intercepting channels shall be provided along the site boundary or at the locations agreed with the ET Leader. Rainwater pumped out from trenches or foundation excavations shall be discharged into silt removal facilities before discharge into storm drains.	*
	• All generators, fuel and oil storage shall be within bunded areas. Drainage from the areas shall be connected to storm drains via a petrol interceptor.	*
	Tunnelling Work	
	• Temporary open storage of excavated materials should be covered with tarpaulin or similar fabric during rainstorms. Any washout of construction or excavated materials form the drill and blast tunnelling work should be diverted to the drainage system via appropriate sediment traps.	N/A
	Ground water pumped out of tunnels should be discharged into the drainage channels which incorporated sediment traps to enhance deposition rates and to remove silt.	N/A
	• Spend grouts used in diaphragm wall construction should be collected in a separate slurry collection system, reconditioned and reused wherever practicable. The disposal of used grouting materials will only be permitted if it is treated to the TM standards before discharge to the storm drains or disposal to landfill.	N/A
	General Construction Activities	
	• Debris and rubbish on site should be collected, handled and disposed of properly to avoid entering the water column and cause water quality impacts.	*
	• All fuel tanks and storage areas will be provided with locks and be located on sealed areas (within bunds of a capacity equal to 110% of the storage capacity of the largest tank or 20% by volume of the fuel stored in that areas, whichever in the greatest).	٨
	Sewage Effluent	
	• Construction work force sewage discharges form fixed toilet facilities on-site should be connected to the nearby existing trunk sewer wherever feasible. However, for areas where existing trunk sewer is not available, it is recommended that appropriate and adequate on site portable chemical toilets should be provided by a licensed contractor who will be responsible for appropriate disposal and maintenance of these facilities.	٨
	• It is considered that sewage discharges could also be treated by on-site septic tanks and soakaway. Minimum clearance away form streams and catchments and other requirements for the proposed septic tank and soakaway should be referred to EPD's Practice Note for Professional Persons, Drainage Plans.	
		N/A

Types of Impacts	Mitigation Measures	Status			
	General	•			
	 Training and instruction shall be given at a site to construction staff to increase awareness and draw attention to waste management issues and the need to minimise waste generation. The training requirement shall be included in the site waste management plan. 	٨			
	Storage, Collection and Transportation of Waste				
	Wastes shall be handled and stored in a manner to ensure that they are held securely without loss or leakage.	*			
	 Authorised or licensed waste hauliers shall be used and they shall only collect wastes prescribed by their permits. 	^			
	Waste shall be removed on a daily basis.	*			
	Waste storage area shall be maintained and cleaned on a daily basis.	*			
	 Windblown litter and dust during transportation shall be minimised by either covering trucks or transporting wastes in enclosed containers. 	٨			
	Obtain necessary waste disposal permits from the appropriate authorities if they are required.	^			
	Wastes shall be disposed of at licensed waste disposal facilities.	^			
	• Develop procedure such as ticketing system to facilitate tracking of loads, particularly for chemical waste, and to ensure that illegal disposal of wastes does not occur.	^			
Waste / Chemical	 Maintain records of the quantities of wastes generated, recycled and disposed. 	^			
Chemicai	Surplus Excavated Materials				
	Due to the high risk of loose material being washed into the existing nullah, stockpile materials should be properly compacted and covered from water erosion and located at least 10m away from the nullah wall.	٨			
	Construction and Demolition (C&D) Waste				
	 Careful design, planning and good site management shall be adopted to minimise over-ordering and generation of waste materials such as concrete grouts. 	*			
	• The handling and disposal of bentonite slurries shall be undertaken in accordance with Practice Note for Professional Persons – Construction Site Drainage (ProPECC PN 1/94) on construction site drainage.	N/A			
	• Construction and demolition (C&D) material shall be segregated to inert and non-inert parts. The inert portion shall re-used at areas of reclamation or land formation, or to public filling area shall such allocation is deemed necessary. The non-inert portion shall be disposed of to landfill.	*			
	Chemical Waste				
	 Chemical waste that is produce during construction shall be handled in accordance with the Code of Practice on the Packaging, Handling and Storage of Chemical Wastes. 	٨			

Types of Impacts	Mitigation Measures	Status
_	 Containers used for the storage of chemical wastes should: a. Be suitable for the substance they are holding, resistant to corrosion, maintained in a good condition, and securely closed; b. Have a capacity of less than 450 litres unless the specifications have been approved by the EPD; c. Display a label in English and Chinese in accordance with instructions prescribed in Schedule 2 of the Chemical Waste Regulations. 	^
	 The storage area for chemical wastes should: a. Be clearly labelled and used solely for the storage of chemical waste; b. Be enclosed on at least 3 sides; c. Have an impermeable floor and bunding of capacity to accommodate 110% of the volume of the largest container or 20% by volume of the chemical waste stored in the area, whichever is largest; d. Have adequate ventilation; 	۸
	 e. Be covered to prevent rainfall entering (water collected within the bund must be tested and disposed as chemical waste if necessary); f. Be arranged so that incompatible materials are adequately separated. 	
	 Disposal of chemical waste shall be via a licensed waste collector; and to a facility licensed to receive chemical waste; or a reuser of the waste (under approval from EPD). 	^
	General Refuse	
	 General refuse generated on-site shall be stored in enclosed bins or compaction unit separate from C&D and chemical wastes. A reputable waste collector shall be employed by the contractor to remove general refuse from the site, separately from C&D and chemical wastes, on a daily for every second day basis to minimise odour, pest and litter impacts. The burning of refuse on construction sites is prohibited by law. 	*
	 Reusable rather than disposable dishware shall be used if feasible. 	^
	Oil and Fuel	
	• The storage area for chemical wastes should have an impermeable floor and bunding of capacity to accommodate 110% of the volume of the largest container;	^
	 No storage of oil or fuel should be stored within the Country Park or the water gathering ground. 	٨
	 Refinement of the route alignment and design of associated structures to minimise loss of woodland and other landscape resources; 	^
Landscape	 Minimising working areas as far as possible; 	^
and Visual	 Protection and retention of existing vegetation where possible;. 	^
Impact	Transplanting of trees where appropriate	^
	 Protection and retention of existing natural rocky outcrops, slope profiles, vegetation, landscape features; 	^
	 Advance planting and visual screening, where possible; 	٨

Mitigation Measures	Status
Compensatory planting;	٨
• Sensitively designed site hoarding, where possible (ie the sensitive design of site hoarding will be disrupted by hoarding panels showing the Highways Department logo, at regular intervals as per the approved engineering design); and	^
 Grassing and woodland planting of soil slopes and disturbed areas 	٨
Construction activities in the stream and other disturbances to it should be avoided.	*
_	 Compensatory planting; Sensitively designed site hoarding, where possible (ie the sensitive design of site hoarding will be disrupted by hoarding panels showing the Highways Department logo, at regular intervals as per the approved engineering design);and Grassing and woodland planting of soil slopes and disturbed areas

Remarks: ^ Compliance of mitigation measure; N/A Not Applicable; * Recommendation was made during site at but improved/rectified by the contractor.	X • dit #	Non-compliance of mitigation measure; Non-compliance but rectified by the contractor; Non-compliance but rectified/improved by the contractor and awaiting IEC's further comment;
--	-----------	--

APPENDIX C COMPLAINT LOGS

Appendix C - Complaint Log

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S63	Tung Chung Road and Cheung Sha Stream	14 Sep 06	The complaint, which was lodged by Green Lantau Association on 13th September 2006, accused the failure of the site drainage system to check the discharge of silt-laden surface water from the site on that day.	ETL is of the view that the complaint is justifiable but the accusation is not substantiated by scientific data in that the rainstorm event was 1 in 25 years. It is therefore beyond the Contractor's terms of contract to design, operate and maintain the carrier pipe and the sedimentation tank to cater for this rainstorm. The Contractor has a defendable case under this increment weather condition.	Closed
S65-S69	Tung Chung Road Southern Section; Cheung Sha Stream;	19 Sep 06	Five complaints, which were lodged by Green Lantau Association on 15th September 2006, accused the failure of the drainage system for the Project on 13th September 2006. The subject of complaints are listed as below: (i) Failed Filtration System (ii) Contaminated Stream (iii) Polluted Cheung Sha Stream (iv) Polluted Cheung Sha Stream (v) Site Debris on Road	ETL is of the view that the complaints are justifiable but the accusation is not substantiated by scientific data in that the rainstorm event was 1 in 25 years. It is therefore beyond the Contractor's terms of contract to design, operate and maintain the carrier pipe and the sedimentation tank to cater for this rainstorm. The Contractor has a defendable case under this increment weather condition.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S71	Northern Section, Tung Chung Road	3 Nov 06	The complaint, which was referred by Resident Site Staff (RSS) to ET on 3 rd November 2006, was raised by a resident living Lantau Island on 17 th October 2006 concerning the Tung Chung Road condition on 16 th October 2006.	Based on the meteorological data extracted from HKO, the total rainfall between 0:45 and 6:45 hours in Lantau was 196 mm with an average intensity of 32.67 mm/hr on 16 th October. Based on the results derived from Table 2 "the Intensity-Duration-Frequency (IDF) for various return periods" and Table 4 "Depth-Duration-Frequency (DDF) for durations of than 4 hours" of the "Stormwater Drainage Manual", the return period should be less than 1 in 10 years. Therefore, the complaint was considered justifiable since the EIA report has recommended the provision of site drainage system shall be 1 in 10 years. The Contractor has implemented remedial measures and preventive measures.	Closed
S72	Lung Tseng Tau Village, Tung Chung	3 Nov 06	The public complaint, which was referred by RSS to ET on 3 rd November 2006, was received by the Integrated Complaint Centre (ICC) on 26 th October 2006 regarding dust nuisance generated from the Project.	Based on the information collected and the monitoring results, the complaint was considered not justifiable due to the following since no exceedance of the air quality monitoring results was recorded in October 2006. During site inspections in the month, dust mitigation measures have been implemented by the Contractor; and no observation was recorded during the site inspections. According to the information provided by the Contractor and the RSS, the Contractor has implemented additional mitigation measures, including increased water spraying on the public road to more than once a day and covered the stockpiling materials.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S73	Southern Section of the Project	3 Nov 06	The complaint, which was referred by RSS to ET on 3 rd November 2006, was raised by a resident living at Cheung Sha on 24 th October 2006 concerning noise generated from rock breaking in Southern Section of the Project.	According to the EM&A records, no exceedance of noise level and no non-compliance were recorded in the month. As advised by the Contractor and RSS, silent rock breaking equipment has been used and noise insulation materials have been used to minimize the noise impact generated from the rock breaking activity. Based on the provided information and the monitoring results, the complaints are considered not justifiable. The Contractor has implemented the mitigation measures to minimize the noise generation from construction activities and was still reminded to continuously implement their practice to prevent noise nuisance generation from the construction works.	Closed
S74	Tung Chung Stream	24 Nov 06	Highways Department (HyD) of HKSAR received a complaint for Agriculture, Fisheries and Conservation (AFCD) regarding untreated site runoff discharged to Tung Chung Stream during the site visit on 21 st November 2006. The Resident Site Staff (RSS) subsequently referred the complaint to the Environmental Team (ET) Leader of the Project on 24 th November 2006.	The investigation revealed that, based on the meteorological data extracted from HKO, the highest rainfall recorded was between 13:45 and 15:45, with a total of 93mm in two hours. With the above rainfall intensities extracted from HKO, together with the Intensity-Duration-Frequency (IDF) for various return periods derived from Table 2 of the "Stormwater Drainage Manual", the return period should be less than 10 years. Therefore, the complaint was considered justifiable and the Contractor has implemented remedial measures and preventive measures.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S75	West of the new Tung Chung Road Southern Section Discharge Point	21 Nov 06	Both Environmental Protection Department (EPD) and China Civil Engineering Construction Corporation and China Railway Wuju Joint Venture (the Contractor) received the same public complaint, regarding muddy water discharged to Chueng Sha on 21st November 2006. The Contractor subsequently referred the complaint to the Environmental Team (ET) Leader of the Project on the same day.	The complainant considered that this stream was muddy and discharging muddy water into the sea. As stated in the above paragraph, the investigation revealed that the return period for the rainfall between 13:45 and 15:45 was 41 years. As the complaint was lodged at 14:58 on 21 st November 2006, it is reasonable to consider the rainfall recorded in the hour between 13:45 to 14:45 which was 57mm. According to "Stormwater Drainage Manual", the return period should be less than 10 years. Therefore, the complaint was considered justifiable and the Contractor has implemented remedial measures and preventive measures.	Closed
\$76	Pui O Wan	27 Nov 06	China Civil Engineering Construction Corporation and China Railway Wuju Joint Venture (the Contractor) received the same public complaint, regarding muddy water discharged into Pui O Wan on 23 rd November 2006. According to the complainant, muddy water was discharged into Pui O Wan from the new Tung Chung Road Southern Section Discharge Point (near proposed round about on South Lantau Road) in the morning of 23 rd November 2006. The complainant suspected that the muddy water was being pumped off site through failed filtration systems into the sea as there had been no recent rainfall on that day.	The investigation revealed that the complaint was considered not justifiable since (1) no muddy water was generated due to the construction activities in the vicinity of the discharged point; and (2) no surface runoff as no rainfall was recorded on 23 rd November 2006.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S77	Sheung Ling Pei, Ha Ling Pei, Wong Ka Wai & Lung Tseng Tau Villages	18 Dec 06	Highways Department (HyD) and the Resident Engineer received a complaint against Water Quality Supply (Muddy Water) at Sheung Ling Pei, Ha Ling Pei, Wong Ka Wai & Lung Tseng Tau Villages via District Office (Islands) on 29 th November 2006. The complainants claimed that subject villages were suffering from muddy water supplied from the water main on the past few days before 29 th November 2006.	Upon receipt of the complaint, the Contractor inspected all streams (above AFCD entrance) in the Northern Section. Muddy water was observed at Stream 13 which was believed the source of muddy water. However, no water flow was found at the stream. The muddy water was considered probably due to the seepage of underground water mixed with excavated soil to Stream 13. Furthermore, an ad-hoc meeting between DO/WSD/AFCD/MOTT/CCJV/IEC/ET was held on 14 December 2006 to discuss this issue. The complaint was considered due to the construction activities of the Project. Emergency remedial works had been taken by the Contractor to rectify the situation and preventive measures had also been implemented.	Closed
S80	Tung Chung Road near Lung Tseng Tau Village	3 Jan 07	The complaint was lodged by a resident at Lung Tseng Tau Village regarding dust nuisance at Tung Chung Road near Lung Tseng Tau Village. According to the complainant, the dust was generated by vehicle movements (about 5 to 7 per day). The complainant noticed that there was only once per day for water spraying on the road. She suggested that the frequency of water spraying should be increased to 1 to 2 per hour. In addition, she requested to provide more water-spraying practice for the concerned area.	According to the Contractor and the RSS, the main dust emission in the vicinity of Lung Tseng Tau Village was due to the vehicle movements on Tung Chung Road. Base on the information collected and the monitoring results, the complaint was considered not justifiable since (1) no exceedance of the air quality monitoring results was recorded in December 2006; (2) dust mitigation measures have been implemented by the Contractor; and (3) no observation was recorded during the site inspections. In response to the complaint, the Contractor had stepped up the dust suppression control immediately. A water truck was mobilized to spray water at Tung Chung Road within particular in the vicinity of the complainant's house from once per day to at least 3 times per day.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S81	Lung Tseng Tau	20 Dec 06	The Contractor, CCECC and CRWJ Joint Venture (CCJV) and Highways Department (HyD) of HKSAR received a complaint regarding dust control at Lung Tseng Tau from the Office of Islands District Councilor, Wong Fukkan on 6 th December 2006. According to the complainant, he had received a number of complaints from residents in South Lantau regarding the dust nuisance when their vehicles passing through Tung Chung Road near Lung Tseng Tau. The residents said their vehicles were full of dust whenever they had passed through Tung Chung Road.	Base on the site inspection records and information collected from the RSS and the Contractor, the complaint was considered due to due to the vehicle movements on Tung Chung Road. In response to the complaint, the RSS has conducted site inspection in the afternoon on 18 th December 2006. The Contractor had immediately mobilized labors to clear the mud trail on Tung Chung Road between ch.3700-4000 using sweepers. In order to maintain the condition of Tung Chung Road, the Contractor has mobilized more staff to clear the mud deposits on the whole Northern Section of Tung Chung Road on 23 rd December 2006. The Contractor has provision wheel washing facilities at each site exit/entrance. In order to maintain Tung Chung Road condition, the Contractor has mobilized a water truck solely for wheel washing purpose at the site entrance near RW37 between ch.3700-4000 since 23 rd December 2006. The location is the most busy site exit/entrance for soil removal as wheel washing facilities. Wheels of each vehicle shall be washed before leaving the site. The wastewater after wheel washing at each site exit/entrance shall be collected and treated before discharge at designated location. also mobilized water trucks	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S82	The nullah near the Yat Tung Estate	15 Jan 07	The complaint was lodged by the Legislative Councillor Hon. Albert W.Y. Chan regarding frequent discharge of muddy water from the Tung Chung Road improvement project on 15 th December 2006. According to Mr. Chan's letter, the complainant was a resident living in Tung Chung. The DSD letter pointed out that muddy water was being frequently discharged to the nullah near the Yat Tung Estate, and confirmed that the site of Tung Chung Road improvement project was the source of such discharge.	After investigation, the discharge of muddy water was largely due to the deposited silts caused by previous heavy rainstorms in November. The contractor has responded promptly in deploying a number of actions to remedy the matter. These include de-silting operation at Wong Lung Hang nullah on 23 rd December 2006 to remove the accumulated soil and silt materials washed down by the discharges, of which photographs are provided. In addition, several intermediate sedimentation ponds along the temporary drainage system south of Shek Mun Kap to improve de-silting capacity have been installed, and that the site condition will be closely monitored so that advice on any practical measures in improving the quality of water discharge to Wong Lung Hang nullah can be given. In addition, the Contractor is also undergoing continual inspections and monitoring on the conditions of the concerned discharge of the construction site, and is in close liaison with the ET to cap exceeding levels of future discharge.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S86	Slope opposite to the AFCD's Office at Tung Chung Road near mileage M2.5	8 Feb 07	The complaint was lodged by a resident in Lantau Island regarding the construction noise generated from the road works at the slope opposite to the AFCD's Office at Tung Chung Road near mileage M2.5.	The site of concern is most likely at the RW6 of the Project. According to the Contractor, soil nailing works was conducted at RW6 and the first stage of soil nailing works at RW6 has been completed before 8th February 2007. According to the noise monitoring results at monitoring station NM5, Tung Chung Au Country Parks Management Centre, which is located near the AFCD's Office, there was no exceedance recorded from 2nd January to 14th February 2007. As advised by the Contractor, the following mitigation measures will be implemented as far as possible to reduce the noise nuisance to the nearby residents when soil nailing works carry out in the future: To cover the soil nailing works area with tarpaulin; To reduce the number of machines for soil nailing; To orientate the machines for soil nailing works so that the major noise generating part will not directly face the Noise Sensitive Receiver; and To scatter the plants so that the noise being generated will not be centralized in certain direction.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S90	Northern and Southern Section of Tung Chung Road	20 May 07	The complaint was lodged by the Green Lantau Association at on 20 May 2007 regarding failed drainage for the Project on that day.	According to the Contractor, the main concern in the Northern Section is that a large amount of seepage from the permanent slope near the Stream 18 and Stream 21 was observed. The permanent hinterland u-channel was not able to collect most of the hinterland water which ultimately collected by the carrier pipe and increased the loading of the treatment facilities at Shek Mun Kap. As advised by the Contractor, the main problem in Southern Section was due to the fact that the silt is too fine to be settled within a short time, i.e. 3 minutes, as stated in the EIA Report. Due to the large catchments of the site, muddy water could not be completely settled or treated before discharged or overflowed. No bigger sedimentation tank can be constructed due to the site constraint to retain all surface water in heavy rainy days. The complaint was considered justifiable. However, it is beyond the Contractor's capability to completely avoid muddy water discharging or overflowing to sea due to the site conditions and constraints under increment weather conditions.	The complaint investigation report was commented

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S91	Zone 4 (STR 14)	1 June 07	The complaint was lodged by a resident in Butterfly Crest, Lantau Island regarding the construction noise generated from the Project on Sunday, which is likely to be 27 th May 2007.	According to the Contractor, construction works were undertaken near STR 14 in the morning of 27th May 2007 and the Powered Mechanical Equipment (PME) used on that day included 2 excavators and 1 dump truck at STR 14. The concerned site was covered under the construction noise permit (CNP) no. GW-RS0281-07. As advised by the Contractor, the 2 excavators and 1 dump truck, which categorized separately as Group A and Group E of the abovementioned CNP, were utilized alternatively during the operation in order to comply with the conditions stipulated in the CNP. Base on the information collected, the complaint was considered not justifiable as the equipment used comply with the CNP conditions.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S93	Western Section of Pui O Bay	22 May 07	The complaint was lodged by the Green Lantau Association at on 22 May 2007 regarding muddy water was observed at 50m west of the Tung Chung Road southern section around 11am on 22 May 2007.	As advised by the Contractor, the main problem in Southern Section was due to the fact that the silt is too fine to be settled within a short time, i.e. 3 minutes, as stated in the EIA Report. Due to the large catchments of the site, muddy water could not be completely settled or treated before discharged or overflowed. No bigger sedimentation tank can be constructed due to the site constraint to retain all surface water in heavy rainy days. In the site near Pui O Wan, the Contractor has exhausted their efforts including to pump the water from sedimentation tanks back to the stockpile area. Unfortunately, one of the pumps was out of order in the early days of that rainy period. However, the pump has been rectified on 22 May 2007. The complaint was considered justifiable. However, it is beyond the Contractor's capability to completely avoid muddy water discharging or overflowing to sea due to the site conditions and constraints under increment weather conditions.	The complaint investigation report was commented

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S100	Stream water behind WSD's weir	Date 27 July 07	The complaint was lodged by a resident living at Lung Tseng Tau area during the meeting between RSS and the representatives from the villages at Lung Tseng Tau area on 17 th July 2007 regarding turbid water supply from DO main to the village houses at Lung Tseng Tau area.	The RSS and the Contractor had a site investigation with the complainant at his household water supply, the WSD weir and a work area immediately upstream of the weir (STR02 near the Stream 12) on the same day. It was observed that the water directly from the household supply was found with low degree of turbidity when comparing it with portable water supply. According to the visual inspection of the RSS and the Contractor, the stream water behind the WSD's weir, which is the source of water supply to the villagers via a DO main, was found clear and there was no sign of contamination. Inspection of the work site at STR02 upstream of the weir indicated no activities affecting the upstream water quality. By reviewing the water quality monitoring data at Tung Chung Stream during early of July 2007, the turbidity and SS values are considered to be low and the data revealed that the Tung Chung Stream and the WSD weir were not contaminated during the above mentioned period. Nevertheless, In order to minimize the water quality impacts, the Contractor has implemented following mitigation measures:	Closed
			Nevertheless, In order to minimize the water quality impacts, the Contractor has		

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S104	Tung Chung Road and Tung Chung Au near AFCD's Office	Date 6 August 07	The complaint was lodged by Mr. Ho on 6 th August 2007 regarding a suspected case of silty runoff and muddy water generated from construction site flowing on public road. Turbid water was observed behind the weir near the AFCD's office at Tung Chung Au.	5 0	Closed
			According to the RSS and the Contractor, no further report of silt and muddy water runoff from concerned area was received after implementation of the aforesaid mitigation measures.		

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S113	Upper and Lower Cheung Sha Village		The complaint was lodged by Mr. Liu on 12 December 2007 regarding dust nuisance at Upper and Lower Cheung Sha Village.	According to the Contractor, the main dust emission in the vicinity of Cheung Sha Village was due to the road works and associated vehicle movements on Tung Chung Road. The Contractor has implemented following mitigation measures: • Cleared the silts on the haul road; • Applied watering on the road by water hose at San Shek Wan; • Increased the number of water browsers; and • Covered the exposed slope and stockpiles with tarpaulin sheets. By reviewing the air quality monitoring data, there was no exceedance of air quality monitoring results on 8 th and 14 th December 2007 and dust mitigation measures have been implemented by the Contractor. According to the RSS and the Contractor, no	Closed
			there was no exceedance of air quality monitoring results on 8 th and 14 th December 2007 and dust mitigation measures have been implemented by the Contractor.		

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S147	Zone 1 Tung Chung Road	14 November 2008	The complaint was referred to ETL from EPD by Mr. Peter Tang on 14 November 2008, regarding a suspected case about land-filling of non-inert construction waste in early 2008 and potential further land-filling of non- inert construction waste stockpiled at Zone 1 Tung Chung Road.	According to the Contractor, there are two major stockpile areas within the construction premise which are located at San Shek Wan and Tung Chung Road. The location specified in the complaint was the stockpile area at San Shek Wan. This location was used for stockpiling reusable materials. Base on the information collected, the complaint was considered not justifiable as San Shek Wan is one of the designated C&D materials sorting areas of the Project and no direct evidence shows there was land-filling activity by this project at the specified location. However, as a follow up of the complaint, the Contractor has implemented mitigation measures as follows: Preliminary segregation of waste was enhanced; and Water was sprayed on the stockpiles more frequently to further suppress dust generation. The Contractor was recommended to continue the following mitigation measures: To provide dust suppression measures to the stockpiles at San Shek Wan, especially during dry season, to minimize dust generation; To carry out continuous segregation of materials on site; To avoid accumulation of stockpiles; and To dispose of non-reusable material to designated outlets as soon as possible.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
	Zone 1 Tung Chung Road	April 2009 April	EPD received a public complaint about suspected land- filling of non-inert construction waste in early 2009 at Zone 1 of Tung Chung Road for the Project and a similar verbal complaint regarding illegal land filling of construction waste on the same site (Zone 1) was received from Lands Department.	Base on the information collected, the complaint was considered not justifiable as San Shek Wan is one of the designated C&D materials sorting areas of the Project and no direct evidence shows there was land-filling activity by this project at the specified location. Sorting and disposal of C&D materials were conducted in accordance with WMP.	
				Nevertheless, the Contractor was recommended to continue the following mitigation measures in order to minimize the environmental impact on the nearby community and the amount of waste produced:	Closed
				Stockpiled material shall be covered by tarpaulins and/or watered as appropriate to prevent windblown dust and/or surface run-off. Storage of material on site shall be kept to a minimum to avoid nuisance to local residents;	
				excavated material in trucks shall be covered by tarpaulins to reduce the potential for spillage and dust generation; and	
				good site practice shall be implemented to avoid waste generation and promote waste minimization.	

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
S157	New Tung Chung Road and near-by soil erosion in Cheung Sha Catchwater	1 st June 2009	The complaint was raised by the WSD on 1 st June 2009. WSD concerned about the soiled water had been collected from New Tung Chung Road and soil erosion was found at Cheung Sha Catchwater. The ETL of the Project was informed of the complaint by CCJV through the e-mail on 5 th June 2009 and initiated the complaint investigation procedures.	complaint was considered justifiable as heavy downpour of rain had caused soil erosion on exposed slopes leading to Cheung Sha Catchwater. The Contractor was recommended to take sufficient mitigation measures to minimize the exposed areas to rain by covering the	Closed

APPENDIX D SUMMARY OF WARNING / DIRECTION ISSUED BY THE EPD AND PROSECUTION

Appendix D - Summary of Warnings / Direction Issued by the EPD and Prosecution

Summary of Warnings / Direction Issued by the EPD

Date of Letter	Warnings/Direction
3 February 2005	The Contractor was requested to construct catch pits and perimeter channels in advance of site formation and earth works
17 May 2005	The Contractor was requested to immediately re-provide the on-site wastewater management systems to adequately cater the rainwater runoff and to submit the detail proposal for runoff management and treatment systems.
4 October 2005	The Contractor was requested to rectify the situation in order to comply with EP Conditions 2.4 & 2.5 regarding the provision of drainage systems, EP Condition 3.16 regarding site runoff mitigation measures and EP Condition 3.6 regarding no works of the Project shall be carried out outside the "limit of works area".
15 December 2005	The Contractor was requested to rectify the situation of Zone D where fuel oil was found spilled onto ground of the works area in contravention to Section 7.5.2.1 of the Waste Management Plan (WMP). The Section stipulates provisions against spillage of fuels to prevent contamination of the construction site.
24 March 2006	The Contractor was requested to rectify the situation in order to comply with EP Condition 3.9 regarding the stipulated span of temporary bridges used during construction to cross the stream.
13 April 2006	The Contractor was requested to rectify the situation of Zone E where fuel oil was stored within the Country Park in contravention to condition 3.14 of the EP.
29 June 2006	The Contractor was requested to rectify the situation that site runoff will not be discharged into Tung Chung Stream in order to comply with EP Condition 2.4.
26 September 2006	The Contractor was requested to rectify the situation that excessive dust emission occurred. Watering programme shall maintain to ensure that all exposed road surfaces and dust sources are wet in order to comply with EP Condition 1.7.
4 October 2006	-The Contractor was requested to rectify the situation that site runoff will not be discharged into Tung Chung Stream in order to comply with EP Condition 2.4. -The Contractor was requested to rectify the situation in order to comply with EP Condition 3.9 regarding the stipulated span of temporary bridges used during construction to cross the stream 28 The Contractor was requested to rectify the situation in order to comply with EP Condition 3.9 regarding the stipulated span of temporary bridges used during construction to cross the stream 32. - The Contractor was requested to rectify the situation in order to comply with EP Condition 3.9 regarding the stipulated span of temporary bridges used during construction to cross the stream 33.
13 February 2007	The Contractor was requested to rectify the situation that site runoff will not be discharged into Tung Chung Stream in order to comply with EP Condition 2.4.
19 February 2008	The Contractor was requested to take all necessary actions to rectify the situation that surface run-off from the construction site discharged into storm drain without treatment in order to comply with EP Condition 3.16.
14 April 2008	The Contractor was required to take all necessary actions to rectify the situation

Date of Letter	Warnings/Direction		
	that a section of the site near Pak Kung Au was not provided with vehicle		
	washing facilities including high pressure water jet at vehicular exit points so as		
	not to contravene the statutory requirement.		
8 December 2008	The Contractor was required to take all necessary actions to rectify the situation		
	that a suspected chemical waste (mineral oil) was found improperly packed and		
	stored at Zone 1 Tung Chung Road on 4 December 2008, so as not to		
	contravene the statutory requirement of the Waste Disposal (Chemical Waste)		
	(General) Regulation (Cap. 354).		

Summary of Notification of Summons

Date of Summons	Details of the Summons	Status		
25 January 2007	Construction works at a slope next to Stream no. 28	Withdrawn by		
	along Tung Chung Road, Cheung Sha, Lantau Island	EPD		
	which contrary to EP Condition 3.9 concerning works at			
	Stream 28 on 26 July 2006			
16 February 2007	Construction works near Stream no. 8 along Tung Chung	The Contractor		
	Road, Cheung Sha, Lantau Island which contrary to EP	was fined \$7500		
	Condition 2.4 by discharging runoff during construction	on 4 June 2007.		
	into Tung Chung Stream on 16 August 2006			
17 May 2007	Construction works near Stream no. 8 along Tung Chung	The Contractor		
	Road, Cheung Sha, Lantau Island which contrary to EP	was fined \$7500		
	Condition 2.4 by discharging runoff during construction	on 4 June 2007.		
	into Tung Chung Stream on 21 November 2006			

Summary of Notification of Successful Prosecution

Date of Successful	Details of the Successful Prosecution	Status		
Prosecution				
4 June 2007	Construction works near Stream no. 8 along Tung Chung	The Contractor		
	Road, Cheung Sha, Lantau Island which contrary to EP	was fined \$7500		
	Condition 2.4 by discharging runoff during construction	ring construction on 4 June 2007		
	into Tung Chung Stream on 16 August 2006			
4 June 2007	Construction works near Stream no. 8 along Tung Chung	The Contractor		
	Road, Cheung Sha, Lantau Island which contrary to EP	was fined \$7500		
	Condition 2.4 by discharging runoff during construction	on 4 June 2007		
	into Tung Chung Stream on 21 November 2006			

APPENDIX E SITE AUDIT SCHEDULE

Contract No. HY/2003/19 - Improvement to Tung chung Road between Lung Tseng Tau and Cheung Sha Tentative Site Audit Schedule for September 2009

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
		1-Sep	2-Sep	3-Sep	4-Sep	5-Sep
	7.0	0.0	0.0	10.0	11.0	12.0
6-Sep	7-Sep	8-Sep	9-Sep	10-Sep	11-Sep	12-Sep
				Bi-weekly Site Audit		
				DI-weekly Site Audit		
13-Sep	14-Sep	15-Sep	16-Sep	17-Sep	18-Sep	19-Sep
10 50	1.50p	10 500	10 200	17 500	10 500	1, 500
20-Sep	21-Sep	22-Sep	23-Sep	24-Sep	25-Sep	26-Sep
				Bi-weekly Site Audit		
27 C	20.5	20.0	20.5			
27-Sep	28-Sep	29-Sep	30-Sep			

The schedule may be changed due to unforeseen circumstances (adverse weather, etc)

Contract No. HY/2003/19 - Improvement to Tung chung Road between Lung Tseng Tau and Cheung Sha Tentative Site Audit Schedule for October 2009

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
				1-Oct	2-Oct	3-Oct
4-Oct	5-Oct	6-Oct	7-Oct	8-Oct	9-Oct	10-Oct
				Bi-weekly Site Audit		
11-Oct	12-Oct	13-Oct	14-Oct	15-Oct	16-Oct	17-Oct
18-Oct	19-Oct	20-Oct	21-Oct	22-Oct	23-Oct	24-Oct
10 00.	17 000	20 000	21 000	22 000	20 000	2.000
				Bi-weekly Site Audit		
25-Oct	26-Oct	27-Oct	28-Oct	29-Oct	30-Oct	31-Oct
25-001	20-001	27-001	28-001	29-001	30-001	31-001

The schedule may be changed due to unforeseen circumstances (adverse weather, etc)