

EM&A Environmental Inspection Record

Contract No.: GE/2005/45

LANDSLIDE PREVENTIVE WORKS AT PO SHAN, MID-LEVELS

DESIGN AND CONSTRUCTION (NATURAL TERRAIN RISK MITIGATION WORKS)

Site Inspection Summary

Inspection Information

Date:	5 May 2009
Time:	15:00
Inspection No.:	057

Non-compliance

Nil

Observations

Follow Up Observation

Nil

New Observation

1. Loose sediment was observed accumulated on the platform at Row AF. The Contractor was reminded to clear the sediment as soon as the soil nailing operation finishes.

Remarks

Nil

EM&A Environmental Inspection Record

Contract No.: GE/2005/45

LANDSLIDE PREVENTIVE WORKS AT PO SHAN, MID-LEVELS

DESIGN AND CONSTRUCTION (NATURAL TERRAIN RISK MITIGATION WORKS)

Site Inspection Summary

Inspection Information

Date:	12 May 2009
Time:	15:00
Inspection No.:	058

Non-compliance

Nil

Observations

Follow Up Observation

1. Loose sediment was still observed accumulated on the platform and on the slope at Row AF. The Contractor was reminded to clear the sediment more frequently.

New Observation

2. A chemical container was observed placed on ground without drip tray at Row AH. The Contractor was reminded to provide drip trays to all chemicals on site.

Remarks

Nil

EM&A Environmental Inspection Record

Contract No.: GE/2005/45

LANDSLIDE PREVENTIVE WORKS AT PO SHAN, MID-LEVELS

DESIGN AND CONSTRUCTION (NATURAL TERRAIN RISK MITIGATION WORKS)

Site Inspection Summary

Inspection Information

Date:	19 May 2009
Time:	15:00
Inspection No.:	059

Non-compliance

Nil

Observations

Follow Up Observations

1. The chemical containers at Row AH had been provided with drip tray. (Closed)
2. Loose sediment was still observed accumulated on the platform and on the slope at Row AF. The Contractor was reminded to clear the sediment more frequently.

New Observations

3. A hole was found on the drip tray at Row AA and oily water was running out. The Contractor was requested to fix the drip tray as soon as possible.
4. Cement powder was observed scattered on the platform at Row AH. While immediate action by Contractor to clear the cement powder into sand bags, the Contractor was still reminded to properly handle all chemicals on site.

Remarks

Nil

EM&A Environmental Inspection Record

Contract No.: GE/2005/45

LANDSLIDE PREVENTIVE WORKS AT PO SHAN, MID-LEVELS

DESIGN AND CONSTRUCTION (NATURAL TERRAIN RISK MITIGATION WORKS)

Site Inspection Summary

Inspection Information

Date:	26 May 2009
Time:	15:00
Inspection No.:	060

Non-compliance

Nil

Observations

Follow Up Observations

1. Loose sediment at the platform of Row AF had been cleared. However, sediment was still observed accumulated on the slope under Row AF. The Contractor was reminded to clear the sediment more frequently.
2. Cement powder on the platform at Row AH had been cleared. (Closed)
3. Holes were still found on the drip tray of a soil nail controller at Row AA. The Contractor was requested to fix the drip tray as soon as possible.

New Observation

Nil

Remarks

Nil