

EM&A Environmental Inspection Record

Contract No.: GE/2005/45

LANDSLIDE PREVENTIVE WORKS AT PO SHAN, MID-LEVELS

DESIGN AND CONSTRUCTION (NATURAL TERRAIN RISK MITIGATION WORKS)

AECOM

Site Inspection Summary

Inspection Information

Date:	4 August 2009
Time:	15:00
Inspection No.:	070

Non-compliance

Nil

Observations

Follow Up Observation

1. Sediment and general refuse inside the u-channel at Row A and Row R had been cleared. (Closed)

New Observation

Nil

Remarks

Nil

EM&A Environmental Inspection Record

Contract No.: GE/2005/45

LANDSLIDE PREVENTIVE WORKS AT PO SHAN, MID-LEVELS

DESIGN AND CONSTRUCTION (NATURAL TERRAIN RISK MITIGATION WORKS)

AECOM

Site Inspection Summary

Inspection Information

Date:	11 August 2009
Time:	15:00
Inspection No.:	071

Non-compliance

Nil

Observations

Follow Up Observation

Nil.

New Observation

Nil.

Remarks

Nil

EM&A Environmental Inspection Record

Contract No.: GE/2005/45

LANDSLIDE PREVENTIVE WORKS AT PO SHAN, MID-LEVELS

DESIGN AND CONSTRUCTION (NATURAL TERRAIN RISK MITIGATION WORKS)

AECOM

Site Inspection Summary

Inspection Information

Date:	18 August 2009
Time:	15:00
Inspection No.:	072

Non-compliance

Nil

Observations

Follow Up Observation

Nil.

New Observation

1. Stagnant water was observed accumulated in a soil nail head at Row AA. The Contractor was reminded to clear the stagnant water.

Remarks

Nil

EM&A Environmental Inspection Record

Contract No.: GE/2005/45

LANDSLIDE PREVENTIVE WORKS AT PO SHAN, MID-LEVELS

DESIGN AND CONSTRUCTION (NATURAL TERRAIN RISK MITIGATION WORKS)

AECOM

Site Inspection Summary

Inspection Information

Date:	25 August 2009
Time:	15:00
Inspection No.:	073

Non-compliance

Nil

Observations

Follow Up Observation

1. Stagnant water in the soil nail head at Row AA had been cleared. (Closed)

New Observation

2. Leaves and debris were observed accumulated inside the u-channel at Row R. The Contractor was reminded to clear the u-channel more frequently.

Remarks

Nil