



Figure 7.4 - Downstream section of LMH01 - concrete-lined channel to be replaced by gabion lining.



Figure 7.5 - Existing concrete-lined bank of LMH01 to be replaced by gabion lining

ICP407D:REAL_JOB1382486_02011617.5_7_A4_CDR1NOV06



Drainage Services Department
渠務署



BLACK & VEATCH HONG KONG LIMITED
博威工程顧問有限公司