

Slope Stabilization



Existing conditions



Indicative photomontage showing overhanging block removed and rock dowels installed



Existing conditions



Indicative photomontage of view with rock dowel installed in drill holes formed into the rock face and filled with grout. No extruding steel bars will be exposed

Revision	Date	Description			Initial
		Designed	Checked	Drawn	
Initial					
Date					

Agreement No.
CE 21/2012 (WS)

Contract title
DESALINATION PLANT AT
TSEUNG KWAN O -
FEASIBILITY STUDY

Drawing title
ILLUSTRATIONS OF
POTENTIAL SLOPE
MITIGATION WORKS

Drawing no. FIGURE 11.13d	Revision
------------------------------	----------

Scale



BLACK & VEATCH HONG KONG LIMITED
博威工程顧問有限公司