


General Condition of Trees

The survey area is located within a degraded mixed woodland which is evidenced by the presence of large proportion of invasive species of *Leucaena leucocephala* and common pioneer species of *Macaranga tanarius*. Most of the trees are young in age. The average trunk diameter ranges 100mm-200mm while the average height ranges 6-9m. The overall health condition of the trees is fair in general.



Plate 3



General Condition of the Vegetation

The survey area (i.e. the proposed works area) was observed to be disturbed recently by vegetation clearance and hill fires. The overall health condition of the undisturbed vegetation is fair in general.

Revision	Date	Description			Initial
		Designed	Checked	Drawn	
Initial					
Date					

Agreement No. CE 21/2012 (WS)

Contract title
DESALINATION PLANT AT
TSEUNG KWAN O -
FEASIBILITY STUDY

Drawing title
VEGETATION SURVEY AND PHOTOGRAPHS
(SHEET 3 OF 10)

Drawing no. FIGURE 11.21c

Revision

Scale

 水務署
Water Supplies Department


BLACK & VEATCH HONG KONG LIMITED
博域工程顧問有限公司