

**General Condition of Trees**

The survey area is located within a degraded mixed woodland which is evidenced by the presence of large proportion of invasive species of *Leucaena leucocephala* and common pioneer species of *Macaranga tanarius*. Most of the trees are young in age. The average trunk diameter ranges 100mm-200mm while the average height ranges 6-9m. The overall health condition of the trees is fair in general.



Photo 17

**General Condition of the Vegetation**

The survey area (i.e. the proposed works area) was observed to be disturbed recently by vegetation clearance and hill fires. The overall health condition of the undisturbed vegetation is fair in general.

Revision	Date	Description			Initial
		Designed	Checked	Drawn	
Initial					
Date					

Agreement No. CE 21/2012 (WS)

Contract title  
**DESALINATION PLANT AT TSEUNG KWAN O - FEASIBILITY STUDY**

Drawing title  
VEGETATION SURVEY AND PHOTOGRAPHS (SHEET 10 OF 10)

Drawing no. **FIGURE 11.21j** Revision

Scale



BLACK & VEATCH HONG KONG LIMITED  
博威工程顧問有限公司