

# Slope Stabilization



Existing conditions



Indicative photomontage showing overhanging block removed and rock dowels installed



Existing conditions



Indicative photomontage of view with rock dowel installed in drill holes formed into the rock face and filled with grout. No extruding steel bars will be exposed

Revision	Date	Description			Initial
		Designed	Checked	Drawn	
Initial					
Date					

Agreement No.  
CE 21/2012 (WS)

Contract title  
DESALINATION PLANT AT  
TSEUNG KWAN O -  
FEASIBILITY STUDY

Drawing title  
ILLUSTRATIONS OF  
POTENTIAL SLOPE  
MITIGATION WORKS

Drawing no. FIGURE 3.3c (cont')	Revision
---------------------------------------	----------

Scale



BLACK & VEATCH HONG KONG LIMITED  
博威工程顧問有限公司