



APPENDIX 10A Built Heritage Catalogue

Ref: HB-01	Title: Village House	Category: Residential
Address: Nos. 126, 128 and 130 Cha Kwo Ling		Reference Plan:
Orientation: Southwest		Grading: Nil

The building is situated near the front of the village and there is a modern sitting out area directly in front. The surrounding buildings are mostly squatter structures.

Historical Appraisal:

The buildings from appearance would most likely date to the middle of the 20^{th} Century. The buildings are part of a substantial terrace row.

Associated Historical/ Cultural Events or Individual: None

Inscriptions: None

Architectural Appraisal:

The row of units would appear to date from the mid Twentieth Century. The many additions and repairs have given the row a rather ramshackle appearance.

Interior: Not Accessible

Existing Condition: Fair

Past and Present Uses: Residential.

Notes on modifications: The terrace row has been heavily modified by metal additions and repairs.



View of the Façade and Northwest Elevation of HB-01



Façade and Southwest Elevation of HB-01

Ref: HB-02	Title: Village House	Category: Residential
Address: Nos. 112 and 114 Cha Kwo Ling		Reference Plan:
Orientation: Southwest		Grading: Nil

Surrounding Environment: The buildings are situated near the front of the village with the majority of the buildings in the vicinity of squatter style.

Historical Appraisal:

The village house is one of the more substantial buildings in the village.

Associated Historical/ Cultural Events or Individual:

Inscriptions: None

Architectural Appraisal:

Central two storey terrace unit with pitched traditional style tile roof. The unit beside It also has a traditional style tile pitched roof, but a modern sliding gate has replaced the original façade. It's appearance has been heavily modified with repairs and additions.

Interior: Not Accessible

Existing Condition: Poor, the walls are being supported by struts.

Past and Present Uses: Residential

Notes on modifications: Modern windows and doors have been added. Mid terrace unit has large metal sliding gate across the façade. Heavily modified appearance.



Façade of HB-02



Northwest Elevation of HB-02



Upper Façade and roof of HB-02

Ref: HB-03	Title: Village House	Category: Residential
Address: No.102 Cha Kwo Ling		Reference Plan:
Orientation: Southwest		Grading: Nil

Surrounding Environment: Residential village houses.

Historical Appraisal:

One of the few remaining traditional style village houses in Cha Kwo Ling

Associated Historical/ Cultural Events or Individual: None

Inscriptions: None

Architectural Appraisal:

Terrace unit with render exterior wall covering. Some sections of wall reveal pounded earth and there are some traditional tiles on the edges of the roof.

Interior: Not Accessible

Existing Condition: Fair

Past and Present Uses: Residential

Notes on modifications: The building has been heavily modified with modern gate and roofing material.



Façade of HB-03



View of the Façade and section of roof of HB-03

Ref: HB-04	Title: Recycling Plant	Category: Industrial
Address: Cha Kwo Ling		Reference Plan:
Orientation: Southeast		Grading: Nil

The building along with HB-03 are in use as a recycling centre and the area is fitted as a depot along with processing facilities (such as compressors and packaging areas). The building along with HB-03 is set apart from the other village houses and there is a wooded hill at the back of the area.

Historical Appraisal:

According to local informants the buildings were formerly associated with the industrial works in the area, either as storehouses for kaolin mining or stone quarrying. The buildings have associations with the past economic and industrial aspects of Cha Kwo Ling.

Associated Historical/ Cultural Events or Individual: None

Inscriptions: None

Architectural Appraisal:


The building is of similar construction to CKL-03. It is set up against a hillside and there are many trees growing close to the structure. There are also piles of recycled materials stacked up against the structure making it difficult to get a good view of the building. It is a stone structure with cut granite blocks and buttresses.

Interior: Not Accessible

Existing Condition: Good

Past and Present Uses: Industrial

Notes on modifications: No visible modifications



View of the Southeast Corner of HB-04



View of HB-04 (Southwest Elevation)



Ref: HB-05	Title: Recycling Depot	Category: Industrial
Address: Cha Kwo Ling		Reference Plan:
Orientation: Southeast		Grading: Nil

The building along with HB-04 are in use as a recycling centre and the area is fitted as a depot along with processing facilities (such as compressors and packaging areas). The building along with HB-04 is set apart from the other village houses and there is a wooded hill at the back of the area.

Historical Appraisal:

According to local informants the buildings were formerly associated with the industrial works in the area, either as storehouses for kaolin mining or stone quarrying. The buildings have associations with the past economic and industrial aspects of Cha Kwo Ling.

Associated Historical/ Cultural Events or Individual: None

Inscriptions: None

Architectural Appraisal:

The building is of similar construction to CKL-03. It is set up against a hillside and there are many trees growing close to the structure. There are also piles of recycled materials stacked up against the structure making it difficult to get a good view of the building. It is a stone structure with cut granite blocks and buttresses.

Interior: Areas that could be seen showed large open areas with a loft that appeared to be in use for storage.

Existing Condition: Good

Past and Present Uses: Industrial

Notes on modifications: Roof has been replaced with corrugated metal sheets.



General View of HB-05 showing the Southwest and Southeast Elevations



View of the Southeast Elevation of HB-05



View of the Buttresses on the Southwest Wall of HB-05

Ref: HB-06	Title: Shrine	Category: Religious, Ritual and Funerary
Address: N/A		Reference Plan:
Orientation: Southwest		Grading: Nil

The shrine is situated at a corner of a building. The surrounding buildings are mostly squatter structures.

Historical Appraisal:

The shrine is associated with the village and may date to the original settlement.

Associated Historical/ Cultural Events or Individual: None

Inscriptions: None

Architectural Appraisal:

The shrine is constructed of metal sheets that have been set up around the corner of a building. Two of the walls are of the building and the other is metal sheeting. The Entrance has metal screens. Modern tile floor has been added.

Interior: A rectangular space with a small shrine in the back corner.

Existing Condition: Good

Past and Present Uses: Religious, Ritual and Funerary

Notes on modifications: None



View of the entrance of the shrine HB-06



Interior view the shrine HB-06

Ref: HB-07	Title: Village House	Category: Residential
Address: No. 63 & 64 Cha Kwo Ling		Reference Plan:
Orientation: Southwest		Grading: Nil

The building is situated at the back central section of the village. There is a mixture of other more substantial and squatter style buildings in the vicinity.

Historical Appraisal:

The building was one of the larger residential buildings in the village. From the appearance it probably dates to mid-twentieth Century.

Associated Historical/ Cultural Events or Individual:

Inscriptions: None

Architectural Appraisal:

An L shaped two storey building. The building is constructed of concrete with a flat roof. No older architectural features have been left on the exterior. The entrance has a folding metal gate.

Interior: Not Accessible

Existing Condition: Fair

Past and Present Uses: Residential. The building was closed up and vacant at the time of the survey.

Notes on modifications: The exterior of the building has been stripped of all older features and the surface covered in concrete



Façade of HB-07



HB-07 (Southern Section)

Ref: HB-08	Title: Village House	Category: Residential
Address: 57A & 57B Cha Kwo Ling		Reference Plan:
Orientation: Southwest		Grading: Nil

Surrounding Environment: The building is situated near the front of the village. The other strucvtures in the vicinity are mainly squatter in style.

Historical Appraisal:

The style of the buildings would suggest they date to the middle of the 20th Century. The building has drains along the side some of which are stone lined. The building whilst not one of the oldest in the village is a substantial building and not a squatter structure.

Associated Historical/ Cultural Events or Individual:

Inscriptions: None

Architectural Appraisal:

Three storey concrete structure with multiple units on each floor. Central concrete staircase leads upwards from the facade. The entrances on the ground floor have modern metal coverings. Some of the windows on the facade are the original mulit-paned and wooden framed units. Exterior walls are render.

Interior: Not Accessible

Existing Condition: Good

Past and Present Uses: Residential (Currently) Local informants had no information on any past uses other than residential.

Notes on modifications: None



Façade of HB-08



Rear Elevation of HB-08

Ref: HB-09	Title: Village House	Category: Residential
Address: No. 65 A Cha Kwo Ling		Reference Plan:
Orientation: South		Grading: Nil

The building is situated at the back central section of the village. There is a mixture of other more substantial and squatter style buildings in the vicinity.

Historical Appraisal:

The house is one of the older more substantial buildings in the village which is dominated by squatter style buildings. It is in close proximity to Law's Mansion.

Associated Historical/ Cultural Events or Individual: None

Inscriptions: None

Architectural Appraisal:

Square shaped house with pitched roof. The walls are constructed of cut stone with thick pointing. There are no decorative features on the building.

Interior: Not Accessible

Existing Condition: Good

Past and Present Uses: Residential

Notes on modifications: Modern windows, gates and doors have been added to the building. The roof is a modern replacement



HB-09: Facade and Western Elevation



Western Elevation of HB-09



HB-09: Rear Elevation

Ref: HB-10	Title: Law Mansion 羅氏大屋	Category: Residential
Address: Nos. 50A, 51 & 51A Cha Kwo Ling		Reference Plan:
Orientation: South		Grading: Grade 3

The house was originally built near the coastline, but due to reclamations it is somewhat inland. The house is surrounded by other village houses many of squatter style.

Historical Appraisal:

It was built by the Law Clan who were one of the two original clans who settled in the village.

Associated Historical/ Cultural Events or Individual: None

Inscriptions: None

Architectural Appraisal:

The building is a Qing vernacular style two storey building square in shape. It is constructed of granite blocks and the roof is of pitched Chinese style. The granite walling and horizontal security barred timber door are interesting features.

Interior: The interior of the building was once used as an ancestral hall.

Existing Condition: Fair

Past and Present Uses:

Residential and after WWII the house was converted into a plastics factory and storeroom. This use was eventually stopped and the house was subdivided to let for residential use once again.

Notes on modifications:

Modern windows, aircon units, cables, junction boxes, corrugated metal sheets and metal security screen have all been added to the building. During the subdivision of the building, it has been divided into three sections, each with its own entrance.



The Façade of Law's Mansion (HB-10)



The Western Elevation of Law's Mansion (HB-10)



Eastern Elevation of Law's Mansion (HB-10)



Entrance of Law's Mansion (HB-10)

Ref: HB-11	Title: Village House	Category: Residential
Address: No. 45 Cha Kwo Ling		Reference Plan:
Orientation: Southwest		Grading: Nil

Surrounding Environment: The area immediately around the building is empty there are a number of squatter style buildings in the vicinity.

Historical Appraisal:

The village house is a stone structure but has been damaged from fire.

Associated Historical/ Cultural Events or Individual: The house shows damage of the devastating fires that swept through the village in the 1980's or 90's.

Inscriptions: None

Architectural Appraisal:

Section of a larger structure that remains after fire damage. The walls are of cut stone and covered with render. The door is wooden and is set in a modern concrete frame.

Interior: Not Accessible

Existing Condition: Fair to Poor

Past and Present Uses: Residential

Notes on modifications: Modern roof material.



Front Elevation of HB-11



Rear Elavation of HB-11