

VP11 – Existing conditions



VP11 – Photomontage at Day 1 of operation with no mitigation / enhancement

Figure 11.18a

Photomontage from VP11 – View from vicinity of the Macau Ferry Route (Sheet 1 of 2)

**Environmental** Resources Management





VP11 – Photomontage at Day 1 of operation with mitigation / enhancement



VP11 – Photomontage at Year 10 of operation with mitigation / enhancement

Figure 11.18b

Photomontage from VP11 – View from vicinity of the Macau Ferry Route (Sheet 2 of 2)

Environmental Resources Management

