

JOB NO.: TCS00491/09

DSD CONTRACT No.: DC/2009/08

CONSTRUCTION OF YUEN LONG SOUTH BRANCH SEWERS AND EXPANSION OF HA TSUEN SEWAGE PUMPING STATION

THE SEVENTH RESULTS OF LANDSCAPE AND VISUAL IMPACT MONITORING FOR AUGUST 2010 (NO.7)

PREPARED FOR

CHINA STATE CONSTRUCTION ENGINEERING (HONG KONG) COMPANY LIMITED

Quality Index

Date		Reference No.	Prepared By	Certified By				
17 Oct 2011		TCS00491/09/600/R00288v1	Wong Fu Nam (Senior Environmental Consultant)	T.W. Tam (Environmental Team Leader)				
			mm .					

Version	Date	Description
1	17 Oct 2011	First submission

This report has been prepared by Action-United Environmental Services & Consulting with all reasonable skill, care and diligence within the terms of the Agreement with the client, incorporating our General Terms and Conditions of Business and taking account of the resources devoted to it by agreement with the client. We disclaim any responsibility to the client and others in respect of any matters outside the scope of the above. This report is confidential to the client and we accept no responsibility of whatsoever nature to third parties to whom this report, or any part thereof, is made known. Any such party relies upon the report at their own risk.

安誠工程顧問有限公司

香港灣仔皇后大道東183號 合和中心47樓

電話: (852) 2911 2233 傳真: (852) 2805 5028

Hyder Consulting Limited

Company Number 126012
47th Floor, Hopewell Centre
183 Queen's Road East
Wan Chai, Hong Kong
Tel: (852) 2911 2233
Fax: (852) 2805 5028
hyder.hk@hyderconsulting.com
www.hyderconsulting.com



27 October 2011

By Post

Action-United Environmental Services & Consulting
Unit A, 20/F, Gold King Industrial Building, 35-41 Tai Lin Pai Road,
Kwai Chung,
New Territories,
Hong Kong.

Your Ref: Our Ref:

EB000586-F/THW11-2558

For attention of: Mr. T. W. Tam

Dear Mr. Tam,

Contract No.: DC/2009/08

Construction of Yuen Long South Branch Sewers and Expansion of Ha Tsuen Sewage

Pumping Station

Monthly EM&A Report for Designated Project, Landscape and Visual Impact Sections, July 2010 to March 2011 – IEC Verification

With reference to ET's captioned Landscape and Visual Impact section of monthly EM&A reports for nine reporting months, July 2010 to March 2011 inclusive (ET's ref.: TCS00491/09/600/R0287v1, TCS00491/09/600/R0288v1, TCS00491/09/600/R0289v1, TCS00491/09/600/R0291v1, TCS00491/09/600/R0292v1, TCS00491/09/600/R0295v1, TCS00491/09/600/R0296v1 and TCS00491/09/600/R0297v1, all dated 17 October 2011) received on 26 October 2011, we have no comment and hereby verify the captioned Landscape and Visual Impact section of monthly EM&A reports.

Should there be any queries, please feel free to contact our William Law on 2911 2511.

Yours sincerely

F.C. TSANG

Independent Environmental Checker HYDER CONSULTING LIMITED

Transless

FCT/WL/my





TABLE OF CONTENTS

1.	INTRODUCTION	-
2.	CONTENT OF THE LVIM RESULTS	1

APPENDIX A SITE INSPECTION CHECKLIST

The Seventh Results of Landscape and Visual Impact Monitoring for August 2010 (No.7)



1. INTRODUCTION

- 1.01 This Results of Landscape and Visual Impact Monitoring (hereinafter "the LVIM Results") is part of the monthly EM&A report under DSD Contract No.: DC/2009/08 Construction of Yuen Long South Branch Sewers and Expansion of Ha Tsuen Sewage Pumping Station: Results of Landscape and Visual Impact of Chapter 4 Impact Monitoring Results. The LVIM Results should therefore be read in conjunction with the corresponding monthly EM&A reports.
- 1.02 Pursuant to Chapter 6 Landscape and Visual of the EM&A Manual, EM&A for landscape and visual resources is considered to be a key aspect during both the construction and operational phases of the Project. The implementation and maintenance of landscape compensatory planting measures should therefore be checked to ensure that they are fully realized and that potential conflicts between the proposed landscape measures and any other project works and operational requirements are resolved at the earliest possible date and without compromise to the intention of the mitigation measures.
- 1.03 Monitoring of the recommended implementation of the mitigation measures is required to be conducted throughout the construction phase of the Project.
- 1.04 As a member of the ET, the landscape architect is responsible for the implementation of landscape construction works and subsequent maintenance operations during the 12 month establishment period. The establishment works should be undertaken throughout the Contractor's one year maintenance period which will be within the first operational year of the Project.
- 1.05 All measures undertaken by both the Contractor and the Landscape Contractor during the construction phase and first year of the operational phase should be audited by the landscape architect on a regular basis to ensure compliance with the intended aims of the measures.
- 1.06 Site inspections should be undertaken at least once every two weeks throughout the construction period and once every two months during the operational phase.
- 1.07 The LVIM Results has been prepared by the landscape architect and compiled by the ET upon receipt for submission to EPD after verification by the IEC.
- 1.08 To cater to closer compliance of the EM&A reporting with the EP requirements, it has been agreed among the RE, IEC and ET that The LVIM Results is submitted separately as a stand-alone submission.
- 1.09 This is the seventh (No. 7) LVIM Results, covering the construction period from 1 to 31 August 2010 (hereinafter "the Result Period").

CONTENT OF THE LVIM RESULTS

- 2.01 This LVIM Results contains the site inspection checklist for the Result Period, where landscape and visual impact monitoring results are presented and where necessary, the associated recommendations are included.
- 2.02 The site inspection checklist is enclosed in *Appendix A*.



Appendix A

Site Inspection Checklist

Landscape and Visual Impact Assessment Site Inspection Checklist

Contract No.: Contract title:		DC/2009/08								
		Construction of Yuen Long South Sewer and Expansion	n of Ha Ts	suen Sew	age Pum	ping Station				
Co	ntractor:	China State Construction Engrg. (HK) Ltd.								
Lo	cation:	Ha Tsuen Sewage Pumping Station								
Inspection Date:		15-Aug-2010								
			S	Satisfacto	ry	Rectified				
			N/A	Yes	No	Yes No	Remarks			
1. (General									
1.	Erect hoardin	g around site boundary properly		✓	Ш	✓				
2.	Keep well ma	intenance of hoarding		\checkmark		✓				
3.	All constructi	on works are carried out within site boundary properly		1		/				
4	Carry out the	initial tree survey prior to construction		\checkmark						
5	Provide tree l	abels according to tree survey records		\checkmark						
Co	mments:									
Sta	ndard hoarding	was erected and well maintained around the works area a	at Ha Tsue	n Sewag	e Pumpir	ng Station (HTSPS).			
All	trees were labe	lled as requirement.			7 4 5 5					
II.	Transplanting	Works								
1.	All transplant specifications	ing works are carried out in accordance with the		~		V				
2.	The transplan establishment	ted trees are kept in regular inspection within the period	~				Item 1			
3.	The transplan	ted trees are kept in maintenance thoughout the estanlish	nment peri	od as fol	lowings:					
	(i) Watering			✓		\checkmark				
	(ii) Weeding			✓		V				
	(iii) Fertilisin	g	1							
	(iv) Littering			✓		\checkmark				
	(v) Grass cutt	ing		1	1	\checkmark				
	(vi) Firming u	п р		✓		\checkmark				
	(vii) Pest con	trol	1							
	(viii) Disease	control		1						
	(ix) Pruning			✓		V				
	(x) Replacem	ent	1	;						
Co	mments:									
The	ere had total 73	nos. of transpalnted trees in Ha Tsuen Sewage Pumping	Station du	e to cons	struction	works under this c	ontact.			
Wa	ntering and week	ding should be undertaking periodically.								
111	. Landscaping	Works								
1.	All landscapi	ng works are carried out in accordance with the		\checkmark						
2.		ing plants are kept in regular inspection within the		✓		V				

Landscape and Visual Impact Assessment Site Inspection Checklist

					Satisfactory		Rectified				
0					N/A	Yes	No	Yes	No	I	Remarks
3.	The landscaping plants are kept in maintenance thoughout the estanlishment period as followings:										
	(i) Watering					V		1			
	(ii) Weeding					V					
	(iii) Fertilising					1		1			
	(iv) Littering					1		1			
	(v) Grass cuttin	g				1		1			
	(vi) Firming up					1		~			
	(vii) Pest contro	ol				1		1			
	(viii) Disease co	ontrol				1		V			
	(ix) Pruning					V		V			
	(x) Replacemen	nt				1		1			
Cor	nments:										
No	landscaping worl	ks were carrie	ed out in the ren	orting month							
				V. 2017 120							
IV.	Preservation an	d Protection	of Trees								
1.	All preserved to	ees are prote	cted in accorda	nce with the specifications							
1.	All preserved ti	ces are protes	cica iii accordai	ice with the specifications	ш				\Box		
2.	All preserved tr	ees are fence	d off properly			1		\checkmark			
3. No construction activities are carried out in the protection zone of the preserved trees					1		1				
Cor	nments:										
All	retained trees we	re fenced off	and protected p	properly within the works ar	ea of the	site.					
				acts on the retained trees wi			a.				
-											
	iclusion	n	and the state of the state of			11. T.	C	D	C+-v'	TTI.	1.4
				e transplanting and visual i						ı. The	condition
	7			ks maintained for the transp							
				eviewed in the regular inspe	ection as	per attacl	ied. Mor	e Freque	ntly wat	ering	is required
	ning of die branc	n is required.									
	narks	VI-Selection 1	macri e		2.25		2-				
1. T	a sylvania serve			was scheduled at the end of	f the rep	orting mo					
	Tree Nos.	Health	Tree Form	Comments			_	gested tr			
	HA211 HA245	Fair Dying	Fair Fair	Die branch Dying				ng the de er more f			
	HA260	Fair	Fair	Fungi attack				to spray			
	D1240	Fair	Fair	Found dead branch and the	ne knot o	f	Pruning,				
	D1233	Fair	Fair	aerial root Found dead brand	ch			Prunir		-5.305	
									- Ann		

Rev.0

(Name: David Bloxham MLI (UK Chartered))

Contract No.:	DC/2009/08							
Contract title:	Construction of Yuen Long South Sewer and Expansion	on of Ha Ts	suen Sew	age Pum	ping Station			
Contractor:	China State Construction Engrg. (HK) Ltd.							
Location:	Ha Tsuen Sewage Pumping Station							
Inspection Date:	30-Aug-2010							
- Inspection Dute.	207145 2010	Satisfactory			Rectified			
		N/A	Yes	No	Yes No	Remarks		
I. General								
1. Erect hoard	ng around site boundary properly		1		\checkmark			
2. Keep well n	naintenance of hoarding		1					
3. All construc	tion works are carried out within site boundary properly		1					
4 Carry out th	e initial tree survey prior to construction		1					
5 Provide tree	labels according to tree survey records		\checkmark					
Comments:								
Standard hoardin	g was erected and well maintained around the works area	at Ha Tsue	n Sewag	e Pumpin	g Station (HTS	PS).		
A 10 10 10 10 10 10 10 10 10 10 10 10 10	nas no implication to protected tree. Close monitoring the					400		
II. Transplantin	g Works							
All transplar specification	nting works are carried out in accordance with the		~			-		
2. The transpla	inted trees are kept in regular inspection within the nt period	1				Item I		
3. The transpla	inted trees are kept in maintenance thoughout the estanlish	hment period as followings:						
(i) Watering	ti d		1		√			
(ii) Weeding	Ţ		1					
(iii) Fertilisi	ng	V						
(iv) Litterin	2		1		\checkmark			
(v) Grass cu	tting		1					
(vi) Firming	up -		1			-		
(vii) Pest co	ntrol	1						
(viii) Diseas	e control		1		\checkmark			
(ix) Pruning			1		\checkmark			
(x) Replaces	nent	1						
Comments:								
There had total 7	3 nos. of transpalnted trees in Ha Tsuen Sewage Pumping	Station du	e to cons	truction v	works under this	s contact.		
Watering should	be undertaking periodically. More pruning for die branch	is required						
III. Landscaping	g Works							
All landscap specification	oing works are carried out in accordance with the		V		V			
	ping plants are kept in regular inspection within the		~		V	-		

					Satisfactory			Rect	ified	
					N/A	Yes	No	Yes	No	Remarks
3.	The landscapin	ng plants are k	ept in maintena	nce thoughout the estanlish	nment per	riod as fo	llowings:			
	(i) Watering					V		1		
	(ii) Weeding								言	
	(iii) Fertilising				Ē		百		百	
	(iv) Littering						一	~	Ħ	
	(v) Grass cuttir	ng				—	三	~	三	
	(vi) Firming up					V	Ħ		司	
	(vii) Pest contr	ol			F	V	\equiv		百	
	(viii) Disease c				E		百	V		
	(ix) Pruning				H		Ħ		Π	
	(x) Replacement	nt			Ħ		Ħ		Ħ	
_						-				
	mments:									
No	landscaping wor	ks were carrie	ed out in the rep	orting month						
_										
IV.	Preservation ar	nd Protection	of Trees							
I.	All preserved to	rees are prote	cted in accordar	nce with the specifications		\checkmark		~		
2.	All preserved to	rees are fence	d off properly			~		V		
3.	No construction preserved trees		e carried out in	the protection zone of the		\checkmark		✓		
Co	mments:									
A11	retained trees we	ere fenced off	and protected n	properly within the works ar	ea of the	site.				
						_	_			
	nclusion									
				e transplanting and visual i						n. The cond
				s maintained for the transp					nealth	
cor	ditions of the tra	nsplanted tree	es should be rev	iewed in the regular inspec	tion in the	e establis	hment pe	riod.		
Son	ne of the die brar	nch need to re	move and frequ	ency watering is required						
Re	marks									
1.	The regular inspe	ction for the t	ranplanted trees	was scheduled at the end of	of the repo	orting mo	nth.			
	Tree Nos.	Health	Tree Form	Comments				gested tre		
	HA211	Fair	Fair	Die branch				ng the de		
	HA245 HA260	Dying Fair	Fair Fair	Dying Fungi attack				r more fr to spray i		
	D1240	Fair	Fair	Found dead branch and the	ne knot o	f	Pruning,			
	D1233	Fair	Fair	Found dead brane			. rannig,	Prunin		
-	OI.									

Signatures:

Senior Landscape Architect

(Name: David Bloxham MLI (UK Chartered))

HAZES HAZES HAZES THATES

HAZES HAZES HAZES THATES

HAZES HAZES HAZES THATES

AZES HAZES HAZES HAZES

AZES HAZES HAZES HAZES HAZES

AZES HAZES HAZES HAZES HAZES

HAZES HAZES HAZES HAZES HAZES

HAZES HAZES HAZES HAZES HAZES HAZES

HAZES HAZES HAZES HAZES HAZES HAZES

HAZES HAZES HAZES HAZES HAZES HAZES HAZES

HAZES HAZES HAZES HAZES HAZES HAZES HAZES

HAZES HAZES HAZES HAZES HAZES HAZES HAZES HAZES

HAZES 000 4 00 4 00 . . . HTSPS EXTENSION

EXISTING CHAMBER 91 ELM 5.97 91229 85510 X D1227 X DIS 33 E&MLP X. D1231 X D1242 6.36 X 01240



D1240



D1240



D1233



D1233



HA245



HA245

Contract No. DC/2009/08

Yuen Long South sewerage and expansion of
Ha Tsuen sewage pumping station

Watering report for August 2010









Hong Kong Landscaping Co. Ltd.

Contract No. DC/2009/08

Yuen Long South sewerage and expansion of
Ha Tsuen sewage pumping station

Watering report for August 2010



