

JOB NO.: TCS00491/09

DSD CONTRACT No.: DC/2009/08

CONSTRUCTION OF YUEN LONG SOUTH BRANCH SEWERS AND EXPANSION OF HA TSUEN SEWAGE PUMPING STATION

THE SEVENTEENTH RESULTS OF LANDSCAPE AND VISUAL IMPACT MONITORING FOR JUNE 2011 (No.17)

PREPARED FOR

CHINA STATE CONSTRUCTION ENGINEERING (HONG KONG) COMPANY LIMITED

Quality Index

Date	Reference No.	Prepared By	Certified By			
12 Dec	TCS00 49 1/09/600/R00312v2	Wong Fu Nam	T.W. Tam			
2011		(Senior Environmental Consultant)	(Environmental Team Leader)			

Version	Date	Description				
1	23 Nov 2011	First submission				
2	12 Dec 2011	Amended against IEC's comments				

This report has been prepared by Action-United Environmental Services & Consulting with all reasonable skill, care and diligence within the terms of the Agreement with the client, incorporating our General Terms and Conditions of Business and taking account of the resources devoted to it by agreement with the client. We disclaim any responsibility to the client and others in respect of any matters outside the scope of the above. This report is confidential to the client and we accept no responsibility of whatsoever nature to third parties to whom this report, or any part thereof, is made known. Any such party relies upon the report at their own risk.

安誠工程顧問有限公司

香港灣仔 皇后大道東183號 合和中心47樓

電話: (852) 2911 2233 傳真: (852) 2805 5028

Hyder Consulting Limited

Company Number 126012 47th Floor, Hopewell Centre 183 Queen's Road East Wan Chai, Hong Kong Tel: (852) 2911 2233 Fax: (852) 2805 5028 hyder.hk@hyderconsulting.com

www.hyderconsulting.com



4 January 2012

By Post

Action-United Environmental Services & Consulting
Unit A, 20/F, Gold King Industrial Building, 35-41 Tai Lin Pai Road,
Kwai Chung,
New Territories,
Hong Kong.

Our Ref:

Your Ref:

EB000586-F/THW12-3742

For attention of: Mr. T. W. Tam

Dear Mr. Tam,

Contract No.: DC/2009/08

Construction of Yuen Long South Branch Sewers and Expansion of Ha Tsuen Sewage

Pumping Station

Monthly EM&A Report for Designated Project, Landscape and Visual Impact Sections, April to September 2011 – IEC Verification

With reference to ET's captioned Landscape and Visual Impact section of monthly EM&A reports for six reporting months, April to September 2011 inclusive (ET's ref.: TCS00491/09/600/R0298v2, TCS00491/09/600/R0312v2, TCS00491/09/600/R0313v2, TCS00491/09/600/R0315v2 and TCS00491/09/600/R0316v2, all dated 12 December 2011) received on 30 December 2011, we have no comment and hereby verify the captioned Landscape and Visual Impact section of monthly EM&A reports.

Should there be any queries, please feel free to contact our William Law on 2911 2511.

Yours sincerely

F.C. TSANG

Independent Environmental Checker HYDER CONSULTING LIMITED

Tang Fambleon

FCT/WL/my

The Seventeenth Results of Landscape and Visual Impact Monitoring for June 2011 (No.17)



TABLE OF CONTENTS

1.	INTRODUCTION	1
2.	CONTENT OF THE LVIM RESULTS	1

APPENDIX A SITE INSPECTION CHECKLIST

The Seventeenth Results of Landscape and Visual Impact Monitoring for June 2011 (No.17)



1. INTRODUCTION

- 1.01 This Results of Landscape and Visual Impact Monitoring (hereinafter "the LVIM Results") is part of the monthly EM&A report under DSD Contract No.: DC/2009/08 Construction of Yuen Long South Branch Sewers and Expansion of Ha Tsuen Sewage Pumping Station: Results of Landscape and Visual Impact of Chapter 4 Impact Monitoring Results. The LVIM Results should therefore be read in conjunction with the corresponding monthly EM&A reports.
- 1.02 Pursuant to Chapter 6 Landscape and Visual of the EM&A Manual, EM&A for landscape and visual resources is considered to be a key aspect during both the construction and operational phases of the Project. The implementation and maintenance of landscape compensatory planting measures should therefore be checked to ensure that they are fully realized and that potential conflicts between the proposed landscape measures and any other project works and operational requirements are resolved at the earliest possible date and without compromise to the intention of the mitigation measures.
- 1.03 Monitoring of the recommended implementation of the mitigation measures is required to be conducted throughout the construction phase of the Project.
- 1.04 As a member of the ET, the landscape architect is responsible for the implementation of landscape construction works and subsequent maintenance operations during the 12 month establishment period. The establishment works should be undertaken throughout the Contractor's one year maintenance period which will be within the first operational year of the Project.
- 1.05 All measures undertaken by both the Contractor and the Landscape Contractor during the construction phase and first year of the operational phase should be audited by the landscape architect on a regular basis to ensure compliance with the intended aims of the measures.
- 1.06 Site inspections should be undertaken at least once every two weeks throughout the construction period and once every two months during the operational phase.
- 1.07 The LVIM Results has been prepared by the landscape architect and compiled by the ET upon receipt for submission to EPD after verification by the IEC.
- 1.08 To cater to closer compliance of the EM&A reporting with the EP requirements, it has been agreed among the RE, IEC and ET that The LVIM Results is submitted separately as a stand-alone submission.
- 1.09 This is the Seventeenth (No. 17) LVIM Results, covering the construction period from 1 to 30 June 2011 (hereinafter "the Result Period").

CONTENT OF THE LVIM RESULTS

- 2.01 This LVIM Results contains the site inspection checklist for the Result Period, where landscape and visual impact monitoring results are presented and where necessary, the associated recommendations are included.
- 2.02 The site inspection checklist is enclosed in *Appendix A*.



Appendix A

Site Inspection Checklist

Contract No.:		DC/2009/08							
Co	Construction of Yuen Long South Sewer and Expansion			suen Sew	age Pump	oing Stat	ion		
Co	ntractor:	China State Construction Engrg. (HK) Ltd.							
Loc	cation:	Ha Tsuen Sewage Pumping Station							
Ins	pection Date:	16-Jun-2011							
			S	atisfacto	ry	Rect	ified		
			N/A	Yes	No	Yes	No	R	emarks
I. C	General								
1.	Erect hoardin	g around site boundary properly	Ш	✓	Ш	✓	Ш-		
2.	Keep well ma	intenance of hoarding		\checkmark		\checkmark			
3.	All constructi	on works are carried out within site boundary properly		\checkmark		\checkmark			
4	Carry out the	initial tree survey prior to construction		\checkmark		✓			
5	Provide tree l	abels according to tree survey records		\checkmark		✓			
Coı	mments:								
Sta	ndard hoarding	was erected and well maintained around the works area at	Ha Tsue	n Sewage	e Pumpin	g Station	n (HTSPS).	
The	contruction ha	s no implication to protected tree.							
II.	Transplanting	Works							
1.	All transplant specifications	ing works are carried out in accordance with the		✓		\checkmark			
2.	The transplan establishment	ted trees are kept in regular inspection within the period		√		\checkmark			
3.	The transplan	ted trees are kept in maintenance thoughout the establish	ment peri	od as foll	owings:				
	(i) Watering	-	√						
	(ii) Weeding		<u> </u>	一	一	一	一		
	(iii) Fertilisin	g	<u> </u>	一	\sqcap	一	一		
	(iv) Littering								
	(v) Grass cutt	ing	<u> </u>	一	一	$\overline{\Box}$	一		
	(vi) Firming u	пр	✓						
	(vii) Pest cont	trol	✓						
	(viii) Disease	control	✓						
	(ix) Pruning		\checkmark						
	(x) Replaceme	ent	✓						
Coı	nments:								
The	ere had total 73	nos. of transpalnted trees in Ha Tsuen Sewage Pumping S	tation du	e to cons	truction v	vorks un	der this c	ontract.	
All	tree have been	handover back to DSD.							
III.	Landscaping '	Works							
1.	All landscapin	ng works are carried out in accordance with the		√		√	□.		
2.	The landscapi	ing plants are kept in regular inspection within the period		✓		\checkmark			

Landscape and Visual Impact Assessment Site Inspection Checklist

	S	Satisfactor	у	Rectified	
	N/A	Yes	No	Yes No	Remarks
. The landscaping plants are kept in maintenance thoughout the esta	blishment per	iod as fol	lowings:		
(i) Watering		\checkmark			
(ii) Weeding		\checkmark		V	
(iii) Fertilising		\checkmark		V	
(iv) Littering		\checkmark		✓	<u> </u>
(v) Grass cutting		\checkmark		✓	3
(vi) Firming up		\checkmark		V	
(vii) Pest control		\checkmark			Sa
(viii) Disease control		\checkmark		✓	
(ix) Pruning		\checkmark		✓	
(x) Replacement		\checkmark		✓	·
Comments:					
No landscaping works were carried out in the reporting month					
		830			
V. Preservation and Protection of Trees					*
. All preserved trees are protected in accordance with the specification	ons 🗸				\$ }
. All preserved trees are fenced off properly	1				7
. No construction activities are carried out in the protection zone of t preserved trees	the 🗸				
Comments:					ñ
All retained trees were fenced off and protected properly within the wor	ks area of the	site.	->-		
Conclusion					
Generally, the overall conditions of transplanting and visual are normal at I atisfactory. The trees which were at Ha Tsuen Pumping Station have been nonitoring since January2011.	Ha Tsuen Sewa returned to Dr	age Pumpi ainage Se	ng Statio rvices De	n. The condition partment for ma	s of hoarding wer nagement and
Remarks					
Communication of the Communica	*				
Signatures:					-8
Senior Landscape Architect					
DAB					
(Name: David Bloxham MLI (UK Chartered))					

Rev.0


Landscape and Visual Impact Assessment Site Inspection Checklist

Co	ntract No.:	DC/2009/08					
Co	ntract title:	Construction of Yuen Long South Sewer and Expansion	of Ha Ts	uen Sewa	ige Pump	ing Station	
Co	ntractor:	China State Construction Engrg. (HK) Ltd.					
Lo	cation:	Ha Tsuen Sewage Pumping Station					
Ins	spection Date:	30-Jun-2011					
			S	atisfacto	ry	Rectified	
			N/A	Yes	No	Yes No	Remarks
I. (General						
1.	Erect hoardin	g around site boundary properly		\checkmark		✓	
2.	Keep well ma	intenance of hoarding		\checkmark		✓	
3.	All constructi	on works are carried out within site boundary properly		\checkmark		✓	
4	Carry out the	initial tree survey prior to construction		\checkmark		/ .	
5	Provide tree la	abels according to tree survey records		\checkmark		/ .	
Co	mments:						
Sta	ndard hoarding	was erected and well maintained around the works area a	t Ha Tsue	n Sewage	Pumpin	g Station (HTSPS).
All	trees were labe	lled as requirement.					
II.	Transplanting	Works					
1.	All transplant specifications	ing works are carried out in accordance with the		✓		✓	
2.	The transplan establishment	ted trees are kept in regular inspection within the		\checkmark		✓	
3.	The transplan	ted trees are kept in maintenance thoughout the estanlish	ment perio	od as foll	owings:		
	(i) Watering	1	· ·				
	(ii) Weeding		✓	一	一	一一	
	(iii) Fertilisin	g	✓	一	一		_
	(iv) Littering		√				
	(v) Grass cutt	ing	✓				
	(vi) Firming u	up	\checkmark				
	(vii) Pest cont	trol	\checkmark				
	(viii) Disease	control	\checkmark				
	(ix) Pruning		\checkmark				
	(x) Replacement	ent	\checkmark				
Con	mments:						
The	ere had total 73	nos. of transpalnted trees in Ha Tsuen Sewage Pumping S	Station due	e to const	ruction w	orks under this c	ontract.
Wa	atering and weed	ling should be undertaking periodically.					
Ш	. Landscaping	Works					
1.	All landscapin	ng works are carried out in accordance with the		✓		✓ .	
2.	The landscapi	ing plants are kept in regular inspection within the		✓		V .	

		Satisfactory		Rectified		entroping by 16 as	H. 24	
		N/A	Yes	No	Yes N	lo	Rem	arks
3.	The landscaping plants are kept in maintenance thoughout the establish	ment per	iod as fol	lowings:	\$70 0			* *
	(i) Watering		\checkmark		V	╗.		
	(ii) Weeding		\checkmark		\checkmark	\Box .		
	(iii) Fertilising		✓		\checkmark	\Box .		
	(iv) Littering		✓		V	\Box .		
	(v) Grass cutting		✓		✓	\Box .		
	(vi) Firming up		\checkmark		V	\Box .		
	(vii) Pest control		\checkmark		\checkmark	\Box .		, , , , , , , , , , , , , , , , , , ,
	(viii) Disease control		\checkmark		\checkmark			
	(ix) Pruning		\checkmark		✓] _	**	
	(x) Replacement		\checkmark		✓	□.		
Con	nments:							
No	landscaping works were carried out in the reporting month							
		0.00			732661			
IV.	Preservation and Protection of Trees				30,000			
1.	All preserved trees are protected in accordance with the specifications	✓].		
2.	All preserved trees are fenced off properly	\checkmark				Ι.		
3.	No construction activities are carried out in the protection zone of the preserved trees	1				Ι.		
Cor	nments:							
All	retained trees were fenced off and protected properly within the works a	ea of the	site. DSE	is carry	ing out the	preserv	vation	
and	protection.		2.4	100 St. 100 St.				
Gen	erally, the overall conditions of transplanting and visual are normal at Ha Tsu factory. The trees which were at Ha Tsuen Pumping Station have been return itoring since January 2011.							vere
								*
Por	narks							
Itti	nai na							
-	Signatures:	9 955	* *			37	75,444,62	2000

Senior Landscape Architect

(Name: David Bloxham MLI (UK Chartered))



Ha Tusen Pumping Station



Ha Tusen Pumping Station