

JOB NO.: TCS00491/09

DSD CONTRACT No.: DC/2009/08

CONSTRUCTION OF YUEN LONG SOUTH BRANCH SEWERS AND EXPANSION OF HA TSUEN SEWAGE PUMPING STATION

THE FORTH-SEVENTH RESULTS OF LANDSCAPE AND VISUAL IMPACT MONITORING FOR DECEMBER 2013 (No.47)

PREPARED FOR

CHINA STATE CONSTRUCTION ENGINEERING (HONG KONG) COMPANY LIMITED

Quality Index

& cross-12, 222					
Date	Reference No.	Prepared By	Certified By		
		Donald Kwok (Assistant Environmental Consultant)	T.W. Tam (Environmental Team Leader)		
11 March 2014	TCS00491/09/600/R0536v2	THE STATE OF THE S	Amn_		

Version	Date	Description
1	13 February 2014	First submission
2	11 March 2014	Amended against the IEC's comment on 10 March 2014

This report has been prepared by Action-United Environmental Services & Consulting with all reasonable skill, care and diligence within the terms of the Agreement with the client, incorporating our General Terms and Conditions of Business and taking account of the resources devoted to it by agreement with the client. We disclaim any responsibility to the client and others in respect of any matters outside the scope of the above. This report is confidential to the client and we accept no responsibility of whatsoever nature to third parties to whom this report, or any part thereof, is made known. Any such party relies upon the report at their own risk.

安誠工程顧問有限公司

香港灣仔皇后大道東183號 合和中心47樓

電話: (852) 2911 2233 傳真: (852) 2805 5028

Hyder Consulting Limited

Company Number 126012 47th Floor, Hopewell Centre 183 Queen's Road East Wan Chai, Hong Kong Tel: (852) 2911 2233 Fax: (852) 2805 5028

hyder.hk@hyderconsulting.com www.hyderconsulting.com

EB000586-F/THW14-16029

Your Ref:

Our Ref:



14 March 2014

By E-mail

Action-United Environmental Services & Consulting
Unit A, 20/F, Gold King Industrial Building, 35-41 Tai Lin Pai Road,
Kwai Chung,
New Territories,
Hong Kong.

For attention of: Mr. T. W. Tam

Dear Mr. Tam,

Contract No.: DC/2009/08

Construction of Yuen Long South Branch Sewers and Expansion of Ha Tsuen Sewage

Pumping Station

Monthly EM&A Report for Designated Project, Landscape and Visual Impact Sections, November and December 2013 – IEC Verification

With reference to ET's captioned Landscape and Visual Impact sections of monthly EM&A Report of the reporting months, November 2013 (ET's ref.: TCS0491/09/600/R0535v2) and December 2013 (ET's ref.: TCS0491/09/600/R0536v2) submitted on 11 March 2014, we have no further comment and hereby verify the captioned Landscape and Visual Impact sections of the monthly EM&A Reports.

Yours sincerely,

for and on behalf of Hyder Consulting Limited

F.C. TSANG

Independent Environmental Checker

FCT/my



1. INTRODUCTION

- 1.01 This Results of Landscape and Visual Impact Monitoring (hereinafter "the LVIM Results") is part of the monthly EM&A report under DSD Contract No.: DC/2009/08 Construction of Yuen Long South Branch Sewers and Expansion of Ha Tsuen Sewage Pumping Station: *Results of Landscape and Visual Impact* of Chapter 4 *Impact Monitoring Results*. The LVIM Results should therefore be read in conjunction with the corresponding monthly EM&A reports.
- 1.02 Pursuant to Chapter 6 Landscape and Visual of the EM&A Manual, EM&A for landscape and visual resources is considered to be a key aspect during both the construction and operational phases of the Project. The implementation and maintenance of landscape compensatory planting measures should therefore be checked to ensure that they are fully realized and that potential conflicts between the proposed landscape measures and any other project works and operational requirements are resolved at the earliest possible date and without compromise to the intention of the mitigation measures.
- 1.03 Monitoring of the recommended implementation of the mitigation measures is required to be conducted throughout the construction phase of the Project.
- 1.04 As a member of the ET, the landscape architect is responsible for the implementation of landscape construction works and subsequent maintenance operations during the 12 month establishment period. The establishment works should be undertaken throughout the Contractor's one year maintenance period which will be within the first operational year of the Project.
- 1.05 All measures undertaken by both the Contractor and the Landscape Contractor during the construction phase and first year of the operational phase should be audited by the landscape architect on a regular basis to ensure compliance with the intended aims of the measures.
- 1.06 Site inspections should be undertaken at least once every two weeks throughout the construction period and once every two months during the operational phase.
- 1.07 The LVIM Results has been prepared by the landscape architect and compiled by the ET upon receipt for submission to EPD after verification by the IEC.
- 1.08 To cater to closer compliance of the EM&A reporting with the EP requirements, it has been agreed among the RE, IEC and ET that The LVIM Results is submitted separately as a stand-alone submission.
- 1.09 This is the forty-seventh (No. 47) LVIM Results, covering the construction period from 1 to 31 December 2013 (hereinafter "the Result Period").

2. LVIM RESULTS

- 2.01 The LVIM Results are presented in the site inspection checklist of the Result Period enclosed in Appendix A.
- 2.02 The trees at Ha Tsuen Sewage Pumping Station have been handed over to DSD since January 2011 for management and monitoring thereafter.
- 2.03 A total of 26 nos. of trees were fallen on 18 November 2013 under instruction of DSD.
- 2.04 DSD has confirmed to plant a total of 42 nos. of new trees with follow species:
 - 10 nos. of Litsea glutlnosa
 - 10 nos. of Schlma superba
 - 12 nos. Bichofla polycarpa
 - 10 nos. of Cinnamomum burmanil
- 2.05 During the reporting period, all the new trees have been planted in the site in accordance with the Tree Treatment and Compensatory Planting Plan as provided on November 2013.

DSD Contract No. DC/2009/08 - Construction of Yuen Long South Branch Sewers and Expansion of Ha Tsuen Sewage Pumping Station
The Forty-seventh Results of Landscape and Visual Impact Monitoring for December 2013 (No.47)



3. STRUCTURE OF THE LVIM RESULTS

3.01	The structure	of this IX	JIM P	enlte ic	as follows:
5.01	i ne structure	OF THIS LA	V IIVI K	esuus is	as ionows:

1.	INTRODUCTION	1
2.	LVIM RESULTS	1

APPENDIX A SITE INSPECTION CHECKLIST



Appendix A

Site Inspection Checklist

Contract No.:		DC/2009/08					
Construction of Yuen Long South Sewer and Expansion		n of Ha T	suen Sew	age Pum	ping Station	_	
Co	ntractor:	China State Construction Engrg. (HK) Ltd.					
Lo	cation:	Ha Tsuen Sewage Pumping Station					
Ins	spection Date:	16-Dec-2013					
			S	atisfacto	ry	Rectified	
			N/A	Yes	No	Yes No	Remarks
I. (General						
1.	Erect hoarding	g around site boundary properly		\checkmark		✓	
2.	Keep well ma	intenance of hoarding		\checkmark		√	
3.	All constructi	on works are carried out within site boundary properly		\checkmark		✓	
4	Carry out the	initial tree survey prior to construction		\checkmark		✓	
5	Provide tree la	abels according to tree survey records		\checkmark		✓ <u> </u>	
Co	mments:						
Sta	ndard hoarding	was erected and well maintained around the works area a	nt Ha Tsue	en Sewag	ge Pumpir	ng Station (HTSPS).	
The	e construction h	as no implication to protected tree.					
II.	Transplanting	Works					
1.	All transplant specifications	ing works are carried out in accordance with the		✓		<u> </u>	
2.	The transplan establishment	ted trees are kept in regular inspection within the period		✓		<u> </u>	
3.	The transplan	ted trees are kept in maintenance thoughout the estanlish	ment peri	iod as fol	lowings:		
	(i) Watering		✓				
	(ii) Weeding		\checkmark				
	(iii) Fertilising		\checkmark				
	(iv) Littering		\checkmark				
	(v) Grass cutt	ing	\checkmark				
	(vi) Firming u	p .	\checkmark				
	(vii) Pest cont	rol	\checkmark				
	(viii) Disease	control	\checkmark				
	(ix) Pruning		\checkmark				
	(x) Replacement	ent	\checkmark				
Comments:							
There had total 73 nos. of transpalnted trees in Ha Tsuen Sewage Pumping Station due to construction works under this contact.							
All tree have been handover back to DSD.							
III	. Landscaping	Works					
1.	All landscapin	ng works are carried out in accordance with the		✓		✓ <u> </u>	
2.	The landscapi	ng plants are kept in regular inspection within the period		✓		<u> </u>	

		Satisfacto	ry	Rectified	
	N/A	Yes	No	Yes No	Remarks
3. The landscaping plants are kept in maintenance thoughout the esta	anlishment pe	eriod as fo	ollowings	:	
(i) Watering		\checkmark		V	
(ii) Weeding		\checkmark		\checkmark	
(iii) Fertilising		\checkmark		\checkmark	
(iv) Littering		\checkmark		\checkmark	
(v) Grass cutting		\checkmark		✓	
(vi) Firming up		\checkmark		\checkmark	
(vii) Pest control		\checkmark		\checkmark	
(viii) Disease control		\checkmark		\checkmark	
(ix) Pruning		\checkmark		✓	
(x) Replacement		\checkmark		✓	
Comments:					
No landscaping works were carried out in the reporting month					
IV. Preservation and Protection of Trees					
1. All preserved trees are protected in accordance with the specification	ons 🗸				
2. All preserved trees are fenced off properly	\checkmark				
 No construction activities are carried out in the protection zone of the preserved trees 	he 🗸				
Comments:					
All retained trees were fenced off and protected properly within the work	s area of the	site. DSE	is carry	ing out the pres	ervation
and protection.					
Conclusion					***
Landscaping sub-contractor fell and removed total of 35 nos. damaged tr	rees on 12/10/	/2013. Dr	ainage S	ervice Departme	ent confirmed to plan
42 nos. new trees with the following species:			Ü		,
10 nos. of Litsea glutlnosa (潺槁樹)					
10 nos. of Schlma superba (木荷)					
12 nos. of Bichofla polycarpa (重陽木)					
10 nos. of Cinnamomum burmanil (陰香)					
26 nos. of trees were felled and removed on 18 November 2013 under ins	struction of D	rainage S	ervice D	epartment.	
Remarks					100
Remarks					
Signatures:					
Senior landscape Architect					
DNZ					
(Name: David Bloxham)					









Contract No.: <u>DC/2009/08</u>							
Co	Contract title: Construction of Yuen Long South Sewer and Expansion of			suen Sew	age Pum	ping Station	_
Co	ntractor:	China State Construction Engrg. (HK) Ltd.					
Lo	cation:	Ha Tsuen Sewage Pumping Station					
Ins	spection Date:	30-Dec-2013					
			S	atisfacto	ry	Rectified	
			N/A	Yes	No	Yes No	Remarks
I. (General						
1.	Erect hoarding	g around site boundary properly		\checkmark		√	
2.	Keep well ma	intenance of hoarding		\checkmark		✓	
3.	All constructi	on works are carried out within site boundary properly		\checkmark		✓ <u> </u>	
4	Carry out the	initial tree survey prior to construction		\checkmark		✓	
5	Provide tree la	abels according to tree survey records		\checkmark		✓	
Co	mments:						
Sta	ndard hoarding	was erected and well maintained around the works area a	nt Ha Tsue	en Sewag	e Pumpir	ng Station (HTSPS).	
The	e construction h	as no implication to protected tree.					
II.	Transplanting	Works					
1.	All transplant specifications	ing works are carried out in accordance with the		✓		<u> </u>	
2.	The transplan establishment	ted trees are kept in regular inspection within the period		✓		<u> </u>	
3.	The transplan	ted trees are kept in maintenance thoughout the estanlish	ıment peri	iod as fol	lowings:		
٥.	(i) Watering	are the second of the second o	√				
	(ii) Weeding		✓	一			_
	(iii) Fertilising	o de la companya de l	✓	\exists	一		_
	(iv) Littering		✓				
	(v) Grass cutt	ing	✓				
	(vi) Firming u		✓	\Box			
	(vii) Pest cont		✓			一一一	
	(viii) Disease		✓	\exists	一		
	(ix) Pruning		✓				
	(x) Replacem	ent	✓				
Co	mments:						
The	ere had total 73	nos. of transpalnted trees in Ha Tsuen Sewage Pumping	Station du	ie to cons	truction v	works under this con	act.
All	tree have been	handover back to DSD.					
III	. Landscaping	Works					
1.	All landscapin	ng works are carried out in accordance with the		√		<u> </u>	
2.	The landscapi	ng plants are kept in regular inspection within the period		✓			

		Satisfacto	ory	Rectified	
	N/A	Yes	No	Yes No	Remarks
3. The landscaping plants are kept in maintenance thoughout the estat	nlishment pe	eriod as fo	ollowings	S:	
(i) Watering		\checkmark		/	
(ii) Weeding		\checkmark		/	
(iii) Fertilising		\checkmark		V	
(iv) Littering		\checkmark			
(v) Grass cutting		\checkmark		✓	
(vi) Firming up		\checkmark		√	
(vii) Pest control		\checkmark		✓	
(viii) Disease control		\checkmark		\checkmark	
(ix) Pruning		\checkmark		✓	
(x) Replacement		\checkmark		✓	
Comments:					
No landscaping works were carried out in the reporting month					
IV. Preservation and Protection of Trees					
1. All preserved trees are protected in accordance with the specification	ns 🗸				
2. All preserved trees are fenced off properly	\checkmark				-
 No construction activities are carried out in the protection zone of the preserved trees 	ne 🗸				
Comments:					
All retained trees were fenced off and protected properly within the works	s area of the	site. DSI	is carry	ing out the pres	ervation
and protection.					
Conclusion		- Nov	***		
Landscaping sub-contractor fell and removed total of 35 nos. damaged tre	ees on 12/10/	/2013. Dr	ainage Se	ervice Denartme	ent confirmed to plant to
42 nos. new trees with the following species:			amage 5	or vice Departine	an committee to plant to
10 nos. of Litsea glutlnosa (瀑槁樹)					
10 nos. of Schlma superba (木荷)					
12 nos. of Bichofla polycarpa (重陽木)					
10 nos. of Cinnamomum burmanil (陰香)					
26 nos. of trees were felled and removed on 18 November 2013 under inst	ruction of D	rainage S	ervice D	epartment.	
		C		1	
Remarks					
Signatures:					
Senior landscape Architect (Name: David Bloxham)					







