

Environmental Permit No. EP-205/2004
Photo Records of the Completed Landscape and Visual Mitigation Works
for Feature No. 13NW-B/C319 Along Keung Shan Road, Lantau



Plate No. 1
General view of the middle portion of the feature



Plate No. 2
General view of the feature from Keung Shan Road

Environmental Permit No. EP-205/2004

**Photo Records of the Completed Landscape and Visual Mitigation Works
for Feature No. 13NW-B/C319 Along Keung Shan Road, Lantau**



Plate No. 3

View of the colour painted slope surface and skin wall at the middle portion of the feature



Plate No. 4

General view of the south-western end of the feature

Environmental Permit No. EP-205/2004
Photo Records of the Completed Landscape and Visual Mitigation Works
for Feature No. 13NW-B/C319 Along Keung Shan Road, Lantau



Plate No. 5
Crest view of the slope, with climbers planted over the entire slope surface



Plate No. 6
Newly planted trees and hydroseeded area along the slope toe

Environmental Permit No. EP-205/2004
Photo Records of the Completed Landscape and Visual Mitigation Works
for Feature No. 13NW-B/C319 Along Keung Shan Road, Lantau



Plate No. 7

All existing trees are preserved in tree rings on the sprayed concrete slope surface



Plate No. 8

View of the newly planted trees along the slope toe

Environmental Permit No. EP-205/2004
Photo Records of the Completed Landscape and Visual Mitigation Works
for Feature No. 13NW-B/C319 Along Keung Shan Road, Lantau



Plate No. 9
General view of the north-eastern portion of the feature



Plate No. 10
View of the north-eastern end of the feature