



SkyCity Nine Eagles Golf Course



SkyCity Nine Eagles Golf Course

EM&A Quarterly Compliance Report

November 2009 to January 2010



Hyder Consulting Limited
Company Number 126012
47th Floor, Hopewell Centre
183 Queen's Road East
Wanchai
Hong Kong
Tel: +852 2911 2233
Fax: +852 2805 5028
hyder.hk@hyderconsulting.com
www.hyderconsulting.com



SkyCity Nine Eagles Golf Course

SkyCity Nine Eagles Golf Course EM&A Quarterly Compliance Report

November 2009 to January 2010

Author YM TSANG

Checker Terence KONG

Approver Roger LEUNG

Report No EB000226-R11-01

Date 3 February 2010

Three horizontal lines with handwritten signatures above them. The first signature is "Tseang", the second is "Terence Kong", and the third is "Roger Leung".

This report has been prepared for SkyCity Nine Eagles Golf Course in accordance with the terms and conditions of appointment for *SkyCity Nine Eagles Golf Course* dated 16 March 2006. Hyder Consulting Limited (Company Number 126012) cannot accept any responsibility for any use of or reliance on the contents of this report by any third party.

CONTENTS

1	EXECUTIVE SUMMARY.....	1
2	LAKE WATER QUALITY EM&A.....	3
2.1	Overview	3
2.2	EM&A Programme.....	3
2.3	Action/Limit Levels.....	5
2.4	Summary of Monitoring Results	6
2.5	Operational Practice	7
2.6	Complaints and Notifications of Summons	8
2.7	Future Monitoring Schedule	8
3	COMMENTS, RECOMMENDATIONS AND CONCLUSIONS.....	11

APPENDICES

1. Lake Water Quality Monitoring Data
2. Graphical Plots for Monitoring Results
3. Equipment Calibration Details
4. Aqua Bio-Trol Liquid – Product Data Sheet

FIGURES

- Figure 1-1 Location of SkyCity Golf Course on the Airport Island
Figure 2-1 Schematic of Lake Water Control System
Figure 2-2 Locations for Lake Water Quality Monitoring

TABLES

- Table 2-1 In-situ Monitoring Equipment Details
Table 2-2 Monitoring Frequency
Table 2-3 Action and Limit Levels for Lake Water Quality
Table 2-4 Event Action Plan for Lake Water Quality Monitoring
Table 2-5 Summary of Compliance Monitoring Data During Reporting Quarter
Table 2-6 Operational Results
Table 2-7 Future Monitoring Schedule

1 EXECUTIVE SUMMARY

The purpose of this Project is to construct and operate a 9-hole Golf Course at the east side of the North Commercial District (NCD) on the Airport Island as an interim arrangement prior to the area's future development as a business park (see **Figure 1-1**). The interim golf facility, known as "SkyCity Nine Eagles Golf Course" is intended to serve airport passengers, overseas visitors and airport workers until August 2013.

The Project is managed by SkyCity Nine Eagles Golf Course, who has engaged Asia Turf Solutions Ltd. to establish and maintain the turfgrass of the Golf Course. Hyder Consulting have been employed as the Environmental Team (ET) for the Operation Period and have engaged ALS Technichem Pty Ltd as the HOKLAS accredited testing laboratory to carry out lake water analysis. Construction was completed on 31 December 2006, the first phase of the Operation Period was completed on 30 April 2007, and the second phase commenced on 1 May 2007.

According to the approved EM&A Manual, monthly compliance monitoring of lake water quality at four locations (W1 to W4) is required during the second phase of the Operation Period, with reporting on a quarterly basis. Parameters monitored comprise Suspended Solids (SS), Dissolved Oxygen (DO), Biochemical Oxygen Demand (BOD₅), nitrogen, phosphorous, temperature and salinity.

This is the eleventh Quarterly Compliance report covering November 2009 to January 2010 and complies with the reporting requirements stated in the approved EM&A Manual.

There was an exceedance of the Action Level for SS during scheduled monitoring in the reporting quarter. On each occasion of a series of exceedances, EPD and the Golf Course Supervisor were notified as required, as soon as the results were available, and **no** follow-on monitoring was arranged in the reporting quarter. Furthermore, the Golf Course Supervisor was advised that lake water was not of an acceptable quality for discharge and that the control valve must not be opened until there is no longer any exceedance of the Action Level.

The exceedance of the Action Level for SS level at W4 were mainly due to low water level at Lake B (0.3m in November 2009) caused by the dry weather in November 2009 as well as the accumulation of silts in Lake B. Hence the non-compliance was considered not related to the operation of the project and no follow-on monitoring was required. Possible mitigation measures were carried out by the Operator to improve the lake water quality, such as application of "Aqua Bio-Trol", a non-chemical, natural liquid microbial pond clarifier, on 2 and 23 September 2009, and arrangement for the pump cleaning system to remove sand and silts settled in Lakes A and B by the end of December 2009 and early February 2010 respectively. ET will keep track of the lake water level and will conduct earlier sampling, if necessary before the lakes are full and ready for discharge.

During the reporting quarter, no complaints were received; and there were no notifications of summons. There were also no openings of the control valve, emergency or otherwise.



Location Map

Figure 1-1 Location of SkyCity Golf Course on the Airport Island

2 LAKE WATER QUALITY EM&A

2.1 Overview

The Golf Course has been designed to contain water within two artificial lakes, which are linked together by two underwater pipes. Because of the sloping topography of the site, all rainwater collected within the Golf Course will drain into the lakes through a sub-soil drainage system. The lakes provide a source of freshwater for irrigation, from which surplus water will flow back into the lakes.

The lakes are normally maintained at a capacity of 15,000m³. This is not "full" but is the level that provides the required visual appearance. During the winter (dry) months, however, the lake water may fall below this level. The maximum capacity of the lakes is 20,000m³.

If more than 20,000m³ of water flows into the lakes, then the Golf Course may flood. To avoid this, the Golf Course Supervisor can authorise the opening of a control valve to allow the water to overflow from the lake and into off-site storm drains that discharge via Outfall No. 8. However, the valve can only be opened if the latest lake water monitoring results indicate that water is of an acceptable quality. In normal circumstances, the control valve remains closed and discharge off-site is not possible. All opening/closing of the control valve is logged on site.

If the latest lake water monitoring results indicate that water is not of an acceptable quality, then the valve cannot be opened, the lake water cannot overflow and the Golf Course may begin to flood. This is part of the mitigation design to prevent off-site discharge of water that does not meet the required standard.

The bund that surrounds the site is at least 1.5m high and up to 90,000m³ of floodwater can be retained within the Golf Course in addition to the 20,000m³ lake capacity. In this situation, water samples from the flooded Golf Course will be taken more frequently. Only when water has returned to an acceptable quality will the control valve be opened to allow water to overflow from the lake and into off-site storm drains that discharge via Outfall No. 8, thereby allowing the flood to recede.

The system by which this water control is achieved is shown in **Figure 2-1**.

2.2 EM&A Programme

Monitoring of Dissolved Oxygen (DO) concentration in mg/l, Suspended Solids (SS) in mg/l, Biochemical Oxygen Demand (BOD₅) in mg/l, Total Nitrogen in mg/l, Total Phosphorous in mg/l, Salinity in mg/l, and temperature in °C was carried out by the ET to ensure that any deterioration in lake water quality could be readily detected and timely action could be taken to rectify the situation if this was due to site operations. DO, temperature and salinity were measured *in-situ* whilst SS was determined in a HOKLAS-accredited laboratory.

2.2.1 Equipment and Methodology

Because of the relatively shallow water, *in-situ* measurements and water sampling were conducted at 0.5m from the surface (the mid-point of the 1m deep lake). Water samples for all monitoring parameters were collected, stored, preserved and analysed according to *APHA Standard Methods for the Examination of Water and Wastewater, 19th Edition, #17*.

In-situ monitoring was carried out using a DO concentration and DO saturation were carried out using a YSI Model 85 CE-C-M-Y multi-parameter meter and the range, resolution and accuracy of the equipment is provided in **Table 2-1**.

In-situ Parameters	Measuring Devices	Measurement Precision
Dissolved Oxygen	YSI Multi-purpose Meter	0.1 mg/l and 0.1%
Salinity	YSI Multi-purpose Meter	0.1 ppt
Temperature	YSI Multi-purpose Meter	0.1 °C

Table 2-1 In-situ Monitoring Equipment Details

A Kahlisco water sampler was used to obtain water samples for subsequent SS analysis in the laboratory. A sufficient volume of the sample is collected in clean, high density polythene bottles, packed in ice (cooled to 4 °C without being frozen), and delivered to the ALS laboratory immediately after monitoring. The analysis of the collected samples will start within the next working day after sample collection, following *APHA Standard Methods #2540D*.

2.2.2 Maintenance and Calibration

All in-situ monitoring instruments are calibrated and certified by ALS at monthly intervals throughout all stages of the lake water quality monitoring programme.

The YSI Multi-purpose Meter is calibrated once per monitoring day by the wet bulb method. Calibration at the ALS laboratory is carried out once every month in a water sample of known dissolved oxygen concentration. The sensor is immersed in the water and after thermal equilibration, the known mg/l value is keyed in and the calibration is carried out automatically. Calibration details are provided in **Appendix 3**.

2.2.3 Parameters Monitored

The following parameters are monitored and compared to A/L Levels:

- Dissolved Oxygen
- Suspended Solids
- BOD₅
- Total Nitrogen
- Total Phosphorous

There are no A/L Levels for temperature or salinity – these parameters are recorded for information only.

2.2.4 Monitoring Locations

Monitoring locations together with grid references are shown in **Figure 2-2**. Monitoring Stations are designated as W1, W2, W3 and W4.

2.2.5 Monitoring Date, Time, Frequency and Duration

In accordance with the EM&A Manual, the monitoring frequency of lake water quality is shown as **Table 2-2**.

	Operation Phase	
	Below Action/Limit Level	Action/Limit Level Exceedance
Monitoring Frequency	Monthly	Weekly

Table 2-2 Monitoring Frequency

2.3 Action/Limit Levels

According to the approved EM&A manual, the A/L Levels for the compliance monitoring (for monitoring locations W1 to W4) are shown in **Table 2-3**.

Parameter	Acceptable Standard (mg/ℓ)	
	Action Level	Limit Level
Suspended Solids	20	30
BOD ₅	13.5	20
Dissolved Oxygen	4	3
Total Nitrogen	20	30
Total Phosphorous	3.5	5

Table 2-3 Action and Limit Levels for Lake Water Quality

In case of exceedance of A/L Levels, the ET shall immediately implement the Event/Action Plan, shown in **Table 2-4**, in order to resolve the lake water quality problem:

Event	Action
Exceedance of Action Level	<ul style="list-style-type: none"> ▪ Notify the Golf Course Supervisor of the exceedance, providing full details (time, location, parameter, level, etc.). ▪ Increase the frequency of monitoring of the particular parameter(s) to “Action/Limit Level Exceedance” as shown in Table 2-2. ▪ If water quality continues to worsen, it may be prudent to review the Turfgrass Management Plan (TMP) in terms of application of nutrients and agree any revisions with the Golf Facility Supervisor. ▪ Notify the Golf Facility Supervisor when water quality falls below “Action Level” and reduce monitoring frequency to “Below Action/Limit Level” as shown in Table 2-2.

Event	Action
Exceedance of Limit Level	<ul style="list-style-type: none"> ▪ Notify EPD and Golf Course Supervisor of the exceedance, providing full details (time, location, parameter, level, etc.). ▪ Suspend any ongoing application of organic nutrients. ▪ Determine the likely cause of the exceedance(s). Review the TMP in terms of application of nutrients and agree any revisions with the Golf Facility Supervisor. Continue to irrigate the Golf Course using lake water. ▪ Increase the frequency of monitoring of the particular parameter(s) to “Action/Limit Level Exceedance” as shown in Table 2-2. (if not already at this frequency) to demonstrate the effectiveness of remedial measures and to confirm that water quality has returned to acceptable levels. ▪ Notify EPD and Golf Course Supervisor when water quality falls below “Action Level” (not “Limit Level”) and reduce monitoring frequency to “Below Action/Limit Level” as shown in Table 2-2.

Table 2-4 Event / Action Plan for Lake Water Quality Monitoring

2.4 Summary of Monitoring Results

2.4.1 Review of Results and Implications

A summary of scheduled lake water monitoring results for the reporting quarter is provided in **Table 2-5**, below. Detailed results are provided in **Appendix 1** and graphical plots since commencement of the second phase of Operation are given in **Appendix 2**.

Monitoring Location		Salinity (mg/ℓ)	Temperature (°C)	SS (mg/ℓ)	BOD ₅ (mg/ℓ)	DO Saturation (%age)	DO Concentration (mg/ℓ)	Total Nitrogen (mg/ℓ)	Total Phosphorous (mg/ℓ)
W1	Mean	0.1	19.3	2.0	2.0	91.5	9.1	1.5	0.1
	Minimum	0.1	16.8	2.0	2.0	86.5	8.4	1.3	0.1
	Maximum	0.1	21.3	2.0	2.0	97.7	9.9	1.9	0.1
W2	Mean	0.1	19.1	2.0	2.0	91.8	9.1	1.6	0.1
	Minimum	0.1	16.8	2.0	2.0	86.4	8.4	1.3	0.1
	Maximum	0.1	21.4	2.0	2.0	98.3	9.7	2.0	0.1
W3	Mean	0.1	19.2	12.3	2.0	91.4	8.8	1.6	0.1
	Minimum	0.1	16.7	2.0	2.0	85.7	8.4	1.4	0.1
	Maximum	0.1	21.2	19.0	2.0	99.4	9.0	1.7	0.1
W4	Mean	0.1	18.9	13.3	2.0	90.6	8.7	1.6	0.1
	Minimum	0.1	16.7	2.0	2.0	83.1	8.5	1.3	0.1
	Maximum	0.1	20.3	22.0	2.0	99.2	9.0	1.9	0.1

Note: **Bold** indicates Action Level exceedance; **Bold** indicates **Limit Level** exceedance

Table 2-5 Summary of Compliance Monitoring Data During Reporting Quarter

As shown above, there was an exceedance of the Action Level for SS at W4 during scheduled monitoring in the reporting quarter, as shown in **Appendix 1**. In accordance with the Event / Action Plan, the source(s) of the impact was identified and it was considered that the exceedance of Action Level was considered **non-project related**. In addition, the possible mitigation measures were discussed with the Operator. In light of that, no follow-on action was required, and this is described below.

2.4.2 Follow-on Action

On each occasion of a series of exceedances, EPD and the Golf Course Supervisor were notified as required, as soon as the results were available, and follow-on monitoring was arranged on weekly basis if necessary. Furthermore, the Golf Course Supervisor was advised that lake water was not of an acceptable quality for discharge and that the control valve must not be opened until there is no longer any exceedance of the Action and Limit Levels.

The exceedance of the Action Level for SS at W4 (22 mg/l) was recorded on 13 November 2009. According to the Event Action Plan for Marine Water Quality Monitoring, the source(s) of impact was identified. The exceedance of SS level at W4 was mainly due to low water level at Lake B (0.3m during the lake water quality monitoring) caused by the dry weather in November 2009 as well as accumulation of silts in Lake B. The monitored results indicated that the nutrient levels in the water remained well below the Action Level (total nitrogen =1.9 mg/l & total phosphorus < 0.1 mg/l) and hence the application of nutrient (in Turfgrass Management Plan) was not the cause of excessive algal growth in the lake in November 2009. Instead, the previously accumulated silts in the lake water in Lake B caused the exceedance of SS Action level. Possible mitigation measures were also discussed with the Operator of the Golf Course. A non-chemical, natural liquid microbial pond clarifier, "Aqua Bio-Trol", was applied to Lakes A and B on 2 and 23 September 2009 to reduce the presence of algae. Besides, more fish (e.g. carps) were added to improve the lake water quality. Considering the low water levels and unnecessary discharge of water at the moment, no follow-on water quality monitoring was required.

In light of the previously accumulated silts in Lakes A and B, the Operator has arranged for the pump cleaning system to remove the sand and silts. The lake cleaning in Lake A was started by the end of December and will be completed before Chinese New Year. For Lake B, the cleaning will be started in February. With the removal of sand and silts, the lake water quality will further be improved.

ET will keep track of the lake water level and will conduct earlier sampling, if necessary before the lakes are full and ready for discharge. Further details of "Aqua Bio-Trol" are provided in **Appendix 4**.

2.5 Operational Practice

Table 2-6 below, shows the operational practice during the reporting quarter, i.e., the activities relating to the management of water in the lakes:

Month	Month-end Lake Water Depth (m)	Can Control Valve Be Opened?	Has Control Valve Been Opened?	Quantity of Water Discharged (m ³)
November 2009	0.3	No (from 13 Nov 2009)	No	-
December 2009	0.4	Yes (from 11 Dec 2009)	No	-
January 2010	0.6	Yes (from 8 Jan 2010)	No	-

Table 2-6 Operational Results

From **Section 2.4**, the EM&A results for the reporting quarter have shown that Action Level was exceeded for periods in November 2009 and so for this period, the control valve could not be opened. For those periods when the control valve could have been opened, it was not. Overall, no water was discharged from the lakes during the reporting quarter.

2.6 Complaints and Notifications of Summons

2.6.1 Complaints

No complaints were received during the reporting month and there are no outstanding follow-on issues to be addressed.

2.6.2 Notifications of Summons

No notifications of summons were received during the reporting month and there are no outstanding follow-on issues to be addressed.

2.7 Future Monitoring Schedule

The lake water monitoring schedule for the next quarter (February to April 2010) is given in **Table 2-7**, below.

Sampling Date	Sampling Locations
12 February 2010	W1 to W4
12 March 2010	W1 to W4
16 April 2010	W1 to W4

Table 2-7 Future Monitoring Schedule




Figure 2-1 Schematic of Lake Water Control System




Figure 2-2 Locations for Lake Water Quality Monitoring

3 COMMENTS, RECOMMENDATIONS AND CONCLUSIONS

Compliance monitoring of lake water quality is required on a monthly basis, with an increase in frequency to weekly if there are exceedances of Action or Limit Levels. Parameters tested for comprise SS, DO, BOD₅, nitrogen, phosphorous, temperature and salinity. Monthly compliance monitoring was carried out on 13 November 2009, 11 December 2009 and 8 January 2010 at four locations within the two lakes.

Reporting during the second phase of the Operation Period is required on a quarterly basis. This is the eleventh Quarterly Compliance report covering November 2009 to January 2010 and complies with the reporting requirements stated in the approved EM&A Manual.

There was an exceedance of the Action Level for SS during scheduled monitoring in the reporting quarter. On each occasion of a series of exceedances, EPD and the Golf Course Supervisor were notified as required, as soon as the results were available, and no follow-on monitoring was arranged in the reporting quarter. Furthermore, the Golf Course Supervisor was advised that lake water was not of an acceptable quality for discharge and that the control valve must not be opened until there is no longer any exceedance of the Action Level.

The exceedance of the Action Level for SS level at W4 were mainly due to low water level at Lake B (0.3m in November 2009) caused by the dry weather in November 2009 as well as accumulation of silts in Lake B. Hence the non-compliance was considered not related to the operation of the project and no follow-on monitoring was required. Possible mitigation measures were carried out by the Operator to improve the lake water quality, such as application of "Aqua Bio-Trol", a non-chemical, natural liquid microbial pond clarifier, on 2 and 23 September 2009, and arrangement for the pump cleaning system to remove sand and silts settled in Lakes A and B by the end of December 2009 and early February 2010 respectively. ET will keep track of the lake water level and will conduct earlier sampling, if necessary before the lakes are full and ready for discharge.

During the reporting quarter, no complaints were received; and there were no notifications of summons. There were also no openings of the control valve, emergency or otherwise.

Appendix 1

Lake Water Quality Monitoring Data



Date	Time	Station	Salinity (mg/ℓ)	Temperature (°C)	SS (mg/ℓ)	BOD ₅ (mg/ℓ)	DO Saturation (%age)	DO Conc. (mg/ℓ)	Total Nitrogen (mg/ℓ)	T. Phosphorous (mg/ℓ)
13-Nov-09	07:35	W1	0.1	21.3	2.0	2.0	97.7	9.9	1.4	0.1
	07:45	W2	0.1	21.4	2.0	2.0	98.3	9.7	1.4	0.1
	07:55	W3	0.1	21.2	19.0	2.0	99.4	9.0	1.7	0.1
	08:00	W4	0.1	20.3	22.0	2.0	99.2	9.0	1.9	0.1
11-Dec-09	07:30	W1	0.1	19.8	2.0	2.0	90.4	9.0	1.9	0.1
	07:35	W2	0.1	19.2	2.0	2.0	90.8	9.2	2.0	0.1
	07:45	W3	0.1	19.6	16.0	2.0	89.2	9.0	1.6	0.1
	07:50	W4	0.1	19.7	16.0	2.0	89.5	8.7	1.6	0.1
08-Jan-10	07:10	W1	0.1	16.8	2.0	2.0	86.5	8.4	1.3	0.1
	07:15	W2	0.1	16.8	2.0	2.0	86.4	8.4	1.3	0.1
	07:20	W3	0.1	16.7	2.0	2.0	85.7	8.4	1.4	0.1
	07:25	W4	0.1	16.7	2.0	2.0	83.1	8.5	1.3	0.1
Mean			0.1	19.1	7.4	2.0	91.4	8.9	1.6	0.1
Minimum			0.1	16.7	2.0	2.0	83.1	8.4	1.3	0.1
Maximum			0.1	21.4	22.0	2.0	99.4	9.9	2.0	0.1



Notes: **Bold** indicates Action Level exceedance; **Bold** indicates **Limit Level** exceedance



* Additional follow-on monitoring (shown in *italic*) carried out only at those locations and only for those parameters which had previously shown exceedance in A/L Levels (these follow-on results are excluded from the mean, minimum and maximum calculations)



Appendix 2

Graphical Plots of Monitoring Results















SkyCity Golf Lake Water Quality Monitoring DO at W1




SkyCity Golf Lake Water Quality Monitoring DO at W2









SkyCity Golf Lake Water Quality Monitoring Total Nitrogen at W3




SkyCity Golf Lake Water Quality Monitoring Total Nitrogen at W4




SkyCity Golf Lake Water Quality Monitoring Total Phosphorous at W1




SkyCity Golf Lake Water Quality Monitoring Total Phosphorous at W2



SkyCity Golf Lake Water Quality Monitoring Total Phosphorous at W3



SkyCity Golf Lake Water Quality Monitoring Total Phosphorous at W4



Appendix 3

Equipment Calibration Details

CERTIFICATE OF ANALYSIS



Batch: HK0924061
Date of Issue: 24/11/2009
Client: HYDER CONSULTING LTD
Client Reference: SKY CITY GOLF COURSE

Calibration of DO System

Item : YSI Multimeter

Model No. : YSI15100 230V

Serial No. : 02C0073AB


Equipment No. : HK739

Calibration Method : This meter was calibrated in accordance with standard method APHA (18th Ed.) 4500-O C & G

Date of Calibration : 10 November, 2009

Testing Results :

Expected Reading	Recording Reading
3.95 mg/L	4.13 mg/L
5.98 mg/L	6.11 mg/L
8.04 mg/L	8.13 mg/L
Allowing Deviation	±0.2 mg/L


Mr Chan Kwok Fai, Godfrey
Laboratory Manager - Hong Kong

CERTIFICATE OF ANALYSIS




Batch: HK0924061
Date of Issue: 24/11/2009
Client: HYDER CONSULTING LTD
Client Reference: SKY CITY GOLF COURSE

Calibration of Thermometer

Item : YSI Multimeter
Model No. : YSI15100 230V
Probe No. : 02C0073AB
Equipment No.: HK739
Calibration Method : In-house Method
Date of Calibration : 10 November, 2009

Testing Results :

Reference Temperature (°C)	Recorded Temperature (°C)
22.0 °C	22.3 °C
36.0 °C	35.4%
Allowing Deviation	±2.0°C


Mr Chan Kwok Fai, Godfrey
Laboratory Manager - Hong Kong

CERTIFICATE OF ANALYSIS



Batch: HK0926437
Date of Issue: 21/12/2009
Client: HYDER CONSULTING LTD
Client Reference: SKY CITY GOLF COURSE

Calibration of DO System

Item : YSI Multimeter

Model No. : YSI15100 230V

Serial No. : 02C0073AB


Equipment No. : HK739

Calibration Method : This meter was calibrated in accordance with standard method APHA (18th Ed.) 4500-O C & G

Date of Calibration : 10 December, 2009

Testing Results :

Expected Reading	Recording Reading
2.20 mg/L	2.07 mg/L
4.50 mg/L	4.72 mg/L
6.50 mg/L	6.43 mg/L
8.10 mg/L	8.00 mg/L
Allowing Deviation	±0.2 mg/L


Mr Chan Kwok Fai, Godfrey
Laboratory Manager - Hong Kong

CERTIFICATE OF ANALYSIS



Batch: HK0926437
Date of Issue: 21/12/2009
Client: HYDER CONSULTING LTD
Client Reference: SKY CITY GOLF COURSE


Calibration of Thermometer

Item : YSI Multimeter
Model No. : YSI15100 230V
Probe No. : 02C0073AB

Equipment No.: HK739
Calibration Method : In-house Method
Date of Calibration : 10 December, 2009

Testing Results :

Reference Temperature (°C)	Recorded Temperature (°C)
22.5 °C	21.9 °C
34.5 °C	33.8 °C
Allowing Deviation	±2.0°C


Mr Chan Kwok Fai, Godfrey
Laboratory Manager - Hong Kong

CERTIFICATE OF ANALYSIS



Batch: HK1000629
Date of Issue: 15/01/2010
Client: HYDER CONSULTING LTD
Client Reference: SKY CITY GOLF COURSE

Calibration of DO System

Item : YSI Multimeter

Model No. : YSI15100 230V

Serial No. : 02C0073AB

Equipment No. : HK739

Calibration Method : This meter was calibrated in accordance with standard method APHA (18th Ed.) 4500-O C & G

Date of Calibration : 05 January, 2010

Testing Results :

Expected Reading	Recording Reading
4.90 mg/L	4.83 mg/L
7.00 mg/L	6.95 mg/L
8.88 mg/L	8.86 mg/L
Allowing Deviation	±0.2 mg/L


Mr Chan Kwok Fai, Godfrey
Laboratory Manager - Hong Kong

CERTIFICATE OF ANALYSIS



Batch: HK1000629
Date of Issue: 15/01/2010
Client: HYDER CONSULTING LTD
Client Reference: SKY CITY GOLF COURSE

Calibration of Thermometer

Item : YSI Multimeter
Model No. : YSI15100 230V
Probe No. : 02C0073AB
Equipment No.: HK739
Calibration Method : In-house Method
Date of Calibration : 05 January, 2010
Testing Results :

Reference Temperature (°C)	Recorded Temperature (°C)
21.0 °C	21.7 °C
31.0 °C	31.4 °C
Allowing Deviation	±2.0°C


Mr Chan Kwok Fai, Godfrey
Laboratory Manager - Hong Kong

Appendix 4

Aqua Bio-Trol Liquid – Product Data Sheet

Aqua Bio-Trol Liquid

Liquid Microbial Pond Clarifier

PRODUCT DATA BULLETIN

Features

- Eliminates pond scum and green, soupy conditions
- Improves water clarity
- Reduces foul odors and organic sediment
- Contains facultative bacteria capable of withstanding low oxygen levels
- Reduces levels of harmful nitrates & ammonia
- Effective under a wide range of climactic conditions
- Enhances conditions for all aquatic life
- Reduces biological oxygen demand
- Non-toxic, safe for fish, plants & applicator
- Microencapsulated, microbial stimulants

Aqua Bio-Trol Liquid is the safe, natural way to establish and maintain cleaner pond and lake water without chemicals. *Aqua Bio-Trol Liquid* eliminates pond scum and green, soupy conditions, while eliminating foul odors. *Aqua Bio-Trol Liquid* improves water clarity and digests excess organic matter in ponds, lakes and fountains.

Aqua Bio-Trol Liquid helps to create and maintain a healthier pond, lake and fountain water ecosystem through non-chemical treatment. *Aqua Bio-Trol Liquid* is an all natural, microbial based product effective for improving poor water conditions, and especially for maintenance of healthy water conditions once they are established. *Aqua Bio-Trol Liquid* is a concentration of naturally occurring microbes, which act to bring pond and lake water into proper ecological balance.

Aqua Bio-Trol Liquid is completely biodegradable and non-toxic to humans, animals and water life. The result of treatment is reduced organic sediment and particulate, reduced sludge, clear water, and enhanced conditions for all aquatic life.

Aqua Bio-Trol Liquid microbes preemptively consume organic matter which feeds algae and which leads to anaerobic conditions, including bad odors. The active microbes in *Aqua Bio-Trol Liquid* feed on excess nutrients in the entire water column, from sludge at the bottom to suspended particulate, to green organic matter on the surface. Routine application helps keep water in it's best condition without the use of potentially harmful chemicals.



DIRECTIONS FOR USE

Aqua Bio-Trol Liquid is most effective when water temperatures range from 50° to 100° F. For best results, provide adequate surface or subsurface aeration. Subsurface aeration is preferred. For maximum efficiency, assure a minimum of 5-6 % dissolved oxygen.

Apply by distributing liquid as much as possible around pond and lake edges. Avoid dumping liquid in one location.

Pond Volume	Initial Treatment	Monthly Maintenance
Acre Foot 325,900 gallons	4 gallons	2 gallons

Formulas to help in your calculations

- Length x Width x Depth (feet) x 7.48 = Number of Gallons
- One acre-foot of water = 325,900 gallons
- One acre-foot of water = 1,233 CuMt

Active Ingredients

A proprietary blend of 58 strains of aerobic and facultative beneficial bacteria at a minimum concentration of 6.6×10^7 CFU per ml (including *Bacillus subtilis*)

Warranty: Seller warrants that the product conforms to its chemical description and is reasonably fit for the purpose stated on the label when used in accordance with directions under normal conditions of use; but neither this warranty nor any other warranty of merchantability or fitness of a particular product expressed or implied, extends to the use of this product contrary to label conditions, or under conditions not reasonably foreseeable to the seller; and buyer assumes the risk of any such use.



13802 Chrisman Road ■ Houston, Texas 77039 USA
800.442.9821 ■ Fax 281.590.3353

www.parkwayresearch.com ■ www.brandtconsolidated.com