Quotation Ref.: AMO1008008

Consultancy for Environmental Monitoring on the Major Restoration of the Residence of Ip Ting-Sz, Lin Ma Hang Tsuen, Sha Tau Kok

Monthly Environmental Monitoring and Audit Report

Mar 2011

(Version 1.0)

Approved By

Dr. Priscilla Choy

(Independent Checker)

REMARKS:

The information supplied and contained within this report is, to the best of our knowledge, correct at the time of printing.

Cinotech accepts no responsibility for changes made to this report by third parties

CINOTECH CONSULTANTS LTD

Room 1710, Technology Park,
18 On Lai Street,
Shatin, NT, Hong Kong
Tel: (852) 2151 2083 Fax: (852) 3107 1388
Email: info@cinotech.com.hk

TABLE OF CONTENTS

		Page
1.	INTRODUCTION	2
	Background	2
2.	ENVIRONMENTAL SITE AUDIT	4
3.	CONCLUSION	6
LIST	OF TABLES	
Table	2.1 Observations and Recommendations of Site Audits	

Environmental License or Permit Obtained in Reporting Month

LIST OF FIGURE

Table 2.2

Figure 1 Organization Chart of Environmental Team

LIST OF APPENDICES

- A Location Plans & Work Boundary of the Project
- B Site Inspection Checklist
- C Site Audit Summary
- D Implementation Status of Environmental Mitigation Measures

1. INTRODUCTION

Background

- 1.1 Cinotech Consultant Limted (CINOTECH) was commissioned by Antiquities and Monuments Office (AMO) to undertake environmental monitoring and audit for the project "Provision of Consultancy for Environmental Monitoring on the Major Restoration to the Residence of Ip Ting-Sz, Lin Ma Hang Tsuen, Sha Tau Kok" (hereinafter called the "the Project").
- 1.2 The residence of Ip Ting-sz (hereinafter called "the Residence") is located at Lin Ma Hang Tsuen, Sha Tau Kok, New Territories, within the Closed Area. It was declared as a Monument in November 2009.
- 1.3 Major restoration works will be carried out to the Residence which include the complete reconstruction of roof, internal and external redecorations (Location plan showing the project area and work boundary is at **Appendix A**).
- 1.4 There is a small brick-built Annex attached to the Residence, which was used as a kitchen, it is not within the declared monument boundary. Emergency repair was carried out in 2005 to reconstruct the roof at the Annex and covered it with corrugated sheets, minimum repair works will be carried out to the Annex, as part of this major renovation project.
- 1.5 A Project Profile was prepared on August 2010 for direct application of Environmental Permit (EP).
- 1.6 An Environmental Permit (EP) (No. EP-400/2010) was issued on 29 September 2010 for Antiquities and Monuments Office, Leisure and Cultural Services Department as the Permit Holder.
- 1.7 Onsite environmental monitoring and audit will be carried out to ensure the proposed mitigation measures in the Project Profile are properly implemented throughout all phases of the project as required in the EP Section 2.8. A table of summary of mitigation measures is included in Appendix VI of the Project Profile.
- 1.8 Environmental monitoring and audit works for the Project was commenced on 1 December 2010.
- 1.9 This is monthly EM&A Report summarizing the EM&A works for the Project in March 2011.

Project Organizations

- 1.10 Different parties with different levels of involvement in the project organization include:
 - Project Proponent–Antiquities and Monuments Office (AMO)
 - Contractor Kin Ming Construction Co. Ltd. (KM).
 - Independent Checker (IC) Cinotech Consultants Limited (Cinotech).
- 1.11 The key contacts of the Project are shown in **Table 1.1** and the organization chart of ET is shown in **Figure 1**.

Table 1.1 Key Project Contacts

Party	Name	Role	Phone No.	Fax No.	
AMO	Ms. Candy Chan	Senior Heritage Officer	2208 4452	2601 0105	
AMO	Mr. Lau Wing Kit	Heritage Officer	2208 4451	3691 8185	
	Ms. Sophia Mak	Heritage Officer	2208 4455		
KM	Mr. Bryan Leung	Project Manager	6332 9423	2807 1949	
Kivi	Mr. Lawrence Au	Project Coordinator	6056 5173	2807 1949	
Cinotech	Dr. Priscilla Choy	Project Director	2151 2089	3107 1388	
Cinotech	Ms. Betty Choi	Project Coordinator	2151 2072	310/ 1300	

Construction Programme

- 1.12 The construction activities undertaken in the reporting month were:
 - Roof Tiling
 - External Redecoration
 - Carpentry
 - Timber flooring
 - Internal Redecoration

Summary of EM&A Requirement

1.13 On-site environmental monitoring and audit will be carried out to ensure the proposed mitigation measures listed in the Project Profile are properly implemented throughout all phases of the project.

2. ENVIRONMENTAL SITE AUDIT

- 2.1 Environmental site audits were carried out on biweekly basis to monitor the timely implementation of proper environmental management practices and mitigation measures in the Project site. As the Kitchen Annex was under renovation starting from January, the site audit frequency was adjusted to weekly basis as required in Section 5.7.1 (iv) of the Project Profile.
- 2.2 Site audits for the Project in the reporting month were conducted on 2, 10, 15, 23 and 30 March 2011. No non-compliance was observed during the site audits.
- 2.3 Site inspections were undertaken to ensure and check the compliance with the EP and that the implementation and maintenance of noise, air quality, solid waste, water quality and ecology mitigation measures are being properly carried out in the reporting month in accordance to section 5.3, 5.4, 5.5, 5.6 and 5.7 of the Project Profile respectively. No non-compliance was observed during the site inspections.
- 2.4 In accordance with to Condition 2.3 of the EP, but surveys were conducted on 19 November and 1 December 2010. No more but was found in the Kitchen Annex of the Residence on the second visit.
- 2.5 Approval from EPD was received on 14 December 2010 for commencement of construction works in the Residence and the work shall be carried out from November to March inclusive when bats were absent.
- 2.6 Renovation work was commenced from 14 December 2010.
- 2.7 A sample of site inspection checklist can be found in **Appendix B**. The summaries of site audits are attached in **Appendix C**.
- 2.8 During site inspections in the reporting month, no non-conformance was identified. The observations and recommendations are summarized in **Table 2.1**.

Table 2.1 Observations and Recommendations of Site Audits

Parameters	Date (Ref. No.)	Observations	Remediation/ Follow up
	02-03-11 (110302-R-1)	Sand pile was not covered.	The situation was improved/rectified on 02-03-11.
Water Quality	02-03-11 (110302-R-2)	Some sand bags were removed.	The situation was observed outstanding and remarked as item 100310-R-1 on 10-03-10.
	10-03-11 (110310-R-1)	Some sand bags were removed.	The situation was observed outstanding and remarked as item 100315-R-1 on 15-03-10.

Parameters	Date (Ref. No.)	Observations	Remediation/ Follow up
	15-03-11 (110315-R-1)	Some sand bags were removed.	The situation was improved/rectified on 23-03-11.

Status of Environmental Licensing and Permitting

2.9 Environmental license or permit obtained in the reporting month is shown in **Table** 2.2.

Table 2.2 Environmental License or Permit Obtained in Reporting Month

Type of		Valid Period			
License/ Permit	From		Detail	Status	
EP	EP-400/20 10	29/9/2010	N/A	Location: Lin Ma Hang Tsuen, Sha Tau Kok	Valid
Section 6 Permit of the AMO (Cap.53)	LCS AM 51/2/11	9/11/2010	31/12/2011	Name of Permit Holder: Chief Heritage Manager of AMO Name of the Monument: Residence of Ip Ting-sz Address: Lin Ma Hang, Sha Tau Kok, New Territories	Valid

Status of Waste Management

2.10 According to the contractor, wastes generated from activities listed in Section 1.12 were reused by or sold to local villagers.

Implementation Status of Environmental Mitigation Measures

2.11 According to the Environmental Permit Section 2.9, the mitigation measures detailed in the documents are required to be implemented. Details of Implementation Status of Environmental Mitigation Measures are provided in **Appendix D**.


Summary of Complaints and Prosecutions

2.12 No environmental complaint and prosecution related to the Project works was received


3. CONCLUSION

- 3.1 Five environmental site audits were performed in March 2011. No non-compliance was observed during the site audits.
- 3.2 No environmental complaint and prosecution related to the project was received in the reporting month.
- 3.3 Construction work was completed in March. No further monitoring and audit on environmental deficiency due to construction will be conducted. Post-construction bat monitoring shall commence and monitoring schedule shall be submitted.

FIGURE 1 ORGANIZATION CHART OF ENVIRONMENTAL TEAM




APPENDIX A LOCATION PLANS & WORK BOUNDARY OF THE PROJECT



© the Government of the Hong Kong SAR, Map reproduced with permission of the Director of Lands

Scale 1:5000

Location Plan 位置圖



只作識別用 FOR IDENTIFICATION PURPOSE ONLY

Work Boundary of the Project 施工範圍

APPENDIX B SITE INSPECTION CHECKLIST

					Audit Ref. No	
Proj	ject	AMO1008008	Env. Team	Cinotech (Consultants Ltd.	
		Provision of Consultancy for Environmental Monitoring	Employer	AMO		
		on the Major Restoration to the Residence of Ip Ting-sz, Lin Ma Hang Tsuen, Sha Tau Kok	Contractor	Kin Ming	Construction Co. Ltd.	
Insp	ected By	ET Auditor:	_	<u>8</u>		
•	•	Contractor:	Inspection Date			
		Employer Rep:	Time Period			
Wea	ather Cond	ition				
	dition	Sunny Fine Overcast Drizzle	Rain	Storm	Hazy	
Ten	perature	°C				
Hur	nidity	High (RH>90%) Moderate (90%>RH>60%)	Low (RH<6	50%)		
Win	nd	Calm Light Breeze Strong				
		N/A or r	ot observed Y	es No	Follow-up N/C	Remarks
Part	t A Wat	er Quality			r	
Brid	lge					
1.		ace of the bridge overlaid with plywood sheets of minimum 25mr flexible/elastic underlay (rubber, plastic, etc.), of minimum	n			-
		ck in-between?				
2.	Are the jo	ints between the sheets taped together by heavy-duty duct tape?				-
3.	Is an upsk plywood s	irt of minimum 150mm high provided on both sides of the heets?				
4.	Are all cut	tting of the materials undertaken off site?				
Site						
5.	Is concrete	e mixing activities observed on site?				
6.		te water properly collected and stored in plastic tanks and filtered charging to drainage system?				
7.	Is the store	ed waste water taken by hand trolley to the nearest drainage point	?			
8.		instruction materials stockpiled, properly covered and located in the stream?				
9.	Is the dista	ance between the hoarding and the stream maximised?				
10.		pags placed along the edge of the hoardings to prevent discharge vater to the stream?				
11.		rater/ chemical leakage or spillage avoided?		$\neg \Box$		
12.		s/stand water avoided?				
13.	Are debris	and spoil on site covered up and/or properly disposed as soon as				

	N/A or no	t observed	Yes	No	Follow-up	N/C	Remarks
Part	t B Construction Noise Impact						
1.	Are hand-held power tools and hand-held manual tools used in this project?						
2.	Is silenced equipment used where practicable?						
4.	Is the existing roof demolished by hand-held manual tools only?						
5.	Is heavy power-operated machinery applied on site?						
6.	Is construction work stopped from 6pm to 8am and any time on Sundays and general holidays?						
7.	Are all plant and equipment well maintained and in good operating condition	?					
8.	Is idle equipment turned off or throttled down?						
9.	Major noise source(s) Traffic Construction activities outside of site	Constru Others	ction activ	vities ins	ide of site		
Part	t C Air Quality						
1.	Are all trucks loaded to a level within the side and tail boards?						
2.	Is hoarding / fencing for designated area being erected?						
3.	Is the reconstruction of roof and brickwork repairs carried out by using either handheld power tools or hand-held manual tools only?						
4.	Is free falling of debris during removal and dismantlement of the roof prevent	ted?					
5.	Is debris carried in baskets or similar containers from the roof to ground level for disposal?						
6.	Is the floor regularly dampened with clean water to avoid spread of dust during the hacking-up of and removing of existing floor finishing?						
7.	Is the debris sprayed with clean water so that it remains damp before it is						
8.	carted away? Is water continuously sprayed on the surface where any drilling, cutting or						
	other small-scale breaking operation is carried out by using hand-held power tools?						
9.	Observable dust sources Wind erosion	Vehicle	equipmer/	nt moven	nents		
	Loading/unloading of materials	Others					

Part	D Ecology	N/A or not obse	erved	Yes	No	Follow-up	N/C	Remarks
1.	Does the construction work commence after confirming that no be in the Residence?	oat is found						
2.	Is the repairing work scheduled in dry season (November to Mar	ch inclusive)?						
3.	Is renovation work mainly taken place in the Residence?							
4.	Is minimum repairing work at the Kitchen Annex restricted to repatching and cleaning on the external wall and the replacement of corrugated roof with tiles only?							
5.	Is the existing purlin in the Kitchen Annex affected?							
6.	Are the corrugated sheets at the roof in the Kitchen Annex replace Chinese tiles?	eed by						
7.	Are visitors prohibited from entering the annex?							
8.	Is bat-friendly gate installed in the Kitchen Annex before operati	on phase?						
9.	Is bat-friendly gate installed according to the specified design?							
10.	Has the furniture in the Kitchen Annex been removed?							
11.	Is the woodland behind the Residence impacted by the project (e unauthorized felling and damaging)?	.g.						
12.	Is the stream impacted by the project (e.g. deterioration of water	quality)?						
13.	Is pruning of the two ${\it Cinnamomum\ camphora}\>\>\>\>\>\>\>\>\>\>\>\>\>\>\>\>\>\>\>\>\>\>\>\>\>\>\>\>\>\>\>\>\>\>\>\>$	Building						
Part	E Waste/Chemical Management							
1. 1 i.	General refuse Accumulation avoided?							
1 ii.	Receptacles (e.g. rubbish bins) available?							
1 iii.			Щ					-
2 i.	Are building materials re-used or repaired in the Residence as far	r as possible?	Щ		Щ			
2 ii.	Disposed off properly?						\sqsubseteq	
3.	Is foam, oil, grease, litter or other objectionable matters in water drain/sewer avoided?	of nearby						
4.	Are all plant and equipment well maintained to avoid chemical/f	uel leakage?						
5.	Are drip trays provided with adequate capacity and maintained w	vell?						
6.	Are loose materials, sand, salvage, builders rubbish, etc., that need transported across the bridge, first carefully wrapped up in heavy sheeting?							
7.	Are all the unwanted construction and demolition waste transportstatutory landfill sites?	ted to						

9.	Are waste termiticide returned to its	N/A or not o	bserved	Yes	No	Follow-up	N/C	Remarks
	contractor's workshop for filtering ar	nd future reuse?						
10.	Are spent chemicals from any waste detergent handled, stored and dispose							-
11.	Are construction debris and spoil cov soon as possible?	rered up and/ or properly disposed of as						
Par	t F Permits/Licences							
1.	Is Environmental Permit displayed co	onspicuously on site?						
2.	Is the Section 6 Permit of the Antiqui 53) available for inspection?	ties and Monuments Ordinance (Cap.						
Par		te Audit (Ref. No.						
1.	Is the situation in item							
2.	Is the situation in item	improved/rectified?	一		一	一	一	
3.	Is the situation in item	_		一	一	一	一	
4.	Is the situation in item		一					
5.	Is the situation in item	improved/rectified?		一	一	一	一	
6.	Is the situation in item	improved/rectified?	一一	一	一	一	一	
7.	Is the situation in item	improved/rectified?		一	一	一	一	
8.	Is the situation in item	improved/rectified?	一	同		一		
9.	Is the situation in item	improved/rectified?		一	一	一	一	
10.	Is the situation in item	improved/rectified?		一				
11.	Is the situation in item	improved/rectified?	一					
12.	Is the situation in item	improved/rectified?		一				
13.	Is the situation in item	improved/rectified?		一		$\overline{\Box}$		
14.	Is the situation in item	improved/rectified?		一	一	\Box	同	
15.	Is the situation in item	improved/rectified?	一	一		一	一	

narks/Observations		N/A or not observed	low-up N/C Remarks
	narks/Observations		

(Name:

(Date:

(Name:

(Date:

(Name:

(Date:

APPENDIX C SITE AUDIT SUMMARY

Quotation Ref.: AMO1008008 Consultancy for Environmental Monitoring on the Major Restoration of the Residence of Ip Ting-Sz, Lin Ma Hang Tsuen, Sha Tau Kok

Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	110302
Date	2 March 2011 (Wednesday)
Time	10:30-11:30

		Related
Ref. No.	Non-Compliance	Item No.
-	None identified	-
		Related
Ref. No.	Remarks/Observations	Item No.
	A. Water Quality	
110302-R-1	Sand pile was not covered.	A8
110302-R-2	Some sand bags were removed.	A10
	B. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Ecology	
	No environmental deficiency was identified during site inspection.	
	E. Waste / Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	G. Others	
	• Follow-up from previous site inspection (s) (Ref. no.: 110223):	
	All environmental deficiencies were improved/rectified by the contractor.	

Weekly Site Inspection Record Summary

	Reminders	Related Item No.
	The Contractor was reminded to implement the following preventive measures:	Tem Ivo.
	A. Water Quality	
110302-R-1	Sand pile should be covered up by tarpaulin.	A8
110302-R-2	Sand bags should be placed along the hoarding.	A10
	B. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Ecology	
	No environmental deficiency was identified during site inspection.	
	E. Waste / Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	G. Others	
	• Follow-up from previous site inspection (s) (Ref. no.: 110223): All environmental deficiencies were improved/rectified by the contractor.	

	Name	Signature	Date
Recorded by	Betty Choi	Rettynn	2-3-2011
Checked by	Dr. Priscilla Choy	NF	3-3-2011

Quotation Ref.: AMO1008008 Consultancy for Environmental Monitoring on the Major Restoration of the Residence of Ip Ting-Sz, Lin Ma Hang Tsuen, Sha Tau Kok

Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	110310
Date	10 March 2011 (Thursday)
Time	10:30-11:30

		Related
Ref. No.	Non-Compliance	Item No.
-	None identified	
		Related
Ref. No.	Remarks/Observations	Item No.
	A. Water Quality	
110310-R-1	Some sand bags were removed.	A10
	B. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Ecology	
	No environmental deficiency was identified during site inspection.	
	E. Waste / Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	G. Others	
	• Follow-up from previous site inspection (s) (Ref. no.: 110302): Environmental deficiency 110302-R-2 was not improved/rectified by the contractor. It was remarked as 110310-R-1 in this site inspection.	

Weekly Site Inspection Record Summary

	Reminders	Related Item No.
	The Contractor was reminded to implement the following preventive measures:	
	A. Water Quality	
110310-R-1	Sand bags should be placed along the hoarding.	A10
	B. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Ecology	
	No environmental deficiency was identified during site inspection.	
	E. Waste / Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	G. Others	
	• Follow-up from previous site inspection (s) (Ref. no.: 110302): Environmental deficiency 110302-R-2 was not improved/rectified by the contractor. It was remarked as 110310-R-1 in this site inspection.	

	Name	Signature	Date
Recorded by	Betty Choi	Bettynn	11-03-2011
Checked by	Dr. Priscilla Choy	NF	11-03-2011

Quotation Ref.: AMO1008008 Consultancy for Environmental Monitoring on the Major Restoration of the Residence of Ip Ting-Sz, Lin Ma Hang Tsuen, Sha Tau Kok

Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	110315
Date	15 March 2011 (Tuesday)
Time	15:30-16:30

D-C N	N. C. II.	Related Item No.
Ref. No.	Non-Compliance None identified	item no.
-	None identified	Related
D.C.M.	Parada (Observations	Item No.
Ref. No.	Remarks/Observations	Hem No.
110017 D 1	A. Water Quality	410
110315-R-1	Some sand bags were removed.	A10
	B. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Ecology	
	No environmental deficiency was identified during site inspection.	
***************************************	E. Waste / Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	G. Others	
	• Follow-up from previous site inspection (s) (Ref. no.: 110310): Environmental deficiency 110310-R-1 was not improved/rectified by the contractor. It was remarked as 110315-R-1 in this site inspection.	

1

Weekly Site Inspection Record Summary

	Reminders	Related Item No.
	The Contractor was reminded to implement the following preventive measures:	item ito.
	A. Water Quality	
110315-R-1	Sand bags should be placed along the hoarding.	A10
	B. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Ecology	
	No environmental deficiency was identified during site inspection.	
	E. Waste / Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	G. Others	
	Follow-up from previous site inspection (s) (Ref. no.: 110310):	
	Environmental deficiency 110310-R-1 was not improved/rectified by the contractor. It was remarked as 110315-R-1 in this site inspection.	

	Name	Signature	Date
Recorded by	Betty Choi	Rettyruj	16-03-5011
Checked by	Dr. Priscilla Choy	N.Z	16-03-2011

Quotation Ref.: AMO1008008 Consultancy for Environmental Monitoring on the Major Restoration of the Residence of Ip Ting-Sz, Lin Ma Hang Tsuen, Sha Tau Kok

Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	110323
Date	23 March 2011 (Wednesday)
Time	10:30 11:30 AM

		Related Item No.
Ref. No.	Non-Compliance	Item No.
-	None identified	TO .1. / - 3
		Related
Ref. No.	Remarks/Observations	Item No
	A. Water Quality	
	No environmental deficiency was identified during site inspection.	
	B. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Ecology	
	No environmental deficiency was identified during site inspection.	
	E. Waste / Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	G. Others	
	Follow-up from previous site inspection (s) (Ref. no.: 110315):	
	All environmental deficiencies were improved/rectified by the contractor.	

Weekly Site Inspection Record Summary

***		Related
	Reminders	Item No.
	The Contractor was reminded to implement the following preventive measures:	
	A. Water Quality	
	No environmental deficiency was identified during site inspection.	
	B. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Ecology	
	No environmental deficiency was identified during site inspection.	
	E. Waste / Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	G. Others	
	• Follow-up from previous site inspection (s) (Ref. no.: 110315):	
	All environmental deficiencies were improved/rectified by the contractor.	

	Name	Signature	Date
Recorded by	Elizabeth Lam	llan	23-3-2011
Checked by	Dr. Priscilla Choy	Wit	

Quotation Ref.: AMO1008008 Consultancy for Environmental Monitoring on the Major Restoration of the Residence of Ip Ting-Sz, Lin Ma Hang Tsuen, Sha Tau Kok

Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	110330
Date	30 March 2011 (Wednesday)
Time	10:30-11:30 AM

		Related
Ref. No.	Non-Compliance	Item No.
-	None identified	
		Related
Ref. No.	Remarks/Observations	Item No.
	A. Water Quality	
	No environmental deficiency was identified during site inspection.	
	B. Construction Noise Impact	
	No environmental deficiency was identified during site inspection.	
	C. Air Quality	
	No environmental deficiency was identified during site inspection.	
	D. Ecology	
	No environmental deficiency was identified during site inspection.	
	E. Waste / Chemical Management	
	No environmental deficiency was identified during site inspection.	
	F. Permits/Licences	
	No environmental deficiency was identified during site inspection.	
	G. Others	
	• Follow-up from previous site inspection (s) (Ref. no.: 110323): All environmental deficiencies were improved/rectified by the contractor.	

Weekly Site Inspection Record Summary

	Related
 Reminders	Item No.
 The Contractor was reminded to implement the following preventive measures:	
 A. Water Quality	
No environmental deficiency was identified during site inspection.	
 B. Construction Noise Impact	
No environmental deficiency was identified during site inspection.	
 C. Air Quality	
No environmental deficiency was identified during site inspection.	
 D. Ecology	
No environmental deficiency was identified during site inspection.	
 E. Waste / Chemical Management	
 No environmental deficiency was identified during site inspection.	
F. Permits/Licences	
No environmental deficiency was identified during site inspection.	
G. Others	
• Follow-up from previous site inspection (s) (Ref. no.: 110323):	
All environmental deficiencies were improved/rectified by the contractor.	

	Name	Signature	Date
Recorded by	Elizabeth Lam	Cellin	30-03-2011
Checked by	Dr. Priscilla Choy	NE	

APPENDIX D IMPLEMENTATION STATUS OF ENVIRONMENTAL MITIGATION MEASURES

Appendix D - Environmental Mitigation Implementation Schedule (EMIS)

Types of Impacts	Mitigation Measures	Status
5.2.3	Overlay plywood sheets with flexible/elastic underlay as a temporary protection to the Old Bridge	V
5.3.1	Use of hand-held tools	V
5.3.2	Implement noise mitigation measures (e.g. use quieter tools)	V
5.3.3	No works will be carried out during 6 p.m. to 8 a.m. and any time on Sundays and	V
7 4 1 (')	General Holidays	1 7
5.4.1 (i)	Use basket and the like to carry debris from the roof to ground level for disposal	V
5.4.1 (ii)	Regularly dampen the floor	N/A
5.4.1 (iii)	Water spray	N/A
5.5.1	Construction and demolition material would transport to the landfill site	N/A
5.5.1	Any loose materials, sand, salvage, builders rubbish, etc , acrossing the bridge must be	N/A
	first carefully wrapped up in heavy duty PVC sheeting	
5.6.1	Waste water would be stored and filtered before discharge into drains	N/A
5.6.1	Placing sand bags along the edge of the hoardings	V
5.6.1	Maximise the distance between the hoarding and the stream	V
5.6.2	Stockpiling of construction materials will be minimised and properly covered and located away from the SSSI Stream	V
5.6.2	Construction debris and spoil will be covered up and/ or properly disposed of as soon as possible	V
5.7.1 (i)	Renovation works mainly within the Residence	V
5.7.1 (ii)	The proposed works will be scheduled during dry season when bats leave	V
,	the Residence for hibernation	
5.7.1 (iii) and (iv)	Maintain the roosting site for bat at the Kitchen Annex	V
5.7.1 (iv)	Minimum repairing works in the Kitchen Annex	V
5.7.1 (vi)	Do not put any furniture inside the annex block	V
5.7.1 (vi)	Visitors are prohibited from entering the annex	V
5.7.1 (vii)	Provide the opening at Kitchen Annex with a bat-friendly gate	V

Remark:	V	Compliance of mitigation measure;
	N/A	Not Applicable/ Not observed;
	*	Recommendation was made during site audit but improved/rectified by the contractor.
	#	Recommendation was made during site audit and to be improved / rectified by the contractor.
	Х	Non-compliance of mitigation measure;
		Non-compliance but rectified by the contractor;