CLP Power Hong Kong Ltd

TETRA Radio Base Station at Kai Kung Leng (Construction Phase): 1st Monthly Environmental Site Audit Report

September 2011

Environmental Resources Management

21/F Lincoln House 979 King's Road Taikoo Place Island East, Hong Kong Telephone: (852) 2271 3000 Facsimile: (852) 2723 5660 E-mail: post.hk@erm.com http://www.erm.com CLP Power Hong Kong Ltd

TETRA Radio Base Station at Kai Kung Leng (Construction Phase): 1st Monthly Environmental Site Audit Report

September 2011

Reference 0132494

For and on behalf of ERM-Hong Kong, Limited					
Approved l	oy: Frank Wan				
Signed:	blad				
Position:	Partner				
C (C 11	147 . 12				
Certified by	v: Winnie Ko				
Signed :	MAS				
Position :	Independent Environmental Checker				
Date :	16 September 2011				

CONTENTS

ENVIRONMENTAL SITE AUDIT	1
BACKGROUND	1
SITE AUDIT FINDINGS AND OBSERVATIONS	1
	BACKGROUND

Annex A Environmental Site Audit Checklist

1 ENVIRONMENTAL SITE AUDIT

1.1 BACKGROUND

The construction works of *TETRA Radio Base Station at Kai Kung Leng* (the Project) has commenced on 31 August 2011.

To fulfill Conditions 2.4 and 2.5 of the Environmental Permit (EP-406/2010), monthly environmental site audit should be undertaken to ensure that the mitigation measures recommended in Project Profile (PP) submitted for direct application of an Environmental Permit under EIA Ordinance (EIAO) (PP-423/2010) are properly implemented. A monthly audit report, certified by the independent checker, should be submitted to the Director of EP.

This is the 1st *Monthly Environmental Site Audit Report* presenting the key findings and observations of the site audit conducted on 7 September 2011. The reporting period covers 31 August to 30 September 2011.

1.2 SITE AUDIT FINDINGS AND OBSERVATIONS

The 1st monthly environmental site audit was conducted on 7 September 2011. The findings of the site inspection are summarised in *Table 1.1* below:

Table 1.1Summary of Site Observations

Observations/Findings	Recommendations	Photos
A rope was observed to be tied to the tree adjacent to the Project Site	The Contractor was recommended not to damage/disturb trees in the surrounding areas.	

Remedial action for the abovementioned environmental deficiency has been taken and verified immediately during the site inspection. The rope was removed immediately.

1

The environmental site audit checklist is appended in *Annex A*.

Annex A

Environmental Site Audit Checklist

	\mathbf{RM} spection Date: $\frac{7/9/2}{7/2}$	TETRA Radion Base Stat Construction Phase - Env	vironmental Site Au		① 中電	
	Inspected By: IEC Representative : CLP Representative : Contractor :	<u>Celine Lee / A</u> <u>Keith Cheur</u> <u>Kelvin Lam</u>	ndrew Fung 2			
Con	ather dition Sunny Fine operature 20 °C d Calm Light	Overcast Drizzle Humidity High Breeze Strong	Rain Moderate	Storm Hazy Low	_	
A	General		Yes Yes, but ne Improver		Photo/Remarks red	
A1	Is the Environmental Permit displayed	at the entrances / exits?			<u></u>	
В	Air Quality	3	Yes Yes, but ne Improver		Photo/Remarks red	
B1 B2 B3	Is open burning avoided? Are exposed soil surfaces regularly wa Are plant and equipment well maintair from powered plant)				·	
B4 B5 B6	Are stockpiles of dusty material cover Is watering implemented during excav Is generation of dust avoided during to	ation?			/	
С	Noise		Yes Yes, but ne Improve	ed not obser	Photo/Remarks /ed	
C1	Is the Construction Noise Permit displ (if any)	ayed at the entrances / exits?			·	
C2	Are all plant and equipment well main condition?	tained and in good operating			(
СЗ	Is idle equipment turned off or throttle	d down?			1	L
C4	Are powered mechanical equipment of acoustic materials?	overed or shielded by		n d	The equipment	5
C5	Are silenced equipment used where p	racticable?				
C6	Is the number of contstruction plant b	eing used minimized?		i 🗆 🗹		
C7	Do air compressors have valid noise l	abels?		$\Box \Box \overline{\nabla}$		
C8	Do compressors operate with doors c	losed?			~ y	
D	Water Quality		Yes Yes but ne Improve	ed not obser	Photo/Remarks ved	
D1	ls wastewater discharge license, if an	y, available for inspection?			7 1	
D2	Is drainage system adequate?	- · · · · · · · · · · · · · · · · · · ·			S Ino chadrage	
D3	Is drainage system well maintained?				Sugton 0	
D4	Is debris and rubbish in the drainage	system collected and] 🗇 🕅		

disposed of properly?

D5	Are there temporary ditches for runoff discharge into appropriate					1
	Watercourse?				\checkmark	> ho hear
	With silt retention pond?				\checkmark	bater course
D6	Are there sedimentation tanks for settling runoff prior to disposal?				\checkmark	
D7	Is the capacity of sedimentation tank adequate?				$\overline{\mathbf{V}}$	The wanterabe,
D8	Is the sedimentation free from silt and sediment?					generate
D9	Are the temporary stockpiles located away from stream or water course?			\square	$\overline{\nabla}$	
D10	Are proper mitigation measures (eg. sand bag, earth bund, trench) prevent silty surface runoff leaving the site.					
D11	Toilet that connects to foul sewer or chemical toilets provided?				$\overline{\checkmark}$	ho tilet
E	Waste/Chemical Management	Yes	Yes,	No	N/A or	Photo/Renjarks
~			but need	r	not observe	•
E1	General refuse Accumulation avoided?		[]			
E2	Receptacles (e.g. rubbish bins) available?					
E3	Disposed of regularly and properly?	\sim				<u></u>
E4	Chemical waste, waste oil Is the Chemical Waste Producer Registration available for inspection?					<u>}</u>
E5	Stored properly in designated area?				\square	
E6	Labelled properly?					
E7	Disposed of properly?					
E8	Trip tickets/ chits available for inspection?				Ī	
E9	Chemical/fuel storage area Are all spillage containment provided for all chemicals, oils and fuels stored on site, those equipment which potentially have oil leakage and for the area where maintenance works carrying out?					(the charted
E10						
E11	Adequate bund capacity? (>110% of the largest tank)				নি	
E12	Are storage areas provided with locks and located on sealed areas?					
E13	Construction Waste Reused where practicable?					Two constructions
	Is sorting conducted on site?					(caste
E14	Transported offsite for proper disposal?					
E15	Are surplus inert materials being reused where practical as an alternative to ordering imported fill material?				Z	
M 7	Excavated Material			·····		- - N
E16					Ľ	(not obline
E17	If suspected contaminated, appropriate procedures followed?					[
E18	Relevant license/permit/trip tickets/chits for disposal of construction waste or excavated materials available for inspection?					
F	General / Housekeeping	Yes	Yes, but need Improvemer		N/A or not observe	Photo/Remarks
F1	Are proper housekeeping measures being maintained?					
F2	Are potential stagnant pools cleared and mosquito breeding prevented?	Ĭ				
G	Ecology	Yes	Yes, but need Improvemen		N/A or not observe	Photo/Remarks ed

€1	Is damage and disturbance to the remaining and surrounding natural shrubby grassland and young woodland habitats avoided? (particularly those caused by filling and illegal dumping)					Note D
32	Is damage to surrounding areas avoided?					
3 3	Are temporary work sites/disturbed areas reinstated?					
34	Is the work site confined within site boundaries?					
35	Temporary buildings located in least visually prominent locations, painted in muted / recessive colours?					
1	Culture Heritage	Yes	Yes, but need		N/A or ot observe	Photo/Remarks d
-11	Is access maintained to the grave during construction?					<u></u>
-12 -13	Is work avioded on the day of Chung Yuen Festival? Is physical distrubance of the grave avioded?					
	Notes / Issues Recorded On Site 1. Rope was absenved tied on the Support. Serve bottles	tree	, 4•	act	0-0	æ
	Corrective Actions [. The Contractor was reminded Order to present protect the been removed immediately by Contr	to ri- tre	Chore L.	the The	hope rape	- ite hers
	Signatures: IEC Representative : CLP Representative :		с	ontractor	·:	

(Name: Cellin Les) Andrew Fung

Mame: Kerth Chenny)

(Name: Kelvin Loun)