CLP Power Hong Kong Ltd

TETRA Radio Base Station at Kai Kung Leng (Construction Phase): 2<sup>nd</sup> Monthly Environmental Site Audit Report

November 2011

**Environmental Resources Management** 

21/F Lincoln House 979 King's Road Taikoo Place Island East, Hong Kong Telephone: (852) 2271 3000 Facsimile: (852) 2723 5660 E-mail: post.hk@erm.com http://www.erm.com CLP Power Hong Kong Ltd

# TETRA Radio Base Station at Kai Kung Leng (Construction Phase): 2<sup>nd</sup> Monthly Environmental Site Audit Report

November 2011

Reference 0132494

For and on b	ehalf of ERM-Hong Kong, Limited
Approved by	y: Frank Wan
Signed:	hardest r
Position:	Partner
Certified by	: Winnie Ko
Signed :	MAS
Position : In	ndependent Environmental Checker
Date :	1 November 2011

### **CONTENTS**

ENVIRONMENTAL SITE AUDIT	1
BACKGROUND	1
SITE AUDIT FINDINGS AND OBSERVATIONS	1
	BACKGROUND

## Annex A Environmental Site Audit Checklist

#### 1 ENVIRONMENTAL SITE AUDIT

#### 1.1 BACKGROUND

The construction works of *TETRA Radio Base Station at Kai Kung Leng* (the Project) has commenced on 31 August 2011.

To fulfill Conditions 2.4 and 2.5 of the Environmental Permit (EP-406/2010), monthly environmental site audit should be undertaken to ensure that the mitigation measures recommended in Project Profile (PP) submitted for direct application of an Environmental Permit under EIA Ordinance (EIAO) (PP-423/2010) are properly implemented. A monthly audit report, certified by the independent checker, should be submitted to the Director of EP.

This is the 2<sup>nd</sup> Monthly Environmental Site Audit Report presenting the key findings and observations of the site audit conducted on 19 October 2011. The reporting period covers 1 to 31 October 2011.

#### 1.2 SITE AUDIT FINDINGS AND OBSERVATIONS

The 2<sup>nd</sup> monthly environmental site audit was conducted on 19 October 2011. The findings of the site inspection are summarised in *Table 1.1* below:

#### Table 1.1Summary of Site Observations

Observations/Findings	Recommendations	Photos
Rubbish was not properly stored on site and placed in the access area.	The Contractor was recommended to store the rubbish properly at designated area.	

Remedial action for the abovementioned environmental deficiency has been taken and verified immediately during the site inspection. The rubbish was removed and stored at designated area after the site audit.

The environmental site audit checklist is appended in *Annex A*.

1

Annex A

Environmental Site Audit Checklist

E	RM		TETRA Radion Base S Construction Phase - E			С	LP	<b>@</b>	]重
In	spection Date:	19/10/201	Time:	:30	to	[2	200		
		epresentative : Representative : actor :	<u>Celine</u> <u>kefth</u> kelvi	tee Cheung n ham					
Wea	ather	/							
	idition Sunny Sunny Sunny Sunny Calm		Overcast Drizzl Humidity High Breeze Stron	Moder	Sto ate Lov	-	Hazy		
A	General			Yes	Yes, but need Improvemen		N/A or ot observed	Photo/Rem 1	arks
A1	Is the Environmental F	Permit displayed at	the entrances / exits?	$\checkmark$					
В	Air Quality			Yes	Yes, but need Improvemen		N/A or ot observed	Photo/Rem	arks
B1	Is open burning avoid	ed?		$\checkmark$					
B2	Are exposed soil surfa	aces regularly water	ed to avoid generation of du	st?			Z,	•	
В3	Are plant and equipme from powered plant)	ent well maintained	? (ie without black smoke						
B4	Are stockpiles of dusty	y material covered (	or regularly watered?	$\checkmark$					
B5	Is watering implement	ted during excavation	on?				$\square$		
B6	Is generation of dust a	avoided during loadi	ing/unloading/excavation?				$\square$		
С	Noise			Yes	Yes, but need Improvemen		N/A or ot observed	Photo/Rem 1	arks
C1	Is the Construction No (if any)	oise Permit displaye	ed at the entrances / exits?				$\checkmark$	]	
C2		oment well maintain	ied and in good operating				$\square$		
C3	Is idle equipment turn	ed off or throttled de	own?				Ń	<u>}</u>	
C4	Are powered mechani acoustic materials?	ical equipment cove	ered or shielded by					observ	uppent
C5	Are silenced equipme	nt used where prac	ticable?						
C6	Is the number of conts	struction plant being	g used minimized?				$\overline{\checkmark}$		
C7	Do air compressors ha								
C8	Do compressors operation	ate with doors close	ed?					)	
D	Water Quality			Yes	Yes, but need Improvemen		N/A or ot observed	Photo/Rem	arks
D1	Is wastewater dischar	ge license, if any, a	vailable for inspection?				$\Box$		
D2	Is drainage system ad	•						ho dra	inage
D3	Is drainage system we		am collected and				$\Box$	<u>_system</u>	<u> </u>
D4	is debris and rubbish i	ar are uramaye syst	tem conecteu anu				LL )	·	

٠

e for

disposed of properly?

D5	Are there temporary ditches for runoff discharge into appropriate					
	Watercourse?				$\nabla$	not near
	With silt retention pond?					watercourse
D6	Are there sedimentation tanks for settling runoff prior to disposal?			$\square$		
D7	Is the capacity of sedimentation tank adequate?					no Wastewater
D8	Is the sedimentation free from silt and sediment?					generated
D9	Are the temporary stockpiles located away from stream or water course?			$\square$		
D10	Are proper mitigation measures (eg. sand bag, earth bund, trench) prevent silty surface runoff leaving the site.					
D11	Toilet that connects to foul sewer or chemical toilets provided?					no toilet on size
E	Waste/Chemical Management	Yes	Yes, but need mprovemen		N/A or not observed	Photo/Remarks
E1	General refuse Accumulation avoided?	$\square$				
E2	Receptacles (e.g. rubbish bins) available?			$\square$	$\overline{\mathbf{A}}$	, <u> </u>
E3	Disposed of regularly and properly?		M	$\square$		NOTE 1
E4	Chemical waste, waste oil Is the Chemical Waste Producer Registration available for					
	inspection?	r1	<b></b> 1	······		
E5	Stored properly in designated area?					
E6	Labelled properly?				L 山 い	<u>no chemical</u>
E7 E8	Disposed of properly?					on. si72
20	Trip tickets/ chits available for inspection?			L		
E9	Chemical/fuel storage area Are all spillage containment provided for all chemicals, oils and fuels stored on site, those equipment which potentially have oil leakage and for the area where maintenance works carrying out?					
E10	Is storage area bunded?					
E11	Adequate bund capacity? (>110% of the largest tank)					
E12	Are storage areas provided with locks and located on sealed areas?					
E13	Construction Waste Reused where practicable?					
	Is sorting conducted on site?					
E14	Transported offsite for proper disposal?					
E15	Are surplus inert materials being reused where practical	بعدا				
	as an alternative to ordering imported fill material?	$\checkmark$				
E16	Excavated Material Appears uncontaminated? (colour, odour)					not observed
E17	If suspected contaminated, appropriate procedures followed?					101 003-1120
E18	Relevant license/permit/trip tickets/chits for disposal of construction waste or excavated materials available for inspection?				Ţ	
F	General / Housekeeping	Yes	Yes, but need mprovemen		N/A or not observed	Photo/Remarks
F1	Are proper housekeeping measures being maintained?		5.7			Note 1
F2	Are potential stagnant pools cleared and mosquito breeding prevented?					
	protonted :					
G	Ecology	Yes	Yes, but need	No	N/A or not observed	Photo/Remarks

Page 2 of 3

Improvement

51							
	Is damage and disturbance to the remaining and surrounding natural shrubby grassland and young woodland habitats avoided? (particularly those caused by filling and illegal dumping)						
;2	Is damage to surrounding areas avoided?						
3	Are temporary work sites/disturbed areas reinstated?					-	
<b>;4</b>	Is the work site confined within site boundaries?						
	Temporary buildings located in least visually prominent locations, painted in muted / recessive colours?						
1	Culture Heritage	Yes	Yes, but need		N/A or tot observe		Remark
		/	mproveme				
	Is access maintained to the grave during construction?						
	Is work avioded on the day of Chung Yuen Festival? Is physical distrubance of the grave avioded?						
	Notes / Issues Recorded On Site						
	1 Dippedude not another charged at	ato na	Est su	ere Di	the 1	3(10(5	arec
	1. Rubbishus not properly stored at Cotractor was recommended to place	- 11-		h at	+ dosis	okate	ed.
	Cottactor was recommended to place	e the	<del>1 UDD (+</del>	<u> </u>	)	)	
	area away from the access area.						
ļ							
ļ							
	Corrective Actions						
	Corrective Actions						
		Nace He	rubbis	n at	desip	nated	,
	Agt The Contractor was remonded to p	slace the	rubbis	n at	desig	nated	
	Aft The Contractor was remmded to p area away from access area.				5		
	Agt The Contractor was remonded to p				5		
	Aft The Contractor was remmded to p area away from access area.				5		
	Aft The Contractor was remmded to p area away from access area. - The nubbish has been placed in a				5		
	Aft The Contractor was remmded to p area away from access area. - The nubbish has been placed in a				5		
	Aft The Contractor was remmded to p area away from access area. - The nubbish has been placed in a				5		
	Aft The Contractor was remmded to p area away from access area. - The nubbish has been placed in a				5		
	Aft The Contractor was remmded to p area away from access area. - The nubbish has been placed in a				5		
	<ul> <li>\$\$\frac{1}{2}\$ The Contractor was reminded to parea away frantaccess area.</li> <li>- The pubbish has been placed in a the access area.</li> </ul> Signatures:		ated i	2 <i>ГL</i> «	aw ay		
	Aft The Contractor was reminded to p area away from access area. - The pubbish has been placed in a the access area.		ated i		aw ay		
	<ul> <li>\$\$\frac{1}{2}\$ The Contractor was reminded to parea away frantaccess area.</li> <li>- The pubbish has been placed in a the access area.</li> </ul> Signatures:		ated i	2 <i>ГL</i> «	aw ay		
	<ul> <li>\$\$\frac{1}{2}\$ The Contractor was reminded to parea away frantaccess area.</li> <li>- The pubbish has been placed in a the access area.</li> </ul> Signatures:	a design	at <i>eo</i> l d	2 <i>ГL</i> «	aw ay		

Page 3 of 3