Independent Environmental Checker (IEC)
Monthly Audit Report No. 1
12 February to 28 February 2014

(182663/B&V/001/Issue 1)

Report Authorized For Issue By:

For and on Behalf of Black & Veatch Hong Kong Limited

Black & Veatch Hong Kong Limited 25/F, Millennium City 6 392 Kwun Tong Road Kowloon Hong Kong

| EZ B&V  | Report Memorandum                                  |  |          |
|---|--|--|----------|
| Project Title  CEDD Contract No. GE/2013/16  Landslip Prevention and Mitigation P  Landslip Prevention and Mitigation V  Above Leung Fai Tin along Clear War  Study Area No.: 12NW-C/SA1 (Study | Vorks in New Territories<br>ter Bay Road, Sai Kung | Job No. 182663/2000  |          |
| Report Subject IEC Monthly Report No.1  |  | RM Ref. No.<br>182663/B&V/001/Issue 1  | Rev.     |
|   |  |  | <u> </u> |
| Requirements of Brief:  |  |  |          |
| Objectives  |  |  | 2012     |
| As stated in Study Brief  |  |  |          |
|   |  |  |          |
|   |  | and the second s |          |
| Method of Approach: Nil   |  |  |          |
|   |  |  |          |
| Tasks and Programme:  |  |  |          |
|   |  |  |          |
|   |  |  |          |
| Report Contents List:   |  |  |          |
| Refer to contents of IEC Report   |  |  |          |
|   |  |  |          |
|   |  |  |          |
|   |  |  |          |
| Author: : Esther Tong   | Signed: Cuffer                                     | Date: 3 13 1 2014  | -        |
| Checker: Manuel Chua  | Signed:  | Date: 3 131 201  | 4        |
| Reviewer: Andy Kwok   | Signed: Maly                                       | _ Date: 3/3/2014   | •        |
| Verification: Kelvin Lau  | Signed:  | Date: 3/3/16   |          |

Rev. 5 Oct 03 Form 668

| EZ. BVHKL   | Document / Drawing / Sketch / Issue Record   |                                 |       |  |  |  |  |  |
|---|--|---------------------------------|-------|--|--|--|--|--|
| Job No : 182663/2000  | Draft /Issue   | 1                               |       |  |  |  |  |  |
| CEDD Contract No. GE/2013/16  Project Title: Landslip Prevention and Mitigat Landslip Prevention and Mitigat Above Leung Fai Tin along Clea Study Area No.: 12NW-C/SA1 (S IEC Monthly Report No. 1 (12 Fe | ion Works in N<br>r Water Bay Ro<br>tudy Area H)   | ew Territories<br>oad, Sai Kung | ge J, |  |  |  |  |  |
| Document / Drawing / Sketch No. Date of Issue   |  |                                 |       |  |  |  |  |  |
| 182663/B&V/001  |  | Mar-14                          |       |  |  |  |  |  |
|   |  |                                 |       |  |  |  |  |  |
|   |  |                                 |       |  |  |  |  |  |
|   |  |                                 |       |  |  |  |  |  |
|   |  |                                 |       |  |  |  |  |  |
|   |  | ·                               |       |  |  |  |  |  |
|   |  |                                 |       |  |  |  |  |  |
|   |  |                                 |       |  |  |  |  |  |
|   |  |                                 |       |  |  |  |  |  |
|   |  |                                 |       |  |  |  |  |  |
|   |  |                                 |       |  |  |  |  |  |
|   |  |                                 |       |  |  |  |  |  |
|   |  |                                 |       |  |  |  |  |  |
|   |  | ·                               |       |  |  |  |  |  |
|   |  |                                 |       |  |  |  |  |  |
|   |  |                                 |       |  |  |  |  |  |
|   |  |                                 |       |  |  |  |  |  |
|   | ·  |                                 |       |  |  |  |  |  |
|   | ALL-PARTITION OF THE PARTITION OF THE PA |                                 |       |  |  |  |  |  |

| Amendment Record  IEC Monthly Audit Report No. 1 (February 2014) |        |              | CEDD Contract No. GE/2013/16 Landslip Prevention and Mitigation Works in New Territories | No:<br>182663/B&V/001/Issue 1<br>Prepared by:<br>B&V |  |
|--|--------|--------------|--|--|--|
|  |        |              | Client: Kwan On Construction Co. Ltd   | Initials: ET  Date: 3rd March 2014                   |  |
| Pages  | Date   | Issue<br>No. | Description  | Initials:  |  |
| All  | Mar 14 | 1            | IEC Monthly Audit Report No. 1   | ET   |  |
|  |        |              |  |  |  |
| ·  |        |              |  |  |  |
|  |        |              |  |  |  |
| -  |        |              |  |  |  |
| <u>, i </u>  |        |              |  |  |  |
|  |        |              |  |  |  |
|  |        |              |  |  |  |
|  |        |              |  |  |  |
|  |        |              |  |  |  |
|  |        |              |  |  |  |
|  |        |              |  |  |  |
|  |        |              |  |  |  |
|  |        |              |  | \  |  |
|  |        |              |  |  |  |

<sup>\*</sup> The Registered Recipient is responsible for destroying or marking as *superseded* all superseded documents.

### **CONTENTS**

|     | D  |
|-----|--|
|     | Page   |
| 1.  | INTRODUCTION2                                    |
| 1.1 | Background and Project Description2              |
| 1.2 | Types of Designated Project2                     |
| 1.3 | Location and Scale of Project3                   |
| 1.4 | Organisation and Reporting Schedule3             |
| 2.  | PROGRESS OF THE CONTRACT4                        |
| 2.1 | Status of the Environmental Licence and Permits4 |
| 2.2 | Progress of the Construction Works4              |
| 2.3 | Summary of Site Inspection and Audit             |
| 2.4 | Summary of Complaints and Prosecutions5          |
| 3.  | conclusions5                                     |
| 4.  | RECOMMENDATIONS                                  |
|     |  |

#### **FIGURES**

Figure 1

Location Plan of the Designated Project

# **APPENDICES**

Appendix A

|  | Name        | Signature | Date     |
|--|-------------|-----------|----------|
| Prepared by  | Esther Tong | Gether    | 3/3/2014 |
| Checked by   | Manuel Chua | len       | 3/3/2014 |
| Reviewed by  | Andy Kwok   | Andy-     | 3/3/2014 |
| the state of the s |             |           |          |

#### 1. INTRODUCTION

# 1.1 Background and Project Description

- 1.1.1 Geotechnical Engineering Office (GEO) of the Civil Engineering and Development Department has identified about 2700 natural hillside catchments with a known history of landslides close to existing buildings and important transport corridors based on interpretation of large-scale historical aerial photographs. Natural hillside catchments affecting individual units of existing development are further grouped into different Study Areas designated for natural terrain hazard studies by GEO.
- The natural hillside, Study Area No. 12NW-C/SA1, at Leung Fai Tin above Clear Water Bay Road in Clear Water Bay Peninsula, includes a number of hillside catchments which warrant high priority for natural terrain hazard study and mitigation actions. The location and the extent of the Study Area are shown in **Figure 1**.
- 1.1.3 The natural hillside within the Study Area has been disturbed since 1940s, and there were 3 landslides identified to have occurred on the natural hillside in 1970s. A detailed natural terrain hazard study concluded that the natural hillside within the Study Area is highly susceptible to landslide failures and the landslide debris would travel downslope and be channelised along the stream course reaching Clear Water Bay Road and the village houses at Leung Fai Tin.
- Hence, natural terrain hazard mitigation works (HMW) are required at the lower portion of the Study Area (hereinafter referred to as the "Works Area") to mitigate the potential hazards arising from natural terrain open hillslope landslides, boulder falls and channelised debris flows at the Study Area affecting Clear Water Bay Road and village houses at Leung Fai Tin downhill. The proposed natural terrain HMW includes erection of tensioned steel mesh fences (also known as flexible barrier), construction of masonry maintenance staircases and associated landscape treatments at the Works Area. The extent of the Works Area has been carefully considered to limit the extent of proposed works, necessary working space and the site access.

#### 1.2 Types of Designated Project

1.2.1 The Natural Terrain Hazard Mitigating Works at Study Area No. 12NW-C/SA 1 above Leung Fai Tin along Clear Water Bay Road, Sai Kung is referred as "Designated Project" (DP) which includes the works area of the Project falls within a Conservation Area under the approved Clear Water Bay Peninsula South Outline Zoning Plan No. S/SK-CWBS/2 and Item Q.1 Part 1 of Schedule 2 under the Environmental Impact Assessment Ordinance (EIAO). The Project Profile (Register No. PP-480/2013) was submitted for directly application of Environmental Permit (EP) on 18 March 2013. Environmental Protection Department (EPD) granted the EP (EP No.: EP-448/2013) to the GEO/Civil Engineering and Development Department (hereinafter referred to as the "Client") in 10 April 2013 to construct the Designated Project (EP) under the Environmental Impact

Assessment Ordinance (EIAO).

1.2.2 According to the EP Specific Condition Clause 2.5, the Permit Holder shall employ an Independent Environmental Checker (IEC) to audit the implementation of all mitigation measures recommended in the Project Profile and the approved Landscape and Compensatory Planting Plan, and to certify in writing in the monthly audit report full implementation of the mitigation measures during and upon completion of the construction works. The IEC shall not be in any way an associated body of the Contractor of the Project.

# 1.3 Location and Scale of Project

- 1.3.1 The proposed HMW will be constructed within the Works Area at the lower portion of the Study Area No. 12NW-C/SA1 above Clear Water Bay Road, Leung Fai Tin in Clear Water Bay Peninsula. The Works Area is located within a Conservation Area. Extent of the Works Area is approximately 6,000m<sup>2</sup> and the project comprises as follows:
  - a. Erect about 250m long, 5m-6m high flexible barrier supported by vertical and raking steel bar anchors (about 120 nos.) to be drilled and installed in ground.
  - b. Construct of 300m long, 600mm wide masonry maintenance access with handrails
  - c. Provision of soft landscape works includes pit-planting of native/shrub seedlings, plant of climbers and hydroseeding.

## 1.4 Organisation and Reporting Schedule

1.4.1 CEDD commissioned CH2M HILL Halcrow China Limited (CHMHC) as the Engineer. The Contractor of the Project is Kwan On Construction Co. Ltd (KOCCL). Black & Veatch Hong Kong Limited (B&V) was appointed as Independent Environmental Checker (IEC) on 10 February 2014. This Report covers the period from 12 February 2014 to 28 February 2014.

#### 2. PROGRESS OF THE CONTRACT

#### 2.1 Status of the Environmental Licence and Permits

2.1.1 Table 2-1 presents a summary of the status of environmental licenses and permits for this Contract.

Table 2-1 Status of Environmental Permit

| Type of Licence         | Permit/License<br>No. | Issue Date    | Covered Area  | Validity      | Status |
|-------------------------|-----------------------|---------------|---|---------------|--------|
| Environmental<br>Permit | EP-448/2013           | 10 April 2013 | Study Area No.<br>12NW-C/SA1<br>above Leung Fai<br>Tin along Clear<br>Water Bay<br>Road, Sai Kung | Whole Project | Valid  |

# 2.2 Progress of the Construction Works

2.2.1 The construction work of the Project has been commenced on 15 January 2014. During the reporting period, no construction works were being carried out during the site inspection.

# 2.3 Summary of Site Inspection and Audit

- During the reporting period, one IEC joint site inspection among CHMHC and KOCCL was conducted on 12 February 2014. One (1) *Aquilaria sinensis* (土沉香) was found collapsed during the site audit which is not related to construction work.
- 2.3.2 No non-compliance and observation were identified. Therefore, follow-up action was not required. However, three reminders were provided as below:
  - It is reminded that the Contractor shall provide tree tags to identified trees in particular to the protected species before commencement of construction. They are *Aquilaria sinensis* (土沉香) and *Pavetta hongkongensis* (香港大沙葉).
  - Protective wrapping shall be provided when the construction works are being carried out in close proximity to the retained trees.
  - According the EP Specific condition Clause 2.4, Landscape and Compensatory Planting Plan (LCPP) shall be submit at least 6 weeks before commencement of construction to EPD for approval. The LCPP was approved by EPD on 15 November 2013 (Letter reference No.: (25) in EP2/N8/O/117 Pt.1).
- 2.3.3 Initial tree survey report (January 2014) showed that some portion of flexible barrier alignment was not totally in line with the original alignment proposed in the Project Profile. The Contractor was reminded to prepare and submit the revised tree felling application for approval, if necessary. The Contractor was also reminded that two rare

and precious species of Hong Kong plant species *Aquilaria sinensis* (土沉香) and *Pavetta hongkongensis* (香港大沙葉) shall be retained in-situ and properly protected during the construction phase.

#### 2.4 Summary of Complaints and Prosecutions

- 2.4.1 No environmental complaint was recorded in the reporting period.
- 2.4.2 No prosecution was recorded in the reporting month.
- 2.4.3 No violation of the environmental permit of the Contract as listed in Table 2-1 was recorded during the reporting month.
- 2.4.4 The update statistical summary of complaint is presented in Table 2-2.

Table 2-2 Status of Complaints and Prosecution

| Donouting Dowland           | Complaint Statistics |            | Area of Concern | Validity | Status       |  |
|-----------------------------|----------------------|------------|-----------------|----------|--------------|--|
| Reporting Period            | Number               | Cumulative | Area of Concern | validity | Status       |  |
| 12 <sup>th</sup> Feb 2014 - | 0                    | 0          |                 |          |              |  |
| 28 <sup>th</sup> Feb 2014   | U                    | U          | -               | -        | <del>-</del> |  |

#### 3. **CONCLUSIONS**

- 3.1.1 During the reporting period, no construction work was carried out.
- 3.1.2 The Landscape and Compensatory Planting Plan was approved by EPD on 15 November 2013.
- One (1) Aquilaria sinensis (土沉香) was found collapsed during the site audit on 12 February 2014 which is not related to construction work.
- 3.1.4 No environmental complaint was received in the reporting month. No summon or prosecution related to the environmental issues was made against the Project in the reporting month.


#### 4. RECOMMENDATIONS

4.1.1 The Contractor was reminded to implement the relevant mitigation measures as stated in the Environmental Permit and the Contract to prevent any non-compliance throughout the construction period.

IEC Monthly Audit Report No. 1 182663/B&V/001/Issue 1 February 2014

Figure

February 2014 B&V



# Appendix A Environmental Inspection Checklist



| *************************************** |  |                            |   |                                      |              |                   | Simental inspection checkins   |
|---|--|----------------------------|---|--------------------------------------|--------------|-------------------|--|
|   |  |                            | Checklist No  | ımber:                               |              | GE/201            | 3/16_No. 1   |
| Project<br>Inspec<br>Time:              | Leung Fai Tin along Clear Water Bay Road Study Area: 12NW-C/SA1 (Study Area H)  11 February 2014                         |                            | Inspected b IEC's Repres RE's Repres ET's Repres Contractor's | sentative:<br>entative:<br>entative: |              | Mr. :             | her Tong<br>Joe Nam<br>Roy Jeung   |
| PART                                    | A: GENERAL INFORMATION   |                            |   |                                      |              | The second second | - Control of the Cont |
| Weath                                   | ner: Sunny Maze Cloudy erature: O C  |                            | Rainy   | Fine                                 |              |                   |  |
| Humid                                   |  |                            | •   |                                      |              |                   |  |
| Wind:                                   | Strong Breeze V Light  |                            | Calm  |                                      |              |                   |  |
|   | or Construction Works Observed   | , la                       | is obse   | w 1                                  |              |                   |  |
|   | commencement date of this site is on 15 Jan 2014.  | on P                       | Co O'Osso   | wen,                                 |              |                   |  |
| -                                       |  |                            |   |                                      | -            |                   |  |
| PART E                                  | 3: SITE AUDIT  | <del>ui (t w. M.C.).</del> |   |                                      |              |                   |  |
| Note:                                   | N/A: Not Applicable; Yes: Compliance; N/C: Non-Compliance; Follow Up: Observations requiring follow-Up actions           |                            | N/A   | Yes                                  | Follow<br>Up | N/C               | Photo/<br>Remarks  |
| Section                                 | 1: Construction Noise  |                            |   |                                      |              |                   |  |
| 1.01                                    | Are noisy equipment and activities positioned as far as practic from the sensitive receivers?                            | able                       | ×   |                                      |              |                   |  |
| 1.02                                    | Is silenced equipment adopted?   |                            | *   |                                      |              |                   |  |
| 1.03                                    | Is idle equipment turned off or throttled down?  |                            | X   |                                      |              |                   |  |
| 1.04                                    | Are plant and equipment kept to a minimum?   |                            | ×   |                                      |              |                   | : : : : : : : : : : : : : : : : : : :  |
| 1.05                                    | Is parallel use of noisy equipment / machinery avoided?  |                            | X   |                                      |              |                   |  |
| 1.06                                    | Are all plant and equipment well maintained and in good cond   | dition?                    | X   |                                      |              |                   |  |
| 1.07                                    | Are noise barriers or enclosures provided at areas where construction activities cause noise impact on sensitive receive | rs?                        |   |                                      |              |                   |  |
| 1.08                                    | Are hand held breakers fitted with valid noise emission labels operation?  | during                     | X   |                                      |              |                   |  |
| 1.09                                    | Are air compressors fitted with valid noise emission labels dur operation?   | ing                        | $\boxtimes$   |                                      |              |                   |  |
| 1.10                                    | Are flaps and panels of mechanical equipment closed during operation?  |                            | $\boxtimes$   |                                      |              |                   |  |
| 1.11                                    | Are Construction Noise Permit(s) applied for general construct works during restricted hours?                            | ion                        | X   |                                      |              |                   |  |
| 1.12                                    | Are valid Construction Noise Permit(s) displayed on the construction?  | uction                     | X   |                                      |              |                   |  |



3.16

mobile toilet.

Landslip Prevention and Mitigation Programme, 2008, Package J, Landslip Prevention and Mitigation Works in New Territories Above Leung Fai Tin along Clear Water Bay Road, Sai Kung Study Area No.: 12NW-C/SA1 (Study Area H)

**Environmental Inspection Checklist** 

GE/2013/16 No. 1 **Checklist Number:** Follow Photo/ N/A: Not Applicable; Yes: Compliance; N/C: Non-Compliance; N/A Yes N/C Follow Up: Observations requiring follow-Up actions Remarks Up Section 2: Air Quality П X Are the excavated materials sprayed with water during handling? 2.01 Are stockpiles of dusty materials sprayed with water, covered or M П 2.02 placed in sheltered areas? Is the exposed earth properly treated within six months after the X 2.03 last construction activities? Is the surface where any drilling, cutting, polishing or breaking 2.04 operation continuously sprayed with water? Are de-bagging, batching and mixing processes carried out in X 2.05 sheltered areas during the use of bagged cement? Are there any fencing provided along the site boundary, which 図 2.06 adjoins areas accessible to the public? Follow Photo/ N/A: Not Applicable; Yes: Compliance; N/C: Non-Compliance; Yes N/C Note: Follow Up: Observations requiring follow-Up actions Up Remarks Section 3: Water Quality N Is the discharge of turbid water avoided? 3.01 Are there proper desilting facilities in the drainage systems to 冈 3.02 reduce SS levels in effluent? Are there channels, sandbags or bunds to direct surface run-off to × 3.03 sedimentation tanks? Are there any perimeter channels provided at site boundaries to 3.04 intercept storm runoff from crossing the site? Are the maintenance access and/or anchor built within the X 3.05 Are temporary exposed slopes properly covered? 3.06 X Are earthworks final surfaces well compacted or protected? 3.08 X Are there any procedures and equipment for rainstorm protection? 3.09 Are the vehicle and plant servicing areas paved and located within 3,10 roofed areas? X Is the oil leakage or spillage avoided? 3.11 Are there any measures to collect spilt cement and concrete 3.12 washings during concreting works?  $\langle \cdot \rangle$ Are the oil interceptors/grease traps maintained properly? 3.13 Concreting wastes water should be neutralized below the pH X 3.14 Action Levels before discharge. Mobile toilets should provide on-site and located away the stream X 3.15 License collector should be employed for handling the sewage of X



|         |  | Checklist   | Number: |              | GE/2013 | 3/16_No. 1        |
|---------|--|-------------|---------|--------------|---------|-------------------|
| Note:   | N/A: Not Applicable; Yes: Compliance; N/C: Non-Compliance;<br>Follow Up: Observations requiring follow-Up actions  | N/A         | Yes     | Follow<br>Up | N/C     | Photo/<br>Remarks |
| Section | n 4: Ecology   |             |         |              |         |                   |
| 4.01    | Are the maintenance access and/or anchor built within the stream?  | $\boxtimes$ |         |              |         |                   |
| 4.02    | is there any opening (at least 0.5m allowed) between the stream bed and the bottom of the flexible barrier provide?                                      | X           |         |              |         |                   |
| 4.03    | Are protected plants species are retained in-situ?   | $\times$    |         |              |         |                   |
| 4.04    | Is there any tree pruning to damage the preserved trees?   | X           |         |              |         |                   |
| 4.05    | Are all <i>Aquilaria sinensis</i> (85 nos.) and <i>Pavetta hongkongensis</i> (10 nos.) retained in-situ and fenced off?                                  | X           |         |              |         |                   |
| 4.06    | Are there any tagged provided at retained in-situ trees?   | X           |         |              |         |                   |
| 4.07    | Are all retained trees closed to the construction works providing protective wrapping properly to minimize the damage?                                   | $\times$    |         |              |         |                   |
| 4.08    | Are only 25 nos. of non-protected trees are felled?  | $\boxtimes$ |         |              |         |                   |
| 4.09    | Are any native light standard trees provided as compensatory planting (ratio 1:3)?   | X           |         |              |         |                   |
| 4.10    | Are the proposed compensatory trees planting native and shade-tolerant trees species according to the recommendation of Project Profile?                 | $\boxtimes$ |         |              |         |                   |
| 4.11    | Is the positioning the alignment has minimum 1.5m in radius away from the alignment?   | $\boxtimes$ |         |              |         |                   |
| 4.12    | Any induction training course to all site personnel (both supervision staff and workers) to brief the persevered trees location and importance?          | X           |         |              |         |                   |
| 4.13    | Any adjustment of the foundation of flexible barriers and staircases to avoid the damage of root systems of existing trees?                              | $\boxtimes$ |         |              |         |                   |
| 4.14    | Is there any re-vegetation area to compensate the temporary loss of 200m² (due to temporary access) understorey area?                                    | $\times$    |         |              |         |                   |
| 4.15    | Is there any re-vegetation area to compensate the permanent loss of 200m² (due to maintenance access and anchor) understorey area?                       | X           |         |              |         |                   |
| Note:   | N/A: Not Applicable; Yes: Compliance; N/C: Non-Compliance; Follow Up: Observations requiring follow-Up actions   | N/A         | Yes     | Follow<br>Up | N/C     | Photo/<br>Rémarks |
| Section | 5: Landscape and Visual  |             |         |              |         |                   |
| 5.01    | Is the landscape design including the compensatory planting follow GEO Publication No. 1/2011?   | X           |         |              |         |                   |
| 5.02    | Is there any erecting of hoarding to minimize the unsightly construction activities?   | X           |         |              |         |                   |
| 5.03    | Is the hoarding with decorative panels with patterns of vegetation mature trees below the hoardings for nature screening) to minimize the visual impact? | $\boxtimes$ |         |              |         |                   |
| 5.04    | Any utilization of existing trees located in fornt of hte flexible barrier as natural screening?   | X           |         |              |         |                   |
| 5.05    | Any provision Pit-planting of native light standard trees and planting of climbers in front of the fence to provided screening effect?                   | ×           |         |              |         |                   |
|         | te the dark colour of the flexible barrier used?   | [Z]         | П       | П            | П       |                   |



|         |  | Checklist   | Number: |              | GE/2013 | /16_No. 1         |
|---------|--|-------------|---------|--------------|---------|-------------------|
| 5.07    | Are the concrete footing of the anchor and the handrails along the maintenance access painted with sub-due colour as far as practical? | $\boxtimes$ |         |              |         |                   |
| 5.08    | Are the maintenance accesses apply masonry finished to blend with surroundings?  | <b>X</b>    |         |              |         |                   |
| Note:   | N/A: Not Applicable; Yes: Compliance; N/C: Non-Compliance;<br>Follow Up: Observations requiring follow-Up actions                      | N/A         | Yes     | Follow<br>Up | N/C     | Photo/<br>Remarks |
| Section | on 6: Waste Management   |             |         |              |         |                   |
| 6.01    | Has the Waste Management Plan prepared according to ETWB TC(W) No. 19/2005 and submit to Engineer?                                     | $\boxtimes$ |         |              |         |                   |
| 6.02    | Are receptacles available for general refuse collection?   | $\times$    |         |              |         |                   |
| 6.03    | Is general refuse sorting or recycling implemented?  | X           |         |              |         |                   |
| 6.04    | Is general refuse disposed of properly and regularly?  | X           |         |              |         |                   |
| 6.05    | Is the Contractor registered as a chemical waste producer?   | X           |         |              |         |                   |
| 6.06    | Are the chemical waste containers properly labelled?   | X           |         |              |         |                   |
| 6.07    | Are the chemical wastes stored in proper storage areas?  | $\square$   |         |              |         |                   |
| 6.08    | Is the chemical waste storage area properly labelled?  | $\boxtimes$ |         |              |         |                   |
| 6.09    | Is the chemical waste storage area used for storage of chemical waste only?  | X           |         |              |         |                   |
| 6.10    | Are incompatible chemical wastes stored in different areas?  | $\times$    |         |              |         | · .               |
| 6.11    | Are the chemical wastes disposed of by licensed collectors?  | $\times$    |         |              |         |                   |
| 6.12    | Are trip tickets for chemical wastes disposal available for inspection?  | Ø           |         |              |         |                   |
| 6.13    | Are chemical/fuel storage areas bunded?  | $\times$    |         |              |         |                   |
| 6.14    | Are designated areas identified for storage and sorting of construction wastes?  | $\boxtimes$ |         |              |         |                   |
| 6.15    | Are construction wastes sorted (inert and non-inert) on site?  | 又           |         |              |         |                   |
| 6.16    | Are construction wastes reused?  | X           |         |              |         |                   |
| 6.17    | Are construction wastes disposed of properly?  | X           |         |              |         |                   |
| 6.18    | Are site hoardings and signboards made of durable materials instead of timber?   | $\boxtimes$ |         |              |         |                   |
| 6.19    | Is trip ticket system implemented for the disposal of construction wastes and records available for inspection?                        | $\boxtimes$ |         |              |         |                   |
| 6.20    | Are appropriate procedures followed if contaminated material exists?   | ×           |         |              |         |                   |
| 6.21    | Is relevant license/ permit for disposal of construction waste or excavated materials available for inspection?                        | X           |         |              |         |                   |
| 6.22    | Site cleanliness and appropriate waste management training had provided for the site workers.  | $\boxtimes$ |         |              |         |                   |



Landslip Prevention and Mitigation Programme, 2008, Package J, Landslip Prevention and Mitigation Works in New Territories Above Leung Fai Tin along Clear Water Bay Road, Sai Kung

Study Area No.: 12NW-C/SA1 (Study Area H)
Environmental Inspection Checklist

|  |  | Checklist No | umber: |              | GE/2013, | /16_No. 1         |  |  |
|--|--|--------------|--------|--------------|----------|-------------------|--|--|
| Note:  | N/A: Not Applicable; Yes: Compliance; N/C: Non-Compliance; Follow Up: Observations requiring follow-Up actions                                 | N/A          | Yes    | Follow<br>Up | N/C      | Photo/<br>Remarks |  |  |
| Sectio   | Section 7: Licence   |              |        |              |          |                   |  |  |
| 7.01   | Is relevant Environmental Permit posted at all vehicle site entrances/exits?   | $\boxtimes$  |        |              |          |                   |  |  |
| Section 8: Follow-up of the previous monthly environmental audit on date (Checklist No. GE/2013/16_No. ) |  |              |        |              |          |                   |  |  |
| Note:  | N/A: Not Applicable; Yes: Compliance; N/C: Non-Compliance;   |              |        | Follow       |          | Photo/            |  |  |
|  | Follow Up: Observations requiring follow-Up actions  | N/A          | Yes    | Up           | N/C      | Remarks           |  |  |
| 8.01   | Follow Up: Observations requiring follow-Up actions  Is the situation in item improved / rectified?  | N/A          | Yes    |              | N/C      |                   |  |  |
|  |  |              | Yes    |              | N/C      |                   |  |  |
| 8.01   | Is the situation in item improved / rectified?   |              | Yes    |              |          |                   |  |  |
| 8.01<br>8.02   | Is the situation in item improved / rectified?  Is the situation in item improved / rectified?   |              | Yes    |              | N/C      |                   |  |  |
| 8.01<br>8.02<br>8.03   | Is the situation in item improved / rectified?  Is the situation in item improved / rectified?  Is the situation in item improved / rectified? | N/A          | Yes    |              | N/C      |                   |  |  |



Contract No. GE/2013/16

Landslip Prevention and Mitigation Programme, 2008, Package J, Landslip Prevention and Mitigation Works in New Territories

Above Leung Fai Tin along Clear Water Bay Road, Sai Kung

Study Area No.: 12NW-C/SA1 (Study Area H)
Environmental Inspection Checklist

**Checklist Number:** 

GE/2013/16\_No. 1

| Remarks / Observations: |  |                     |                                  |
|-------------------------|--|---------------------|----------------------------------|
| . 4                     |  |                     |                                  |
| 土地直门                    | 199) was found denter<br>lated to construction   | during site andi    | - A-1                            |
| It is not ro            | lated to construction  | n work.             |                                  |
|                         |  |                     |                                  |
|                         |  |                     |                                  |
|                         |  |                     |                                  |
|                         |  |                     |                                  |
|                         |  |                     |                                  |
|                         |  |                     |                                  |
|                         |  |                     |                                  |
|                         |  |                     |                                  |
|                         |  |                     |                                  |
|                         |  |                     |                                  |
|                         |  |                     |                                  |
|                         |  |                     |                                  |
|                         |  |                     |                                  |
|                         |  |                     |                                  |
|                         |  |                     |                                  |
|                         |  |                     |                                  |
|                         |  |                     |                                  |
|                         |  |                     |                                  |
|                         | rduction (valid) 4 Supplementary and 1 Supplementary (see Supplementar |                     |                                  |
| Signature:              |  |                     |                                  |
| IEC's Representative    | RE's representative  | ET's representative | Contractor's representative      |
| Gerslov                 | 706  |                     | 5                                |
| Name: Ms. Esther Tong   | Name: Joe Nam  | Name:               | Name: Ry (Cov)  Date: 12/12/2014 |
| Date: 12/12/2014        | Date: 12/12/7014   | Date:               | Date: 1/2/2014                   |



**Environmental Inspection Checklist** 

**Checklist Number:** 

GE/2013/16\_No. 1

#### Observation (O) or Reminder (R) during site inspection on 11 February 2014.

Item R1: It is reminded that tree tags shall be provided for the trees being felled and retained trees. The numbers of retained trees for *Aquilaria sinensis* (土沉香) and *Pavetta hongkongensis* (香港大沙葉) are 85 and 10 respectively. The numbers of trees being felled are 25.

**Item R2**: Protective wrapping shall be provided when the construction works are carried out in close proximity to the retained trees.

Item R3: According the EP Specific condition Clause 2.4 (EP448-2013), Compensatory Planting Plan shall be submit at least 6 weeks before commencement of construction to EPD for approval. The plan shall include details of compensatory plantings and protective measures for existing trees and plants during construction. The Landscape and Compensatory Planting Plan was approved by EPD on 15 November 2013.

#### **Photo Record**



Photo 1: Aquilaria sinensis (T599) was found collapsed.




Photo 2: No construction work was observed.