Route 8 (previously known as Route 9) between Cheung Sha Wan & Sha Tin

Contract No. HY/2003/10 - Environmental Team for Lai Chi Kok Viaduct and Eagle's Nest Tunnel

Monthly EM&A Report
Part I – Lai Chi Kok Viaduct (Version 1.0)

November 2007

Approved By

(Environmental Team/Leader)

REMARKS:

The information supplied and contained within this report is, to the best of our knowledge, correct at the time of printing.

CINOTECH accepts no responsibility for changes made to this report by third parties.

CINOTECH CONSULTANTS LTD

Room 1710, Technology Park, 18 On Lai Street, Shatin, NT, Hong Kong Tel: (852) 2151 2083 Fax: (852) 3107 1388 Email: info@cinotech.com.hk

TABLE OF CONTENTS

EX	ECUTIVE SUMMARY	1
	Introduction Environmental Monitoring and Audit Works Environmental Licenses and Permits Key Information in the Reporting Month	1
1.	INTRODUCTION	3
	Background Project Organizations Construction Programme Summary of EM&A Requirements	4 4
2.	AIR QUALITY	7
	Monitoring Requirements Monitoring Locations Monitoring Equipment Monitoring Parameters, Frequency and Duration Monitoring Methodology and QA/QC Procedure Results and Observations	7 7 8
3.	NOISE	10
	Monitoring Requirements Monitoring Locations Monitoring Equipment Monitoring Parameters, Frequency and Duration Monitoring Methodology and QA/QC Procedures Maintenance and Calibration Results and Observations	10 11 11 12
4.	ENVIRONMENTAL AUDIT	13
	Site Audits Review of Environmental Monitoring Procedures Status of Environmental Licensing and Permitting Implementation Status of Environmental Mitigation Measures Summary of Exceedance Implementation Status of Event Action Plans Summary of Complaint and Prosecution	13 13 16
5.	FUTURE KEY ISSUES	18
	Key Issues for the Coming Month Monitoring Schedule for the Next Month Construction Program for the Next Month	18
6.	CONCLUSIONS AND RECOMMENDATIONS	19
	Conclusions	

LIST OF TABLES

Table I	Summary Table for Events Recorded in the Reporting Month
Table II	Summary Table for Key Information in the Reporting Month
Table 1.1	Key Project Contacts
Table 2.1	Locations for Air Quality Monitoring
Table 2.2	Air Quality Monitoring Equipment
Table 2.3	Impact Dust Monitoring Parameters, Frequency and Duration
Table 3.1	Noise Monitoring Stations
Table 3.2	Noise Monitoring Equipment
Table 3.3	Noise Monitoring Parameters, Frequency and Duration
Table 4.1	Summary of Environmental Licensing and Permit Status
Table 4.2	Observations and Recommendations of Site Audit for Civil Works
Table 4.3	Observations and Recommendations of Site Audits for TCSS
Table 4.4	Observations and Recommendations of Site Audits Followed up for Pervious Month
	for Civil Works
Table 4.5	Observations and Recommendations of Site Audits Followed up for Pervious Month
	for TCSS

LIST OF FIGURES

Figure 1 Locations of Monitoring Stations

LIST OF APPENDICES

A	Action and Limit Levels for Air Quality and Noise
В	Copies of Calibration Certificates
C	Environmental Monitoring Schedules
D	Wind Data
E	1-hour TSP Monitoring Results and Graphical Presentations
F	24-hour TSP Monitoring Results and Graphical Presentations
G	Noise Monitoring Results and Graphical Presentations
Н	Summary of Exceedance
I	Site Audit Summary
J	Event Action Plans
K	Environmental Mitigation Implementation Schedule (EMIS)
L	Construction Programme
M	Complaint Log

ABBREVIATION AND ACRONYM

AL Levels Action and Limit Levels

CEDD Civil Engineering and Development Department

E / ER Engineer/Engineer's Representative

EIA Environmental Impact Assessment

EM&A Environmental Monitoring and Audit

EMIS Environmental Mitigation Implementation Schedule

EP Environmental Permit

EPD Environmental Protection Department

ET Environmental Team

HVS High Volume Sampler

HyD Highways Department

IEC Independent Environmental Checker

NOE Notification of Exceedancee

QA/QC Quality Assurance / Quality Control

RE Resident Engineer
RH Relative Humidity
SLM Sound Level Meter

TSP Total Suspended Particulates

EXECUTIVE SUMMARY

Introduction

This is the 48th monthly Environmental Monitoring and Audit (EM&A) Report prepared by Cinotech Consultants Limited for the "Route 8 (previously known as Route 9) between Cheung Sha Wan & Sha Tin, Lai Chi Kok Viaduct & Eagle's Nest Tunnel". This report documents the findings of EM&A Works conducted in November 2007 for Contract No. HY/2003/01, Lai Chi Kok Viaduct (the Project).

The major site activities for civil works undertaken in the reporting month included:

- Retaining wall construction at CCR-R2 & CCR-R3 and LCK-R2 to LCK-R3.
- Slope upgrading works for Feature No. 11NW-A/FR 54 & A/FR55.
- Drainage works at Lai Po Road and Castle Peak Road
- Offsite fabrication of top rail of parapet.
- Erection of noise barrier and signage at slip roads A, B C, D and Main Viaduct.
- Installation of E&M works in Wai Man Tsuen pump house, Irrigation Pump House near pier C14 and Lai Po Road pump house.
- RSSM and slope drains for slope CCR-S4.
- Road works at main viaduct, slip roads C & D, Lai Po Road, Butterfly Valley Interchange, Butterfly Valley Road and Ching Cheung Road.
- Feature walls construction for landscape hardworks at Lai Po Road.

The major site activities for Traffic Control and Surveillance System (TCSS) works undertaken in the reporting month included:

- SCT for cables at Section A, B, C, D, E, F, G and Kiosk K2;
- SCT for Field Equipment at Sections A, B, C, D, E, F and G; and
- Installation of Equipment Cabinet at Kiosk K2.

Environmental Monitoring and Audit Works

Environmental monitoring and audit works for the Project was performed regularly as stipulated in the updated EM&A Manual and the results were checked and reviewed. Site audits were conducted once per week. The implementation of the environmental mitigation measures, Event Action Plans and environmental complaint handling procedures were also checked.

• Summary of the events and action taken in the reporting month is tabulated in **Table I**.

 Table I
 Summary Table for Events Recorded in the Reporting Month

 Parameter	No. of 1	Events	No. of Events	Action Taken
1 al allietei	Action Level	Limit Level	Due to the Project	Action Taken
1-hr TSP	1-hr TSP 0 0		0	N/A
24-hr TSP	0	0	0	N/A
Noise	0	0	0	N/A

Environmental Licenses and Permits

Licenses/Permits granted to the Project include the Environmental Permit (EP) for the Project, the Water Discharge Licenses (WDLs) and the Construction Noise Permits (CNPs). One new CNP was issued to the Project by EPD in the reporting month.

Key Information in the Reporting Month

Summary of key information in this reporting month is tabulated in **Table II**.

Table II Summary Table for Key Information in the Reporting Month

Event	Event Details		Action Taken	Status	Remark
Event	Number	Nature	Action Taken	Status	Kemark
Complaint received	2	Noise	Investigation report was submitted	Closed	
	2	Air quality	Investigation report was submitted	Closed	
Changes to the assumptions and key construction / operation activities recorded	0		N/A	N/A	
Status of submissions under EP	0		N/A	N/A	
Notifications of any summons & prosecutions received	0		N/A	N/A	

Future Key Issues:

Major site activities for civil works in the coming month include:

- Retaining wall construction at CCR-R2 & CCR-R3 and LCK-R2 to LCK-R3.
- Slope upgrading works for Feature No. 11NW-A/FR 54 & A/FR55.
- Drainage works at Lai Po Road and Castle Peak Road
- Offsite fabrication of top rail of parapet.
- Erection of noise barrier and signage at slip roads A, B C, D and Main Viaduct.
- Construction of Wai Man Tsuen pump house, Irrigation Pump House near pier C14, kiosk at CCR-S1 and Lai Po Road pump house
- Hydro-multching and tree planting for slope CCR-S4.
- Roadworks at mainviaduct, slip roads C & D, Lai Po Road, Butterfly Valley Interchange and Butterfly Valley Road.

Major site activities for TCSS works in the coming month include:

• SAT for TCSS equipment at Section A, B, C, D, E, F, G and Kiosk K2.

The anticipated environmental issues will be mainly on dust impact from retaining wall construction, slope upgrading works and noise nuisance from construction of Wai Man Tsuen Pump House, Irrigation Pump House and Lai Po Road pump house.

1. INTRODUCTION

Background

- 1.1 Route 9 (Kowloon Section) (R9K) (hereinafter call the R9K-Project) forms part of the Route 9 between Cheung Sha Wan and Sha Tin (R9-CSWST) project, which will be a new expressway connecting West Kowloon and Sha Tin. It will be the fourth external link between Sha Tin and Kowloon and will form an important link between the northeast New Territories and the west Kowloon, Lantau Island and the western New Territories. R9K is being managed and implemented by the Highways Department (HyD).
- 1.2 The engineering design of R9K is covered under Agreement No. CE 50/98 "Route 9 between Cheung Sha Wan and Sha Tin Design Construction Assignment". The main consultant engaged under Agreement No. CE 50/98 is Maunsell Hyder Joint Venture (MHJV), who will act as the Engineer for the construction contracts. The works of R9K mainly comprise a 1.4km dual 3-lane Lai Chi Kok Viaduct from Lai Wan Interchange to Butterfly Valley; 0.5 km of dual 3-lane at-grade carriageway linking to the 2.1 km dual 3-lane twin-bore Eagle's Nest Tunnel with associated portal buildings; a toll plaza with an administration building located with the Sha Tin valley woodland; a ventilation building and an adit; associated noise barriers, noise enclosures, drainage, slope and landscape works; and electrical and mechanical works for the whole R9-CSWST. The remainder of the R9-CSWST forms the Sha Tin Section (R9S) of the project and is being managed and implemented separately by the Civil Engineering and Development Department (CEDD).
- 1.3 The R9-CSWST project is a Designated Project under the Environmental Impact Assessment Ordinance (Cap. 499) (EIAO). An environmental impact assessment (EIA) report has been prepared in 1998 for the R9-CSWST project (1998 R9 EIA) to consider the key issues of noise, air quality, water quality, ecological, construction waste, landscape and visual, land use and cultural impacts, and identify possible mitigation measures.
- 1.4 An Updated Final EIA report was subsequently completed in September 1999 for the R9-CSWST project (1999 R9 EIA), to cater for some changes in R9K portion as mentioned in paragraph 1 in the report. The 1999 R9 EIA was endorsed by Environmental Protection Department (EPD) in November 1999. The 1998 R9 EIA and the 1999 R9 EIA (R9 EIA Reports) were included in the EIA register under the EIAO as report no. EIA-135/BC and AEIAR-022/1999 respectively. Environmental Monitoring and Audit (EM&A) Manuals for each of the R9 EIA Reports (EM&A Manuals) were also included as part of the EIA reports in the register.
- 1.5 Subsequent to the endorsement of the R9 EIA Reports by EPD in November 1999, the project programme was deferred to start in 2002/2003 for completion by 2006/07. The implementation of the project was then separated into the R9S and R9K portion. An Environmental Permit (EP) No. EP-103/2001 was issued on 17 September 2001 for R9K to the HyD as Permit Holder and a varied EP No. EP-103/2001/A was subsequently issued on 20 May 2003 for R9K (R9K EP) to HyD as Permit Holder. A varied EP-103/2001/C was recently issued on 22 July 2005.

- 1.6 The major construction activities of two civil contracts of the R9K project, Contract No. HY/2003/01 entitled "Route 9 Lai Chi Kok Viaduct" and Contract No. HY/2003/02 entitled "Route 9 Eagle's Nest Tunnel and Associated Works", were commenced in 15th December 2003 for completion in April 2007.
- 1.7 "Route 9" was recently re-titled as "Route 8 (previously known as Route 9)". Cinotech Consultants Limited (Cinotech) was commissioned by HyD to undertake the Environmental Monitoring and Audit works for "Route 8 between Cheung Sha Wan and Sha Tin Environmental Team (ET) for Lai Chi Kok Viaduct and Eagle's Nest Tunnel (Contract No. HY/2003/10)". Dr. Priscilla CHOY of Cinotech Consultants Ltd. was appointed as the ET Leader under Condition 2.2 of the EP. Mr. Kenneth LUK of CH2M HILL Hong Kong Ltd. was appointed as the IEC under Condition 2.1 of the EP. This is the 48th monthly EM&A report summarizing the EM&A works for the Project in November 2007.

Project Organizations

- 1.8 Different parties with different levels of involvement in the project organization include:
 - Project Proponent Major Works Project Management Office (MWPMO) of Highways Department (HyD)
 - Engineer (E) / Engineer's Representative (ER) Maunsell-Hyder Joint Venture
 - Environmental Team (ET) Cinotech Consultants Limited
 - Independent Environmental Checker (IEC) CH2M HILL Hong Kong Limited
 - Contractor Acciona Infraestructuras S.A.
 - Engineer's Representative for TCSS works Ove Arup & Partners Hong Hong Limited
 - Contractor for TCSS works Delcan-Imtech-Gtech Joint Venture
- 1.9 The responsibilities of respective parties are detailed in Section 1.8.3 of the EM&A Manual (1999) of the Project.
- 1.10 The key contacts of the Project are shown in **Table 1.1**.

Construction Programme

- 1.11 The site activities for civil works undertaken in the reporting month included:
 - Retaining wall construction at CCR-R2 & CCR-R3 and LCK-R2 to LCK-R3.
 - Slope upgrading works for Feature No. 11NW-A/FR 54 & A/FR55.
 - Drainage works at Lai Po Road and Castle Peak Road
 - Offsite fabrication of top rail of parapet.
 - Erection of noise barrier and signage at slip roads A, B C, D and Main Viaduct.
 - Installation of E&M works in Wai Man Tsuen pump house, Irrigation Pump House near pier C14 and Lai Po Road pump house.
 - RSSM and slope drains for slope CCR-S4.
 - Road works at main viaduct slip roads C & D, Lai Po Road, Butterfly Valley Interchange, Butterfly Valley Road and Ching Cheung Road.
 - Feature walls construction for landscape hardworks at Lai Po Road.

- 1.12 The site activities for TCSS works undertaken in the reporting month included:
 - SCT for cables at Section A, B, C, D, E, F, G and Kiosk K2;
 - SCT for Field Equipment at Sections A, B, C, D, E, F and G; and
 - Installation of Equipment Cabinet at Kiosk K2.

Table 1.1 Key Project Contacts

Party	rty Role Name		Position	Phone No.	Fax No.		
		Mr. Kroc Leung	SE2/R8K	2762 3662			
HyD	Permit Holder	Mr. Esther Yung	E1/R8K	2762 3677	2714 5198		
		Mr. LC Chung	E2/R8K	2762 3613			
	Engineer	Mr. Conrad Ng	Project Manager	2605 6262	2691 2649		
		Mr. Peter Poon	CRE	2959 0010			
MHJV	Engineer's	Mr. Henry Liu	SRE	2991 1068	2959 0290		
	Representative	Mr. Alan Chan	IOW	9860 8791	2939 0290		
		Mr. Alex Tam	RE	9856 0199			
		Dr. Priscilla Choy	ET Leader	2151 2089			
Cinotech	Environmental	Mr. Grace Wong	Audit Team Leader	2151 2092	3107 1388		
	Team	Mr. Henry Leung	Monitoring Team Leader	2151 2087	3107 1300		
CH2M	Independent Environmental	Mr. Kenneth Luk	Independent Environmental Checker	2507 2209	2507 2293		
CHZM	Checker	Mr. Roy Leung	Assistant Independent Environmental Checker	2872 2931	2307 2293		
Acciona	a Contractor Mr. William D. Payne		Project Director	2956 3300	2956 3331		
Acciona	Contractor	Mr. Lawrence Kwok	QA/E Manager	2930 3300	2930 3331		
ADUD	Engineer's	Mr. Donald Leung	RE	2436 7489	2426 1002		
ARUP	Representative (TCSS)	Mr. Daniel So	ARE	2436 7435	2436 1803		
DIGJV	DIGJV Contractor (TCSS) Ms. Joyce Chan		Quality Manager	2123 0845	2123 0889		
24-hour Er	24-hour Emergency Hotline						

Summary of EM&A Requirements

- 1.13 The EM&A programme requires construction phase monitoring for air quality and construction noise, and environmental site audit. The EM&A requirements for each parameter are described in the following sections, including:
 - All monitoring parameters;
 - Action and Limit levels for all environmental parameters;
 - Event Action Plans;
 - Environmental mitigation measures, as recommended in the project EIA study final report; and
 - Environmental requirements in contract documents.
- 1.14 The advice on the implementation status of environmental protection and pollution control/mitigation measures is summarized in Section 4 of this report.
- 1.15 This report presents the environmental monitoring results, observations, locations, equipment, period, methodology and QA/QC procedures of the required monitoring parameters, namely dust and noise levels and audit works for the Project in the reporting month.

2. AIR QUALITY

Monitoring Requirements

2.1 Monitoring of 1-hour and 24-hour TSP was conducted to monitor the air quality. **Appendix** A shows the established Action/Limit Levels for the environmental monitoring works.

Monitoring Locations

2.2 One designated monitoring station, AM2 was selected for impact dust monitoring for the Project. **Table 2.1** describes the air quality monitoring location, which is also depicted in **Figures 1**.

Table 2.1 Locations for Air Quality Monitoring

Monitoring Station	Description	Location	
AM2	Lai Chi Kok Park Sports Centre	Rooftop	

Monitoring Equipment

2.3 **Table 2.2** summarizes the equipment used for the air quality monitoring. Copies of calibration certificates are attached in **Appendix B**.

Table 2.2 Air Quality Monitoring Equipment

Equipment	Equipment Model and Make	
Calibrator GMW25; S/N: 1536		1
HVS Sampler	Graseby GMW Model GS2310 High Volume TSP Sampler and associated equipment and shelter	1

Monitoring Parameters, Frequency and Duration

2.4 **Table 2.3** summarizes the monitoring parameters and frequencies of impact dust monitoring for the whole construction period. The air quality monitoring schedule for the reporting period is shown in **Appendix C**.

 Table 2.3
 Impact Dust Monitoring Parameters, Frequency and Duration

Parameters	Frequency
1-hr TSP	Three times / 6 days
24-hr TSP	Once / 6 days

Monitoring Methodology and QA/QC Procedure

Instrumentation

2.5 Graseby GMW Model GS2310 TSP High Volume Sampler (HVS) was employed for 1-hour & 24-hour TSP monitoring. The sampler was composed of a motor, a filter holder, a flow controller and a sampling inlet and its performance specification complied with that required by USEPA Standard Title 40, Code of Federation Regulations Chapter 1 (Part 50). Moreover, the HVS also met all the requirements in Sections 2.2 to 2.4 of the EM&A Manual (1999).

Operating/Analytical Procedures

- 2.6 Operating/analytical procedures for the operation of HVS were as follows:
 - A horizontal platform was provided with appropriate support to secure the samplers against gusty wind.
 - No two samplers were placed less than 2 meters apart.
 - The distance between the sampler and an obstacle, such as buildings, was at least twice the height that the obstacle protrudes above the sampler.
 - A minimum of 2 meters of separation from walls, parapets and penthouses was required for rooftop samples.
 - A minimum of 2 meters separation from any supporting structure, measured horizontally was required.
 - No furnaces or incineration flues were nearby.
 - Airflow around the sampler was unrestricted.
 - The sampler was more than 20 meters from the drip line.
 - Any wire fence and gate, to protect the sampler, should not cause any obstruction during monitoring.
- 2.7 Prior to the commencement of the dust sampling, the flow rate of the high volume sampler was properly set (between 1.1 m³/min. and 1.4 m³/min.) in accordance with the manufacturer's instruction to within the range recommended in USEPA Standard Title 40, CFR Part 50.
- 2.8 For TSP sampling, fiberglass filters (G810) were used.
- 2.9 The power supply was checked to ensure the sampler worked properly.
- 2.10 On sampling, the sampler was operated for 5 minutes to establish thermal equilibrium before placing any filter media at the designated air monitoring station.
- 2.11 The filter holding frame was then removed by loosening the four nuts and a weighted and conditioned filter was carefully centered with the stamped number upwards, on a supporting screen.
- 2.12 The filter was aligned on the screen so that the gasket formed an airtight seal on the outer edges of the filter. Then the filter holding frame was tightened to the filter holder with swing bolts. The applied pressure should be sufficient to avoid air leakage at the edges.

- 2.13 The shelter lid was closed and secured with the aluminum strip.
- 2.14 The timer was then programmed. Information was recorded on the record sheet, which included the starting time, the weather condition and the filter number (the initial weight of the filter paper can be found out by using the filter number).
- 2.15 After sampling, the filter was removed and sent to the laboratory for weighing. The elapsed time was also recorded.
- 2.16 Before weighing, all filters were equilibrated in a conditioning environment for 24 hours. The conditioning environment temperature should be between 25°C and 30°C and not vary by more than ±3°C; the relative humidity (RH) should be < 50% and not vary by more than ±5%. A convenient working RH is 40%.

Maintenance/Calibration

- 2.17 The following maintenance/calibration was required for the HVS:
 - The high volume motors and their accessories were properly maintained. Appropriate maintenance such as routine motor brushes replacement and electrical wiring checking were made to ensure that the equipment and necessary power supply are in good working condition.
 - High volume samplers were calibrated at bi-monthly intervals using GMW-25 Calibration Kit throughout all stages of the air quality monitoring.

Results and Observations

- 2.18 All TSP monitoring was conducted as scheduled in this reporting month. No Action/Limit Level exceedance for both 1-hr and 24-hr TSP was recorded in the reporting month.
- 2.19 Wind data monitoring equipment has been installed in Shatin Heights for logging wind speed and wind direction. These wind data for the reporting month is summarized in **Appendix D**.
- 2.20 The monitoring data and graphical presentations of 1-hour and 24-hour TSP monitoring results are shown in **Appendices E** and **F**, respectively.

3. NOISE

Monitoring Requirements

- 3.1 Monitoring and audit of construction noise levels is required to be conducted, in accordance with the EM&A Manual, to ensure that any unacceptable noise impacts could be readily detected and timely and appropriate action be undertaken to rectify the situation.
- 3.2 The construction noise levels shall be measured in terms of the A-weighted equivalent continuous sound pressure level (Leq). Leq (30min) shall be used as the monitoring parameter for the time period between 0700-1900 hours on normal weekdays. For all other time periods, Leq (5min) shall be employed for comparison with the Noise Control Ordinance (NCO) criteria. As supplementary information for data auditing, statistical results such as L₁₀ and L₉₀ shall also be obtained for reference.
- 3.3 Five designated noise monitoring stations, namely NM2, NM4, NM8a, NM8b and NM9 were selected for impact monitoring. **Appendix A** shows the established Action and Limit Levels for the environmental monitoring works.

Monitoring Locations

3.4 Noise monitoring was conducted at five designated monitoring stations as summarized in **Table 3.1**. **Figures 1** show the locations of these stations.

Table 3.1 Noise Monitoring Stations

Stations ⁽¹⁾	Description	Location
NM2 Lai Chi Kok Correctional Institution		Rooftop
NM4	Mei Foo Sun Chuen, Phase 5	Rooftop of Block 9
NM8a	Nob Hill	M/F of Car Park
NM8b	Nob Hill	3/F of Car Park
NM9	Hoi Lai Estate	G/F of Hoi Fai House

⁽¹⁾ The Lai Chi Kok Hospital (NM3) was also found vacated and noise monitoring has been suspended since January 2005, as approved by EPD on 15th March 2005.

3.5 Stations NM8a and NM8b were installed at Nob Hill in May 2004. Station NM8b is located at 3/F of the car park of Nob Hill, which is strongly influenced by traffic noise from Ching Cheung Road. The measurement at this station is for reference purpose, but not for compliance check of construction noise. The measured noise level at Station NM8a, which is located at M/F of car park and closer to the construction site, acts as an indicator of the construction noise. Since the domestic premises are located above 5/F, noise assessment would be performed to assess the level of nuisance resulting from the construction noise at the domestic premises whenever the measured noise level at NM8a exceeds the noise limit level.

- 3.6 The noise monitoring at Lai Chi Kok Correctional Institution (NM2), which was formerly known as Lai Chi Kok Reception Centre, has been resumed since 8th September 2006 after the completion of the renovation works.
- 3.7 A new housing estate, Hoi Lai Estate, became one of the noise sensitive receivers close to the Project site. As recommended by the Regional (West) Office of EPD, noise monitoring at this location (Station NM9) was newly included in the EM&A programme. Approval for the change of EM&A programme was granted by EPD on 30th December 2004.

Monitoring Equipment

3.8 **Table 3.2** summarizes the noise monitoring equipment model being used. Copies of calibration certificates are attached in **Appendix B**.

Table 3.2 Noise Monitoring Equipment

Equipment	Model and Make	Qty.
Integrating Sound Level Meter	B&K Model 2238	5
Calibrator	B&K 4231	2
Wind Speed Anemometer	RS232 Integral Vane Digital Anemometer	1

Monitoring Parameters, Frequency and Duration

3.9 **Table 3.3** summarizes the monitoring parameters, frequency and total duration of monitoring. The noise monitoring schedule is shown in **Appendix C**.

 Table 3.3
 Noise Monitoring Parameters, Frequency and Duration

Stations	Parameter	Period	Frequency	Measurement
NM2	L ₁₀ (30 min.)dB(A) L ₉₀ (30 min.)dB(A) L _{eq} (30 min.)dB(A)			Façade
NM4				Façade
NM8a		0700-1900 hrs. on weekdays	Once per week	Façade
NM8b		on condays	3611	Façade
NM9				Façade

Monitoring Methodology and QA/QC Procedures

- The Sound Level Meter was generally set on a tripod at a height of 1.2 m above the ground, depending to the actual monitoring condition.
- The battery condition was checked to ensure the correct functioning of the meter.
- Parameters such as frequency weighting, the time weighting and the measurement time were set as follows:

frequency weightingtime weightingFast

time measurement : 30 minutes / 5 minutes

• Prior to and after each noise measurement, the meter was calibrated using a Calibrator for

- 94.0 dB at 1000 Hz. If the difference in the calibration level before and after measurement was more than 1.0 dB, the measurement would be considered invalid and repeat of noise measurement would be required after re-calibration or repair of the equipment.
- The wind speed was frequently checked with the portable wind meter.
- At the end of the monitoring period, the L_{eq} , L_{90} and L_{10} were recorded. In addition, site conditions and noise sources were recorded on a standard record sheet.
- Noise measurement was paused during periods of high intrusive noise if possible and observation was recorded when intrusive noise was not avoided.
- Noise monitoring was cancelled in the presence of fog, rain, and wind with a steady speed exceeding 5 m/s, or wind with gusts exceeding 10 m/s.

Maintenance and Calibration

- 3.10 The microphone head of the sound level meter and calibrator was cleaned with soft cloth regularly.
- 3.11 The meters were sent to the supplier to check and calibrate on a yearly interval.

Results and Observations

- 3.12 Noise monitoring was performed at the five designated locations (NM2, NM4, NM8a, NM8b and NM9) as scheduled in the reporting month.
- 3.13 All the Construction Noise Levels (CNLs) reported in this report, except those collected at Stations NM8a, NM8b and NM9, were adjusted with the corresponding baseline level (i.e. Measured Leq Baseline Leq = Measured CNL), in order to facilitate the interpretation of the noise exceedance.
- 3.14 Noise monitoring results and graphical presentations are shown in **Appendix G**.
- 3.15 No Action/Limit Level exceedance was recorded in the reporting month.
- 3.16 At Stations NM8a and NM8b, the major noise source identified during the monitoring exercises was mainly the road traffic noise.
- 3.17 At Stations NM2, NM4 and NM9, construction noise from the Project and occasionally the traffic noise were identified as the major noise source during monitoring.

4. ENVIRONMENTAL AUDIT

Site Audits

- 4.1 Site audits were carried out by ET on weekly basis to monitor the timely implementation of proper environmental management practices and mitigation measures in the Project site. The summaries of site audits are attached in **Appendix I**.
- 4.2 Site audits for Civil contract were conducted on 7th, 14th, 21st and 28th November 2007 by ET. A joint site audit for Civil works was conducted on 7th November 2007 with representatives from, IEC, ER, the Contractor and ET while the joint site audit for TCSS works was conducted on 7th November 2007 with the representatives from IEC, ER, the Contractor and ET. No environmental deficiency was recorded for TCSS contract during site inspections.

Review of Environmental Monitoring Procedures

4.3 The monitoring works conducted by the monitoring team were inspected regularly. The following observations have been recorded for the monitoring works:

Air Quality Monitoring

- The monitoring team recorded all observations around the monitoring stations within and outside the construction site.
- The monitoring team recorded the temperature and weather conditions on the monitoring days.

Noise Monitoring

- The monitoring team recorded all observations around the monitoring stations, which might affect the monitoring result.
- Major noise sources were identified and recorded. Other intrusive noise attributing to the result was trimmed off by pausing the monitoring temporarily.

Status of Environmental Licensing and Permitting

4.4 All valid permits/licenses obtained for the Project are summarized in **Table 4.1**. One new CNP was issued to the Project in the reporting month.

Implementation Status of Environmental Mitigation Measures

4.5 According to the Environmental Permit and the EM&A Manuals, the mitigation measures detailed in the documents are required to be implemented. An updated summary of the EMIS is provided in **Appendix K**.

Table 4.1 Summary of Environmental Licensing and Permit Status

Permit No.	Valid	Period	Details	Status
rermit No.	From	To	Details	
Environmental Per	mit (EP)	<u>. </u>		
EP-103/2001/C	22/7/05	N/A	Construction and operation of (a) All civil works (including highways, traffic, geotechnical, drainage, structural, architectural and landscaping works) for the Lai Chi Kok Viaduct, the interchange with Ching Cheung Road, the main road within Butterfly Valley and the Eagle's Nest Tunnel; (b) All E&M works (including ventilation, Traffic Control & Surveillance System (TCSS), toll collection system and lighting) for the whole Route 9 between Cheung Sha Wan and Sha Tin; © The permanent slope works above the northern portal of the Eagle's Nest Tunnel; (d) The architectural works (including fitting out and furnishings) of the portal buildings of the Sha Tin Heights Tunnel.	Valid
Registration of Che	emical Wast	e Producer		
WPN 5213-261-	17/11/03	N/A	N/A	Valid
N2413-04				
Water Discharge L	isence			
EP482/260/251/1	05/12/03	31/12/08	Discharge of industrial trade effluent arising from the construction site at Route 9 – Lai Po Road Section of Lai Chi Kok Viaduct (Contract HY/2003/01).	Valid
EP482/260/251/2	15/12/03	31/12/08	Discharge of industrial trade effluent arising from the construction site at Route 9 – Lai Chi Kok Viaduct excluding Lai Po Road Section.	Valid
Construction Noise	Permit (CN	(P)		
GW-RW0328-07	08/07/07	04/11/07	Location: Ching Cheung Road near Nob Hill, Lai Chi Kok, Kowloon Time Period: 0900-2300 (general holiday including Sundays).	Expired
GW-RW0323-07	30/06/07	28/12/07	Location: Ching Cheung Road section between Ching Lai Court and Castle Peak Road Time Period: 0700-2300 (general holiday including Sundays) and 1900-2300 (any day not being a general holiday).	Valid
GW-RW0329-07	08/07/07	02/12/097	Location: Ching Cheung Road near Mei Foo Sun Chuen,, Kowloon Time Period: 0900-1900 (general holiday including Sundays).	Valid
GW-RW0349-07	15/07/07	11/11/07	Location: Ching Cheung Road section between Nob Hill and Castle Peak Road Time Period: 0900-2100 (anyone day being a general holiday, including Sundays).	Expired
GW-RW0378-07	28/07/07	27/12/07	Location: Ching Cheung Road near Mei Foo Sun Cheun, Kowloon Time Period: 0700-2300 (general holiday including Sundays) and 1900-2300 (any day not being a general holiday).	Valid
GW-RW0409-07	19/08/07	30/12/08	Location: Ching Cheung Road section between Nob Hill and Castle Peak Road, Lai Chi Kok Time Period: 0900-1900 (general holiday including Sundays).	Valid

Permit No.	Valid Period		Details	Status	
i crimit ivo.	From	To	Details	Status	
GW-RW0419-07	23/08/07	20/02/08	Location: Ching Cheung Road near Castle Peak Road, Kowloon Time Period: 0000-0600(any day not being a general holiday or not immediately following a general holiday including Sundays).	Valid	
GW-RW0465-07	22/09/07	21/02/08	Location: Butterfly Valley Road, Lai Chi Kok, Kowloon Time Period: 1900-2300 (any day not being a general holiday) and 0700-2300 (General holidays including Sundays).	Valid	
GW-RW0466-07	15/09/07	12/12/07	Location: Kom Tsun Street near Lai Chi Kok Reception Centre, Kowloon Time Period: 2300-2400 (any day not being a general holiday if the preceding day is a general holiday), 0000-0700 and 2300-2400(any day not being a general holiday if the preceding day is not a general holiday).	Valid	
GW-RW0470-07	23/09/07	23/12/07	Location: Lai Po Road Near Hoi Lai Estate, Lai Chi Kok, Kowloon Time Period: 0900-1900 (general holidays including Sundays)	Valid	
GW-RW0477-07	28/09/07	27/03/08	Location: Butterfly Valley, Lai Chi Kok, Kowloon Time Period: 0700-2300 (general holidays including Sundays) and 1900-2300(any day not being a general holiday).	Valid	
GW-RW0478-07	30/09/07	29/03/08	Location: Junction of Ching Cheung Road and Castle Peak Road <i>Time Period</i> : 0700-2300 (general holidays including Sundays) and 1900-2300(any day not being a general holiday).	Valid	
GW-RW0514-07	07/10/07	30/12/07	Location: Castle Peak Road near Ching Cheung Road, Kwai Chung, N.T. Time Period: 0700-2300 (general holidays including Sundays) and 1900-2300(any day not being a general holiday)	Valid	
GW-RW0589-07	11/11/07	27/01/08	Location: Butterfly Valle Road near, Lai Chi Kok Reception Centre, Kowloon Time Period: 0900-1900 (general holidays including Sundays).	Valid	

4.6 During site inspections in the reporting month, no non-conformance was identified. The observations and recommendations are summarized in **Table 4.2** and **Table 4.3**.

Table 4.2 Observations and Recommendations of Site Audits for Civil Works

Parameters	Date	Observations and Recommendations	Follow-up
Water Quality	7-Nov-07	Reminder Standing water was observed under the bridge at Nob Hill. The Contractor was reminded to spray the larvicide oil to prevent mosquito breed.	The situation was found improved / rectified during the audit on 14 th November 07.
<u>2</u> y	14-Nov-07	Reminder Standing water was observed in the drip tray at D12. The Contractor was reminded to dry it out to prevent mosquito breeding.	The situation was found improved / rectified during the audit on 21 st November 07.
Air Quality	28-Nov-07	Observation The haul road was found to the dusty at Mui Kong Tsuen. The Contractor was advised to clean the haul road to suppress the dust generation.	This item will be followed up on the next site audit.
	28-Nov-07	Reminder General refuse was found dumping at S4. The Contractor was reminded to clear the refuse.	This item will be followed up on the next site audit.

Table 4.3 Observations and Recommendations of Site Audits for TCSS

Parameters	Date	Observations and Recommendations	Follow-up
-	-	-	-

4.7 The observations and recommendations arising from pervious month and followed up in the reporting month are summarized in **Table 4.4 and Table 4.5**.

Table 4.4 Observations and Recommendations of Site Audits Followed up for Pervious Month for Civil Works

Parameters	Date	Observations and Recommendations	Follow-up
-	-	-	-

Table 4.5 Observations and Recommendations of Site Audits Followed up for Pervious Month for TCSS

Parameters	Date	Observations and Recommendations	Follow-up
-	-	-	-

Summary of Exceedance

1-hr and 24-hr TSP Monitoring

4.8 No Action/Limit Level exceedance was recorded in the reporting month.

Construction Noise Monitoring

4.9 No Action/Limit Level exceedance was recorded in the reporting month.

Implementation Status of Event Action Plans

4.10 The Event Action Plans for air quality and construction noise are presented in **Appendix J**.

Summary of Complaint and Prosecution

- 4.11 Two public complaints were received in the reporting month.
- 4.12 The first complaint was referred by the Resident Site Staff (RSS) on 19th November 2007. It was raised by a resident via The Integrated Complaint Centre (ICC) on 16 November 2007 about the noise generated from breaking the footpath on King Lai Path opposite to Nob Hill on 16 November 2007. The complaint was considered unjustifiable and the complaint investigation report was submitted to HyD on 21st November 2007.

The second complaint was referred by the Resident Site Staff (RSS) on 21^{st} November 2007. It was raised by a resident via The Integrated Complaint Centre (ICC) on 21^{st} November 2007 about the construction dust generated from the lorry (JA2315) leaving the works site opposite to Lai Chi Kok Park Sports Centre at 8:35am on 21^{st} November 2007. The complaint was considered unjustifiable and the complaint investigation report was submitted to HyD on 26^{th} November 2007.

4.13 There were 41 environmental complaints referred to the ET and 1 prosecution received since the commencement of the Project. The Complaint Log is attached in **Appendix M**.

5. FUTURE KEY ISSUES

Key Issues for the Coming Month

- 5.1 Key issues to be considered in the coming month include:
 - Construction noise from slope stabilization works at slope upgrading works for Feature No. 11NW-A/FR 54 & A/FR55, construction of pump station and retaining wall at CCR-R2 & CCR-R3 and LCK-R2 to LCK-R3;
 - Dust generation from stockpiles or any other dusty materials.

Monitoring Schedule for the Next Month

5.2 The tentative monitoring schedule for the next month is shown in **Appendix C**.

Construction Program for the Next Month

- 5.3 The major construction activities for civil works in the coming month include:
 - Retaining wall construction at CCR-R2 & CCR-R3 and LCK-R2 to LCK-R3.
 - Slope upgrading works for Feature No. 11NW-A/FR 54 & A/FR55.
 - Drainage works at Lai Po Road and Castle Peak Road
 - Offsite fabrication of top rail of parapet.
 - Erection of noise barrier and signage at slip roads A, B C, D and Main Viaduct.
 - Construction of Wai Man Tsuen pump house, Irrigation Pump House near pier C14, kiosk at CCR-S1 and Lai Po Road pump house
 - Hydro-multching and tree planting for slope CCR-S4.
 - Roadwork at main viaduct, slip roads C & D, Lai Po Road, Butterfly Valley Interchange and Butterfly Valley Road.
- 5.4 The tentative construction program for civil works is provided in **Appendix L**.
- 5.5 The major activities for TCSS works in the coming month include:
 - SAT for TCSS equipment at Section A, B, C, D, E, F, G and Kiosk K2;

6. CONCLUSIONS AND RECOMMENDATIONS

Conclusions

- 6.1 Environmental monitoring works were conducted in the reporting month and all monitoring results were checked and reviewed.
- 6.2 No Action/Limit Level exceedance for both 1-hour TSP and 24-hours TSP was recorded in the reporting month.
- 6.3 No Action/Limit Level exceedance for noise was recorded in the reporting month.
- 6.4 Two public complaints were received in the reporting month.
- 6.5 No prosecution was received in the reporting month.

Recommendations

6.6 According to the environmental audit performed in the reporting month, the following recommendations were made:

Water Impact

- To ensure properly maintenance for de-silting facilities
- To review the capacity of de-silting facilities for discharge.
- To avoid stagnant water accumulation on site.

Noise Impact

- To provide temporary noise barriers for noisy activities, such as slope upgrading works for Feature No. 11NW-A/FR 54 & A/FR55
- To review the works sequence of site activities so as to reduce the number of noisy equipment in concurrent operation.
- To employ quiet powered mechanical equipment if possible.
- To ensure compliance of CNP conditions during restricted-hour works.


Dust Impact

- To ensure water spray is applied for the dust emissive works, such as slope upgrading, loading and unloading of soil materials.
- To cover soil stockpiles and exposed slope surface by impervious sheets or other means.
- To ensure that all vehicles carrying dusty material are properly covered before leaving the site.

Waste / Chemical Management

- To ensure the performance of sorting of C&D materials at source (during generation);
- To carry out inspection of dump truck at site exit to ensure inert and non-inert C&D materials are properly segregated before removing off site.
- To ensure proper collection and disposal of rubbish generated on site.
- To avoid any discharge or accidental spillage of chemical waste directly from the site.

FIGURES



APPENDIX A ACTION AND LIMIT LEVELS

Appendix A - Action and Limit Levels (LCKV)

1-Hour TSP

Location	Action Level, μg/m ³	Limit Level, μg/m³
AM2	301	500

24-Hour TSP

Location	Action Level, μg/m ³	Limit Level, μg/m³
AM2	177	260

Construction Noise

Period	Action Level	Limit Level
0700-1900 hrs on normal weekdays		75 dB(A)
0700-2300 hrs on holidays & 1900-2300 hrs on all other days	When one documented complaint is received	70* dB(A)
2300-0700 hrs of next day		55* dB(A)

^(*) The Area Sensitivity Rating for the noise monitoring stations (NM4, NM8a, NM8b and NM9) is taken as C, according to Table 1 of EPD's Technical Memorandum on Noise from Construction Work other than Percussive Piling.

APPENDIX B COPIES OF CALIBRATION CERTIFCATES

High-Volume TSP Sampler 5-POINT CALIBRATION DATA SHEET



File No. MA3024/20/0025 WK Station Operator: Lai Chi Kok Sport Centre (AM2) Next Due Date: 10-Nov-07 Date: 11-Sep-07 Serial No. 0818 Equipment No.: A-01-20 **Ambient Condition** Temperature, Ta(K) 300.3 Pressure, Pa (mmHg) 759.5 Orifice Transfer Standard Information A-04-05 Intercept, bc 0.0395 Equipment No.: Slope, mc mc x Qstd + bc = $[\Delta H \times (Pa/760) \times (298/Ta)]^{1/2}$ Last Calibration Date: 12-Mar-07 Qstd = $\{ |\Delta H \times (Pa/760) \times (298/Ta) |^{1/2} -bc \} / mc$ Next Calibration Date: 11-Mar-08 Calibration of TSP Sampler Orfice HVS Calibration $[\Delta W \times (Pa/760) \times (298/Ta)]^{1/2}$ Y-Qstd (CFM) ΔH (orifice), [ΔH x (Pa/760) x (298/Ta)]1/2 Point in. of water X - axis (HVS), in. of oil axis 11.3 3.35 57.53 1 8.2 2.85 2 3.12 53.53 2.54 9.8 6.5 3 7.0 2.63 45.13 4.3 2.07 4 5.4 2.31 39.56 3.2 1.78 5 3.1 1.75 29.81 1.7 1.30 By Linear Regression of Y on X Intercept, bw : -0.3838 Slope, mw = 0.0552Correlation coefficient* = *If Correlation Coefficient < 0.990, check and recalibrate. Set Point Calculation From the TSP Field Calibration Curve, take Qstd = 43 CFM From the Regression Equation, the "Y" value according to mw x Qstd + bw = $[\Delta W \times (Pa/760) \times (298/Ta)]^{1/2}$ Therefore, Set Point; $W = (mw \times Qstd + bw)^2 \times (760 / Pa) \times (Ta / 298) =$ 4.00 Remarks: Conducted by: 41k- Tang

High-Volume TSP Sampler 5-POINT CALIBRATION DATA SHEET



File No. MA3024/20/0026 Operator: Station Lai Chi Kok Sport Centre (AM2) WK Date: 12-Nov-07 Next Due Date: 11-Jan-08 Equipment No.: A-01-20 Serial No. 0818 **Ambient Condition** Temperature, Ta(K) 293.6 Pressure, Pa (mmHg) 766.6 Orifice Transfer Standard Information Equipment No.: A-04-05 Slope, mc 0.0575 Intercept, bc 0.0395 mc x Qstd + bc = $[\Delta H \times (Pa/760) \times (298/Ta)]^{1/2}$ Last Calibration Date: 12-Mar-07 Qstd = $\{ [\Delta H \times (Pa/760) \times (298/Ta)]^{1/2} -bc \} / mc$ Next Calibration Date: 11-Mar-08 Calibration of TSP Sampler Orfice HVS Calibration $[\Delta W \times (Pa/760) \times (298/Ta)]^{1/2} Y$ ΔH (orifice), Qstd (CFM) ΔW $[\Delta H \times (Pa/760) \times (298/Ta)]^{1/2}$ Point in. of water X - axis (HVS), in. of oil axis 3.42 11.4 58.73 8.5 2.95 1 3.20 54.96 7.0 2 10.0 2.68 3 7.2 2.72 46.53 4.8 2.21 4 2.29 39.05 3.3 1.84 5.1 5 3.0 1.75 29.79 1.8 1.36 By Linear Regression of Y on X 0.0542 Intercept, bw : -0.2770 Slope, mw = Correlation coefficient* = *If Correlation Coefficient < 0.990, check and recalibrate. **Set Point Calculation** From the TSP Field Calibration Curve, take Qstd = 43 CFM From the Regression Equation, the "Y" value according to mw x Qstd + bw = $[\Delta W \times (Pa/760) \times (298/Ta)]^{1/2}$ Therefore, Set Point; W = $(mw \times Qstd + bw)^2 \times (760 / Pa) \times (Ta / 298) =$ Remarks: Conducted by: W. Lang Signature: Signature: Date: Date:

WELLAB LTD.

Unit C, 1/F, Goldlion Holdings Center 13-15 Yuen Shun Circuit, Shatin, Hong Kong.

Tel: (852) 2898 7388 Fax: (852) 2898 7076

TEST REPORT

APPLICANT: Cinotech Consultants Limited

1602-1610 Delta House,

3 On Yiu Street, Shatin, N.T. Test Report No.: C/07/70502
Date of Issue: 2007-05-02
Date Received: 2007-05-01
Date Tested: 2007-05-01
Date Completed: 2007-05-02

ATTN:

Mr. Henry Leung

Page:

1 of 1

Certificate of Calibration

Item for calibration:

Description

: RS232 Integral Vane Digital Anemometer

Manufacturer

: AZ Instrument

Model No.

: 451104

Serial No.

: 9020746

Equipment No.

: A-03-01

Test conditions:

Room Temperature

: 21 degree Celsius

Relative Humidity

: 65%

Pressure

: 101.3 kPa

Methodology:

The anemometer has been calibrated in accordance with the documented procedures and using standard(s) and instrument(s) which are recommended by the manufacturer, or equivalent.

Results:

Results	Reference Set Point	Instrument Readings
Measuring Air Velocity, m/s	2.00	2.00
Temperature, °C	21.0	21.0

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

Senior Chemist



TISCH ENVIROMENTAL, INC.
145 SOUTH MIAMI AVE.
VILLAGE OF CLEVES, OH 45002
513.467.9000
877.263.7610 TOLL FREE
513.467.9009 FAX
WWW.TISCH-ENV.COM

AIR POLLUTION MONITORING EQUIPMENT

ORIFICE TRANSFER STANDARD CERTIFICATION WORKSHEET TE-5025A

Date - Ma	ar 12, 200 Tisch	7 Rootsmeter Orifice I.I		9833640 0999	Ta (K) - Pa (mm) -	294 74676
PLATE OR Run #	VOLUME START (m3)	VOLUME STOP (m3)	DIFF VOLUME (m3)	DIFF TIME (min)	METER DIFF Hg (mm)	ORFICE DIFF H2O (in.)
1 2 3 4 5	NA NA NA NA	NA NA NA NA NA	1.00 1.00 1.00 1.00	1.3890 0.9850 0.8810 0.8410 0.6950	3.2 6.3 7.8 8.6 12.5	2.00 4.00 5.00 5.50 8.00

DATA TABULATION

Vstd	(x axis) Qstd	(y axis)		Va .	(x axis) Qa	(y axis)
0.9917 0.9876 0.9854 0.9844 0.9792	0.7139 1.0026 1.1185 1.1706 1.4090	1.4113 1.9959 2.2315 2.3405 2.8227		0.9957 0.9916 0.9894 0.9884 0.9832	0.7168 1.0067 1.1231 1.1753 1.4147	0.8874 1.2549 1.4030 1.4715 1.7747
Qstd slop intercept coefficie	(b) = ent (r) =	2.03154 -0.03970 0.99999		Qa slope intercept coefficie	(b) = ent (r) =	1.27212 -0.02496 0.99999
y = xis = SQRT[H2O(Pa/760)(298/Ta)] $y = xis = SQRT[H2O(Ta/Pa)]$						

CALCULATIONS

Vstd = Diff. Vol[(Pa-Diff. Hg)/760](298/Ta)
Qstd = Vstd/Time

Va = Diff Vol [(Pa-Diff Hg)/Pa]
Qa = Va/Time


For subsequent flow rate calculations:

Qstd = $1/m\{[SQRT(H2O(Pa/760)(298/Ta))] - b\}$ Qa = $1/m\{[SQRT H2O(Ta/Pa)] - b\}$



TISCH ENVIROMENTAL, INC.
145 SOUTH MIAMI AVE.
VILLAGE OF CLEVES, OH 45002
513.467.9000
877.263.7610 TOLL FREE
513.467.9009 FAX
WWW.TISCH-ENV.COM

AIR POLLUTION MONITORING EQUIPMENT



* y-axis equations:

Qstd series:

$$\sqrt{\Delta H \left(\frac{Pa}{Pstd}\right) \left(\frac{Tstd}{Ta}\right)}$$

Qa series:

$$\sqrt{(\Delta H (Ta/Pa))}$$

WELLAB LTD.

Unit C, 1/F, Goldlion Holdings Center 13-15 Yuen Shun Circuit, Shatin, Hong Kong.

Tel: (852) 2898 7388 Fax: (852) 2898 7076

TEST REPORT

APPLICANT: Cinotech Consultants Limited

1602-1610 Delta House,

3 On Yiu Street, Shatin, N.T.

Test Report No.: C/N/61215/1
Date of Issue: 2006-12-15
Date Received: 2006-12-14
Date Tested: 2006-12-15
Date Completed: 2006-12-15
Next Due Date: 2007-12-14

ATTN: Mr. Henry Leung Page: 1 of 1

Certificate of Calibration

Item for calibration:

Description : Integrating Sound Level Meter

Manufacturer : Brüel & Kjær Model No. : B&K 2238 Serial No. : 2337665 Microphone No. : 2289749 Equipment No. : N-01-01

Test conditions:

Room Temperatre : 20 degree Celsius

Relative Humidity : 60%

Test Specifications:

Performance checking at 94 and 114 dB

Methodology:

In-house method, according to manufacturer instruction manual

Results:

Reference Set Point, dB	Instrument Readings, dB
94	94.0
114	114.0

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE
Operation Manager

This test document cannot be reproduced in any way, except in full context, without the prior approval in writing of the laboratory.

WELLAB LTD.

Unit C, 1/F, Goldlion Holdings Center 13-15 Yuen Shun Circuit, Shatin, Hong Kong.

Tel: (852) 2898 7388 Fax: (852) 2898 7076

TEST REPORT

APPLICANT: Cinotech Consultants Limited

1602-1610 Delta House,

3 On Yiu Street, Shatin, N.T. Test Report No.: C/N/61116/1
Date of Issue: 2006-11-16
Date Received: 2006-11-15
Date Tested: 2006-11-15
Date Completed: 2006-11-16
Next Due Date: 2007-11-15

ATTN:

Mr. Henry Leung

Page:

1 of 1

Certificate of Calibration

Item for calibration:

Description ·

: Integrating Sound Level Meter

Manufacturer Model No.

: Brüel & Kjær : B&K 2238

Serial No.

: 2337666

Microphone No. Equipment No.

: 2289750 : N-01-02

Test conditions:

Room Temperatre

: 20 degree Celsius

Relative Humidity

: 59%

Test Specifications:

Performance checking at 94 and 114 dB

Methodology:

In-house method, according to manufacturer instruction manual

Results:

Reference Set Point, dB	Instrument Readings, dB
94	94.0
114	114.0

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

Operation Manager



Unit C, 1/F., Goldlion Holdings Center, 13-15 Yuen Shun Circuit, Shatin, NT, HK. Tel: 2898 7388 Fax: 2898 7076 Website: www.wellab.com.hk

TEST REPORT

APPLICANT: Cinotech Consultants Limited

Room 1710, Technology Park,

18 On Lai Street,

Shatin, NT, Hong Kong

Test Report No.: C/N/71116/1
Date of Issue: 2007-11-16
Date Received: 2007-11-15
Date Tested: 2007-11-15
Date Completed: 2007-11-16
Next Due Date: 2008-11-15

ATTN:

Mr. Henry Leung

Page:

1 of 1

Certificate of Calibration

Item for calibration:

Description

: Integrating Sound Level Meter

Manufacturer Model No. : Brüel & Kjær

Model No.
Serial No.

: B&K 2238 : 2337666

Microphone No.

: 2289750

Equipment No.

: N-01-02

Test conditions:

Room Temperatre

: 20 degree Celsius

Relative Humidity

: 59%

Test Specifications:

Performance checking at 94 and 114 dB

Methodology:

In-house method, according to manufacturer instruction manual

Results:

Reference Set Point, dB	Instrument Readings, dB
94	94.0
114	114.0

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE Senior Chemist

This report may not be reproduced except with prior written approval from WELLAB LIMITED and the results relate only to the items calibrated or tested.



Unit C, 1/F., Goldlion Holdings Center, 13-15 Yuen Shun Circuit, Shatin, NT, HK. Tel: 2898 7388 Fax: 2898 7076 Website: www.wellab.com.hk

TEST REPORT

APPLICANT: Cinotech Consultants Limited

1601-1610 Delta House,

3 On Yiu Street, Shatin, N.T. Test Report No.: C/N/70903-1
Date of Issue: 2007-09-03
Date Received: 2007-09-01
Date Tested: 2007-09-03
Date Completed: 2007-09-03
Next Due Date: 2008-09-02

ATTN:

Mr. Henry Leung

Page:

1 of 1

Certificate of Calibration

Item for calibration:

Description

: Integrating Sound Level Meter

Manufacturer Model No.

: Brüel & Kjær : B&K 2238

Serial No. Microphone No.

: 2359311 : 2346382

Equipment No.

: N-01-03

Test conditions:

Room Temperatre

: 22 degree Celsius

Relative Humidity

: 62%

Test Specifications:

Performance checking at 94 and 114 dB

Methodology:

In-house method, according to manufacturer instruction manual

Results:

Reference Set Point, dB	Instrument Readings, dB
94	94.0
114	114.0

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

Senior Chemist





TEST REPORT

APPLICANT: Cinotech Consultants Limited

1602-1610 Delta House,

3 On Yiu Street, Shatin, N.T.

 Test Report No.:
 C/N/70903-2

 Date of Issue:
 2007-09-03

 Date Received:
 2007-09-01

 Date Tested:
 2007-09-03

 Date Completed:
 2007-09-03

 Next Due Date:
 2008-09-02

ATTN:

Mr. Henry Leung

Page:

1 of 1

Certificate of Calibration

Item for calibration:

Description

: Integrating Sound Level Meter

Manufacturer Model No. Serial No. Equipment No.

: B&K 2238 : 2359303 : N-01-04

: Brüel & Kjær

Test conditions:

Room Temperatre

: 22 degree Celsius

Relative Humidity

: 62%

Test Specifications:

Performance checking at 94 and 114 dB

Methodology:

In-house method, according to manufacturer instruction manual

Results:

Reference Set Point, dB	Instrument Readings, dB
94	94.0
114	114.0

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

Senior Chemist





TEST REPORT

APPLICANT: Cinotech Consultants Limited

Room 1710, Technology Park,

18 On Lai Street,

Shatin, NT, Hong Kong

Test Report No.: C/N/71015/1
Date of Issue: 2007-10-15
Date Received: 2007-10-13
Date Tested: 2007-10-13
Date Completed: 2007-10-15
Next Due Date: 2008-10-14

ATTN:

Mr. Henry Leung

Page:

1 of 1

Certificate of Calibration

Item for calibration:

Description

: Integrating Sound Level Meter

Manufacturer

: Brüel & Kjær

Model No.

: B&K 2238

Serial No. Microphone No. : 2394976 : 2407349

Equipment No.

: N-01-05

Test conditions:

Room Temperatre

: 21 degree Celsius

Relative Humidity

: 60%

Test Specifications:

Performance checking at 94 and 114 dB

Methodology:

In-house method, according to manufacturer instruction manual

Results:

Reference Set Point, dB	Instrument Readings, dB
94	94.0
114	114.0

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE Senior Chemist

This report may not be reproduced except with prior written approval from WELLAB LIMITED and the results relate only to the items calibrated or tested.

WELLAB LTD.

Unit C, 1/F, Goldlion Holdings Center 13-15 Yuen Shun Circuit, Shatin, Hong Kong.

Tel: (852) 2898 7388 Fax: (852) 2898 7076

TEST REPORT

APPLICANT: Cinotech Consultants Limited

1602-1610 Delta House,

3 On Yiu Street, Shatin, N.T.

 Test Report No.:
 C/N/61116/2

 Date of Issue:
 2006-11-16

 Date Received:
 2006-11-15

 Date Tested:
 2006-11-15

 Date Completed:
 2006-11-16

 Next Due Date:
 2007-11-15

ATTN:

Mr. Henry Leung

Page:

1 of 1

Item for calibration:

Description

: Acoustical Calibrator

Manufacturer

: Brüel & Kjær

Model No.

: 4231

Serial No.

: 2326353

Project No.

: C13

Equipment No.

: N-02-01

Test conditions:

Room Temperatre

: 20 degree Celsius

Relative Humidity

: 59%

Pressure

: 1015.2 hPa

Methodology:

The sound calibrator has been calibrated in accordance with the documented procedures and using standard(s) and instrument(s) which are recommended by the manufacturer, or equivalent.

Results:

Sound Pressure Level	Measured SPL	Tolerance	
At 94 dB SPL	94.0	$94.0 \pm 0.1 \mathrm{dB}$	

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

Operation Manager



TEST REPORT

APPLICANT: Cinotech Consultants Limited

Room 1710, Technology Park,

18 On Lai Street,

Shatin, NT, Hong Kong

Test Report No.:	C/N/71116/2	
Date of Issue:	2007-11-16	
Date Received:	2007-11-15	
Date Tested:	2007-11-15	
Date Completed:	2007-11-16	
Next Due Date:	2008-11-15	

ATTN:

Mr. Henry Leung

Page:

1 of 1

Item for calibration:

Description

: Acoustical Calibrator

Manufacturer

: Brüel & Kjær

Model No.

: 4231

Serial No.

: 2326353

Project No. Equipment No.

: C13 : N-02-01

Test conditions:

Room Temperatre

: 20 degree Celsius

Relative Humidity

: 59%

Pressure

: 1015.2 hPa

Methodology:

The sound calibrator has been calibrated in accordance with the documented procedures and using standard(s) and instrument(s) which are recommended by the manufacturer, or equivalent.

Results:

Sound Pressure Level	Measured SPL	Tolerance
At 94 dB SPL	94.0	94.0 ± 0.1 dB

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE Senior Chemist

This report may not be reproduced except with prior written approval from WELLAB LIMITED and the results relate only to the items calibrated or tested.

WELLAB LTD.

Unit C, 1/F, Goldlion Holdings Center 13-15 Yuen Shun Circuit, Shatin, Hong Kong. Tel: (852) 2898 7388

Fax: (852) 2898 7076

TEST REPORT

APPLICANT: Cinotech Consultants Limited

1602-1610 Delta House,

3 On Yiu Street, Shatin, N.T.

C/06/70305	
2007-03-05	
2007-03-03	
2007-03-03	
2007-03-05	
2008-03-04	
	2007-03-05 2007-03-03 2007-03-03 2007-03-05

ATTN:

Mr. Henry Leung

Page:

1 of 1

Item for calibration:

Description

: Acoustical Calibrator

Manufacturer

: Brüel & Kjær

Model No. Serial No. : 4231 : 2343007

Project No. Equipment No.

: C13 : N-02-02

Test conditions:

Room Temperatre

: 20 degree Celsius

Relative Humidity

: 65%

Pressure

: 1020.1hPa

Methodology:

The sound calibrator has been calibrated in accordance with the documented procedures and using standard(s) and instrument(s) which are recommended by the manufacturer, or equivalent.

Results:

Sound Pressure Level	Measured SPL	Tolerance
At 94 dB SPL	94.0	94.0 ± 0.2 dB

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

PATRICK TSE

Operation Manager

This test document cannot be reproduced in any way, except in full context, without the prior approval in writing of the laboratory.



Unit C, 1/F., Goldlion Holdings Center, 13-15 Yuen Shun Circuit, Shatin, NT, HK. Tel: 2898 7388 Fax: 2898 7076 Website: www.wellab.com.hk

TEST REPORT

APPLICANT: Cinotech Consultants Limited

1602-1610 Delta House,

3 On Yiu Street, Shatin, N.T. Test Report No.: C/N/70903-3
Date of Issue: 2007-09-03
Date Received: 2007-09-01
Date Tested: 2007-09-03
Date Completed: 2007-09-03
Next Due Date: 2008-09-02

ATTN:

Mr. Henry Leung

Page:

1 of 1

Item for calibration:

Description

: Acoustical Calibrator

Manufacturer

: Brüel & Kjær

Model No.

: 4231

Serial No.

: 2412367

Equipment No.

: N-02-03

Test conditions:

Room Temperatre

: 22 degree Celsius

Relative Humidity

: 62%

Methodology:

The Sound Level Calibrator has been calibrated in accordance with the documented procedures and using standard(s) and instrument(s) which are recommended by the manufacturer, or equivalent.

Results:

Sound Pressure Level (1kHz)	Measured SPL	Tolerance
At 94 dB SPL	94.0	94.0 ± 0.1 dB
At 114 dB SPL	114.0	114.0 ± 0.1 dB

PREPARED AND CHECKED BY:

For and On Behalf of WELLAB Ltd.

Senior Chemist

APPENDIX C ENVIRONMENTAL MONITORING AND AUDIT SCHEDULE

Environmental Monitoring for Lai Chi Kok Viaduct Tentative Air Quality and Noise Monitoring Schedule for November 2007

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
28-Oct	29-Oct	30-Oct	31-Oct	1-Nov	2-Nov	3-Nov
	24 hr TSP	1 hr TSP Noise	1 hr TSP	1 hr TSP		24 hr TSP
4-Nov	5-Nov	6-Nov	7-Nov	8-Nov	9-Nov	10-Nov
	1 hr TSP Noise	1 hr TSP		1 hr TSP	24 hr TSP	
11-Nov	12-Nov	13-Nov	14-Nov	15-Nov	16-Nov	17-Nov
	1 hr TSP Noise	1 hr TSP		24 hr TSP	1 hr TSP	
18-Nov	19-Nov	20-Nov	21-Nov	22-Nov	23-Nov	24-Nov
	1 hr TSP Noise	1 hr TSP	24 hr TSP	1 hr TSP		
25-Nov	26-Nov	27-Nov	28-Nov	29-Nov	30-Nov	1-Dec
	1 hr TSP Noise	24 hr TSP	1 hr TSP	1 hr TSP		

The schedule may be changed due to unforeseen circumstances (adverse weather, etc)

AM2 Lai Chi Kok Sports Centre

NM2 Lai Chi Kok Correctional Institution

NM4 Mei Foo Sun Chuen, Phase 5

NM8a M/F of Nob Hill NM8b 3/F of Nob Hill

NM9 G/F, Hoi Fai House, Hoi Lai Estate

Environmental Monitoring for Lai Chi Kok Viaduct Tentative Air Quality and Noise Monitoring Schedule for December 2007

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
2-Dec	3-Dec	4-Dec	5-Dec	6-Dec	7-Dec	8-Dec
	24 hr TSP	1 hr TSP Noise		1 hr TSP	1 hr TSP	24 hr TSP
9-Dec	10-Dec	11-Dec	12-Dec	13-Dec	14-Dec	15-Dec
	1 hr TSP	1 hr TSP Noise		1 hr TSP	24 hr TSP	
16-Dec	17-Dec	18-Dec	19-Dec	20-Dec	21-Dec	22-Dec
	1 hr TSP	1 hr TSP Noise	24 hr TSP	1 hr TSP		
23-Dec	24-Dec	25-Dec	26-Dec	27-Dec	28-Dec	29-Dec
	1 hr TSP Noise		24 hr TSP	1 hr TSP	1 hr TSP	
30-Dec	31-Dec	1-Jan	2-Jan	3-Jan	4-Jan	5-Jan
		1 hr TSP Noise 24 hr TSP	1 hr TSP	1 hr TSP		

The schedule may be changed due to unforeseen circumstances (adverse weather, etc)

AM2 Lai Chi Kok Sports Centre

NM2 Lai Chi Kok Correctional Institution

NM4 Mei Foo Sun Chuen, Phase 5

NM8a M/F of Nob Hill NM8b 3/F of Nob Hill

NM9 G/F, Hoi Fai House, Hoi Lai Estate

APPENDIX D WIND DATA

Date	Time	Wind Speed m/s	Direction
1-Nov-2007	0:00	5.0	W
1-Nov-2007	1:00	4.0	WNW
1-Nov-2007	2:00	5.0	WNW
1-Nov-2007	3:00	5.0	WSW
1-Nov-2007	4:00	7.0	WNW
1-Nov-2007	5:00	9.0	W
1-Nov-2007	6:00	5.0	W
1-Nov-2007	7:00	8.0	WNW
1-Nov-2007	8:00	9.0	W
1-Nov-2007	9:00	7.0	WNW
1-Nov-2007	10:00	6.0	WNW
1-Nov-2007	11:00	3.0	WNW
1-Nov-2007	12:00	3.0	WSW
1-Nov-2007	13:00	5.0	WSW
1-Nov-2007	14:00	6.0	WSW
1-Nov-2007	15:00	6.0	WSW
1-Nov-2007	16:00	7.0	WSW
1-Nov-2007	17:00	8.0	WSW
1-Nov-2007	18:00	7.0	WSW
1-Nov-2007	19:00	6.0	W
1-Nov-2007	20:00	9.0	WSW
1-Nov-2007	21:00	10.0	WSW
1-Nov-2007	22:00	9.0	WSW
1-Nov-2007	23:00	8.0	WSW
2-Nov-2007	0:00	6.0	WSW
2-Nov-2007	1:00	6.0	WSW
2-Nov-2007	2:00	8.0	WSW
2-Nov-2007	3:00	6.0	WSW
2-Nov-2007	4:00	2.0	SW
2-Nov-2007	5:00	2.0	WNW
2-Nov-2007	6:00	5.0	W
2-Nov-2007	7:00	5.0	WSW
2-Nov-2007	8:00	5.0	WNW
2-Nov-2007	9:00	5.0	WNW
2-Nov-2007	10:00	10.0	WNW
2-Nov-2007	11:00	9.0	WNW
2-Nov-2007	12:00	7.0	WNW
2-Nov-2007	13:00	5.0	W
2-Nov-2007	14:00	3.0	SSW
2-Nov-2007	15:00	4.0	WSW
2-Nov-2007 2-Nov-2007	16:00	2.0	WSW
2-Nov-2007 2-Nov-2007	17:00	1.0	SW
2-Nov-2007 2-Nov-2007	18:00	2.0	SW
2-Nov-2007 2-Nov-2007	19:00	5.0	SW
2-Nov-2007 2-Nov-2007	20:00	5.0	SW
2-Nov-2007 2-Nov-2007	21:00	2.0	SW
2-Nov-2007 2-Nov-2007	22:00	4.0	SW
2-Nov-2007 2-Nov-2007	23:00	5.0	SW
3-Nov-2007	0:00	6.0	WSW
3-Nov-2007 3-Nov-2007	1:00	4.0	WSW
	2:00	2.0	SW
3-Nov-2007 3-Nov-2007			
.>-INUV-ZUU/	3:00	2.0	SW
3-Nov-2007	4:00	1.0	SW

Date	Time	Wind Speed m/s	Direction
3-Nov-2007	6:00	1.0	WNW
3-Nov-2007	7:00	4.0	WNW
3-Nov-2007	8:00	5.0	W
3-Nov-2007	9:00	8.0	WNW
3-Nov-2007	10:00	9.0	W
3-Nov-2007	11:00	8.0	WNW
3-Nov-2007	12:00	6.0	WNW
3-Nov-2007	13:00	6.0	W
3-Nov-2007	14:00	6.0	SW
3-Nov-2007	15:00	5.0	WSW
3-Nov-2007	16:00	3.0	WSW
3-Nov-2007	17:00	2.0	SSW
3-Nov-2007	18:00	0.0	SSW
3-Nov-2007	19:00	0.0	
3-Nov-2007	20:00	0.0	
3-Nov-2007	21:00	0.0	
3-Nov-2007	22:00	0.0	
3-Nov-2007	23:00	0.0	
4-Nov-2007	0:00	0.0	
4-Nov-2007	1:00	0.0	
4-Nov-2007	2:00	0.0	SSW
4-Nov-2007	3:00	3.0	SW
4-Nov-2007	4:00	3.0	SW
4-Nov-2007	5:00	1.0	SW
4-Nov-2007	6:00	3.0	SW
4-Nov-2007	7:00	7.0	WSW
4-Nov-2007	8:00	9.0	WSW
4-Nov-2007	9:00	10.0	WSW
4-Nov-2007	10:00	10.0	WNW
4-Nov-2007	11:00	8.0	WNW
4-Nov-2007	12:00	8.0	WSW
4-Nov-2007	13:00	7.0	SW
4-Nov-2007	14:00	4.0	SW
4-Nov-2007	15:00	5.0	WSW
4-Nov-2007	16:00	3.0	SSW
4-Nov-2007	17:00	3.0	W
4-Nov-2007	18:00	1.0	W
4-Nov-2007	19:00	0.0	SSW
4-Nov-2007	20:00	0.0	
4-Nov-2007	21:00	0.0	
4-Nov-2007 4-Nov-2007	22:00	0.0	
4-Nov-2007 4-Nov-2007	23:00	0.0	
5-Nov-2007	0:00	0.0	
			 SS/M
5-Nov-2007	1:00 2:00	0.0	SSW SSW
5-Nov-2007	3:00		SSW
5-Nov-2007 5-Nov-2007		1.0	SW
	4:00	1.0	
5-Nov-2007	5:00	2.0	SW
5-Nov-2007	6:00	3.0	SW
5-Nov-2007	7:00	2.0	SW
5-Nov-2007	8:00	2.0	SW
5-Nov-2007	9:00	7.0	WNW
5-Nov-2007	10:00	8.0	WNW

Date	Time	Wind Speed m/s	Direction
5-Nov-2007	12:00	8.0	WNW
5-Nov-2007	13:00	6.0	WSW
5-Nov-2007	14:00	4.0	WSW
5-Nov-2007	15:00	5.0	W
5-Nov-2007	16:00	7.0	W
5-Nov-2007	17:00	6.0	SW
5-Nov-2007	18:00	4.0	SW
5-Nov-2007	19:00	3.0	SW
5-Nov-2007	20:00	4.0	SW
5-Nov-2007	21:00	4.0	SW
5-Nov-2007	22:00	6.0	WSW
5-Nov-2007	23:00	8.0	WSW
6-Nov-2007	0:00	7.0	SW
6-Nov-2007	1:00	8.0	WSW
6-Nov-2007	2:00	7.0	SW
6-Nov-2007	3:00	3.0	SW
6-Nov-2007	4:00	5.0	SW
6-Nov-2007	5:00	7.0	WSW
6-Nov-2007	6:00	6.0	WSW
6-Nov-2007	7:00	1.0	WNW
6-Nov-2007	8:00	1.0	WSW
6-Nov-2007	9:00	5.0	WSW
6-Nov-2007	10:00	4.0	WNW
6-Nov-2007	11:00	5.0	WNW
6-Nov-2007	12:00	4.0	WNW
6-Nov-2007	13:00	5.0	SW
6-Nov-2007	14:00	4.0	W
6-Nov-2007	15:00	10.0	WNW
6-Nov-2007	16:00	8.0	W
6-Nov-2007	17:00	6.0	SW
6-Nov-2007	18:00	3.0	SW
6-Nov-2007	19:00	4.0	SW
6-Nov-2007	20:00	7.0	WSW
6-Nov-2007	21:00	7.0	WSW
6-Nov-2007	22:00	7.0	SW
6-Nov-2007	23:00	10.0	SW
			WSW
7-Nov-2007	0:00	9.0	
7-Nov-2007	1:00	8.0	SW
7-Nov-2007	2:00	7.0	WSW WSW
7-Nov-2007	3:00	8.0	_
7-Nov-2007	4:00	7.0	WSW
7-Nov-2007	5:00	7.0	SW
7-Nov-2007	6:00	8.0	WSW
7-Nov-2007	7:00	6.0	WSW
7-Nov-2007	8:00	7.0	WSW
7-Nov-2007	9:00	8.0	WSW
7-Nov-2007	10:00	9.0	W
7-Nov-2007	11:00	11.0	WNW
7-Nov-2007	12:00	8.0	WNW
7-Nov-2007	13:00	7.0	W
7-Nov-2007	14:00	7.0	WNW
7-Nov-2007	15:00	8.0	W
7-Nov-2007	16:00	6.0	W
7-Nov-2007	17:00	6.0	SW

Date	Time	Wind Speed m/s	Direction
7-Nov-2007	18:00	6.0	WSW
7-Nov-2007	19:00	4.0	SW
7-Nov-2007	20:00	7.0	SW
7-Nov-2007	21:00	8.0	WSW
7-Nov-2007	22:00	7.0	SW
7-Nov-2007	23:00	6.0	WSW
8-Nov-2007	0:00	6.0	SW
8-Nov-2007	1:00	2.0	SW
8-Nov-2007	2:00	2.0	W
8-Nov-2007	3:00	5.0	WSW
8-Nov-2007	4:00	7.0	WSW
8-Nov-2007	5:00	7.0	WSW
8-Nov-2007	6:00	10.0	WNW
8-Nov-2007	7:00	6.0	W
8-Nov-2007	8:00	7.0	W
8-Nov-2007	9:00	8.0	WNW
8-Nov-2007	10:00	7.0	W
8-Nov-2007	11:00	8.0	W
8-Nov-2007	12:00	10.0	W
8-Nov-2007	13:00	7.0	W
8-Nov-2007	14:00	6.0	W
8-Nov-2007	15:00	6.0	WSW
8-Nov-2007	16:00	7.0	WSW
8-Nov-2007	17:00	6.0	WSW
8-Nov-2007	18:00	6.0	WSW
8-Nov-2007	19:00	6.0	SW
8-Nov-2007	20:00	9.0	SW
8-Nov-2007	21:00	9.0	WNW
8-Nov-2007	22:00	8.0	W
8-Nov-2007	23:00	6.0	SW
9-Nov-2007	0:00	6.0	WSW
9-Nov-2007	1:00	5.0	WSW
9-Nov-2007	2:00	4.0	W
9-Nov-2007	3:00	6.0	WNW
9-Nov-2007	4:00	6.0	W
9-Nov-2007	5:00	4.0	WNW
9-Nov-2007	6:00	0.0	W
9-Nov-2007	7:00	2.0	WNW
9-Nov-2007	8:00	2.0	W
9-Nov-2007	9:00	7.0	WNW
9-Nov-2007	10:00	12.0	W
9-Nov-2007	11:00	11.0	WNW
9-Nov-2007	12:00	9.0	W
9-Nov-2007	13:00	8.0	W
9-Nov-2007	14:00	8.0	WNW
9-Nov-2007	15:00	6.0	W
9-Nov-2007	16:00	5.0	W
9-Nov-2007	17:00	2.0	SSW
9-Nov-2007	18:00	0.0	SSW
9-Nov-2007	19:00	0.0	
9-Nov-2007	20:00	0.0	SSW
9-Nov-2007 9-Nov-2007	21:00	2.0	WNW
	22:00		WSW
9-Nov-2007		1.0	1/// 2.1//

Date	Time	Wind Speed m/s	Direction
10-Nov-2007	0:00	2.0	WSW
10-Nov-2007	1:00	1.0	WSW
10-Nov-2007	2:00	4.0	SW
10-Nov-2007	3:00	3.0	SW
10-Nov-2007	4:00	1.0	SW
10-Nov-2007	5:00	0.0	SSW
10-Nov-2007	6:00	0.0	
10-Nov-2007	7:00	0.0	
10-Nov-2007	8:00	0.0	
10-Nov-2007	9:00	3.0	WNW
10-Nov-2007	10:00	9.0	WNW
10-Nov-2007	11:00	7.0	W
10-Nov-2007	12:00	7.0	SW
10-Nov-2007	13:00	6.0	WNW
10-Nov-2007	14:00	6.0	WNW
10-Nov-2007	15:00	5.0	WNW
10-Nov-2007	16:00	5.0	W
10-Nov-2007	17:00	5.0	WSW
10-Nov-2007	18:00	6.0	W
10-Nov-2007	19:00	5.0	W
10-Nov-2007	20:00	0.0	WNW
10-Nov-2007	21:00	0.0	W
10-Nov-2007	22:00	0.0	WSW
10-Nov-2007	23:00	1.0	W
11-Nov-2007	0:00	5.0	W
11-Nov-2007	1:00	5.0	SW
11-Nov-2007	2:00	6.0	W
11-Nov-2007	3:00	4.0	WSW
11-Nov-2007	4:00	4.0	SW
11-Nov-2007	5:00	4.0	SW
11-Nov-2007	6:00	4.0	SW
11-Nov-2007	7:00	1.0	SW
11-Nov-2007	8:00	1.0	WNW
11-Nov-2007	9:00	6.0	WNW
11-Nov-2007	10:00	5.0	SW
11-Nov-2007	11:00	5.0	WNW
11-Nov-2007	12:00	4.0	WSW
11-Nov-2007	13:00	5.0	WNW
11-Nov-2007	14:00	6.0	WNW
11-Nov-2007	15:00	5.0	WNW
11-Nov-2007	16:00	6.0	W
11-Nov-2007	17:00	6.0	WNW
11-Nov-2007	18:00	5.0	WSW
11-Nov-2007	19:00	6.0	WSW
11-Nov-2007	20:00	7.0	WNW
11-Nov-2007 11-Nov-2007	21:00	7.0	WNW
11-Nov-2007	22:00	6.0	WNW
11-Nov-2007	23:00	7.0	WNW
12-Nov-2007	0:00	7.0	WNW
12-Nov-2007 12-Nov-2007	1:00	7.0	WNW
	2:00	7.0	W
12-Nov-2007			W
12-Nov-2007	3:00	6.0	
12-Nov-2007	4:00	5.0	WSW
12-Nov-2007	5:00	4.0	SW

Date	Time	Wind Speed m/s	Direction
12-Nov-2007	6:00	5.0	SW
12-Nov-2007	7:00	5.0	SW
12-Nov-2007	8:00	6.0	SW
12-Nov-2007	9:00	7.0	W
12-Nov-2007	10:00	7.0	W
12-Nov-2007	11:00	8.0	W
12-Nov-2007	12:00	8.0	WNW
12-Nov-2007	13:00	7.0	WNW
12-Nov-2007	14:00	6.0	NNW
12-Nov-2007	15:00	9.0	WNW
12-Nov-2007	16:00	7.0	WNW
12-Nov-2007	17:00	6.0	WNW
12-Nov-2007	18:00	5.0	W
12-Nov-2007 12-Nov-2007	19:00	6.0	W
12-Nov-2007	20:00	6.0	W
			W
12-Nov-2007	21:00	4.0	WSW
12-Nov-2007	22:00	6.0	WNW
12-Nov-2007	23:00	7.0	
13-Nov-2007	0:00	8.0	W
13-Nov-2007	1:00	7.0	WNW
13-Nov-2007	2:00	4.0	W
13-Nov-2007	3:00	6.0	WSW
13-Nov-2007	4:00	7.0	WSW
13-Nov-2007	5:00	7.0	SW
13-Nov-2007	6:00	5.0	SW
13-Nov-2007	7:00	4.0	SSW
13-Nov-2007	8:00	3.0	SW
13-Nov-2007	9:00	5.0	W
13-Nov-2007	10:00	8.0	W
13-Nov-2007	11:00	9.0	WNW
13-Nov-2007	12:00	9.0	W
13-Nov-2007	13:00	8.0	WNW
13-Nov-2007	14:00	5.0	WSW
13-Nov-2007	15:00	6.0	WNW
13-Nov-2007	16:00	4.0	W
13-Nov-2007	17:00	2.0	WNW
13-Nov-2007	18:00	1.0	WSW
13-Nov-2007	19:00	0.0	WSW
13-Nov-2007	20:00	0.0	WSW
13-Nov-2007	21:00	0.0	WSW
13-Nov-2007	22:00	0.0	
13-Nov-2007	23:00	1.0	SW
14-Nov-2007	0:00	2.0	SW
14-Nov-2007	1:00	5.0	W
14-Nov-2007	2:00	5.0	WSW
14-Nov-2007	3:00	5.0	SW
14-Nov-2007	4:00	5.0	SW
14-Nov-2007	5:00	5.0	WSW
14-Nov-2007	6:00	5.0	SW
14-Nov-2007	7:00	3.0	SW
14-Nov-2007	8:00	3.0	SW
	0.00	0.0	577
	Q·00	8 0	\\/\\\\
14-Nov-2007 14-Nov-2007	9:00 10:00	8.0 8.0	WNW WNW

Date	Time	Wind Speed m/s	Direction
14-Nov-2007	12:00	6.0	W
14-Nov-2007	13:00	6.0	WNW
14-Nov-2007	14:00	5.0	WSW
14-Nov-2007	15:00	5.0	WNW
14-Nov-2007	16:00	4.0	WSW
14-Nov-2007	17:00	5.0	W
14-Nov-2007	18:00	3.0	WSW
14-Nov-2007	19:00	3.0	W
14-Nov-2007	20:00	2.0	W
14-Nov-2007	21:00	3.0	WSW
14-Nov-2007	22:00	1.0	SW
14-Nov-2007	23:00	0.0	
15-Nov-2007	0:00	0.0	
15-Nov-2007	1:00	3.0	SW
15-Nov-2007	2:00	2.0	SW
15-Nov-2007	3:00	1.0	SW
15-Nov-2007	4:00	0.0	
15-Nov-2007	5:00	0.0	
15-Nov-2007	6:00	0.0	
15-Nov-2007	7:00	0.0	SE
15-Nov-2007	8:00	0.0	
15-Nov-2007	9:00	2.0	WNW
15-Nov-2007	10:00	4.0	WNW
15-Nov-2007	11:00	5.0	WNW
15-Nov-2007	12:00	6.0	WNW
15-Nov-2007	13:00	5.0	WNW
15-Nov-2007	14:00	4.0	WNW
15-Nov-2007	15:00	6.0	WNW
15-Nov-2007 15-Nov-2007	16:00	8.0	WNW
15-Nov-2007	17:00	8.0	WNW
			WNW
15-Nov-2007	18:00	6.0	W
15-Nov-2007	19:00	8.0	W
15-Nov-2007	20:00	7.0	
15-Nov-2007	21:00 22:00	3.0	SSW SSW
15-Nov-2007		3.0	
15-Nov-2007	23:00	1.0	SW
16-Nov-2007	0:00	0.0	
16-Nov-2007	1:00	1.0	SW
16-Nov-2007	2:00	0.0	SW
16-Nov-2007	3:00	0.0	SW
16-Nov-2007	4:00	0.0	
16-Nov-2007	5:00	0.0	SW
16-Nov-2007	6:00	0.0	
16-Nov-2007	7:00	0.0	
16-Nov-2007	8:00	1.0	WSW
16-Nov-2007	9:00	3.0	WNW
16-Nov-2007	10:00	6.0	W
16-Nov-2007	11:00	11.0	WNW
16-Nov-2007	12:00	11.0	WNW
16-Nov-2007	13:00	10.0	WNW
16-Nov-2007	14:00	8.0	WNW
16-Nov-2007	15:00	9.0	WNW
16-Nov-2007	16:00	4.0	WNW
16-Nov-2007	17:00	3.0	WNW

Date	Time	Wind Speed m/s	Direction
16-Nov-2007	18:00	2.0	WSW
16-Nov-2007	19:00	2.0	WSW
16-Nov-2007	20:00	0.0	SW
16-Nov-2007	21:00	0.0	SW
16-Nov-2007	22:00	2.0	SW
16-Nov-2007	23:00	3.0	NW
17-Nov-2007	0:00	7.0	SW
17-Nov-2007	1:00	7.0	W
17-Nov-2007	2:00	8.0	W
17-Nov-2007	3:00	8.0	W
17-Nov-2007	4:00	8.0	W
17-Nov-2007	5:00	7.0	W
17-Nov-2007	6:00	7.0	W
17-Nov-2007	7:00	7.0	W
17-Nov-2007	8:00	7.0	WNW
17-Nov-2007	9:00	9.0	W
17-Nov-2007	10:00	8.0	W
17-Nov-2007	11:00	8.0	WNW
17-Nov-2007	12:00	5.0	WNW
17-Nov-2007	13:00	5.0	WNW
17-Nov-2007	14:00	4.0	W
17-Nov-2007	15:00	4.0	W
17-Nov-2007	16:00	2.0	WNW
17-Nov-2007	17:00	2.0	SW
17-Nov-2007	18:00	2.0	SSW
17-Nov-2007	19:00	0.0	SSW
17-Nov-2007	20:00	3.0	W
17-Nov-2007	21:00	1.0	W
17-Nov-2007	22:00	2.0	W
17-Nov-2007	23:00	3.0	SW
18-Nov-2007	0:00	2.0	SW
18-Nov-2007	1:00	3.0	SSW
18-Nov-2007	2:00	3.0	W
18-Nov-2007	3:00	2.0	SW
18-Nov-2007	4:00	1.0	SSW
18-Nov-2007	5:00	2.0	SW
18-Nov-2007	6:00	6.0	W
18-Nov-2007	7:00	12.0	W
18-Nov-2007	8:00	8.0	W
18-Nov-2007	9:00	9.0	W
18-Nov-2007	10:00	12.0	WNW
18-Nov-2007	11:00	10.0	W
18-Nov-2007	12:00	12.0	WNW
18-Nov-2007	13:00	10.0	WNW
18-Nov-2007	14:00	10.0	WNW
18-Nov-2007	15:00	8.0	WNW
18-Nov-2007	16:00	8.0	WSW
18-Nov-2007	17:00	8.0	WSW
18-Nov-2007 18-Nov-2007			SW
	18:00	7.0	WSW
18-Nov-2007	19:00	7.0	
18-Nov-2007	20:00	6.0	WSW
18-Nov-2007	21:00	6.0	SW
18-Nov-2007	22:00	6.0	WSW
18-Nov-2007	23:00	7.0	SW

Date	Time	Wind Speed m/s	Direction
19-Nov-2007	0:00	7.0	WSW
19-Nov-2007	1:00	4.0	W
19-Nov-2007	2:00	5.0	WSW
19-Nov-2007	3:00	8.0	WNW
19-Nov-2007	4:00	8.0	WNW
19-Nov-2007	5:00	6.0	W
19-Nov-2007	6:00	2.0	SW
19-Nov-2007	7:00	4.0	SW
19-Nov-2007	8:00	3.0	WSW
19-Nov-2007	9:00	5.0	WSW
19-Nov-2007	10:00	6.0	WSW
19-Nov-2007	11:00	6.0	SW
19-Nov-2007	12:00	6.0	WNW
19-Nov-2007	13:00	6.0	WNW
19-Nov-2007	14:00	9.0	W
19-Nov-2007	15:00	8.0	W
19-Nov-2007	16:00	6.0	W
19-Nov-2007	17:00	2.0	W
19-Nov-2007	18:00	0.0	W
19-Nov-2007	19:00	0.0	
19-Nov-2007	20:00	1.0	S
19-Nov-2007	21:00	4.0	SW
19-Nov-2007	22:00	8.0	SW
19-Nov-2007	23:00	7.0	WSW
20-Nov-2007	0:00	4.0	SW
20-Nov-2007	1:00	4.0	W
20-Nov-2007	2:00	5.0	SW
20-Nov-2007	3:00	5.0	SW
20-Nov-2007	4:00	8.0	WNW
20-Nov-2007	5:00	6.0	SW
20-Nov-2007	6:00	8.0	SW
20-Nov-2007	7:00	5.0	WSW
20-Nov-2007	8:00	7.0	W
20-Nov-2007	9:00	12.0	WNW
20-Nov-2007	10:00	13.0	WNW
20-Nov-2007	11:00	11.0	WNW
20-Nov-2007	12:00	8.0	WNW
20-Nov-2007	13:00	6.0	W
20-Nov-2007	14:00	4.0	WNW
20-Nov-2007	15:00	6.0	W
20-Nov-2007	16:00	5.0	W
20-Nov-2007	17:00	4.0	W
20-Nov-2007	18:00	0.0	WSW
20-Nov-2007	19:00	0.0	
20-Nov-2007	20:00	0.0	
20-Nov-2007	21:00	0.0	
20-Nov-2007	22:00	0.0	
20-Nov-2007	23:00	0.0	
21-Nov-2007	0:00	0.0	
21-Nov-2007	1:00	0.0	
21-Nov-2007	2:00	1.0	WSW
21-Nov-2007	3:00	2.0	SW
21-Nov-2007	4:00	4.0	W
	1.00	1.0	* *

Date	Time	Wind Speed m/s	Direction
21-Nov-2007	6:00	2.0	W
21-Nov-2007	7:00	2.0	W
21-Nov-2007	8:00	5.0	W
21-Nov-2007	9:00	6.0	W
21-Nov-2007	10:00	8.0	W
21-Nov-2007	11:00	10.0	WNW
21-Nov-2007	12:00	9.0	W
21-Nov-2007	13:00	8.0	W
21-Nov-2007	14:00	7.0	W
21-Nov-2007	15:00	8.0	W
21-Nov-2007	16:00	5.0	WSW
21-Nov-2007	17:00	5.0	WSW
21-Nov-2007	18:00	2.0	WSW
21-Nov-2007	19:00	3.0	W
21-Nov-2007	20:00	3.0	WSW
21-Nov-2007	21:00	1.0	NW
21-Nov-2007	22:00	3.0	SW
21-Nov-2007	23:00	5.0	WNW
22-Nov-2007	0:00	9.0	WNW
22-Nov-2007	1:00	9.0	W
22-Nov-2007	2:00	4.0	WNW
22-Nov-2007	3:00	1.0	SSW
22-Nov-2007	4:00	2.0	SSW
22-Nov-2007	5:00	3.0	SSW
22-Nov-2007	6:00	5.0	SW
22-Nov-2007	7:00	6.0	WSW
22-Nov-2007	8:00	5.0	WNW
22-Nov-2007 22-Nov-2007	9:00	3.0	WSW
22-Nov-2007 22-Nov-2007	10:00	5.0	WNW
22-Nov-2007	11:00	7.0	WNW
22-Nov-2007 22-Nov-2007	12:00	9.0	WNW
22-Nov-2007 22-Nov-2007	13:00	8.0	W
22-Nov-2007 22-Nov-2007	14:00	5.0	WSW
22-Nov-2007 22-Nov-2007	15:00	6.0	SW
22-Nov-2007 22-Nov-2007	16:00	3.0	WSW
22-Nov-2007 22-Nov-2007	17:00	5.0	W
22-Nov-2007 22-Nov-2007	18:00	5.0	W
22-Nov-2007 22-Nov-2007	19:00	4.0	W
22-Nov-2007 22-Nov-2007	20:00	3.0	W
22-Nov-2007 22-Nov-2007	21:00	1.0	W
	22:00	2.0	W
22-Nov-2007	23:00	1.0	NW
22-Nov-2007			W
23-Nov-2007	0:00	2.0	WSW
23-Nov-2007	1:00	3.0	WSW
23-Nov-2007	2:00	6.0	W
23-Nov-2007	3:00	1.0	
23-Nov-2007	4:00	3.0	SW
23-Nov-2007	5:00	3.0	SW
23-Nov-2007	6:00	4.0	SW
23-Nov-2007	7:00	2.0	WSW
23-Nov-2007	8:00	4.0	WNW
23-Nov-2007	9:00	7.0	WNW
23-Nov-2007	10:00	7.0	WNW
23-Nov-2007	11:00	7.0	W

Date	Time	Wind Speed m/s	Direction
23-Nov-2007	12:00	7.0	SW
23-Nov-2007	13:00	6.0	SW
23-Nov-2007	14:00	8.0	W
23-Nov-2007	15:00	7.0	WNW
23-Nov-2007	16:00	4.0	WNW
23-Nov-2007	17:00	5.0	W
23-Nov-2007	18:00	2.0	W
23-Nov-2007	19:00	0.0	SSW
23-Nov-2007	20:00	0.0	
23-Nov-2007	21:00	0.0	
23-Nov-2007	22:00	2.0	WNW
23-Nov-2007	23:00	3.0	W
24-Nov-2007	0:00	3.0	SSW
24-Nov-2007	1:00	2.0	SSW
24-Nov-2007	2:00	0.0	SSW
24-Nov-2007	3:00	0.0	
24-Nov-2007	4:00	0.0	
24-Nov-2007	5:00	2.0	WSW
24-Nov-2007	6:00	2.0	W
24-Nov-2007	7:00	0.0	WNW
24-Nov-2007	8:00	2.0	SW
24-Nov-2007	9:00	6.0	SW
24-Nov-2007	10:00	9.0	WNW
24-Nov-2007	11:00	9.0	W
24-Nov-2007	12:00	8.0	WSW
24-Nov-2007	13:00	8.0	SW
24-Nov-2007	14:00	7.0	WSW
24-Nov-2007	15:00	5.0	SW
24-Nov-2007	16:00	7.0	W
24-Nov-2007	17:00	5.0	W
24-Nov-2007	18:00	5.0	WNW
24-Nov-2007	19:00	3.0	WNW
24-Nov-2007	20:00	3.0	WSW
24-Nov-2007	21:00	2.0	SSW
24-Nov-2007	22:00	2.0	SW
24-Nov-2007	23:00	2.0	SSW
25-Nov-2007	0:00	3.0	W
25-Nov-2007	1:00	1.0	WNW
25-Nov-2007	2:00	0.0	WSW
25-Nov-2007 25-Nov-2007	3:00	0.0	
25-Nov-2007	4:00	0.0	
25-Nov-2007 25-Nov-2007	5:00	0.0	
25-Nov-2007 25-Nov-2007	6:00	0.0	
25-Nov-2007 25-Nov-2007	7:00	0.0	
25-Nov-2007 25-Nov-2007	8:00	0.0	
25-Nov-2007 25-Nov-2007	9:00	0.0	WSW
25-Nov-2007 25-Nov-2007	10:00	4.0	WNW
25-Nov-2007 25-Nov-2007	11:00	6.0	W
			SW
25-Nov-2007	12:00	7.0	
25-Nov-2007	13:00	8.0	W
25-Nov-2007	14:00	3.0	W
25-Nov-2007	15:00	3.0	WSW
25-Nov-2007	16:00	1.0	SSW
25-Nov-2007	17:00	0.0	SSW

Date	Time	Wind Speed m/s	Direction
25-Nov-2007	18:00	1.0	SW
25-Nov-2007	19:00	1.0	SSW
25-Nov-2007	20:00	1.0	SSW
25-Nov-2007	21:00	4.0	SW
25-Nov-2007	22:00	5.0	SW
25-Nov-2007	23:00	7.0	WSW
26-Nov-2007	0:00	5.0	W
26-Nov-2007	1:00	4.0	WNW
26-Nov-2007	2:00	6.0	WSW
26-Nov-2007	3:00	5.0	WSW
26-Nov-2007	4:00	6.0	WNW
26-Nov-2007	5:00	4.0	WNW
26-Nov-2007	6:00	4.0	WSW
26-Nov-2007	7:00	2.0	WSW
26-Nov-2007	8:00	6.0	WSW
26-Nov-2007	9:00	7.0	WSW
26-Nov-2007	10:00	7.0	WSW
26-Nov-2007	11:00	5.0	SW
26-Nov-2007	12:00	9.0	WSW
26-Nov-2007	13:00	7.0	SW
26-Nov-2007	14:00	6.0	WSW
26-Nov-2007	15:00	7.0	SW
26-Nov-2007	16:00	6.0	SW
26-Nov-2007	17:00	5.0	W
26-Nov-2007	18:00	5.0	W
26-Nov-2007	19:00	10.0	WSW
26-Nov-2007	20:00	8.0	WSW
26-Nov-2007	21:00	7.0	W
26-Nov-2007	22:00	10.0	WSW
26-Nov-2007	23:00	8.0	WSW
27-Nov-2007	0:00	12.0	WSW
27-Nov-2007	1:00	10.0	WSW
27-Nov-2007	2:00	10.0	WSW
27-Nov-2007 27-Nov-2007	3:00	6.0	W
27-Nov-2007 27-Nov-2007	4:00	7.0	WSW
27-Nov-2007 27-Nov-2007	5:00	14.0	WSW
27-Nov-2007 27-Nov-2007	6:00	13.0	WSW
27-Nov-2007 27-Nov-2007	7:00	7.0	WSW
27-Nov-2007 27-Nov-2007	8:00	10.0	WSW
27-Nov-2007 27-Nov-2007	9:00	13.0	WSW
	10:00	14.0	WSW
27-Nov-2007 27-Nov-2007		15.0	WSW
	11:00		W
27-Nov-2007	12:00	7.0	W
27-Nov-2007	13:00 14:00	3.0	W
27-Nov-2007 27-Nov-2007			SSW
	15:00 16:00	4.0	
27-Nov-2007	16:00	4.0	WSW
27-Nov-2007	17:00	2.0	WSW
27-Nov-2007	18:00	2.0	SW
27-Nov-2007	19:00	3.0	SW
27-Nov-2007	20:00	2.0	WSW
07 NL 0007			
27-Nov-2007 27-Nov-2007	21:00 22:00	3.0	SSW WSW

Date	Time	Wind Speed m/s	Direction
28-Nov-2007	0:00	5.0	WSW
28-Nov-2007	1:00	2.0	SW
28-Nov-2007	2:00	3.0	SW
28-Nov-2007	3:00	2.0	SW
28-Nov-2007	4:00	2.0	WSW
28-Nov-2007	5:00	4.0	SW
28-Nov-2007	6:00	2.0	W
28-Nov-2007	7:00	4.0	WSW
28-Nov-2007	8:00	6.0	SW
28-Nov-2007	9:00	6.0	W
28-Nov-2007	10:00	6.0	WSW
28-Nov-2007	11:00	6.0	WSW
28-Nov-2007	12:00	7.0	W
28-Nov-2007	13:00	4.0	WNW
28-Nov-2007	14:00	5.0	WSW
28-Nov-2007	15:00	4.0	W
28-Nov-2007	16:00	4.0	WSW
28-Nov-2007	17:00	1.0	SSW
28-Nov-2007	18:00	0.0	SW
28-Nov-2007	19:00	1.0	SSW
28-Nov-2007 28-Nov-2007	20:00	1.0	SW
28-Nov-2007	21:00	1.0	SW
28-Nov-2007	22:00	4.0	SW
	23:00	5.0	SW
28-Nov-2007 29-Nov-2007	0:00	4.0	SW
	1:00	3.0	SW
29-Nov-2007 29-Nov-2007	2:00	1.0	SW
29-Nov-2007 29-Nov-2007			SW
	3:00	0.0	
29-Nov-2007	4:00	0.0	
29-Nov-2007	5:00	0.0	
29-Nov-2007	6:00	0.0	
29-Nov-2007	7:00	0.0	
29-Nov-2007	8:00	0.0	
29-Nov-2007	9:00	1.0	W
29-Nov-2007	10:00	7.0	WNW
29-Nov-2007	11:00	9.0	W
29-Nov-2007	12:00	7.0	W
29-Nov-2007	13:00	7.0	WNW
29-Nov-2007	14:00	8.0	WNW
29-Nov-2007	15:00	6.0	W
29-Nov-2007	16:00	4.0	W
29-Nov-2007	17:00	1.0	WNW
29-Nov-2007	18:00	0.0	ENE
29-Nov-2007	19:00	0.0	
29-Nov-2007	20:00	0.0	
29-Nov-2007	21:00	0.0	
29-Nov-2007	22:00	0.0	
29-Nov-2007	23:00	0.0	
30-Nov-2007	0:00	0.0	
30-Nov-2007	1:00	0.0	
30-Nov-2007	2:00	0.0	
30-Nov-2007	3:00	0.0	
30-Nov-2007	4:00	0.0	
30-Nov-2007	5:00	0.0	

Date	Time	Wind Speed m/s	Direction
30-Nov-2007	6:00	0.0	
30-Nov-2007	7:00	0.0	
30-Nov-2007	8:00	0.0	
30-Nov-2007	9:00	0.0	
30-Nov-2007	10:00	1.0	W
30-Nov-2007	11:00	6.0	WNW
30-Nov-2007	12:00	5.0	WNW
30-Nov-2007	13:00	6.0	WNW
30-Nov-2007	14:00	6.0	WNW
30-Nov-2007	15:00	5.0	NW
30-Nov-2007	16:00	7.0	W
30-Nov-2007	17:00	6.0	W
30-Nov-2007	18:00	3.0	WNW
30-Nov-2007	19:00	1.0	WSW
30-Nov-2007	20:00	0.0	SW
30-Nov-2007	21:00	0.0	
30-Nov-2007	22:00	0.0	
30-Nov-2007	23:00	0.0	


APPENDIX E 1-HOUR TSP MONITORING RESULTS AND GRAPHICAL PRESENTATION

Appendix E - 1-hour TSP Monitoring Results

Location AM 2 - Lai Chi Kok Sports Centre

Date	Weather	Filter We	eight (g)	Flow Rate	e (m³/min.)	Elaps	se Time	Air	Atmospheric	Particulate	Av. flow	Total vol.	Sampling	Conc.
	Condition	Initial	Final	Initial	Final	Initial	Final	Temp. (K)	Pressure(Pa)	weight(g)	(m ³ /min)	(m^3)	Time(hrs.)	$(\mu g/m^3)$
1-Nov-07	Cloudy	2.7659	2.7826	1.24	1.24	6770.1	6771.1	291.9	767.1	0.0167	1.24	74.3	1.0	224.9
5-Nov-07	Sunny	2.8163	2.8295	1.23	1.23	6795.1	6796.1	293.5	765.2	0.0132	1.23	74.0	1.0	178.4
6-Nov-07	Sunny	2.8137	2.8307	1.23	1.23	6796.1	6797.1	294.1	764.0	0.0170	1.23	73.9	1.0	230.0
8-Nov-07	Sunny	2.8011	2.8220	1.24	1.24	6797.1	6798.1	291.2	763.7	0.0209	1.24	74.2	1.0	281.7
12-Nov-07	Sunny	2.8456	2.8616	1.21	1.21	6822.1	6823.1	294.0	766.3	0.0160	1.21	72.8	1.0	219.7
13-Nov-07	Sunny	2.8207	2.8323	1.21	1.21	6823.1	6824.1	294.2	766.3	0.0116	1.21	72.8	1.0	159.4
16-Nov-07	Sunny	2.8301	2.8363	1.20	1.20	6848.1	6849.1	298.9	765.7	0.0062	1.20	72.3	1.0	85.8
19-Nov-07	Sunny	2.8208	2.8340	1.22	1.22	6849.0	6850.0	291.7	769.9	0.0132	1.22	73.2	1.0	180.3
20-Nov-07	Sunny	2.8024	2.8163	1.22	1.22	6850.1	6851.1	291.9	769.7	0.0139	1.22	73.2	1.0	189.9
22-Nov-07	Sunny	2.8208	2.8357	1.21	1.21	6875.1	6876.1	296.2	766.2	0.0149	1.21	72.6	1.0	205.3
26-Nov-07	Sunny	2.8097	2.8292	1.21	1.21	6876.1	6877.1	294.6	764.4	0.0195	1.21	72.7	1.0	268.4
28-Nov-07	Sunny	2.8197	2.8356	1.21	1.21	6901.1	6902.1	297.7	765.4	0.0159	1.21	72.4	1.0	219.7
29-Nov-07	Sunny	2.8147	2.8271	1.22	1.22	6901.1	6902.1	289.5	769.7	0.0124	1.22	73.5	1.0	168.8
	-	-		-				-				-	Min	85.8
													Max	281.7
													Average	201.0

1-hr TSP Levels



Route 8 (previously known as Route 9) between Cheung Sha Wan & Sha Tin Contract HY/2003/01 - Lai Chi Kok Viaduct

Title

Graphical Presentation of 1-hour TSP Impact Monitoring Results

Scale Project No.

N.T.S MA3024

Date Appendix
Nov 07 E

CINOTECH


APPENDIX F 24-HOUR TSP MONITORING RESULTS AND GRAPHICAL PRESENTATION

Appendix F - 24-hour TSP Monitoring Results

Location AM 2 - Lai Chi Kok Sports Centre

Date	Weather	Filter W	eight (g)	Flow Rate	e (m³/min.)	Elaps	se Time	Air	Atmospheric	Particulate	Av. flow	Total vol.	Sampling	Conc.
	Condition	Initial	Final	Initial	Final	Initial	Final	Temp. (K)	Pressure(Pa)	weight(g)	(m ³ /min)	(m^3)	Time(hrs.)	$(\mu g/m^3)$
3-Nov-07	Sunny	2.8388	2.9779	1.24	1.24	6771.1	6795.1	291.9	767.1	0.1391	1.24	1782.1	24.0	78.1
9-Nov-07	Sunny	2.8333	2.9902	1.23	1.23	6798.1	6822.1	295.2	764.4	0.1569	1.23	1771.1	24.0	88.6
15-Nov-07	Sunny	2.8130	2.9584	1.21	1.21	6824.1	6848.1	295.4	767.5	0.1454	1.21	1744.9	24.0	83.3
21-Nov-07	Sunny	2.8159	2.9548	1.22	1.22	6851.1	6875.1	291.8	769.7	0.1389	1.22	1756.5	24.0	79.1
27-Nov-07	Sunny	2.8209	3.0760	1.22	1.22	6877.1	6901.1	291.6	763.9	0.2551	1.22	1751.3	24.0	145.7
													Min	78.1
													Max	145.7
													Average	94.9

24-hr TSP Levels



Title

Route 8 (previously known as Route 9) between Cheung Sha Wan & Sha Tin Contract HY/2003/01 - Lai Chi Kok Viaduct

Graphical Presentation of 24-hour TSP Impact Monitoring Results

Scale Project No. MA3024

Appendix Nov 07



APPENDIX G NOISE MONITORING RESULTS AND GRAPHICAL PRESENTATION

Appendix G - Noise Monitoring Results

Location N	Location NM2 - Lai Chi Kok Reception Centre											
						Unit: dB (A) (30						
Date	Time Weather		Measured Noise Level			Baseline Level	Construction Noise Level	Remarks				
			L _{eq}	L ₁₀	L 90	L _{eq}	L _{eq}					
5-Nov-07	13:40	Fine	64.8	67.7	60.2		64.8, Measured ≤ Baseline					
12-Nov-07	14:31	Fine	65.4	67.7	61.2	68.4	65.4, Measured ≤ Baseline	Resumed since September 2006				
19-Nov-07	15:30	Sunny	59.7	60.5	56.0	00.4	59.7, Measured ≤ Baseline	Resultied silice September 2000				
26-Nov-07	09:00	Sunny	63.9	65.7	58.2		63.9, Measured ≤ Baseline					

Location N	Location NM4 - Mei Foo Sun Chuen, Phase 5											
						Unit: dB (A) (30						
Date	Date Time Weather		Measured Noise Level			Baseline Level	Construction Noise Level	Remarks				
			L _{eq}	L ₁₀	L 90	L _{eq}	L _{eq}					
5-Nov-07	10:06	Fine	74.3	76.0	71.5		64.7	Dood traffic poins from China				
12-Nov-07	11:10	Fine	74.8	76.5	71.5	72.0	67.9	Road traffic noise from Ching				
19-Nov-07	17:25	Sunny	66.4	69.5	63.0	73.8	66.4, Measured ≤ Baseline	Cheung Road was identified as the major noise source.				
26-Nov-07	09:47	Sunny	70.2	72.0	63.5		70.2, Measured ≤ Baseline	major noise source.				

Location N	Location NM8a - M/F of Nob Hill									
Date	ate Time Weather		Unit: d	IB (A) (3	0-min)	Remarks				
			L _{eq}	L ₁₀	L 90					
5-Nov-07	10:50	Fine	69.9	72.5	66.0					
12-Nov-07	13:07	Fine	69.1	72.0	65.5	Road traffic noise from Ching Cheung Road				
19-Nov-07	16:10	Sunny	70.7	73.0	66.5	was identified as the major noise source.				
26-Nov-07	10:24	Sunny	72.3	74.0	65.5					

Location N	Location NM8b - 3/F of Nob Hill										
Date	Time	Weather	Unit: d	IB (A) (3	0-min)	Remarks					
			L _{eq}	L ₁₀	L ₉₀						
5-Nov-07	11:25	Fine	75.7	78.0	72.5	This Station (NM8b) which is strongly					
12-Nov-07	13:40	Fine	75.2	77.5	72.5	influenced by road traffic noise from Ching Cheung Road. The measurement at this station					
19-Nov-07	16:45	Sunny	74.6	76.5	71.0	is for reference purpose, but not for compliance					
26-Nov-07	10:57	Sunny	71.8	73.0	64.5	check for construction noise.					

Location N	Location NM9 - Hoi Lai Estate									
Date Time		Weather	Unit: d	IB (A) (3	0-min)	Remarks				
			L _{eq}	L ₁₀	L 90					
5-Nov-07	14:30	Fine	68.6	72.0	65.0					
12-Nov-07	15:20	Fine	66.8	71.5	62.5	_				
19-Nov-07	18:20	Sunny	61.7	64.0	59.0	-				
26-Nov-07	13:00	Sunny	66.2	67.5	62.0					

[#] Construction Noise Level (Leq) = Measured Noise Level (Leq) - Baseline Noise Level (Leq)


^{*}Bolded value indicated limit level exceedance

Appendix G - Noise Monitoring Results

Restricted Hours - 19:00 to 23:00 on normal weekdays

Location N	М9 - Но	oi Lai Estat	:e					
Data	Time	\A/a athan	dB (A) (5-min)					
Date	Time	Weather	L _{eq}	L ₁₀	L 90	Average L _{eq}		
	19:00		62.5	65.5	58.5			
6-Nov-07	19:05	Cloudy	62.8	65.5	58.5	62.7		
	19:10		62.9	65.5	58.5			
	19:05		62.3	66.5	59.0			
13-Nov-07	19:10	Cloudy	62.5	66.5	59.5	62.6		
	19:15		62.9	67.0	60.0			
	19:20		63.5	68.0	60.5			
20-Nov-07	19:25	Cloudy	63.8	68.5	61.0	63.6		
	19:30		63.5	68.0	60.5			
	19:00		64.0	69.0	61.0			
27-Nov-07	19:05	Cloudy	64.1	69.0	61.0	64.2		
	19:10		64.4	69.0	61.0			

[#] Construction Noise Level (Leq) = Measured Noise Level (Leq) - Baseline Noise Level (Leq)



* Construction Noise Level = Measured Noise Level - Baseline Level (If the measured noise level is lower than the baseline level, the construction noise level will be taken as the measured one)


Title
Route 8 (previously known as Route 9) between Cheung Sha Wan and Sha Tin
Contract HY/2003/01 - Lai Chi Kok Viaduct


Graphical Presentation of Construction Noise Monitoring Results

Scale		Project
	N.T.S	No. MA3024
Date	Nov 07	Appendix G



Noise Levels





Title


Route 8 (previously known as Route 9) between Cheung Sha Wan and Sha Tin Contract HY/2003/01 - Lai Chi Kok Viaduct

Graphical Presentation of Construction Noise Monitoring Results

Scale		Project				
	N.T.S	No.	MA3024			
Date		Apper	ndix			
	Nov 07		G			



Restricted Hours (19:00 to 23:00) - Noise Levels



Title
Route 8 (previously known as Route 9) between Cheung Sha Wan and Sha Tin
Contract HY/2003/01 - Lai Chi Kok Viaduct

Graphical Presentation of Construction Noise Monitoring Results

 Scale
 Project No.
 MA3024

 Date
 Nov 07
 Appendix G



APPENDIX H SUMMARY OF EXCEEDANCE

Environmental Monitoring and Audit Report – November 2007

Summary of Exceedances Recorded in the Reporting Month

a) Exceedance Report for 1-hr TSP

• No Action/Limit Level exceedance was recorded in the reporting month.

b) Exceedance Report for 24-hr TSP

• No Action/Limit Level exceedance was recorded in the reporting month.

c) Exceedance Report for Construction Noise

• No Action/Limit Level exceedance was recorded in the reporting month.

APPENDIX I SITE AUDIT SUMMARY

Weekly Site Inspection Record Summary

Non-Compliance

Inspection Information

Ref. No.

Checklist Reference Number	71107C-LCKV
Date	7 November 2007 (Wed)
Time	9:45 – 10:45

Related Item No.

-	None identified	-
Ref. No.	Remarks/Observations	Related Item No.
	A. Water Quality	
	Standing water was observed under the bridge at Nob Hill. The	
	Contractor was reminded to spray the larvicide oil to prevent mosquito	B14
R01	breed.	G5
	B. Air Quality	
	No environmental deficiency was identified during the site inspection.	
	C. Noise	•
	No environmental deficiency was identified during the site inspection.	
	D. Waste / Chemical Management	
	No environmental deficiency was identified during the site inspection.	,
	E. Permit / Licenses	
1	No environmental deficiency was identified during the site inspection.	
	F. Others	
	• Follow-up on previous audit (Ref. No.:71031-LCKV), no environmental	
	deficiency was observed.	
	• Covering of loaded truck leaving the site was checked during the site	
	inspection. No uncovered truck leaving the construction site was	
	observed during the site inspection.	

Chace.	7 November 2007
Não	7 November 2007
-	NIT

CINOTECH MA3024 71107_LCKV

Route 8 - Environmental Team for Lai Chi Kok Viaduct and Eagle's Nest Tunnel Contract No. HY/2003/05 - Traffic Control and Surveillance System

Weekly Site Inspection Record Summary

Inspection Information

CINOTECH MA3024

Checklist Reference Number	71107-LCKV-TCSS	
Date	7 November 2007 (Wednesday)	
Time	14:30-14:40	

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	A. Water Quality	
	No environmental deficiency was identified during the site inspection.	
	B. Air Quality	
	No environmental deficiency was identified during the site inspection.	
	C. Noise	
	• No environmental deficiency was identified during the site inspection.	·
}		
	D. Waste / Chemical Management	
	• No environmental deficiency was identified during the site inspection.	
	E. Permit / Licenses	
	• No environmental deficiency was identified during the site inspection.	
	F. Others	
	• Follow-up for previous audit session (Ref. No.: 71009-LCKV-TCSS), no	
	environmental deficiency was identified during the site inspection.	

	Name	Signature	Date
Recorded by	Grace Wong	Crace.	7 November 2007
Checked by	Dr. Priscilla Choy	MF	7 November 2007

Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	71114C-LCKV
Date	14 November 2007 (Wed)
Time	13:35 – 14:35

_	Rel. No.	Non-Comphance	Related Item No.
	-	None identified	
	Ref No	Remarks/Observations	Related Item No.

Ref. No.	Remarks/Observations	Related Item No.
R01	 A. Water Quality Standing water was observed in the drip tray at D12. The Contractor was reminded to dry it out to prevent mosquito breeding. 	B14 G5
	 B. Air Quality No environmental deficiency was identified during the site inspection. 	
	 C. Noise No environmental deficiency was identified during the site inspection. 	
	 D. Waste / Chemical Management No environmental deficiency was identified during the site inspection. 	
	E. Permit / Licenses No environmental deficiency was identified during the site inspection.	į
	 F. Others Follow-up on previous audit (Ref. No.:71107-LCKV), the environmental deficiency was observed. Covering of loaded truck leaving the site was checked during the site inspection. No uncovered truck leaving the construction site was observed during the site inspection. 	

	Name	Signature	Date
Recorded by	Robert Tsang	Toing	14 November 2007
Checked by	Dr. Priscilla Choy	N.T.	14 November 2007

CINOTECH MA3024 71114_LCKV

Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	71121C-LCKV
Date	21 November 2007 (Wed)
Time	13:45 – 15:00

Ref. No.	Non-Compliance	Related Item No.	
-	None identified	-	

Ref. No.	Remarks/Observations	Related Item No.
	A. Water Quality	
	• No environmental deficiency was identified during the site inspection.	
	B. Air Quality	
	• No environmental deficiency was identified during the site inspection.	}
ļ		
	C. Noise	
	No environmental deficiency was identified during the site inspection.	
	D. Waste / Chemical Management	
	No environmental deficiency was identified during the site inspection.	
	E Barwit / Licanos	
	E. Permit / Licenses	
	No environmental deficiency was identified during the site inspection.	
	F. Others	
	• Follow-up on previous audit (Ref. No.:71114-LCKV), the environmental	
	· ·	
	deficiency was rectified.	
	• Covering of loaded truck leaving the site was checked during the site	
	inspection. No uncovered truck leaving the construction site was	
	observed during the site inspection.	

	Name	Signature	Date
Recorded by	Grace Wong	Grace.	21 November 2007
Checked by	Dr. Priscilla Choy	MI	21 November 2007

CINOTECH MA3024 71121_LCKV

Weekly Site Inspection Record Summary

Inspection Information

Checklist Reference Number	71128C-LCKV
Date	28 November 2007 (Wed)
Time	13:30 – 15:20

Ref. No.	Non-Compliance	Related Item No.
-	None identified	-

Ref. No.	Remarks/Observations	Related Item No.
	 A. Water Quality No environmental deficiency was identified during the site inspection. 	
O-01	 B. Air Quality The haul road was found to the dusty at Mui Kong Tsuen. The Contractor was advised to clean the haul road to suppress the dust generation. 	C7
	C. NoiseNo environmental deficiency was identified during the site inspection.	10
R-01	 D. Waste / Chemical Management General refuse was found dumping at S4. The Contractor was reminded to clear the refuse. 	Eli
	E. Permit / Licenses No environmental deficiency was identified during the site inspection.	
	F. Others • Follow-up on previous audit (Ref. No.:71121-LCKV), the environmental deficiency was rectified.	
	Covering of loaded truck leaving the site was checked during the site inspection. No uncovered truck leaving the construction site was observed without cover during the site inspection.	

	Name	Signature	Date
Recorded by	Grace Wong	Que	28 November 2007
Checked by	Dr. Priscilla Choy	WIL	28 November 2007

CINOTECH MA3024 71128_LCKV

APPENDIX J EVENT ACTION PLANS

Appendix J - Event Action Plans

Event/Action Plan for Air Quality

EVENT		ACTIO	N			
EVENI	ET	IEC	ER	Contractor		
ACTION LEVEL	CTION LEVEL					
1. Exceedance for one	1. Identify source	1. Check monitoring data submitted by ET	1. Notify Contractor	1. Rectify any unacceptable practice		
sample	2. Inform ER & IEC	2. Check Contractor's working methods	2. Check monitoring data and Contractor's	2. Amend working methods if		
	3. Repeat measurement to confirm finding		working methods	appropriate		
	4. Increase monitoring frequency to daily					
2. Exceedance for two or	1. Identify source	1. Checking monitoring data submitted by	1. Confirm receipt of notification of failure	1. Submit proposals for remedial		
more consecutive samples	2. Inform ER & IEC	ET	in writing	actions to ER within 3 working days		
	3. Repeat measurement to confirm findings	2. Check Contractor's working methods	2. Notify Contractor	of notification		
	4. Increase monitoring frequency to daily	3. Discuss with ET and Contractor on	3. Check Contractor's working methods	2. Implement the agreed proposals		
	5. Discuss with ER & for remedial actions	possible remedial measure	4. Discuss with ET, IEC and Contractor on	3. Amend proposal if appropriate		
	required	4. Advise the ER & ET on the effectiveness	proposed remedial actions			
	6. If exceedance continues, arrange	of the proposed remedial measures	5. Ensure remedial actions properly			
	meeting with ER & IEC	5. Supervise the implementation of the	implemented			
	7. If exceedance stops, cease additional	remedial measures				
	monitoring					
LIMIT LEVEL						
1. Exceedance for one	1. Identify source	1. Checking monitoring data submitted by	1. Confirm receipt of notification of failure	1. Take immediate action to avoid		
sample	2. Inform ER & IEC and EPD	ET	in writing	further exceedance		
	3. Repeat measurement to confirm finding	2. Check Contractor's working methods	2. Notify Contractor	2. Submit proposals for remedial		
	4. Increase monitoring frequency to daily	3. Discuss with ET and Contractor on	3. Check Contractor's working methods	actions to ER within 3 working days		
	5. Assess effectiveness of Contractor's	possible remedial measure	4. Discuss with ET, IEC and Contractor on	of notification		

EVENT	ACTION				
EVENT	ET	IEC	ER	Contractor	
	remedial actions and keep EPD and ER &	4. Advise the ER & ET on the effectiveness	proposed remedial actions	3. Implement the agreed proposals	
	IEC informed of the results	of the proposed remedial measures	5. Ensure remedial actions properly	4. Amend proposal if appropriate	
		5. Supervise the implementation of the	implemented		
		remedial measures			
2. Exceedance for two or	1. Identify source	1. Checking monitoring data submitted by	1. Confirm receipt of notification of failure	1. Take immediate action to avoid	
more consecutive samples	2. Inform ER, IEC, Contractor and EPD	ET	in writing	further exceedance	
	the cause & actions taken for the	2. Discuss amongst ER, ET and Contractor	2. Notify Contractor	2. Submit proposals for remedial	
	exceedances	on possible remedial measures	3. Carry out analysis of Contractor's	actions to IEC, ER within 3 working	
	3. Repeat measurement to confirm findings	3. Review Contractor's remedial measures	working procedures to determine possible	days of notification	
	4. Increase monitoring frequency to daily	whenever necessary to ensure their	mitigation to be implemented	3. Implement the agreed proposals	
	5. Investigate the causes of exceedance	effectiveness and advise the ER	4. Discuss amongst ET, IEC and the	4. Resubmit proposals if problem	
	6. Carry out analysis of contractor's	accordingly	Contractor on proposed remedial actions	still not under control	
	working procedures to determine possible	4. Supervise the implementation of the	5. In consultation with IEC, agree with the	5. Stop the relevant portion of works	
	mitigation to be implemented.	remedial measures	contractor remedial measures to be	as determined by the ER until the	
	7. Arrange meeting with EPD, IEC and ER		implemented	exceedance is abated	
	to discuss the remedial actions to be taken		6. Ensure remedial measure are properly		
	8. Assess effectiveness of Contractor's		implemented		
	remedial actions and keep EPD and ER &		7. If exceedance continues, consider what		
	IEC informed of the results		portion of the work is responsible and		
	9. If exceedance stops, cease additional		instruct the Contractor to stop that portion		
	monitoring		of work until the exceedance is abated		

Event/Action Plan for Construction Noise

Exceedance	ACTION				
Exceedance	ET	.IEC	ER	Contractor	
Action Level	1. Discuss with the IEC and ER and seek to	1. Review the analyzed results submitted	1. Confirm receipt of notification of	1. Submit proposals for remedial	
	identify potential noise source	by the ET	complaint and notify Contractor	actions to ER within three working	
			immediately	days of notification	
	2. Undertake noise measurement to	2. Review the proposed remedial measures	2. Check monitoring data trends and	2. Amend proposals if required by	
	confirm the validity of complaint	by the Contractor and advise the ER & ET	Contractor's working methods	the Engineer	
		accordingly			
	3. Inform ER&IEC in writing	3. Supervise the implementation of	3. Remind the Contractor of his contractual	3. Implement the remedial actions	
	Discuss remedial actions required with	remedial measures	obligations and discuss with ET, IEC and	immediately upon instruction	
	ER&IEC if an exceedance is recorded		Contractor on proposed remedial actions		
	4. Increase monitoring frequency to		4. Assess the efficacy of remedial actions	4. Liaise with the ER to optimize the	
	demonstrate efficacy of remedial measures		and keep the Contractor informed	effectiveness of the agreed	
				mitigation	
	5. If exceedance continues, meet with		5. Inform complainant of actions taken	5. Amend proposal if appropriate	
	ER&IEC to review implementation of				
	appropriate mitigation measures.				
	6. If exceedance stops, cease additional				
	monitoring				

Exceedance		ACTIO	N	
Exceedance	ET	IEC	ER	Contractor
Limit Level	1. Repeat measurement to confirm findings	1. Check monitoring data submitted by ET	1. Confirm receipt of notification of	1. Take immediate action to avoid
			exceedance and notify Contractor	further exceedance
	2. Investigate the cause of the exceedance	2. Review Contractor's remedial actions to	2. Check monitoring data trends and	2. Submit proposals for remedial
	and identify the main source(s) of impact	assure their effectiveness and advise the	Contractor's working methods	actions to ER immediately not more
		ER &ET accordingly		than 3 working days of notification
	3. Inform ER&IEC and EPD in writing	3. Supervise the implementation of the	3. Discuss with ET, IEC and Contractor on	3. Amend proposals if required by
		remedial measures	proposed remedial actions to be	the ER
			implemented	
	4. Discuss remedial actions required with		4. Assess the efficacy of remedial actions	4. Implement remedial actions
	ER&IEC		and keep the Contractor informed	immediately upon instruction
	5. Increase monitoring frequency to		5. If exceedance continuous, consider what	5. Liaise with the ER to optimize the
	demonstrate efficacy of remedial measures		portion of the work is responsible and	effectiveness of the agreed
			instruct the Contractor to stop that portion	mitigation
			of work until the exceedance is aborted	
	6. Assess efficacy of remedial actions and			6. Resubmit proposals if problem
	keep ER & IEC informed of the results			still not under control
	7. If exceedance continues, meet with			7. Stop the relevant portion of works
	ER&IEC to identify appropriate mitigation			as determined by the ER until the
	measures			exceedance is aborted
	8. If exceedance stops, cease additional			
	monitoring			

APPENDIX K ENVIRONMENTAL MITIGATION IMPLEMENTATION SCHEDULE (EMIS)

Appendix K - Summary of Environmental Mitigation Implementation Schedule

Types of Impacts	Mitigation Measures	Status
Construction Dust	 Any stockpile of dusty materials or stockpile of dusty material should be covered entirely by impervious sheeting or sprayed with water so as to maintain the entire surface wet. A stockpile of dusty materials should not extend beyond the pedestrian barriers, fencing or traffic cones. Vehicle washing facilities should be provided at every exit point. The area where vehicle washing takes place and the section of the road between the washing facilities and the exit point should be paved with concrete, bituminous materials or hardcores. Where a site boundary adjoins a road, street, service lane or other area accessible to the public, hoarding of not less than 2.4m high from ground level should be provided along the entire length of that portion of the site boundary except for a site entrance or exit. Every main haul road should be sprayed with water or a dust suppression chemical so as to maintain the entire road surface wet. The portion of any road leading only to a construction site that is within 30m of a discernible or designated vehicle entrance or exit should be kept clear of dusty materials. Any stockpile of dusty materials should be either covered entirely be impervious sheeting, placed in an area sheltered on the top and the 3 sides or sprayed with water or a dust suppression chemical immediately prior to any loading, unloading or transfer operation so as to maintain the dusty materials wet. All dusty materials should be washed to remove any dusty materials from its body and wheels immediately before leaving a construction site. The working area of any excavation should be sprayed with water or a dust suppression chemical immediately before, during and immediately after the operation so as to maintain the entire surface wet. 	^ ^ ^
Construction Noise Water Quality	 Only well-maintained plant should be operated on –site and plant should be serviced regularly during the construction works. Machines and plant that may be in intermittent use should be shut down between work periods or should be throttled down to a minimum. Plant know to emit noise strongly in one direction, should where possible, be orientated to direct noise away from the NSRS. Mobile plant should be sited as far away from NSRs as possible. Material stockpiles and other structures should be effectively utilised, where practicable, to screen noise from on-site construction activities. Use quite plant and Working Method Reduce the number of plant operating in critical areas close NSRs. Construct temporary and movable noise barriers Construction Runoff and Drainage	^ ^ ^

Types of Impacts	Mitigation Measures	Status
	 Use of sediment traps and the adequate maintenance of drainage systems to prevent flooding and overflow. Boundaries of critical areas of earthworks should be marked and surrounded by dykes or embankments for flood protection. Temporary ditches should be provided to facilities runoff discharge into the appropriate watercourses, via a silt retention pond. Permanent drainage channels should incorporate sediment basins or traps and baffles to enhance deposition rates. 	^
	• All temporary and permanent drainage pipes and culverts provided to facilitate runoff discharge should be adequately designed for the controlled release of storm flows. All sediment traps should be regularly cleaned and maintained. The temporarily diverted drainage should be reinstated to its original condition when the construction works has finished or the temporary diversion is no longer required	۸
	• Sand silt in the wash water from the wheel washing facilities, which ensure no earth, mud and debris is deposited on roads, should be settled out the removed before discharging into storm drains. A section of the road between the wheel washing bay and the public road should be paved with backfill to prevent wash water or other site runoff form entering public road drains.	^
	• Oil interceptors should be provided in the drainage system and regularly emptied to prevent the release of oils and grease into the storm water drainage system after accidental spillage. The interceptor should have a bypass to prevent flushing during periods of heavy rain.	N/A
	 Catchpits and perimeter channels shall be constructed in advance of site formation works and earthworks. 	٨
	• Silt removal facilities, channels and manholes shall be suitably maintained with the deposited silt and grit being removed at least once a week, and at the onset of and after each rainstorm to ensure that these facilities are functioning properly at all times.	^
	• Earthworks final surfaces shall be well compacted and the subsequent permanent work or surface protection shall be carried out immediately after the final surfaces are formed to prevent erosion caused by rainstorms. Appropriate intercepting channels shall be provided along the site boundary or at the locations agreed with the ET Leader. Rainwater pumped out from trenches or foundation excavations shall be discharged into silt removal facilities before discharge into storm drains.	^
	• All generators, fuel and oil storage shall be within bunded areas. Drainage from the areas shall be connected to storm drains via a petrol interceptor.	^
	Tunnelling Work	ı
	• Temporary open storage of excavated materials should be covered with tarpaulin or similar fabric during rainstorms. Any washout of construction or excavated materials form the drill and blast tunnelling work should be diverted to the drainage system via appropriate sediment traps.	N/A
	 Ground water pumped out of tunnels should be discharged into the drainage channels which incorporated sediment traps to enhance deposition rates and to remove silt. 	N/A
	 Spend grouts used in diaphragm wall construction should be collected in a separate slurry collection system, reconditioned and reused wherever practicable. The disposal of used grouting materials will only be permitted if it is treated to the TM standards before discharge to the storm drains or disposal to landfill. 	N/A
	General Construction Activities	

Types of Impacts	Mitigation Measures	Status
	Debris and rubbish on site should be collected, handled and disposed of properly to avoid entering the water column and cause water quality impacts.	^
	• All fuel tanks and storage areas will be provided with locks and be located on sealed areas (within bunds of a capacity equal to 110% of the storage capacity of the largest tank or 20% by volume of the fuel stored in that areas, whichever in the greatest).	۸
	Sewage Effluent	
	• Construction work force sewage discharges form fixed toilet facilities on-site should be connected to the nearby existing trunk sewer wherever feasible. However, for areas where existing trunk sewer is not available, it is recommended that appropriate and adequate on site portable chemical toilets should be provided by a licensed contractor who will be responsible for appropriate disposal and maintenance of these facilities.	^
	• It is considered that sewage discharges could also be treated by on-site septic tanks and soakaway. Minimum clearance away form streams and catchments and other requirements for the proposed septic tank and soakaway should be referred to EPD's Practice Note for Professional Persons, Drainage Plans.	N/A
Waste	General	
	 Training and instruction shall be given at a site to construction staff to increase awareness and draw attention to waste management issues and the need to minimise waste generation. The training requirement shall be included in the site waste management plan. 	^
	Storage, Collection and Transportation of Waste	l
	Wastes shall be handled and stored in a manner to ensure that they are held securely without loss or leakage.	٨
	• Authorised or licensed waste hauliers shall be used and they shall only collect wastes prescribed by their permits.	^
	Waste shall be removed on a daily basis.	^
	Waste storage area shall be maintained and cleaned on a daily basis.	^
	 Windblown litter and dust during transportation shall be minimised by either covering trucks or transporting wastes in enclosed containers. 	^
	Obtain necessary waste disposal permits from the appropriate authorities if they are required.	^
	 Wastes shall be disposed of at licensed waste disposal facilities. 	^
	• Develop procedure such as ticketing system to facilitate tracking of loads, particularly for chemical waste, and to ensure that illegal disposal of wastes does not occur.	^
	 Maintain records of the quantities of wastes generated, recycled and disposed. 	٨
	Surplus Excavated Materials	
	• Due to the high risk of loose material being washed into the existing nullah, stockpile materials should be properly compacted and covered from water erosion and located at least 10m away from the nullah wall.	۸
	Construction and Demolition (C&D) Waste	
	 Careful design, planning and good site management shall be adopted to minimise over-ordering and generation of waste materials such as concrete grouts. 	^

Types of Impacts	Mitigation Measures	Status
	 The handling and disposal of bentonite slurries shall be undertaken in accordance with Practice Note for Professional Persons – Construction Site Drainage (ProPECC PN 1/94) on construction site drainage. 	N/A
	• Construction and demolition (C&D) material shall be segregated to inert and non-inert parts. The inert portion shall re-used at areas of reclamation or land formation, or to public filling area shall such allocation is deemed necessary. The non-inert portion shall be disposed of to landfill.	۸
	Chemical Waste	
	 Chemical waste that is produce during construction shall be handled in accordance with the Cod of Practice on the Packaging, Handling and Storage of Chemical Wastes. 	^
	 Containers used for the storage of chemical wastes should: a. Be suitable for the substance they are holding, resistant to corrosion, maintained in a good condition, and securely closed; b. Have a capacity of less than 450 litres unless the specifications have been approved by the EPD; c. Display a label in English and Chinese in accordance with instructions prescribed in Schedule 2 of the Chemical Waste Regulations. 	۸
	 The storage area for chemical wastes should: a. Be clearly labelled and used solely for the storage of chemical waste; b. Be enclosed on at least 3 sides; c. Have an impermeable floor and bunding of capacity to accommodate 110% of the volume of the largest container or 20% by volume of the chemical waste stored in the area, whichever is largest; d. Have adequate ventilation; e. Be covered to prevent rainfall entering (water collected within the bund must be tested and disposed as chemical waste if necessary); f. Be arranged so that incompatible materials are adequately separated. Disposal of chemical waste shall be via a licensed waste collector; and to a facility licensed to receive chemical waste; or a 	۸
	reuser of the waste (under approval from EPD).	^
	General Refuse	
	• General refuse generated on-site shall be stored in enclosed bins or compaction unit separate from C&D and chemical wastes. A reputable waste collector shall be employed by the contractor to remove general refuse from the site, separately from C&D and chemical wastes, on a daily for every second day basis to minimise odour, pest and litter impacts. The burning of refuse on construction sites is prohibited by law.	۸
	Reusable rather than disposable dishware shall be used if feasible.	۸
Ecology	 A sediment barrier shall be erected to minimize stream sedimentation at downstream of the project boundary of the Toll Plaza. Conduct a tree survey before commencement of the construction work. 	N/A

Types of Impacts	Mitigation Measures	Status
	• All measures recommended in the approved landscape proposals under Condition 2.4 in EP above shall be fully implemented in accordance with the details and time schedule set out in the submission.	^
	• Loss of the adjacent woodland due to temporary land take shall be returned to the original status immediately.	N/A
	 Wild and uncontrolled fire shall be strictly prohibited Fences shall be erected along the boundary of the construction sites at the Toll Plaza before commencement of works, to prevent tipping, vehicle movements, and encroachment of personnel onto adjacent wooded areas. 	N/A
	• Landscape mitigation measure 1 (LMM1) – Construction programming and management. The periphery of the works areas at street level shall be managed so that they do not appear cluttered, untidy and unattractive and inconvenient to pedestrians. For example, all hoarding shall be colorfully designed with interesting motifs demonstrating the work of Highways Department. Hoardings with bland colours shall be avoided.	۸
Landscape and Visual Impact	• Landscape mitigation measure 2 (LMM2) – Advanced planting and erosion control works. Where possible, the transplantation of existing valuable trees, the stockpiling of topsoil, new planting and erosion control works shall be carried out as early as possible in the construction period instead of at the end. This will assist in maximizing the time for carrying out transplantation and new planting, resulting in a higher success rate for the survival of transplantation and new planting, resulting in a higher success rate for the survival of transplanted trees and the establishment of new screen trees. The stockpiling of topsoil will provide an abundant use of on-site material for growing media. During detailed design, the issue of stockpiling of topsoil in a manner that would avoid washing into the drainage scheme should be examined comprehensively.	۸
	Measurement of vibration would also be carried out on a need basis during the piling work	٨


Remarks:


Compliance of mitigation measure; Not Applicable; ٨


Non-compliance of mitigation measure; Non-compliance but rectified by the contractor X


N/A


APPENDIX L CONSTRUCTION PROGRAMME


























Site Commissioning Tests (SCT)	20 20-24 20-34	31		09 2 J A S O N D J F M
March 1979	19 19 19 19 19 19 19 19	Section 1.5		
March Marc	March Marc	Express 10		
Electric content Proceedings Process P	March 1972 1972 1974 1974 1975	Section Sect		
Section Sect	Section Sect	10 1,46 1,	Install Operation Facilties @Portion D	Kiosk F)
1	15 28 26 27 28 28 28 28 28 28 28	Section Sect	■Install SDH Node 4,5,6 & COMMUNICATIO	N SYSTEM @D
20	30 20,727 75,877 75,878 75 10,100 75 11,10	20 20-707 7-9-707 1-9-707		D
3 St. 12 St. 13 Ct. St. 14 Ct. 15	Big 197 191 197 191 197 191 197	## 11 107 15 11 107 15 11 107 15 11 107 12 11 107 12 127 15 ## 12 11 107 15 11 107 12 11 107 12 11 107 12 12 ## 12 11 107 15		
\$ 0.14-02 0.14	\$ 0.14-02 0.14	S		(Kingle E)
3 20 10 7 10 10 7 10 10 10	Second Second Content	S		
Parent Line Parent Par	Control Cont	Section Company Comp		
India	Include Color Color Color Color			
20	20	25 70.00 26 Col. C		
22 17 18 20 20 30 C 61 20 30 10 10 10 10 10 10 1	23 27 22 8 20 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	20	□Install Cable Containment @P	rtion F
25	23 174 24 24 24 24 24 24 24	22 27 02 28 22 30 68 1	■Electrical Installation @Portion	ı E
44 70 0.06 1 6.0 6.0 1	44 77 27 0.0	44 270-2011 164-09 0 0.05-000 0.		
17 776 CR	17 270.04 1.430.68 C 0.40.40 1.40.40 54.40 1.40.40	17. 27.02.39 14.02.30 0. 0.00-048 3.9 1.00-048 3.9 1.00-048 2.00-04		
14 17 0 20 at 11 20 ft at 12 20 ft a	14 27 0 0 0	14		
22 27-239 28-239 0 13-249 15-249 44	20 27-2-29 25-2-29 0 19-9-100 19-9-100 44	29 27 29 29 20 20 3 3 114 40 20 20 40 20 20 20 2		
Value Valu	Table Tabl	Instant Provided Professor		
7 7 2-73-06	7 27 CO-30 27-30	7 27-53-98 127-328 0 120-100 12		
11	19	15 10 10 10 10 10 10 10	Electrical Installation @Porti	n E
Total Control 4 15 15 15 15 15 15 15	10	19 0.03 cold 14.03 cold 0. 25.05 cold 25.04 cold 25.05 c		
4	4	4 \$ 50.00 1 \$19.30 0 \$0.00 0.00 0.00 0.00 0.00 0.00 0.0	■Install Traffic Control Field D	vices @Portion E
A 15 0 Or 16 0 Or	A 15 0 Or 16 0 Or	4 15-3-3-68 18-3-9-8 0 9-3-9-8 0 9-3-9-8 0 9-3-9-8 0 9-3-9-8 0 9-3-9-8 18-9-9-8 18-9-9-9-8 18-9-9-9-8 18-9-9-9-8 18-9-9-9-8 18-9-9-9-8 18-9-9-9-8 18-9-9-9-8 18-9-9-9-8 18-9-9-9-8 18-9-9-9-8 18-9-9-9-8 18-9-9-9-8 18-9-9-9-8 18-9-9-9-8 18-9-9-9-9-9-9-9-9-9-9-9-9-9-9-9-9-9-9-9		
Section Commissional Republic Section 1	Section Commissional Republic Section 1	Second Commission Commis		
Installation Strategy Stra	Installation Strategy Stra	Install Cable Containment (@Portion File Containment	Install Vehicle Detector Syste	n @Portion E
13 1 11 12 02 0 20 20 0 0 25 02 0 0 0 0 0 0 0 0 14 1 1 1 1 1 1 1 1 1 1	13 1 11 12 02 0 20 20 0 0 25 02 0 0 0 0 0 0 0 0 14 1 1 1 1 1 1 1 1 1 1	11 11 12 08 29 20 8 10 55 20 8 68 30 14		
11 11 12 20 20 20 20 20	19 10 10 10 10 10 10 10	15 11-12-26 28-12-28 28 29 28 20 28 29 30 1 29 30 30		tion F
Column C	6 01 63 68 68 68 68 70 70 70 69 10 64 70 30 80 80 10 10 64 70 30 80 80 10 10 64 70 70 70 70 70 70 70 7	Section Commission 19.03 8 0.05 9 0.07 0.08 10.14 10.14 10.00 10		
10 101-203 100-203 100-203 10 20-203 10-20-203 10	10 101-203 100-203 100-203 10 20-203 10-20-203 10	10 0 10-03-08 10-03-08 0 0 07-04-08 15-04-08 36 19 1 11-02-08 0 02-02-08 0 02-02-08 0 10-03-08 14 19 1 11-02-08 19-03-08 0 02-02-08 0 02-02-08 0 10-03-08 17-04-08 37 19 1 11-02-08 19-03-08 19-03-08 0 10-03-08 0 07-04-08 14 19 1 11-02-08 19-03-08 19-03-08 0 10-03-08 0 07-04-08 14 19 1 11-02-08 19-03-08 19-03-08 0 02-03-08 0 10-03-08 0 07-04-08 14 19 1 11-02-08 19-03-08 0 10-03-08 0 07-04-08 14 19 1 11-02-08 20-02-09 0 10-03-08 0 07-04-08 14 19 1 11-02-08 20-02-09 0 10-03-08 0 07-04-08 37 19 1 11-02-08 20-02-09 0 10-03-08 0 07-04-08 37 19 1 11-02-08 19-03-08 0 02-04-08 19-04-08 22 19 1 11-02-08 19-03-08 0 02-04-08 19-04-08 22 19 1 11-02-08 19-03-08 0 02-04-08 19-04-08 23 19 1 11-02-08 19-03-08 0 02-04-08 19-04-08 23 19 1 11-02-08 19-03-08 0 02-04-08 19-04-08 23 19 1 11-02-08 19-03-08 0 02-04-08 19-04-08 23 19 1 11-02-08 19-03-08 0 02-04-08 19-04-08 23 10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	<u> </u>	
10 10 10 10 10 10 10 10	19 10 10 10 10 10 10 10	10 1.03-28 19-39-8 0 31-99-8 0 31-99-96 30 1-99-96 30 1-99-96	□Install O&M Radio System @P	rtion F (Kiosk Z)
B 01-03-08 03-05-08 0 07-04-08 14 14 14 14 14 14 14 1	B 01-02-08 03-02-08 0 07-04-08 1-04-08 07-04-08 1-04-08 07-04-08 1-04-08 07-04-08 1-04-08 07-04-08 1-04-08	A 10 10 10 10 10 10 10		
19 01-02-08 19-02-08 0 01-02-08 0 0 02-09 0 03-09 07-04-08 14	19 10-10-2-08 19-0-2-08 0 0 19-0-2-08 0 0 19-0-2-08 18	19 0.00 08 19 0.00 08 0.9 19 0.00 08 0.70 0.00 070 0.00 070 0.00 070 0.00 070 07		
14 12 20 15 20 16 20 16 20 20 20 20 20 20 20 2	3-4 1-0-2-08 1-0-2-08 1-0-2-08 0 0 0 0 0 0 0 0 0	34 11 02 08 15 00 08 0 26 00 08 0 26 00 08 20 00 08 14	_ 	
1 1 1 19 2 0	1 1 1 2 0 8 20 0 0 0	19 11 02 08 29 29 20 8 0 10 20 20 10 40 8 31	- 	
18 01-03-08 18-03-08 02-03-08 02-04-08 19-04-08 32 19-04-08 36 19-04-08 36 19-04-08 36 19-04-08 36 19-04-08 36 19-04-08 36 19-04-08 36 19-04-08 36 19-04-08 36 19-04-08 36 19-04-08 36 19-04-08 37 19-04-08 37 19-04-08 37 19-04-08 38 19-04-08 38 19-04-08 38 19-04-08 38 19-04-08 38 19-04-08 19-	10 10 30 18 30 38 0 20 40 88 19 40 40 36 10 40 40 36 10 40 40 36 10 40 40 36 10 40 40 36 10 40 40 36 10 40 40 36 10 40 40 36 10 40 40 36 10 40 40 40 40 40 40 40	18 01-30-56 16-30-38 0 0 20-40-38 19-40-8 32 0 19-40-8 32 0 19-40-8 32 0 19-40-8 18-30-8 16-30-38 0 19-40-9 19-40-8 38 19-40-38 18-30-38 0 03-40-8 11-40-8 33 19-40-40 18-30-38 19-40-		
9 07/03-08 15-03-08 0 1 12-04-08 1 10-04-08 38	9 07-03-08 1-03-03-08 0 0 12-04-08 2 1-04-08 3 5 8 10-03-08 0 03-04-08 1 10-04-08 3 3	9 0/43-06 1653-38 0 1 204-08 214048 35 214048 35 2 104048 35 2 104048 35 2 104048 35 2 104048 35 2 104048 35 2 104048 35 2 104048 35 3 2 1040497A 25-0607 7 1 00407A 12.06.07 228 3 1040497A 25-0607 7 1 00407A 12.06.07 228 3 1040497A 25-0607 7 1 00407A 12.06.07 228 3 1040497A 25-0607 7 1 00407A 12.06.07 120 10407A 12.06.07 120		
Sisting and Commissioning Sisting Conting Fixed SCD GROK	Sting and Commissioning Sting Commissioning Tests (CCT) GRRK Still Commissioning Tests (CCT) GRRK Sting Commissioning Tests (CCT) GRRK Still CCT Tests Still C	Sitis Commissioning Tests (SCT) @RBX 139 10 0 407A 26 08 07 7 10 04 07A 12 08 07 228 **SET of SEC system @RBX & Portion B 12 08 08 07 7 10 04 07A 12 08 07 228 **SET of SEC system @RBX & Portion B 12 08 08 07 20 08 08 20 07 20 08 07 20 08 07 20 08 08 20 07 20 08 08 20 07 20 08 08 20 07 20 08 08 20 07 20 08 08 20 07 20 08 08 20 07 20 08 08 20 07 20 08 08 20 07 20 08 08 20 07 20 08 08 20		
Site Commissioning Tests (SCF) @RSK 10 10 10 10 10 10 10 1	Size Commissioning Tests (SCT) @RBK 1900-007	Site Commissioning Tests (SCT) @18K Scholar B 12 0 0 4 0 7 \ 20 0 0 4 0 7 \ 20 0 0 1 20 0 0 7 \ 20 0 0 4 0 7 \ 20 0 0 1 20 0 0 7 \ 20 0 0 4 0 7 \ 20 0 1 20 0 0 7 \ 20 0 1 20 0 0 7 \ 20 0 0 1 20 0 0 7 \ 20 0 0 1 20 0 0 7 \ 20 0 1 20 0 0 7 \ 20 0 1 20 0 0 7 \ 20 0 1 20 0 0 7 \ 20 0 1 20 0 0 7 \ 20 0 1 20 0 0 7 \ 20 0 1 20 0 0 7 \ 20 0 1 20 0 0 7 \ 20 0 1 20 0 0 7 \ 20 0 1 20 0 0 7 \ 20 0 0 0 0 7 \ 20 0 0 0 0 7 \ 20 0 0 0 0 7 \ 20 0 0 0 0 7 \ 20 0 0 0 0 7 \ 20 0 0 0 0 7 \ 20 0 0 0 0 7 \ 20 0 0 0 0 7 \ 20 0 0 0 0 0 7 \ 20 0 0 0 0 0 7 \ 20 0 0 0 0 0 7 \ 20 0 0 0 0 0 0 0 7 \ 20 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Install SEC System (Stage 1 &	2) @Portion F
139 10-04-O7A 20-08-07 7 10-04-07A 12-08-07 228	100-4-07A 26-06-07 7 10-4-07A 12-06-08 -228	139 10-04-07A 25-08-07 7 10-04-07A 12-08-07 -228		
Sect of SEC system @RBK & Portion B 12 09-08-07 0.1 3-05-07 10-05-08 9.0	SCT of SEC system @R8K & Portion B 12	SCT of SEC system		
12 09-08-07 20-08-07 0 13-05-07 10-08-08 -90	12 09-08-17 20-08-07 01-08-08 -10 -1	12		
Site Commissioning Tests @RBT 220 07 0 0 0 5 0 8	Size Commissioning Tests @RBT	Site Commissioning Tests @RBT		
298 20-07-07 20-07-08 0 23-11-07 12-08-08 4-3	200 200 70 70 200 200 201 107 201 200 201 200 201 200 201 200 201 200 201 200 201 201 200 201	295 20-07-07 20-05-08 0 23-1-07 12-06-08 -43 System Acceptance Tests (SAT) @R8K 89 27-07-07 23-10-07 0 23-02-07 29-05-07 -161 System Acceptance Tests (GR8 (with EOT) 168 19-01-08 04-07-08 0 07-12-07 07-08-08 -43 Operability Test (OFT) @R8K 39 22-10-07 20-11-07 0 14-05-07 26-06-07 -161 SAT & OPT for SEC system @R8K 58 21-08-07 17-10-07 0 24-05-07 26-06-07 -161 SAT & OPT for SEC system @R8K 58 21-08-07 17-10-07 0 24-05-07 26-09-08 -89 Operability Test (GR8 (with EOT) 44 88-06-08 21-07-08 0 09-06-08 20-09-08 0 Portation and Maintenance Documents & Training Documentation for R8K Opening 893 18-05-06A 28-10-08 21 18-05-06A 22-02-10 -218 Documentation for 18K Opening 252 25-07-07 01-04-08 9 30-09-07 23-06-08 80 Training for R8K **Training for R8K **Trainin		
System Acceptance Tests (SAT) @RBK 89 27-07-70 221-070 0 23-02-07 29-05-07 -161 System Acceptance Tests (SAT) @RBK EOT) 188 19-01-09 0 047-08 0 07-12-07 07-08-08 4-43 Operability Test (OPT) @RBK	System Acceptance Tests (SAT) @RBK 89 27-07-07 23-10-07 03-10-07 0 0 23-02-07 29-05-07 -161 System Acceptance Tests (SRR) with EOT 168 19-01-08 0-07-08 0 0 07-12-07 07-08-08 43 Operability Test (OPD) @RBK 58 21-08-07 17-10-07 0 24-05-07 20-08-08 -89 Operability Test (OPD) @RBK 58 21-08-07 17-10-07 0 24-05-07 20-09-08 -89 Operability Test (OPD) @RBK 58 21-08-07 17-10-07 0 24-05-07 20-09-08 -89 Operability Test (OPD) @RBK 58 21-08-07 17-10-07 0 24-05-07 20-09-08 -89 Operability Test (OPD) @RBK 58 21-08-07 17-10-07 0 24-05-07 20-09-08 -89 Operability Test (OPD) @RBK 58 21-08-07 17-10-07 0 24-05-07 20-09-08 -89 Operability Test (OPD) @RBK 58 21-08-07 17-10-07 0 24-05-07 20-09-08 -89 Operability Test (OPD) @RBK 59 21-09-08 21 18-05-06A 20-09-08 0 Operability Test (OPD) @RBK 14 29-10-07 15-11-07 0 0 04-03-11 23-03-11 846 Training tor RBK 14 26-03-08 15-04-08 0 0 22-07-08 08-08-08 80 Training tor RBK 20 09-08-08 0 01-05-06 12-06-07 -414 Section Completion of RBK 20 05-04-07 20-08-07 0 0 01-06-06 12-06-07 -414 Section Completion of RBK 51 12-03-07 20-08-08 0 12-03-07 0 0 01-06-06 12-06-07 -414 Section Completion of RBK 20 05-04-07 20-08-07 0 0 0 05-04-07 -414 Section Completion of RBK 21 11-107 20 0 0 0 0 0 0 0 0	System Acceptance Tests (SAT) @R8K 89 27-07.07 23-10.07 0 23-02.07 29-05-07 -161		
88	88	88 \$7-07-07 \$2-10-07 0 \$2-00-07 2-00-07 1-61 System Acceptance Tests @R8 (with EOT) 168 19-01-08 04-07-08 0 07-12-07 07-08-08 -43 Operability Test (OPT) @R8K 50 \$2-10-07 \$2-11-07 0 14-05-07 26-06-07 -161 SAT & OPT for SEC system @R8K 59 \$2-10-08 0 0 0 0 0 0 0 0 0		
168	168 19-01-08 04-07-08 0 07-12-07 07-08-08 4-43 Operability Test (OPT) @R8K	168 19-01-08 04-07-08 0 07-12-07 07-08-08 -43 **Operability Test (OPT) @R8K 30 22-10-07 20-11-07 0 14-05-07 26-06-07 -161 **SAT & OPT for SEC system @R8K 58 21-09-07 17-10-07 0 24-05-07 20-09-08 -89 **Operability Test @R8 (with EOT) 44 08-09-08 21-07-08 0 08-06-08 20-09-08 0 **Operability Test @R8 (with EOT) 44 08-09-08 21-07-08 21-07-08 0 08-06-08 20-09-08 0 **Procumentation for R8 C Opening 893 18-05-06A 26-10-08 21 19-05-06A 22-02-10 -218 **Procumentation for R8 Opening 252 25-07-07 01-04-08 9 30-09-07 23-06-08 67 **Training for R8K** 14 26-03-08 15-04-08 0 22-07-08 08-08-08 80 **Promise for R8 Opening Areas (to be advised) 42 20-07-07 30-08-07 0 01-08-06 12-06-07 -414 **Section Completion of R8K** 42 20-07-07 30-08-07 0 05-04-07A 12-06-07 -414 **Section Completion of R8RB** **Sect		
Operability Test (OPT) ©RBK 30	Operability Test (OPT) @RBK 30 22-10-07 20-11-07 0	Operability Test (OPT) @B8K 30 22-10-07 20-11-07 0 14-05-07 26-06-07 -161 SAT & OPT for SEC system @R8K 58 21-08-07 17-10-07 0 24-05-07 20-09-08 -89 Operability Test @R8 (with EOT) 44 08-06-08 21-07-08 0 08-06-08 20-09-08 0 Peration and Maintenance Documents & Training Documentation for R8K Opening 893 18-05-06A 26-10-08 21 18-05-06A 22-02-10 -218 Documentation for R8K Opening 1-22 25-07-07 01-04-08 9 30-09-07 32-06-08 80 Training for R8K 14 28-10-07 15-11-07 0 04-03-11 23-03-11 846 Training for R8 14 28-00-08 15-04-08 0 22-07-08 08-08-08 80 Ompletion Dates 0 20-11-07 0 30-09-07 -51 0 0 90-30-08 0 01-07-09 326 1-2-10-10-10-10-10-10-10-10-10-10-10-10-10-		
33 22-10-07 20-11-07 0 14-05-07 26-06-07 -161 SAT & OPT for SEC system @RIX 58 21-08-07 17-10-07 0 24-05-07 20-09-08 -59 Operability Test @RIX (with EOT) 44 88-06-08 21-07-08 0 08-06-08 20-09-08 0 Peration and Maintenance Documents & Training	33	30 22-10-07 20-11-07 0 14-05-07 26-06-07 1-61 SAT & OPT for SEC system @RK 58 21-08-07 17-10-07 0 24-05-07 20-09-08 8-9 Operability Test @R8 (with EOT) 44 08-08-08 21-07-08 0 08-06-08 20-09-08 0 Peration and Maintenance Documents ** Training Documentation for R8K Opening 993 18-05-06 28-10-09 21 18-05-06 22-02-10 -218 Documentation for R8K Opening 252 25-07-07 01-04-08 9 90-09-07 23-06-08 67 Training for R8K 14 29-10-07 15-11-07 0 04-03-11 23-03-11 846 1		
SR 21-0.9 OP 107 SEC system @R8K 58 21-0.9 O7 17-10-07 0 0 24-0.5 O7 20-0.9 O8 -89 Operatifier Set @R8 (with EOT) 44 08-06-08 21-07-08 0 0 0.8 06-08 20-09-08 0 Documentation for R8K Opening 883 18-05-06A 26-10-08 21 18-05-06A 22-02-10 218 Documentation for R8K Opening 14 29-10-07 15-11-07 0 0.4-0.3 11 23-03-11 846 Training for R8K 14 29-10-07 15-11-07 0 0.4-0.3 11 23-03-11 846 Training for R8 14 29-00-08 15-04-08 0 0 22-07-08 06-08-08 80 O 9-08-08 0 0 0.0 10-07-09* 326 Early Road Opening Areas (be advised) 42 20-07-07 30-08-07 0 01-06-06 12-06-07 414 Section Completion of R8K Section Completion of R8K Section Completion of R8K Section Completion of R8K 15 12-03-07 0 0 05-04-07A 12-06-07 161 Section Completion of R8K 15 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 Section Completion of R8K 16 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 Section Completion of R8K Training for R8K 17 10 10 10 10 10 10 10 10 10 10 10 10 10	SAT & OPT for SEC system @R8K 58	SAT & OPT for SEC system @R8K 58		
58 21-08-07 17-10-07 0 24-05-07 20-09-08 -89 Operability Test @R8 (with EOT)	58 21-08-07 17-10-07 0 24-05-07 20-09-08 -89	58 21-08-07 17-10-07 0 24-05-07 20-09-08 -89 Operability Test @R8 (with EOT)		
Operability Test @R8 (with EOT) 44 08-06-08 21-07-08 0 08-06-08 20-09-08 0 peration and Maintenance Documents & Training Documentation for R8K Opening 893 18-05-06A 26-10-08 21 18-05-06A 22-02-10 -218 Documentation for R8 Opening 252 25-07-07 01-04-08 9 30-09-07 23-06-08 67 Training for R8K 14 29-10-07 15-11-07 0 04-03-11 23-03-11 846 Training for R8 14 26-03-08 15-04-08 0 22-07-08 08-08-08 80 Dompletion Dates 0 20-11-07 0 30-09-07 -51 0 09-07-09 326 Early Road Opening Areas (to be advised) 42 20-07-07 30-08-07 0 01-06-06 12-06-07 -161 -161 Section Completion of R8K 230 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 -161 Section Completion of R8K 250 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 -161 Section Completion of R8K 250 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 -161 Section Completion of R8K 250 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 -161 Section Completion of R8K 250 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 -161 Section Completion of R8K 260 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 -161 Section Completion of R8K 260 05-04-07A 20-11-07 20-12-09 -163 DLP for R8K Work	Operability Test @R8 (with EOT) 44 08-06-08 21-07-08 0 08-06-08 20-09-08 0 Decention and Maintenance Documents & Training Documentation for R8K Opening 893 18-05-06A 26-10-08 21 18-05-06A 22-02-10 -218 Documentation for R8 Opening 252 25-07-07 01-04-08 9 30-09-07 23-06-08 67 Training for R8K 14 28-10-07 15-11-07 0 04-03-11 23-03-11 846 Training for B 14 26-03-08 15-04-08 0 22-07-08 08-08-08 80 Description Dates 0 20-11-07 0 30-09-07 -51 0 90-08 0 01-07-09 326 Early Road Opening Areas (to be advised) 42 20-07-07 30-08-07 0 01-06-06 12-06-07 -161 Section Completion of R8K 230 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 Section Completion of R8R 230 05-04-07A 20-11-07 0 01-05-06 05-04-07A 12-06-07 -161 Section Completion of R8K Work DLP for R8K Work DLP for R8K Work DLP for R8F Work	Operability Test @R8 (with EOT) 44 08-06-08 21-07-08 0 08-06-08 20-09-08 0 90 08-06-08 21-07-08 0 08-06-08 20-09-08 0 Documentation for R8 Opening 893 18-05-06A 26-10-08 21 18-05-06A 22-02-10 -218 Documentation for R8 Opening 892 25-07-07 01-04-08 9 30-09-07 23-06-08 67 Training for R8K 14 29-10-07 15-11-07 0 04-03-11 23-03-11 846 Training for R8 14 26-03-08 15-04-08 0 22-07-08 08-08-08 80 Ompletion Dates 0 09-08-08 0 01-07-09* 326 Early Road Opening Areas (to be advised) 42 20-07-07 30-08-07 0 01-06-06 12-06-07 414 Section Completion of R8K 230 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 Section Completion of R8R8 250 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 Section Completion of R8R8 260 08-08-08 0 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 Section Completion of R8K 250 05-04-07A 20-01-07 0 05-04-07A 12-06-07 -161 Section Completion of R8K 260 08-08-08 0 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 Section Completion of R8K 270 05-04-07A 20-01-09 0 12-03-07A 08-08-08 -51 Section Completion of R8K 270 05-04-07A 20-01-07 20-01-09 0 12-03-07A 08-08-08 -51 Section Completion of R9K Work 280 05-04-07A 20-01-09 0 12-03-07A 08-08-08 -51 Section Completion of R9K Work		
44 08-06-08 21-07-08 0 08-06-08 20-09-08 0 Decration and Maintenance Documents & Training 893 18-05-06A 26-10-08 21 18-05-06A 22-02-10 -218 Documentation for RBK Opening 893 18-05-06A 26-10-08 9 30-09-07 23-06-08 67 Training for RBK 14 29-10-07 15-11-07 0 04-03-11 23-03-11 846 Training for RB 14 26-03-08 15-04-08 0 22-07-08 08-08-08 80 Documentation for RBK Opening 14 26-03-08 15-04-08 0 22-07-08 08-08-08 80 Documentation for RBK Opening Areas (to be advised) 42 20-07-07 30-08-07 0 01-06-08 12-06-07 -414 Section Completion of RBK 230 05-04-07A 20-11-07 0 0 05-04-07A 12-06-07 -161 Section Completion of RBRRBT 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 Defects Liability Period (DLP) for Works DLP for R8K Work 10 01-07-09 01-06-08 -51 DLP for R8K Work	44	44		
Decementation for R8 Opening 25 25 07 07 01 04 08 08 08 08 08 08 08	Decementation for R8 Opening 25 25 07 07 01 04 08 08 08 08 08 08 08	Decimentation for R8 Cypening September Septemb		
Bost	Documentation for R8K Opening	Section Completion of R8K Section Secti		
893	893	893 18-05-06A 26-10-08 21 18-05-06A 22-02-10 -218 Documentation for R8 Opening		
Documentation for R8 Opening 252 25-07-07 01-04-08 9 30-09-07 23-06-08 67 1-Training for R8K 14 29-10-07 15-11-07 0 04-03-11 23-03-11 846 1-Training for R8 14 26-03-08 15-04-08 0 22-07-08 08-08-08 80 15 20-07-07 20-11-07 0 30-09-07* -51 0 20-11-07 0 30-09-07* -51 0 09-08-08 0 01-07-09* 326 1-Early Road Opening Areas (to be advised) 42 20-07-07 30-08-07 0 01-06-06 12-06-07 -414 1-Section Completion of R8K 230 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 1-Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 1-Early Road Opening Areas (to be advised) 230 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 2-Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 3-Early Road Opening Areas (to be advised) 3-Early Road Opening Areas (to be advised) 4-Early Road Opening Areas (to	Documentation for R8 Opening 252 25-07-07 01-04-08 9 30-09-07 23-06-08 67	Documentation for R8 Opening 252 25-07-07 01-04-08 9 30-09-07 23-06-08 67 Training for R8K 14 29-10-07 15-11-07 0 04-03-11 23-03-11 846 Training for R8 14 26-03-08 15-04-08 0 22-07-08 08-08-08 80 Ompletion Dates 0 20-11-07 0 30-09-07 -51 0 09-08-08 0 01-07-09 326 Early Road Opening Areas (to be advised) 42 20-07-07 30-08-07 0 01-06-06 12-06-07 -414 Section Completion of R8K 230 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 Sectos Liability Period (DLP) for Works DLP for R8K Work 761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 DLP for R8T Work		
252 25-07-07 01-04-08 9 30-09-07 23-06-08 67 Training for R8K 14 29-10-07 15-11-07 0 04-03-11 23-03-11 846 Training for R8 14 26-03-08 15-04-08 0 22-07-08 08-08-08 80 Training for B8 0 20-11-07 0 30-09-07* -51 0 09-08-08 0 01-07-09* 326 Early Road Opening Areas (to be advised) 42 20-07-07 30-08-07 0 01-06-06 12-06-07 -414 Section Completion of R8K 230 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 Effects Liability Period (DLP) for Works DLP for R8K Work 751 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 DLP for R8T Work	252 25-07-07 01-04-08 9 30-09-07 23-06-08 67 Training for R8K 14 29-10-07 15-11-07 0 04-03-11 23-03-11 846 Training for R8 14 26-03-08 15-04-08 0 22-07-08 08-08-08 80 Discription Dates 0 20-11-07 0 30-09-07 -51 0 09-08-08 0 01-07-09 326 Early Road Opening Areas (to be advised) 42 20-07-07 30-08-07 0 01-06-06 12-06-07 -414 Section Completion of R8K 230 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 DLP for R8K Work DLP for R8K Work DLP for R8K Work DLP for R8T Work	252 25-07-07 01-04-08 9 30-09-07 23-06-08 67 Training for R8K 14 29-10-07 15-11-07 0 04-03-11 23-03-11 846 Training for R8 14 26-03-08 15-04-08 0 22-07-08 08-08-08 80 Discription Dates 0 20-11-07 0 30-09-07* -51 0 09-08-08 0 01-07-09* 326 Early Road Opening Areas (to be advised) 42 20-07-07 30-08-07 0 01-06-06 12-06-07 -414 Section Completion of R8K 230 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 DLP for R8K Work 761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 DLP for R8T Work		
Training for R8K 14	Training for R8K 14	Training for R8K 14		
14	14	14		
14 26-03-08 15-04-08 0 22-07-08 08-08-08 80 Ompletion Dates	14	14		
0	O	0		
0	0	0		
0	0	0		
Early Road Opening Areas (to be advised) 42 20-07-07 30-08-07 0 01-06-06 12-06-07 -414 Section Completion of R8K 230 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 Section Completion of R8/R8T 517 516 12-03-07A 08-08-08 -51 Section Completion of R8/R8T 518 516 12-03-07A 08-08-08 -51 Section Completion of R8/R8T 517 516 12-03-07A 08-08-08 -51 Section Completion of R8/R8T 518 516 12-03-07A 08-08-08 -51 Section Completion of R8/R8T 519 516 12-03-07A 08-08-08 -51 Section Completion of R8/R8T 510 516 12-03-07A 08-08-08 -51 Section Completion of R8/R8T 510 516 12-03-07A 08-08-08 -51 Section Completion of R8/R8T 510 516 12-03-07A 08-08-08 -51 Section Completion of R8/R8T 510 516 12-03-07A 08-08-08 -51 Section Completion of R8/R8T 510 516 12-03-07A 08-08-08 -51 Section Completion of R8/R8T Sect	Early Road Opening Areas (to be advised) 42 20-07-07 30-08-07 0 01-06-06 12-06-07 -414 Section Completion of R8K 230 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 Effects Liability Period (DLP) for Works DLP for R8K Work 761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 DLP for R8T Work	Early Road Opening Areas (to be advised) 42 20-07-07 30-08-07 0 01-06-06 12-06-07 -414 Section Completion of R8K 230 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 Sefects Liability Period (DLP) for Works DLP for R8K Work 761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 DLP for R8T Work		
42 20-07-07 30-08-07 0 01-06-06 12-06-07 -414 - Section Completion of R8K 230 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 - Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 - Section Liability Period (DLP) for Works - DLP for R8K Work 761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 - DLP for R8T Work	42 20-07-07 30-08-07 0 01-06-06 12-06-07 -414 Section Completion of R8K 230 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 Section Completion of R8/R8T DLP for R8K Work 761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 DLP for R8T Work	42 20-07-07 30-08-07 0 01-06-06 12-06-07 -414 - Section Completion of R8K 230 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 - Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 - DLP for R8K Work 761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 - DLP for R8T Work	Overall Completion	DI HO I &HO
- Section Completion of R8K 230 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 - Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 - Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 - DLP for R8K Work 761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 - DLP for R8T Work	Section Completion of R8K 230 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 Section Completion of R8/R8T 516 12-03-07A 08-08-08 -51 DLP for R8K Work 761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 DLP for R8T Work	- Section Completion of R8K 230 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 - Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 - Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 - DLP for R8K Work 761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 - DLP for R8T Work		
230 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161	230 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161	230 05-04-07A 20-11-07 0 05-04-07A 12-06-07 -161 ★ ★ ★ ★ ★ ★ ★ ★ ★ ★ ★ ★ ★ ★ ★ ★ ★ ★		
- Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 efects Liability Period (DLP) for Works - DLP for R8K Work 761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 - DLP for R8T Work	Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 efects Liability Period (DLP) for Works DLP for R8K Work 761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 DLP for R8T Work	- Section Completion of R8/R8T 516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 efects Liability Period (DLP) for Works - DLP for R8K Work 761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163	<u> </u>	
516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 ◆	516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 efects Liability Period (DLP) for Works DLP for R8K Work 761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 DLP for R8T Work	516 12-03-07A 08-08-08 0 12-03-07A 08-08-08 -51 ♦ ♦ ♦ ♦ ♦ ♦ ♦ ♦ ♦ ♦ ♦ ♦ ♦ ♦ ♦ ♦ ♦ ♦		
## DLP for R8K Work 761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 DLP for R8T Work	## DLP for R8K Work 761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 DLP for R8T Work	## DLP for R8K Work 761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 DLP for R8T Work		
- DLP for R8K Work 761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 -164 - DLP for R8T Work	DLP for R8K Work 761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 DLP for R8T Work	- DLP for R8K Work 761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 -164 -165		
761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 - DLP for R8T Work	761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 DLP for R8T Work	761 21-11-07 20-12-09 0 12-07-07 20-12-09 -163 - DLP for R8T Work	<u> </u>	
- DLP for R8T Work	DLP for R8T Work	- DLP for R8T Work		

APPENDIX M COMPLAINT LOG

Appendix M - Complaint Log

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
			Kwai Tsing District Officer (KTDO) recently received a public noise complaint about construction noise generated from the Route 8 – Lai Chi Kok Viaduct (R8-LCKV) Project, near Nob Hill, Lai Chi Kok, KTDO referred the complaint to the Highways Department (HyD) on the same day. HyD subsequently referred the complaint to the Environmental Team (ET) Leader of the Project on 18 March 2004.	Based on the information provided by the ER, the construction activities conducted in the vicinity of Nob Hill in the period between 2 and 18 March 2004 were: Item 1 – Breaking off existing planter and excavate trial trench to expose underground utilities (using one to two backhoes) Item 2 – Erect rock fall fence & forming platform for predrilling (using one backhoe and occasionally one crane lorry) Item 4 – Excavate further to expose all underground utilities (using hand tools) Item 5 – Pre-drilling works (using one drilling rig)	
40318	Citybase Property Man (the management comp Hill) and the Secretarty Owners Committee (M about construction nois from the R8-LCKV Pro areas near Nob Hill. M mentioned that resident Hill have greatly been a noise impacts generatir LCKV construction wo requested relevant gove departments to conside barrier along Ching Ch to work out possible m minimize the noise nuis	The complaint was raised by the Citybase Property Management Ltd. (the management company of Nob Hill) and the Secretarty of Nob Hill Owners Committee (Mr. Kevin Tse) about construction noise generated from the R8-LCKV Project at the work	Considering the scale of work and the PMEs adopted, the ET believed that the construction noise impact at Nob Hill from the above construction activities of R8-LCKV was not significant. The bored piling work (Item 3) using one crawler crane and one oscillator was started on 19 March 2004, which was two days	Closed	
			areas near Nob Hill. Mr. Kevin Tse mentioned that residents living in Nob Hill have greatly been affected by the noise impacts generating from the R8-LCKV construction works. He also requested relevant government departments to consider installing noise barrier along Ching Cheung Road and to work out possible measures to minimize the noise nuisances to the residents living in the vicinity.	after the issue date of this complaint, so this activity was not considered in this report. According to the EM&A Manuals, Nob Hill was not selected as Noise Monitoring Location (NML) for the Project. Therefore, no direct noise monitoring data could be provided for the complaint investigation. However, there was no noise level exceedance recorded at the nearby NML (NM4 – Mei Foo Sun Chuen, Phase	
				5) since the commencement of the project according to ET's inventory. During ET's weekly environmental site inspections on 3, 10, 17 March 2004, no serious noise nuisance induced by the Project works was observed at the sites near Nob Hill. Based on the joint site visit with the representative of HyD, IEC, RSS and ET to the Nob Hill on 30 March 2004, the major noise source at Nob Hill was identified as traffic noise on Ching	

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
				Cheung Road, which is located very close to this building, especially at or above the Podium Floor (i.e. 5/F).	
				 Based on the information obtained, this noise complaint is not considered due to the construction activities of the Project. Nevertheless, the Contractor was recommended to adopt good site practice to minimize the construction noise, such as: To space out noisy equipment and position it as far away as possible from the sensitive receivers; To avoid concurrent uses of noisy equipment near the sensitive area; To ensure the equipment are maintaining in good operation condition; and To turned off any idle equipment on site. 	
				Adding to that, ET is proposed to install one to two noise monitoring stations at Nob Hill in order to monitor the noise impact generated from the R8-LCKV Project to the resident of Nob Hill or the nearby buildings.	

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
40330	Site Areas near Nob Hill	30 March 2004	Highways Department (HyD) recently received a public noise complaint about construction noise generated from the Route 8 – Lai Chi Kok Viaduct (R8-LCKV) Project, near Nob Hill, Lai Chi Kok. HyD referred the complaint to the RSS and subsequently referred to the ET Leader of the Project on 30 March 2004. The complaint was raised by Mr. Yau, the Office of DCV Member Mr. Cheung Wing Shum, regarding the high pitch construction noise generated at the R8-LCKV site which cause serious nuisance to the residents at Mei Foo.	Based on the information provided by the RSS, the Contractor was not aware of any high pitched construction noise arising from plant employed for their works. The noise complaint referred to may be originated from the damage of a gas main valve on the afternoon of 29 March 2004 in the vicinity of the junction of Mai Lai Road with Lai King Hill Road. The high pitched whistle apparently resulted from the damage which was repaired by TownGas in that afternoon. Based on the information obtained, this noise complaint is considered not due to the construction activities of the Project. Nevertheless, the Contractor was recommended to adopt good site practice to minimize the construction noise, such as: To space out noisy equipment and position it as far away as possible from the sensitive receivers; To avoid concurrent uses of noisy equipment near the sensitive area; To ensure the equipment are maintaining in good operation condition; and To turned off any idle equipment on site.	Closed
40402	Nob Hill	06 April 2004	A public noise complaint was received by the Contractor (NECSO) on 02 April 2004 regarding the noise generated from the Ching Cheung Road Widening Works of the Route 8 – Lai Chi Kok Viaduct (R8-LCKV) Project, near Nob Hill, Lai Chi Kok. NECSO referred the complaint to the RSS and subsequently referred to the ET Leader of the Project on 6 April 2004	The complaint was raised by Ms Wong, regarding the noise generated from the Ching Cheung Road Widening Works of the R8-LCKV Project, which cause serious nuisance to her. Based on the information provided by the RSS, the plants employed by the Contractor for carrying out bored piling works in front of Nob Hill should not generate excessive noise. The RSS had also checked against the site records that no piling works was in progress in front of Nob Hill on 1-3 April 2004. According to telephone communication between the complainant (Ms Wong) and the RSS on 8 April 2004, the RSS reported that Ms Wong was not complaining about the construction noise generated by the R8-LCKV Project. She was actually complaining about the traffic noise she anticipated to be generated after completion of widening work at Ching Cheung Road in front of Nob Hill.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
				During ET's weekly environmental site inspections on 17, 24 & 31 March 2004 and 7 April 2004, no serious noise nuisance induced by the Project works was observed at the construction sites near Nob Hill.	
				Based on the joint site visit with the representative of HyD, IEC, RSS and ET to the Nob Hill on 30 March 2004, the major noise source at Nob Hill was identified as traffic noise on Ching Cheung Road, which is located very close to this building, especially at or above the Podium Floor (i.e. 5/F).	
				Based on the information obtained, this noise complaint is considered not due to the construction activities of the Project.	
				Nevertheless, the Contractor was recommended to adopt good site practice to minimize the construction noise, such as • To space out noisy equipment and position it as far away as possible from the sensitive receivers; • To avoid concurrent uses of noisy equipment near the	
				 To avoid concurrent uses of horsy equipment hear the sensitive area; To ensure the equipment are maintaining in good operation condition; and To turned off any idle equipment on site. 	
40710	Pier P7 in Portion E1	10 July 2004	A public complaint was raised on 30 th June 2004 regarding the washout of muddy water from the site area of the Route 8 – Lai Chi Kok Viaduct (R8-LCKV) Project, at Pier P7 onto Lai Chi Kok Road. The complaint was referred to the RSS	Based on the information provided by the RSS, the spillage of muddy water was in fact due to a burst in a temporary water pipe being utilized in the piling operations at Pier P7 in Portion E1. Emergency remedial works were undertaken preventing further spillage of muddy water. The remaining ponding water within the works area arising from the burst was all removed from the area on 5 th July 2004.	Closed
	I oldon E1		on 3 rd July 2004 and subsequently referred to the ET Leader of the Project on 10 th July 2004. The complaint was raised by Mr. Chan,	During ET's weekly environmental site inspection on 14 th July 2004, no serious water quality nuisance induced by the Project works was observed at the construction sites near Pier P7. It was also noted that the back of profile barriers along the site boundary had been sealed up by cement as preventive measures.	

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
			regarding the washout of muddy water from the works area of the R8-LCKV Project onto Lai Chi Kok Road. The washout caused nuisance to the drivers utilizing the road, and may also cause danger to the motorbikes.	During ET's weekly environmental site inspections on 17, 24 & 31 March 2004 and 7 April 2004, no serious noise nuisance induced by the Project works was observed at the construction sites near Nob Hill.	
			danger to the motoroixes.	Based on the information obtained, the complaint is considered due to the construction activities of the Project. Emergency remedial works had been taken by the Contractor to rectify the situation and preventive measures had also been implemented.	
				Nevertheless, the Contractor was recommended to adopt the following measures to avoid re-occurrence of similar incidents: to enhance surface runoff control measures along the site boundary; to provide adequate training to the frontline workers; and to regularly inspect temporary water supply equipment, such as hose pipe to make sure the equipment is in good condition.	
40809	Ching Cheung Road area near Nob Hill	22-Jul-04 (by EPD) 09-Aug-04 (by ET Leader)	EPD received a public noise complaint on 22 July 2004 about construction noise and dust generated from Route 8 – Lai Chi Kok Viaduct (R8-LCKV) Project, at the Ching Cheung Road Area near Nob Hill. EPD subsequently referred the complaint to the ET Leader of the Project on 9 August 2004. The complaint was about the construction noise and dust observed at the Ching Cheung Road area near Nob Hill. The locations of the works areas being concerned by the complainant include:	 Information Provided by RSS Information (construction activities and equipment adopted) in a 2-week period before the date of complaint, i.e. 7 to 21 July 2004, was obtained from the Resident Site Staff. Area A: Item 1 – Drainage works by using 1 x backhoe; Item 2 – Bored piling works by using 1 x crawler crane, 1 x air compressor, 1 x reverse circulation drill and 1 x power pack; Item 3 – Trial trench excavation by man power; Item 4 – Gas main diversion by 1 x backhoe (performed by TGC's Contractor) Area B: No construction activity was undertaken in the concerned period. 	Closed
			 Area A: Works area between Nob Hill and Lai Chi Kok Park Swimming Pool Area B: Works area between Ching 	Review of Environmental Monitoring Results The routine monitoring stations, which are in the vicinity of the concerned works areas, include: Noise Monitoring	

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
			Cheung Road and Mei Lai Road / Lai Wan Road opposite to Mei Foo Sun Cheung (Phase 5) and Lai Chi Kok Public Library.	NM4: R/F of Mei Foo Sun Chuen (Phase 5) NM8a: M/F of Nob Hill NM8b: 3/F of Nob Hill Air Quality (1-hr TSP / 24-hr TSP) Monitoring AM2: R/F of Lai Chi Kok Sports Centre No Action / Limit level exceedance was identified in July 2004. Environmental Site Inspection During the ET site inspections on 8th, 14th and 20th July 04, no major environmental deficiency with regard to noise and air quality was identified by the auditors. Conclusions Based on the RSS's information, environmental monitoring results as well as the observations made during site inspections, this complaint is considered to be invalid and not due to the construction activities of the Project. Nevertheless, the Contractor was recommended to adopt good site practice to minimize the construction noise and dust impacts, such as: To space out noisy equipment and position it as far away as possible from the sensitive receivers; To avoid concurrent uses of noisy equipment near the sensitive area; To ensure the equipment are maintaining in good operation condition; To turn off any idle equipment on site. To cover excavated dusty materials by impervious sheeting; To provide water spray for haul roads, loading/unloading and concrete breaking operations; To perform wheel wash for every vehicle immediately before leaving the site.	
50215	Mei Foo Sun Chuen, Phase 5 (Retaining Wall CC-R3)	15-Feb-05 (by ET Leader)	A public complaint was raised on 8 th Feb 2005 regarding construction noise from the site area of the Route 8 – Lai Chi Kok Viaduct (R8-LCKV) Project	Construction Activities During the weekly site inspection on 17 Feb 05, piling work was being conducted at the concerned. The major powered	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
Log Ref.	Location	Received Date	near Mei Foo Sun Chuen. The complaint was referred to the Resident Site Staff on 14 th Feb 2005 and subsequently referred to the ET Leader of the Project on 15 th Feb 2005. The complaint was raised by a resident in Mei Foo Sun Chuen, regarding the noise generation from the piling work at Retaining Wall CC-R3, adjacent to Po Leung Kuk Tong Nai Kan College.	Investigation/Mitigation Action mechanical equipment (PME) in operation included a mobile crane, an air compressor, a reverse circulation drill and a generator. In view of the separation of the site area and the residential building (around 40 m) and also the high traffic noise from Ching Cheung Road as well as Mei Lai Road, the noise generated from the operation of the PME was believed to be insignificant. Environmental Monitoring The noise monitoring results at Station NM4 (Mei Foo Sun Chuen, Phase 5) for the last 3 months were reviewed in order to evaluate the noise impact from the Project on the noise sensitive receiver. The measured noise levels in last three threes were ranged from 70.8 to 75.8 dB(A). It was observed that the measured noise levels were well within the range of baseline noise levels (69.2 to 75.8 dB(A)). The corrected construction noise levels were found to be ranged from 63.5 to 71.5 dB(A), which were well below the noise criterion of 75 dB(A). Conclusions Based on the information obtained and the noise monitoring results, this complaint is considered to be invalid and not due to the construction activities of the Project. Nevertheless, the Contractor was recommended to adopt good site practice to minimize the construction noise impacts.	Status
50322	Seung Lai House, Wah Lai Estate (Slope S1)	11-Mar-05 (by EPD) 22-Mar-05 (by ET Leader)	Environmental Protection Department (EPD) received a public noise complaint on 11 Mar 05 about daytime construction noise generation from R8-LCKV. EPD subsequently referred the	Construction Activities As advised by the RSS, the major construction work during 25 Feb 05 to 11 Mar 05 (2 weeks before the date of complaint) in the vicinity of Wah Lai Estate included excavation work, soil	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
			complaint to the Environmental Team (ET) Leader of the Project on 22 Mar 05. The complaint was raised by a resident of Seung Lai House of Wah Lai Estate, regarding the daytime (0800-1800 hrs) construction noise generated from the slope work and road work of R8-LCKV Project. As advised by EPD, the complainant is living on 20/F or above in Seung Lai House.	nail work and installation of u-channel and manholes. The major powered mechanical equipment included excavators, drilling machine and air compressor. In view of the separation of the site area (Slope S1) and the Seung Lai House (around 140 m) and also the traffic noise from Ching Cheung Road, the noise generated from the construction activities at Slope S1 was believed to be insignificant. **Environmental Monitoring** Ad-hoc noise measurement was conducted at Seung Lai House on 30th Mar 05 and the measured noise level (Leq-30min) was 66.9 dB(A), which was well below the criterion for daytime construction noise of 75 dB(A). The construction noise level (with reduction of background noise level) is expected to be even lower. **Conclusion** Based on the information obtained and the noise measurement results, this complaint is considered not justifiable. Nevertheless, the Contractor was recommended to adopt good site practice to minimize the construction noise impact.	
50330, 50331, 50404 & 50407	Wah Lai Estate	30-Mar-05, 31- Mar-05, 4-Apr- 05 & 7-Apr-05 (by ET Leader via RSS)	Four public complaints were lodged by the residents of Wah Lai Estate regarding the construction noise from the site area of the Route 8 – Lai Chi Kok Viaduct (R8-LCKV) Project near Wah Lai Estate. The complaints were	Construction Activities The site of concern was likely to be Slope S1, which is around 140 m away from Wah Lai Estate. The major construction work at Slope S1 included trimming of slope, soil nail work and erection of u-channels and step channels.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
Log Ref.	Location	Received Date	referred by the Resident Site Staff to the Environmental Team (ET) Leader on 30 th , 31 st March, 4 th and 7 th April 2005, respectively.	Environmental Monitoring Ad-hoc noise measurement was conducted at Seung Lai House on 30 th Mar 05 and 7 th Apr 05 and the measured noise levels (Leq-30min) were ranged from 66.9 to 69.1 dB(A), which were well below the criterion for daytime construction noise of 75 dB(A). The construction noise level (with reduction of background noise level) is expected to be even lower. Conclusion Based on the results of the ad-hoc noise measurements at Wah Lai Estate, no exceedance of daytime noise criterion of 75 dB(A) was recorded. The complaints lodged are therefore considered not justifiable. Mitigation The Contractor agreed to arrange the noisy activities to commence after 8:00 am. This arrangement could effectively reduce the disturbance to the residents within the more sensitive time period (7:00 am to 8:00 am).	Status
50404-v2	Mei Foo Sun Chuen	4-Apr-05 (by ET Leader via RSS)	A public complaint was raised on 1 st April 2005 regarding construction noise from the site area of the Route 8 – Lai Chi Kok Viaduct (R8-LCKV) Project near Mei Foo Sun Chuen. The complaint was referred to the Resident Site Staff and the ET Leader on 4 th	Construction Activities The site of concern was likely to Retaining Wall CC-R3, adjacent to Po Leung Kuk Tong Nai Kan College. The major construction works at this area included bored piling works and excavation works.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
			April 2005.	Environmental Monitoring	
				According to the EM&A Manual, Mei Foo Sun Chuen, Phase 5 (NM4) is designated as one of the noise monitoring stations.	
				Since the commencement of the impact monitoring programme, the construction noise levels recorded at this station were all below the noise criterion.	
				Conclusion	
				Based on the noise monitoring results at Station NM4 (Mei Foo Sun Chuen), no exceedance of daytime noise criterion of 75 dB(A) was recorded since the commencement of the impact monitoring programme. The complaint lodged is therefore considered not justifiable.	
				Mitigation	
				The Contractor has agreed to arrange the noisy activities to commence after 8:00 am. This arrangement could effectively reduce the disturbance to the residents within the more sensitive time period (7:00 am to 8:00 am). The Contractor also agreed to provide some temporary noise barriers for the noisy machinery if found necessary.	
50613	Mei Foo Sun Chuen	7-Jun-05 (by EPD) 13-Jun-05 (by ET Leader)	According to EPD, the complaint was raised by a resident of Mei Foo Sun Chuen (Block 7, Phase 5) on 7 June 2005. It was about construction dust emitted intermittently from the slope works undertaken on the other side of Mei Lai Road.	Site Activities The site of concern was likely to be CCR-R3. Bored piling works and demolition of existing retaining walls were undertaken at this area in the period between 1 and 7 June 2005. It was believed that the demolition of existing retaining wall, which involved concrete breaking, was the activity of concern.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
Log Rei.	Location	Received Date	The complainant was particularly concerned about the fugitive dust emission during rock / concrete breaking activities.	On 1 Jun 05, one of the environmental deficiencies noted by the ET was about fugitive dust emission from breaking activities at CCR-R3. The Contractor was reminded to provide sufficient dust mitigation measures for the breaking works. Immediate action was taken by the Contractor to apply water spray for the works as observed during the audit session. On 9 Jun 05, the breaking works were still being taken at CCR-R3. Water spray as a dust mitigation measure was being adopted by the Contractor during the audit. No observable dust emission was noted from the breaking works or other site activities. On 15 Jun 05, the same area was re-inspected due to the receipt of the complaint from EPD. The demolition works had been finished and no other dust emissive activity was being taken. No other dust source from the construction site was observed during the inspection. Conclusion Based on the observations noted during our site inspections, this complaint is considered to be valid and related to the construction activities of the Project. However, corrective action had been taken by the Contractor and the situation was found improved during the follow-up inspections.	Status
50721	Hei Lai House, Wah Lai Estate	21-Jul-05 (by ET Leader)	The complaint was lodged by a resident of Hei Lai House of Wah Lai Estate through a Legislative Council member. The complaint was about construction noise nuisance caused by rock breaking work, which claimed to be started from 8:30am daily, carried out at Ching Cheung Road near Wah Lai Estate.	Site Activities The slope work at Slope S1 was likely to be the activity of concern. The work at Slope S1 recently included the operation of excavator mounted breakers, excavators and dump trucks. The time period of concern was within normal working hours (7am to 7pm) on a weekday not being a public holiday. The noise criterion is 75 dB(A) for domestic premises.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
			The complainant hoped that the rock breaking work could start later i.e. be carried out from noon to afternoon and the site could be fully enclosed. The Environmental Team (ET) of the Project received the complaint on 21 July 2005 and forwarded it to the Resident Site Staff (RSS) to obtain necessary information.	Noise Measurement Ad-hoc measurements were carried out on the roof of Hei Lai House on 25 July 2005. The results show that the measured noise level is well below the noise criterion of 75 dB(A). The construction noise level (with reduction of background noise) is expected to be even lower. Conclusion Since the noise measurement results at Wah Lai Estate were below 75 dB(A), the complaint was considered not justifiable. Nevertheless, noise mitigation measures have been implemented by the Contractor to minimize the noise impact arising from the breaking activities: 1. Employment of silenced-type breakers; 2. Temporary noise barriers, attached with sound adsorption materials, were erected to screen the site of breaking from sensitive receivers 3. While the permitted hours for construction works are 7am to 7pm on non-holidays, the Contractor has commenced the rock breaking activity after 8:30am.	
51107	Ching Cheung Road near Mei Foo Sun Chuen	7-Nov-05 (by the ET Leader)	Environmental Protection Department (EPD) received a public complaint about environmental nuisance generated from Route 8 – Lai Chi Kok Viaduct (R8-LCKV) Project. EPD subsequently referred the complaint to the Environmental Team (ET) Leader of the Project on 7 November 2005. According to EPD, the complaint was	The site of concern was likely to be CCR-S4 and CCR-R3. According to RSS's records, bored piling works and soil nail drilling at CCR-R3, excavation works at CCR-S4 in the concerned period. Site Inspection After receipt of the complaint, an ad-hoc site inspection was carried by ET on 9 November 2005 and the following	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
			raised by a resident of Mei Foo Sun Chuen. The complaint was about dark smoke, dust and noise nuisance caused by the construction work of R8-LCKV near Mei Foo Sun Chuen.	 Breaking activities were undertaken at CCR-R2 and R3. Continuous water spray was applied by the workers for dust suppression. Movable noise barriers were erected to alleviate the noise impact. The haul roads and exposed works areas were observed wet. A water sprinkler was installed at the CCR-S4 for water spraying. Most of the slope was shot-creted to avoid wind erosion. Bored piling work was carried out near the site exit of CCR-R3. Since bored piling mainly involves handling of wet materials, dust nuisance causing by this type of work is not anticipated. Gas exhaust from the machines was visually clear and no dark smoke was identified. Environmental Monitoring Air quality monitoring was conducted at Lai Chi Kok Sports Centre and noise monitoring is conducted at Mei Foo Sun Chuen. No exceedance was recorded for both monitoring. Conclusion Based on the ad-hoc site inspection and the environmental monitoring results, this complaint was considered not justifiable. 	
60118	Lai Po Road near Hoi Lai Estate	18-Jan-06 (by the ET Leader)	Environmental Protection Department (EPD) received a public complaint about environmental nuisance generated from Route 8 – Lai Chi Kok Viaduct (R8-LCKV) Project. EPD subsequently referred the complaint to the Environmental Team (ET) Leader of the Project on 18 January 2006. According to EPD, the complaint was lodged by a resident of Hoi Ming	 Site Activities According to the RSS's records, night works were carried out by the Contractor between 2000 hrs on 14 January 2006 and 0530 hrs on 15 January 2006: Delivery of segment from storage yard near Pier P5/L to Pier 15 for erection; Stressing to temporary PT bars of segments at Pier B3. The above night works, which involved operation of tractor, 	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
Log Rei.	Location	Received Date	House of Hoi Lai Estate. The complaint was about construction noise nuisance caused by construction work of R8-LCKV carried out at Lai Po Road near Hoi Lai Estate. The noise nuisance was noted since 14 January 2006 during the periods from 2330 hrs to 0600 hrs.	mobile crane, lifting frame and generator, were undertaken under the two construction noise permits CNP no. GW-RW0739-05 and GW-RW0740-05. Environmental Monitoring In order to evaluate the noise impact onto the residents of Hoi Lai Estate, nighttime noise monitoring was carried out on 18 January 2006 at 23:00. The above monitoring results revealed that the measured noise levels were close to the reference background levels. After correction of the mean background level, all corrected noise levels were below the noise criterion of 55 dB(A). Conclusion Based on the information collected and the monitoring results, the complaint is considered not justifiable. Nevertheless, the Contractor was reminded to take sufficient noise mitigation measures to minimize the environmental impact on the nearby community.	Status
60119	Mei Foo Sun Chuen (Phase 5)	18-Jan-06 (by the ET Leader)	Environmental Protection Department (EPD) received a public complaint about environmental nuisance generated from Route 8 – Lai Chi Kok Viaduct (R8-LCKV) Project. EPD subsequently referred the complaint to the Environmental Team (ET) Leader of the Project on 19 January 2006. According to EPD, the complaint was raised by a resident of Mei Foo Sun Chuen via a Sham Shui Po District	Site Activities The site of concern was likely to be CCR-S4, CCR-R2 and CCR-R3. According to RSS's records, site activities included: • Trimming of existing rock slope at CCR-S4; • Excavation and rock dowel installation at CCR-R2; and • Construction of cable trough at CCR-R3 by CLP's contractor. Site Inspection After receipt of the complaint, an ad-hoc site inspection was carried by ET on 19 January 2006. No environmental deficiency	Closed

				Investigation/Mitigation Action	Status
			Council Member's Office. The complaint mentioned that residents of	regarding construction dust was identified during the inspection.	
			Mei Foo Sun Chuen Stage 5 were adversely affected by construction dust	Environmental Monitoring	
			caused by the Route 8 work carried out at the slopes adjacent to Ching Cheung Road.	All monitoring results in Jan 06 revealed that no exceedance was recorded for the air quality (1-hr and 24-hr TSP) criteria.	
				Contractor's Action	
				 The Contractor of R8-LCKV had implemented several dust mitigation measures: Haul roads, exposed slope surface and soil stockpiles were watered regularly by hose pipes and sprinklers; Idled exposed slope were shot-creted; and Watering was applied for the dust emissive activities, such as loading and unloading of dusty materials, excavation and breaking works. 	
				Conclusion	
				Based on the ad-hoc site inspection and the environmental monitoring results, this complaint was considered not justifiable. Nevertheless, the Contractor was reminded to keep on the dust mitigation measures being implemented and step up the measures if necessary.	
			Four environmental complaints were	Site Activities	
60213 60216	Hoi Lai Estate	13-Feb-06 16-Feb-06 20-Feb-06	received in this reporting month. Three of them were referred by EPD on 13 th , 20 th and 22 nd Feb 06 and the other one was referred by HyD via MHJV on 16 th Feb 06.	Since around mid-January 2006, segments were transported to Piers P15 and B4, under the permission of construction noise permit (CNP).	
60216 60220 60222	(Lai Po Road)	22-Feb-06 (by the ET Leader)	All about construction noise due to night works at Lai Po Road near Hoi Lai Estate.	It was suspected that the sound of concern was generated from tractors for precast segment transportation. In view of the safety of workers, an alert sound and flashing are maintained during backing action of the tractors.	Closed
				Site Inspection	

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
				An ad-hoc inspection was carried out by the ET on 16 Feb 06 from 00:30 to 02:30 am. Noise measurement was carried out during the inspection to evaluate the noise impact onto the residents of Hoi Lai Estate. During the monitoring, the major noise source identified was the road traffic noise from Sham Mong Road and Lai Po Road. No alarm sound or alike from the construction equipment was noted. The above monitoring results revealed that the measured noise levels were close to the reference baseline level. After correction of the mean background level, most of data were below the noise criterion of 55 dB(A).	
				Conclusion	
				Based on the information collected and the monitoring results, the complaints are considered not justifiable.	
				It was suspected that the nuisance was caused by the alert sound of tractors during backward movement which servers as a safety measure. However, the RSS and the Contractor are considering the possibility of lowering the alert sound level or replacing by a less disturbing pitch in order to minimize the noise nuisance to residents of Hoi Lai Estate.	
			Environmental Protection Department	Site Activities	
			(EPD) received a public complaint about environmental nuisance generated from Route 8 – Lai Chi Kok Viaduct (R8-LCKV) Project. EPD subsequently referred the complaint to the ET Leader on 20 April 2006.	According to the Resident Site Staff (RSS)'s records, the construction works were carried out by the Contractor from daytime to 2230 hours on 14 April and from 2000 hours to 0600 hours16 April 2006.	
			The complaint is about construction noise nuisance caused by construction work of night works at location near both Hoi Lai Estate and West Kowloon Highway between 14 and 17 April 2006.	 The construction activities near Hoi Lai estate included: - Erecting segments at column PA/R; Stressing of top tendon wires of segments and erecting segments at column P1/R; and Transporting segments to storage yard. 	

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
60420	Near both Hoi Lai Estate and West Kowloon Highway	20-Apr-06 (by the ET Leader)		The above construction activities were undertaken under a construction noise permit CNP no. GW-RW0172-06. Base on the RSS's preliminary investigation, it was suspected that the noise nuisance of concern was caused by loading and unloading of materials, hammering and/or dropping of materials on ground during the stressing works and transportation of precast segment by tractors.	Close
				Contractor's Action	
				The Contractor had implemented a short term mitigation measures:-	
				 Turned off the alert sound of tractors during backward movement in order to reduce the potential for noise impact; Strengthened their management on worker's working manner such as avoid dropping of material on ground, wrapping up of hammering equipment and etc.; and Conducted training of worker in order to reducing noise nuisance during the night works. 	
				Conclusion	
				Based on the information collected and the monitoring results, the complaints are considered not justified.	
				It was suspected that the nuisance was caused by loading and unloading of materials, hammering and/or dropping of materials on ground during the stressing works and transportation of precast segment by tractors.	
				The Contractor has strictly complied with PME allowed in the CNP No. GW-RW0172-06. Besides, night work at the concerned location was completed. No further construction work at night at this location is anticipated.	

Log Ref. Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
Between Chin Cheung Road and Mei Lai Road (near Phase 5 of Me Foo Sun Chue	28-Apr-06 (by the ET Leader)	Environmental Protection Department (EPD) received a public complaint about tree cutting in the area between Ching Cheung Road and Mei Lai Road (near Phase 5 of Mei Foo Sun Chuen). EPD subsequently referred the complaint to the ET Leader on 28 April 2006. The complaint was about the Contractor cu trees in the area between Ching Cheung Road and Mei Lai Road (near Phase 5 of Mei Foo Sun Chuen). This had removed the traffic noise barrier effect of the trees and hence made the residents of Mei Foo Sun Chuen becoming being seriously affected by the traffic noise nuisance.	Contractor Action	Close

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
60522	Hoi Lai Estate (Hoi Fai House)	22-May-06 (by ET Leader)	Environmental Protection Department (EPD) received a public complaints about noise nuisance generated from Route 8 – Lai Chi Kok Viaduct Project. EPD subsequently referred the complaint to ET Leader on 22 May 2006. The complaint was concerned about the noise produced from construction work during the period between 2300 hours and 0100 hours every night since 3 weeks ago. The complaint described the noise being like sound of poring concrete.	According to the RSS's records, only precast segment transportation works at the concerned area which was used as the segment storage yard near Pier P5L to Piers near Mui Kong Tsuen. No concreting activities were carried out at the abovementioned area between 2300 hours and 0100 hours every night in concerned period. In addition, the transportation works were usually carried out from 2000 hours to 0300 hours (or before 0300 hours). Contractor Action The idle and backup equipments such as tractors has turned off or throttled down in order to reduce the noise impact since the last complaint on this issue near Hoi Lai Estaet. Besides, the above night works were undertaken with three construction noise permits. Site Inspection An ad-hoc inspection was carried out by the ET at 2300 on 26 May 2006. During the inspection, no construction activities were carried out at the concerned area, where the tractor and mobile crane were throttled down. Conclusion According to RSS's information, no concreting activities were carried out at the concerned area. Therefore, the major noise nuisance (pouring concrete) might not be generated from the abovementioned area. Besides, the Contractor strictly complied with PME allowed in the CNP No. GW-RW0172-06. In addition, the Contractor had turned off the alert sound of tractors during backward movement. Based on the information collected, the complaint is considered	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
			•	not justifiable.	
				However, the Contractor was reminded to continuously implement their practice to prevent noise nuisance generation due to the construction works. The site situation will be continuously reviewed by ET and RSS also.	
			The Integrated Complaint Centre (ICC) of HKSAR received a public complaint about environment nuisance generated from Route 8 – Lai Chi Kok Viaduct (R8-LVKC). Resident Site Staff (RSS) subsequently referred the complaint to the ET Leader on 9 June 2006. The complaint was about the noise generated from rock excavation work from 9 a.m. to 6 p.m. at the area between Ching Cheung Road and Mei Lai Road (near Phase 5 of Mei Foo Sun Cheun).	Site Activities As advised by the RSS, the site of concerned area was likely to be CCR-S4. According to the RSS's records, 1 number of excavator mounted breaker was unsed to carry out rock breaking work at CCR-S4 during the period between 9 a.m. and 6 p.m. The excavation and rock breaking activities at the concerned area will likely be completed by end of September 2006. Contractor Action	
60609	Near Phase 5 of Mei Foo Sun Chuen	9-Jun-06 (by ET Leader)		The silent rock breaking equipment has been used and noise barriers were erected to minimize the noise impact generated from the breaking activity. Site Inspection and Environmental Monitoring	Closed
				An ad-hoc inspection was carried out by ET on 14 June 2006 from 1:30 p.m. to 4:30 p.m. and 16 June 2006 from 4:00 p.m. to 4:45 p.m.	
				During the inspections, the construction activities at CCR-S4 included handheld breaking, excavation and rock breaking activities were carried out at CCR-S4. However, the temporary noise barriers were erected at the abovementioned location as same as RSS's mentioned.	
				Noise measurement was carried out during the inspection to	

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
				evaluate the noise impact onto the residents of Mei Foo Sun Chuen. The monitoring location was original monitoring location NM4 (Mei Foo Sun Chuen Phase 5).	
				The measured monitoring results were close to the reference baseline level. After correction of the mean background level, the monitoring data were below the noise criterion of 75 dB(A).	
				Conclusion	
				Base on the information collection and the monitoring result, the complaint was considered not justifiable.	
				The Contractor had implemented noise mitigation measures to minimize the noise impact. Besides, the monitoring result were below the noise criteria of 75dB(A). However, the Contractor was still reminded to continuously implement their practice to prevent noise nuisance generation from the construction works.	
				The environmental conditions of the site will be continuously reviewed by the RSS and the ET.	
			The Integrated Complaint Centre (ICC) of HKSAR received a public complaint through a facsimile on 12 June 2006 about an environmental nuisance generated from Route 8 – Lai Chi Kok	Site Activities As advised by the RSS, the site of concerned area was likely to be CCR-S4.	
60626	Near Phase 5 of	26-Jun-06	Viaduct 9R8-LCKV) Project. Resident Site Staff (RSS) subsequently referred the complaint to the ET Leader on 26 June 2006.	According to the RSS's records, 1 number of excavator mounted breaker was unsed to carry out rock breaking work at CCR-S4 during the period between 9 a.m. and 6 p.m.	Closed
00020	Mei Foo Sun Chuen	(by ET Leader)	According to the explanation from the RSS, this complaint was indeed the same as that received by the ET on 9	The excavation and rock breaking activities at the concerned area will likely be completed by end of September 2006.	Closed
			June 2006. The complaint initiated the complaint verbally to the ICC on 8	Contractor Action	
			June 2006 and then also issued a facsimile to the ICC. The facsimile was transferred to the RSS on 12 June 06	The silent rock breaking equipment has been used and noise barriers were erected to minimize the noise impact generated from the breaking activity.	

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
			and eventually reached the ET on 26 June 2006.	Site Inspection and Environmental Monitoring	
			The complaint was about the noise generated from rock excavation work from 9 a.m. to 6 p.m. at the area between Ching Cheung Road and Mei Lai Road (near Phase 5 of Mei Foo Sun Cheun).	As the complaint was identical to the one received on 9 June 06 by the ET, the ad-hoc inspections carried out on 14 June 2006 from 1:30 p.m. to 4:30 p.m. and 16 June 2006 from 4:00 p.m. to 4:45 p.m. were still applicable to this report. In addition, further ad-hoc inspections were carried out on 28 June 2006 from 1:30 p.m. to 4:00 p.m. and 3 July 2006 from 9:30 a.m. to 11:30 a.m.	
			This complaint was made by the same complainant to the ICC through two different channels (by phone and by facsimile) and the ET of the Project was firstly notified on 9 June 2006. A complaint investigation report was	During the aforesaid inspections, the construction activities at CCR-S4 included handheld breaking, excavation and rock breaking activities were carried out at CCR-S4. However, the temporary noise barriers were erected at the abovementioned location.	
			issued on 22 June 06. As the ET received this separate complaint after the issue of the complaint investigation report and considered the nature of the	In addition to the noise measurement conducted on 14 and 16 June 2006, further noise measurement was carried out on 30 June 2006 to evaluate the noise impact onto the residents of Mei Foo Sun Chuen. The monitoring location was original monitoring location NM4 (Mei Foo Sun Chuen Phase 5).	
			complained event (general construction during daytime but not single event at a particular moment), the complaint investigation procedures were initiated.	Noise measurement carried out on 30 June 06, after correction of the mean background level, the monitoring data were below the noise criterion of 75 dB(A) **Conclusion**	
				This complaint was identical to the one received by the ET on 9 June 06 because the complainant addressed the complaint to the ICC through two different channels (by phone and by facsimile). The facsimile was transferred to the RSS on 12 June 06 and eventually reached the ET on 26 June 06.	
				Base on the information collection and the monitoring result, the complaint was considered not justifiable.	
				The Contractor had implemented noise mitigation measures to minimize the noise impact. Besides, the monitoring result were	

Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
	Received Date	The Integrated Complaint Centre (ICC) of HKSAR received a public complaint on 25 August 2006 about an environmental nuisance generated from Route 8 – Lai Chi Kok Viaduct 9R8-LCKV) Project. Resident Site Staff (RSS) subsequently referred the complaint to the ET Leader on 30 August 2006. The complaint was concerned about dust generated from the rock drilling works affected the nearby ASRs. The complaint described that spraying of	below the noise criteria of 75dB(A). However, the Contractor was still reminded to continuously implement their practice to prevent noise nuisance generation from the construction works. The environmental conditions of the site will be continuously reviewed by the RSS and the ET. Site Activities According to RSS's record, rock dowel installation for slope stabilization at CCR-S1 was commenced on 22 August 2006 and would likely last for at least 6 months. Contractor Action After receiving the complaint, the Contractor has further enhanced the dust mitigation measures as follows:- • Enclosing the rock dowel drilling work on three sides, i.e. top, back and the left hand side, with tarpaulin sheets;	Status
Near Mei Foo and Lai King Hill Road	30-Aug-06 (by ET Leader)	complaint described that spraying of water during rock drilling works was not implemented.	 Spraying of water at the hole during drilling; Wrapping the head of the drilling rig with a wet thick towel. Site Inspection and Environmental Monitoring During the monthly site inspection on 4th September 2006, rock drilling at the slope CCR-S1 was carrying out. The ET observed that the work area was enclosed by tarpaulin sheets at three sides. Water was sprayed continuously at the drilling hole and head of the drilling rig was enclosed with a wet thick towel. All the mitigation measures mentioned by the RSS were implemented. Conclusion Base on the information collected and the monitoring results, the complaints are considered not justifiable. 	Closed
	and Lai King	and Lai King 30-Aug-06	of HKSAR received a public complaint on 25 August 2006 about an environmental nuisance generated from Route 8 – Lai Chi Kok Viaduct 9R8-LCKV) Project. Resident Site Staff (RSS) subsequently referred the complaint to the ET Leader on 30 August 2006. The complaint was concerned about dust generated from the rock drilling works affected the nearby ASRs. The complaint described that spraying of water during rock drilling works was not implemented.	was still reminded to continuously implement their practice to prevent noise nuisance generation from the construction works. The Integrated Complaint Centre (ICC) of HKSAR received a public complaint on 25 August 2006 about an environmental nuisance generated from Route 8 – Lai Chi Kok Viaduct 9R8-LCKV) Project. Resident Site Staff (RSS) subsequently referred the complaint to the ET Leader on 30 August 2006. The complaint was concerned about dust generated from the rock drilling works affected the nearby ASRs. The complaint described that spraying of water during rock drilling works was not implemented. Wear Mei Foo and Lai King Hill Road Agree T Leader) Wear Mei Foo and Lai King Hill Road Mear Mei Foo and Lai King Hill Road Boar Mei Foo and Lai King Hilling work on three sides, i.e. top, back and the left hand side, with tarpaulin sheets; Boar Will Road Hilling Hill Road Boar Mei Foo And Lai King Hilling Work on three sides, i.e. top, back and the left hand side, with tarpaulin sheets; Boar Mei Foo And Hilling Hilling Work on three sides, i.e. top, back and the left hand side, with tarpaulin sheets; Boar Mei Foo And Hilling Hil

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
				monitoring results and dust mitigation measures were implemented by the Contractor during the rock drilling works.	
				However, the Contractor was still reminded to take sufficient dust mitigation measures to minimize the environmental impact on the nearby community:	
				• Enclose dusty activity such as rock drilling with tarpaulin sheet;	
				 Apply water spraying for any dust emissive activities, such as breaking, excavation, loading and unloading of dusty materials; 	
				Cover long-term idle exposed slope surfaces and stockpiles with tarpaulin sheets.	
				The environmental conditions of the site will be continuously reviewed by the RSS and the Environmental Team through site inspections and monitoring exercises.	
			Environmental Protection Department (EPD) received a public complaint about environment nuisance generated from Route 8 – Lai Chi Kok Viaduct Project. EPD subsequently referred the complaint to ET Leader on 31 August 2006.	Site Activities According to RSS's record, rock dowel installation for slope stabilization at CCR-S1 was commenced on 22 August 2006 and would likely last for at least 6 months. Contractor Action	
60831	Between Lai Wan Road and Lai King Hill Road	an Road and ai King Hill Road (by ET Leader) (by ET Leader) (an Assault of ET Leader) (by ET Lea	The complaint was concerned about construction noise, dust and waste water generated from the construction work affect the nearby NSRs after 19.00 hrs, the nearby ASRs and discharged to exiting road respectively	With reference to RSS's site diary, all site activities including drilling works at the concerned area were conducted between 8:00 and 18:00 daily. Ad hoc site observation carried out by the RSS confirmed that no construction activity was carried out after 18:00.	Closed
			and the state of t	As advised by the RSS, tarpaulin sheet covering and water spraying were provided by the Contractor to mitigate the dust nuisance generated from the rock drilling works. On 31 August 2006, the Contractor was further enhanced the dust mitigation measures as follows:-	
				• Enclosing the rock dowel drilling work on three sides, i.e.	

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
				top, back and the left hand side (LHS) with tarpaulin sheets;	
				Spraying water at the hole during drilling;	
				Wrapping the head of the drilling rig with a wet thick towel.	
				Site Inspection and Environmental Monitoring	
				During the monthly site inspection on 4 th September 2006, rock drilling at the slope CCR-S1 was carrying out. The ET observed that the work area was enclosed by tarpaulin sheets at three sides. Water was sprayed continuously at the drilling hole and head of the drilling rig was enclosed with a wet thick towel. All the mitigation measures mentioned by the RSS were implemented.	
				Conclusion	
				Base on the information collected and the monitoring results, the complaint was considered not justifiable.	
				It was because there was no exceedance of the air quality monitoring results and dust mitigation measures were implemented by the Contractor during the rock drilling works. No construction activities were carried after 18:00 in the period mentioned by the complainant. In addition, no wastewater discharge was observed.	
				However, the Contractor was still recommended to take the following mitigation measures to minimize the environmental impact on the nearby community:	
				<u>Dust Nuisance</u>	
				Enclose dusty activity such as rock drilling by tarpaulin sheet;	
				 Apply water spraying for any dust emissive activities, such as breaking, excavation, loading and unloading of dusty materials; 	
				Cover long-term idle exposed slope surfaces and stockpiles with tarpaulin sheets.	

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
				Construction Noise	
				The Contractor was reminded that construction activities during restricted hours could only be carried out with a valid Construction Noise Permit (CNP). In addition, appropriate noise mitigation measures described in the CNP should be implemented in order to minimize the noise impact on the nearby noise sensitive receivers.	
				Wastewater Discharge	
				Fill up the gaps under the footings of hoarding fence along Lai King Hill Road so as to prevent spillage of muddy water during heavy rain onto the existing road.	
				The environmental conditions of the site will be continuously reviewed by the Resident Site Staff and the Environmental Team through site inspections and monitoring exercises.	
			The Integrated Complaint Centre (ICC) of HKSAR received a public complaint	Site Activities	
			on 25 September 2006 about the an environmental nuisance generated from Route 8 – Lai Chi Kok Viaduct 9R8-LCKV) Project. Resident Site Staff (RSS) subsequently referred the complaint to the ET Leader on 25	According to RSS's record, rock dowel installation for slope stabilization at the Slope CCR-S1 was commenced on 22 August 2006 and would last for at least 6 months and the first batch of rock drilling works at the Slope CCR-S4 was commenced on 19 September 2006 and completed on 23 September 2006.	
	Near Ching		September 2006.	Contractor Action	
60925	O925 Cheung Road, Nob Hill and Mei Lai Road	ung Road, 25-Sep-06 O Hill and (by ET Leader)	The complaint was concerned about the	After receiving the complaint, the Contractor has further enhanced the noise mitigation measures as follows:-	Closed
			noise generated from the construction works after 19:00 at the area near	Placing of a wooden box to cover the head of drilling;	
			Ching Cheung Road, Nob Hill and Mei Lai Road	Spraying of water at the hole during drilling and erecting of nylon sheets;	
			Providing silent type drilling rigs for the drilling works at both Slopes CCR-S1 and CCR-S4		
				Site Inspection and Environmental Monitoring	

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
				During the weekly site inspection on 27 September 2006, rock drilling at the Slope CCR-S1 was not carrying out. The ET observed that the work area was enclosed by tarpaulin sheets at three sides. Temporary noise barrier was erected at the working platform of the Slope CCR-S1.	
				The ET also undertook an ad hoc site inspection at the concerned areas after 19:00 on 27 September 2006. No construction activities were observed and noise monitoring was not conducted.	
				Conclusion	
				Base on the information collected and the monitoring results, there was no exceedance of the noise monitoring results and noise mitigation measures were implemented by the Contractor during the rock drilling works.	
				However, the Contractor was still reminded to carry out construction activities only within the permitted working hours (i.e. 07:00 – 19:00 on weekday) and to take sufficient noise mitigation measures to minimize the environmental impact on the nearby community:	
				Provide silent type drilling rigs for the drilling works;	
				Placing of wooden box to cover the head of drilling;	
				Apply water spraying for at the hole during drilling;	
				The environmental conditions of the site will be continuously reviewed by the RSS and the Environmental Team through site inspections and monitoring exercises.	
61025	Lai Chi Kok Road Flyover near PCCW building	25-Oct-06 (by ET Leader)	The Integrated Complaint Centre (ICC) of HKSAR received a public complaint on 25 th October 2006 regarding noise nuisance generated from Route 8 – Lai Chi Kok Viaduct R8-LCKV) Project. Resident Site Staff (RSS) subsequently	Site Activities: According to RSS's record, installation of catchfan at Pier P5/L to P6 near PCCW was carried out at around 0115 to 0500 at both nights of 19 th and 20 th October 2006. The construction equipment used in both nights included one mobile crane, one crane lorry and one generator.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
			referred the complaint to the ET Leader on 25 th October 2006. The complaint was concerned about the noise nuisance generated from workers and construction vehicles during the mid-night between 0100 and 0200 on both 19 th and 20 th October 2006 at Lai Chi Kok Road Flyover near PCCW building.	Contractor Action According to RSS' record, acoustic material wrapping the head of chain blocks and hessian bags placing on ground around catchfans to suppress noise generation when hand tools were dropped onto ground. Environmental Monitoring An ad-hoc site observation and noise monitoring at Hoi Fai House of Hoi Lai Estate were conducted by the Contractor on 26 th October 2006 between 0100 and 0130. The ET also carried out an ad-hoc inspection on 28 th October 2006 from 0100 to 0200. During the inspection, segment erection work was carried out at Pier P5 to P6, which involved the operation of mobile crane and movement of lorry and trucks. During the monitoring, the major noise source identified was the road traffic noise. The monitoring results revealed that the measured noise levels were close to the reference background levels. After correction of the mean background level, all corrected noise levels were below the noise criterion of 55 dB (A) which consists with the noise monitoring results from the Contractor.	
				Conclusion Based on the information collected, the complaint is considered justifiable although the monitoring results complied with the noise criteria. Nevertheless, the Contractor was reminded to take sufficient noise mitigation measures to minimize the environmental impact	
				 on the nearby community: To strengthen management on worker's working manner, such as avoiding dropping materials on ground; No hammering is allowed during restricted hours; and To provide adequate training to workers working, esp. for night works. The environmental conditions of the site will be continuously	

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
				reviewed by the Resident Site Staff and the Environmental Team.	
61103	Pier C13 and C14 at Lai Wan Road Overpass	3-Nov-06 (by ET Leader)	The Integrated Complaint Centre (ICC) of HKSAR received a public complaint on 28 th October 2006 regarding noise nuisance generated from Route 8 – Lai Chi Kok Viaduct R8-LCKV) Project. Resident Site Staff (RSS) subsequently referred the complaint to the ET Leader on 3 rd November 2006. The complaint was concerned about noise generated from the general cleaning work of deck surface using water jet between Pier C13 and C14 at Lai Wan Road Overpass, at the evening of 28 th October 2006.	Site Activities According to the RSS's record, there is a CNP (CNP no. GW-RW0563-06) at the concerned location. Construction activities were allowed to be carried out between 19:00hr and 23:00hr (any day not being a general holiday) under the CNP. Environmental Monitoring During the weekly site inspections in October 2006, no non-compliance or observation on noise was recorded. Accordance to the EM&A program, two noise monitoring stations at Nob Hill, namely (NM8a and NM8b), have been set up in order to monitor the noise level generated from the construction activities. The Station (NM8b) is strongly influenced by road traffic noise from Ching Cheung Road. The measurement at this station is for reference purpose, but not for compliance check for construction noise. All measured value were lower than the noise criterion of 75 dB(A). No exceedance of noise level has been recorded in October 2006. Moreover, based on our site observation record during monitoring, road traffic noise from Ching Cheung Road was the major noise source. Conclusion Based on the information collected, the complaint is considered not justifiable. Nevertheless, the Contractor was reminded to take sufficient noise mitigation measures to minimize the environmental impact on the nearby community: As the general cleaning work could be carried out during normal working hours (i.e. 07:00 to 19:00hr) instead as the work was not critical. RSS would remind the Contractor to programme	Closed
				their works better in order to minimize nuisance to nearby residents. The environmental conditions of the site will be continuously reviewed by the Resident Site Staff and the Environmental	

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
61121-1	Area near Lai Chi Kok Swimming Pool	21-Nov-06 (by ET Leader)	The Integrated Complaint Centre (ICC) of HKSAR received a public complaint through telephone on 18 th November 2006 regarding noise nuisance generated from Route 8 – Lai Chi Kok Viaduct R8-LCKV) Project. Resident Site Staff (RSS) subsequently referred the complaint to the ET Leader on 21 st November 2006. The complaint was concerned about noise generated from the construction works between 09:00 and 18:30 at the area near Lai Chi Kok Swimming Pool.	Team. Site Activities According to RSS's record, rebar fixing, formwork erection, placing concrete and preparation work for construction joint were carried out at the concerned site during the period of 13 th to 18 th November 2006 and the construction works within the mentioned period were occasionally finished at 18:30. As advised by the RSS, the RSS has recommended the Contractor to finish the construction works at the concerned areas before 18:00 in order to minimize the noise nuisance to the public. Environmental Monitoring During the weekly site inspections in November 2006, no noncompliance or observation on noise was recorded. Accordance to the EM&A programme, one noise monitoring station at Mei Foo Sun Chuen, Phase 5 (NM4) and two noise monitoring stations at Nob Hill, namely (NM8a and NM8b), were set up in order to monitor the noise level generated from the construction activities. The Station (NM8b) is strongly influenced by road traffic noise from Ching Cheung Road. The measurement at this station is for reference purpose, but not for compliance check for construction noise. The noise monitoring results in the period between 1 st and 21 st November 2006 at the M/F of Nob Hill and at Mei Foo Sun Chuen, Phase 5 are all lower than or equal to the noise criterion of 75 dB(A). No exceedance of noise level has been recorded in the above mentioned period. Moreover, based on our site observation record during monitoring, road traffic noise from Ching Cheung Road was the major noise source. Conclusion Base on the information collected and the monitoring results, the complaint was considered not justifiable. However, the Contractor was still reminded to finish the	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
				construction works at the concerned areas before 18:00 and to carry out construction activities only within the permitted working hours (i.e. 07:00 – 19:00 on weekday).	
				The environmental conditions of the site will be continuously reviewed by the RSS and the Environmental Team through site inspections and monitoring exercises.	
61121-2	Construction works opposite Tong Nai Kan College	21-Nov-06 (by ET Leader)	The Integrated Complaint Centre (ICC) of HKSAR received a public complaint through telephone on 17 th November 2006 regarding dust and noise nuisance generated from Route 8 – Lai Chi Kok Viaduct R8-LCKV) Project. Resident Site Staff (RSS) subsequently referred the complaint to the ET Leader on 21 st November 2006. The complaint was concerned about dust and noise generated from the construction works opposite Tong Nai Kan College in the past years.	Site Activities According to RSS's record, construction works adjacent to Tong Nai Kan College in the past years included the construction of Retaining Wall CCR-R3 and Slip Road D. As advised by the RSS, noise and dust mitigation measures such as provision of noise barriers and acoustic materials at drill pit, dust suppression system and water browser were provided in order to minimize the noise and dust nuisance generated from the above mentioned construction activities. Environmental Monitoring During the weekly site inspections in November 2006, no noncompliance or observation on noise and air at the concerned site was recorded. Accordance to the EM&A programme, one noise monitoring station at Mei Foo Sun Chuen, Phase 5 (NM4) and one air monitoring station at Lai Chi Kok Sports Centre (AM2), were set up in order to monitor the noise and dust level generated from the construction activities. The monitoring results revealed that no exceedance was recorded for the noise and air quality (1-hr and 24-hr TSP). Conclusion Base on the information collected and the monitoring results, the complaint was considered not justifiable. However, the Contractor was still reminded to continuously	Closed
				Base on the information collected and the monitoring results, the complaint was considered not justifiable.	

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
			Environmental Protection Department	acoustic materials at drill pit and applying water spraying for any dust emissive activities to minimize the noise and dust nuisance generated from these construction activities. The environmental conditions of the site will be continuously reviewed by the RSS and the Environmental Team through site inspections and monitoring exercises. Site Activities	
61205	Banyan Garden	5 th December 2006 (by ET Leader)	(EPD) received a public complaint about environment nuisance generated from Route 8 – Lai Chi Kok Viaduct Project. EPD subsequently referred the complaint to ET Leader on 5 th December 2006. The complaint was concerned construction noise near Banyan Garden within the period of 01:00 – 02:00hr on 29 th November 2006.	According to RSS's record, a catchfan was moved from bay (AL-62) to (AL-58) from 22:00 to 02:00hr. Installation of catchfan at parapet bay (MS-R-74) was carried out from 00.00 to 04:00hr on 29 th November 2006. As advised by the RSS, the Contractor has been requested to: - Wrapping of tools with acoustic material - Erection of noise barrier (mill barrier with acoustic material) adjacent to isolated noise source - Placing of hessin bags on ground to mitigate noise generated as a result of the dropping of tools on ground. According to the RSS, there is no evidence of hammering of metals on site. Conclusion Based on the information collected, the complaint is considered unjustifiable. Nevertheless, the Contractor was reminded to take sufficient noise mitigation measures to minimize the environmental impact on the nearby community: - To strengthen management on worker's working manner, such as avoiding dropping materials on ground; - No hammering is allowed during restricted hours; and - To provide adequate training to workers working, esp. for night works. The environmental conditions of the site will be continuously reviewed by the Resident Site Staff and the Environmental Team.	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
70117-1	P6 – P8 near Lai Chi Kok Road Interchange	17 th January 2007 (by ET Leader)	The Integrated Complaint Centre (ICC) of HKSAR received a public complaint through telephone on 16 th January 2007 regarding noise nuisance generated from Route 8 – Lai Chi Kok Viaduct R8-LCKV) Project. Resident Site Staff (RSS) subsequently referred the complaint to the ET Leader on 17 th January 2007. The complaint was concerned about noise generated from the P6 – P8 near Lai Chi Kok Road Interchange in the past months.	Site Activities According to RSS's record, the construction activities at the concerned area was mainly central stitch construction and parapet erection and similar works will be carried out in the concerted site in coming one month. The equipment used on site during the complaint period was covered under the construction noise permit (CNP) no. GW-RW0624-06. Based on the RSS's record of PME used in the concerned area from 15 November 2006 to 30 December 2006, the construction works complied with the CNP no. GW-RW0624-06. Conclusion Based on the information collected, the complaint is considered unjustifiable as the equipment used complied with the CNP conditions. Nevertheless, the Contractor was recommended to take further noise mitigation measures to minimize the environmental impact on the nearby community: To strengthen management on worker's working manner, such as avoiding dropping materials on ground; No hammering is allowed during restricted hours; and To provide adequate training to workers working, esp. for night works.	Closed
70117-2	P3 – P6 near Banyan Garden	17 th January 2007 (by ET Leader)	Environmental Protection Department (EPD) received a public complaint about environment nuisance generated from Route 8 – Lai Chi Kok Viaduct Project. EPD subsequently referred the complaint to ET Leader on 17 th January 2007. The complaint was concerned construction noise near Banyan Garden within the period of 01:00 – 02:00hr on 11 th January 2007.	Site Activities According to RSS's record, the construction activities at the concerned area was mainly central stitch construction and parapet erection and similar works will be carried out in the concerned site in coming one month. The equipment used on site during the complaint period was covered under the construction noise permit (CNP) no. GW-RW0624-06. Based on the RSS's record of PME used in the concerned area from 1 st December 2006 to 13 th January 2007, the construction	Closed

Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
			Conclusion Based on the information collected, the complaint is considered unjustifiable as the equipment used complied with the CNP conditions. Nevertheless, the Contractor was recommended to take further noise mitigation measures to minimize the environmental impact on the nearby community: - To strengthen management on worker's working manner, such as avoiding dropping materials on ground; - No hammering is allowed during restricted hours; and - To provide adequate training to workers working, esp. for	
Construction site near Mei Lai Road and Tong Nai Kan College	17 th July 2007 (by ET Leader)	The Integrated Complaint Centre (ICC) of HKSAR received a public complaint through telephone on 21 July 2007 about an environment nuisance generated from Route 8 – Lai Chi Kok Viaduct (R8-LCKV) Project. Resident Site Staff (RSS) subsequently referred the complaint to the Environmental Team (ET) Leader of the Project on 23 July 2007. The complaint was concerned about noise generated from the construction works near Mei Lai Road and Tong Nai Kan College.	Site Activities The concerned site was likely the Slope CCR-S4 near Ching Cheung Road. A location plan is provided in Appendix A and the work programme near Slope CCR-S4 from February 2007 to September 2007 is provided in Appendix B. According to RSS's record and the above mentioned work programme, excavation and rock breaking works for slope stabilization near the Slope CCR-S4 was begun on early of July 2007 and to be completed on early of August 2007. As advised by the RSS, noise mitigation measures implemented at the concerned site include: - installing a line of noise barriers formed by acoustic materials in front of the noise sources; - warping the breaker with acoustic material; and - deploying silence type of breaker. Environmental Monitoring During the weekly site inspections in July 2007, no noncompliance or observation on noise was recorded. Accordance to the EM&A programme, one noise monitoring	Closed
	Construction site near Mei Lai Road and Tong Nai Kan	Construction site near Mei Lai Road and Tong Nai Kan Construction site Para Mei Lai Road and Tong Nai Kan 17 th July 2007 (by ET Leader)	The Integrated Complaint Centre (ICC) of HKSAR received a public complaint through telephone on 21 July 2007 about an environment nuisance generated from Route 8 – Lai Chi Kok Viaduct (R8-LCKV) Project. Resident Site Staff (RSS) subsequently referred the complaint to the Environmental Team (ET) Leader of the Project on 23 July 2007. Construction site near Mei Lai Road and Tong Nai Kan Tong Nai Kan The Integrated Complaint Centre (ICC) of HKSAR received a public complaint through telephone on 21 July 2007 about an environment nuisance generated from Route 8 – Lai Chi Kok Viaduct (R8-LCKV) Project. Resident Site Staff (RSS) subsequently referred the complaint to the Environmental Team (ET) Leader of the Project on 23 July 2007. The complaint was concerned about noise generated from the construction works near Mei Lai Road and Tong Nai	works complied with the CNP no. GW-RW0624-06. Conclusion Based on the information collected, the complaint is considered unjustifiable as the equipment used complied with the CNP conditions. Nevertheless, the Contractor was recommended to take further noise mitigation measures to minimize the environmental impact on the nearby community: The Integrated Complaint Centre (ICC) of HKSAR received a public complaint through telephone on 21 July 2007 about an environment nuisance generated from Route 8 – Lai Chi Kok Viaduct (R8-LCKV) Project. Resident Site Staff (RSS) subsequently referred the complaint to the Environmental Team (ET) Leader of the Project on 23 July 2007. The complaint to the Environmental Team (ET) Leader of the Project on 23 July 2007. The complaint was concerned about noise generated from the construction was near Mei Lai Road and Tong Nai Kan College. The complaint was concerned about noise generated from the construction was near Mei Lai Road and Tong Nai Kan College. The complaint was concerned about noise generated from the construction was near Mei Lai Road and Tong Nai Kan College. The complaint was concerned about noise generated from the construction was near Mei Lai Road and Tong Nai Kan College. The complaint was concerned about noise generated from the construction was near Mei Lai Road and Tong Nai Kan College. The complaint was concerned about noise generated from the construction was near Mei Lai Road and Tong Nai Kan College. The complaint was concerned about noise generated from the construction was near Mei Lai Road and Tong Nai was concerned about noise generated from the construction was near Mei Lai Road and Tong Nai Was project was begun on early of July 2007 and to be completed on early of August 2007. As advised by the RSS, noise mitigation measures implemented at the concerned sits include: intalling a line of noise barriers formed by acoustic materials in front of the noise sources: warping the breaker with acoustic material; and deploying silence type of br

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
				order to monitor the noise level generated from the construction activities.	
				The noise monitoring results in the period between 3 rd and 23 rd July 2007 at Mei Foo Sun Chuen, Phase 5 are all lower than or equal to the noise criterion of 75 dB(A). No exceedance of noise level has been recorded in the above mentioned period.	
				Conclusion Base on the information collected and the monitoring result, the complaints are considered not justifiable.	
				It was suspected that the nuisance was caused by the breaking activities. However, the Contractor has implemented the mitigation measures to minimize the noise generation from construction activities.	
	Construction	0 0 1 1 0 1 1 1 0 1 1	The Integrated Complaint Centre (ICC) of HKSAR received a public complaint through telephone on 1 October 2007 about an environment nuisance generated from Route 8 – Lai Chi Kok Viaduct (R8-LCKV) Project. Resident Site Staff (RSS) subsequently referred the complaint to the Environmental Team (ET) Leader of the Project on 3 October 2007	Site Activities According to RSS's record, approximately 100m long asphalt material on carriageway was removed on 30 th September and 1 st October 2007. The equipment used on site during the complaint period was covered under the construction noise permit (CNP) no. GW-RW0469-07. Environmental Monitoring	
71003	site near Ching Cheung Road and Tong Nai Kan College	3 rd October 2007 (by ET Leader)	The complaint was concerned construction noise near Tong Nai Kan College and Ching Cheung Road during public holiday on 1st October 2007.	During the weekly site inspections in September 2007, no non-compliance or observation on noise was recorded. Accordance to the EM&A programme, one noise monitoring station at Mei Foo Sun Chuen, Phase 5 (NM4) was set up in order to monitor the noise level generated from the construction activities. The noise monitoring results on 25 September 2007 and 2 October 207 at Mei Foo Sun Chuen, Phase 5 are all lower than the noise criterion of 75 dB(A). No exceedance of noise level has been recorded in the above mentioned period	Closed

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
				Conclusion Based on the information collected, the complaint is considered unjustifiable as the equipment used complied with the CNP conditions.	
				Nevertheless, the Contractor was recommended to implement a good sit practice and mitigation measures to prevent noise nuisance generated from the construction work to minimize the environmental impact on the nearby community: - wrapping the breaker with acoustic material; and - deploying silence type of breaker.	
			The Integrated Complaint Centre (ICC) of HKSAR received a public complaint through telephone on 16 November 2007 about a noise nuisance generated from Route 8 – Lai Chi Kok Viaduct	Site Activities According to the RSS, footpath breaking by hand-held breaker was carried out on 16 November 2007. Environmental Monitoring	
			(R8-LCKV) Project. Resident Site Staff (RSS) subsequently referred the complaint to the Environmental Team	During the weekly site inspections on November 2007, no non-compliance or observation on noise was recorded.	
71119	Construction site near Nob Hill	19 th November 2007 (by ET Leader)	(ET) Leader of the Project on 19 November 2007 The complaint was concerned the noise generated from breaking the footpath on King Lai Path opposite to Nob Hill on 16 November 2007	Accordance to the EM&A programme, noise monitoring was conducted at Nob Hill M/F of Car Park (NM8a) and 3/F of Car Park (NM8b) in order to monitor the noise level generated from the construction activities. There was no Action/Limit Level exceedance identified, except the noise monitoring conducted at Station NM8b on 12 November 2007, which is strongly influenced by the road traffic noise from Ching Cheung Road. The measurements at these two stations are for reference purpose but not for compliance check for construction noise.	Closed
				Conclusion Base on the information collected and the monitoring result, the complaints are considered not justifiable.	
				Nevertheless, the Contractor was recommended to implement a good sit practice and mitigation measures to prevent noise nuisance generated from the construction work to minimize the environmental impact on the nearby community: - wrapping the breaker with acoustic material; and	

Log Ref.	Location	Received Date	Details of Complaint	Investigation/Mitigation Action	Status
				deploying silence type of breaker.	
71121	Construction site at Lai Wan Road opposite to the Lai Chi Kok Park Sports Centre	21st November 2007 (by ET Leader)	The Integrated Complaint Centre (ICC) of HKSAR received a public complaint through telephone on 21 st November 2007 about the construction dust nuisance generated from Route 8 – Lai Chi Kok Viaduct (R8-LCKV) Project. Resident Site Staff (RSS) subsequently referred the complaint to the Environmental Team (ET) Leader of the Project on 21 st November 2007 The complaint was raised by a resident via the ICC hotline and EPD about the construction dust generated from the lorry (JA2315) leaving the works site opposite to Lai Chi Kok Park Sports Centre at 8.35am on 21 st November 2007	Site Activities According to the information provided by RSS, the site of the concern was likely to be the site access at R2 opposite to Lai Chi Kok Park Sports Centre. The construction works at the sports centre included the masonry on retaining wall, surface drain along slope toe, road work at the footpath, street furniture and reinstatement the pavement. Environmental Monitoring During the weekly site inspection on 21 November 2007, no non-compliance or major dust generation construction activity was recorded. Accordance to the EM&A programme, the air monitoring station at Lai Chi Kok Sports Centre (AM2), was set up in order to monitor the dust level generated from the construction activities. There was no exceedance of the air quality monitoring results and dust mitigation measures were implemented by the Contractor. Conclusion Base on the information collected and the monitoring results, the complaints are considered not justifiable. It was because there was no exceedance of the air quality monitoring results. After receiving the complaint, the Contractor has further enhanced the dust mitigation measures as follows: • Spraying of water for any dust emissive activities; The environmental conditions of the site will be continuously reviewed by the RSS and the Environmental Team through site inspections and monitoring exercises.	Closed