<u>Photo Records for the Repairing of Deteriorated Cracks on Existing Concrete Ground Slab</u> during the reporting month











