

JOB NO.: TCS00491/09

DSD CONTRACT NO.: DC/2009/08

CONSTRUCTION OF YUEN LONG SOUTH BRANCH SEWERS AND EXPANSION OF HA TSUEN SEWAGE PUMPING STATION

THE NINTH RESULTS OF LANDSCAPE AND VISUAL IMPACT MONITORING FOR OCTOBER 2010 (NO.9)

PREPARED FOR

CHINA STATE CONSTRUCTION ENGINEERING (HONG KONG) COMPANY LIMITED

## **Quality Index**

Date	Reference No.	Prepared By	Certified By
17 Oct 2011	TCS00491/09/600/R00290v1	Wong Fu Nam (Senior Environmental Consultant)	T.W. Tam (Environmental Team Leader)
		W/m A	Imm

Version	Date	Description
1	17 Oct 2011	First submission

This report has been prepared by Action-United Environmental Services & Consulting with all reasonable skill, care and diligence within the terms of the Agreement with the client, incorporating our General Terms and Conditions of Business and taking account of the resources devoted to it by agreement with the client. We disclaim any responsibility to the client and others in respect of any matters outside the scope of the above. This report is confidential to the client and we accept no responsibility of whatsoever nature to third parties to whom this report, or any part thereof, is made known. Any such party relies upon the report at their own risk.

#### 安誠工程顧問有限公司 香港灣仔 皇后大道東183號 合和中心47樓 電話:(852)29112233 傳真:(852)28055028

Hyder Consulting Limited

Company Number 126012 47th Floor, Hopewell Centre 183 Queen's Road East Wan Chai, Hong Kong Tel: (852) 2911 2233 Fax: (852) 2805 5028 hyder.hk@hyderconsulting.com www.hyderconsulting.com



27 October 2011

By Post

Action-United Environmental Services & Consulting Unit A, 20/F, Gold King Industrial Building, 35-41 Tai Lin Pai Road, Kwai Chung, New Territories, Hong Kong.

For attention of: Mr. T. W. Tam

#### Your Ref:

Our Ref: EB000586-F/THW11-2558

Dear Mr. Tam.

#### Contract No.: DC/2009/08 Construction of Yuen Long South Branch Sewers and Expansion of Ha Tsuen Sewage Pumping Station <u>Monthly EM&A Report for Designated Project, Landscape and Visual Impact Sections, July</u> 2010 to March 2011 – IEC Verification

With reference to ET's captioned Landscape and Visual Impact section of monthly EM&A reports for nine reporting months, July 2010 to March 2011 inclusive (ET's ref.: TCS00491/09/600/R0287v1, TCS00491/09/600/R0288v1, TCS00491/09/600/R0299v1, TCS00491/09/600/R0291v1, TCS00491/09/600/R0292v1, TCS00491/09/600/R0295v1, TCS00

Should there be any queries, please feel free to contact our William Law on 2911 2511.

Yours sincerely

Itan Jaroleon

F.C. TSANG Independent Environmental Checker HYDER CONSULTING LIMITED

FCT/WL/my

# ber 2010 (No.9)

1

1

## TABLE OF CONTENTS

## 1. INTRODUCTION

## 2. CONTENT OF THE LVIM RESULTS

APPENDIXA SITE INSPECTION CHECKLIST



### 1. INTRODUCTION

- 1.01 This Results of Landscape and Visual Impact Monitoring (hereinafter "the LVIM Results") is part of the monthly EM&A report under DSD Contract No.: DC/2009/08 Construction of Yuen Long South Branch Sewers and Expansion of Ha Tsuen Sewage Pumping Station: *Results of Landscape and Visual Impact* of Chapter 4 *Impact Monitoring Results*. The LVIM Results should therefore be read in conjunction with the corresponding monthly EM&A reports.
- 1.02 Pursuant to Chapter 6 *Landscape and Visual* of the EM&A Manual, EM&A for landscape and visual resources is considered to be a key aspect during both the construction and operational phases of the Project. The implementation and maintenance of landscape compensatory planting measures should therefore be checked to ensure that they are fully realized and that potential conflicts between the proposed landscape measures and any other project works and operational requirements are resolved at the earliest possible date and without compromise to the intention of the mitigation measures.
- 1.03 Monitoring of the recommended implementation of the mitigation measures is required to be conducted throughout the construction phase of the Project.
- 1.04 As a member of the ET, the landscape architect is responsible for the implementation of landscape construction works and subsequent maintenance operations during the 12 month establishment period. The establishment works should be undertaken throughout the Contractor's one year maintenance period which will be within the first operational year of the Project.
- 1.05 All measures undertaken by both the Contractor and the Landscape Contractor during the construction phase and first year of the operational phase should be audited by the landscape architect on a regular basis to ensure compliance with the intended aims of the measures.
- 1.06 Site inspections should be undertaken at least once every two weeks throughout the construction period and once every two months during the operational phase.
- 1.07 The LVIM Results has been prepared by the landscape architect and compiled by the ET upon receipt for submission to EPD after verification by the IEC.
- 1.08 To cater to closer compliance of the EM&A reporting with the EP requirements, it has been agreed among the RE, IEC and ET that The LVIM Results is submitted separately as a stand-alone submission.
- 1.09 This is the ninth (No. 9) LVIM Results, covering the construction period from 1 to 30 October 2010 (hereinafter "the Result Period").

#### CONTENT OF THE LVIM RESULTS

- 2.01 This LVIM Results contains the site inspection checklist for the Result Period, where landscape and visual impact monitoring results are presented and where necessary, the associated recommendations are included.
- 2.02 The site inspection checklist is enclosed in *Appendix A*.



Appendix A

Site Inspection Checklist

 $\label{eq:list} Z:Jobs\2009\TCS00491\DC-2009-08)\600\EM\&A\Monthly\Report\LVIA\Oct\2010\R0290v1.doc\Action-United\ Environmental\ Services\ and\ Consulting$ 

## Landscape and Visual Impact Assessment Site Inspection Checklist

		Site Inspection Cl	hecklist	t			
Co	ntract No.:	DC/2009/08					
Co	ontract title:	Construction of Yuen Long South Sewer and Expansion	n of Ha Ta	suen Sew	age Pum	ping Station	
Co	ontractor:	China State Construction Engrg. (HK) Ltd.					
Lo	cation:	Ha Tsuen Sewage Pumping Station					
Ins	spection Date:	15-Oct-2010					
-			S	Satisfacto	ry	Rectified	
		144	N/A	Yes	No	Yes No	Remarks
1. 0	General						
1.	Erect hoardin	g around site boundary properly		$\checkmark$			
2.	Keep well ma	intenance of hoarding		$\checkmark$			
3.	All constructi	ion works are carried out within site boundary properly		$\checkmark$			
4	Carry out the	initial tree survey prior to construction		$\checkmark$			
5	Provide tree l	abels according to tree survey records		$\checkmark$			
Co	mments:						
Sta	ndard hoarding	was erected and well maintained around the works area a	it Ha Tsue	en Sewag	e Pumpin	ng Station (HTSPS	5).
All	trees were labe	lled as requirement.			_		
П.	Transplanting	Works					
1.	All transplant specifications	ting works are carried out in accordance with the		$\checkmark$		$\square$	
2.	The transplanet	ted trees are kept in regular inspection within the period	$\checkmark$				ltem 1
3.	The transplan	ted trees are kept in maintenance thoughout the estanlish	iment peri	od as fol	lowings:		
	(i) Watering			$\checkmark$		$\checkmark$ $\Box$ .	
	(ii) Weeding			$\checkmark$		$\square$	
	(iii) Fertilisin	g	$\checkmark$	1		$\Box$ $\Box$ .	
	(iv) Littering			1		$\checkmark$ $\Box$ .	
	(v) Grass cutt	ing		$\checkmark$		$\checkmark$	
	(vi) Firming	qu		$\checkmark$			
	(vii) Pest con	trol	$\checkmark$				
	(viii) Disease	control		$\checkmark$			
	(ix) Pruning			$\checkmark$			
	(x) Replacem	ent	$\checkmark$				
Co	omments:						
Th	ere had total 73	nos. of transpalnted trees in Ha Tsuen Sewage Pumping	Station du	ie to cons	struction	works under this c	contract.
Wa	atering and wee	ding should be undertaking periodically.					
Ш	. Landscaping	Works					
1.	All landscapi specifications	ng works are carried out in accordance with the		$\checkmark$			

2. The landscaping plants are kept in regular inspection within the establishment period

 $\checkmark$ 

E

## Landscape and Visual Impact Assessment Site Inspection Checklist

		Satisfactory		Rec	tified		
		N/A	Yes	No	Yes	No	Remarks
3.	The landscaping plants are kept in maintenance thoughout the estanlish	iment per	riod as fo	llowings			
	(i) Watering		$\checkmark$		$\checkmark$		
	(ii) Weeding		$\checkmark$		$\checkmark$	$\Box$ .	
	(iii) Fertilising		1		$\checkmark$		
	(iv) Littering		$\checkmark$		$\checkmark$		
	(v) Grass cutting		$\checkmark$		$\checkmark$	$\Box$ .	
	(vi) Firming up		$\checkmark$		$\checkmark$		
	(vii) Pest control		$\checkmark$		$\checkmark$	$\Box$ .	
	(viii) Disease control		$\checkmark$		$\checkmark$	$\Box$ .	
	(ix) Pruning		$\checkmark$		$\checkmark$	$\Box$ .	(
	(x) Replacement		$\checkmark$		$\checkmark$	$\Box$ .	
Cor	nments:						
No	landscaping works were carried out in the reporting month						
v.	Preservation and Protection of Trees						
1	All preserved trees are protected in accordance with the specifications		$\checkmark$		$\checkmark$	□.	
	All preserved trees are fenced off properly		$\checkmark$		$\checkmark$		
3.	No construction activities are carried out in the protection zone of the preserved trees		$\checkmark$		$\checkmark$	□.	
Cor	nments:						
A11	retained trees were fenced off and protected properly within the works are	ea of the	site.				
Ke	ep in review of the piling works with the impacts on the retained trees wit	thin the v	vorks are	a.			
7.07	volucion						
	nclusion nerally, the overall conditions are normal in the transplanting and visual ir	manat at	Uo Tou	Courses	Dummin	or Station	The condition

conditions of some transplanted trees should be reviewed in the regular inspection as per attached. We are found out the trees was dead

in HSPS, We are monitoring health of the tree regularly and continuous to make protection for the the tree.

## Remarks

1. The regular inspection for the tranplanted trees was scheduled at the end of the reporting month.

Tree Nos.	Health	Tree Form	Comments	Suggested treatment
HA260	Poor	Poor	Dying	Water more frequently
HA265	Poor	Poor	Dying	Water more frequently
HA245	Dead	Dead	Removed from the site	To plant a new tree
T3519	Dead	Dead	Removed from the site	To plant a new tree
T3591	Dead	Dead	Removed from the site	To plant a new tree
T3596	Dead	Dead	Removed from the site	To plant a new tree

Signatures:

Senior Landscape Architect

V NZ 1

(Name: David Bloxham MLI (UK Chartered))

Cor	ntract No.:	DC/2009/08					
Contract title: Contractor:		Construction of Yuen Long South Sewer and Expansio	n of Ha T	suen Sew	age Pum	ping Station	
		China State Construction Engrg. (HK) Ltd.					
Location:	Ha Tsuen Sewage Pumping Station						
Insp	pection Date:	31-Oct-2010					
-			S	Satisfacto	ry	Rectified	1
			N/A	Yes	No	Yes No	Remarks
I. G	eneral		723	1.0	- 1	1.2.2.4	4
1,	Erect hoardin	g around site boundary properly		~		$\checkmark$	],
2.	Keep well ma	intenance of hoarding		$\checkmark$			]
3.	All construct	ion works are carried out within site boundary properly		$\checkmark$			]
4	Carry out the	initial tree survey prior to construction		$\checkmark$			]
5	Provide tree l	abels according to tree survey records		$\checkmark$			]
Con	nments:						
Star	ndard hoarding	was erected and well maintained around the works area a	nt Ha Tsue	en Sewag	e Pumpir	ng Station (H	TSPS).
The	contruction ha	as no implication to protected tree. Close monitoring the i	mplication	n of pilin	g works t	to protected t	ree is required
11. 1	Fransplanting	Works					
1.	All transplant specifications	ting works are carried out in accordance with the		$\checkmark$			]
2.	The transplar	nted trees are kept in regular inspection within the	$\checkmark$				Item 1

3. The transplanted trees are kept in maintenance thoughout the estanlishment period as followings:

(i) Watering	
(ii) Weeding	
(iii) Fertilising	
(iv) Littering	
(v) Grass cutting	
(vi) Firming up	
(vii) Pest control	
(viii) Disease control	
(ix) Pruning	
(x) Replacement	

Comments:

There had total 73 nos. of transpalnted trees in Ha Tsuen Sewage Pumping Station due to construction works under this contract.

Watering should be undertaking periodically. More pruning for die branch is required

Ш	<ul> <li>III. Landscaping Works</li> <li>1. All landscaping works are carried out in accordance with the specifications</li> </ul>				
1.			V		
2.	The landscaping plants are kept in regular inspection within the establishment period				

		Satisfactory		Rectified					
		N/A	Yes	No	Yes	No	Remarks		
3.	The landscaping plants are kept in maintenance thoughout the estanlishment period as followings:								
	(i) Watering		$\checkmark$		$\checkmark$		_		
	(ii) Weeding		1		$\checkmark$				
	(iii) Fertilising		$\checkmark$		$\checkmark$				
	(iv) Littering		$\checkmark$		$\checkmark$				
	(v) Grass cutting		$\checkmark$		$\checkmark$				
	(vi) Firming up		$\checkmark$		$\checkmark$				
	(vii) Pest control		$\checkmark$		$\checkmark$		-		
	(viii) Disease control		$\checkmark$		$\checkmark$				
	(ix) Pruning		$\checkmark$		$\checkmark$				
	(x) Replacement		$\checkmark$		$\checkmark$		<u> </u>		
Co	nments:								
No	landscaping works were carried out in the reporting month								
IV.	Preservation and Protection of Trees			-					
1.	All preserved trees are protected in accordance with the specifications		$\checkmark$		$\checkmark$				
2.	All preserved trees are fenced off properly		1		$\checkmark$				
3.	No construction activities are carried out in the protection zone of the preserved trees						-		
	nments:								
Co									


Generally, the overall conditions are normal in the transplanting and visual impact at Ha Tsuen Sewage Pumping Station. The cond of hoarding was satisfactory. The protection works maintained for the transplanted and the preserved trees. The health conditions of the transplanted trees should be reviewed in the regular inspection in the establishment period. Some of the die branch need to remove and frequency watering is required


Remarks

Signatures:

Senior Landscape Architect

## (Name; David Bloxham MLI (UK Chartered))










HA260





Contract No. DC/2009/08 Yuen Long South sewerage and expansion of Ha Tsuen sewage pumping station Watering report for October 2010



Hong Kong Landscaping Co. Ltd.

Contract No. DC/2009/08 Yuen Long South sewerage and expansion of Ha Tsuen sewage pumping station Watering report for October 2010





Hong Kong Landscaping Co. Ltd.