

<u>Landscape and Visual Impact Assessment Checklist for Site Audit – North Point PTW</u>

Inspection Date: 28 March, 2022 Weather: <u>Sunny/ Fine/ Cloudy / Rainy</u>
Time: 10:00 am Wind: <u>Strong/ Breeze/ Light/-Calm</u>

Item	Description	Yes	No	N/A	Actions / Remarks
1	Aesthetic design of the façade of PTW and associated structures to harmonize with the surrounding settings				
1.1	Is the aesthetic design match the surrounding environment?	√			
1.2	Are the buildings maintained properly that do not cause any visual impact?	✓			
2	Shrub and Climbing Plants to soften proposed structures / Roof Greening / Vertical Greening				
2.1	Is the roof greening maintained properly?			✓	
2.2	Is the vertical greening maintained properly?			√	
2.3	Are the Shrub and Climbing Plants free from sign of deterioration of health?	√			
3	Buffer Tree and Shrub Planting to screen proposed associated structures				
3.1	Are the health of those buffer trees and shrub plantings generally in order?	√			
3.2	Is all new planting maintained properly to ensure further establishment?	√			
4	Reinstatement of disturbed area				
4.1	Are the compensated planting covered the disturbed area?			✓	
5	Others				
5.1	Are existing trees retained on-site are being well preserved?	√			
5.2	Are newly planted vegetations are being generally maintained during the establishment period (12 months)?	_			



Follow up action taken by Contractor for previous comments:

- No visible irregularities were found

The contractor was reminded to rectify the following:

- N/A


New Observation:

- N/A

Reminders:

- Contractor was reminded to carry out proper maintenance to plantings.

Photo Record:



		Signature	Date
Inspected & Recorded by	Registered Landscape Architect	Xylem"	4 th April 2022



<u>Landscape and Visual Impact Assessment Checklist for Site Audit – Ap Lei Chau PTW</u>

Inspection Date: 28 March, 2022 Weather: <u>Sunny/ Fine/-Cloudy / Rainy</u>
Time: 10:43am Wind: <u>Strong/ Breeze/ Light/-Calm</u>

Item	Description	Yes	No	N/A	Actions / Remarks
1	Aesthetic design of the façade of PTW and associated structures to harmonize with the surrounding settings				
1.1	Is the aesthetic design match the surrounding environment?	√			
1.2	Are the buildings maintained properly that do not cause any visual impact?	√			
2	Shrub and Climbing Plants to soften proposed structures / Roof Greening / Vertical Greening				
2.1	Is the roof greening maintained properly?	✓			
2.2	Is the vertical greening maintained properly?			√	
2.3	Are the Shrub and Climbing Plants free from sign of deterioration of health?	>			
3	Buffer Tree and Shrub Planting to screen proposed associated structures				
3.1	Are the health of those buffer trees and shrub plantings generally in order?	√			
3.2	Is all new planting maintained properly to ensure further establishment?	✓			
4	Reinstatement of disturbed area				
4.1	Are the compensated planting covered the disturbed area?			1	
5	Others				
5.1	Are existing trees retained on-site are being well preserved?	✓			
5.2	Are newly planted vegetations are being generally maintained during the establishment period (12 months)?	-			



Follow up action taken by Contractor for previous comments:

- No visible irregularities were found

The contractor was reminded to rectify the following:

- N/A


New Observation:

- N/A

Reminders:

- Contractor was reminded to carry out proper maintenance to plantings and recommended to increase the frequency of watering.

Photo Record:



		Signature	Date
Inspected & Recorded by	Registered Landscape Architect	Xylem*	4 th April 2022



<u>Landscape and Visual Impact Assessment Checklist for Site Audit – Wa Fu PTW</u>

Inspection Date: 28 March, 2022 Weather: <u>Sunny/ Fine/ Cloudy / Rainy</u>
Time: 11:05 am Wind: <u>Strong/ Breeze/ Light/-Calm</u>

Item	Description	Yes	No	N/A	Actions / Remarks
1	Aesthetic design of the façade of PTW and associated structures to harmonize with the surrounding settings				
1.1	Is the aesthetic design match the surrounding environment?	√			
1.2	Are the buildings maintained properly that do not cause any visual impact?	✓			
2	Shrub and Climbing Plants to soften proposed structures / Roof Greening / Vertical Greening				
2.1	Is the roof greening maintained properly?			✓	
2.2	Is the vertical greening maintained properly?			√	
2.3	Are the Shrub and Climbing Plants free from sign of deterioration of health?	√			
3	Buffer Tree and Shrub Planting to screen proposed associated structures				
3.1	Are the health of those buffer trees and shrub plantings generally in order?	√			
3.2	Is all new planting maintained properly to ensure further establishment?	√			
4	Reinstatement of disturbed area				
4.1	Are the compensated planting covered the disturbed area?			✓	
5	Others				
5.1	Are existing trees retained on-site are being well preserved?	✓			
5.2	Are newly planted vegetations are being generally maintained during the establishment period (12 months)?	_			



Follow up action taken by Contractor for previous comments:

- No visible irregularities were found

The contractor was reminded to rectify the following:

- N/A


New Observation:

- N/A

Reminders:

- Contractor was reminded to carry out proper maintenance to plantings.

Photo Record:



		Signature	Date
Inspected & Recorded by	Registered Landscape Architect	Xylem*	4 th April 2022



<u>Landscape and Visual Impact Assessment Checklist for Site Audit – Aberdeen PTW</u>

Inspection Date: 28 March, 2022 Weather: <u>Sunny/ Fine/-Cloudy / Rainy</u>
Time: 10:55 am Wind: <u>Strong/ Breeze/ Light/-Calm</u>

Item	Description	Yes	No	N/A	Actions / Remarks
1	Aesthetic design of the façade of PTW and associated structures to harmonize with the surrounding settings				
1.1	Is the aesthetic design match the surrounding environment?	√			
1.2	Are the buildings maintained properly that do not cause any visual impact?	√			
2	Shrub and Climbing Plants to soften proposed structures / Roof Greening / Vertical Greening				
2.1	Is the roof greening maintained properly?			✓	
2.2	Is the vertical greening maintained properly?			√	
2.3	Are the Shrub and Climbing Plants free from sign of deterioration of health?	>			
3	Buffer Tree and Shrub Planting to screen proposed associated structures				
3.1	Are the health of those buffer trees and shrub plantings generally in order?	>			
3.2	Is all new planting maintained properly to ensure further establishment?	√			
4	Reinstatement of disturbed area				
4.1	Are the compensated planting covered the disturbed area?			✓	
5	Others				
5.1	Are existing trees retained on-site are being well preserved?	✓			
5.2	Are newly planted vegetations are being generally maintained during the establishment period (12 months)?	-			



Follow up action taken by Contractor for previous comments:

- No visible irregularities were found

The contractor was reminded to rectify the following:

- N/A


New Observation:

- N/A

Reminders:

- Contractor was reminded to carry out proper maintenance to plantings.

Photo Record:



		Signature	Date
Inspected & Recorded by	Registered Landscape Architect	Xylem*	4 th April 2022



<u>Landscape and Visual Impact Assessment Checklist for Site Audit – Cyberport PTW</u>

Inspection Date: 28 March, 2022 Weather: <u>Sunny/ Fine/-Cloudy/ Rainy</u>
Time: 11:15 am Wind: <u>Strong/ Breeze/-Light/-Calm</u>

Item	Description	Yes	No	N/A	Actions / Remarks
1	Aesthetic design of the façade of PTW and associated structures to harmonize with the surrounding settings				
1.1	Is the aesthetic design match the surrounding environment?	√			
1.2	Are the buildings maintained properly that do not cause any visual impact?	√			
2	Shrub and Climbing Plants to soften proposed structures / Roof Greening / Vertical Greening				
2.1	Is the roof greening maintained properly?	✓			
2.2	Is the vertical greening maintained properly?			√	
2.3	Are the Shrub and Climbing Plants free from sign of deterioration of health?	√			
3	Buffer Tree and Shrub Planting to screen proposed associated structures				
3.1	Are the health of those buffer trees and shrub plantings generally in order?	√			
3.2	Is all new planting maintained properly to ensure further establishment?	√			
4	Reinstatement of disturbed area				
4.1	Are the compensated planting covered the disturbed area?			√	
5	Others				
5.1	Are existing trees retained on-site are being well preserved?	√			
5.2	Are newly planted vegetations are being generally maintained during the establishment period (12 months)?	_			



Follow up action taken by Contractor for previous comments:

- No visible irregularities were found

The contractor was reminded to rectify the following:

- N/A


New Observation:

- N/A

Reminders:

- Contractor was reminded to carry out proper maintenance to plantings and removal of weeds.

Photo Record:



		Signature	Date
Inspected & Recorded by	Registered Landscape Architect	Xylem*	4 th April 2022



<u>Landscape and Visual Impact Assessment Checklist for Site Audit – Sandy Bay PTW</u>

Inspection Date: 28 March, 2022 Weather: <u>Sunny/ Fine/ Cloudy/ Rainy</u>
Time: 11:20 pm Wind: <u>Strong/ Breeze/ Light/-Calm</u>

Item	Description	Yes	No	N/A	Actions / Remarks
1	Aesthetic design of the façade of PTW and associated structures to harmonize with the surrounding settings				
1.1	Is the aesthetic design match the surrounding environment?	√			
1.2	Are the buildings maintained properly that do not cause any visual impact?	>			
2	Shrub and Climbing Plants to soften proposed structures / Roof Greening / Vertical Greening				
2.1	Is the roof greening maintained properly?			√	
2.2	Is the vertical greening maintained properly?			√	
2.3	Are the Shrub and Climbing Plants free from sign of deterioration of health?	>			
3	Buffer Tree and Shrub Planting to screen proposed associated structures				
3.1	Are the health of those buffer trees and shrub plantings generally in order?	√			
3.2	Is all new planting maintained properly to ensure further establishment?	√			
4	Reinstatement of disturbed area				
4.1	Are the compensated planting covered the disturbed area?			✓	
5	Others				
5.1	Are existing trees retained on-site are being well preserved?	✓			
5.2	Are newly planted vegetations are being generally maintained during the establishment period (12 months)?	-			



Follow up action taken by Contractor for previous comments:

- No visible irregularities were found

The contractor was reminded to rectify the following:

- N/A


New Observation:

- N/A

Reminders:

- Contractor was reminded to carry out proper maintenance to plantings and recommended to increase the frequency of watering.

Photo Record:



		Signature	Date
Inspected & Recorded by	Registered Landscape Architect	Xylem"	4 th April 2022



<u>Landscape and Visual Impact Assessment Checklist for Site Audit – Central PTW</u>

Inspection Date: 28 March, 2022 Weather: <u>Sunny/ Fine/-Cloudy/ Rainy</u>
Time: 11:40 pm Wind: <u>Strong/ Breeze/ Light/-Calm</u>

Item	Description	Yes	No	N/A	Actions / Remarks
1	Aesthetic design of the façade of PTW and associated structures to harmonize with the surrounding settings				
1.1	Is the aesthetic design match the surrounding environment?	√			
1.2	Are the buildings maintained properly that do not cause any visual impact?	✓			
2	Shrub and Climbing Plants to soften proposed structures / Roof Greening / Vertical Greening				
2.1	Is the roof greening maintained properly?	✓			
2.2	Is the vertical greening maintained properly?			√	
2.3	Are the Shrub and Climbing Plants free from sign of deterioration of health?	>			
3	Buffer Tree and Shrub Planting to screen proposed associated structures				
3.1	Are the health of those buffer trees and shrub plantings generally in order?	√			
3.2	Is all new planting maintained properly to ensure further establishment?	✓			
4	Reinstatement of disturbed area				
4.1	Are the compensated planting covered the disturbed area?			1	
5	Others				
5.1	Are existing trees retained on-site are being well preserved?	✓			
5.2	Are newly planted vegetations are being generally maintained during the establishment period (12 months)?	-			



Follow up action taken by Contractor for previous comments:

- No visible irregularities were found

The contractor was reminded to rectify the following:

- N/A


New Observation:

- N/A

Reminders:

- Contractor was reminded to carry out proper maintenance to plantings.

Photo Record:



		Signature	Date
Inspected & Recorded by	Registered Landscape Architect	Xylem*	4 th April 2022



<u>Landscape and Visual Impact Assessment Checklist for Site Audit – Wan Chai PTW</u>

Inspection Date: 28 March, 2022 Weather: <u>Sunny/ Fine/ Cloudy / Rainy</u>
Time: 12:05 pm Wind: <u>Strong/ Breeze/ Light/-Calm</u>

Item	Description	Yes	No	N/A	Actions / Remarks
1	Aesthetic design of the façade of PTW and				
	associated structures to harmonize with				
	the surrounding settings				
1.1	Is the aesthetic design match the	√			
	surrounding environment?				
1.2	Are the buildings maintained properly that	√			
	do not cause any visual impact?				
2	Shrub and Climbing Plants to soften				
	proposed structures / Roof Greening / Vertical Greening				
2.1	Is the roof greening maintained properly?	√			
2.2	Is the vertical greening maintained properly?			✓	
2.3	Are the Shrub and Climbing Plants free from	√			
	sign of deterioration of health?	•			
3	Buffer Tree and Shrub Planting to screen				
	proposed associated structures				
3.1	Are the health of those buffer trees and	\			
	shrub plantings generally in order?				
3.2	Is all new planting maintained properly to	√			
	ensure further establishment?				
4	Reinstatement of disturbed area				
4.1	Are the compensated planting covered the			✓	
	disturbed area?				
5	Others				
5.1	Are existing trees retained on-site are being	✓			
	well preserved?				
5.2	Are newly planted vegetations are being generally maintained during the establishment period (12 months)?	_			



Follow up action taken by Contractor for previous comments:

- No visible irregularities were found

The contractor was reminded to rectify the following:

- N/A


New Observation:

- N/A

Reminders:

- Contractor was reminded to carry out proper maintenance to plantings and recommended to provide adequate protection to trees adjacent to works area.

Photo Record:



		Signature	Date
Inspected & Recorded by	Registered Landscape Architect	Xylem*	4 th April 2022



<u>Landscape and Visual Impact Assessment Checklist for Site Audit – Stonecutters PTW</u>

Inspection Date: 28 March, 2022 Weather: <u>Sunny/ Fine/ Cloudy-/ Rainy</u>
Time: 12:40 pm Wind: <u>Strong/ Breeze/ Light/- Calm</u>

Item	Description	Yes	No	N/A	Actions / Remarks
1	Aesthetic design of the façade of PTW and				
	associated structures to harmonize with				
	the surrounding settings				
1.1	Is the aesthetic design match the	✓			
	surrounding environment?				
1.2	Are the buildings maintained properly that	✓			
	do not cause any visual impact?				
2	Shrub and Climbing Plants to soften				
	proposed structures / Roof Greening / Vertical Greening				
2.1	Is the roof greening maintained properly?	√			
2.2	Is the vertical greening maintained properly?			√	
2.3	Are the Shrub and Climbing Plants free from	√			
	sign of deterioration of health?				
3	Buffer Tree and Shrub Planting to screen				
	proposed associated structures				
3.1	Are the health of those buffer trees and	√			
	shrub plantings generally in order?				
3.2	Is all new planting maintained properly to	✓			
	ensure further establishment?				
4	Reinstatement of disturbed area				
4.1	Are the compensated planting covered the			✓	
	disturbed area?				
5	Others				
5.1	Are existing trees retained on-site are being	√			
	well preserved?				
5.2	Are newly planted vegetations are being generally maintained during the establishment period (12 months)?	-			



Follow up action taken by Contractor for previous comments:

- No visible irregularities were found

The contractor was reminded to rectify the following:

- N/A

New Observation:

- N/A

Reminders:

- Contractor was reminded to carry out proper maintenance to plantings and recommended to check any broken branches at trees along roadside.

Photo Record:



		Signature	Date
Inspected & Recorded by	Registered Landscape Architect	Xylem*	4 th April 2022