



Figure 3: Positions of Sub-seabed Anomalies at SS1 and SS2 (Reproduced based on Figure 9.10 in EIA Report)

圖 3：海床下於 SS1 及 SS2 出現異常跡象的位置圖

Environmental Permit No.: EP-262/2007/A

環境許可證編號：EP-262/2007/A

