



Figure 2a  
圖二 a

Liantang/Heung Yuen Wai Boundary Control Point and Associated Works (蓮塘/香園圍口岸與相關工程)  
Location of Woodland Compensation Area (林地補償地區位置)

This figure was prepared based on Figure 9.26 of the EIA Report (Register No.: AEIAR-161/2011)  
本圖是根據環境影響評估報告(登記冊編號: AEIAR-161/2011)圖 9.26 編制

Environmental Permit No. EP-404/2011/B  
環境許可證編號 EP-404/2011/B

