

Photomontage Viewpoint Location




Shui Wing Steelmill

Existing Condition from vpt.3.2 -SVR 3

CED Reclamation Site

Fuel Tanks Phase 2005

Concrete Bundwall



Photomontage of the proposed PAFF at Operation Day 1 (Year 2005) with unmitigated impacts, vpt.3.2 -SVR 3