



LEGEND

■ ASSUMED WORST LOCATIONS OF VENTILATION SHAFT OPENING:
(TUNG YING BUILDING - EITHER WEST OR SOUTH SIDE;
HOTEL MIRAMAR - WEST SIDE ONLY)

NOTE

THE EXACT LOCATION OF VENTILATION SHAFT WILL BE CONFIRMED PRIOR TO THE COMMENCEMENT OF THE CONSTRUCTION

MTR

SCALE	1:500	FIGURE NO.	4.4
CAD REF.	(A3)	DRAWING NO.	
	Fig. 4-3.dgn	REV.	A

NEX/1034 TSIM SHA TSUI NORTHERN SUBWAY

ASSUMED WORST LOCATIONS OF VENTILATION SHAFT OPENINGS

MAUNSELL | AECOM in association with
MTRC, Aedas, MVA

Maunsell Consultants Asia Ltd.
茂盛(亞洲)工程顧問有限公司