



Plate 1
Majority of the dwellings in Hang Hau Tsuen are tin-sheeted and/or wooden structures on low-lying land. (red arrow indicates localized flooding of footpath due to over-topping of stream water during high tide)



Plate 2
Polluted water from upstream San Hing Tsuen Channel.



Plate 3
Polluted water from upstream Fung Kong Tsuen Channel.



Plate 4
Water from San Hing Tsuen Channel and Fung Kong Tsuen Channel merges and drains into Hang Hau Tsuen stream via a single cell box culvert underneath Deep Bay Road.



Plate 5
Mangroves found along Hang Hau Tsuen stream.



Plate 6
Container yards near the Project area.



Plate 7
Abandoned fishpond within the Coastal Protection Area zone.



Plate 8
Inter-tidal mudflats and clusters of mangrove stands along the Deep Bay coastline.



Plate 9
Localised flooding within Hang Hau Tsuen during high tide.



Plate 10
Collapsed footbridge (16 June 2008).



Plate 11
Collapsed footbridge (16 June 2008).