

Drilling Machine

Geological Fault

Grout Curtain formed through Pressure Grouting

Drillhole Packer

Inclined Drillholes

Schematic Section

Ground Treatment of Faults –
at edge of Landfill Boundary

Landfill Liner

Concrete / Shotcrete Plug

Small area of over-excavation

Geological Fault

Schematic Section

Ground Treatment of Faults –
within Landfill Boundary

Rev	Description	By	Date
-	FIRST ISSUE	PM	01/09

Consultant
ARUP 奧雅納工程顧問
 Ove Arup & Partners Hong Kong Limited

Project title
 Agreement No. CE 43/2006 (EP)
 West New Territories (WENT)
 Landfill Extensions
 Feasibility Study

Drawing title

MITIGATION MEASURES
 (SEALING OF FAULT LINE)

Drawing no. **FIGURE 7.5** Rev. -

Drawn CN	Date 01/09	Checked PM	Approved FW
Scale N.T.S.	Status PRELIMINARY		

COPYRIGHT RESERVED

環境保護署
 廢物設施組
 Environmental Protection Department
 Waste Facilities Group