



**Agreement CE 63/2008 (CE)
Providing Sufficient Water Depth for Kwai Tsing Container
Basin and its Approach Channel**

Environmental Impact Assessment (Final)

Volume 2 of 4 - Figures

July 2010

Civil Engineering and Development Department

**Agreement CE 63/2008 (CE)
Providing Sufficient Water Depth for Kwai Tsing Container
Basin and its Approach Channel**

Environmental Impact Assessment (Final)
Volume 2 of 4 - Figures

July 2010

Civil Engineering and Development Department

3/F Civil Engineering and Development Building, 101 Princess Margaret Road, Homantin

Content

Figures

Figure 2.1	Project Layout	Figure 5.6a	Chinese White Dolphin Distribution Patterns in the Past 6 Years (Sheet 1 of 2)
Figure 2.1a	General Layout of Submarine Outfall Works	Figure 5.6b	Chinese White Dolphin Distribution Patterns in the Past 6 Years (Sheet 2 of 2)
Figure 2.2	Sounding Data for Area A from MD 2000	Figure 5.7a	Finless Porpoise Distribution Patterns in the Past 6 Years (Sheet 1 of 2)
Figure 2.3	Sounding Data for Area A from MD 2001	Figure 5.7b	Finless Porpoise Distribution Patterns in the Past 6 Years (Sheet 2 of 2)
Figure 2.4	Sounding Data for Area A from MD 2002	Figure 6.1	Overall Distribution of Fishing Operations
Figure 2.5	Sounding Data for Area A from MD 2003	Figure 6.2	Distribution of Fishing Operation (Vessel ≤ 15m)
Figure 2.6	Sounding Data for Area A from MD 2004	Figure 6.3	Distribution of Fishing Operation (Vessel > 15m)
Figure 2.7	Sounding Data for Area A from MD 2005	Figure 6.4	Distribution of Adult Fish Production
Figure 2.8	Sounding Data for Area A from MD 2006	Figure 6.5	Distribution of Overall Fisheries Production (Adult Fish & Fish Fry)
Figure 2.9	Sounding Data for Area A from MD 2007	Figure 6.6	Distribution of Fish Fry Production
Figure 2.10	Sounding Data for Area A from MD 2008	Figure 7.1	Extent of Dredging
Figure 2.11	Sounding Data for Area A from MD 2009	Figure 7.2	Location of Depots and Extent of Consultation Zones
Figure 2.12	Sounding Data for Area A from EGS 2009	Figure 7.3	Societal Risk Guideline
Figure 2.13	Siltation Map for Area A 2003 - 2009	Figure 7.4	Kwai Chung Dredging Hazard to Life Assessment Methodology
Figure 2.14	Sounding Data for Area B 1999 - 2009	Figure 7.5	Land Sites and Roads in the Vicinity of the Depots
Figure 2.15	Siltation Map for Area B 1999 – 2009	Figure 7.6	Fairways near the Tsing Yi PHIs N6 and N11
Figure 2.16	Locations of Potentially Concurrent Projects	Figure 7.7	Outcome Event Tree
Figure 3.1	Locations of Water Sensitive Receivers and Water and Sediment Quality Monitoring Stations	Figure 7.8	Outcome Event Tree (Above Ground LPG Storage Vessels in Exxon Mobil Depot)
Figure 3.2	Extent of the Western Harbour Model Grid	Figure 7.9	Individual Risk for SINOPEC Depot N11
Figure 3.3a	Grid Refinement at the Project Area	Figure 7.10	Individual Risk for ExxonMobil Depot N6
Figure 3.3b	Coastline Configuration near the Project Area	Figure 7.11	Societal Risk for SINOPEC Depot for Years 2009, 2012 and 2014
Figure 3.4a	Current flow in the vicinity of the Project Area (dry season)	Figure 7.12	Societal Risk of ExxonMobil Depot for Years 2009, 2012 and 2014
Figure 3.4b	Current flow in the vicinity of the Project Area (wet season)	Figure 8.1	Landscape Impact Assessment Area
Figure 3.5a	Potential Sediment Source Locations within the Project Area	Figure 8.2a	Landscape Impact Assessment – Landscape Resources (Sheet 1 of 3)
Figure 3.5b	Dredging Scenario 1	Figure 8.2b	Landscape Impact Assessment – Landscape Resources (Sheet 2 of 3)
Figure 3.5c	Dredging Scenario 2	Figure 8.2c	Landscape Impact Assessment – Landscape Resources (Sheet 3 of 3)
Figure 3.5d	Dredging Scenario 3	Figure 8.2d	Photo-views of Landscape Resources
Figure 3.5e	Dredging Scenario 4	Figure 8.3a	Landscape Impact Assessment – Landscape Character Areas (Sheet 1 of 3)
Figure 3.5f	Dredging Scenario 5	Figure 8.3b	Landscape Impact Assessment – Landscape Character Areas (Sheet 2 of 3)
Figure 3.5g	Dredging Scenario 6	Figure 8.3c	Landscape Impact Assessment – Landscape Character Areas (Sheet 3 of 3)
Figure 3.5h	Dredging Scenario 7	Figure 8.3d	Photo-views of Landscape Character Areas
Figure 3.5i	Working Zones of different Scenarios	Figure 8.4a	Zone of Visual Influence and VSRs
Figure 3.5j	Working Zones of different Scenarios	Figure 8.4b	Photo-views of Visual Sensitive Receivers
Figure 3.6	Locations of Tsing Yi and Kwai Chung Submarine Outfalls	Figure 8.5	Residual Visual and Glare Impacts in Construction and Operation Phases
Figure 3.7	Schematic Diagram of Silt Curtain with Grab Dredger	Figure 9.1:	Tsing Yi Section of the Study Area
Figure 4.1	Grab/ Vibrocore Sampling Locations (Sheet 1 of 2)	Figure 9.2:	Western Fairway Section of the Study Area
Figure 4.2	Grab/ Vibrocore Sampling Locations (Sheet 2 of 2)	Figure 9.3:	Survey areas A & B
Figure 4.3	Grab / Vibrocore Sampling Results	Figure 9.4:	Tsuen Wan around 1900. The waterfront at Hoi Pa also called the 'embankment at the sea' (Hayes, 1983).
Figure 5.1	Assessment Area for Marine Ecological Impact Assessment	Figure 9.5:	The Fatal Fire on the QE1
Figure 5.2	Locations of Marine Ecological Survey	Figure 9.6:	The Wrecked Hull of the QE1
Figure 5.3	Survey Locations for Marine Ecological Impact Assessment in Literature	Figure 9.7:	Current location of the QE1
Figure 5.4	Representative Intertidal Habitats	Figure 9.8:	Aerial Photograph of the Study Area 1924
Figure 5.5a	Intertidal Habitat Map (Sheet 1 of 2)	Figure 9.9:	Aerial Photograph of the Study Area from 1954
Figure 5.5b	Intertidal Habitat Map (Sheet 2 of 2)	Figure 9.10:	Aerial Photograph of the Study Area 1964

Agreement CE 63/2008 (CE)
Providing Sufficient Water Depth for Kwai Tsing Container Basin
and its Approach Channel
Environmental Impact Assessment Report



- Figure 9.11: Aerial Photograph of the Study Area 1975
Figure 9.12: Aerial Photograph of the Study Area 1989
Figure 9.13: Aerial Photograph of the Study Area from 2007
Figure 9.14: Navigation Chart of the Study Area 1764
Figure 9.15: Navigation Chart 1841
Figure 9.16: Navigation Chart 1864
Figure 9.17: Navigation Chart 1888
Figure 9.18: Side Scan Sonar Data showing construction debris associated with Kwai Chung Submarine Outfall and Tsing Yi Submarine Outfall
Figure 9.19: Location of Unidentified Sonar Contacts
Figure 9.20: Seismic Data showing acoustic hyperbola associated with HKT buried cable and WSD pipeline
Figure 9.21: Seismic Data showing Kwai Chung Outfall
Figure 9.22: Maintenance Dredging Location prior to CT9 works
Figure 9.23: Dredging Location after CT9 works.
Figure 9.24: Dredging History
- Figure 10.1a Study Area of Noise Impact Assessment (Sheet 1 of 2)
Figure 10.1b Study Area of Noise Impact Assessment (Sheet 2 of 2)
Figure 10.2 Location of Representative Noise Sensitive Receivers
- Figure 11.1a Study Area of Air Quality Impact Assessment (Sheet 1 of 2)
Figure 11.1b Study Area of Air Quality Impact Assessment (Sheet 2 of 2)
Figure 11.2 Location of Representative Air Sensitive Receivers
Figure 11.3a Acid Volatile Sulphide (AVS) Sampling Locations (Sheet 1 of 2)
Figure 11.3b Acid Volatile Sulphide (AVS) Sampling Locations (Sheet 2 of 2)