

NOTES :

Guillotine Failure of Loading Arm During Bulk Filling (Sinopec HK Oil Terminal Chai Wan)

		<i>Ignition Prob.</i>	<i>Event Outcome</i>	<i>Outcome Probability</i>
1.00E+0	Oil Release	yes 0.004	Pool Fire	4.00E-3
		no 0.996	Unignited Release	9.96E-1
				1.00

Guillotine Failure of Flexible Hose During Drum Filling (Sinopec HK Oil Terminal Chai Wan)

		<i>Ignition Prob.</i>	<i>Event Outcome</i>	<i>Outcome Probability</i>
1.00E+0	Oil Release	yes 0.004	Pool Fire	4.00E-3
		no 0.996	Unignited Release	9.96E-1
				1.00

Guillotine Failure of Pump Connecting Pipeline in Pump Farm (Sinopec HK Oil Terminal Chai Wan)

		<i>Ignition Prob.</i>	<i>Event Outcome</i>	<i>Outcome Probability</i>
1.00E+0	Oil Release	yes 0.004	Pool Fire	4.00E-3
		no 0.996	Unignited Release	9.96E-1
				1.00

Consultant



Allied Environmental Consultants Limited
ACOUSTICIANS & ENVIRONMENTAL ENGINEERS

Project No. : 1158

File Name :

Project :
Chai Wan Government Complex and Vehicle Depot

Drawing Title :
Event Trees for Guillotine Failure of Loading Arm, Flexible Hose and Pump Connecting Pipeline (Sinopec HK Oil Terminal)

Drawing No : Figure 10.11 Revision : 4

Scale : NTS Date : May 2015

DO NOT SCALE OFF DRAWING. THIS DRAWING IS NOT FOR CONSTRUCTION PURPOSES UNLESS EXPRESSLY STATED. ALL RIGHTS RESERVED AND REPRODUCTION IN ANY FORM MUST BE APPROVED BY ALLIED ENVIRONMENTAL CONSULTANTS LIMITED.